



National Inspection Services
 # : 183816 on 05/12/2020
 VIN: 1M2P267C31M055625

Housby Auctions Marcus Bowersox
 4747 NE 14th St Des Moines, IA 50313 USA
 (515) 299-6265

2001 MACK RD688S

RD688S Specifications	
Mileage	88,788
Engine Hours	38866
Engine	Mack E7 350 HP
Engine Brake	Yes
Engine Serial	OD2069
Fuel	Diesel 2 Steel Tanks 100 Gal. Total
Transmission	Eaton Manual 8LL Spd
Axles	Tandem
Frame Type	Steel
Suspension	Chalmers
Tire Size F	315/80R22.5
Tire Size R	315/80R22.5
Wheels	Steel
A/C	Yes * See Notes
Interior Color	CHARCOAL
Radio Config	AM/FM/CD * Operational
Power Mirrors	RH Power Only
Hi Back Seats	Driver Side Only
Pass Seat	Stationary
Exterior Color	WHITE
Bumper	Painted
Heated Mirrors	Yes
External Visor	No

Drive Options
Cruise Control, Power Steering

Inspection Photos



Notes / Description



National Inspection Services

: 183816 on 05/12/2020

VIN: 1M2P267C31M055625

Housby Auctions Marcus Bowersox

4747 NE 14th St Des Moines, IA 50313 USA

(515) 299-6265

2001 MACK RD688S PHOTOS







National Inspection Services
 # : 183816 on 05/12/2020
 VIN: 1M2P267C31M055625

Housby Auctions Marcus Bowersox
 4747 NE 14th St Des Moines, IA 50313 USA
 (515) 299-6265

2001 MACK RD688S

Brakes	
26	25
24	26
19	14
Additional Brake Detail	

Tires			
Front 315/80R22.5	Bridgestone 13 / 32 Steel	Bridgestone 13 / 32 Steel	Rear 315/80R22.5
Bridgestone 16 / 32 Steel	20 / 32 Steel	Michelin 18 / 32 Steel	Michelin 19 / 32 Steel
Bridgestone 13 / 32 Steel	Goodyear 13 / 32 Steel	Bridgestone 13 / 32 Steel	Bridgestone 9 / 32 Steel
Additional Tire Detail			
Unmarked tire is City Transport brand.			

General Observations	
Oil Milky? No	Oil Leaks? Yes
Water Leaks? No	Oil in Coolant? No
Clutch Play? NA	Starts? No
Drives? No	
Safety / Operational Observations	
Lights Work? See Notes	Wipers Work? See Notes
Gauges Work? See Notes	City Horn Works? Yes
Air Horn Works? See Notes	
Additional Observation Detail	
Unit would not start. Boost start attempted, unit would crank but not start. Unit appears to have been towed in. Wet oil noted on the hoses on the D/S of the engine and bottom of block near oil pan.	

Wear and Tear Items	
Rust	Rust noted on bumper, battery compartments, roll-off frame, fuel tanks, rears, frame, rims, wheel covers
Hood	Multiple areas of fiberglass cracks and repairs noted.
Headlight	Headlight bezel missing D/S.
Bumper	Front bumper bent inward on ends.
License Plate Light	Loose.
Rear fenders	Excessive deterioration noted; cracks, rust holes, failing mounts.
Stowage Compartment	Bottom rusted through.
Exhaust Tip	Damaged.
Brakes	One side of the front brake covers is missing on both front tires.
ECM Connection	Missing from mount.
Roll-off Controls	Cap missing from actuator.

Shifter	Cap missing, collar loose.
Windshield	Chipped.
Tires	1 below terms
Overhead console	Metal brace noted near radio
Grill	Damaged
Mud flap	Right side torn
Hydraulic tank	Damaged / rusted
Paint	Various chips and scratches

Condition report only. National Inspection Services does not guarantee mechanical reliability.

© 2020 National Inspection Services (NIS)
 101 W. Shrader St. Liberty, MO 64068
www.nationalinspect.com