



## Printable Catalog

<b>Title</b>	NOVEMBER 29 12:00 CST	
<b>Description</b>	Closing Times TBD	
<b>Date</b>	Wed, Nov 29, 2023	
<b>Starts at</b>	12:00 PM	
<b>Address</b>	4747 NE 14th St, Des Moines, IA 50313 USA	
<b>Categories</b>		


---

<b>Lot #</b>	1	
<b>Qty</b>	1	
<b>Title</b>	2009 FREIGHTLINER M2 106 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. Missing Items, Including: Headlights, Side Mirrors, D/S Cab Steps, Tires On First Rear Axle, Odometer And Gauges, P/S Seat Tattered, Wiring On Cab Floor, Rust Throughout. Mileage Unavailable. Location: Sacramento, CA Serial: 1FVFCYBS99HAD1862	


---

<b>Lot #</b>	2	
<b>Qty</b>	1	
<b>Title</b>	2005 FREIGHTLINER FLD120SD REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Oil Leaking, L/S Yellow, L/S Rear And R/S Mirror Marker Lights INOP, Heater Control And Radio Volume Knobs Missing From Dash, Air Intake Trim Cracked, Tires Worn, Hole Noted In P/S Seat, Scratches, Paint Chips And Rust Noted Throughout. Showing 18,223 Miles; 5,140 Hours. Location: East Wentachee, WA Serial: 1FVMALEDL25DU32596	


---








<b>Lot #</b>	3	
<b>Qty</b>	1	
<b>Title</b>	2018 PETERBILT 567 DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. ENGINE DERATE MESSAGE DISPLAYED ON DASH, Emissions, Engine And Stop Engine Warning Lights On Dash, Ravens By Kruz RDP-20-60 Dump Body, Damage Noted On Bumper, Engine Tag Not Located, Small Tears In D/S Seat. Showing 404,389 Miles; 1,184 Hours. Location: Des Moines, IA Serial: 1NPCLPEX9JD455970	








---








<b>Lot #</b>	4	
<b>Qty</b>	1	
<b>Title</b>	2005 STERLING A9500 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Oil Leaks From Rear Engine Seal And PTO, Fuel And Engine Hours Gauge INOP, Dash Panels Are Broken And Others Are Missing, Door Trim Panel Has Cracked Plastic, Rust And Body Damage Throughout. Showing 801,772 Miles. Location: Converse, TX Serial: 2FWJA3DE35AV17894	








---







<b>Lot #</b>	5	
<b>Qty</b>	1	
<b>Title</b>	2003 CONSTRUCTION SPECIALIST SBD240 DUMP TRAILER	
<b>Des.</b>	APPROXIMATE MEASUREMENTS 40 FT LENGTH, 96 IN WIDTH, 118 IN HEIGHT, FULL OPERATIONS NOT TESTED. BOTH BRAKE AND TURN SIGNAL LIGHTS MISSING, Scratches, Dents, Rust Throughout Unit. Location: Waco, TX Serial: 1C91140273S770158	

<b>Lot #</b>	6	
<b>Qty</b>	1	
<b>Title</b>	2005 INTERNATIONAL 7300 4X2 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. ENGINE PARTIALLY DISASSEMBLED, Axle Weight Tag Not Located, Reman Engine, Rust And Body Damage Throughout. Mileage Unavailable. Location: Weatherford, TX Serial: 1HTWAAAR65J186898	
<b>Lot #</b>	7	
<b>Qty</b>	1	
<b>Title</b>	2006 FREIGHTLINER FLD120SD REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. REAR BRAKES ARE LOCKED UP, Oil Leaks, Center And L/S Cab Marker Lights Are INOP, D/S Door Trim Panel Is Damaged, D/S Steps Damaged, Grill Is Missing Bolts, Paint Is Scratched, Chipped And Cracked, Body Damage Noted On Bumper. Showing 18,223 Miles; 5,140 Hours. Location: East Wentachee, WA Serial: 1FVMALDL26DW00268	
<b>Lot #</b>	8	
<b>Qty</b>	1	
<b>Title</b>	1995 CASE 621B WHEEL LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. Hydronic Leaks Noted, Oil Seepage And Known Hydraulic Fluid Leaks, Engine Tag Not Located, Small Tear In D/S Seat, Heavy Rust Throughout. Showing 9,626 Hours. Location: Des Moines, IA Serial: JEE0042384	
<b>Lot #</b>	9	
<b>Qty</b>	1	
<b>Title</b>	2003 INTERNATIONAL 9100i 6X4 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Oil Leak Noted, Dashboard Is Broken With Loose And Missing Panels, Glove Box Cover, A/C Vents On P/S And Door Pull Handle Cushions Missing, Steering Wheel Worn And Taped Up, D/S Seat Torn, P/S Steps Bent, Various Body Damage Throughout. Showing 1,109,028 Miles; 40,533 Hours. Location: Converse, TX Serial: 2HSCBAXR73C060055	
<b>Lot #</b>	10	
<b>Qty</b>	1	
<b>Title</b>	1998 MACK RD690S DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Body Would Not Lift To View Engine, P/S Headlight And P/S Seat Are Missing, Henderson Dump Body, Body Tag Is Illegible, Dash Apart On P/S. Showing 268,985 Miles; 13,240 Hours. Location: Des Moines, IA Serial: 1M2P264C1WM027673	
<b>Lot #</b>	11	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CT713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. Chrome Peeling Away From Grill, Bulldog Ornament And Hood Mirrors Are Missing, Engine Tag Not Located, Body Damage And Rust Throughout. Mileage Unavailable. Location: McComb, MS Serial: 1M2AL02C86M004216	
<b>Lot #</b>	12	
<b>Qty</b>	1	
<b>Title</b>	2004 FREIGHTLINER FLD120SD REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. ENGINE OIL LEAK ON P/S REAR CORNER, Rear Fenders Rusted Through, Floor Damaged, Bumper Bent, Rust And Scratches Throughout Unit, Passenger Mirror Housing Damaged, Interior Drivers Door Panel Damaged. Showing: 9,047 Hours. Location: Yakima, WA Serial: 1FVMALDL94DN31267	








<b>Lot #</b>	13	
<b>Qty</b>	1	
<b>Title</b>	2008 CONSTRUCTION SPECIALIST BDT-40 DUMP TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. TARP CABLE IS BROKEN ON P/S, HEAVY RUST- Exposed Metal In Some Areas, Weld Repairs And Body Damage Noted, P/S Rear Tire Fender Has Piece Of Metal Missing From Side Edge, Approximate Measurements: 40 FT Length, 96 IN Width, 9.84 FT Height. Location: Waco, TX Serial: 5TU1140298S000453	
<b>Lot #</b>	14	
<b>Qty</b>	1	
<b>Title</b>	2003 INTERNATIONAL 9100i 6X4 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Dash Panel Is Broken On P/S, A/C Vents Broken On P/S, Floor Mat Worn On D/S, Various Body Damage Noted, Items Missing, Including: D/S Dash Panel, R/S Headlight Bezel, Batteries Box Cover, L/S Fuel Tank, P/S Mirror Is Broken And Taped In Place. Showing 240,055 Miles; 10,932 Hours. Location: Converse, TX Serial: 2HSCBAXR03C060057	
<b>Lot #</b>	15	
<b>Qty</b>	1	
<b>Title</b>	2005 KAWASAKI 85ZV WHEEL LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. OVERHEATS QUICKLY AFTER STARTING, Warning Lights On Dash, Varying Rust Throughout. Showing 20,267 Hours. Location: Greenville, OH Serial: 0705-162845-1	
<b>Lot #</b>	16	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. Rear Poly Fenders Twisted Up, Odometer Cover Is Cracked, Rust And Body Damage Throughout. Mileage Unavailable. Location: McComb, MS Serial: 1M2AG11C97M064390	
<b>Lot #</b>	18	
<b>Qty</b>	1	
<b>Title</b>	2013 WESTERN STAR 4900FA DUMP TRUCK	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. ENGINE DISASSEMBLED, Left Side Landing Bent, Passenger Exterior Trim Missing Fastener, Paint Scratched And Chipped, Seats Stained, Drivers Seat Torn. Showing: Mileage/Hours Unavailable. Location: Pasco, WA Serial: 5KKSABG0DPBZ2550	
<b>Lot #</b>	19	
<b>Qty</b>	1	
<b>Title</b>	2006 PETERBILT 335 FUEL TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Oil Leaking At Bottom Of Engine/Oil Pan And At Upper R/S Of Engine, Hood Hinges Are Unstable With Side To Side Motion (See Video), 2006 Hutchinson Industries Fuel Tanker, Cab Interior Is Soiled, Steering Wheel Surfaces Are Worn. Showing 464,439 Miles; 15,490 Hours. Location: Le Grand, IA Serial: 2NPLHD7X06M631402	
<b>Lot #</b>	20	
<b>Qty</b>	1	
<b>Title</b>	2001 MIDLAND MG40MC3000 BELLY DUMP TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. FRONT GATE CHAIN AND INTERIOR VERSA VALVE ARE MISSING, Brake Guards Are Bent, Inside Lights Are Out Of Holders, Body Damage And Rust Noted, Approximate Measurements: 40 FT Length, 96 IN Width, 11.25 FT Height. Location: Waco,TX Serial: 2MFB2S4C71R001389	








<b>Lot #</b>	21	
<b>Qty</b>	1	
<b>Title</b>	2014 CATERPILLAR CT660S SBA 6X4 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. Missing items, Including: Transmission, One Battery, Grill, Rear Chassis Area Is Bent, Front Tires Worn, Drive Shaft Removed And In Cab, D/S Seat Torn, Interior Soiled. Mileage Unavailable. Location: Meridian, MS Serial: 1HTJGTKT6EJ498346	
<b>Lot #</b>	22	
<b>Qty</b>	1	
<b>Title</b>	2005 FREIGHTLINER FLD120SD REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. OIL LEAK FROM THE FRONT ENGINE SEAL AND OIL PAN, Missing Fasteners On Dashboard, Interior Drivers Door Panel Damaged, Seats Stained And Worn, Rear Window Trim Damaged, Windshield Has Rock Chip. Showing: 48,262 Miles; 2,557 Hours. Location: Pasco, WA Serial: 1FVMALEDL35DU23468	
<b>Lot #</b>	24	
<b>Qty</b>	1	
<b>Title</b>	2014 OSHKOSH S2386 FRONT MIXER	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. CHECK ENGINE LIGHT AND ABS LIGHT ON, ECU BAD, Axle, Hub And Drum Are Off On Drivers Side, Water Tank Missing, Missing Chutes. Showing: 147,942 Miles. Location: Harrisburg, PA Serial: 10TAFGGF4ES769226	
<b>Lot #</b>	25	
<b>Qty</b>	1	
<b>Title</b>	2012 WESTERN STAR 4900FA DUMP TRUCK	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. TAGGED OUT, Tires Worn, Oil Leaking From The Cylinder, Bottom Of Hydraulic Tank Is Leaking At The Shut Off Valve, Oil Leaking On P/S Of Oil Pan, Oil Milky Inside Of Filler Tube- Dipstick Is Not Milky, Intermediate Axle Is Missing Tires, Seats Worn, Torn And Stained, Rust And Body Damage Throughout. Showing 289,919 Miles; 15,268 Hours. Location: Pacific, WA Serial: 5KKSIEDR8CPBH5004	
<b>Lot #</b>	26	
<b>Qty</b>	1	
<b>Title</b>	2006 VOLVO VHD64B CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. UNABLE TO POWER UNIT, Rust Throughout Unit, Part Of Dash Taken Apart, Interior Dirty And Stained. Showing: Mileage/Hours Unavailable. Location: Pelham, AR Serial: 4V5KC9GF46N405157	
<b>Lot #</b>	27	
<b>Qty</b>	1	
<b>Title</b>	2003 FREIGHTLINER FLD120SD REAR MIXER	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. OIL LEAKAGE AT LOWER RIGHT SIDE OF ENGINE, FRONT OF OIL PAN AND AT REAR SEAL AREA, Bumper Damaged, Grille Missing Slats, Chrome Damaged, Windshield Cracked, Paint Scratches, Rear Fender Rusted And Dented, Mixer Parts Removed, Right Fender Flare Loose, Interior Door Panel Damaged, Dashboard Parts Missing, Rear Window Trim Damaged. Showing: 69,485 Miles; 8,500 Hours. Location: Pasco, WA Serial: 1FVHALAN53DL88971	
<b>Lot #</b>	28	
<b>Qty</b>	1	
<b>Title</b>	2001 MIDLAND MG40MC2000 BELLY DUMP TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Tires Worn, Tarp Is Torn By Attachment Bar, Interior Versa Valve Is Missing, Brake Guards Are Slightly Bent, Heavy Rust And Areas Of Body Damage Are Noted, Approximate Measurements: 40 FT Length, 96 IN Width, 11.25 FT Height. Location: Waco, TX Serial: 2MFB2S4C51R001388	

<b>Lot #</b>	29	
<b>Qty</b>	1	
<b>Title</b>	1993 JOHN DEERE 410J BACKHOE	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. NON RUNNER, FULL OPERATIONS NOT TESTED. Warning Lights On Dash, Rear Tire Is Cracking, Heavy Rust Throughout, Interior Soiled, Seat Arm Rest Is Taped Up, Approximate Measurements: 26 FT Shipping Length, 108 IN Shipping Width, 12 FT Shipping Height. Showing 15,694 Hours. Location: Elkhorn, WI Serial: T0410JX159005	
<b>Lot #</b>	31	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. Missing Items, Including: Batteries, Bulldog Ornament From Hood, Headlights, Tail Lights, Marker Lights From Top, Center Of Steering Wheel, Rust Throughout. Mileage Unavailable. Location: Cairo, GA Serial: 1M2AG11C37M055023	
<b>Lot #</b>	32	
<b>Qty</b>	1	
<b>Title</b>	2005 FREIGHTLINER FLD120SD REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. BOTTOM SIDE OF ENGINE COVERED IN OIL, Window Trim Damaged, Paint Chips And Rust Throughout Unit, Interior Panel Of Door Damaged, Seat Stained, Headliner Sagging. Showing: 277,318 Miles; 6,256 Hours. Location: Pasco, WA Serial: 1FVMA LDL65DU32598	
<b>Lot #</b>	33	
<b>Qty</b>	1	
<b>Title</b>	1989 FORD F700 LUBE TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. LOW COOLANT LIGHT ON, Missing Fuel Cap, Interior In Rough Shape, Some Rust Throughout Unit. Showing: 124,417 Miles; 2,932 Hours. Location: Harrisburg, PA Serial: 1FDXK74A0KVA0023	
<b>Lot #</b>	34	
<b>Qty</b>	1	
<b>Title</b>	1990 BOBCAT 2410 WHEEL LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Missing Bucket Attachment, Rear Tires Are Worn, Exterior Dirty And Rusted, Dents And Body Damage Throughout, Seat Is Torn, Approximate Measurements: 12.5 FT Shipping Length, 72 IN Shipping Width, 7.10 FT Shipping Height. Showing 698 Hours. Location: Serial: 509212105	
<b>Lot #</b>	35	
<b>Qty</b>	1	
<b>Title</b>	2001 MIDLAND MG40MC3000 BELLY DUMP TRAILER	
<b>Des.</b>	APPROXIMATE MEASUREMENTS 40 FT LENGTH, 96 IN WIDTH, 135 IN HEIGHT, FULL OPERATIONS NOT TESTED. Rust Throughout Unit, Swivel Plate Worn, Missing Gate Chains, Dents Throughout Unit, Brake Guard Very Bent, License Plate Light Missing. Location: Waco, TX Serial: 2MFB2S4C91R001331	
<b>Lot #</b>	36	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. ABS And Electrical Warning Lights On Dash, Missing D/S Hood Vent Grill, Rear Tires Singled Out, Some Tail Lights Are Damaged, Small Tears In D/S Seat, Rust And Body Damage Throughout. Showing 541,599 Miles; 26,055 Hours. Location: Jacksonville, FL Serial: 1M2AG11C87M067992	








<b>Lot #</b>	37	
<b>Qty</b>	1	
<b>Title</b>	2007 KENWORTH W900 6X4 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. ENGINE OIL PAN SEAL LEAKING ALL AROUND, Interior Drivers Door Damaged, Scratched And Rusting Bumper, Seats Are Worn And Stained. Showing: 211,853 Miles; 19,857 Hours. Location: Pendleton, OR Serial: 1NKWL00X07J163359	
<b>Lot #</b>	39	
<b>Qty</b>	1	
<b>Title</b>	2013 CATERPILLAR D6T-LGP DOZER-CRAWLER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Bolts Removed From Blade Arms, Attachment Removed With Machine, Tracks Worn, Rust Throughout, Approximate Measurements: 19 FT Shipping Length, 138 IN Shipping Width, 10.6 FT Shipping Height. Location: Greenville, OH Serial:MYE07159	
<b>Lot #</b>	40	
<b>Qty</b>	1	
<b>Title</b>	2005 INTERNATIONAL 7600 6X4 DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. BAD CLUTCH- TRUCK WILL DIE WHEN CLUTCH IS FULLY RELEASED, Oil Residue Build Up Around Front, Both Sides Of Engine And Bottom Of Oil Pan, Oil Leakage Noted At Transmission Rear Output Shaft, Lift Cylinder Hoses For Bed Are Leaking Oil, ABS Warning Light On Dash, Steps Bent On Both Sides, D/S Seat Worn/Torn, Clutch Pedal Pad Is Missing, Windshield Is Cracked, Headliner Is Split, Ox Bodies 17 FT Dump Body, D/S Mirror Is Missing Housing, Dump Bed Filled With Soil, Crack In Odometer Cover. Showing 406,742 Miles; 406,733 ECM; 22,798 Hours. Location: San Antonio, TX Serial: 1HTWXAHT85J011486	
<b>Lot #</b>	41	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Low Air And ABS Warning Lights On Dash, Truck Has Been Repainted, Components Missing From P/S Dash Area, Rear Tires Are Singled Out, Rust Throughout. Showing 589,847 Miles; 36,240 Hours. Location: Newark, NJ Serial: 1M2AG11C16M035416	
<b>Lot #</b>	42	
<b>Qty</b>	1	
<b>Title</b>	2015 VOLVO VHD REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. CHECK ENGINE WARNING LIGHT ON DASH, 1 Active Fault Found- Dashboard Unit Registers A Short Circuit, P/S Tail Light Bent/Broken, L/S Tank Missing Cap, P/S Steps Are Loose, D/S Seat Torn, Upholstery Worn, Headliner Sagging And Soiled, Cracks, Dents And Various Damage Throughout. Showing 212,842 Miles; 19,895 Hours. Location: Converse, TX Serial: 4V5KC9DF4FN192277	
<b>Lot #</b>	43	
<b>Qty</b>	1	
<b>Title</b>	2001 MIDLAND MG40MC3000 BELLY DUMP TRAILER	
<b>Des.</b>	APPROXIMATE MEASUREMENTS 40 FT LENGTH, 96 IN WIDTH, 136 IN HEIGHT, FULL OPERATIONS NOT TESTED. Rear Trailer Lights Missing, Versa Valve Missing, Gate Chains Missing, Gate Weld Is Cracked, Brake Guards Bent, Paint Chips And Rust Throughout Unit. Location: Waco, TX Serial: 2MFB2S4C71R001327	

















<b>Lot #</b>	44	
<b>Qty</b>	1	
<b>Title</b>	2018 FREIGHTLINER CASCADIA 126 SLEEPER TRUCK	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Stability Control And Lane Departure Lights On, Paint Peeling Of Frame, Rust Exposed, Sleeper Fairing Brackets Are Broken, Mismatch Tires, Front Bumper Scratched And Cracked On Right Side. Showing: 669,678 Miles; 18,851.36 Hours. Location: Yermo, CA Serial: 3AKJHHDR8JSJH8672	
<b>Lot #</b>	45	
<b>Qty</b>	1	
<b>Title</b>	2014 TRAILBOSS DP333 EQUIPMENT TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Outer Hub Seals On Axle Are Showing Oil Residue And Build Up, Wooden Deck Is Rotten, Missing Boards, And Improperly Secured, Approximate Measurements: 33 FT Length, 102 IN Width. Location: San Antonio, TX Serial: 4S0DP333E1003364	
<b>Lot #</b>	47	
<b>Qty</b>	1	
<b>Title</b>	2014 VOLVO VHD REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. STOP ENGINE AND ENGINE WARNING LIGHTS ON DASH, DPF FAIL- EGR Flow To Rear Heated Oxygen Sensor, DEF Particulate Matter Sensor Control At Limit, 7 Active Faults Found, Oil Leak Coming From Oil Pan And PTO, Steps Have A Broken Weld, P/S Door Window Handle Is Missing, Windshield Is Cracked, D/S Seat Torn, Various Body Damage Throughout. Showing 217,055 Miles; 24,269 Hours. Location: Converse, TX Serial: 4V5KC9DF4EN172397	
<b>Lot #</b>	48	
<b>Qty</b>	1	
<b>Title</b>	2003 MACK DM690S TANDEM AXLE DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Oil Pan Has Oil Leakage, Seats Torn, Interior Soiled With Mud, Rust, Abrasions And Various Body Damage Throughout. Showing 89,231 Miles; 11,205 Hours. Location: Memphis, TN Serial: 1M2B209C43M029381	
<b>Lot #</b>	50	
<b>Qty</b>	1	
<b>Title</b>	2005 MONTONE AD24545454 DUMP TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Front Aluminum Spill Plate Bent On R/S, Scrapes, Abrasions And Rust Noted, Approximate Measurements: 25 FT Length, 96 IN Width, 9.5 FT Height. Location: Memphis, TN Serial: 1M9SD302X5S567261	
<b>Lot #</b>	52	
<b>Qty</b>	1	
<b>Title</b>	2014 VOLVO VHD REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. ENGINE WARNING LIGHT ON DASH, DPF FAIL- NOX CATALYST IS BELOW THE THRESHOLD, 3 Active Faults Found, Oil Leak From PTO, Windshield Is Cracked, Dried Concrete Over Rear, Oil Fill Cap Is Missing, D/S Door Keyhole Is Broken, P/S Seat Missing, Various Body Damage Noted. Showing 220,107 Miles; 21,704 Hours. Location: Converse, TX Serial: 4V5KC9DF0EN172395	
<b>Lot #</b>	53	
<b>Qty</b>	1	
<b>Title</b>	2007 TRAILBOSS DP333 EQUIPMENT TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Tires Worn, Axle Outer Seal Leaking, Front R/S Marker Light Is Mounted Improperly, Wooden Deck And Ramps Rotten And Missing Wood, Approximate Measurements: 33 FT Length, 102 IN Width. Location: San Antonio, TX Serial: 4S0DP333571002462	




<b>Lot #</b>	54	
<b>Qty</b>	1	
<b>Title</b>	2015 KENWORTH T680 SLEEPER TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. WARNING LIGHTS ON, Chrome On Mirror Bracket Worn, Paint Chipping Around headlight With Scratches, Marker Lights Above Windshield In Rough Shape, Paint Chipping Throughout Unit, Hood Mirror Not Attached. Showing: 273,286 Miles; 17,283 Hours. Location: El Reno, OK Serial: 1XKYDP8X5FJ434407	
<b>Lot #</b>	55	
<b>Qty</b>	1	
<b>Title</b>	2010 FORD F150 4X2 EXT CAB PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. BRAKE AND ABS WARNING LIGHTS ON DASH, Tail Gate Bent And Dented, D/S Mirror Is Damaged, Seats Are Stained, D/S Seat Torn, Various Body Damage Throughout. Showing 203,104 Miles. Location: East Wentachee, WA Serial: 1FTFX1CV3AFC54223	
<b>Lot #</b>	57	
<b>Qty</b>	1	
<b>Title</b>	2014 VOLVO VHD REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Check Engine Warning Light On Dash, D/S Seat Torn And P/S Seat Is Missing, Windshield Is Cracked On D/S, Headliner Soiled And Sagging, Various Body Damage Throughout. Showing 225,281 Miles; 23,285 Hours. Location: Converse, TX Serial: 4V5KC9DF6EN156721	
<b>Lot #</b>	58	
<b>Qty</b>	1	
<b>Title</b>	2001 TRAVIS DUMP TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Abrasions And Scrapes Noted, Bed Insert Rear Edge Is Badly Worn In Center Area, Approximate Measurements: 25 FT Length, 96 IN Width, 9.9 FT Height. Location: Memphis, TN Serial: 48X1E252111001679	
<b>Lot #</b>	60	
<b>Qty</b>	1	
<b>Title</b>	2008 DODGE RAM 1500 CREW CAB PICKUP TRUCK	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. ENGINE HAS FAILED, Bumper Dented In Rear, Bed Is Dented And Scratched, Seats Stained And Worn, Drivers Seat Torn, Paint Has Scratches And Chips Throughout Unit. Showing: 210,935 Miles. Location: Yakima, WA Serial: 1D7HU18278J197179	
<b>Lot #</b>	61	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. Missing Items, Including: Grill, Bulldog Ornament, Headlights, D/S Hood Mirror, Tires On Middle Axle, Rear Tires Singled Out-Remaining Tires Are Worn, Misc. Components In Cab, Interior Soiled. Mileage Unavailable. Location: Rochester, MN Serial: 1M2AG11C07M054833	
<b>Lot #</b>	62	
<b>Qty</b>	1	
<b>Title</b>	2007 FREIGHTLINER M2 112 8X4 DUMP TRUCK	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Batteries Dead, Hood Has Paint Chips, Pusher Axle Missing Tire And Wheel, Interior Dirty And Worn, Drivers Seat Torn, Floor Mat Is Worn, Headliner Stained And Dirty. Showing: Mileage/Hours Unavailable. Location: Burnet, TX Serial: 1FVMC5CV77HY89215	



<b>Lot #</b>	63	
<b>Qty</b>	1	
<b>Title</b>	2004 RELIANCE PUP DUMP TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Side Steps Damaged, Hitch Is Damaged, Exterior Has Dents Throughout Unit. Location: Wapato, WA Serial: 5RETE04854S046115	
<b>Lot #</b>	64	
<b>Qty</b>	1	
<b>Title</b>	2007 FORD F450 4X2 FLATBED TRUCK	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. ENGINE DISASSEMBLED, L/S Head Light Lens Is Cracked, D/S Mirror Damaged, Dashboard Trim Is Missing, Bed Boards Are Damaged And Side Rails Are Bent, Windshield Cracked On P/S, Seats Worn And Stained, Body Damage Throughout. Mileage Unavailable. Location: Wapato, WA Serial: 1FDXF46P67EA79997	
<b>Lot #</b>	66	
<b>Qty</b>	1	
<b>Title</b>	2003 INTERNATIONAL DURASTAR 4400 SBA 4X2 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. MIDDLE AXLE MISSING TIRES, DOES NOT BUILD AIR, Rust And Body Damage Throughout. Showing 472,457 Miles; 32,117 Hours. Location: Rochester, MN Serial: 1HTMKAAN83H600432	
<b>Lot #</b>	67	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CV713 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Oil Pan Is Leaking Oil, ABS And Low Air Warning Lights On Dash, Graphics Adhesive On Cab Exterior, Rust And Body Damage Throughout, Seat Worn/Torn. Showing 205,684 Miles; 25,038 Hours. Location: Memphis, TN Serial: 1M2AG11C67M057073	
<b>Lot #</b>	68	
<b>Qty</b>	1	
<b>Title</b>	1993 TRAILMOBILE TLR90D VAN TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. VIN Tag Not Located, Body Damage Throughout And Spray Paint To Front End, Approximate Measurements: 48 FT Shipping Length, 100 IN Shipping Width, 23.3 FT Shipping Height. Location: Wittenberg, WI Serial: 1PT01JAH4P9012892	
<b>Lot #</b>	69	
<b>Qty</b>	1	
<b>Title</b>	2006 FORD F450 4X2 FLATBED TRUCK	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. OIL LEAKING FROM OIL PAN AND LOWER ENGINE, Wood Damaged In Bed, Rails Bent, Bumper Bent, Headlight Lens Cracked, Shifter Boot Loose, Side Mirrors Have Damage, Paint Scratched And Chipped Throughout, Seat Stained And Torn, Headliner Stained. Showing: 138,679 Miles. Location: Wapato, WA Serial: 1FDXF46P86ED26449	
<b>Lot #</b>	70	
<b>Qty</b>	1	
<b>Title</b>	2012 FORD F250 4X4 SUPER DUTY CREW CAB PICKUP TRUCK	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. BLOWN ENGINE, Engine Tag Not Located. Showing 169,529 Miles. Location: Elgin, IL Serial: 1FT7W2BT2CEA01917	

<b>Lot #</b>	71	
<b>Qty</b>	1	
<b>Title</b>	2002 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. STUCK IN GEAR, BRAKE AIR WARNING LIGHT ON DASH, Missing Hood Mirror On D/S, Holes Drilled In The Center Dash, Rust And Body Damage Throughout. Showing 532,945 Miles; 37,855 Hours. Location: Rochester, MN Serial: 1M2P267C02M063151	
<b>Lot #</b>	72	
<b>Qty</b>	1	
<b>Title</b>	2005 MACK CV713 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Tires Worn, Chrome Peeling From Grill, Steps Are Zip Tied In Place- Not Sturdy, P/S Seat Is Missing, Hole In D/S Seat, Dents Throughout. Mileage Unavailable. Location: Highland, IL Serial: 1M2AG11C45M027325	
<b>Lot #</b>	73	
<b>Qty</b>	1	
<b>Title</b>	1999 GALBREATH AP3A ROLLOFF TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. LIGHTS AND AIR BAGS INOP, Rust Throughout, Approximate Measurements: 35.10 FT Shipping Length, 34.8 FT Overall Length, 24.2 FT Bed Length, 98 IN Shipping Width, 5.9 FT Shipping Height. Location: Wittenberg, WI Serial: 1G9L12336XB157192	
<b>Lot #</b>	74	
<b>Qty</b>	1	
<b>Title</b>	1991 INTERNATIONAL 7100 4X2 FLATBED TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Oil Leak At Oil Filters And Around Oil Pan, Bumper Is Rock Chipped, Missing Headliner, Door Handle Knobs And Dome Light Cover From Interior, Seats Worn/Torn, Plastic Water Tank On Flatbed, Damage Throughout Body. Showing 391,783 Miles; 4,916 Hours. Location: Pendleton, OR Serial: 1HSHAZ7N4MH313816	
<b>Lot #</b>	75	
<b>Qty</b>	1	
<b>Title</b>	2002 FORD F150 PICKUP TRUCK	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. D/S Tail Light Is Busted, Missing Part Of Rear Body Near D/S Rear Corner, Inside Door Panels Disassembled, 3 Flat Tires . Mileage Unavailable. Location: Elgin, IL Serial: 1FTRF17202NB75115	
<b>Lot #</b>	76	
<b>Qty</b>	1	
<b>Title</b>	2003 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE W/JUMP, FULL OPERATIONS NOT TESTED. Rear Tires Singled Out, Hood Mirrors And P/S Hood Vent Grill Missing, Rust And Body Damage Are Present. Showing 792,145 Miles; 38,576 Hours. Location: Rochester, MN Serial: 1M2AG11C63M007123	
<b>Lot #</b>	77	
<b>Qty</b>	1	
<b>Title</b>	2005 MACK CV713 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. DASH DOES NOT ILLUMINATE, Cab Steps Are Loose And Bent-Held In Place With Zip Ties, Tires Worn, Rust And Body Damage Throughout. Mileage Unavailable. Location: Madison, IL Serial: 1M2AG11C85M027327	

<b>Lot #</b>	78	
<b>Qty</b>	1	
<b>Title</b>	1997 LODE KING FLATBED TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Front Axle Tires Are Singled Out, Boards Missing On Deck, Rust Throughout, Approximate Measurements: 53 FT Shipping Length, 103 IN Shipping Width, 4.8 FT Shipping Height. Location: Elgin, IL Serial: 2LDPF5326VA028730	
<b>Lot #</b>	79	
<b>Qty</b>	1	
<b>Title</b>	1985 MACK DM688S WATER TRUCK	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. TITLE BRANDED RECONSTRUCTED, Motor Is Taken Apart-Block And Transmission Still In Place, Fuel Tank Has Been Removed , P/S Rear Tank Has Large Dent, Rust Throughout, Body And Axle Weight Tags Not Located. Showing 4,653 Miles; 97 Hours. Location: Lebanon, PA Serial: 1M3B166KXFT003374	
<b>Lot #</b>	80	
<b>Qty</b>	1	
<b>Title</b>	2011 FORD F150 EXT CAB PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Engine Warning Light On Dash, D/S Seat Is Torn And Missing Panel At Bottom On L/S Of Seat. Showing 213,132 Miles. Location: Shelby, AL Serial: 1FTEX1CM5BFA48616	
<b>Lot #</b>	81	
<b>Qty</b>	1	
<b>Title</b>	2008 MACK GU813 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. ENGINE PARTIALLY DISASSEMBLED- Misc. Parts In Cab, Rust And Body Damage Throughout. Mileage Unavailable. Location: Blue Springs, MO Serial: 1M2AX13C98M002809	
<b>Lot #</b>	82	
<b>Qty</b>	1	
<b>Title</b>	2005 MACK CV713 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Steps Are Broken And Loose, P/S Seat Is Missing, Tires Worn, Brakes Gauge Hole Is Blocked By Brackets, Radio Knob Is Missing, Rust And Body Damage Present. Mileage Unavailable. Location: Highland, IL Serial: 1M2AG11CX5M027328	
<b>Lot #</b>	85	
<b>Qty</b>	1	
<b>Title</b>	1996 SPECTOR WALKING FLOOR TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. VIN Plate Not Located-Ground Away, Missing Items, Including: Blue Glad Hand, Electric Connection, Front Axle Wheels, Interior Filled With Trash Receptacles, Approximate Measurements: 53 FT Shipping Length, 96 IN Shipping Width, 13.6 FT Shipping Height. Location: Elgin, IL Serial: 1S9WA4522TS188349	
<b>Lot #</b>	86	
<b>Qty</b>	1	
<b>Title</b>	1994 INTERNATIONAL 2554 WATER TRUCK	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. OIL LEAK BETWEEN ENGINE AND TRANSMISSION, Crack Windshield, Interior Has Multiple Stains And Worn, Missing Shifter Cap. Showing: 356,483 Miles. Location: Austin, TX Serial: 1HTGCAAR9RH579418	

<b>Lot #</b>	87	
<b>Qty</b>	1	
<b>Title</b>	2008 CHEVROLET SILVERADO 1500 EXT CAB PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Engine And TPMS Warning Lights On Dash, Small Tear In D/S Seat, Rust Noted. Showing 364,299 Miles. Location: McCrory, AR Serial: 2GCEC19J381142955	
<hr/>		
<b>Lot #</b>	88	
<b>Qty</b>	1	
<b>Title</b>	2007 PETERBILT 357 REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. LEAKING ENGINE OIL FROM OIL PAN, Passenger Side Tire Flat And Off Bead, Small Air Leak, No Headlights, Body And Frame Have Minimal Rust. Showing: 260,823 Miles; 21,283 Hours. Location: Harrisburg, PA Serial: 1NPALT0X57N651222	
<hr/>		
<b>Lot #</b>	89	
<b>Qty</b>	1	
<b>Title</b>	1996 GIANT VAC FLATBED TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. MISSING L/S FRONT WHEEL, Deck Boards Are Rotten, Rough Frame, Approximate Measurements: 36.10 FT Shipping Length, 27.10 FT Bed Length, 97 IN Shipping Width, 3.2 FT Shipping Height. Location: Wittenberg, WI Serial: 1G9C1282XTB151562	