



National Inspection Services

: **136991** on 04/10/2017
VIN: **1HTMKAAN04H604461** Unit: **1277**

Housby Auctions Marcus Bowersox

4747 NE 14th St Des Moines, IA 50313 USA
(515) 299-6265

2004 INTERNATIONAL 4400

4400 Specifications	
Mileage	522,012 / 522,012 ECM
Engine Hours	3647
Engine	International DT466 250 HP
Engine Brake	No
Fuel	Diesel 1 Steel Tank 50 Gal. Total
Transmission	Eaton Manual FR-9210B 10 Spd
Rear	Spicer 3.90
Axles	Single 11,000 Front / 21,900 Rear
GVW (lbs)	32,900
Frame Type	Steel
Suspension	Spring
Wheelbase	189"
Tire Size F	11R22.5
Tire Size R	11R22.5
Wheels	Steel
Rear Door	Roll-Up 84"w x 75"h
Lift Gate Make	Anthony
Lift Gate Capac	2,500 (Lbs)
2nd Gen Body	No
Interior Height	84"
Exterior	89"H 96"W 16'L
A/C	Yes * Operational
Interior Color	GREY
Radio Config	AM/FM/CD * Operational
Hi Back Seats	Dual
Pass Seat	Stationary
Exterior Color	WHITE
Bumper	Painted
External Visor	No

Drive Options
Cruise Control, Power Steering

Inspection Photos



Notes / Description

--



National Inspection Services
: 136991 on 04/10/2017
VIN: 1HTMKAAN04H604461 Unit: 1277

Housby Auctions Marcus Bowersox
4747 NE 14th St Des Moines, IA 50313 USA
(515) 299-6265

2004 INTERNATIONAL 4400 PHOTOS







National Inspection Services

: 136991 on 04/10/2017

VIN: 1HTMKAAN04H604461 Unit: 1277

Housby Auctions Marcus Bowersox

4747 NE 14th St Des Moines, IA 50313 USA

(515) 299-6265

2004 INTERNATIONAL 4400

Brakes	
19	20
24	23
Additional Brake Detail	

Tires			
Front 11R22.5	Continental 9 / 32 Steel	Continental 7 / 32 Steel	Rear 11R22.5
General 11 / 32 Steel	General 13 / 32 Steel	General 13 / 32 Steel	Continental 9 / 32 Steel
Additional Tire Detail			

General Observations
Oil Milky? No Oil Leaks? Yes Water Leaks? No Oil in Coolant? Yes Clutch Play? Ok Starts? Yes Drives? Yes
Safety / Operational Observations
Lights Work? Yes - All Wipers Work? Yes Gauges Work? Yes - All City Horn Works? No Air Horn Works? NA
Additional Observation Detail
Evidence of seepage at pan / rear seal and left side of block. Dark residue noted inside coolant reservoir. Oil filler tube loose. City horn did not function. Equipment still in cargo box.

Wear and Tear Items		
Lift Gate	Advancing corrosion noted.	NA
Bumper	Paint flaking, corrosion noted, bent.	NA
Roll-up Door	Missing top section. Latch does not secure.	NA
Fuel Tank	Cap missing, paint flaking.	NA
Mirror	P/S convex mirror loose on pole.	NA
Head Liner	Drooping.	NA
Hood	Fiberglass damaged noted above both front wheels.	NA
Seat	Seats worn and ripped.	NA
Doors	Interior pulls damaged.	NA
Fault	Engine fault 254-8, ABS fault 790-4, 790-5, 790-10 noted on ECM.	NA
Tires	3 below terms	NA
Paint	Various chips and scratches	NA
Total Estimate		NA

Condition report only. National Inspection Services does not guarantee mechanical reliability.

© 2017 National Inspection Services (NIS)
6501 E. Commerce Ave. Suite 135 Kansas City, MO 64120
www.nationalinspect.com