



Housby Auctions (Marcus Bowersox)  
4747 NE 14th St, Des Moines, IA 50313 USA  
(515) 299-6265

VIN: 1FVMAQL94DN31270  
Stock #: 56.0196

## 2004 FREIGHTLINER FLD120SD WITH REAR MIXER

SPECIFICATIONS	
MILEAGE	248,370 / 155,141 (ECM)
ENGINE HOURS	11,809
ENGINE	CAT C11 333 HP
ENG BRAKE	YES
ENG SERIAL	KCA00738
FUEL / TANKS	DIESEL - 1 ALUM 80 GAL TOTAL
TRANSMISSION	ALLISON HD4560 6 SPD AUTO
DRIVE OPTS	POWER STEERING, CRUISE
REAR END	MERITOR 6.14
AXLE TYPE	TRI - F 13,200 LB / R 20,000 LB
GVWR	53,200
FRAME	STEEL
SUSPENSION	WALKING BEAM
WHEELBASE	248"
TIRE SIZE	F 425/65R22.5 / R 11R24.5
WHEELS	F ALUMINUM / R STEEL
AIR COND	YES, OPERATIONAL
INTERIOR COLOR	GREY
RADIO	AM/FM / CD, OPERATIONAL
MIRRORS	DUAL POWER
HIGH BACK SEATS	DRIVER SIDE ONLY
PASSENGER SEAT	STATIONARY
EXTERIOR COLOR	RED
BUMPER	PAINTED
EXTERIOR OPTS	HEATED MIRRORS



NOTES / DESCRIPTION
TOOL BOX 32X16X16

BRAKES	
LEFT REAR 1	RIGHT REAR 1
LEFT REAR 2	RIGHT REAR 2
LEFT REAR 3	RIGHT REAR 3

TIRES & WHEELS			
LEFT FRONT	RIGHT FRONT	LEFT OUTER 1	RIGHT OUTER 1
11 / 32 BRIDGESTONE ALUMINUM	12 / 32 BRIDGESTONE ALUMINUM	-	-
18 / 32 BRIDGESTONE ALUMINUM	-	-	-
LEFT OUTER 2	LEFT INNER 2	RIGHT INNER 2	RIGHT OUTER 2
12 / 32 BRIDGESTONE STEEL	13 / 32 BRIDGESTONE STEEL	17 / 32 TOYO STEEL	14 / 32 TOYO STEEL
LEFT OUTER 3	LEFT INNER 3	RIGHT INNER 3	RIGHT OUTER 3
9 / 32 BRIDGESTONE STEEL	9 / 32 BRIDGESTONE STEEL	7 / 32 BRIDGESTONE STEEL	9 / 32 BRIDGESTONE STEEL
FRONT TIRES: 425/65R22.5		REAR TIRES: 11R24.5	

ADDITIONAL TIRE DETAIL
COVERED

GENERAL OBSERVATIONS			
OIL MILKY?	NO	LIGHTS WORK?	YES - ALL
OIL LEAKS?	SEE NOTES	WIPERS WORK?	YES
WATER LEAKS?	NO	GAUGES WORK?	SEE NOTES

OIL IN COOLANT?	NO
CLUTCH PLAY?	NA
STARTS?	YES
DRIVES	YES

AIR HORN WORKS?	YES
CITY HORN WORKS?	YES

#### ADDITIONAL OBSERVATIONS


FUEL GAUGE SHOWS EMPTY, TACH DOES NOT ZERO WHEN ENGINE IS OFF, LEFT TURN INDICATOR ON DASH DOES NOT ILLUMINATE. RESIDUE NOTED AT BOTTOM OF BLOCK / OIL PAN.

#### WEAR & TEAR DETAIL

DIAGNOSTICS	ENGINE 524287-31
CAB	SMALL DENTS BEHIND DRIVERS DOOR, PAINT BUBBLED ON PASSENGER DOOR
REAR FENDERS	PAINT CHIPPED
DASH	DAMAGED PASSENGER SIDE
TIRES	4 BELOW 10/32'S
BUMPER	FRONT AND REAR BENT
PAINT	VARIOUS CHIPS, SCRATCHES AND PEELING
MUD FLAPS	DAMAGED / MISSING
HEADLINER	LOOSE
TRANSMISSION	RESIDUE NOTED
DRUM	DENTED

#### REPORT VIDEOS

#### REPORT PHOTOS







Condition report only. National Inspection Services does not guarantee mechanical reliability.

© National Inspection Services  
101 W. Shrader St. Liberty, MO 64068  
[www.nationalinspect.com](http://www.nationalinspect.com)