



National Inspection Services

Report: 237872

06/17/2023

Housby Auctions (Marcus Bowersox)
4747 NE 14th St, Des Moines, IA 50313 USA
(515) 299-6265

VIN: 1HTWGAZT18J647136
Stock #: 384

2008 INTERNATIONAL 7400

SPECIFICATIONS	
ENGINE	INTERNATIONAL MAXXFORCE 9 300 HP
ENG SERIAL	2U3026137
FUEL / TANKS	DIESEL - 1 STEEL 50 GAL TOTAL
TRANSMISSION	ALLISON HD4560 6 SPD AUTO
DRIVE OPTS	POWER STEERING, CRUISE
REAR END	MERITOR 5.57
AXLE TYPE	TANDEM - F 16,000 LB / R 40,000 LB
GVWR	56,000
FRAME	STEEL
SUSPENSION	WALKING BEAM
TIRE SIZE	315/80R22.5
WHEELS	F ALUMINUM / R ALUM/STEEL
AIR COND	YES, NOT OPERATIONAL
INTERIOR COLOR	GRAY
MIRRORS	DUAL POWER
HIGH BACK SEATS	DRIVER SIDE ONLY
PASSENGER SEAT	STATIONARY
EXTERIOR COLOR	GRAY
BUMPER	PAINTED



BRAKES	
LEFT FRONT	RIGHT FRONT
23	23
LEFT REAR 1	RIGHT REAR 1
18	20
LEFT REAR 2	RIGHT REAR 2
17	21

TIRES & WHEELS			
LEFT FRONT		RIGHT FRONT	
13 / 32 BRIDGESTONE ALUMINUM		17 / 32 BRIDGESTONE ALUMINUM	
LEFT OUTER 1	LEFT INNER 1	RIGHT INNER 1	RIGHT OUTER 1
23 / 32 BRIDGESTONE ALUMINUM	23 / 32 BRIDGESTONE STEEL	20 / 32 BRIDGESTONE STEEL	20 / 32 BRIDGESTONE ALUMINUM
LEFT OUTER 2	LEFT INNER 2	RIGHT INNER 2	RIGHT OUTER 2
17 / 32 YOKOHAMA ALUMINUM	17 / 32 YOKOHAMA STEEL	17 / 32 CONTINENTAL STEEL	17 / 32 CONTINENTAL ALUMINUM
FRONT TIRES: 315/80R22.5		REAR TIRES: 315/80R22.5	

GENERAL OBSERVATIONS

OIL MILKY?	NO	LIGHTS WORK?	SEE NOTES
OIL LEAKS?	YES	WIPERS WORK?	SEE NOTES
WATER LEAKS?	NO	GAUGES WORK?	SEE NOTES
OIL IN COOLANT?	NO	AIR HORN WORKS?	SEE NOTES
CLUTCH PLAY?	NA	CITY HORN WORKS?	SEE NOTES
STARTS?	SEE NOTES		
DRIVES	SEE NOTES		

ADDITIONAL OBSERVATIONS

BATTERIES WERE UNHOOKED. PTO UNHOOKED. TRANSMISSION IS FAULTY PER CONTACT. BOTH REAR AXLES ARE LEAKING BETWEEN THE DIFFERENTIAL AND THE HOUSING. SURGE TANK IS LEAKING AT LOWER FITTING. OIL LEAKING AT BOTH SIDES AND BOTTOM OF ENGINE / OIL PAN.

WEAR & TEAR DETAIL

DIAGNOSTICS	UNABLE TO RUN DIAGNOSTICS BATTERIES UNHOOKED
DOORS	D/S RUST/DRILL HOLE IN CENTER OF DOOR
	OVERALL DIRTY. P/S FLOOR HAS RUST AND SEAT BRACKETS ARE RUSTED. D/S DOOR PANEL IS CRACKED AND SCUFFED.

INTERIOR	OVERALL DIRTY. P/S FLOOR HAS RUST AND SEAT BRACKETS ARE RUSTED. D/S DOOR PANEL IS CRACKED AND COGLED BEHIND THE ARMREST. SEAM ON D/S SUN VISOR RIPPED.
CAB	RUST ON P/S ROCKER PANEL AREA. D/S FENDER EXTENSION DAMAGED, FIBERGLASS CRACKED IN LOWER CORNER.
REAR BODY	VARIOUS DENTS. D/S REAR CORNER IS BENT . RUST ON D/S REAR FENDER - UPPER REAR CORNER.
REAR LIGHT PANEL	HEAVILY RUSTED ALSO HAS RUST HOLES. BENT AND SHIFTED IN.
HEADLINER	DIRTY AND HAS TEARS AND IS FALLING DOWN
FENDER	D/S BROKEN AT LOWER / REAR
PAINT	VARIOUS CHIPS AND SCRATCHES







Condition report only. National Inspection Services does not guarantee mechanical reliability.

© National Inspection Services
 101 W. Shrader St. Liberty, MO 64068
www.nationalinspect.com