



National Inspection Services
: **141691** on 07/27/2017
VIN: **1HSHXAGR17J424919** Unit: **42618**

Housby Auctions Marcus Bowersox
4747 NE 14th St Des Moines, IA 50313 USA
(515) 299-6265

2007 INTERNATIONAL 8600

8600 Specifications	
Mileage	467,221
Engine Hours	16431
Engine	Cummins ISM 330 HP
Engine Brake	Yes
Fuel	Diesel 2 Alum Tanks 180 Gal. Total
Exhaust	Single
Transmission	Eaton Manual FRO-13210C 10 Spd
Rear	Meritor 3.58
Axles	Tandem 12,000 Front / 40,000 Rear
GVWR (lbs)	52,000
Frame Type	Steel
Suspension	Air Ride
Wheelbase	163"
Tire Size F	11R22.5
Tire Size R	11R22.5
Wheels	Aluminum
5th Wheel	Air Slide
A/C	Yes * Operational
Interior Color	GRAY
Radio Config	AM/FM/CD * Not Operational
Power Mirrors	Dual Power
Hi Back Seats	Dual
Pass Seat	Stationary
Exterior Color	RED
Bumper	Painted
Heated Mirrors	No
Fairings	None
External Visor	Yes

Drive Options
Overdrive, Cruise Control, Power Steering

Inspection Photos



Notes / Description

--



National Inspection Services

: 141691 on 07/27/2017

VIN: 1HSHXAGR17J424919 Unit: 42618

Housby Auctions Marcus Bowersox

4747 NE 14th St Des Moines, IA 50313 USA

(515) 299-6265

2007 INTERNATIONAL 8600 PHOTOS







National Inspection Services

: 141691 on 07/27/2017
VIN: 1HSHXAGR17J424919 Unit: 42618

Housby Auctions Marcus Bowersox

4747 NE 14th St Des Moines, IA 50313 USA
(515) 299-6265

2007 INTERNATIONAL 8600

Brakes	
16	19
23	22
20	19
Additional Brake Detail	

Tires			
Front 11R22.5	Bridgestone 17 / 32 Aluminum	Bridgestone 17 / 32 Aluminum	Rear 11R22.5
Bridgestone 08 / 32 Aluminum	Bridgestone 09 / 32 Aluminum	Bridgestone 10 / 32 Aluminum	Goodyear 15 / 32 Aluminum
Bridgestone 16 / 32 Aluminum	Bridgestone 18 / 32 Aluminum	Goodyear 15 / 32 Aluminum	Bridgestone 21 / 32 Aluminum
Additional Tire Detail			

General Observations	
Oil Milky? No Oil Leaks? No Water Leaks? No Oil in Coolant? No Clutch Play? Ok Starts? Yes Drives? Yes	
Safety / Operational Observations	
Lights Work? Yes - All Wipers Work? Yes Gauges Work? Yes - All City Horn Works? Yes Air Horn Works? Yes	
Additional Observation Detail	
Minor residue noted at right side of valve cover.	

Wear and Tear Items		
Bumper	both corners pushed in	NA
Cab	left side, rear lower corner dented	NA
Step	left side drivers bottom step damaged	NA
Step	left side catwalk access bottom step damaged	NA
Fender	right side fiberglass cracked	NA
Seat	drivers side torn	NA
Mirrors	adjustment doesn't work	NA
Tires	2 below terms	NA
Clutch	missing rubber pad	NA
Fenders	drivers side cracked at half fender, passenger side missing	NA
Headlights	lenses dulled	NA

Paint	various chips and scratches	NA
Total Estimate		NA

Condition report only. National Inspection Services does not guarantee mechanical reliability.

© 2017 National Inspection Services (NIS)
6501 E. Commerce Ave. Suite 135 Kansas City, MO 64120
www.nationalinspect.com