



National Inspection Services

Report: 339674
08/06/2026

Housby Auctions (Ashly Healey)
4747 NE 14th St, Des Moines, IA 50313 USA
(515) 299-6265

VIN: 1FVHCYDJ07HY41019
Stock #: MK0910

2007 FREIGHTLINER M2 106 MD

SPECIFICATIONS	
MILEAGE	224,516
ENGINE HOURS	9,430
ENGINE	MERCEDES MBE900 7.2L 330 HP
ENG BRAKE	YES
ENG SERIAL	0906600313
FUEL / TANKS	DIESEL - 2 STEEL 160 GAL TOTAL
TRANSMISSION	ALLISON 3000 RDS 6 SPD AUTO
DRIVE OPTS	POWER STEERING, OVERDRIVE, CRUISE
REAR END	MERITOR 5.86
AXLE TYPE	TRI - F 14,600 LB / R 40,000 LB
GVWR	54,600
FRAME	STEEL
SUSPENSION	SPRING
WHEELBASE	280"
TIRE SIZE	11R22.5
WHEELS	F STEEL / R STEEL
EXTERIOR L (FT)	25.0
AIR COND	YES
INTERIOR COLOR	GREY/BLACK
RADIO	AM/FM, OPERATIONAL
HIGH BACK SEATS	DUAL
PASSENGER SEAT	STATIONARY
EXTERIOR COLOR	YELLOW
BUMPER	PAINTED
EXTERIOR OPTS	HEATED MIRRORS



BRAKES	
LEFT FRONT	RIGHT FRONT
COVERED	COVERED
LEFT REAR 1	RIGHT REAR 1
24	24
LEFT REAR 2	RIGHT REAR 2
COVERED	COVERED
LEFT REAR 3	RIGHT REAR 3
COVERED	COVERED

TIRES & WHEELS			
LEFT FRONT		RIGHT FRONT	
9 / 32 GENERAL STEEL		10 / 32 GENERAL STEEL	
LEFT OUTER 1	LEFT INNER 1	RIGHT INNER 1	RIGHT OUTER 1
18 / 32 FIRESTONE STEEL	- - -	- - -	18 / 32 FIRESTONE STEEL
LEFT OUTER 2	LEFT INNER 2	RIGHT INNER 2	RIGHT OUTER 2
18 / 32 GENERAL STEEL	18 / 32 GENERAL STEEL	15 / 32 GENERAL STEEL	15 / 32 GENERAL STEEL
LEFT OUTER 3	LEFT INNER 3	RIGHT INNER 3	RIGHT OUTER 3
18 / 32 GENERAL STEEL	18 / 32 GENERAL STEEL	18 / 32 GENERAL STEEL	18 / 32 GENERAL STEEL
FRONT TIRES: 11R22.5		REAR TIRES: 11R22.5	

ADDITIONAL TIRE DETAIL	
RECAPS	

GENERAL OBSERVATIONS

OIL MILKY?	NO	LIGHTS WORK?	YES - ALL
OIL LEAKS?	YES	WIPERS WORK?	YES

WATER LEAKS?	NO	GAUGES WORK?	SEE NOTES
OIL IN COOLANT?	NO	AIR HORN WORKS?	NA
CLUTCH PLAY?	NA	CITY HORN WORKS?	YES
STARTS?	NO		
DRIVES	NO		

WEAR & TEAR DETAIL	
DIAGNOSTICS	NO POWER AT J1939 UNABLE TO SCAN. CRANKS BUT WILL NOT START.
HEADLINER	LOOSE AND STAINED
STEPS	LEFT AND RIGHT SIDES DAMAGED
GRILLE	DAMAGED ON P/S
HOOD	DAMAGED BETWEEN HEADLIGHT AND GRILLE
SEATS	STAINED, WORN, AND TORN.
DASH	HELD TOGETHER WITH TAPE ON P/S
FLOORING	MAT TAPED TOGETHER ON THE D/S
DRIVESHAFT	REMOVED AT REAR AXLE

REPORT PHOTOS					
1A	1B	1C	1D	1E	1F
2A	2B	2C	2D	2E	2F
3A	3B	3C	3D	3E	3F
4A	4B	4C	4D	4E	4F
5A	5B	5C	5D	5E	5F
6A	6B	6C	6D	6E	6F
7A	7B	7C	7D	7E	7F





Condition report only. National Inspection Services does not guarantee mechanical reliability.

© National Inspection Services
239 W. Mill St. Liberty, MO 64068
www.nationalinspect.com