



Housby Auctions (Ashly Healey)
4747 NE 14th St, Des Moines, IA 50313 USA
(515) 299-6265

VIN: 2FWJA3DE87AY55679
Stock #: AZTK10

2007 STERLING A9500

SPECIFICATIONS	
MILEAGE	929,963 / 393,448 (ECM)
ENGINE HOURS	14,168
ENGINE	CAT C13 12.5L 450 HP
ENG BRAKE	YES
ENG SERIAL	RCB84164
FUEL / TANKS	DIESEL - 2 ALUM 240 GAL TOTAL
EXHAUST	SINGLE
TRANSMISSION	EATON-FULLER FRW-15210B 10 SPD MANUAL
DRIVE OPTS	POWER STEERING, CRUISE
AXLE TYPE	TANDEM - F 12,000 LB / R 20,000 LB
GVWR	52,000
FRAME	STEEL
SUSPENSION	AIR RIDE
TIRE SIZE	11R 22.5
WHEELS	F ALUMINUM / R ALUMINUM
WHEEL 5TH	AIR SLIDE
AIR COND	YES
INTERIOR COLOR	BROWN
MIRRORS	DUAL POWER
HIGH BACK SEATS	DUAL
PASSENGER SEAT	STATIONARY
EXTERIOR COLOR	WHITE
BUMPER	PAINTED
EXTERIOR OPTS	HEATED MIRRORS



NOTES / DESCRIPTION
OIL PAN LEAKING POWER STEERING LEAKING CHECK ENGINE LIGHT FLASHING ABS LIGHT LAMINATED ENGINE MAKE DIFFERENT THEN ECM READING

BRAKES	
LEFT FRONT	RIGHT FRONT
16	16
LEFT REAR 1	RIGHT REAR 1
24	24
LEFT REAR 2	RIGHT REAR 2
26	26

TIRES & WHEELS			
LEFT FRONT		RIGHT FRONT	
15 / 32 ALUMINUM		16 / 32 ALUMINUM	
LEFT OUTER 1	LEFT INNER 1	RIGHT INNER 1	RIGHT OUTER 1
10 / 32 FIRESTONE ALUMINUM	12 / 32 FIRESTONE ALUMINUM	12 / 32 - ALUMINUM	8 / 32 BRIDGESTONE ALUMINUM
LEFT OUTER 2	LEFT INNER 2	RIGHT INNER 2	RIGHT OUTER 2
6 / 32 FIRESTONE ALUMINUM	7 / 32 FIRESTONE ALUMINUM	11 / 32 - ALUMINUM	12 / 32 - ALUMINUM
FRONT TIRES: 11R 22.5		REAR TIRES: 11R 22.5	

GENERAL OBSERVATIONS

OIL MILKY?	NO	LIGHTS WORK?	YES - ALL
OIL LEAKS?	SEE NOTES	WIPERS WORK?	YES
WATER LEAKS?	NO	GAUGES WORK?	YES - ALL
OIL IN COOLANT?	NO	AIR HORN WORKS?	YES
CLUTCH PLAY?	NEEDS ATTENTION	CITY HORN WORKS?	YES
STARTS?	YES		
DRIVES	YES		

WEAR & TEAR DETAIL

WARNINGS	CHECK ENGINE AND ABS LIGHTS ARE ON.
LEFT DOOR	PAINT CHIPS, SCRAPE, SCRATCHES, TAPE RESIDUE OUTSIDE HANDLE BROKEN (INOPERABLE)

LEFT FENDER	SCRAPES, PAINT CHIPS, PAINT FADE
BUMPER	SCRATCHES, PAINT CHIPS, MISALIGNED
HOOD	PAINT FADE PAINT CHIPS
RIGHT DOOR	PAINT CHIPS, SCRATCHES, TAPE RESIDUE
RIGHT STEP	BOTTOM STEP DENTED/ LOOSE TOP STEP DENTED
ROOF TAIL FAIRING	MISSING
INTERIOR	PANELS BROKEN, REMOVED DASHBOARD DAMAGED WIRING EXPOSED INTERIOR SOILED SEATS STAINED

REPORT VIDEOS

REPORT PHOTOS







Condition report only. National Inspection Services does not guarantee mechanical reliability.

© National Inspection Services
101 W. Shrader St. Liberty, MO 64068
www.nationalinspect.com