



## National Inspection Services

Report: 242605

08/11/2023

**Housby Auctions (Marcus Bowersox)**  
4747 NE 14th St, Des Moines, IA 50313 USA  
(515) 299-6265

VIN: 1GBT8C4C26F426553  
Stock #: AR1929

### 2006 CHEVROLET C8500

| SPECIFICATIONS       |                                    |
|----------------------|------------------------------------|
| ENGINE               | CAT C7 7.2L 300 HP                 |
| ENG SERIAL           | EAX30478                           |
| FUEL / TANKS         | DIESEL - 2 STEEL 100 GAL TOTAL     |
| TRANSMISSION         | ALLISON 3500 RDS 6 SPD AUTO        |
| DRIVE OPTS           | POWER STEERING, CRUISE             |
| REAR END             | 6.17                               |
| AXLE TYPE            | TANDEM - F 12,000 LB / R 40,000 LB |
| GVWR                 | 52,000                             |
| FRAME                | STEEL                              |
| SUSPENSION           | WALKING BEAM                       |
| WHEELBASE            | 272"                               |
| TIRE SIZE            | 11R 22.5                           |
| WHEELS               | F STEEL / R STEEL                  |
| AIR COND             | YES, NOT OPERATIONAL               |
| INTERIOR COLOR       | GRAY                               |
| RADIO                | AM/FM, NOT OPERATIONAL             |
| HIGH BACK SEATS      | DUAL                               |
| PASSENGER SEAT       | STATIONARY                         |
| EXTERIOR COLOR       | WHITE                              |
| BUMPER               | PAINTED                            |
| COLLISION AVOIDANCE? | NO                                 |



| BRAKES             |                     |
|--------------------|---------------------|
| <b>LEFT FRONT</b>  | <b>RIGHT FRONT</b>  |
| COVERED            | COVERED             |
| <b>LEFT REAR 1</b> | <b>RIGHT REAR 1</b> |
| COVERED            | COVERED             |
| <b>LEFT REAR 2</b> | <b>RIGHT REAR 2</b> |
| COVERED            | COVERED             |

| TIRES & WHEELS                 |                              |                                 |                       |
|--------------------------------|------------------------------|---------------------------------|-----------------------|
| <b>LEFT FRONT</b>              |                              | <b>RIGHT FRONT</b>              |                       |
| 8 / 32<br>BRIDGESTONE<br>STEEL |                              | 10 / 32<br>BRIDGESTONE<br>STEEL |                       |
| <b>LEFT OUTER 1</b>            | <b>LEFT INNER 1</b>          | <b>RIGHT INNER 1</b>            | <b>RIGHT OUTER 1</b>  |
| 11 / 32<br>YOKOHAMA<br>STEEL   | 21 / 32<br>YOKOHAMA<br>STEEL | 20 / 32<br>-<br>STEEL           | 20 / 32<br>-<br>STEEL |
| <b>LEFT OUTER 2</b>            | <b>LEFT INNER 2</b>          | <b>RIGHT INNER 2</b>            | <b>RIGHT OUTER 2</b>  |
| 19 / 32<br>-<br>STEEL          | 20 / 32<br>-<br>STEEL        | 19 / 32<br>-<br>STEEL           | 20 / 32<br>-<br>STEEL |
| FRONT TIRES: 11R 22.5          |                              | REAR TIRES: 11R 22.5            |                       |

### GENERAL OBSERVATIONS

|                        |     |                         |    |
|------------------------|-----|-------------------------|----|
| <b>OIL MILKY?</b>      | NO  | <b>LIGHTS WORK?</b>     | NA |
| <b>OIL LEAKS?</b>      | YES | <b>WIPERS WORK?</b>     | NA |
| <b>WATER LEAKS?</b>    | NO  | <b>GAUGES WORK?</b>     | NA |
| <b>OIL IN COOLANT?</b> | NO  | <b>AIR HORN WORKS?</b>  | NA |
| <b>CLUTCH PLAY?</b>    | OK  | <b>CITY HORN WORKS?</b> | NA |
| <b>STARTS?</b>         | NO  |                         |    |
| <b>DRIVES</b>          | NO  |                         |    |

### ADDITIONAL OBSERVATIONS

MISSING BATTERIES. UNABLE TO OPERATE. OIL LEAKING AT ENGINE AND OIL PAN

### WEAR & TEAR DETAIL

|             |                                                                |
|-------------|----------------------------------------------------------------|
| <b>RUST</b> | CAB, BED, FRAME, WHEELS, EXHAUST, FUEL TANK, STEPS, SUSPENSION |
|-------------|----------------------------------------------------------------|




|                |                                   |
|----------------|-----------------------------------|
| HOOD           | CRACKED ABOVE RIGHT HEADLIGHT     |
| PAINT          | VARIOUS CHIPS                     |
| POWER STEERING | FLUID LEAKING                     |
| CENTER CONSOLE | MISSING LID                       |
| INTERIOR       | SURFACES AND UPHOLSTERY ARE DIRTY |
| TIRES          | 1 MEASURES BELOW 10/32            |

REPORT PHOTOS







Condition report only. National Inspection Services does not guarantee mechanical reliability.

© National Inspection Services



