



## National Inspection Services

# : **117005** on 02/01/2015

VIN: **106372W** Unit: **B4517**

VOCON Marcus Bowersox

4747 NE 14th St Des Moines, IA 50313 USA

(515) 299-6265

## 0000 OTHER TRACKMOBILE

### TRACKMOBILE Specifications

Engine	Diesel engine
Engine Serial	UNKNOWN
Fuel	Diesel
Tire Size F	solid rubber
Tire Size R	solid rubber

### Drive Options

### Notes / Description

This piece of equipment is termed a Trackmobile. It moves RR cars and equipment from side tracks to primary track for positioning purposes. The engine starts and runs but there is NO Way to test the transmission. It's old it is dirty and it has been neglected of maintenance stem to stern. I found NO ID plates of manufactures description.

### Inspection Photos











## National Inspection Services

# : 117005 on 02/01/2015

VIN: 106372W Unit: B4517

VOCON Marcus Bowersox

4747 NE 14th St Des Moines, IA 50313 USA

(515) 299-6265

## 0000 OTHER TRACKMOBILE

Brakes	
Additional Brake Detail	
Solid friction type brakes of unknown origin....non-accessible to this inspection.	

Tires			
Front solid rubber	/ 32	/ 32	Rear solid rubber
Additional Tire Detail			
Four solid rubber tires and four solid steel rail rims			

General Observations	
Oil Milky? No	Oil Leaks? Yes
Water Leaks? No	Oil in Coolant? No
Clutch Play? NA	Starts? Yes
Drives? No	
Safety / Operational Observations	
Lights Work? NA	Wipers Work? Yes
Gauges Work? See Detail	City Horn Works? NA
Air Horn Works? NA	
Additional Observation Detail	
Oil stick is rusted, maybe condensation. Oil has sandy substance and separating oil deposit on stick. Unit does crank and run with no irregular noises. Oil pressure is 20 lbs.at idle and 35 lbs full throttle. Blow by tube is producing smoke. There is an unknown gauge missing in dash.	

### Wear and Tear Items

Engine	Engine needs oil and filter changes	NA
Air filter	Filter needs cleanig or changing.	NA
Electrical	Bare wiring needs insulating or removal	NA
Batteries	Batteries need to be changed or charging system diagnosed.	NA
Machine	Machine needs to be assembled and on RR tracks to be fully accessed.	NA
Seat	Cushion worn/torn needs replaced	NA
Wiper	Blade missing	NA
<b>Total Estimate</b>		<b>NA</b>

Condition report only. National Inspection Services does not guarantee mechanical reliability.

© 2015 National Inspection Services (NIS)  
6501 E. Commerce Ave. Suite 135 Kansas City, MO 64120  
[www.nationalinspect.com](http://www.nationalinspect.com)