





Printable Catalog


| | | |
|--------------------|---|--|
| Title | MARCH 10 12:00 CST | |
| Description | Closing Times TBD | |
| Date | Wed, Mar 10, 2021 | |
| Starts at | 12:00 PM | |
| Address | 4747 NE 14th St, Des Moines, IA 50313 USA | |
| Categories | | |






| | | |
|--------------|--|---|
| Lot # | 1 | |
| Qty | 1 | |
| Title | 2010 MACK MRU613 GARBAGE PACKER |  |
| Des. | STARTED ON SITE - NOT ROAD TESTED. LOW POWER REGEN PROBLEMS. AIR LEAK AT PARKING BRAKE VALVE. Mack MP7, Automatic, Camelback Suspension, 190 WB, 33 Yrd McNeilus Front Loader, Non Steer Tag Axle, Backup Camera, Steel Wheels, 315/80R22.5, PTO, AC, Warning Lights Active. Showing 366,211 Miles; 22,879 Hours. Approximate Measurements: 32.5ft Length, 13ft Height. Location: Hope Mills, NC Serial: 1M2AV02C7AM007224 | |







| | | |
|--------------|---|---|
| Lot # | 2 | |
| Qty | 1 | |
| Title | 2002 CATERPILLAR 928G WHEEL LOADER |  |
| Des. | NO TITLE PER STATE REGULATIONS. NON RUNNER. CAT 3116 170 HP Diesel, Automatic, Enclosed ROPS, 100in Bucket, Steel Wheels, 20.5-25, AC/Heated Cab, Left Rear Tire Flat Off Rim, Rust. Hours Unavailable. Location: Pelham, AL Serial: 6XR03479 | |







| | | |
|--------------|--|---|
| Lot # | 3 | |
| Qty | 1 | |
| Title | 2007 INTERNATIONAL 5600i REAR MIXER |  |
| Des. | STARTED W/ JUMP AND STARTING FLUID, FULL OPERATIONS NOT TESTED. Cummins ISM (Leaks And Blow By Noted), 8 Speed Manual, Hendrickson Suspension, 20 FA, 46 RA, 212 WB, McNeilus Mixer (Gear Box Oil Leak And Chutes Missing), 150 Gallon Side Mount Water Tank, Pusher Axle, Tag Axle, Bridge Axle, Steel Wheels, 11R22.5, Aluminum Fuel Tank, PTO, AC, Warning Lights Illuminated. Showing 205,270 Miles; 1,922 Hours. Location: Duluth, GA Serial: 1HTXHAHT67J415391 | |



| | | |
|--------------|---|---|
| Lot # | 4 | |
| Qty | 1 | |
| Title | 2007 MACK CTP713 CAB & CHASSIS |  |
| Des. | STARTED ON SITE, NOT ROAD TESTED. Mack MP7, T310- 10 Speed, Air Suspension, 257 WB, 234 Cab To Frame End, Aluminum Wheels, 11R22.5; 11R24.5, AC, Dual Aluminum Fuel Tanks. Mileage Pending. Location: Kansas City, MO Serial: 1M2AT04C37M001738 | |







| | | |
|--------------|---|---|
| Lot # | 5 | |
| Qty | 1 | |
| Title | 2010 MACK LEU613 GARBAGE PACKER |  |
| Des. | STARTED ON SITE - NOT ROAD TESTED. DRIVE SHAFT REMOVED W/ TRUCK. Mack MP7, Allison Model 4500 RDS Automatic, Camelback Suspension, 212 WB, 28 Yrd Heil Side Loader, Backup Camera, L/R Steering, Steel Wheels, 315/80R22.5, PTO, AC. Showing 85,675 Miles; 743 Hours. Approximate Measurements: 32.75ft Length, 13ft Height. Location: Hope Mills, NC Serial: 1M2AU04C5AM003821 | |








| | | |
|--------------|---|---|
| Lot # | 6 |  |
| Qty | 1 | |
| Title | 2002 GALBREATH A5-0R-330 ROLLOFF TRAILER | |
| Des. | 36.75ft Length, 100in Width, 34 FA, 34 RA, Center Point Suspension, Single Pusher Axle, Steel Wheels, 275/80R22.5; 225/75R16, Rust. Location: Weatherford, TX Serial: 1G9F137342A157378 | |
| Lot # | 7 |  |
| Qty | 1 | |
| Title | PUSHER AXLE | |
| Des. | NON TITLED UNIT. PULLED FROM 2001 MACK RD690S. Location: Des Moines, IA Serial: 1M2P264C71M033454 | |
| Lot # | 8 |  |
| Qty | 1 | |
| Title | 2007 PETERBILT 357 CAB & CHASSIS | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. CAT C9 335 HP, Eaton Fuller 9LL, Hendrickson Haulmaxx Suspension, 20 FA, 46 RA, 250 WB, Aluminum Wheels, 425/65R22.5; 11R22.5, AC. Showing 246,950 Miles; 18,640 Hours. Location: Commerce, City, CO Serial: 1NPALF0X07D686676 | |
| Lot # | 9 |  |
| Qty | 1 | |
| Title | 2015 JOHN DEERE 326E SKID LOADER | |
| Des. | NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. Tires Heavily Worn/Pitted, Headlight Lenses Cracked, Interior Worn, No SN Tag Located. Showing 6,604 Miles. Location: Doswell, VA Serial: 1T0326EJLFJ284492 | |
| Lot # | 10 |  |
| Qty | 1 | |
| Title | 1990 MACK RD688SX DUMP TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Mack E6-270-4VH, Allison HT750DR Automatic, Camelback Suspension, 18 FA, 29 RA, 180 WB, Steel Dump Body, Dual Steel Fuel Tanks, Steel Wheels, 12R24, PTO, AC, Warning Lights Illuminated, Unable To Locate Body Tag. Showing 73,179 Miles; 9,393 Hours. Approximate Measurements: 24ft Length, 102in Width, 140in Height. Location: Walford, IA Serial: 1M2P232C4LM008502 | |
| Lot # | 11 |  |
| Qty | 1 | |
| Title | 2007 INTERNATIONAL 5600i REAR MIXER | |
| Des. | STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. DRUM THIN AND CRACKED. Cummins ISM (Oil Leaks And Blow By Noted), 8 Speed Manual, Chalmers Suspension, 20 FA, 46 RA, 222 WB, 11 YRD. McNeilus Mixer, 110 Gallon Side Mount Water Tank, Pusher Axle, Tag Axle, Bridge Axle, Alum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Warning Lights Illuminated. Showing 210,528 Miles; 24,941 Hours. Location: Duluth, GA Serial: 1HTXHAHT27J526598 | |
| Lot # | 12 |  |
| Qty | 1 | |
| Title | 2007 MACK CV713 CAB & CHASSIS | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Mack AMI-370 ASET, Mack ITP T310MX 10 Speed, Camelback Suspension, 18 FA, 266 WB, 226in Back Cab To End Frame, Double Frame, Dual Aluminum Fuel Tanks, Steel Wheels, 315/80R22.5, Missing Tail Lights, Damage/Rust. Showing 635,481 Miles; 23,344 Hours. Location: Kansas City, MO Serial: 1M2AG11C57M040457 | |








| | | |
|-------|--|---|
| Lot # | 14 |  |
| Qty | 1 | |
| Title | 2016 JOHN DEERE 624K WHEEL LOADER | |
| Des. | NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. UNIT DOES NOT MOVE UNDER OWN POWER. GRINDING/SQUEALING NOISE FROM ENGINE AREA. Oil Leaks Noted, Interior Worn, Tires Worn, Damage/Rust. Showing 14,407 Hours. Location: North Baltimore, OH Serial: 1DW624KZKGF677152 | |
| Lot # | 16 |  |
| Qty | 1 | |
| Title | 2013 PETERBILT 384 CAB & CHASSIS | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Cummins ISX12 370 HP, Automatic, Air Ride Suspension, 14.6 FA, 40 RA, 226 WB, 239in Back Cab To End Frame, 80 Gallon Aluminum Fuel Tank, Aluminum/Steel Wheels, 315/80R22.5; 11R22.5, AC. Showing 366,103 Miles; 16,197 Hours. Location: Weatherford, TX Serial: 1NPVL79X0DD185518 | |
| Lot # | 17 |  |
| Qty | 1 | |
| Title | 2005 FONTAINE FTW58045SL FLATBED TRAILER | |
| Des. | 45ft Length, 102in Width, Steel Composition, Wood Decking, Sliding Tandems, Under Storage, Moffett Kit, Steel Wheels, 11R24.5, Rust. Location: Lakeland, FL Serial: 13N1452C551525954 | |
| Lot # | 18 |  |
| Qty | 1 | |
| Title | 2004 MACK CV713 DUMP TRUCK | |
| Des. | NON RUNNER. AI-400 ASET, Allison 4560P, Camelback Suspension, 210 WB, 20 FA. Steel Wheels, 425/65R22.5; 11R24.5, 80 Gallon Steel Fuel Tank, PTO, AC. Dash Apart. Mileage Unavailable. Location: Sacramento, CA Serial: 1M2AG11C84M012342 | |
| Lot # | 19 |  |
| Qty | 1 | |
| Title | 2005 INTERNATIONAL 5600i REAR MIXER | |
| Des. | STARTED ON SITE W/ JUMP AND STARTING FLUID, FULL OPERATIONS NOT TESTED. DRUM THIN. AIR LEAK, VERY SLOW TO BUILD AIR PRESSURE. Cummins ISM (Oil Leaks And Blow By Noted), 8 Speed Manual, Chalmers Suspension, 20 FA, 43 RA, 222 WB, 11 YRD. McNeilus Mixer (Mixer Controls Missing), 110 Gallon Side Mount Water Tank, Pusher Axle, Tag Axle, Bridge Axle, Steel Wheels, 11R22.5, PTO, AC, Warning Lights. Showing 205,558 Miles; 17,478 Hours. Location: Duluth, GA Serial: 1HTXHAHT25J000131 | |
| Lot # | 20 |  |
| Qty | 1 | |
| Title | 2005 MACK CV713 CAB & CHASSIS | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Mack AMI-370 ASET, ITP T310M/MLR 10 Speed, Camelback Suspension, 18 FA, 266 WB, 226in Back Cab To End Frame, Double Frame, Dual Aluminum Fuel Tanks, Steel Wheels, 315/80R22.5, PTO, Missing Tail Lights. Showing 298,295 Miles; 38,336 Hours. Location: Kansas City, MO Serial: 1M2AG11CX5M017141 | |







| | | |
|--------------|--|---|
| Lot # | 21 |  |
| Qty | 1 | |
| Title | 2007 MACK MR688S GARBAGE PACKER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. DOES NOT REV UP. CAB WOULD NOT JACK. Mack AI-350 ASET, Allison Model 4560P Automatic, Camelback Suspension, 186 WB, 28 Yrd Heil Front Loader, Non-Steer Tag Axle, Steel Wheels, 315/80R22.5, PTO, AC, Backup Camera, Warning Lights Active, Right Rear Tire Flat, Dead Batteries, VIN Tag Not Located See Frame. Showing 380,674 Miles; 28,759 Hours. Approximate Measurements: 33ft Length, 13ft Height. Location: Henderson, NC Serial: 1M2K189CX7M035368 | |
| Lot # | 22 |  |
| Qty | 1 | |
| Title | 2013 CASE SV250 SKID LOADER | |
| Des. | NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. LESS BUCKET ATTACHMENT. Various Minor Hydraulic Leaks Throughout, Seat Torn, Tires Pitted/Chipped/Poor Condition, Body Damage/Rust. Hours Unavailable. Location: North Baltimore, OH Serial: NCM444842 | |
| Lot # | 24 |  |
| Qty | 1 | |
| Title | 2006 INTERNATIONAL 8600 6X4 CAB & CHASSIS | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. UNIT DOES NOT BUILD AIR. CAT C13 445 HP, 10 Speed Manual, Air Ride Suspension, 12 A, 40 RA, 161 WB, 225in Back Cab To End Frame, Double Frame, Aluminum Fuel Tank, Steel/Aluminum Wheels, 315/80R22.5; 11R22.5, PTO, AC, Check Electrical Warning And ABS Light Illuminated. Showing 666,806 Miles; 28,459 Hours. Location: Weatherford, TX Serial: 1HSHXSBRO6J236776 | |
| Lot # | 25 |  |
| Qty | 1 | |
| Title | 2012 KENWORTH T370 GARBAGE PACKER | |
| Des. | STARTED ON SITE W/ STARTING FLUID - NOT ROAD TESTED. PACKER BODY WORN OUT. Paccar PX8, Automatic, Spring Suspension, 12 FA, 21 RA, 205 WB, 20 Yrd McNeilus Rear Loader, Two Can Tippers, Upper Winch, Steel Wheels, 295/75R22.5; 315/80R22.5, PTO, AC, Warning Lights Active, Damage/Rust. Showing 167,465 Miles; 7,549 Hours. Location: Conyers, GA Serial: 2NKHNN7X6CM308999 | |
| Lot # | 27 |  |
| Qty | 1 | |
| Title | 2007 INTERNATIONAL 5600i REAR MIXER | |
| Des. | CRANKS- WONT START. DRUM THIN. Cummins ISM (Oil Leaks), 8 Speed Manual, Chalmers Suspension, 20 FA, 43 RA, 222 WB, 11 YRD. McNeilus Mixer, 110 YRD. McNeilus Mixer, 110 Gallon Side Mount Water Tank, Pusher Axle, Tag Axle, Bridge Axle, Alum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC. Showing 272,938 Miles; 26,770 Hours. Location:Duluth, GA Serial: 1HTXHAHT27J526537 | |
| Lot # | 28 |  |
| Qty | 1 | |
| Title | 2003 MACK CH613 CAB & CHASSIS | |
| Des. | STARTED ON SITE, NOT ROAD TESTED. Mack E7-427 E-TECH LSR, Fuller FRO15210C, Air Ride Suspension, 12 FA, 20 RA, 173 WB, Steel Wheels, 11R22.5, AC, Dual Aluminum Fuel Tanks. Showing 647,408 Miles; 26,080 Hours. Location: Kansas City, MO Serial: 1M1AA18Y43W153726 | |








| | | |
|--------------|--|---|
| Lot # | 29 |  |
| Qty | 1 | |
| Title | 1982 CATERPILLAR D8L DOZER-CRAWLER | |
| Des. | NO TITLE PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. CAT 3408- 400 HP, 102in Track Width, 166in Track Length, EROPS, Cab Heat/AC. Last Recorded Hours (1.11.13) 12,314. Location: Sacramento, CA Serial: 53Y01434 | |
| Lot # | 31 |  |
| Qty | 1 | |
| Title | PUSHER AXLE | |
| Des. | NON TITLED UNIT. PULLED FROM 2002 MACK RD690S. Location: Des Moines, IA Serial: 1M2P264CX2M033806 | |
| Lot # | 32 |  |
| Qty | 1 | |
| Title | 2004 KENWORTH T800 CAB & CHASSIS | |
| Des. | NON RUNNER. CAT C10- 335 HP, 10 Speed Manual, Chalmers Suspension, 233 WB, Double Frame, 218 Cab To Frame End, Steel Wheels, 11R24.5; 425/65R22.5, L/R Rim Damage- Tire Damaged, PTO, AC. Showing 59,660 Miles; 31,319 Hours. Location: Houston, TX Serial: 1NKDLT0X54J064623 | |
| Lot # | 33 |  |
| Qty | 1 | |
| Title | 2012 FREIGHTLINER M2 106 GARBAGE PACKER | |
| Des. | NON RUNNER. BAD ENGINE. MISSING PARTS INCLUDING: SIDE HOPPER, RADIATOR HOSE, AND LIGHTS. MUFFLER APART. DASH APART. VALVE BODY APART. ELECTRIC PANEL APART. Cummins ISM, Automatic, Spring Suspension, 16 FA, 40 RA, 246 WB, G-S Products Side Loader, L/R Steering, Steel Wheels, 315/80R22.5, PTO, AC, Damage/Rust. Mileage Unavailable. Location: Fairburn, GA Serial: 1FVHCYBS6CHBJ9501 | |
| Lot # | 35 |  |
| Qty | 1 | |
| Title | 2007 INTERNATIONAL 5600i REAR MIXER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. HARD STARTING. ENGINE SKIP. ENGINE BLOW BY. BROKEN HYDRAULIC LINE - HYDRAULIC LEAKS. BAD DRUM, CRACKED. DRUM WILL NOT TURN- LOW HYDRAULIC OIL. MIXER MISSING CONTROLS. Cummins ISM, 8 Speed Manual, Chalmers Suspension, 20 FA, 46 RA, 222 WB, 11 Yrd McNeilus Rear Mixer, 110 Gallon Side Mount Water Tank, Aluminum Fuel Tank, Tag Axle, Bridge Axle, Two Chutes, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Dead Batteries, Warning Lights Active, Oil And Coolant Leaks, Rust. Showing 224,353 Miles; 25,706 Hours. Location: Duluth, GA Serial: 1HTXHAHT27J526603 | |
| Lot # | 36 |  |
| Qty | 1 | |
| Title | 2003 MACK CV713 CAB & CHASSIS | |
| Des. | NON RUNNER. ENGINE DISASSEMBLED. LESS KEYS. LESS HEADLIGHTS. Mack E7-350 E-TECH LSR, Allison Model 4560P Automatic, Camelback Suspension, 18 FA, 266 WB, 8ft Back Cab To End Frame, Double Frame, Engine Brake, Dual 55 Gallon Aluminum Fuel Tanks, Steel Wheels, 315/80R22.5, PTO, Damage/Rust. Mileage Unavailable. Location: Kansas City, MO Serial: 1M2AG11C93M003728 | |








| | | |
|--------------|--|---|
| Lot # | 37 |  |
| Qty | 1 | |
| Title | 2010 FREIGHTLINER M2 106 GARBAGE PACKER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. ENGINE BLOW BY. MISSING LEFT SIDE ACCELERATOR PEDAL. MISSING HYDRAULIC CYLINDER SIDE CAN. Cummins ISC, Automatic, Spring Suspension, 16 FA, 40 RA, 244 WB, G-S Products Side Loader, L/R Steering, Steel Wheels, 315/80R22.5, PTO, AC, Backup Camera, Dead Batteries, Warning Lights Active. Showing 245,491 Miles. Location: Henderson, NC Serial: 1FVHCYBS9ADAU6791 | |
| Lot # | 38 |  |
| Qty | 1 | |
| Title | 2002 VOLVO VNL64T DAY CAB TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Oil Residue Covering Both Lower And Upper Portions Of Engine, Clutch Play Needs Attention, Windshield Cracked, Several Lights Inop/Broken, Torque Arms Bushings Torn, Interior Worn, Minor Damage/Rust. Showing 977,878 Miles. Location: Butler, KY Serial: 4V4NC9GF12N337833 | |
| Lot # | 39 |  |
| Qty | 1 | |
| Title | PUSHER AXLE | |
| Des. | NON TITLED UNIT. PULLED FROM 2004 MACK RD688S. Location: Des Moines, IA Serial: 1M2P296C24M067577 | |
| Lot # | 40 |  |
| Qty | 1 | |
| Title | 2004 KENWORTH T800 CAB & CHASSIS | |
| Des. | NON RUNNER- MISSING: IGNITION, TRANSMISSION AND STARTER. DRIVE SHAFT REMOVED. Cummins ISM 335 HP, Chalmers Suspension, 233 WB, Double Frame, 218 Cab TO Frame End, Steel Wheels, 425/65R22.5; 11R24.5, PTO. Showing 329,225 Miles; 3,636 Hours. Location: Houston, TX Serial: 1NKDL00X14R068927 | |
| Lot # | 41 |  |
| Qty | 1 | |
| Title | 2010 FREIGHTLINER M2 106 GARBAGE PACKER | |
| Des. | NON RUNNER. MISSING: RADIATOR HOSE, EGR LINE, FAN BELT, AND REAR LIGHTS. VALVE BODY APART, ELECTRIC PANEL APART, DASH APART. Cummins ISM, Automatic, Spring Suspension, 13.2 FA, 40 RA, 246 WB, G-S Products Side Loader, L/R Steering, Steel Wheels, 315/80R22.5, PTO, AC, Damage/Rust. Mileage Unavailable. Location: Fairburn, GA Serial: 1FVHCYBS7AHZ90059 | |
| Lot # | 42 |  |
| Qty | 1 | |
| Title | 2006 OSHKOSH S2146 FRONT MIXER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Cummins ISM, Allison Automatic, Air Ride Suspension, 22 FA, 46 RA, 218 WB, 11 Yrd Oshkosh Front Mixer, 150 Gallon Cross Mount Water Tank, Steel Fuel Tank, Aluminum Wheels, 445/65R22.5, PTO, Dead Batteries, Check Engine Light Illuminated, Engine Tag Missing, Rust. Showing 223,387 Miles; 24,965 Hours. Location: Des Moines, IA Serial: 10TDAAC276S087390 | |








| | | |
|--------------|---|---|
| Lot # | 43 |  |
| Qty | 1 | |
| Title | 2007 INTERNATIONAL 5600i REAR MIXER | |
| Des. | NON RUNNER. BAD BATTERY CABLES. BLOW BY. BAD DRUM- THIN AND CRACKED. NO CLUTCH FREE PLAY. Cummins ISM, 8 Speed Manual, Chalmers Suspension, 20 FA, 46 RA, 222 WB, 11 Yrd McNeilus Rear Mixer, 110 Gallon Side Mount Water Tank, Aluminum Fuel Tank, Tag Axle, Bridge Axle, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Engine Oil Leaks, Coolant Leaks. Showing 188,533 Miles; 25,228 Hours. Location: Duluth, GA Serial: 1HTXHAHT27J526553 | |
| Lot # | 44 |  |
| Qty | 1 | |
| Title | 2006 INTERNATIONAL 8600 6X4 CAB & CHASSIS | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Cummins ISM-C, Eaton Fuller, Air Ride Suspension, 12 FA, 40 RA, 210 WB, 210in Back Cab To End Frame, Double Frame, Dual Steel Fuel Tanks, Steel Wheels, 315/80R22.5; 11R22.5, AC, Warning Lights Active. Showing 518,480 Miles; 22,273 Hours. Approximate Measurements: 28.75ft Length, 98in Width, 130in Height. Location: Des Moines, IA Serial: 1HSHXAGR16J246945 | |
| Lot # | 46 |  |
| Qty | 1 | |
| Title | 1994 VOLVO VNL64T DAY CAB TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Frame Damaged At Right Rear Corner, Oil Residue Noted At Lower Portion Of Engine, Warning Lights Active, AC Accessories Removed, Tires Worn, Interior Worn, Identification Tags Faded, Damage/Rust. Showing 589,669 Miles; 45,192 Hours. Location: Starke, FL Serial: 4V1JDBDF6RR828664 | |
| Lot # | 47 |  |
| Qty | 1 | |
| Title | 2009 FREIGHTLINER M2 106 DISTRIBUTOR TRUCK | |
| Des. | NON RUNNER. LESS KEYS. Oil Seepage At Lower Portion Of Engine, Interior Worn, Sprayer Covered In Residue, Minor Damage/Rust. Mileage Unavailable. Location: Wayne, MI Serial: 1FVACYBS99HAC7918 | |
| Lot # | 48 |  |
| Qty | 1 | |
| Title | 2011 KENWORTH T800 CAB & CHASSIS | |
| Des. | STARTED ON SITE W/ JUMP AND STARTING FLUID. CAT C13- 350 HP, 9LL Manual, Chalmers Suspension, 20 FA, 46 RA, 287 WB, Double Frame, Steel Wheels, 315/80R22.5- Rears Singled Out, AC. Showing 251,721 Miles; 40,109 Hours. Location: Houston, TX Serial: 1NKDXUTX2BJ291514 | |
| Lot # | 49 |  |
| Qty | 1 | |
| Title | 2015 AUTOCAR ACX64 GARBAGE PACKER | |
| Des. | NON RUNNER. INTERIOR AND EXTERIOR HEAVILY DAMAGED FROM FIRE, FRAME RAILS BENT. Cummins ISL9, Automatic, Right Steering, PTO, AC, VIN Tag Not Located On Unit. Mileage Unavailable. Location: Fairburn, GA Serial: 5VCACRVFXFH219462 | |
| Lot # | 51 |  |
| Qty | 1 | |
| Title | 2013 SUPER SHOT 250 DIESEL COMPRESSOR MELTER CRACKFILL ASPHALT EQUIP | |
| Des. | NO POWER TO TEST LIGHTS. NO VIN TAG LOCATED ON UNIT. PONY MOTOR STARTED ON SITE- Showing 343 Hours. Tires Worn, Various Minor Damage/Rust. Location: Wayne, MI Serial: 1C9SC1225D1418097 | |








| | | |
|--------------|--|---|
| Lot # | 52 |  |
| Qty | 1 | |
| Title | 1996 MACK CH613 CAB & CHASSIS | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Mack EM7-300, Eaton Fuller TX14607B 7 Speed, Camelback Suspension, 214 WB, 205in Back Cab To End Frame, Double Frame, Dual Aluminum Fuel Tanks, Steel Wheels, 315/50R22.5; 11R22.5, AC. Showing 154,616 Miles; 31,654 Hours. Approximate Measurements: 29ft Length, 98in Width, 125in Height. Location: Des Moines, IA Serial: 1M1AA12Y8TW069532 | |
| Lot # | 54 |  |
| Qty | 1 | |
| Title | 1999 OTTAWA YARD DOG | |
| Des. | NON RUNNER, BAD ENGINE. Cummins ISB, Automatic, Solid Suspension, 101 WB, Hydraulic Lift Fifth Wheel, Wet Kit, Steel Fuel Tank, Steel Wheels, 11R22.5, PTO, No Speedometer. Showing 27,247 Hours. Location: Thomaston, GA Serial: 78432 | |
| Lot # | 55 |  |
| Qty | 1 | |
| Title | 2013 RAM 1500 CREW CAB PICKUP TRUCK | |
| Des. | STARTED ON SITE, NOT ROAD TESTED. DEAD BATTERY. Hemi 5.7L Gas V8 (ENGINE TICKS), Automatic, Spring Suspension, 3.7 FA, 3.7 RA, 138 WB, Aluminum Wheels, 265/70R17, AC, PW, PL, PM. Showing 249,411 Miles. Location: Des Moines, IA Serial: 1C6RR6GT3DS692997 | |
| Lot # | 56 |  |
| Qty | 1 | |
| Title | 2014 PETERBILT 365 CAB & CHASSIS | |
| Des. | NON RUNNER. FRONT END DAMAGES/COMPONENTS MISSING; INCLUDING RADIATOR- SEE PHOTOS. TRANSMISSION BELL HOUSING CRACKED. COMPONENTS MISSING. BRAKE CHAMBERS MISSING/APART, COMPONENTS MISSING. DASH APART- COMPONENTS MISSING. Cummins ISX12G 350 HP CNG Engine, Air Ride Suspension, 20 FA, 46 RA, 264 WB, 244 Cab To Frame End, Aluminum Wheels, 315/80R2235- Rears Singled Out. Location: Houston, TX Serial: 1NPSXHEX0ED244538 | |
| Lot # | 57 |  |
| Qty | 1 | |
| Title | 2015 AUTOCAR ACX64 GARBAGE PACKER | |
| Des. | NON RUNNER. CAB HEAVILY DAMAGED FROM FIRE. Cummins ISL9, Hendrickson Suspension, 186 WB, 28 Yrd Heil Front Loader, L/R Steering, Steerable Tag Axle, Steel Wheels, 315/80R22.5, VIN Tag Not Located, Damage/Rust. Mileage Unavailable. Location: Americus, GA Serial: 5VCACDVF1FH219823 | |
| Lot # | 58 |  |
| Qty | 1 | |
| Title | 2006 TEREX FDM FRONT MIXER | |
| Des. | STARTED ON SITE, FULL OPERATIONS NOT TESTED. Cummins ISM (Leak Noted) Automatic, Air Ride Suspension, 22 FA, 40 RA, 201 WB, 11 YRD. Terex Front Mixer, 150 Gallon Cross Mount Water Tank, Tag Axle, Aluminum Wheels, 445/65R22.5, Aluminum Fuel Tank, PTO, AC, Transfer Case Leak. Mileage/Hours Unavailable- Dash Inop. Location: Des Moines, IA Serial: 5DG8AU4T260011181 | |
| Lot # | 59 |  |
| Qty | 1 | |
| Title | 2013 KMI KM 4-40 INFARED ASPHALT RECYCLER ASPHALT EQUIP | |
| Des. | RUNNING CONDITION UNKNOWN. DEAD BATTERIES. NO POWER TO TEST LIGHTS. Solar Panel Cracked, Nose Bent, Tires Weather Cracked. Showing 230 Hours. Location: Wayne, MI Serial: 1K9BU0910DN246068 | |

| | | |
|--------------|--|---|
| Lot # | 60 |  |
| Qty | 1 | |
| Title | 2003 FREIGHTLINER COLUMBIA CAB & CHASSIS | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Detroit Diesel 60 12.7L, 10 Speed Manual, Air Ride Suspension, 12 FA, 40 RA, 233 WB, 212in Back Cab To End Frame, Double Frame, Dual 120 Gallon Aluminum Fuel Tanks, Steel Wheels, 315/80R22.5; 11R22.5, PTO, AC, Dead Batteries, Damage To Front Bumper. Showing 689,348 Miles; 33,090 Hours. Approximate Measurements: 27.75ft Length, 98in Width, 120in Height. Location: Des Moines, IA Serial: 1FUJA6CG03LK66126 | |
| Lot # | 62 |  |
| Qty | 1 | |
| Title | 1997 UTILITY VS2R REEFER TRAILER | |
| Des. | REEFER UNIT HAD DEAD BATTERIES. Thermo King SB-III SR+ Reefer, Hours Unavailable. Right Front Axle Cap Busted- Possible Bearing Damage, Reefer Unit Missing Doors, Rear Doors Difficult To Operate, Various Body Damage/Rust. Location: Springdale, AR Serial: 1UYVS2537VU940523 | |
| Lot # | 63 |  |
| Qty | 1 | |
| Title | 2005 INTERNATIONAL 5600i CAB & CHASSIS | |
| Des. | NON RUNNER. TRANSMISSION CONTROLS MISSING. BOTH STEERING BOXES MISSING. DRIVE SHAFT REMOVED. Cummins ISM, Automatic, Hendrickson Suspension, 212 WB, 229in Back Cab To End Frame, Aluminum Fuel Tank, Aluminum Wheels, 425/65R22.5, PTO, AC, No Data Link Warning Message, Dash Parts Hanging - See Photos, Rust. Mileage Unavailable. Location: Houston, TX Serial: 1HTXHAHT25J128983 | |
| Lot # | 64 |  |
| Qty | 1 | |
| Title | 2008 DODGE RAM 2500 PICKUP TRUCK | |
| Des. | STARTED ON SITE W/ JUMP- NOT ROAD TESTED. Dodge Hemi 5.7L Gas, Automatic, Spring Suspension, 4.41 FA, 6 RA, 140 WB, 8.5ft Box, Steel Wheels, 245/70R17, AC, PW, PL, Dead Batteries, Check Engine Light Active. Showing 109,200 Miles. Location: Des Moines, IA Serial: 3D7KR26D68G186225 | |
| Lot # | 65 |  |
| Qty | 1 | |
| Title | 2007 MACK MR688S GARBAGE PACKER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Mack AI-350 ASET, Allison Model 4500RDS Automatic, Camelback Suspension, 20 FA, 44 RA, 210 WB, 28 Yrd Heil Front Loader, Steel Fuel Tank, Double Frame, Steel Wheels, 315/80R22.5, AC, Damage/Rust. Showing 388,817 Miles; 37,413 Hours. Location: Bennett, CO Serial: 1M2K189C37M036197 | |
| Lot # | 66 |  |
| Qty | 1 | |
| Title | 2006 MACK CV713 CAB & CHASSIS | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Mack AI-375A ASET, Allison Model 4500RDS Automatic, Camelback Suspension, 18 FA, 46 RA, 230 WB, 198in Back Cab To End Frame, Dual 81 Gallon Steel Fuel Tanks, Spoke/Steel Wheels, 315/80R22.5; 11R22.5, PTO, AC, Oil Seepage Noted, Warning Lights Active. Showing 254,281 Miles; 33,151 Hours. Location: Des Moines, IA Serial: 1M2AG11C96M043344 | |

| | | |
|--------------|---|---|
| Lot # | 69 |  |
| Qty | 1 | |
| Title | 2005 INTERNATIONAL 5600I CAB & CHASSIS | |
| Des. | NON RUNNER. Cummins ISM, Automatic, Hendrickson Suspension, 212 WB, 230 Cab To Frame End, Steel Wheels, 425/65R22.5; 315/80R22.5; 275/80R22.5; 11R24.5, Aluminum Fuel Tank, PTO, AC, Dash Inop. Mileage Unavailable. Location: Houston, TX Serial: 1HTXHAHTX5J039520 | |
| Lot # | 71 |  |
| Qty | 1 | |
| Title | 2003 CHEVROLET SILVERADO K2500HD PICKUP TRUCK | |
| Des. | STARTED ON SITE, NOT ROAD TESTED. TRUCK IN LIMP MODE. DASH INOP. 6.0L V8, Auto, Spring Suspension, 133 WB, Aluminum Wheels, 265/75R6, AC, PW, PL, PM, Check Engine Light Illuminated. Mileage Unavailable. Location: Des Moines, IA Serial: 1GCHK24U63E301305 | |
| Lot # | 72 |  |
| Qty | 1 | |
| Title | 2004 MACK RD688S CAB & CHASSIS | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. STEERING DIFFICULT. Mack AI-300A ASET, Allison Model HD4560P Automatic, Camelback Suspension, 18 FA, 240 WB, 198in Back Cab To End Frame, Double Frame, Dual 79 Gallon Steel Fuel Tanks, Steel Wheels, 11R22.5, PTO, AC, Oil Seepage. Showing 414,586 Miles; 37,962 Hours. Location: Des Moines, IA Serial: 1M2P296C64M067579 | |
| Lot # | 73 |  |
| Qty | 1 | |
| Title | 2004 TRAIL KING TKU18 EQUIPMENT TRAILER | |
| Des. | NO POWER TO TEST LIGHTS. Ramp Latch Bars Bent/Twisted, Nose Cone Bar Weld Broken, Minor Damage/Rust. Location: Wayne, MI Serial: 1TKU020394M036428 | |
| Lot # | 74 |  |
| Qty | 1 | |
| Title | 2006 INTERNATIONAL 7400 GARBAGE PACKER | |
| Des. | RUNNING CONDITION UNKNOWN. DEAD BATTERIES. International DT530, Allison Automatic, Hendrickson Haulmaxx Suspension, 18 FA, 46 RA, 25 Yrd Heil Rear Loader, Double Frame, Steel Fuel Tank, Steel Wheels, 11R22.5; 315R22.5, AC, Missing Body ID Tag, Damage/Rust. Mileage Unavailable. Location: Bennett, CO Serial: 1HTWHAZR76J377103 | |
| Lot # | 77 |  |
| Qty | 1 | |
| Title | 2003 FORD F350 SUPER DUTY SERVICE TRUCK | |
| Des. | STARTED ON SITE W/ JUMP- NOT ROAD TESTED. Ford Power Stroke Diesel, 5 Speed Manual, Spring Suspension, 4.85 FA, 9.75 RA, 162 WB, 9ft Knapheide Service Body, Body Storage, Steel Wheels, 235/85R16, AC, Dead Batteries. Showing 374,633 Miles. Location: Pelham, AL Serial: 1FDWX36P73ED07003 | |
| Lot # | 78 |  |
| Qty | 1 | |
| Title | 2004 MACK RD688S CAB & CHASSIS | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. BRAKES WON'T RELEASE DUE TO AIR LEAK. Mack AI-300A ASET, Allison Model HD4560P Automatic, Camelback Suspension, 18 FA, 236 WB, 198in Back Cab To End Frame, Double Frame, Dual 79 Gallon Steel Fuel Tanks, Steel Wheels, 11R22.5, PTO, AC, Warning Lights Active. Showing 425,685 Miles; 35,695 Hours. Approximate Measurements: 27ft Length, 98in Width, 120in Height. Location: Des Moines, IA Serial: 1M2P296C24M067577 | |

| | | |
|--------------|---|---|
| Lot # | 79 |  |
| Qty | 1 | |
| Title | 2010 DODGE RAM 1500 PICKUP TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. CONTENTS IN BED NOT INCLUDED. Dodge 3.7L Gas, Automatic, Spring Suspension, 3.7 FA, 3.9 RA, 141 WB, 8.25ft Box W/ Liner, Steel Wheels, 265/70R17, AC. Showing 122,701 Miles. Location: Dallas, TX Serial: 3D7JB1EKXAG103945 | |
| Lot # | 82 |  |
| Qty | 1 | |
| Title | 1998 TRAIL KING TKU18 EQUIPMENT TRAILER | |
| Des. | NO POWER TO TEST LIGHTS. Wood On Ramps Splitting/Worn, Minor Damage/Rust. Location: Wayne, MI Serial: 1TKU02039WM012844 | |
| Lot # | 84 |  |
| Qty | 1 | |
| Title | 2002 MACK RD690S CAB & CHASSIS | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Mack EM7-300 EUP LSR, Allison Model 4560P Automatic, Camelback Suspension, 195in Back Cab To End Frame, Double Frame, Dual Steel 78 Gallon Fuel Tanks, Steel Wheels, 11R22.5, PTO, AC, Damage/Rust. Showing 338,802 Miles; 34,855 Hours. Approximate Measurements: 25ft Length, 98in Width, 125in Height. Location: Des Moines, IA Serial: 1M2P264C52M033809 | |
| Lot # | 86 |  |
| Qty | 1 | |
| Title | 2008 FORD F450 CREW CAB PICKUP TRUCK | |
| Des. | NON RUNNER. BOX MISSING. 6.4L Diesel, Automatic, Spring Suspension, 5.25 FA, 9.75 RA, 176 WB, Steel Wheels, 245/75R17, AC. Showing 286,915 Miles. Location: Houston, TX Serial: 1FDWW36RX8EC84246 | |
| Lot # | 87 |  |
| Qty | 1 | |
| Title | 2005 MACK CV713 CAB & CHASSIS | |
| Des. | NON RUNNER. DASH APART. NO BATTERIES. PTO TAKEN OFF TRANS, PAPER TOWELS IN HOLE. Mack AMI-335 ASET, Mack T310, Camelback Suspension, 18 FA, 44 RA, 290 WB, 224in Body Length, Double Frame, Engine Brake, Dual Aluminum Fuel Tanks, Steel Wheels, 315/80R22.5, AC, Hood Latch Broken, Damage/Rust. Mileage Unavailable. Location: Greenville, OH Serial: 1M2AG11C45M027910 | |
| Lot # | 88 |  |
| Qty | 1 | |
| Title | 2001 FORD F250 SUPER DUTY XL SERVICE TRUCK | |
| Des. | CRANKS, NO START. Ford 7.3L Diesel, Automatic, Spring Suspension, 4.1 FA, 6.084 RA, 137 WB, 8.25ft Knapheide Service Body, Body Storage, Steel Wheels, 265/75R16, AC, PW, Damage/Rust. Showing 391,671 Miles. Location: Pelham, AL Serial: 1FDNF20F11EC74618 | |
| Lot # | 89 |  |
| Qty | 1 | |
| Title | HOMEMADE EQUIPMENT TRAILER | |
| Des. | NO VIN TAG LOCATED ON UNIT. NO POWER TO TEST LIGHTS. Side Rails Have Several Torch Cut Holes, Various Minor Damage/Rust. Location: Wayne, MI Serial: N/A | |

| | | |
|--------------|--|---|
| Lot # | 90 |  |
| Qty | 1 | |
| Title | 2004 OSHKOSH S2146 FRONT MIXER | |
| Des. | STARTED ON SITE W/JUMP. LESS DRUM. Cummins ISMC, Automatic, Chalmers Suspension, 21 FA, 42 RA, 214 WB, 150 Gallon Side Mount Water Tank, Pusher Axle, Tag Axle, Aluminum Wheels, 425/65R22.5, PTO, AC. Showing 203,459 Miles; 15,578 Hours. Location: Des Moines, IA Serial: 10TJAC264S080690 | |
| Lot # | 92 |  |
| Qty | 1 | |
| Title | 2012 FREIGHTLINER M2 106 GARBAGE PACKER | |
| Des. | NON RUNNER. ENGINE FIRE. DRIVE SHAFT REMOVED WITH TRUCK. MISSING SEVERAL COMPONENTS, INCLUDING: HYDRAULIC CYLINDER, LEAVERS OFF VALVE BODY, TRANSMISSION PUSH BUTTON CONTROL, LEFT ACCELERATION PEDAL, AND DRIVER'S SEAT. Cummins ISC, Automatic, Spring Suspension, 13.2 FA, 40 RA, 246 WB, G-S Products Side Loader, L/R Steering, Steel Wheels, 315/80R22.5, PTO, AC, Backup Camera, Right Front Tire Flat. Mileage Unavailable. Approximate Measurements: 33.75ft Length, 12.5ft Height. Location: Henderson, NC Serial: 1FVHCYBS9CHBJ0260 | |
| Lot # | 93 |  |
| Qty | 1 | |
| Title | 2003 MACK CV713 CAB & CHASSIS | |
| Des. | NON RUNNER. MISSING #2 INJECTOR. MISSING VIN/WEIGHT TAG. Mack E7-400 E-TECH LSR, Eaton Fuller RTO14908LL, Camelback Suspension, 267 WB, 223in Back Cab To End Frame, Double Frame, 55 Gallon Steel Fuel Tank, Steel Wheels, 11R22.5, PTO, AC, Rear Tires Singled, Instrument Panel Missing, Damage/Rust. Mileage Unavailable. Location: Pelham, AL Serial: 1M2AG11C83M002974 | |
| Lot # | 94 |  |
| Qty | 1 | |
| Title | 2002 FORD F550 SUPER DUTY XL SERVICE TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. CRANE REMOVED FROM BODY - SEE PHOTOS. Ford Powerstroke 7.3L, Automatic, Spring Suspension, 6 FA, 13.5 RA, 165 WB, 11.75ft Rawson-Koenig Service Body, Body Storage, Steel Wheels, 225/70R19.5, AC, Missing Rear Outer Tires, Missing Body ID Tags, Rust. Showing 215,701 Miles. Location: Kansas City, MO Serial: 1FDAF56F52EA30933 | |
| Lot # | 95 |  |
| Qty | 1 | |
| Title | 2003 FORD F150 XL PICKUP TRUCK | |
| Des. | CRANKS, NO START. Ford 5.4L Gas, Automatic, Spring Suspension, 2.95 FA, 3.2 RA, 139 WB, 8.25ft Box, Steel Wheels, 225/75R16, AC, SOS Light Active, Missing Tail Lights. Showing 383,471 Miles. Location: Weatherford, TX Serial: 2FTRF17L03CA06678 | |
| Lot # | 97 |  |
| Qty | 1 | |
| Title | HOMEMADE EQUIPMENT TRAILER | |
| Des. | NO VIN TAG LOCATED ON UNIT. NO POWER TO TEST LIGHTS. Weld Cracks On Rack, Multiple Hub Seals Leaking, Minor Damage/Rust. Location: Wayne, MI Serial: N/A | |
| Lot # | 99 |  |
| Qty | 1 | |
| Title | 1987 INTERNATIONAL 5000 CAB & CHASSIS | |
| Des. | NON RUNNER. Cummins L10, 7 Speed Manual, Hendrickson Suspension, 191in Back Cab To End Frame, Double Frame, Spoke Wheels, 425/65R22.5; 11R22.5, PTO, VIN Tag Not Located, Damage/Rust. Showing 192,863 Miles; 3,302 Hours. Location: Pelham, AL Serial: 2HTTGGHT8HC002442 | |

| | | |
|--------------|---|---|
| Lot # | 100 |  |
| Qty | 1 | |
| Title | 2005 INTERNATIONAL 4300 SBA 4X2 STAKE BODY TRUCK | |
| Des. | NON RUNNER. ENGINE DISASSEMBLED. INTERIOR DISASSEMBLED AND FILLED WITH SOME PARTS. International DT466, Eaton 6 Speed, Spring Suspension, 14 FA, 23 RA, 256 WB, 24ft Stake Body, Eaglelift Lift Gate, Steel Wheels, 11R22.5, Rust. Mileage Unavailable. Location: Kansas City, MO Serial: 1HTMMAAN75H123165 | |
| Lot # | 101 |  |
| Qty | 1 | |
| Title | 1999 FORD F250 SERVICE TRUCK | |
| Des. | NON RUNNER. BROKEN IGNITION SWITCH. ALL TIRES FLAT. Ford 5.4L Gas, Automatic, Spring Suspension, 139 WB, 8ft Reading Service Body, Body Storage, Steel Wheels, 235/85R16, AC, Body Damage/Rust. Showing 301,663 Miles. Location: Lugoff, SC Serial: 1FDNF20L0XEA52201 | |
| Lot # | 102 |  |
| Qty | 1 | |
| Title | 1999 MACK DM690S CAB & CHASSIS | |
| Des. | STARTED ON SITE, NOT ROAD TESTED. EM7-300 EUP, T2070, Camelback Suspension, 242 WB, Double Frame, 210 Cab To Frame End, Steel Wheels, 11R22.5; 315/80R22.5, PTO, AC. Showing 261,176 Miles; 35,719 Hours. Location: Des Moines, IA Serial: 1M2B209C8XM025341 | |
| Lot # | 103 |  |
| Qty | 1 | |
| Title | 2000 FORD F150 PICKUP TRUCK | |
| Des. | STARTED ON SITE, NOT ROAD TESTED. EXHAUST LEAK. 4.6L V8. Automatic, Spring Suspension, 120 WB, Steel Wheels, 225/75R16, AC, Tailgate Wont Open, Body Damage/Rust. Showing 128,909 Miles. Location: San Bernardino, CA Serial: 3FTRF17W2YMA50400 | |
| Lot # | 104 |  |
| Qty | 1 | |
| Title | 2003 KOMATSU FG25T-12 FORKLIFT | |
| Des. | NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. BAD TRANSMISSION. LESS PROPANE TANK AND KEY. Nissan 4 Cyl Gas, Automatic, Open ROPS, Side Shift, 7ft Height, Two 48x4in Forks, Three Masts, Steel Wheels, 7.00-12; 6.00-9, AC, Dead Batteries. Showing 12,437 Hours. Location: Morristown, TN Serial: 558501A | |
| Lot # | 105 |  |
| Qty | 1 | |
| Title | 1998 SIMPSON EQUIPMENT TRAILER | |
| Des. | WIRING CUT/MISSING. SLIGHT BEND IN NECK. 18ft Length, 103in Width, Steel Composition, Spring Suspension, Steel Wheels, 225/75R15, Two Flat Tires, Jack Froze Up, Fender Damaged. Location: Kansas City, MO Serial: 464UT1828WF000300 | |
| Lot # | 106 |  |
| Qty | 1 | |
| Title | 2000 MICKEY AT-B BEVERAGE TRAILER | |
| Des. | FIFTH WHEEL KING PIN PLATE HAS MAJOR ROT DAMAGE TO STEEL. SEVERAL COMPARTMENTS WON'T OPEN DUE TO COUNTER-BALANCE LIFT ASSIST SYSTEMS NOT FUNCTIONING. 37ft Length, Aluminum Composition, Spring Suspension, 16 Compartments- Only 5 Open, Steel Wheels, 295/75R22.5, Bottom Of Trailer Damaged, Locking Mechanism For Compartment Doors Seized/Inop. Location: Portland, MI Serial: 5CWRA3717YH997368 | |