



## Printable Catalog

<b>Title</b>	MAY 12 12:00 CDT	
<b>Description</b>	Closing Times TBD	
<b>Date</b>	Wed, May 12, 2021	
<b>Starts at</b>	12:00 PM	
<b>Address</b>	4747 NE 14th St, Des Moines, IA 50313 USA	
<b>Categories</b>		


---

<b>Lot #</b>	1	
<b>Qty</b>	1	
<b>Title</b>	2009 MACK GU813 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE W/ JUMP - NOT ROAD TESTED. Mack MP7, Eaton Fuller RTO14908LL 10 Speed, Air Ride Suspension, Double Frame, Air Lift Pusher Axle, Dual Aluminum Fuel Tanks, Wet Kit, Steel/Aluminum Wheels, 315/80R22.5, PTO, AC, Dead Batteries. Showing 473,393 Miles. Location: Summerville, SC Serial: 1M2AX13C39M005285	


---

<b>Lot #</b>	2	
<b>Qty</b>	1	
<b>Title</b>	2005 STERLING L9500 REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. CAT C11 350 HP, 9LL, HN Suspension, 250 WB, 11 Yrd Housby Rear Mixer, 150 Gallon Cross Mount Water Tank, Aluminum Fuel Tank, Bridge Axle, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Weight Tag Missing. Showing 165,589 Miles; 32,922 Hours. Location: Algonquin, IL Serial: 2FZHAZDL55AU06248	


---








<b>Lot #</b>	3	
<b>Qty</b>	1	
<b>Title</b>	2001 MACK CL713 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Tri-Axle, Air Lift Pusher Axle. Leak At Bottom Of Block/Oil Pan And Right Side Of Block, Check Engine Light Illuminated, Active Fault Code - See Report, Failed Air Pressure Drop Test, Engine EPU Covers Missing, Coolant Cap Won't Release, Interior Worn, Various Damage/Rust. Showing 17,749 Miles; 25,863 Hours. Location: Muskogee, OK Serial: 1M1AD62Y51M011343	








---



<b>Lot #</b>	4	
<b>Qty</b>	1	
<b>Title</b>	2005 INTERNATIONAL 7600 FLATBED TRUCK	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. Cummins ISM, 10 Speed Manual, Air Ride Suspension, 248 WB, Steel Fuel Tank, Steel Wheels, 11R22.5, AC, Rears Singled. Showing 208,466 Miles; 19,435 Hours. Location: Newark, NJ Serial: 1HTWYAHR35J011414	








---







<b>Lot #</b>	5	
<b>Qty</b>	1	
<b>Title</b>	2009 MACK GU713 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE W/ JUMP - NOT ROAD TESTED. Mack MP7-365, Allison Model 4500RDS Automatic, Camelback Suspension, 18 FA, 46 RA, 255 WB, 215in Back Cab To End Frame, Double Frame, Dual Steel Fuel Tanks, Wet Kit, Steel Wheels, 315/80R22.5, AC, Dead Batteries, Warning Lights Active. Showing 258,223 Miles; 16,120 Hours. Approximate Measurements: 29.25ft Length, 98in Width, 115in Height. Location: Des Moines, IA Serial: 1M2AX04CX9M005695	

<b>Lot #</b>	6	
<b>Qty</b>	1	
<b>Title</b>	2004 CATERPILLAR 972G SERIES II WHEEL LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED ON SITE W/ JUMP - NOT ROAD TESTED. CAT Diesel, Automatic, Enclosed ROPS, 126x58in Bucket, Steel Wheels, 26.5R25, AC/Heated Cab, Dead Batteries. Showing 32,764 Hours. Location: Lakeland, FL Serial: AWP00359	
<b>Lot #</b>	7	
<b>Qty</b>	1	
<b>Title</b>	2002 FREIGHTLINER FLD132 XL CLASSIC DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Oil Leaks At Both Sides Of Block And Bottom Of Block/Oil Pan, Rear Window Busted, Spot Mirror Cracked, Power Steering Leaking, #3 Axle Leaking On Right Side, City Horn Inop, Air System Failed Air Pressure Drop Test, Interior Worn. Showing 983,289 Miles. Location: Muskogee, OK Serial: 1FUJAHCG32PG29105	
<b>Lot #</b>	8	
<b>Qty</b>	1	
<b>Title</b>	PUSHER AXLE	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. PULLED FROM 2004 MACK RD690S. Location: Des Moines, IA Serial: 1M2P296C24M067580	
<b>Lot #</b>	9	
<b>Qty</b>	1	
<b>Title</b>	2009 MACK GU813 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE W/ JUMP - NOT ROAD TESTED. Mack MP7, Eaton Fuller RTO14908LL 10 Speed, Air Ride Suspension, 285 WB, Double Frame, Air Lift Pusher Axle, Dual Aluminum Fuel Tanks, Wet Kit, Steel Wheels, 315/85R22.5, PTO, AC, Dead Batteries. Showing 403,072 Miles. Location: Summerville, SC Serial: 1M2AX13C89M005282	
<b>Lot #</b>	10	
<b>Qty</b>	1	
<b>Title</b>	2006 STERLING L9500 REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. CAT C11 350 HP, 9LL, HN Suspension, 18 FA, 40 RA, 250 WB, Housby Rear Mixer, Bridge Axle, 150 Gallon Cross Mount Water Tank, Aluminum Fuel Tank, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Check Engine Light Illuminated, Engine Protect Light Flashing, Body Tag Missing. Showing 83,397 Miles; 12,308 Hours. Location: Algonquin, IL Serial: 2FZHAZDL56AW30153	
<b>Lot #</b>	11	
<b>Qty</b>	1	
<b>Title</b>	2019 PETERBILT 337 LUBE TRUCK	
<b>Des.</b>	Paccar PX-9- 300 HP Diesel, Allison 3000 RDS-P, Spring Suspension, 12 FA, 21 RA, 196 WB, 17.5ft TPL-Lube Master Body Including: 3- 110 Gallon Oil Tanks; 1- 55 Gallon Oil Tank; 1- 220 Gallon Oil Tank; 1- 55 Gallon Stainless Antifreeze Tank; 1- 350 Gallon Waste Oil Tank, Aluminum/Steel Wheels, 11R22.5, 20 Gallon Aluminum Fuel Tank, AC, PW, PL. Showing 56,813 Miles; 2,416 Hours. Location: Des Moines, IA Serial: 2NP2HJ7X2KM625654	
<b>Lot #</b>	12	
<b>Qty</b>	1	
<b>Title</b>	2004 PETERBILT 330 FLATBED TRUCK	
<b>Des.</b>	STARTED ON SITE W/ STARTING FLUID - NOT ROAD TESTED. SLOW TO BUILD AIR PRESSURE. CAT C7, Allison Automatic, Air Ride Suspension, 257 WB, Dual Aluminum Fuel Tanks, Steel Wheels, 315/80R22.5; 11R22.5, AC, Rears Singled. Showing 24,747 Miles; 23,074 Hours. Approximate Measurements: 33.25ft Length, 10.25ft Height. Location: Newark, NJ Serial: 2NPNLD9X04M827793	








<b>Lot #</b>	13	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Mack AI-375A ASET, Allison Model 4500RDS Automatic, Camelback Suspension, 18 FA, 46 RA, 238 WB, 198in Back Cab To End Frame, Double Frame, Dual 81 Gallon Steel Fuel Tanks, Steel Wheels, 315/80R22.5; 11R22.5, PTO, AC, Dash Broken, Warning Lights Active. Showing 257,900 Miles; 31,483 Hours. Location: Des Moines, IA Serial: 1M2AG11C56M043342	
<b>Lot #</b>	14	
<b>Qty</b>	1	
<b>Title</b>	2005 CATERPILLAR 988G WHEEL LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED ON SITE W/ JUMP - NOT ROAD TESTED. BAD HYDRAULIC PUMP, BUCKET WILL NOT LIFT. CAT Diesel, Automatic, Enclosed ROPS, 151x76in Spade Type Bucket, Steel Wheels, 65R33, AC/Heated Cab, Dead Batteries, Warning Lights Active, Damage/Rust. Showing 36,508 Hours. Location: Lakeland, FL Serial: BNH01472	
<b>Lot #</b>	15	
<b>Qty</b>	1	
<b>Title</b>	1995 INTERNATIONAL 9200 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Oil Seepage At Bottom Of Block/Pan, Residue On Both Sides Of Block, PDL Light Illuminated, Left Side Fuel Tank Damaged, Air System Failed Air Pressure Drop Test, VIN Tag Faded, Interior Worn. Showing 723,717 Miles; 726,884 ECM Miles; 21,403 Hours. Location: Muskogee, OK Serial: 2HSFMALR0SC024221	
<b>Lot #</b>	16	
<b>Qty</b>	1	
<b>Title</b>	PUSHER AXLE	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. PULLED FROM 2006 MACK CV713. Location: Des Moines, IA Serial: 1M2AG11C56M043342	
<b>Lot #</b>	17	
<b>Qty</b>	1	
<b>Title</b>	2009 MACK GU813 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. DASH APART. LESS KEYS. MP7, Allison 4500RDS, Camelback Suspension, Alum/Steel Wheels, 315/80R22.5; 11R22.25 (Rears Singled Out), Less Keys, Seats Removed. Mileage Unavailable. Location: Jacksonville, FL Serial: 1M2AX13C99M005274	
<b>Lot #</b>	18	
<b>Qty</b>	1	
<b>Title</b>	2006 STERLING L9500 REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/ FLUID - NOT ROAD TESTED. CAT C13, 9LL, HN Suspension, 252 WB, Housby Bridge Rear Mixer W/ McNeilus Hopper, Bridge Axle, Cross Mount Water Tank, Aluminum Fuel Tank, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Dead Batteries, Body Tag Missing, Engine Tag Missing, Weight Tag Missing. Showing 128,454 Miles; 14,534 Hours. Location: Algonquin, IL Serial: 2FZHAZDE76AW30138	
<b>Lot #</b>	20	
<b>Qty</b>	1	
<b>Title</b>	1999 FORD F800 FLATBED TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. HARD STARTING. UNIT HAS BEEN SITTING FOR AN EXTENDED PERIOD. Cummins 5.9L Diesel, Automatic, Spring Suspension, 8.5 FA, 17.5 RA, 182 WB, 16ft Flatbed Body, Steel Wheels, 275/80R22.5, AC, Dead Batteries. Showing 108,732 Miles; 1,153 Hours. Approximate Measurements: 26.75ft Length, 7.75ft Height. Location: Oxford, NJ Serial: 3FENF80Z0XMA22077	







<b>Lot #</b>	21	
<b>Qty</b>	1	
<b>Title</b>	2009 MACK GU713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. MISSING IGNITION AND STEERING COMPONENTS. Mack MP7-365, Allison Model 4500RDS Automatic, Camelback Suspension, 18 FA, 46 RA, 250 WB, 215in Back Cab To End Frame, Double Frame, Dual 54 Gallon Steel Fuel Tanks, Tag Axle W/ No Wheels/Tired, Steel Wheels, 315/80R22.5, AC, Windshield Cracked, Hood Damaged, Flat Tire. Mileage Unavailable. Location: Des Moines, IA Serial: 1M2AX04C39M005697	
<b>Lot #</b>	22	
<b>Qty</b>	1	
<b>Title</b>	2003 CATERPILLAR 988G WHEEL LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED ON SITE - NOT ROAD TESTED. CAT Diesel, Automatic, Enclosed ROPS, 151x78in Spade Type Bucket, Steel Wheels, 35/65R33, AC/Heated Cab, AUT Light Illuminated, Damage/Rust. Showing 34,888 Hours. Location: Lakeland, FL Serial: BNH00682	
<b>Lot #</b>	23	
<b>Qty</b>	1	
<b>Title</b>	1997 MACK RD690S DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE W/ FLUID - NOT ROAD TESTED. TRAILER NOT INCLUDED IN SALE. Mack EM7-300, T2080B 8 Speed, Camelback Suspension, 12 FA, 202 WB, Manual Fifth Wheel, Steel Fuel Tank, Steel Wheels, 11R22.5, PTO, Dead Batteries, Warning Lights Active. Showing 456,815 Miles; 21,950 Hours. Location: Algonquin, IL Serial: 1M2P264Y5VM023913	
<b>Lot #</b>	24	
<b>Qty</b>	1	
<b>Title</b>	PUSHER AXLE	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. PULLED FROM 2001 MACK RD690S. Location: Des Moines, IA Serial: 1M2P264C31M033452	
<b>Lot #</b>	25	
<b>Qty</b>	1	
<b>Title</b>	2007 INTERNATIONAL 5600i 6X4 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. ENGINE DISASSEMBLED. NO COOLANT IN RESERVOIR. DRIVE SHAFT REMOVED. Large Oil And Coolant Stains Below Unit, Oil Leaks At Bottom Of Engine/Pan, Valve Cover, And Engine Block, AC Vents Removed From Dash, Left Rear Tire Split Around Cap, Hydraulic Pump Leaking. Interior Worn, Damage/Rust. Mileage Unavailable. Location: Byron, GA Serial: 1HTXHAHT17J478947	
<b>Lot #</b>	26	
<b>Qty</b>	1	
<b>Title</b>	2001 MACK RD690S REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. DRUM DAMAGED. Mack EM7-300 E-TECH LSR, Fuller Model RTO14909MLL 9LL, HN Suspension, 20 FA, 252 WB, 10.5 Yrd Terex Rear Mixer, Bridge Axle, Cross Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, No Weight Tag, Warning Lights Active. Showing 130,044 Miles; 19,782 Hours. Location: Algonquin, IL Serial: 1M2P264C21M033832	
<b>Lot #</b>	28	
<b>Qty</b>	1	
<b>Title</b>	2002 INTERNATIONAL 4300 SBA 4X2 FLATBED TRUCK	
<b>Des.</b>	NON RUNNER. HOLE IN DIESEL FUEL TANK. UNIT HAS BEEN SITTING FOR AN EXTENDED PERIOD. International DT466E Diesel, Allison Automatic, Spring Suspension, 152 WB, 12 Flatbed Body, Steel Wheels, 295/75R22.5, AC. Showing 128,873 Miles; 4,481 Hours. Approximate Measurements: 23.25ft Length. Location: Oxford, NJ Serial: 1HTMMAAM62H506887	

<b>Lot #</b>	29	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. NO DASH CLUSTER. BRAKES ARE CAGED. AIR FITTING BROKEN. Mack AI-375A ASET, Allison Model 4500RDS Automatic, Camelback Suspension, 18 FA, 238 WB, 197in Back Cab To End Frame, Double Frame, Dual 81 Gallon Steel Fuel Tanks, Pusher Axle, Steel Wheels, 315/80R22.5; 11R22.5, PTO, AC, Driver's Door Missing Latch, Bumper Rusty. Mileage Unavailable. Approximate Measurements: 28ft Length, 98in Width, 118in Height. Location: Des Moines, IA Serial: 1M2AG11C66M043348	
<b>Lot #</b>	30	
<b>Qty</b>	1	
<b>Title</b>	2004 STERLING L9500 REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. CAT C12-355, 9LL, Chalmers Suspension, 20 FA, 46 RA, 252 WB, 11 Yrd McNeilus Rear Mixer, Bridge Axle, 150 Cross Mount Water Tank, Aluminum Fuel Tank, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC. Showing 183,522 Miles; 23,234 Hours. Location: Algonquin, IL Serial: 2FZHAZAS94AM30711	
<b>Lot #</b>	31	
<b>Qty</b>	1	
<b>Title</b>	1997 MACK RD690S DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Mack EM7-300, T2080B 8 Speed, Camelback Suspension, 12 FA, 38 RA, 202 WB, Air Slide Fifth Wheel, Dual Steel Fuel Tanks, Wet Kit, Steel Wheels, 11R22.5, PTO. Showing 450,356 Miles; 22,484 Hours. Location: Algonquin, IL Serial: 1M2P264Y9VM023915	
<b>Lot #</b>	32	
<b>Qty</b>	1	
<b>Title</b>	PUSHER AXLE	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. PULLED FROM 2003 MACK RD690S. Location: Des Moines, IA Serial: 1M2P264C23M034255	
<b>Lot #</b>	33	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CV713 6X6 CAB & CHASSIS	
<b>Des.</b>	CRANKS, NO START. DRIVE SHAFT REMOVED. MISSING AIR CLEANER OFF ENGINE. Mack AMI-335 ASET, Eaton RTO 14909ALL 9LL, HN Suspension, 20 FA, 46 RA, 240 WB, 253in Back Cab To End Frame, 13,200 Lbs Bridge Axle, Steel Wheels, 385/65R22.5; 11R22.5, PTO, Electrical Warning Illuminated. Showing 141,786 Miles; 18,500 Hours. Location: Mokena, IL Serial: 1M2AG11CX6M031803	
<b>Lot #</b>	34	
<b>Qty</b>	1	
<b>Title</b>	2003 CATERPILLAR 950G WHEEL LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. UNABLE TO LIFT HOOD TO INSPECT ALL COMPONENTS. Bucket Bent In Areas, Interior Worn, Minor Damage. Showing 17,140 Hours. Location: Auburn, AL Serial: 0BAA00144	
<b>Lot #</b>	36	
<b>Qty</b>	1	
<b>Title</b>	1997 CHEVROLET C3500 FLATBED TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. RUNS ROUGH. ITEMS ON BED TO BE REMOVED PRIOR TO SALE. Vortec 7.4L Gas, Automatic, Spring Suspension, 159 WB, 12.25ft Flatbed Body, Steel Wheels, 225/70R19.5, Driver Door Doesn't Open From Inside. Showing 90,858 Miles. Location: Algonquin, IL Serial: 1GBKC34J1VJ113529	







<b>Lot #</b>	37	
<b>Qty</b>	1	
<b>Title</b>	2008 FREIGHTLINER M2 106 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE W/ STARTING FLUID - NOT ROAD TESTED. Cummins ISC, Automatic, Hendrickson Suspension, 23 FA, 46 RA, 231 WB, 207in Back Cab To End Frame, Double Frames, Dual 40 Gallon Aluminum Fuel Tanks, Steel Wheels, 315/80R22.5; 11R22.5, AC, Warning Lights Active, Cracked Windshield, Dead Batteries. Showing 253,430 Miles; 22,016 Hours. Approximate Measurements: 19.5ft Length, 98in Width, 106in Height. Location: Des Moines, IA Serial: 1FVHCYBS48HZ17614	
<b>Lot #</b>	38	
<b>Qty</b>	1	
<b>Title</b>	2003 OSHKOSH F-2146 6X6 REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Cummins ISM, Eaton Fuller, HN Suspension, 21 FA, 46 RA, 237 WB, 10.5 Yrd McNeilus Rear Mixer, Bridge Axle, 150 Gallon Cross Mount Water Tank, Aluminum Fuel Tank, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, ABS Light Illuminated, Engine Tag Missing. Showing 47,678 Miles; 16,868 Hours. Location: Algonquin, IL Serial: 10TDDAC383S079536	
<b>Lot #</b>	39	
<b>Qty</b>	1	
<b>Title</b>	1990 FREIGHTLINER FLD120 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE W/ JUMP AND FLUID - NOT ROAD TESTED. NO READABLE VIN OR FRAME VIN LOCATED. ENGINE BLOW BY. Detroit Series 60 12.7L 425 HP, 9 Speed Manual, Air Ride Suspension, 12 FA, 38 RA, 208 WB, Manual Fifth Wheel, Dual Aluminum Fuel Tanks, Wet Kit, Engine Brake, Aluminum Wheels, 295/75R22.5, AC. Showing 38,302 Miles. Approximate Measurements: 26ft Length, 96in Width, 10ft Height. Location: Afton, MN Serial: 1FUVDZYB2LH369149	
<b>Lot #</b>	40	
<b>Qty</b>	1	
<b>Title</b>	PUSHER AXLE	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. PULLED FROM 2002 MACK RD690S. Location: Des moines, IA Serial: 1M2P264C42M033803	
<b>Lot #</b>	41	
<b>Qty</b>	1	
<b>Title</b>	2004 INTERNATIONAL 7400 6X4 CAB & CHASSIS	
<b>Des.</b>	STARTS/RUNS BRIEFLY ON JUMP BEFORE IT DIES. LESS KEYS. MISSING SHOCK PLATES. International DT530, Automatic, HN Suspension, 252 WB, 225in Back Cab To End Frame, Double Frame, Steel Wheels, 315/80R22.5, Engine Tag Missing, Hub Cap Broken. Showing 138,072 Miles. Location: Lakeville, IN Serial: 1HTWGADT64J081010	
<b>Lot #</b>	44	
<b>Qty</b>	1	
<b>Title</b>	1989 GMC CG-70 FLATBED TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. WILL NOT BUILD AIR PRESSURE. SMOKE OUT EXHAUST. GMC 8.2L Diesel, Automatic, Spring Suspension, 9 FA, 19 RA, 172 WB, 16ft Flatbed Body, Steel Wheels, 9.00R20, Body Rust Holes, Damage/Rust. Showing 17,912 Miles; 4,202 Hours. Location: Lakeland, FL Serial: 1GBM7D1F8KV104849	
















<b>Lot #</b>	45	
<b>Qty</b>	1	
<b>Title</b>	2008 INTERNATIONAL 4400 CAB & CHASSIS	
<b>Des.</b>	ENGINE TURNS OVER, MISSING PARTS. International Maxxforce DT, Automatic, Spring Suspension, 12 FA, 40 RA, 237 WB, 215in Back Cab To End Frame, Steel Fuel Tank, Steel Wheels, 315/80R22.5; 11R22.5, Dead Batteries. Showing 191,140 Miles; 15,115 Hours. Location: Des Moines, IA Serial: 1HTMSAAR98H675361	
<b>Lot #</b>	46	
<b>Qty</b>	1	
<b>Title</b>	2007 STERLING L9500 REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/ FLUID - NOT ROAD TESTED. ENGINE BLOW BY. DRUM CONTROLS NOT WORKING. Mercedes Benz OM460 335 HP, Allison Automatic, Chalmers Suspension, 250 WB, 11 Yrd McNeilus Rear Mixer, Bridge Axle, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Check Engine Light Illuminated, Batteries Dead, Rear Axle Seal Leaking. Showing 218,612 Miles; 19,032 Hours. Location: Algonquin, IL Serial: 2FZHAZCV87AY12644	
<b>Lot #</b>	47	
<b>Qty</b>	1	
<b>Title</b>	2000 VOLVO VNL64T DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. SERPENTINE BELT LOOKS MISMATCHED TO PULLEYS AND STARTED TO SHRED. TRANS WON'T SHIFT INTO HIGH RANGE. Oil Leak At Bottom Of Block/Oil Pan, Power Steering Issues - Difficult Turning, Rear Turn Lights Inop, Hood Release Loose, AC Not Cold, Interior Worn, Minor Damage/Rust. Showing 413,561 Miles; 413,370 ECM Miles; 33,738 Hours. Location: Melvindale, MI Serial: 4V4M22GF4YN238180	
<b>Lot #</b>	49	
<b>Qty</b>	1	
<b>Title</b>	2004 INTERNATIONAL 7400 6X4 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. LESS KEYS. International DT530, Allison Automatic, HN Suspension, 252 WB, 225in Back Cab To End Frame, Double Frame, Steel Wheels, 315/80R22.5; 11R22.5, AC, Engine Tag Missing. Mileage Unavailable. Location: Lakeville, IN Serial: 1HTWGADTX4J081012	
<b>Lot #</b>	50	
<b>Qty</b>	1	
<b>Title</b>	2004 KENWORTH W900S REAR MIXER	
<b>Des.</b>	NON RUNNER. HEAVY DAMAGE FROM COLLISION. MAJOR COMPONENTS MISSING, INCLUDING: ENGINE PARTS, TRANSMISSION TOP PLATE AND OTHER TRANS PARTS, AND ECM. Oil Leak At Pan, Doors Will Not Open, Missing Fuel Cap, Oil Fill Tube Cap, Hydraulic Cap, And Radiator Cap, Interior Worn, Body Damage/Rust. Mileage Unavailable. Location: Van Buren, AR Serial: 1NKWLTEX44J051184	
<b>Lot #</b>	51	
<b>Qty</b>	1	
<b>Title</b>	2008 CORN BELT TRAIL BLAZER BELLY DUMP TRAILER	
<b>Des.</b>	48ft Length, 98in Width, 125in Height, 38 RA, Steel Composition, Aluminum Wheels, 235/75R24.5, Rust. Location: Des Moines, IA Serial: 1C9SS442581425204	
<b>Lot #</b>	52	
<b>Qty</b>	1	
<b>Title</b>	1989 INTERNATIONAL 1654 FLATBED TRUCK	
<b>Des.</b>	NON RUNNER. International 7.3L Diesel, Automatic, Spring Suspension, 190 WB, 16ft Body, Body Storage Containers, Steel Wheels, 295/75R22.5, Damage/Rust. Showing 58,435 Miles. Location: Lakeland, FL Serial: 1HTLAZRL6KH656366	







<b>Lot #</b>	54	
<b>Qty</b>	1	
<b>Title</b>	2006 STERLING L9500 REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. MISSING PTO, HYDRAULIC PUMP, AND WATER TANK. CAT C13 335 HP, 9LL, HN Suspension, 18 FA, 40 RA, 252 WB, 11 Yrd Housby Mixer, 13,200 Lbs Bridge Axle, Aluminum Fuel Tank, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, AC, Check Engine Light Illuminated, ABS Light Illuminated, Body Tag Painted Over. Showing 176,484 Miles; 19,031 Hours. Location: Algonquin, IL Serial: 2FZHAZDE96AW30139	
<b>Lot #</b>	55	
<b>Qty</b>	1	
<b>Title</b>	2005 INTERNATIONAL 9400i 6X4 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. RUNS BRIEFLY BEFORE SHUTTING DOWN. Air Leak Behind Dashboard, Heavy Deposits Of Sludge/Mud At Engine, Missing Rear Lights, Hydraulic Tank Fill Cap Missing, Incorrect Service Line Installed, PTO Control Box Damaged, Interior Worn, Various Body Damage/Rust. Showing 563,259 Miles; 16,188 Hours. Location: Imperial, PA Serial: 2HSCNAPR85C184376	
<b>Lot #</b>	56	
<b>Qty</b>	1	
<b>Title</b>	2006 INTERNATIONAL 4400 SHREDDING TRUCK	
<b>Des.</b>	STARTED ON SITE W/ STARTING FLUID - NOT ROAD TESTED. WARNING ALARM ON. International DT466E, Automatic, Spring Suspension, 12 FA, 21 RA, 249 WB, 22ft Commander Body, Shred-Tech Paper Shredding Equipment, Left Side Door, Aluminum Wheels, 11R22.5, PTO, AC, Warning Lights Active. Showing 210,859 Miles. Location: Lakeland, FL Serial: 1HTMKAA86H332471	
<b>Lot #</b>	57	
<b>Qty</b>	1	
<b>Title</b>	2002 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. ENGINE RUNS ROUGH. Mack E7-350 E-TECH LSR, Allison Model HD4560P, Hendrickson Suspension, 20 FA, 46 RA, 276 WB, Double Frame, Engine Brake, Pusher Axle, Wet Kit, Dual Steel Fuel Tanks, Aluminum Wheels, 11R22.5, PTO, AC, Rust. Showing 105,419 Miles; 2,297 Hours. Location: Wittenberg, WI Serial: 1M2P267C52M062786	
<b>Lot #</b>	58	
<b>Qty</b>	1	
<b>Title</b>	2004 INTERNATIONAL 4300 SBA 4X2 DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE W/ JUMP - NOT ROAD TESTED. Leak Above Oil Pan, Power Steering Leak, Moderate Leak At Transmission Rear Housing, Hydraulic Leaks Around Reservoir And Lift Cylinder, Dump Bed Right Side Damaged, Interior Worn, Dead Batteries. Showing 370,265 Miles; 15,999 Hours. Location: Union City, TN Serial: 1HTMMAALX4H606274	
<b>Lot #</b>	59	
<b>Qty</b>	1	
<b>Title</b>	1995 FREIGHTLINER FL70 DISTRIBUTOR TRUCK	
<b>Des.</b>	STARTED ON SITE W/ JUMP - NOT ROAD TESTED. Cummins 5.9L, Allison Automatic, Spring Suspension, 165 WB, Etnyre Black Topper BT-HL Distributor Body, 1,604 Gallon Tank Capacity, Steel Wheels, 10R22.5, PTO, AC, Oil Leaks, Dead Batteries. Showing 53,227 Miles. Location: Wharton, NJ Serial: 1FV6HFAA6SL789161	








<b>Lot #</b>	61	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. ENGINE APART. MISSING DRIVE SHAFTS. MISSING LIGHTS. Mack AI-375A ASET, Allison Model 4500RDS Automatic, Camelback Suspension, 18 FA, 270 WB, Double Frame, Pusher Axle, Dual Aluminum Fuel Tanks, Steel Wheels, 315/80R22.5, PTO, AC, Rear Tires Singled Out, Oil Pan Off, Body Damage/Rust. Showing 365,031 Miles; 33,665 Hours. Approximate Measurements: 30.75ft Length, 10.25ft Height. Location: Attleboro, MA Serial: 1M2AG11C76M029894	
<b>Lot #</b>	62	
<b>Qty</b>	1	
<b>Title</b>	2006 STERLING L9500 REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. CAT C13 335 HP, 9LL, HN Suspension, 18 FA, 40 RA, 250 WB, 11 Yrd Housby Rear Mixer, 13,200 Lbs Bridge Axle, Cross Mount Water Tank, Aluminum Fuel Tank, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC. Showing 180,862 Miles; 19,855 Hours. Location: Algonquin, IL Serial: 2FZHAZDE36AW30136	
<b>Lot #</b>	63	
<b>Qty</b>	1	
<b>Title</b>	1989 PETERBILT 379 DAY CAB TRUCK	
<b>Des.</b>	NON RUNNER. BLOWN ENGINE. CAT 3406, 15 Speed Manual, Air Ride Suspension, 12 FA, 44 RA, 204 WB, Stationary Fifth Wheel, Dual Aluminum Fuel Tanks, Wet Kit, Aluminum/Steel/Spoke Wheels, 11R24.5, PTO, AC, Less Keys, Power Steering Oil Leaks, Rear Tire Flat. Showing 260,718 Miles. Approximate Measurements: 25ft Length, 11.3ft Height. Location: New City, NY Serial: 1XP5DB9X1KN281168	
<b>Lot #</b>	64	
<b>Qty</b>	1	
<b>Title</b>	1992 INTERNATIONAL 4900 FUEL TRUCK	
<b>Des.</b>	NON RUNNER. DT466, 6 Speed Manual, Spring Suspension, 184 WB, 15.5FT Fuel Body W/ Side Storage-Some Compartments Stuck Shut, Steel Wheels, 11R22.5, R/Door Wont Open. Showing 402,095 Miles; 2,042 Hours. Location: Des Moines, IA Serial: 1HTSDNUP0NH404736	
<b>Lot #</b>	65	
<b>Qty</b>	1	
<b>Title</b>	2002 MACK CH613 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. MISSING REAR DIFFERENTIAL. Remack E7-427 E-TECH LSR, Eaton Fuller FRO16210C, Air Suspension, 12 FA, 38 RA, 171 WB, 280in Back Cab To End Frame, Double Frame, Engine Brake, Steel Fuel Tank, Aluminum/Steel Wheels, 11R22.5, PTO, AC. Showing 105,419 Miles; 22,977 Hours. Location: Wittenberg, WI Serial: 1M1AA18Y72W149118	
<b>Lot #</b>	66	
<b>Qty</b>	1	
<b>Title</b>	2011 FORD F350 SUPER DUTY 4X4 XL PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Ford Power Stroke Diesel 6.7L, Automatic, Spring Suspension, 5.94 FA, 6.29 RA, 137 WB, 8ft Box W/ Tool Box, Steel Wheels, 265/70R17, AC, Warning Lights Active, Damage/Rust. Showing 372,002 Miles. Location: Greenville, OH Serial: 1FTRF3BT4BEC18348	

<b>Lot #</b>	67	
<b>Qty</b>	1	
<b>Title</b>	2011 FREIGHTLINER M2 106 SWEEPER	
<b>Des.</b>	NON RUNNER. REGEN PROBLEMS. UNIT HAS BEEN SITTING FOR AN EXTENDED PERIOD. PONY MOTOR NEEDS A STARTER AND MAKES A BAD NOISE. Cummins ISC, Allison Automatic, Spring Suspension, 12 FA, 21 RA, 176 WB, Elgin Crosswind Sweeper, John Deere Pony Motor -Showing 3,640 Hours, L/R Steering, Steel Wheels, 11R22.5, AC, Rust Hole In Sweeper Suction Pipe, Water Filter Off With Truck. Showing 34,630 Miles; 6,508 Hours. Location: New City, NY Serial: 1FVACXDT7BDBC6427	
<b>Lot #</b>	69	
<b>Qty</b>	1	
<b>Title</b>	2000 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. WILL NOT BUILD AIR PRESSURE. Mack E7-350 EUP, Mack T2090 9 Speed, Camelback Suspension, 18 FA, 268 WB, Double Frame, Steel Fuel Tank, Steel Wheels, 315/80R22.5, PTO, AC, Air Pressure Light Illuminated, Oil Leaks From Turbo, Rears Singled, Damage/Rust. Showing 751,761 Miles; 7,594 Hours. Approximate Measurements: 30.5ft Length, 10ft Height. Location: Attleboro, MA Serial: 1M2P267C4YM051268	
<b>Lot #</b>	70	
<b>Qty</b>	1	
<b>Title</b>	2000 MACK RD690S REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/ JUMP - NOT ROAD TESTED. Mack EM7-300 EUP, Fuller RTO14909MLL 9LL, HN Suspension, 20 FA, 248 WB, 10.5 Yrd McNeilus Rear Mixer, Bridge Axle, 110 Cross Mount Water Tank, Aluminum Fuel Tank, Steel Wheels, 365/80R20; 11R22.5, PTO, AC, Dead Batteries, Weight Tag Painted Over. Showing 100,057 Miles; 8,485 Hours. Location: Algonquin, IL Serial: 1M2P264C7YM030242	
<b>Lot #</b>	71	
<b>Qty</b>	1	
<b>Title</b>	2005 MACK CV713 DAY CAB TRUCK	
<b>Des.</b>	NON RUNNER. BAD ENGINE. VALVE COVERS LOOSE ON ENGINE. AIR CLEANER ASSEMBLY OFF, IN CAB. MISSING FUEL LINES AND FILTER. Mack AI-427 ASET, Maxitorque T310 10 Speed, Air Ride Suspension, 14.3 FA, 200 WB, Stationary Fifth Wheel, Wet Kit, Dual Aluminum Fuel Tanks, Aluminum/Steel Wheels, 11R24.5, PTO, AC. Showing 412,952 Miles; 16,649 Hours. Approximate Measurements: 25.25ft Length, 10.25ft Height. Location: New City, NY Serial: 1M1AG11Y75M018229	
<b>Lot #</b>	73	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. ENGINE MISSING COMPONENTS. Mack AI-350 ASET, Eaton Fuller RTO14908LL, Spring Suspension, 18 FA, 46 RA, 320 WB, 60,000 Lbs Body Capacity, Wet Kit, Steel Wheels, 315/80R22.5, PTO, AC. Mileage Unavailable. Location: Mc Crory, AR Serial: 1M2AG11CX7M064379	
<b>Lot #</b>	74	
<b>Qty</b>	1	
<b>Title</b>	2012 FORD F250 SUPER DUTY XL PICKUP TRUCK	
<b>Des.</b>	CRANKS, NO START. Ford Power Stroke Diesel, Automatic, Spring Suspension, 4.4 FA, 6.1 RA, 137 WB, 8ft Box W/ Liner, Steel Wheels, 245/75R17, AC, PW, PL, PM, Missing Front Bumper. Showing 391,685 Miles. Approximate Measurements: 18.75ft Length, 84in Width, 84in Height. Location: Des Moines, IA Serial: 1FTBF2AT4CEA28130	

<b>Lot #</b>	75	
<b>Qty</b>	1	
<b>Title</b>	2008 FORD ECONOLINE E350 SUPER DUTY VAN	
<b>Des.</b>	NON RUNNER. BAD ENGINE. Ford Power Stroke Diesel, Automatic, Spring Suspension, Ladder Rack, Steel Wheels, 245/75R16, AC, PW, PL, PM, Body Rust. Showing 110,877 Miles. Location: New City, NY Serial: 1FTSS34P98DA48421	
<b>Lot #</b>	77	
<b>Qty</b>	1	
<b>Title</b>	2004 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	CRANKS, NO START. LESS KEYS AND LIGHTS. Mack AI-350 ASET, Allison Model 4560P Automatic, Camelback Suspension, 18 FA, 265 WB, Double Frame, Dual Aluminum Fuel Tanks, Spoke Wheels, 12R24.5, PTO, AC, Oil Leaks, Rears Singled, Body Damage. Showing 492,743 Miles; 2,198 Hours. Approximate Measurements: 30.75ft Length, 9.25ft Height. Location: Attleboro, MA Serial: 1M2AG11C84M010008	
<b>Lot #</b>	78	
<b>Qty</b>	1	
<b>Title</b>	1998 MACK RD690S REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Mack EM7-300, T2080B 8 Speed, Walking Beam Suspension, 20 FA, 44 RA, 239 WB, 10.5 Yrd McNeilus Rear Mixer, 13,200 Lbs Bridge Axle, 110 Gallon Cross Mount Water Tank, Steel Fuel Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO. Showing 249,151 Miles; 6,776 Hours. Location: Algonquin, IL Serial: 1M2P264C7WM026138	
<b>Lot #</b>	79	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CHN613 DAY CAB TRUCK	
<b>Des.</b>	NON RUNNER. BLOWN ENGINE. Mack AC-460P ASET, Eaton Fuller 18 Speed Manual, Air Ride Suspension, 214 WB, Stationary Fifth Wheel, Wet Kit, Dual Aluminum Fuel Tanks, Aluminum Wheels, 11R24.5, PTO, AC, Hydraulic Leaks. Showing 483,882 Miles; 18,127 Hours. Location: New City, NY Serial: 1M1AJ07YX6N004128	
<b>Lot #</b>	80	
<b>Qty</b>	1	
<b>Title</b>	2008 FORD F550 SUPER DUTY XL 4X4 SERVICE TRUCK	
<b>Des.</b>	NON RUNNER. Ford 6.4L Diesel, Manual, Spring Suspension, 6.5 FA, 13.66 RA, 165 WB, Auto Crane Service Body, 225/70R19.5, AC. Mileage Unavailable. Location: Lewis, CO Serial: 1FDAF57R08EB67697	
<b>Lot #</b>	81	
<b>Qty</b>	1	
<b>Title</b>	2008 PETERBILT 386 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. CRACKED BELL HOUSING. MISSING RADIATOR, AIR HOSE, AND AXLES. CAT C13, 10 Speed Manual, Flex Air Ride Suspension, 12 FA, 40 RA, 192 WB, Dual Fuel Tanks, Aluminum/Steel Wheels, 315/80R22.5; 11R22.5, No Weight Tag, Hood Would Not Hold Open, Wheels Leak Air, Headlight Missing, Bumper Damaged, Interior Worn, Damage/Rust. Mileage Unavailable. Location: Buckeye, AZ Serial: 1XPHDU9XX8D738227	
<b>Lot #</b>	82	
<b>Qty</b>	1	
<b>Title</b>	2007 CHEVROLET SILVERADO 1500 4X4 PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE W/ JUMP - NOT ROAD TESTED. GMC 5.3L Gas, Allison Automatic, Spring Suspension, 134 WB, 8ft Box W/ Liner, Steel Wheels, 245/70R17, AC, PW, PL, PM, Dead Batteries, Missing Tailgate, Warning Lights Active, Body Damage/Rust. Showing 213,983 Miles. Location: New City, NY Serial: 1GCEK14J77Z601873	

<b>Lot #</b>	83	
<b>Qty</b>	1	
<b>Title</b>	2001 PETERBILT 385 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. BAD CLUTCH. CAT C12 430 HP, Eaton 9 Speed, Air Suspension, 12 FA, 40 RA, 80 Gallon Aluminum Fuel Tank, Engine Brake, Wet Kit, Aluminum Wheels, 11R22.5, PTO, AC, Damage/Rust. Showing 556,748 Miles; 37,727 Hours. Location: San Bernardino, CA Serial: 1XPGDU9X01D569904	
<b>Lot #</b>	85	
<b>Qty</b>	1	
<b>Title</b>	2007 INTERNATIONAL 4400 SBA 4X2 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. International DT466, Eaton Fuller, Spring Suspension, 226 WB, 254in Back Cab To End Frame, Dual 50 Gallon Steel Fuel Tanks, Steel/Spoke Wheels, 11R22.5, PTO, AC, Damage/Rust. Showing 231,632 Miles; 74,847 Hours. Approximate Measurements: 29.5ft Length, 88in Width, 106in Height. Location: Harrisburg, PA Serial: 1HTMKAAAN37H476365	
<b>Lot #</b>	86	
<b>Qty</b>	1	
<b>Title</b>	1994 MACK RD690S REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/ JUMP - NOT ROAD TESTED. Mack EM7-300, T2080 8 Speed, Camelback Suspension, 18 FA, 44 RA, 250 WB, 11 Yrd McNeilus Rear Mixer, 13,000 Lbs Bridge Axle, 125 Gallon Cross Mount Water Tank, Aluminum Fuel Tank, Spoke Wheels, 425/65R22.5; 11R22.5, PTO, AC, Dead Batteries, Warning Lights Active. Showing 188,521 Miles; 24,227 Hours. Location: Algonquin, IL Serial: 1M2P264C4RM017160	
<b>Lot #</b>	87	
<b>Qty</b>	1	
<b>Title</b>	2001 PETERBILT 385 DAY CAB TRUCK	
<b>Des.</b>	NON RUNNER. MISSING ELECTRICAL COMPONENTS. DRIVE LINE REMOVED. LESS BATTERIES. CAT C12 430 HP, Eaton 9 Speed, Air Suspension, 12 FA, 40 RA, 80 Gallon Aluminum Fuel Tank, Engine Brake, Wet Kit, Aluminum Wheels, 11R22.5, PTO, AC, Johnson Particulate Filters Level 3, Air Window Rams Missing. Showing 125,289 Miles. Location: San Bernardino, CA Serial: 1XPGDU9X91D569903	
<b>Lot #</b>	88	
<b>Qty</b>	1	
<b>Title</b>	2008 FORD F450 SUPER DUTY EXT CAB 4X4 XL SERVICE TRUCK	
<b>Des.</b>	NON RUNNER. DRIVE LINE DISCONNECTED. LESS BATTERIES. Ford Powerstroke 6.4L, Automatic, Spring Suspension, 6.5 FA, 12 RA, SE Inc Service Body, Steel Wheels, 225/70R19.5, AC, Body Damage/Rust. Showing 61,584 Miles. Location: San Bernardino, CA Serial: 1FDXX47R98EC09981	
<b>Lot #</b>	89	
<b>Qty</b>	1	
<b>Title</b>	1995 KENTUCKY VAN TRAILER	
<b>Des.</b>	48ft Length, 162in Width, 114in Height, Aluminum/Steel Composition, Spring Suspension, Sliding Tandem, Swing Doors, Wood Floor, Steel Wheels, 11R22.5, Rear Doors Rough. Location: Greenville, OH Serial: 1KKVA4820SL100655	

<b>Lot #</b>	90	
<b>Qty</b>	1	
<b>Title</b>	1996 MACK RD690S REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/ JUMP - NOT ROAD TESTED. ENGINE BLOW BY. DRUM DOES NOT SPIN. Mack EM7-300, T2070B 7 Speed, Walking Beam Suspension, 20 FA, 238 WB, 10.5 Yrd McNeilus Rear Mixer, Bridge Axle, 110 Cross Mount Water Tank, Steel Fuel Tank, Aluminum/Spoke Wheels, 425/65R22.5; 11R22.5, PTO, Dead Batteries, No Weight Tag, Bridge Axle Chained Up. Showing 239,756 Miles; 35,327 Hours. Location: Algonquin, IL Serial: 1M2P264C3TM021899	
<b>Lot #</b>	91	
<b>Qty</b>	1	
<b>Title</b>	2001 PETERBILT 385 DAY CAB TRUCK	
<b>Des.</b>	NON RUNNER. KNOWN ELECTRICAL ISSUES. DRIVE LINE MISSING. MISSING HUB TIRES AND AXLE #2 ON DRIVER'S SIDE. MISSING TWO AXLES #3. 3RD MEMBER IN REAR MISSING. CAT C12 430 HP, Eaton Fuller 9 Speed, Air Suspension, 12 FA, 40 RA, 80 Gallon Aluminum Fuel Tank, Engine Brake, Wet Kit, Aluminum Wheels, 11R22.5, PTO, AC, Johnson Particulate Filter Level 3. Showing 798,379 Miles. Location: San Bernardino, CA Serial: 1XPGDU9XX1D569893	
<b>Lot #</b>	92	
<b>Qty</b>	1	
<b>Title</b>	2002 STECO PUSHOUT TRAILER	
<b>Des.</b>	NO SERIAL TAG LOCATED ON UNIT. 50ft Total Length, 7.75ft Inside Height, Spring Suspension, Steel Composition, 4 Axles, 4 Lift Axles, Tarp System, Swing Door, Steel Wheels, 11R22.5, Latch Hooks For Rear Door Damaged (See Photos), Holes In Mesh Covering, Body Damage/Rust. Location: Portland, MI Serial: 5EWES488621253618	
<b>Lot #</b>	93	
<b>Qty</b>	1	
<b>Title</b>	1999 FORD F350 SUPER DUTY XL SERVICE TRUCK	
<b>Des.</b>	CRANKS, NO START. MISSING AC COMPRESSOR AND BOTH MIRRORS. Ford 7.3L Diesel, 5 Speed Manual, Spring Suspension, 4.25 FA, 9.75 RA, 141 WB, 9ft Knapheide Body, Steel Wheels, 215/85R16, PS, Interior Worn. Showing 296,329 Miles. Location: Houston, TX Serial: 1FDWF36F2XED68033	
<b>Lot #</b>	94	
<b>Qty</b>	1	
<b>Title</b>	2004 FORD F350 SUPER DUTY XL STAKE BODY TRUCK	
<b>Des.</b>	NON RUNNER. INTAKE HOSES OFF TURBO. BAD TURBO. LESS KEYS. Ford Power Stroke, Automatic, Spring Suspension, 4.55 FA, 9.75 RA, 165 WB, 12ft Steel Stake Body, Tommy Gate, Headache Rack, Steel Wheels, 235/65R16, AC, Flat Tires, Damage/Rust. Mileage Unavailable; Showing 17,169 Hours. Location: Concord, NC Serial: 1FDWF36P14ED48456	