Printable Catalog

Title OCTOBER 11 12:00 CDT

Description Closing Times TBD **Date** Wed, Oct 11, 2023

Starts at 12:00 PM

Address 4747 NE 14th St, Des Moines, IA 50313 USA

Categories

Lot # 1
Oty 1

Title 2013 CATERPILLAR CT660S SBA 6X4 CAB & CHASSIS

Des. NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Missing Items, Including: Dash, Fuel

Tank, Headlights, Battery Cables, Misc. Engine Components, Rear Tires Singled Out, Engine Tag Not Located, Body Damage Noted Throughout. Mileage Unavailable. Location: Des Moines, IA Serial:

1HTJGTKT3DJ304421

Lot # 2

Qty 1

Title 2002 MACK RD690S 6X4 REAR MIXER

Des. STARTED ON SITE, FULL OPERATIONS NOT TESTED. P/S Seat Worn, D/S Seat Torn, Holes Drilled In

Center Of Dash, Body Damage And Rust Throughout. Showing 102,930 Miles; 2,674 Hours. Location: South

Sioux City, NE Serial: 1M2P264C52M034149

Lot # 3

Qty 1

Title 2009 KENWORTH T800 6X4 DAY CAB TRUCK

Des. STARTED ON SITE, FULL OPERATIONS NOT TESTED. Aluminum Hydraulic Oil Tank. Air Slide Fifth

Wheel. Eaton Fuller Transmission. Has Rust Throughout Unit. Showing 608,782 Miles; 18,844 Hours.

Location: Thornville, OH Serial: 1XKDD40X09J247878

Lot # 4

Oty 1

Title 2018 JOHN DEERE 324E SKID LOADER

Des. NO TITLE PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED.

Missing Bucket Attachment, Missing Glass Panel On Front, Heavy Rust And Body Damage Throughout.

Showing 9,782 Hours. Location: Des Moines, IA Serial: 1T0324EJPHJ317022

Lot # 6

Qty 1

Title 2008 ETNYRE PRTN35TDPS FOLDING LOWBOY TRAILER

Des. FULL OPERATIONS NOT TESTED. Rust Throughout Unit. Deck Boards Are Weathered. Removable

Gooseneck With Front Load Ramps. Approximate Measurements: 50 FT Length, 60 IN Height, 103.2 IN

Width. Location: Thornville, OH Serial: 1E93007168E111291

Lot # 7

Qty 1

Title 2007 PETERBILT 357 WATER TRUCK

Des. NON RUNNER, FULL OPERATIONS NOT TESTED. Tire Flat And Off Rim, Body Damage And Rust

Throughout, Electrical Components Are Missing, Drive Shaft Removed- In Cab, P/S Dash Taped Up. Mileage

Unavailable. Location: McCrory, AR Serial: 1NPALFEX57D648434











Lot # 8

Oty 1

Title 2007 MACK CV513 8X4 REAR MIXER

Des.STARTED ON SITE, FULL OPERATIONS NOT TESTED. ENGINE OIL LEAK D/S FRONT CORNER AND AROUND OIL FILTER, Interior Is Worn And Stained, Rear Steps Bent, Paint Chips Throughout Unit.

Showing: 250,042 Miles; 23,105 Hours Location: South Sioux City, NE Serial: 1M2AG02C37M003092

Lot # 9

Oty 1

Title 2011 MACK GU813 CAB & CHASSIS

Des. NON RUNNER, FULL OPERATIONS NOT TESTED. MISSING MULTIPLE ENGINE COMPONENTS,

Dash Apart, Hood And Front Fenders Missing, D/S Seat Torn, Wiring Hanging From P/S, Rust Throughout.

Mileage Unavailable. Location: Lakeville, IN Serial: 1M2AX13C1BM014430

Lot # 10

Qty 1

Title 2008 KENWORTH T800 6X4 DAY CAB TRUCK

Des. STARTED ON SITE, FULL OPERATIONS NOT TESTED. Check Engine And ABS Warning Lights On

Dash, Engine Tag Not Located, Batteries Recently Replaced, Engine Oil Noted On Front And Pump, Crack In D/S Of Windshield, Rust Noted. Showing 458,989 Miles; 10,322 Hours. Location: Belpre, OH Serial:

1XKDD40X18J220008

Lot # 11

Qty 1

Title 1998 BOBCAT 773 SKID LOADER

Des. NO TITLE PER STATE REGULATIONS. NON RUNNER, FULL OPERATIONS NOT TESTED. Missing

Front Glass Panel, Rear Tire Flat And Off Rim, Rust And Body Damage Throughout. Hours Unavailable.

Location: Greenville, OH Serial: 509646513

Lot # 12

Oty 1

Title 1996 FONTAINE H1AB LOWBOY TRAILER

Des. FULL OPERATIONS NOT TESTED. Frame Rusted Through, Vin Tag Not Located, Approximate

Measurements: 48 FT Length, 96 IN Width, 11 FT Shipping Height. Location: Rochester, MN Serial:

13N24830XT1568340

Lot # 13

Oty 1

Title 2014 FREIGHTLINER M2 106 CAB & CHASSIS

Des. STARTED ON SITE, FULL OPERATIONS NOT TESTED. Brake And Engine Warning Lights On Dash,

Scan Tool Reads Active Fault Undefined, Rust Throughout. Showing 97,762 Miles; 20,744 Hours. Location:

Greenville, OH Serial: 1FVHCYCY3EHFR3668

Lot # 14

Qty 1

Title 2007 MACK CV513 8X4 REAR MIXER

Des. STARTED ON SITE, FULL OPERATIONS NOT TESTED. D/S OF ENGINE OIL PAN IS LEAKING, 7

INACTIVE SEE ECM REPORT, Right Rear Lower Tail Light Out, Holes Drilled In Dash, Adhesive Residue On Dash, Seats Do Not Match And Are Stained. Showing: 244,745 Miles; 24,473 Hours. Location: South

Sioux City, NE Serial: 1M2AG02C87M003475













Lot # 15

Oty 1

2013 MACK CXU613 6X4 DAY CAB TRUCK Title

STARTED ON SITE, FULL OPERATIONS NOT TESTED. Check Engine Warning Light On Dash, 3 Des. Active/4 Inactive Fault Codes Detected- See ECM Report, Needs Regen Derate, Engine Oil Leak At Oil Fill Tube Mounting Flange, Floor Damaged, Missing P/S Window Crank, Rust And Body Damage Throughout.

Showing 329,543 Miles; 13,174 Hours. Location: Berlin, WI Serial: 1M1AW09Y7DM029733

Lot # 17

Qty 1

Title 1998 MACK RD688SX CAB & CHASSIS

NON RUNNER, FULL OPERATIONS NOT TESTED. Head Lights Are Missing, Dash Taped Up On P/S, Des.

Rust Throughout. Showing 271,989 Miles. Location: Attleboro, MA Serial: 1M2P268C2WM034223

Lot # 18

Qty 1

Title 2003 BOBCAT SKID LOADER

NO TITLE PER STATE REGULATION. NON RUNNER. HOURS UNAVAILABLE. LESS KEYS. Des.

Location: Buckeye, AZ Serial: 512266006

Lot # 19

Qty 1

2002 MACK RD690S 6X4 REAR MIXER Title

STARTED ON SITE, FULL OPERATIONS NOT TESTED. Windshield Is Cracked, Seats Torn, Rear Steps Des. Are Bent, Paint Faded And Rock Chips Throughout Unit. Showing: 70,489 Miles; 23,415 Hours. Location:

Wisner, NE Serial: 1M2P264C32M034151

Lot # 20

Qty 1

Title 2000 MACK RD688S CAB & CHASSIS

NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, TRANSMISSION REMOVED, Rear Des.

Outer Tire On L/S Is Flat, Body Damage Noted, Missing Grill And Bulldog Ornament, Misc. Items In Cab.

Showing 235,497 Miles; 9,954 Hours. Location: Harrisburg, PA Serial: 1M2P267CXYM048391

Lot # 21

1 **Qty**

2007 MACK CV713 CAB & CHASSIS Title

STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Bulldog Ornament Missing From Des.

Hood, Low Air And Electrical Warnings On Dash, D/S Hood Mirror Missing, Rust And Body Damage

Throughout. Showing 599,183 Miles; 35,372 Hours. Location: Newark, NJ Serial: 1M2AG11C97M058346

22 Lot #

1 **Qty**

Title 1995 VOLVO WG64T DAY CAB TRUCK

NON RUNNER, FULL OPERATIONS NOT TESTED. BAD ENGINE, Missing Items, Including: Instrument Des. Cluster, Fuses And Relays, P/S Steps, Has Callahan Attachment, D/S Rear Tires Singled Out, Rust And Body

Damage Throughout. Mileage Unavailable. Location: East Dublin, GA Serial: 4V2JCBPE7SR837607













Lot # 23

Qty 1

Title 2005 KENWORTH T300 4X2 DUMP TRUCK

Des.NON RUNNER, FULL OPERATIONS NOT TESTED. MISSING BATTERIES AND IGNITION, Dash Apart, No Engine Or VIN Tags Located, Rust Throughout. Showing 244,715 Miles; 3,650 Hours. Location:

Newark, NJ Serial: 2NKMHD7X75M079373

Lot # 25

Oty 1

Title 2009 PETERBILT 365 CAB & CHASSIS

Des.NON RUNNER, FULL OPERATIONS NOT TESTED. ENGINE DISASSEMBLED- Misc Engine Parts In Cab On P/S, D/S Mirror Missing, P/S Bumper Pushed Out, P/S Steps Bent, Rear Tires Singled Out, Steering

Wheel Damaged/Taped, Rust And Body Damage Throughout. Showing 481,006 Miles; 7,783.9 Hours.

Location: Newark, NJ Serial: 1NPSL00X19D787228

Lot # 26

Qty 1

Title 2007 MACK CV513 8X4 REAR MIXER

Des. STARTED ON SITE, FULL OPERATIONS NOT TESTED. ENGINE OIL LEAK FRONT P/S CORNER,

Right Marker Light Out And Right Rear Upper Light Out, Dash Has Drill Holes In It, Interior Is Worn And Stained, Scratches Throughout Unit. Showing: 190,874 Miles; 24,746 Hours. Location: Wisner, NE Serial:

1M2AG02C17M003091

Lot # 27

Oty 1

Title 1999 GEHL 5635SXT SKID LOADER

Des. NO TITLE PER STATE REGULATIONS. NON RUNNER, FULL OPERATIONS NOT TESTED. LESS

KEY, Serial Plate Not Located, Missing Front And Rear Glass, Scrapes, Scratches And Rust Throughout.

Showing 1,955 Hours. Location: Buckeye, AZ Serial: 500167

Lot # 28

Oty 1

Title 2012 INTERNATIONAL WORKSTAR 7400 SBA 6X4 MANUAL SIDELOAD

GARBAGE PACKER

Des. NON RUNNER, FULL OPERATIONS NOT TESTED. DEAD BATTERIES, Engine Oil Pan Gasket Is

Leaking All Around, Grill Missing Bar, P/S Seat Mount Is Broken, Rust And Body Damage Throughout.

Mileage Unavailable. Location: Saint Paul, MN Serial: 1HTWGAZT4CJ437400

Lot # 30

Qty 1

Title 2015 MACK CXU613 6X4 DAY CAB TRUCK

Des. STARTED ON SITE, FULL OPERATIONS NOT TESTED. Left 2 Center Cab Markers Out. Chips In

Windshield. Bumper Guard Is Dented And Cracked. Left Side Fender Is Cracked. Interior Is Stained.

Showing 657,336 Miles. Location: Tacoma, WA Serial: 1M1AW09Y7FM045515

Lot # 31

Qty 1

Title 2007 MACK CV513 8X4 REAR MIXER

Des.STARTED ON SITE, FULL OPERATIONS NOT TESTED. Paint Chips And Scrathes Throughout Unit, Holes In Dash, Missing HVAC Knob, Instrument Cluster Lens Cracked, Seats Are Worn With Holes, Door

Panels Damaged. Showing: 194,043 Miles; 18,443 Hours. Location: Omaha, NE Serial:

1M2AG02C57M003479













Lot # 32

Oty 1

Title 2007 MACK CV713 CAB & CHASSIS

Des.

NON RUNNER, FULL OPERATIONS NOT TESTED. MISSING ELECTRICAL SOLENOID ON FIREWALL, Missing D/S Head Light And Tail Lights, Rust And Body Damage Throughout. Mileage

Unavailable. Location: Adel, GA Serial: 1M2AG11C97M058203

Lot # 33

Qty 1

Title 2001 MACK RD688S CAB & CHASSIS

Des. NON RUNNER, FULL OPERATIONS NOT TESTED. Rust Throughout, Holes Drilled In Dash, Spray Paint

On Cab. Showing 213,055 Miles; 33,151 Hours. Location: Adel, GA Serial: 1M2P267C11M057955

Lot # 35

Qty 1

Title CASE 1838 SKID LOADER

Des. NO TITLE PER STATE REGULATIONS. NON RUNNER, FULL OPERATIONS NOT TESTED. R/S

Front Tire Is Flat And Off Bead, Tires Worn, Seat Cover Torn, Body Damage And Rust Throughout.

Showing 2,509 Hours. Location: Miami, FL Serial: JAF0220918

Lot # 36

Qty 1

Title 2011 MACK GU713 CAB & CHASSIS

Des. NON RUNNER, FULL OPERATIONS NOT TESTED. Missing Items, Including: Hood, Head Lights,

Engine Components, D/S Seat. Mileage Unavailable. Location: McComb, MS Serial:

1M2AX04C5BM008820

Lot # 37

Qty 1

Title 2003 MACK RD688S CAB & CHASSIS

Des. STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. Drive Shaft Removed-

In Cab, D/S Seat Torn, Missing Gauges In Center Dash, Rust And Body Damage Throughout. Showing

166,157 Miles. Location: McComb, MS Serial: 1M2P267C03M066746

Lot # 38

Qty 1

Title 2007 MACK CV513 8X4 REAR MIXER

Des. STARTED ON SITE, FULL OPERATIONS NOT TESTED. Engine Oil Leak Noted By Engine Fill Tube,

Mounting Area, Dash Components Missing, Instrument Panel Damage. Showing 174,518 Miles; 15,941

Hours.

Lot # 39

Qty 1

Title 2015 MACK CXU613 6X4 DAY CAB TRUCK

Des. STARTED ON SITE, FULL OPERATIONS NOT TESTED. Oil Leaking From Oil Pan. Check Engine Light

Is On. Paint Chips And Dents Throughout Unit. Showing 539,144 Miles; 20,938 Hours. Location: Tacoma,

WA Serial: 1M1AW09Y9FM045516













Lot # 41

Oty 1

2006 MACK CV713 CAB & CHASSIS Title

NON RUNNER, FULL OPERATIONS NOT TESTED. Odometer Cracked, Rust And Body Damage Des.

Throughout. Mileage Unavailable. Location: McComb, MS Serial: 1M2AG11C36M034879

Lot # 43

1 Qty

Title 2004 CATERPILLAR 420D BACKHOE

NO TITLE PER STATE REGULATIONS. NON RUNNER, FULL OPERATIONS NOT TESTED. KNOWN Des.

TRANSMISSION ISSUES, Unable To Open Engine Compartment, Front Tire Flat And Off Rim, Rust And

Body Damage Throughout. Hours Unavailable. Location: Greenville, OH Serial: CAT0420DPFDP15542

44 Lot #

Oty 1

Title 2007 MACK CV713 CAB & CHASSIS

STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Low Air Warning On Dash, P/S Seat Des.

Torn, Rust And Body Damage Throughout. Showing 302,246 Miles; 26,282.9 Hours. Location: McCrory, AR

Serial: 1M2AG11C27M045969

Lot # 45

Oty 1

2006 MACK CV713 CAB & CHASSIS Title

NON RUNNER, FULL OPERATIONS NOT TESTED. DEAD BATTERIES, DRIVE SHAFT BROKEN Des.

AND REMOVED- W/ TRUCK LAYING ON FRAME, Shifter Missing Cap, Transmission Leaking, Hydraulics Leaking, Power Steering Leaking, D/S Head Lamp And Both Sides Rear Lights Missing, Exhaust Heat Shield Is Bent, Rust And Body Damage Throughout. Mileage Unavailable. Location: Oklahoma City,

OK Serial: 1M2AG11C06M043118

Lot # 46

1 **Qty**

2015 PETERBILT 365 REAR MIXER Title

STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. DOES NOT DRIVE, Des.

Transmission Warning, Check Engine, ABS And Low Air Warning Lights On Dash, Does Not Build Sufficient Air, Continental Mixer Paving Mixer Drum, Rust Throughout. Showing 209,105 Miles; 19,696

Hours. Location: Conroe, TX Serial: 1NPSX7EX8FD273393

Lot# 47

Qty 1

Title 2006 FREIGHTLINER COLUMBIA 12064S 6X4 DAY CAB TRUCK

STARTED ON SITE, FULL OPERATIONS NOT STARTED. Reader Connection Not Working, Chrome Des.

Peeling On Grille, Bumper Rusted, Seats Stained And Worn, Paint Chipped And Peeling. Showing: 825,613

Miles; 27,688 Hours. Location: Tacoma, WA Serial: 1FUJA6CK56LV98491

Lot # 49

Qty 1

Title 2006 MACK CV713 CAB & CHASSIS

NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Weight Tag And Engine Tag Not Des. Located, Missing Bull Dog Ornament From Hood And Some Tail Lights, Cracked Glass On Odometer Cover,

Rust Throughout. Mileage Unavailable. Location: Weatherford, TX Serial: 1M2AG11C86M046770













Lot # 50

Oty 1

Title 2016 FREIGHTLINER CASCADIA 113 6X4 SLEEPER TRUCK

Des. STARTED ON SITE, FULL OPERATIONS NOT TESTED. R/S Front Corner Bumper Has A Broken Bracket, Sleeper Mattress Is Missing. Showing 529,707 Miles; 19,145 Hours. Location: Newark, NJ Serial:

1FUJGHDV4GLGN7635

Lot # 51

Oty 1

Title 2015 PETERBILT 365 REAR MIXER

Des. STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Oil Leaking From Back Of Oil Pan,

Cracked Windshield, Continental Mixer Paving Mixer Drum, Rust Throughout. Showing 175,910 Miles;

18,418 Hours. Location: Conroe, TX Serial: 1NPSX7EX9FD273404

Lot # 52

Qty 1

Title 2018 JOHN DEERE 323E TRACK LOADER

Des. NO TITLE PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED.

Warning Lights On Dash, Oil Leaks, Arms Are Cracked, Missing Bucket Attachment, Body Damage And Rust Throughout, Tracks Worn. Showing 6,232 Hours. Location: Marshville, NC Serial: 1T0323EJCJJ325814

Lot # 53

Qty 1

Title 2015 FORD F750 SUPER DUTY 4X2 CAB & CHASSIS

Des. STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. ABS Warning Light On Dash, D/S

Door Does Not Properly Shut, Engine Tag Not Located, Ford Emblem Missing From Front Grill, Misc. Parts In Cab, Rust Throughout. Showing 352,258 Miles. Location: Weatherford, TX Serial: 3FRXF7FE2FV658964

Lot # 54

Qty 1

Title 2002 INTERNATIONAL 4700 DAY CAB TRUCK

Des. STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. LESS KEY, Weight

And Engine Tag Not Located, Missing Headlights And Grill, Rust And Body Damage Throughout. Showing

107,919 Miles; 2,615 Hours. Location: Weatherford, TX Serial: 1HTSCAAN92H511374

Lot # 56

Qty 1

Title 2005 MACK CV713 CAB & CHASSIS

Des.

NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Electrical And ABS Warning Lights On Dash, Missing Items, Including: Transmission, P/S Windshield, Headlights Both Sides, Bulldog Ornament From Hood, Rear Tires Singled Out, Ayle Weight Tag And Engine Tag Not Located, Misc. Parts In Cab, Rust

From Hood, Rear Tires Singled Out, Axle Weight Tag And Engine Tag Not Located, Misc. Parts In Cab, Rust And Body Damage Throughout. Showing 903,087 Miles; 31,651 Hours. Location: Weatherford, TX Serial:

1M2AG11C25M022429

Lot # 57

Qty 1

Title 2015 PETERBILT 365 REAR MIXER

Des. STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. ABS And Check Engine Light On, Does Not Build Secondary Air, Blown Tire On Push Axle, Continental Mixers Paving

Mixer Drum. Showing 182,710 Miles; 17,889 Hours. Location: Conroe, TX Serial: 1NPSX7EX1FD278466

W.











Lot # 58

Oty 1

Title 2013 VOLVO VNL 6X4 SLEEPER TRUCK

Des. STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. NEEDS 4 NEW BATTERIES, SOME PARTS OF EMISSIONS SYSTEM HAVE BEEN DELETED, Scan Indicates Issues

With The Following: EGR Sensor, Intake Manifold Pressure Sensor, Injector Metering Rail Pressure, Rust Noted, D/S Door Does Not Open From Outside. Showing 769,429 Miles. Location: Mulberry, FL Serial:

4V4NC9TG5DN563732

Lot # 59

Qty 1

Title 1998 TRAIL KING TK70LCS-482 FLATBED TRAILER

Des. FULL OPERATIONS NOT TESTED. Hole In Deck, Boards Weathered, Approximate Measurements: 48 FT Shipping Length, 110 IN Shipping Width, 4.9 FT Shipping Height. Location: Bradford, OH Serial:

1TKB04825WG070172

Lot # 60

Oty 1

Title 2015 FORD F750 4X2 PICKUP TRUCK

Des. STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Grill Is Missing, Interior Soiled, Part

Of Dash Damaged On L/S Of Steering Wheel, Body Damage Throughout. Mileage Unavailable. Location:

McComb, MS Serial: 3FRWF7FC2FV653385

Lot # 61

Oty 1

Title 2009 MACK GU813 CAB & CHASSIS

Des. NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Missing Items, Including: Ignition,

Transmission, Engine Components, Fan Assembly, Parts Of Fuel Rail, Steering Wheel, And Tail Lights, Rear Tires Singled Out, Hole In Cab Floor, Rust And Body Damage Throughout. Mileage Unavailable. Location:

Weatherford, TX Serial: 1M2AX13C49M002069

Lot # 62

Qty 1

Title 2007 CATERPILLAR P50001 FORKLIFT

Des.NO TITLE PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. LP TANK TO BE REMOVED PRIOR TO SALE. All Lights Are INOP, Tires Worn, Heavy Rust Noted, Seat

Heavily Damaged. Showing 1,283 Hours. Location: Starke, FL Serial: AT3510692

Lot # 63

Oty 1

Title 2015 PETERBILT 365 REAR MIXER

Des. STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Check Engine Warning Light On Dash, Hydraulic Fluid Leaking From Tank Pressure Gauge, No Chutes, Drum Is Thin And Leaking, Does Not

Dash, Hydraulic Fluid Leaking From Tank Pressure Gauge, No Chutes, Drum Is Thin And Leaking, Does Not Build Secondary Air, Cracked Windshield, Continental Mixers Paving Mixer Drum. Showing 196,996 Miles;

16,001 Hours. Location: Conroe, TX Serial: 1NPSX7EX5FD278471

Lot # 65

Qty 1

Title 2005 MACK CV713 CAB & CHASSIS

Des.

NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, NO BATTERIES, Weight Tag And Engine Tag Not Located, Missing D/S Hood Mirror, Dash Apart On P/S, Rust And Body Damage

Throughout. Mileage Unavailable. Location: Wetaherford, TX Serial: 1M2AG11C15M023989













Lot # 67

Qty 1

Title 2008 CLUB CAR CARRYALL 294 4X4 UTV

Des.NO TITLE PER STATE REGULATIONS. STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Seat Cover Is Not Attached. Showing 800 Hours. Location: Des Moines, IA Serial:

GC0518-501420

Lot # 68

Qty 1

Title 1997 YALE GLP050RFNUAE086 FORKLIFT

Des. NO TITLE PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. LP

TANK TO BE REMOVED PRIOR TO SALE. Rear Amber Lights Do Not Work, Rear Tires Have Chunks Of Tread Missing, Rubber Pad On Brake Pedal Missing, Dashboard Trim Is Loose, Rust And Body Damage

Throughout. Showing 9,099 Hours. Location: Doswell, VA Serial: E177B10004T

Lot # 70

Qty 1

Title 2015 PETERBILT 365 REAR MIXER

Des. STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. ABS LIGHT ON,

Drum Data Tag Not Located, Rust Throughout. Showing 184,384 Miles; 17,847 Hours. Location: Conroe, TX

Serial: 1NPSX7EX1FD278483

Lot # 71

Qty 1

Title 2006 ISUZU NPR FLATBED TRUCK

Des. STARTED ON SITE, FULL OPERATIONS NOT TESTED. THE RELEASE LATCHES TO TILT THE

CAB ARE HEAVILY RUSTED AND SEIZED, UNABLE TO TILT THE CAB TO GET ANY ENGINE INFORMATION, BRAKES ARE WORN, Rust Throughout Unit, Worn Tires. Showing 339,508 Miles.

Location: Starke, FL Serial: JALC4B16167015685

Lot # 72

Oty 1

Title 2005 FORD F250 PICKUP TRUCK

Des. NON RUNNER, FULL OPERATIONS NOT TESTED. D/S Seat Torn, Body Damage And Rust Throughout.

 $\label{eq:mileage} \mbox{Mileage Unavailable. Location: Buckeye, AZ Serial: 1FTNF20595EC90390}$

Lot # 73

Oty 1

Title 2006 MACK CT713 CAB & CHASSIS

Des.NON RUNNER, FULL OPERATIONS NOT TESTED. ABS And Electrical Warning Lights On Dash, Missing Items, Including: Batteries, Hood Vent Cover On D/S, Dash Apart, Weight And Engine Tags Not

Located. Showing 968,892 Miles; 27,513 Hours. Location: Weatherford, TX Serial: 1M2AL02CX6M003455

Lot # 74

Qty 1

Title 2003 DAEWOO G30S FORKLIFT

Des. NO TITLE PER STATE REGULATIONS. NON RUNNER, FULL OPERATIONS NOT TESTED. Oil Leak

From Valve Cover, Front Work Lights INOP, Axle Wheel Arm Broken On R/S Rear And Dragging, L/S Rear Tire Cut, Seat Torn, Rust And Body Damage Throughout. Showing 11,324 Hours, Location: Berlin, WI

Serial: 1209018













Lot # 75

Qty 1

Title 1996 WABASH VAN TRAILER

FULL OPERATIONS NOT TESTED. Door Propped Open, VIN Number Has Been Reissued, Approximate Des.

Measurements: 53 FT Length, 102 IN Width. Location: Des Moines, IA Serial: IA045731

76 Lot #

Qty 1

Title 2015 PETERBILT 365 REAR MIXER

NON RUNNER, FULL OPERATIONS NOT TESTED. CRANK- NO START, Front Axle Removed And In Des. Cab, Rust Throughout. Showing 160,808 Miles; 17,978 Hours. Location: Conroe, TX Serial:

1NPSX7EX3FD273396

78 Lot #

Oty 1

2005 FORD F550 FLATBED TRUCK Title

NON RUNNER, FULL OPERATIONS NOT TESTED. Seats Tattered, Dash Apart Under Steering Wheel, Des.

Various Rust And Body Damage. Mileage Unavailable. Location: Serial: 1FDAW57P25EC21107

79 Lot #

1 Qty

Title 2002 GALBREATH A5-0R-250 ROLLOFF TRAILER

FULL OPERATIONS NOT TESTED. Broken Hydraulic Hoses, Body Damage And Rust, Approximate Des.

Measurements: 32 FT Length. Location: Adel, GA Serial: 1G9F127262A157416

82 Lot #

Qty 1

Title 2007 INTERNATIONAL PAYSTAR 5600i 6X4 REAR MIXER

STARTED ON SITE, FULL OPERATIONS NOT TESTED. DRUM NOTED AS THIN. ENGINE BLOW Des.

BY. Tailights And Rear Bumper Missing, Body Damage/Rust Throughout. Showing 258,314 Miles; 30,415 Hours. Location: Duluth, GA Serial: STARTED ON SITE, FULL OPERATIONS NOT TESTED. DRUM NOTED AS THIN. ENGINE BLOW BY. Tailights And Rear Bumper Missing, Body Damage/Rust

Throughout. Showing 258,314 Miles; 30,415 Hours.

Lot# 84

Qty 1

Title 2009 WOODS MOWER ATTACHMENTS

NO TITLE PER STATE REGULATIONS. FULL OPERATIONS NOT TESTED. Rust Throughout, Des.

Approximate Measurements: Mower Deck 120 IN Length, 66 IN Width. Location: Des Moines, IA Serial:

2178020114E1050309ZA

Lot # 86

Qty 1

Title 2001 G&H TBX-50 ROLLOFF TRAILER

FULL OPERATIONS NOT TESTED. Tarp System Is Missing Parts, Rust Throughout, Approximate Des. Measurements: 50.1 FT Shipping Length, 102 IN Width. Location: Buckeye, AZ Serial:

1G9TX50291A116001













Lot # 87

Qty 1

Title WACKER LTC4L LIGHT TOWER



