



## Printable Catalog

<b>Title</b>	OCTOBER 22ND 12:00 CST	
<b>Description</b>	Closing Times TBD	
<b>Date</b>	Wed, Oct 22, 2025	
<b>Starts at</b>	12:00 PM	
<b>Address</b>	4747 NE 14th St, Des Moines, IA 50313 USA	
<b>Categories</b>		


---

<b>Lot #</b>	1	
<b>Qty</b>	1	
<b>Title</b>	2013 MACK CXU613 PINNACLE DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. WARNING LIGHTS ILLUMINATED. Showing: 569,589 Miles. Location: Adel, GA Serial: 1M1AW09Y9DM030351	


---

<b>Lot #</b>	1	
<b>Qty</b>	1	
<b>Title</b>	2012 MACK CXU613 PINNACLE DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE W/JUMP, FULL OPERATIONS NOT TESTED. WARNING LIGHTS ILLUMINATED. Showing: 498,393 Miles. Location: Adel, GA. Serial: 1M1AW09Y4CM024553.	


---

<b>Lot #</b>	1	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CV513 GRANITE REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing: 191,730 Miles; 23,857 Hours. Location: Ankeny, IA. Serial: 1M2AG02C47M002906.	


---

<b>Lot #</b>	1	
<b>Qty</b>	1	
<b>Title</b>	2009 MACK GU813 GRANITE CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. LESS KEYS, BODY DAMAGE: HOOD CRACKED, D/S HEADLIGHT MISSING, WIRING FOR D/S MIRROR CUT, P/S HOOD LATCH MISSING, INTERIOR DASH IS DISASSEMBLED, NO POWER. Showing: Mileage/Hours Unavailable. Location: Seminole, TX. Serial: 1M2AX13C29M004368.	


---

<b>Lot #</b>	1	
<b>Qty</b>	1	
<b>Title</b>	2008 MACK GU813 GRANITE CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. LESS KEYS. Showing: Mileage/Hours Unavailable. Location: Attleboro, MA. Serial: 1M2AX13C38M002627.	


---

<b>Lot #</b>	1	
<b>Qty</b>	1	
<b>Title</b>	2019 HINO XJC740/XFC740 STRAIGHT TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. CAB SWAPPED. FRAME STAMP MATCHES TITLE. REEFER UNIT AND BOX SHOW MANUFACTURING DATES OF 2014/2015. Showing 81,731 Miles. Location: Labelle, FL Serial: 1JHHSPM2H6KK002046	


---

<b>Lot #</b>		
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CV713 GRANITE CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. LESS KEYS, P/S DASH COVER REMOVED. Showing: Mileage/Hours Unavailable. Location: Attleboro, MA. Serial: 1M2AG11C97M056287.	


---

<b>Lot #</b>		
<b>Qty</b>	1	
<b>Title</b>	2001 MACK RD688S REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. LESS DRUM. Showing: 51,736 Miles; 4,290 Hours. Location: Ankeny, IA. Serial: 1M2P267C21M058239.	


---

<b>Lot #</b>		
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CV713 GRANITE CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. NO POWER, DASH DISASSEMBLED, REAR TIRES SINGLED OUT, DROP AXLE NO TIRES. Showing: Mileage/Hours Unavailable. Location: Hagerstown, MD. Serial: 1M2AG11C27M068779.	

---

<b>Lot #</b>		
<b>Qty</b>	1	
<b>Title</b>	2005 MACK CV713 GRANITE CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. HOOD DAMAGE, REAR TIRES SINGLED OUT. Showing: 989,446 Miles; 44,502 Hours. Location: Jacksonville, FL. Serial: 1M2AG11C85M021088.	

---

<b>Lot #</b>		
<b>Qty</b>	1	
<b>Title</b>	KOBELCO SK270 EXCAVATOR	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. STARTED ON SITE W/JUMP, FULL OPERATIONS NOT TESTED. RUST FORMING IN VARIOUS AREAS. Showing: 8,985 Hours. Location: Mulberry, FL. Serial: LBU0024.	