



## Printable Catalog

<b>Title</b>	OCTOBER 30 12:00 CDT	
<b>Description</b>	Closing Times TBD	
<b>Date</b>	Wed, Oct 30, 2019	
<b>Starts at</b>	12:00 PM	
<b>Address</b>	4747 NE 14th St, Des Moines, IA 50313 USA	
<b>Categories</b>		


---

<b>Lot #</b>	1	
<b>Qty</b>	1	
<b>Title</b>	1992 MACK CH613 DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. Mack E7-350-4VH, Eaton Fuller RTO14613, Spring Suspension, 212 WB, 16ft Steel Body, Dual 90 Gallon Aluminum Fuel Tanks, Aluminum/Steel Wheels, 315/80R22.5; 11R24.5, PTO, AC, Pintle Hitch, Dead Batteries, Body Damage/Rust. Showing 15,628 Miles; 28,864 Hours. Location: Colville, WA Serial: 1M2AA13YXNW014657	


---

<b>Lot #</b>	2	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CT713 REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. ENGINE BLOW BY. Mack AMI-335 ASET, Maxitorque T310MLR, Camelback Suspension, 20 FA, 46 RA, 208 WB, 11 Yrd McNeilus Rear Mixer, Steel Fuel Tank, 125 Gallon Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, ABS Warning Light Illuminated, Air Cleaner In Cab, Body Damage/Rust. Showing 141,936 Miles; 1,790 Hours. Location: Des Moines, IA Serial: 1M2AL02CX6M004170	


---







<b>Lot #</b>	3	
<b>Qty</b>	1	
<b>Title</b>	2002 FREIGHTLINER ARGOSY FUEL TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Detroit Diesel Series 60 550 HP, Eaton Fuller 18 Speed, Air Ride Suspension, 24 FA, 40 RA, 292 WB, 5,000 Gallon Capacity Advance Body, 12,350 Lbs Drop Axle, Aluminum/Steel Wheels, 285/75R24.5; 11R22.5, Body Damage/Rust. Showing 661,093 Miles. Location: Spokane, WA Serial: 1FVSAWCK32LJ59896	







---







<b>Lot #</b>	4	
<b>Qty</b>	1	
<b>Title</b>	1999 VOLVO WG64 ROLLOFF TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. LOW ON COOLANT. Oil Seepage At Pan/Rear Seal, Hoses, And Transmission, Right Turn Signal Not Working, Right Tail Light Not Working, No Brake Lights, Cable Not Working, Cracked Hood, Dump Cover Torn, Windshield Chipped, ABS Light Illuminated, Various Body Damage/Rust. Showing 19,844 Miles; 912 Hours. Location: Springfield, MO Serial: 4VHJCBPFIYN866629	






---








<b>Lot #</b>	5	
<b>Qty</b>	1	
<b>Title</b>	2008 FORD F550 SERVICE TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. CRANE INOPERABLE. Oil Seepage Noted At Oil Pan, Dead Batteries, Multiple Warning Lights Illuminated - See Photos, Various Body Damage/Rust. Showing 166,824 Miles; 9,029 Hours. Location: Mokena, IL Serial: 1FDAF56R68EA75639	

<b>Lot #</b>	6	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CT713 GARBAGE PACKER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Oil Seepage At Pan/Rear Seal, Bright Lights Don't Work, Light Missing At Rear, Few Gauges Missing, Rear Compactor Goes Down But Does Not Go Up, Air Horn Inop., Windshield Chipped, Active Fault Codes - See Report, Inner Rear Dual Tires Missing, Body Damage/Rust. Showing 254,982 Miles; 20,113 Hours. Location: Springfield, MO Serial: 1M2AL02C66M003422	
<b>Lot #</b>	9	
<b>Qty</b>	1	
<b>Title</b>	1995 INTERNATIONAL 9300 DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Cummins N14, Eaton 18 Speed, Walking Beam Suspension, 225 WB, 15.25ft Steel Body, Air Lift Pusher Axle, Aluminum Fuel Tank, Tarp System, Steel Wheels, 11R24.5, PTO, Pintle Hitch, Dead Batteries, Body Damage/Rust. Showing 672,399 Miles; 1,796 Hours. Location: Pendleton, OR Serial: 2HSFBAER2SC016804	
<b>Lot #</b>	10	
<b>Qty</b>	1	
<b>Title</b>	2007 KENWORTH W900B REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. ENGINE BLOW BY. Schwing 10.5 YRD. Bridge Mixer, Oil Leaks Noted At Pan/Rear Seal, Both Sides Of Block, And Front Cover, Multiple Lights Inoperable - See Report, Various Body Damage/Rust. Showing 184,771 Miles; 17,076 Hours. Location: Algonquin, IL Serial: 1NKWL00X77J172835	
<b>Lot #</b>	11	
<b>Qty</b>	1	
<b>Title</b>	2005 MACK CH613 ROLLOFF TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. LOW COOLANT. CLUTCH NEEDS ADJUSTMENT. Oil Leak At Pan/Rear Seal, Bright Lights Do Not Work, Wipers Inop., Could Not Get Hydraulics To Function, Hood Cracked, Dump Cover Torn, Windshield Cracked, Body Damage/Rust. Showing 612,650 Miles; 34,764 Hours. Location: Springfield, MO Serial: 1M1AJ06Y35N001555	
<b>Lot #</b>	13	
<b>Qty</b>	1	
<b>Title</b>	1977 MACK CRASH ATTENUATOR TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. TITLE BRANDED RECONSTRUCTED. Mack Diesel, 5 Speed Manual, 172 WB, Concrete Weight, Arrow Board, Energy Absorption, Spoke Wheels, 11R22.5, Dead Batteries, Body Damage/Rust. Showing 529,510 Miles; 6,312 Hours. Location: Wapwallopen, PA Serial: R686ST12587	
<b>Lot #</b>	14	
<b>Qty</b>	1	
<b>Title</b>	2005 FREIGHTLINER FL80 GARBAGE PACKER	
<b>Des.</b>	NON RUNNER - NO POWER. DRIVE SHAFT REMOVED. Oil Leaks Noted At Pan/Rear Seal And Right Side Of Block, Coolant Cap Missing, Fuel Cap Missing, Dash Apart, Various Body Damage/Rust. Mileage Unavailable. Location: Joplin, MO Serial: 1FVACYCS25HN87922	







<b>Lot #</b>	15	
<b>Qty</b>	1	
<b>Title</b>	2004 KENWORTH T300 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. CAT C7 Diesel, Automatic, Spring Suspension, 176 WB, 56 Gallon Aluminum Fuel Tank, 137in Back Cab To End Frame, Steel Wheels, 11R22.5, AC, Body Damage/Rust. Showing 375,240 Miles; 912 Hours. Location: Harrisburg, PA Serial: 2NKMHD6X44M066533	
<b>Lot #</b>	16	
<b>Qty</b>	1	
<b>Title</b>	2003 CATERPILLAR M316C WHEELED EXCAVATOR	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED ON SITE. CAT 3056E DIT ATAAC- 138HP, Hydrostatic 2 F/R, F/R Outriggers, Wain Roy Tilting Coupler/Ditching Bucket, CF hydraulic Thumb, 16ft 7in Single Piece Boom, 8.5ft Stick, 18-18.5 Flotation Tires, EROPS. Showing 8,997 Hours. Location: Cedar Rapids, IA Serial: CATM316CLBDX00460	
<b>Lot #</b>	17	
<b>Qty</b>	1	
<b>Title</b>	2009 INTERNATIONAL 7700 DUMP TRUCK	
<b>Des.</b>	NON RUNNER - BAD ENGINE. CAT Rebuild, Automatic, Hendrickson Suspension, 20 FA, 46 RA, 265 WB, 18.75ft Steel Strong Body, Aluminum Fuel Tank, Tarp System, Drop Axles, Aluminum Wheels, 385/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 296,104 Miles; 7,071 Hours. Location: Spokane, WA Serial: 1HTTVSBTX9J139161	
<b>Lot #</b>	20	
<b>Qty</b>	1	
<b>Title</b>	1999 VOLVO WG64 ROLLOFF TRUCK	
<b>Des.</b>	NON RUNNER - UNIT HAD SOME POWER BUT NOT ENOUGH TO START. NO COOLANT IN THE TANK. Oil Leaks Noted At Both Sides Of Block And Pan/Rear Seal, Right Rear Turn Signal Doesn't Work, Dash Apart, Windshield Chipped, Various Body Damage/Rust. Showing 66,989 Miles (Hubodometer Showing 80,380 Miles). Location: Joplin, MO Serial: 4VHJCCBE6XN864640	
<b>Lot #</b>	21	
<b>Qty</b>	1	
<b>Title</b>	1995 CHEVY C3500 SERVICE TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. GMC 5.7L V8, Automatic, 161 WB, 11ft Phoenix Body, Steel Wheels, 225/75R16, Check Engine Light Illuminated, Body Damage/Rust. Showing 119,268 Miles. Location: Pittston, PA Serial: 1GBJC34K1SE115080	
<b>Lot #</b>	23	
<b>Qty</b>	1	
<b>Title</b>	2009 PETERBILT 335 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Paccar PX-6 300 HP, Automatic, Spring Suspension, 10 FA, 23 RA, 169 WB, 60 Gallon Aluminum Fuel Tank, 135in Back Cab To End Frame, Steel Wheels, 295/75R22.5, AC, Needs New Batteries, Body Damage/Rust. Showing 189,470 Miles; 2,658 Hours. Location: Harrisburg, PA Serial: 2NPLHM7X19M779109	








<b>Lot #</b>	24	
<b>Qty</b>	1	
<b>Title</b>	2005 OSHKOSH S2346 FRONT MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. ENGINE BLOW BY. CAT C13, Automatic, Air Ride Suspension, 22 FA, 42 RA, 196 WB, 10.5 Yrd McNeilus FDM Front Mixer, Aluminum Fuel Tank, 200 Gallon Cross Mount Water Tank, Two Chutes, Pusher Axle, Aluminum Wheels, 445/65R22.5, PTO, AC, Missing Water Tank Fitting, Body Damage/Rust. Showing 170,821 Miles; 17,384 Hours. Location: Harrisburg, PA Serial: 10TFAAP285S084385	
<b>Lot #</b>	25	
<b>Qty</b>	1	
<b>Title</b>	1988 INTERNATIONAL 9300 DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. CAT 3406B 350 HP, Eaton 9 Speed, Walking Beam Suspension, 218 WB, 15ft Steel Body, Aluminum Fuel Tank, Tarp System, Steel Wheels, 11R24.5, PTO, Pintle Hitch, Body Damage/Rust. Showing 332,075 Miles; 7,701 Hours. Location: Pendleton, OR Serial: 2HSFEX3R1JC010312	
<b>Lot #</b>	26	
<b>Qty</b>	1	
<b>Title</b>	1998 KENWORTH W900 REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Cummins M11 280 HP, Eaton 8 Speed LL, Bogey Suspension, 20 FA, 46 RA, 250 WB, 11 Yrd McNeilus Rear Mixer, 56 Gallon Aluminum Fuel Tank, 125 Gallon Cross Mount Water Tank, Pusher Axle, Bridge Axle, Aluminum/Steel Wheels, 425/65R22.5; 11R24.5, AC, Body Damage/Rust. Showing 132,901 Miles; 7,116 Hours. Location: The Dalles, OR Serial: 1NKWL90X2WR759450	
<b>Lot #</b>	27	
<b>Qty</b>	1	
<b>Title</b>	1997 VOLVO L70C WHEEL LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. NON RUNNER - NO POWER TO DASH OR STARTER. VE TD 63 KDE 6 Cylinder 130 HP, Power Shift 4F/3R, Enclosed ROPS, 96in Bucket, Steel Wheels, 20.5R25, Body Damage/Rust. Hours Unavailable. Location: Mobile, AL Serial: L70CV14080	
<b>Lot #</b>	29	
<b>Qty</b>	1	
<b>Title</b>	1991 INTERNATIONAL 4900 SERVICE TRUCK	
<b>Des.</b>	CRANKS BUT WILL NOT START. LOSES PRIME AFTER IT SITS. Oil Leak At Right Side Of Block, City Horn Inop, Missing Right Hood Mirror, Right Door Won't Open From Outside, Rear Differential Leaking, Various Body Damage/Rust. Showing 295,920 Miles; 27,764 Hours. Location: Huntington, AR Serial: 1HTSDNWMXMH382214	
<b>Lot #</b>	30	
<b>Qty</b>	1	
<b>Title</b>	2010 AUTOCAR ACX XPEDITOR GARBAGE PACKER	
<b>Des.</b>	NON RUNNER. VARIOUS WIRING LOOSE OR DISCONNECTED, BATTERIES DEAD. Oil Leaking At Bottom Of Engine, Parked Long Term, Holes And Rust Through Compactor Body, Tires/Wheels Missing, Several Lights Broken Or Missing, Windshield Cracked, Cargo Side Door Missing To Hold Area, Body Damage/Rust. Mileage Unavailable. Location: Princeton, KY Serial: 5VCACLKF8AH210138	

<b>Lot #</b>	31	
<b>Qty</b>	1	
<b>Title</b>	2013 MACK CXU613 DAY CAB TRUCK	
<b>Des.</b>	UNIT STARTED. MP8- 445 HP, Cruise, Maxitorque T310, Air Ride Suspension, 12 FA, 40 RA, 190 WB, Adjustable 5th Wheel, Aluminum Wheels, 445/50R22.5, 295/75R22.5, 125 Gallon Aluminum Fuel Tank, PTO, AC. Showing 487,399 Miles. Location: Saint Louis, MO Serial: 1M1AW07Y4DM030163	
<b>Lot #</b>	32	
<b>Qty</b>	1	
<b>Title</b>	2006 VOLVO VHD64B CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE W/ STARTING FLUID - DID NOT STAY RUNNING. PTO DISMANTLED. Volvo VE D12 365 HP, RTO-14909ALL, T-Ride Suspension, 22 FA, 46 RA, 212 WB, 228in Back Cab To End Frame, 70 Gallon Aluminum Fuel Tank, Aluminum/Steel Wheels, 455/65R22.5; 11R24.5, PTO, AC, Damage/Missing Parts On Passenger Door, Missing Grill, Body Damage/Rust. Mileage Unavailable. Location: Des Moines, IA Serial: 4V5KC9GF26N405156	
<b>Lot #</b>	33	
<b>Qty</b>	1	
<b>Title</b>	1999 PETERBILT 378 DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. CAT 3406 550 HP, Eaton, Air Ride Suspension, 18 FA, 44 RA, 224 WB, 16ft Steel Strudyweld Dump Body, Dual 100 Gallon Aluminum Fuel Tanks, Tarp System, Air Lift Pusher, Aluminum Wheels, 425/65R22.5; 11R22.5, PTO, AC, Pintle Hitch, Body Damage/Rust. Showing 337,978 Miles. Location: Richland, WA Serial: 1NPFLB0X7XD510514	
<b>Lot #</b>	35	
<b>Qty</b>	1	
<b>Title</b>	1974 DYNAPAC CA25 ROLLER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. ARTICULATES BUT DOES NOT MOVE FORWARD OR BACKWARD. CAT 3145 Diesel 125 HP, Enclosed ROPS, 92in Roller Width, Steel Wheels, 23.1-26, Dead Batteries, Tires Bad Dry Rot, Body Damage/Rust. Showing 1,416 Hours. Location: Pendleton, OR Serial: 910000D17	
<b>Lot #</b>	38	
<b>Qty</b>	1	
<b>Title</b>	2010 AUTOCAR ACX XPEDITOR GARBAGE PACKER	
<b>Des.</b>	ENGINE STARTS BUT DOESN'T BUILD AIR PSI. SEVERE HYDRAULIC LEAK AT REAR - REQUIRED SHUTTING OFF ENGINE. Audible Air Leak, Oil Leaks At Front Main Seal, Top, And Bottom Of Engine, Severe Rust On Packer Body, Holes Through Floor Of Packer Body, Missing Lights At Rear, Tires Missing, Wiring Damaged/Plugs Missing, Body Damage/Rust. Showing 168,207 Miles. Location: Princeton, KY Serial: 5VCACLKF9AH210133	
<b>Lot #</b>	39	
<b>Qty</b>	1	
<b>Title</b>	2006 KENWORTH T800 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER - PARTS OF ENGINE MISSING. CAT C15 475 HP, 6 Speed Manual, Hendrickson Suspension, 266 WB, 245in Back Cab To End Frame, Double Frame, 106 Gallon Aluminum Fuel Tank, Tag Axle, Steel Wheels, 315/80R22.5, AC, Issues Opening Hood, Body Damage/Rust. Showing 517,308 Miles; 23,328 Hours. Location: Harrisburg, PA Serial: 1NKDXBEX16J111642	







<b>Lot #</b>	40	
<b>Qty</b>	1	
<b>Title</b>	2006 OSHKOSH S2346 FRONT MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Cummins ISM Diesel, Automatic, Air Ride Suspension, 22.8 FA, 42 RA, 195 WB, 11 Yrd Oshkosh FDM Front Mixer, Steel Fuel Tank, 200 Gallon Cross Mount Water Tank, Two Chutes, Pusher Axle, Aluminum Wheels, 445/65R22.5, PTO, AC, Body Damage/Rust. Showing 185,876 Miles; 15,858 Hours. Location: Harrisburg, PA Serial: 10TFAAC256S089373	
<b>Lot #</b>	41	
<b>Qty</b>	1	
<b>Title</b>	2009 INTERNATIONAL 7700 DUMP TRUCK	
<b>Des.</b>	NON RUNNER - BAD ENGINE. POWER STEERING PUMP MISSING. CAT C13 ACERT, Automatic, Hendrickson Suspension, 20 FA, 46 RA, 265 WB, 18.75ft Steel Strong Body, Aluminum Fuel Tank, Tarp System, 8,000 Lbs Drop Axles, Aluminum Wheels, 385/65R22.5; 11R22.5, AC, PTO Switch Missing, Tailgate Missing, Body Damage/Rust. Mileage Unavailable. Location: Spokane, WA Serial: 1HTTVSBT89J139160	
<b>Lot #</b>	42	
<b>Qty</b>	1	
<b>Title</b>	2001 KENWORTH W900 REAR MIXER	
<b>Des.</b>	20 FA, 46 RA, MTM Standard Mixer, Oil Seepage Noted At Engine And Pan, Radio Missing, Door Handles Missing/Broken. Showing 227,047 Miles. Location: Mabelvale, AR Serial: 1NKWLT0X71J879412	
<b>Lot #</b>	45	
<b>Qty</b>	1	
<b>Title</b>	1995 FORD F250 SERVICE TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. NEEDS EXHAUST SYSTEM. Ford 5.8L V8 Gas, 5 Speed Manual, Spring Suspension, 3.559 FA, 6.084 RA, 133 WB, 8ft Home Made Body, Steel Wheels, 235/85R16, AC, Dead Batteries, Roof Damage, Cracked Windshield, Body Damage/Rust. Showing 175,082 Miles. Location: Harrisburg, PA Serial: 1FTHF26H0SNB43224	
<b>Lot #</b>	47	
<b>Qty</b>	1	
<b>Title</b>	2002 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. Mack E7 350 HP, Mack Trans, Camelback Suspension, 266 WB, 50 Gallon Steel Fuel Tank, 255in Back Cab To End Frame, Tag Axle, Double Frame, Steel Wheels, 315/80R22.5, No Fuel Tank On Right Side Of Cab, Body Damage/Rust. Mileage Unavailable. Location: Harrisburg, PA Serial: 1M2P267C32M061863	
<b>Lot #</b>	48	
<b>Qty</b>	1	
<b>Title</b>	2006 VOLVO VNL64T DAY CAB TRUCK	
<b>Des.</b>	NON RUNNER - ENGINE WILL NOT TURN OVER. Volvo D12 365 HP, Eaton 10 Speed, Air Ride Suspension, 13.2 FA, 40 RA, 172 WB, Air Slide Fifth Wheel, Dual Aluminum Fuel Tanks, Wet Kit, Aluminum Wheels, 295/75R22.5, PTO, AC, Oil Leak Noted, Missing Hydraulic Tank Cap, Body Damage/Rust. Showing 699,543 Hours. Location: Ellenwood, GA Serial: 4V4NC9GFX6N426371	
<b>Lot #</b>	49	
<b>Qty</b>	1	
<b>Title</b>	1971 INTERNATIONAL DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Cummins Big Cam III, Walking Beam Suspension, 215 WB, Aluminum Fuel Tank, 14ft Steel Body, Steel Wheels, 11R24.5; 11R22.5, PTO, Pintle Hitch, Body Damage/Rust. Mileage Unavailable. Location: The Dalles, OR Serial: 437471Y024692	








<b>Lot #</b>	50	
<b>Qty</b>	1	
<b>Title</b>	2006 INTERNATIONAL 5600i REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. NEEDS ENGINE OVERHAUL - USES 2 GALLONS OF WATER PER DAY. NEEDS BUSHINGS. Cummins ISM Diesel, Eaton 8LL, Chalmers Suspension, 20 FA, 46 RA, 224 WB, 11 Yrd McNeilus Rear Mixer, Aluminum Fuel Tank, 110 Gallon Side Mount Water Tank, 3 Chutes, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Missing Rear Chute, Several Oil Leaks Noted, Body Damage/Rust. Showing 231,211 Miles; 21,680 Hours. Location: Byron, GA Serial: 1HTXHAHT86J308163	
<b>Lot #</b>	54	
<b>Qty</b>	1	
<b>Title</b>	2011 AUTOCAR ACX XPEDITOR GARBAGE PACKER	
<b>Des.</b>	STARTED ON SITE, DEAD BATTERIES. Has Been Parked Long Term, Oil Leaks At Top And Bottom Of Engine, Loose Wiring/Missing/Damaged Lights, Compactor Body Is Severely Rusted, Compactor Body Has Holes Through Floor, Tires/Wheels Missing, Body Damage/Rust. Mileage Unavailable. Location: Princeton, KY Serial: 5VCACLKG0BH211620	
<b>Lot #</b>	56	
<b>Qty</b>	1	
<b>Title</b>	2005 OSHKOSH S2346 FRONT MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. ENGINE BLOW BY. Cummins ISM Diesel, Automatic, Air Ride Suspension, 22 FA, 42 RA, 196 WB, 11 Yrd Oshkosh FDM Front Mixer, Aluminum Fuel Tank, 200 Gallon Cross Mount Water Tank, Two Chutes, Pusher Axle, Aluminum Wheels, 445/65R22.5, PTO, AC, Oil Leaking, Low Coolant Warning Light Illuminated, Missing Rear Bumper, Body Damage/Rust. Showing 173,013 Miles; 17,524 Hours. Location: Harrisburg, PA Serial: 10TFAAC205S086296	
<b>Lot #</b>	57	
<b>Qty</b>	1	
<b>Title</b>	2009 INTERNATIONAL 7700 DUMP TRUCK	
<b>Des.</b>	NON RUNNER - BAD ENGINE. CAT C13 ACERT, Automatic, Hendrickson Suspension, 20 FA, 46 RA, 265 WB, Steel Strong Body, Aluminum Fuel Tank, Tarp System, 8,000 Lbs Drop Axles, Aluminum Wheels, 385/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 315,919 Miles; 8,101 Hours. Location: Spokane, WA Serial: 1HTTVSBTX9J139158	
<b>Lot #</b>	58	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CT713 REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/ STARTING FLUID - NOT ROAD TESTED. Mack AMI-335 ASET, T310MLR, Camelback Suspension, 20 FA, 46 RA, 206 WB, 10.5 Yrd McNeilus Rear Mixer, 96 Gallon Steel Fuel Tank, 125 Gallon Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, ABS Warning Light Illuminated, Electrical Warning Light Illuminated, Body Damage/Rust. Showing 107,681 Miles; 13,559 Hours. Location: Des Moines, IA Serial: 1M2AL02CX6M003178	
<b>Lot #</b>	59	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. MANY PARTS MISSING - NO DRIVE SHAFT, ENGINE AND TRANS STRIPPED, PTO GONE, AND MISSING FOUR TIRES AND WHEELS. Mack AMI-370 ASET, Mack T310, Spring Suspension, 265 WB, Double Frame, 30ft Body Length, Steel Wheels, 275/80R22.5; 11R22.5, AC, No Hood, Dash Apart, No Muffler, Windshield Busted, No Keys, Body Damage/Rust. Mileage Unavailable. Location: Avondale, LA Serial: 1M2AG11C77M067515	







<b>Lot #</b>	60	
<b>Qty</b>	1	
<b>Title</b>	2012 VOLVO VNL DAY CAB TRUCK	
<b>Des.</b>	NON RUNNER. No Power To Dash. Various Dash Components Removed. Body Damage/Rust. Mileage Unavailable. Location: Byram, MS Serial: 4V4NC9EG7CN545955	
<b>Lot #</b>	61	
<b>Qty</b>	1	
<b>Title</b>	1989 DODGE D2500 SERVICE TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Frame Makes A Popping Sound Near The Front When Reversing, Passenger Door Would Not Open, Windshield Chipped, Various Body Damage/Rust. Showing 46,648 Miles; 1,174 Hours. Location: Arcadia, KS Serial: 1B7KE268XKS189380	
<b>Lot #</b>	62	
<b>Qty</b>	1	
<b>Title</b>	2004 STERLING ACTERRA GARBAGE PACKER	
<b>Des.</b>	DOOR SWAP- CHECK FRAME FOR S/N. NON RUNNER - NO POWER TO TRUCK. DRIVE SHAFT REMOVED. Coolant Tank Has No Cap, Fuel Tank Has No Cap, Oil Seepage At Pan/Rear Seal, Dash Apart, Windshield Chipped, Transmission Gear Shifter Unhooked, Body Damage/Rust. Mileage Unavailable. Location: Joplin, MO Serial: 2FZHCHDC64AN21007	
<b>Lot #</b>	63	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. DASH APART- COMPONENTS MISSING, INCLUDING: INSTRUMENT PANEL. AMI-370 ASET, T310, Camelback Suspension, 18 FA, 46 RA, 265 WB, 225 Cab To Frame End, Double Frame, Pusher Axle, Steel Wheels, 11R22.5 (Rears Singled Out), Headlights Missing, Body Damage/Rust. Mileage Unavailable. Location: Harrisburg, PA Serial: 1M2AG11C26M042925	
<b>Lot #</b>	65	
<b>Qty</b>	1	
<b>Title</b>	1992 MACK CH613 DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. HEAD GASKET LEAK. Mack E7-350-4VH, Eaton Fuller RTO14613, Spring Suspension, 212 WB, 16ft Steel Body, Dual 90 Gallon Aluminum Fuel Tanks, Aluminum Wheels, 315/80R22.5; 11R24.5, PTO, AC, Pintle Hitch, Body Damage/Rust. Showing 197,520 Miles; 27,953 Hours. Location: Colville, WA Serial: 1M2AA13Y3NW014659	
<b>Lot #</b>	66	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CT713 REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. ENGINE BLOW BY. Mack AMI-335 ASET, Maxitorque T310MLR, Camelback Suspension, 20 FA, 46 RA, 206 WB, 11 Yrd McNeilus Rear Mixer, Steel Fuel Tank, 125 Gallon Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, ABS Warning Light Illuminated, Electrical Warning Light Illuminated, Dead Batteries, Windshield Chipped, Body Damage/Rust. Showing 257,905 Miles; 1,749 Hours. Location: Des Moines, IA Serial: 1M2AL02C06M001715	
<b>Lot #</b>	69	
<b>Qty</b>	1	
<b>Title</b>	2006 FORD E350 SERVICE TRUCK	
<b>Des.</b>	NON RUNNER. Ford 6.0L V8, Automatic, Spring Suspension, 4.4 FA, 7.8 RA, 138 WB, 10ft Reading Body, Steel Wheels, 225/75R16, AC, Dead Batteries, Rust Throughout. Mileage Unavailable. Location: Harrisburg, PA Serial: 1FDWE35P56HB27402	

















<b>Lot #</b>	70	
<b>Qty</b>	1	
<b>Title</b>	2001 FORD F650 GARBAGE PACKER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Oil Leaks Noted At Lower Front Seal And Oil Pan Gasket, Oil Seepage At Left Side Of Engine, ABS Light Illuminated, Packer Ram And Hatch Operation Slow, Brake Fluid Seepage, Power Steering Fluid Seepage, Various Body Damage/Rust. Showing 140,221 Miles; 140,709 ECM; 7,901 Hours. Location: Lewisport, KY Serial: 3FDNF65Y51MA22110	
<b>Lot #</b>	71	
<b>Qty</b>	1	
<b>Title</b>	2004 PETERBILT 357 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. ENGINE COMPONENTS MISSING. TRANSMISSION SHIFTER REMOVED W/ UNIT. DRIVE SHAFT REMOVED. CAT C11, Spring Suspension, 18 FA, 46 RA, 262 WB, 221in Cab To End Of Frame, Aluminum Fuel Tank, Double Frame, Steel Wheels, 315/80R22.5; 11R22.5 (Rears Singled Out), PTO, Body Damage/Rust. Showing 573,794 Miles; 1,654 Hours. Location: Houston, TX Serial: 1NPALT0X14D836546	
<b>Lot #</b>	74	
<b>Qty</b>	1	
<b>Title</b>	2005 MACK CV713 REAR MIXER	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. ENGINE BLOW BY. Mack AMI-335 HP, Maxitorque T310MLR, Camelback Suspension, 20 FA, 46 RA, 220 WB, 11 Yrd. McNeilus Rear Mixer, Steel Fuel Tank, 125 Gallon Side Mount Water Tank, Steel Wheels, 11R22.5, PTO, AC, ABS Warning Light Illuminated, No Chutes, Missing Passenger Seat, Rear Outer Wheels Only, Body Damage/Rust. Showing 181,223 Miles; 19,166 Hours. Location: Des Moines, IA Serial: 1M2AG11C35M019586	
<b>Lot #</b>	75	
<b>Qty</b>	1	
<b>Title</b>	2003 PETERBILT 320 RECYCLING TRUCK	
<b>Des.</b>	NON RUNNER. VARIOUS PARTS REMOVED, WIRING HAS BEEN TAMPERED WITH. Sitting Extended Time, Lights Missing/Broken/Damaged Wires, Tires Flat/Missing, Severe Rust On Packer Body Including Inside, Body Damage/Rust. Mileage Unavailable. Location: Mayfield, KY Serial: 1NPZLT0X43D714667	
<b>Lot #</b>	76	
<b>Qty</b>	1	
<b>Title</b>	1995 ADVANCE TANKER PUP TRAILER	
<b>Des.</b>	32.5ft Length, 96in Width, 8,000 Gallon Capacity, 3 Hatches, 3 Hook Ups, Aluminum Wheels, 285/65R24.5; 285/75R24.5, Pintle Dolly Goes With And Is Hard Line Connected, Body Damage/Rust. Location: Spokane, WA Serial: 2AEAPSAC1SR000348	
<b>Lot #</b>	77	
<b>Qty</b>	1	
<b>Title</b>	1994 FORD F450 SERVICE TRUCK	
<b>Des.</b>	NON RUNNER. ALTERNATOR FAN BELT REMOVED. Ford 7.5L V8 Gasoline, Manual 5 Speed, Spring Suspension, 5 FA, 11 RA, 161 WB, IMT 3000 Crane, 11ft Reading Body, F/Outriggers, Steel Wheels, 235/75R16, AC, Trailer Hitch. Mileage Unavailable. Location: Harrisburg, PA Serial: 1FDLF47G8REA10731	

<b>Lot #</b>	78	
<b>Qty</b>	1	
<b>Title</b>	2007 INTERNATIONAL 7400 GARBAGE PACKER	
<b>Des.</b>	NON RUNNER - NO POWER TO UNIT. ENGINE APART AND ENGINE HEAD MISSING, TRANSMISSION SHIFTER IN THE FLOOR BOARD, NO RADIATOR OR COOLANT TANK, DRIVERS DOOR REMOVED. Various Body Damage/Rust. Mileage Unavailable. Location: Lebanon, MO Serial: 1HTWHAZR87J371456	
<b>Lot #</b>	79	
<b>Qty</b>	1	
<b>Title</b>	2006 INTERNATIONAL 5600i CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. Cummins ISM, Automatic, Hendrickson Suspension, 212 WB, 230 Cab To Frame End, Steel Wheels, 425/65R22.5; 11R24.5, AC, Engine Warning Light Illuminated, Body Damage/Rust. Showing 82,282 Miles; 23,904 Hours. Location: Houston, TX Serial: 1HTXHAHTX6J391403	
<b>Lot #</b>	83	
<b>Qty</b>	1	
<b>Title</b>	1980 TRAILMOBILE T41-1CBF4 TANKER TRAILER	
<b>Des.</b>	41.5ft Total Length, 40ft Body Length, 96in Width, Aluminum Body Composition, 9,500 Gallon Capacity, 4 Compartments, 4 Hatches, 4 Hook Ups, Steel Wheels, 11R24.5, Body Damage/Rust. Location: Spokane, WA Serial: V41434	
<b>Lot #</b>	85	
<b>Qty</b>	1	
<b>Title</b>	2004 MACK MR688S GARBAGE PACKER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. LIMITED ACCESS TO UNIT FOR INSPECTION - UNIT IS FULL OF WASPS. City Horn Inop., ECM Mileage Differs From Dash Mileage, L/ Rear Dual Tires Missing, Body Damage/Rust. Location: Springfield, MO Serial: 1M2K189C04M025198	
<b>Lot #</b>	86	
<b>Qty</b>	1	
<b>Title</b>	2001 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. UNIT DOES NOT BUILD SUFFICIENT AIR PSI - CROSSOVER AIR LINE LEAK AT REAR AXLE. Mack E7 350 HP, Mack, Camelback Suspension, 271 WB, Steel Fuel Tank, 244in Back Cab To End Frame, Double Frame, Steel Wheels, 315/80R22.5, PTO, Dead Batteries, Body Damage/Rust. Showing 157,826 Miles; 4,152 Miles. Location: Weatherford, TX Serial: 1M2P267C41M061837	
<b>Lot #</b>	87	
<b>Qty</b>	1	
<b>Title</b>	2004 FREIGHTLINER COLUMBIA SLEEPER TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Detroit Diesel Series 60 302 HP, Freightliner 10 Speed, Air Ride Suspension, 238 WB, Manual Fifth Wheel, Dual Aluminum Fuel Tanks - R/ 100 Gallon Capacity; L/ 150 Gallon Capacity, Wet Kit, Engine Brake, 60in Sleeper Area, Aluminum Wheels, 11R22.5, AC, ABS Light Illuminated, Body Damage/Rust. Showing 499,259 Miles. Location: Des Moines, IA Serial: 1FUJA6CK54DN24561	







<b>Lot #</b>	89	
<b>Qty</b>	1	
<b>Title</b>	2000 STERLING LT9501 DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. KNOWN TRANS ISSUE - STUCK IN GEAR, GEAR SELECTOR DISCONNECTED INSIDE TRANS. CAT C12 430 HP, Eaton Fuller 13 Speed, Hendrickson Suspension, 14.06 FA, 46 RA, 223 WB, 17.5ft Steel Sturdyweld Body, Dual Aluminum Fuel Tanks, Tarp System, Aluminum Wheels, 12R22.5; 11R24.5, PTO, AC, Pintle Hitch, Body Damage/Rust. Showing 400,903 Miles; 23,398 Hours. Location: Spokane, WA Serial: 2FZXEWB6YAB34773	
<b>Lot #</b>	90	
<b>Qty</b>	1	
<b>Title</b>	2003 KENWORTH W900 REAR MIXER	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. ENGINE BLOW BY. Cummins ISM-320V, Chalmers Suspension, 20 FA, 44 RA, 246 WB, 10.5 Yrd. McNeilus Rear Mixer, 56 Gallon Aluminum Fuel Tank, 85 Gallon Side Mount Water Tank, Bridge Axle, Aluminum Wheels, 425/65R22.5; 11R22.5, PTO, AC, Oil Seepage Noted, Missing Right Side Headlight, Body Damage/Rust. Showing 272,012 Miles; 4,778 Hours.	
<b>Lot #</b>	92	
<b>Qty</b>	1	
<b>Title</b>	2007 LANDOLL 43553A FLATBED TRAILER	
<b>Des.</b>	53ft Length, 102in Width, Steel Wheels, 10R17.5, Stands Not Working, Body Damage/Rust. Location: Des Moines, IA Serial: 1LH435WH571A15747	
<b>Lot #</b>	93	
<b>Qty</b>	1	
<b>Title</b>	2002 FREIGHTLINER FL80 GARBAGE PACKER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Oil Leaking At Bottom Of Engine And Transmission, All Rear Lights Stay On All The Time, No Turn Signal Switch, Active Fault Code - See Photos, Wires Below Dash Exposed, Chipped Windshield, Various Body Damage/Rust. Showing 279,802 Miles; 8,875 Hours. Location: Newburg, MO Serial: 1FVHBXAK92HJ87060	
<b>Lot #</b>	95	
<b>Qty</b>	1	
<b>Title</b>	2003 INTERNATIONAL 8100 DAY CAB TRUCK	
<b>Des.</b>	RUNNING CONDITION UNKNOWN. LESS KEYS. Cummins ISM Diesel, Eaton 10 Speed, Air Ride Suspension, 12 FA, 40 RA, 191 WB, Air Slide Fifth Wheel, Dual Aluminum Fuel Tanks, Wet Kit, Steel Wheels, 11R24.5, PTO, AC, Body Damage/Rust. Mileage Unavailable. Location: Luling, TX Serial: 2HSCBAHR93C060993	
<b>Lot #</b>	96	
<b>Qty</b>	1	
<b>Title</b>	1997 REDI-HAUL TANDEM AXLE EQUIPMENT TRAILER	
<b>Des.</b>	22ft Total Length, 208in Trailer Bed Length, 78in Width, Side Storage Box, Steel Wheels, St225/75R15, Compressor (Starts W/ A Jump; Serial 4500A061XXH610468), Body Damage/Rust. Compressor Showing 745 Hours. Location: Des Moines, IA Serial: 47SS142TXV1012861	
<b>Lot #</b>	97	
<b>Qty</b>	1	
<b>Title</b>	1992 MACK DM690S DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Mack EM7, T2070, Camelback Suspension, 210 WB, 17ft Steel Body, Steel Fuel Tank, Spoke Wheels, 315/80R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 88,712 Miles; 2,450 Hours. Location: Harrisburg, PA Serial: 1M2B209CXNM009624	

<b>Lot #</b>	98	
<b>Qty</b>	1	
<b>Title</b>	2003 PETERBILT 357 REAR MIXER	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. CAT C12 395 HP, Eaton Fuller 8 Speed, Chalmers Suspension, 20 FA, 46 RA, 230 WB, 10.5 Yrd. McNeilus Rear Mixer, 78 Gallon Aluminum Fuel Tank, 150 Gallon Side Mount Water Tank, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Dead Batteries, Missing Chutes, Body Damage/Rust. Showing 189,903 Miles; 2,769 Hours. Location: Des Moines, IA Serial: 1NPALU0X93D802598	
<b>Lot #</b>	100	
<b>Qty</b>	1	
<b>Title</b>	1997 FORD LT9513 DISTRIBUTOR TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Cummins M11 Diesel, Automatic, Spring Suspension, 16 FA, 40 RA, 211 WB, Etnyre 3,000 Gallon Capacity Distributor Body, Steel Wheels, 315/80R22.5; 11R24.5, PTO, Body Damage/Rust. Showing 62,637 Miles; 13,222 Hours. Location: Spokane, WA Serial: 1FDZS96P5VVA39117	
<b>Lot #</b>	102	
<b>Qty</b>	1	
<b>Title</b>	2002 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Mack E7 400 HP, Automatic, Camelback Suspension, 259 WB, Dual Steel Fuel Tanks, 219in Back Cab To End Frame, Double Frame, Steel Wheels, 315/80R22.5 (Multiple Singled Out), PTO, Dead Batteries, Check Transmission Warning Light Illuminated, Electric Malfunction Warning Light Illuminated, Right Rear Tire Flat Off Rim, Body Damage/Rust. Showing 806,693 Miles; 37,562 Hours. Location: Weatherford, TX Serial: 1M2P270C32M063757	
<b>Lot #</b>	103	
<b>Qty</b>	1	
<b>Title</b>	1994 MACK RB690S WATER TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. BRAKE PEDAL FROZEN - CAN NOT BE DRIVEN. Mack EM7 300 HP, Mack T2080-8 Speed, Camelback Suspension, 224 WB, 1,800 Gallon Water Tank Body, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 198,304 Miles; 28,817 Hours. Location: Wapwallopen, PA Serial: 1M2AM20CXRM002421	
<b>Lot #</b>	105	
<b>Qty</b>	1	
<b>Title</b>	1995 MACK RD690S DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. L/ REAR MOUNT BROKEN OFF TRANSMISSION - UNIT CAN NOT BE DRIVEN. Mack EM7-300, T2080, Camelback Suspension, 18 FA, 236 WB, 17ft Steel Body, Dual Steel Fuel Tanks, Pusher Axle, Spoke Wheels, 425/65R22.5; 11R24.5, PTO, AC, Backup Camera, Bad Frame Damage, Dead Batteries, Body Damage/Rust. Showing 67,362 Miles; 6,784 Hours. Location: Harrisburg, PA Serial: 1M2P264C1SM019423	
<b>Lot #</b>	107	
<b>Qty</b>	1	
<b>Title</b>	CIMLINE 150 TAR POT ASPHALT EQUIP	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED ON SITE. DEAD BATTERY. 150 Gallon, Diesel. Location: Ankeny, IA Serial: 54050	

<b>Lot #</b>	108	
<b>Qty</b>	1	
<b>Title</b>	2002 VOLVO VNL64T DAY CAB TRUCK	
<b>Des.</b>	NON RUNNER - HARD CRANKS BUT DOES NOT START. Volvo N14 Diesel 370 HP, Meritor, Air Ride Suspension, 12 FA, 40 RA, 170 WB, Dual Aluminum Fuel Tanks, Wet Kit, Air Slide Fifth Wheel, Steel/Aluminum Wheels, 295/75R22.5, PTO, AC, Dead Batteries, Body Damage/Rust. Showing 26,495 Miles; 704 Hours. Location: Weatherford, TX Serial: 4V4NC9JF62N328702	
<b>Lot #</b>	110	
<b>Qty</b>	1	
<b>Title</b>	LULL 644TT TELEHANDLER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. NON RUNNER. LESS KEYS. Diesel, 113in Total Height, OROPS, 2- 40x4in Forks, Steel Wheels, 13-24 Tires, Body Damage/Rust. Hours Unavailable. Location: Mobile, AL Serial: JD1127L	
<b>Lot #</b>	111	
<b>Qty</b>	1	
<b>Title</b>	1989 MACK RB690S WATER TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. BAD AIR LEAK AT REAR FRAME. TITLE BRANDED AS RECONSTRUCTED. Mack EM6-275L-4VH, T2080-8 Speed, Camelback Suspension, 210 WB, 3,400 Gallon Allied Water Tank Body, Spoke Wheels, 315/80R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 301,332 Miles; 2,661 Hours. Location: Wapwallopen, PA Serial: 2M2AM17C5KC001084	
<b>Lot #</b>	112	
<b>Qty</b>	1	
<b>Title</b>	2002 STERLING ACTERRA ASPHALT DISTRIBUTOR TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Cummins 5.9L, 6 Speed Manual, Spring Suspension, 12 FA, 21 RA, 189 WB, 2,000 Gallon Capacity Distributor Body, Steel Wheels, 11R22.5, PTO, AC, Low Water Warning Light Illuminated, Body Damage/Rust. Showing 55,446 Miles; 6,174 Hours. Location: Harrisburg, PA Serial: 2FZAAKBV72AJ83896	
<b>Lot #</b>	113	
<b>Qty</b>	1	
<b>Title</b>	CAT 3306 GEN SET SR-4 GENERATOR	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. NON RUNNER - LOCKED UP. TRAILER AND FUEL TANK INCLUDED. CAT 3306 Diesel, Steel Wheels, 10-20, Body Damage/Rust. Hours Unavailable. Location: Richland, WA Serial: 45BH853	
<b>Lot #</b>	114	
<b>Qty</b>	1	
<b>Title</b>	2007 CHEVROLET 1500 PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Duramax 6.6L Diesel, Automatic, Spring Suspension, 4.67 FA, 6.084 RA, 158 WB, Bed Liner, Aluminum Wheels, 275/70R18, AC, PW, PL, PS, PM, Body Damage/Rust. Showing 425,914 Miles. Location: Luling, TX Serial: 1GCHK23D27F148195	
<b>Lot #</b>	116	
<b>Qty</b>	1	
<b>Title</b>	1986 BEALL INSULATED ASPHALT PUP TRAILER	
<b>Des.</b>	31ft Trailer Length, 30.5ft Body Length, 96in Width, Steel Composition, 6,800 Gallon Tank Capacity, Single Compartment, Single Hatch, Single Hook Up, Center Discharge, Tandem Axle Front Turn Table, Spring Suspension, Tandem Rear Axle, Steel Wheels, 11R24.5, Tongue Slightly Bent, Body Damage/Rust. Location: Richland, WA Serial: 1BN1M3047GB001828	

<b>Lot #</b>	118	
<b>Qty</b>	1	
<b>Title</b>	1988 LOAD KING LOWBOY TRAILER	
<b>Des.</b>	46.25ft Length, 101in Width, Steel Wheels, 255/70R22.5, Body Damage/Rust. Location: Des Moines, IA Serial: 1L4L4634XJ1015538	
<b>Lot #</b>	119	
<b>Qty</b>	1	
<b>Title</b>	1996 LIFTKING LK8M22 FORKLIFT	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. Diesel, Power Shuttle Trans, 2 Wheel Drive, ROPS, 14ft Lift Height, 8,000 Lb. Capacity, Body Damage/Rust. Location: St. Louis, MO Serial: FL809006	
<b>Lot #</b>	121	
<b>Qty</b>	1	
<b>Title</b>	GM RS 6-71 168 GENERATOR	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED ON SITE W/ STARTING FLUID AND JUMP - FULL OPERATIONS NOT TESTED. THROTTLE STICKS. GM RD 6-71N65 Diesel, 20ft Total Trailer Length, Steel Wheels, LT235/85R16, Pintle Hitch, No Key, Body Damage/Rust. Location: Des Moines, IA Serial: N/A	
<b>Lot #</b>	122	
<b>Qty</b>	1	
<b>Title</b>	2007 FORD F150 PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Ford 5.4L V8, Automatic, Spring Suspension, 3.45 FA, 3.85 RA, 145 WB, 6.75ft Body, Steel Wheels, 265/70R17, AC, PW, PL, PM, Body Damage/Rust. Showing 176,014 Miles. Location: Richland, WA Serial: 1FTPX12577FB21849	
<b>Lot #</b>	123	
<b>Qty</b>	1	
<b>Title</b>	1995 INTERNATIONAL 4700 LPX VAN BODY TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. TITLE BRANDED AS MILEAGE EXCEEDS THE MECHANICAL LIMITS. International T444E Diesel, Automatic, Spring Suspension, 147 WB, 15ft Morgan Body, Lift Gate, Steel Wheels, 245/70R19.5, PTO, Dead Batteries, Body Damage/Rust. Showing 209,240 Miles; 13,199 Hours. Location: Wapwallopen, PA Serial: 1HTSMABM5SH691729	
<b>Lot #</b>	124	
<b>Qty</b>	1	
<b>Title</b>	1989 CLEMENT 3AT1310L PUP TRAILER	
<b>Des.</b>	14ft Length, 96in Width, Steel Wheels, 11R22.5, Body Damage/Rust. Location: Richland, WA Serial: 1CADD14C9EM110135	
<b>Lot #</b>	126	
<b>Qty</b>	1	
<b>Title</b>	2002 FORD F150 PICKUP TRUCK	
<b>Des.</b>	UNIT STARTED ON SITE - NOT ROAD TESTED. KNOWN ISSUES W/ SPARK PLUGS. Showing 274,334 Miles. Location: Denver, CO Serial: 1FTRW08L22KB93070	



<b>Lot #</b>	127	
<b>Qty</b>	1	
<b>Title</b>	1998 MACK CS300P WATER TRUCK	
<b>Des.</b>	UNIT STARTED ON SITE - WAS NOT ROAD TESTED. Mack 6.2L 6 Cyl Diesel, 6 Speed Manual, Spring Suspension, 222 WB, 18ft Morgan Body (From 2010), 1,000 Gallon Capacity Water Tank (Tank Has No Hoses/Pony Motor), Steel Wheels, 11R22.5, AC, Body Damage/Rust. Showing 21,800 Miles; 724 Hours. Location: Manheim, PA Serial: VG6BA09B1WB701844	
<b>Lot #</b>	129	
<b>Qty</b>	1	
<b>Title</b>	MILLER BIG 40 ARCH WELDER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED ON SITE W/ STARTING FLUID - WOULD NOT STAY RUNNING. Gas Engine, No Key, Body Damage/Rust. Location: Des Moines, IA Serial: HE813181	
<b>Lot #</b>	130	
<b>Qty</b>	1	
<b>Title</b>	2002 CHEVROLET 2500 EXT CAB PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE, KNOWN TRANSMISSION ISSUE- REVERSE INOP. 6.0L V8, Automatic, Spring Suspension, 143.5 WB, Steel Wheels, V-Plow Attachment, AC, PW, PL, PM, Multiple Warning Lights Illuminated- See Photos, Fuel Gauge Inoperable, Body Damage/Rust. Showing 166,953 Miles. Location: Wittenberg, WI Serial: 1GCHK29U72E225522	
<b>Lot #</b>	132	
<b>Qty</b>	1	
<b>Title</b>	1999 WILKENS WALKING FLOOR TRAILER	
<b>Des.</b>	48ft Length, 99in Width, 96in Inside Width, Steel Composition, Clam Gates, 3 Axles, Steel Wheels, 425/65R22.5, Body Damage/Rust. Location: Wittenberg, WI Serial: 1W91V4836XM077666	
<b>Lot #</b>	133	
<b>Qty</b>	1	
<b>Title</b>	2007 CHEVROLET 3500 STAKE BODY TRUCK	
<b>Des.</b>	NON RUNNER. Duramax 6.6L V8, Automatic, Spring Suspension, 4.67 FA, 8.55 RA, 160 WB, Steel Wheels, Lt225/75R16, AC, Broken Hood Latch- Hood Wont Open, Body Damage/Rust. Mileage Unavailable. Location: St. Louis, MO Serial: 1GBJC34D77E149520	
<b>Lot #</b>	135	
<b>Qty</b>	1	
<b>Title</b>	1984 FORD C8000 WATER TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Oil Seepage Noted At Pan/Rear Seal. Engine Covered In Oil Residue, All Lights Inop. Except Headlights, Exhaust Smoking, City Horn Inop., R/ Turn Signal Broken, Water Tank Exterior Damaged At Rear, L/ Door Wing Latch Broken, Windshield Chipped, Dash Missing Component At Center, Headliner Damaged, Various Body Damage/Rust. Showing 206,609 Miles; 9,374 Hours. Location: Springfield, MO Serial: 1FDXD80U4EVA24733	