



## Printable Catalog

<b>Title</b>	NOVEMBER 8 12:00 CDT	
<b>Description</b>	Closing Times TBD	
<b>Date</b>	Wed, Nov 8, 2023	
<b>Starts at</b>	12:00 PM	
<b>Address</b>	4747 NE 14th St, Des Moines, IA 50313 USA	
<b>Categories</b>		


---

<b>Lot #</b>	2	
<b>Qty</b>	1	
<b>Title</b>	2012 FREIGHTLINER CORONADO SD 122 6X4 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. OIL LEAKAGE AT BOTTOM OF ENGINE / OIL PAN, FLUID SEEPAGE AROUND SENSOR FITTING ABOVE FUEL RAIL, ACTIVE AFTER TREATMENT SYSTEM FAULTS DETECTED, Drivers Door Jammed Shut, Steps Bent And Dented, Interior Dirty, Bumper Bent, Paint Chipped Throughout Unit. Showing: 373,152 Miles; 19,234 Hours. Location: Calumet, OK Serial: 1FUJGNDR6CDBM5400	


---

<b>Lot #</b>	3	
<b>Qty</b>	1	
<b>Title</b>	2005 MACK GRANITE CV713 DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. NOT DRIVABLE, Upholstery Is Worn And Dirty, Frame Showing Some Rusting Throughout. Showing: 632,309 Miles; 21,364 Hours. Location: Walford, IA Serial: 1M2AG10C75M016515	


---








<b>Lot #</b>	4	
<b>Qty</b>	1	
<b>Title</b>	2015 PETERBILT 365 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. BAD TRANSMISSION, UNIT DOES NOT MOVE, DRUM THIN AND PATCHED IN MULTIPLE AREAS, Windshield Cracked. Showing: 180,566 Miles; 18,008 Hours. Location: Conroe, TX Serial: 1NPSX7EX1FD273400	








---








<b>Lot #</b>	5	
<b>Qty</b>	1	
<b>Title</b>	2008 FREIGHTLINER M2112 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. Rear Tires Singled Out. Mileage/Hours Unavailable. Location: Rochester, MN Serial: 1FVHC5CV38HZ21919	








---








<b>Lot #</b>	6	
<b>Qty</b>	1	
<b>Title</b>	2000 KENWORTH T800 6X4 TANK TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. OIL LEAKS AT MULTIPLE AREAS ON LEFT SIDE OF ENGINE / OIL PAN AND LOWER RIGHT REAR OF ENGINE / OIL PAN, Hood And Grill Have Paint Chipping And Peeling, Front And Rear Differential Have Wet Oil, Interior Soiled And Coming Apart, Inside Panel Missing On Drivers Side And No Handle. Showing: 154,542 Miles. Location: Calumet, OK Serial: 3WKDDU9X6YF839503	

<b>Lot #</b>	7	
<b>Qty</b>	1	
<b>Title</b>	2001 MACK MR688 GARBAGE PACKER	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Rust Throughout Unit, Interior Dirty/Worn, Seat Torn. Showing: 231,072 Miles; 19,701 Hours. Location: Carteret, NJ Serial: 1M2K185C41M008132	
<b>Lot #</b>	8	
<b>Qty</b>	1	
<b>Title</b>	2011 MACK GU813 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Missing Mack Emblem On Grill And Hood Mirrors. Showing 233,954 Miles; 22,806 Hours. Location: Rochester, MN Serial: 1M2AX13C5BM014155	
<b>Lot #</b>	9	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CT713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. Rear Tires Singled Out. Mileage/Hours Unavailable. Location: Rochester, MN Serial: 1M2AL02C77M006606	
<b>Lot #</b>	10	
<b>Qty</b>	1	
<b>Title</b>	2012 INTERNATIONAL WORKSTAR 7600 6X4 DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. ABS LIGHT ON, PTO Engages Bed, Minimal Amount Of Rust. Showing: 325,319 Miles; 12,322 Hours. Location: Dunbar, WV Serial: 1HTGRSJ9CJ591732	
<b>Lot #</b>	11	
<b>Qty</b>	1	
<b>Title</b>	2014 PETERBILT 365 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. NO KEY, STOP ENGINE LIGHT ON, CHECK COOLANT LIGHT ON, Fan Assembly Shaft Broken, Engine Over Heating, Does Not Build Air. Showing: 198,138 Miles; 19,696 Hours. Location: Conroe, TX Serial: 1NPSX7EX3ED230272	
<b>Lot #</b>	12	
<b>Qty</b>	1	
<b>Title</b>	2006 CHEVROLET C5500 MECHANICS TRUCK	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Engine, Low Oil And Brake Warning Lights On Dash, Engine Tag Not Located, D/S Seat Torn, Venturo CE1500FB Crane Attachment, Rust And Body Damage Throughout. Showing 155,594 Miles. Location: Elgin, IL Serial: 1GBE5C1286F408331	
<b>Lot #</b>	15	
<b>Qty</b>	1	
<b>Title</b>	2006 OSHKOSH S2346 FRONT MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. OIL RESIDUE/LEAKAGE ON LS OF ENGINE/OIL PAN SEAL/OIL PAN DRAIN PLUG, Rust Throughout Unit, Bottom Of Seat Is Worn And Stained, Missing Headliner. Showing: 261,995 Miles; 18,248 Hours. Location: Sanbornton, NH Serial: 10TFAAP2X6S08932	








<b>Lot #</b>	16	
<b>Qty</b>	1	
<b>Title</b>	2012 INTERNATIONAL PAYSTAR 5900i 6X4 DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. CHECK ENGINE LIGHT ON, Missing Mirror On Hood On Drivers Side, Hood Has Some Damage And Does Not Line up Correctly To Close, Minimal Amount Of Rust. Showing: 355,060 Miles; 13,775 Hours. Location: Dunbar, WV Serial: 1HTXYSJT6CJ540126	
<b>Lot #</b>	17	
<b>Qty</b>	1	
<b>Title</b>	2009 STERLING LT8500 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Engine And Battery Warning Lights On Dash, Rear Tires Singled Out, Sterling Emblem Missing Above Grill, Rust Throughout. Showing 333,744 Miles; 13,717 Hours. Location: Rochester, MN Serial: 2FZHAWCY49AAD9889	
<b>Lot #</b>	18	
<b>Qty</b>	1	
<b>Title</b>	2015 PETERBILT 365 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. UNIT SLOW TO BUILD AIR, CHECK ENGINE LIGHT ON, ABS LIGHT ON. Showing: 198,368 Miles; 18,999 Hours. Location: Conroe, TX Serial: 1NPSX7EX5FD273402	
<b>Lot #</b>	19	
<b>Qty</b>	1	
<b>Title</b>	2007 MITSUBISHI FM61F CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing 142,539 Miles. Location: Des Moines, IA Serial: JL6DGP1E77K009915	
<b>Lot #</b>	20	
<b>Qty</b>	1	
<b>Title</b>	1999 STERLING LT8513 STAKE BODY TRUCK	
<b>Des.</b>	STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. Body Damage To Front End, Bottom Half Of Dash Missing, P/S Seat Torn, Some Toggles Loose In Dash, Engine Tag Worn And Illegible, Rust Throughout. Showing 435,667 Miles; 27,288 Hours. Location: Elgin, IL Serial: 2FZ6MLAAXXA982452	
<b>Lot #</b>	22	
<b>Qty</b>	1	
<b>Title</b>	1996 PETERBILT 330 4X2 DISTRIBUTOR TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Body Damage/Rust. Showing 45,520 Miles; 900 Hours. Location: Stephenson, VA Serial: 1XPNH7X5TN389602	
<b>Lot #</b>	23	
<b>Qty</b>	1	
<b>Title</b>	2012 INTERNATIONAL PAYSTAR 5900i 6X4 DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. ENGINE OIL LEAK NOTED. Body Tag Missing From Bed, Check Engine And ABS Lights Illuminated. Showing 307,483 Miles; 12,080 Hours. Location: Dunbar, WV Serial: 1HTXYSJT6CJ540160	








<b>Lot #</b>	24	
<b>Qty</b>	1	
<b>Title</b>	2011 MAC MACSIMIZER HALF ROUND DUMP TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Rust Noted, Tires Worn, Approximate Measurements: 40 FT Length, 102 In Width, 9.75 FT Height. Location: English, IN Serial: 5MADN4021BC020506	
<b>Lot #</b>	25	
<b>Qty</b>	1	
<b>Title</b>	2001 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Grill Has Broken Bars, Rear Tires Singled Out, Spray Paint On Body, Seat Torn, Rust And Body Damage Throughout. Showing 258,552 Miles; 33,328 Hours. Location: Des Moines, IA Serial: 1M2P267CX1M057078	
<b>Lot #</b>	26	
<b>Qty</b>	1	
<b>Title</b>	2014 PETERBILT 365 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. CHECK ENGINE LIGHT ON, ABS LIGHT ON, DRUM THIN AND PATCHED IN MULTIPLE AREAS, Windshield Cracked. Showing: 174,928 Miles; 21,577 Hours. Location: Conroe, TX Serial: 1NPSX7EX8ED230266	
<b>Lot #</b>	28	
<b>Qty</b>	1	
<b>Title</b>	2006 FORD F550 STRAIGHT TRUCK	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. DOES NOT STAY RUNNING LONG ENOUGH TO LIGHT UP DASH, Engine Tag Not Located, Supreme Corp Box Body, R/S Rear Tire Is Blown, Rust And Body Damage Throughout. Mileage Unavailable. Location: Elgin, IL Serial: 1FDAF57P26EC67215	
<b>Lot #</b>	30	
<b>Qty</b>	1	
<b>Title</b>	2007 INTERNATIONAL PAYSTAR 5900i 6X4 DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. ENGINE OIL LEAK NOTED AT OIL FILTER, OIL NOTED ON ENGINE EXTERIOR. Tires Bad. Showing 604,087 Miles; 7,316 Hours. Location: Dunbar, WV Serial: 1HTXRAPT47J464491	
<b>Lot #</b>	31	
<b>Qty</b>	1	
<b>Title</b>	2009 MACK GU713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. Missing Dash Components And Hood, Rear Tires Singled Out, D/S Seat Torn, Rust Throughout. Mileage Unavailable. Location: Kingdom City, MO Serial: 1M2AX04C49M005689	
<b>Lot #</b>	32	
<b>Qty</b>	1	
<b>Title</b>	2011 MAC MACSIMIZER HALF ROUND DUMP TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Rust Noted, Rear Tarp Is Torn, Approximate Measurements: 40 FT Height, 102 IN Width, 9.75 Height. Location: English, IN Serial: 5MADN402XBC020505	

<b>Lot #</b>	33	
<b>Qty</b>	1	
<b>Title</b>	2011 FREIGHTLINER M2 106 4X2 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. ABS, Brake Air, And Brake Warning Lights On Dash, Rear Tires Singled Out, Seats Torn, Rust And Body Damage Throughout. Showing 248,136 Miles. Location: Kingdom City, MO Serial: 1FVACXBS9BHAZ2322	
<b>Lot #</b>	34	
<b>Qty</b>	1	
<b>Title</b>	2015 PETERBILT 365 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. CHECK ENGINE LIGHT ON, Drum Is Thin, Drum Is Patches In Places, Left Front Drive Brake Locked Up. Showing: 148,172 Miles; 16,591 Hours. Location: Conroe, TX Serial: 1NPSX7EX7FD278469	
<b>Lot #</b>	36	
<b>Qty</b>	1	
<b>Title</b>	2009 KENWORTH T800 DUMP TRUCK	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. NO POWER, NOT MOVABLE, Rust Throughout Unit, Interior Dirty. Showing: Mileage/Hours Unavailable. Location: Airway Heights, WA Serial: 1NKDX4EX49R245627	
<b>Lot #</b>	37	
<b>Qty</b>	1	
<b>Title</b>	2013 FREIGHTLINER M2 106 6X4 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, NO CRANK, Missing Ignition, D/S Seat Torn, Rear Tires Singled Out, Rust Throughout, Engine Tag Not Located, Misc Parts On Cab Floor. Mileage Unavailable. Location: Kingdom City, MO Serial: 1FVHCYBS7DHBZ0515	
<b>Lot #</b>	38	
<b>Qty</b>	1	
<b>Title</b>	2014 HINO 195 4X2 STRAIGHT TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. BATTERIES DEAD, BODY DAMAGE, Scratches And Rust Throughout Unit. Showing: 240,479 Miles. Location: Gastonia, NC Serial: JHHHDM2H3EK001282	
<b>Lot #</b>	39	
<b>Qty</b>	1	
<b>Title</b>	2016 FORD F-450 SUPER DUTY 4X2 VAN BODY TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Has Rear Lift Gate, Frame Of Truck Starting To Rust. Showing: 84,657 Miles. Location: Des Moines, IA Serial: 1FDUF4GY7GEA67030	
<b>Lot #</b>	40	
<b>Qty</b>	1	
<b>Title</b>	1984 EAST DUMP TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Tarp Is Torn, Side Boards Are Broken, Tires Worn, Rust Throughout, Approximate Measurements: 22 FT Length, 96 IN Width, 9.58 FT Height. Location: English, IN Serial: 1E1D1J282ERC05626	








<b>Lot #</b>	41	
<b>Qty</b>	1	
<b>Title</b>	2014 PETERBILT 365 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. Compressed Natural Gas Truck- Has An Empty Tank, Engine Tag Illegible, Missing Items, Including: Batteries, Headlights, Tail Light On P/S, Rust And Body Damage Throughout. Mileage Unavailable. Location: Elkhorn, WI Serial: 1NPSX20X0ED226545	
<b>Lot #</b>	42	
<b>Qty</b>	1	
<b>Title</b>	2014 PETERBILT 365 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. CHECK ENGINE LIGHT ON, CHECK COOLANT LIGHT ON, Cracked Windshield. Showing: 178,260 Miles; 17,601 Hours. Location: Conroe, TX Serial: 1NPSX7EX2ED230280	
<b>Lot #</b>	43	
<b>Qty</b>	1	
<b>Title</b>	1997 KENWORTH T800 DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Rust And Paint Scratches Throughout Unit. Showing: 387,296 Miles; 329 Hours. Location: Airway Heights, WA Serial: 1NKDX2EX4VR752753	
<b>Lot #</b>	44	
<b>Qty</b>	1	
<b>Title</b>	2014 HONDA ACCORD CAR	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Radiator Coolant Is Low, TPMS Warning Light On Dash, Hail Dents To Body, P/S Rear Lamp Lens Is Cracked, Interior Soiled, Tires Worn, Headlamp Low Beam Is INOP, D/S Seat Worn. Showing 284,641 Miles. Location: Calumet, OK Serial: 1HGCR2F32EA204611	
<b>Lot #</b>	45	
<b>Qty</b>	1	
<b>Title</b>	2014 PETERBILT 365 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. Showing 221,000 Miles. Location: Elkhorn, WI Serial: 1NPSX20X9ED226544	
<b>Lot #</b>	47	
<b>Qty</b>	1	
<b>Title</b>	2007 MITSUBISHI FM61F VAN BODY TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. LIFT GATE INOPERABLE, ABS LIGHT ILLUMINATED, TAIL LIGHTS REMOVED. Showing 184,673 Miles. Location: Des Moines, IA Serial: JL6DGP1E57K007211	
<b>Lot #</b>	48	
<b>Qty</b>	1	
<b>Title</b>	2001 RELIANCE DS48TF-HFS DUMP TRAILER	
<b>Des.</b>	APPROXIMATE MEASUREMENTS 42 FT Length, 97 IN Width, 124 IN HEIGHT, FULL OPERATIONS NOT TESTED. Rust Throughout Unit. Location: Airway Heights, WA Serial: 5REFE4482YS016001	

















<b>Lot #</b>	49	
<b>Qty</b>	1	
<b>Title</b>	2007 FREIGHTLINER M2106 6X4 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. WILL NOT CRANK, Missing Alternator, Oil All Over Underneath Hood, Front Differential Has Stripped Gear - Horrible Grinding Noise. Unavailable Mileage. Location: Wittenberg, WI Serial: 1FVHCYDJ47HX10546	
<b>Lot #</b>	50	
<b>Qty</b>	1	
<b>Title</b>	2014 PETERBILT 365 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. LEAKING FROM HEAD, OIL PAN AND FUEL FILTER HOUSING, CHECK ENGINE LIGHT ON, Climate Controls Missing, Lower Ladder Missing, No Chutes. Showing: 212,015 Miles; 19,451 Hours. Location: Conroe, TX Serial: 1NPSX7EXXED230270	
<b>Lot #</b>	51	
<b>Qty</b>	1	
<b>Title</b>	2002 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. P/S Dash Apart, Engine Tag Not Located, Rust Throughout. Showing 611,662 Miles; 33,357 Hours. Location: Lakeville, IN Serial: 1M2AG11C82M001113	
<b>Lot #</b>	54	
<b>Qty</b>	1	
<b>Title</b>	1988 CHEVROLET C-30 FOOD TRUCK VAN BODY TRUCK	
<b>Des.</b>	STARTED ON SITE< FULL OPERATIONS NOT TESTED. UNKNOWN OPERATION OF GENERATOR, WOULDNT START. Showing 3,042 Miles. Location: Des Moines, IA Serial: ID41740COLO	
<b>Lot #</b>	55	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. Missing Items, Including: Top Of Transmission, Hood Mirrors, Bulldog Ornament, D/S Rear Mud Flap, Dash Apart On P/S, Misc Parts On Cab Floor, Rust And Body Damage Throughout. Mileage Unavailable. Location: Newark, NJ Serial: 1M2AG11C36M039452	
<b>Lot #</b>	56	
<b>Qty</b>	1	
<b>Title</b>	1999 MCCLAIN WALKING FLOOR TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Vin Tag Not Located, Rust And Body Damage Throughout, Approximate Measurements: 48 FT 5 IN Shipping Length, 98 IN Shipping Width, 13 FT Shipping Height. Location: Wittenberg, WI Serial: 1M9CD4854X2309300	
<b>Lot #</b>	57	
<b>Qty</b>	1	
<b>Title</b>	2005 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. Missing Items, Including: ECM, Bulldog Ornament, Grill, P/S Hood Vent Grill, Hood Mirrors, Rear Tires Are Singled Out, Front Tires Worn, P/S Dash Apart, Rust And Body Damage Throughout. Mileage Unavailable. Location: Newark, NJ Serial: 1M2AG11C45M020911	







<b>Lot #</b>	58	
<b>Qty</b>	1	
<b>Title</b>	2015 PETERBILT 365 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. REAR OIL PAN LEAKERS, CHECK ENGINE LIGHT ON, ABS LIGHT ON, Drum Has Bad Rollers, Unit Does Not Build Secondary Air. Showing: 200,210 Miles; 20,599 Hours. Location: Conroe, TX Serial: 1NPSX7EX5FD273397	
<b>Lot #</b>	61	
<b>Qty</b>	1	
<b>Title</b>	2013 FREIGHTLINER M2112 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Compressed Natural Gas Truck, Components Missing From Engine, Engine Tag Not Located, Missing Hood Mirrors, Rear Tires Singled Out, Dash Apart, Rust And Body Damage Throughout. Mileage Unavailable. Location: Bardstown, KY Serial: 1FVXG1DX7DHFF0393	
<b>Lot #</b>	62	
<b>Qty</b>	1	
<b>Title</b>	2005 GMC C5500 VAN BODY TRUCK	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. Engine Warning Light On Dash, D/S Seat Torn, Rust And Body Damage Throughout. Mileage Unavailable. Location: Rochester, MN Serial: 1GDE5C1225F528440	
<b>Lot #</b>	63	
<b>Qty</b>	1	
<b>Title</b>	1997 MCCLAIN WALKING FLOOR TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Missing Tail Lights, Jack Will Not Turn, Brakes INOP, Holes On Sides, Pieces Of Aluminum Cracked Off Of Safety Rail, Rust Throughout, Approximate Measurements: 48.5 FT Shipping Length, 100 IN Shipping Width, 13.3 FT Shipping Height. Location: Wittenberg, WI Serial: 1M9BD4824V2309005	
<b>Lot #</b>	64	
<b>Qty</b>	1	
<b>Title</b>	2002 FREIGHTLINER FLD120SD 8X4 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing: 304,760 Miles; 6,577 Hours. Location: Elk, WA Serial: 1FVMALAN92PJ58491	
<b>Lot #</b>	65	
<b>Qty</b>	1	
<b>Title</b>	2013 FREIGHTLINER M2112 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. Compressed Natural Gas Truck, Engine Tag Not Located, Rear Tires Singled Out, Lower Dash Loose On P/S, Rust And Body Damage Throughout. Showing 154,202 Miles. Location: Bardstown, KY Serial: 1FVXG1DX5DHFF0389	
<b>Lot #</b>	66	
<b>Qty</b>	1	
<b>Title</b>	2013 FORD F250 4X2 PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. P/S Interior Step Panel And Side Kick Panel Removed And Laying On Floor, Tail Gate Is Missing, Interior Soiled, Bed Liner Is Peeling Away, Tires Worn, Body Damage Noted Throughout. Showing 194,055 Miles. Location: Calumet, OK Serial: 1FTBF2A62DEA81095	










<b>Lot #</b>	67	
<b>Qty</b>	1	
<b>Title</b>	2013 FREIGHTLINER M2 112 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. Compressed Natural Gas Truck- Fuel Tanks Removed, Missing P/S Headlight And Hood Mirrors, Rear Tires Singled Out, D/S Seat Torn, Rust And Body Damage Throughout. Mileage Unavailable. Location: Bardstown, KY Serial: 1FVXG1DX5DHFF0392	
<b>Lot #</b>	69	
<b>Qty</b>	1	
<b>Title</b>	2013 FREIGHTLINER M2 112 6X4 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. D/S Hood Mirror Is Missing, Rust And Body Damage Throughout. Mileage Unavailable. Location: Cowan, TN Serial: 1FVHC5DV7DDFB2966	
<b>Lot #</b>	70	
<b>Qty</b>	1	
<b>Title</b>	2002 FREIGHTLINER FLD120SD 8X4 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. MISSING BRIDGE CONTROL INTERLOCK SWITCH, Missing Drum Discharge Switch. Showing: 29,291 Miles; 4,911 Hours. Location: Elk, WA Serial: 1FVMALAN82PJ58496	
<b>Lot #</b>	71	
<b>Qty</b>	1	
<b>Title</b>	1988 STECO END DUMP WALKING FLOOR TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. VIN Plate Not Located, Missing Items, Including: Lift Cylinder, Crank Handle, Front Axle Wheels Both Sides, One Tail Light On Each Side, Approximate Measurements: 53 FT Length. Location: Elgin, IL Serial: 1S9WAR2T1J1007167	
<b>Lot #</b>	72	
<b>Qty</b>	1	
<b>Title</b>	2012 HORSE CREEK MANUFACTURING GOOSENECK TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. VIN Tag Not Located, Rust Noted, Tires Worn, Approximate Measurements: 20 FT Length, 84 IN Width, 12.2 FT Height. Location: Calumet, OK Serial: 5BSCA2026CC026837	
<b>Lot #</b>	73	
<b>Qty</b>	1	
<b>Title</b>	2010 INTERNATIONAL WORKSTAR 7400 SBA 4X2 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. D/S Hood Mirror Is Missing, Rust And Body Damage Throughout. Mileage Unavailable. Location: Cowan, TN Serial: 1HTWCAAN1AJ215774	
<b>Lot #</b>	74	
<b>Qty</b>	1	
<b>Title</b>	2008 FORD F250 EXT CAB PICKUP TRUCK	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. Missing Tail Gate Trim From Rear, Debris In Bed, D/S Seat Torn, Residue From Logos On Doors, Body Damage Throughout. Mileage Unavailable. Location: Jacksonville, FL Serial: 1FTSX20R58EB50537	

<b>Lot #</b>	75	
<b>Qty</b>	1	
<b>Title</b>	2007 ALUMA 8212 TANDEM AXLE EQUIPMENT TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED, BROKEN WELDS. BENT TONGUE. 202 IN LENGTH. Location: Des Moines, IA Serial: 1YGHD18237B034467	
<b>Lot #</b>	76	
<b>Qty</b>	1	
<b>Title</b>	2002 FREIGHTLINER FLD120SD 8X4 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. ENGINE STARTED, SHUT OFF IMMEDIATELY DUE TO LARGE HYDRAULIC LEAK, Missing One Extension Chute. Showing: 76,937 Miles; 1,878 Hours. Location: Airway Heights, WA Serial: 1FVMALAN72PJ58490	
<b>Lot #</b>	77	
<b>Qty</b>	1	
<b>Title</b>	2003 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. Missing Items, Including: Hood Mirrors, Bulldog Ornament And Grill Parts, D/S Headlight, P/S Hood Vent Grill, Radio, Chunk Of Poly Fender On P/S, Rust And Body Damage Throughout. Mileage Unavailable. Location: Carnesville, GA Serial: 1M2AG11C53M004746	
<b>Lot #</b>	79	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Rear Tires Singled Out, D/S Hood Mirror And P/S Hood Vent Grill Are Missing, Some Tail Lights Damaged/Missing, Dash Components Missing, Odometer Cover Cracked, Rust And Body Damage Throughout. Mileage Unavailable. Location: Jacksonville, FL Serial: 1M2AG11C67M061432	
<b>Lot #</b>	80	
<b>Qty</b>	1	
<b>Title</b>	2012 BENLEE TRABM41 ROLLOFF TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Axle Weight Tag Not Located, Drop Axle Has A Blown Tire, Approximate Measurements: 40 FT Shipping Length, 96 IN Shipping Width, 8 FT Shipping Height. Location: Elgin, IL Serial: 1B9E14133CB180304	
<b>Lot #</b>	81	
<b>Qty</b>	1	
<b>Title</b>	2007 STERLING L9513 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Dash Apart On P/S, D/S Hood Mirror And Grill Missing From Front, Tail Lights Damaged, Rust Throughout, Seat Tattered, Headliner Torn, Odometer Cover Is Cracked. Mileage Unavailable. Location: Jacksonville, FL Serial: 2FZHAZCVX7AY45919	
<b>Lot #</b>	82	
<b>Qty</b>	1	
<b>Title</b>	2001 FREIGHTLINER FLD120SD 8X4 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. ALL EXTENSION CHUTES ARE MISSING, MIL Light Strip Missing In Dash, Interior Has Signs Of Wear And Tear. Showing: 459,916 Miles; 9,691 Hours. Location: Airway Heights, WA Serial: 1FVMALAN61PK00551	

<b>Lot #</b>	83	
<b>Qty</b>	1	
<b>Title</b>	2005 B&B UT6X12NRT EQUIPMENT TRAILER	
<b>Des.</b>	APPROXIMATE MEASUREMENT 17.5 FT LENGTH, 94 IN WIDTH, 30 IN HEIGHT, FULL OPERATIONS NOT TESTED. Frame Is Bent, Tongue Is Bent, Rust Throughout Unit. Location: Des Moines, IA Serial: 4L5UA16135F008645	
<b>Lot #</b>	84	
<b>Qty</b>	1	
<b>Title</b>	1992 GREAT DANE FLATBED TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Missing Items, Including: Red Glad Hand, Connection For Lights, Front Axle Wheels, And Slack Adjusters, Brake Shoes Are Sitting On Trailer, VIN Tag Not Located, Approximate Measurements: 53 FT Shipping Length, 96 IN Shipping Width, 8.75 Shipping Height. Location: Elgin, IL Serial: 1GRDM9027NM020411	
<b>Lot #</b>	85	
<b>Qty</b>	1	
<b>Title</b>	2005 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEYS. Unavailable Mileage/Hours. Location: Cairo, GA Serial: 1M2AG11C85M022323	
<b>Lot #</b>	86	
<b>Qty</b>	1	
<b>Title</b>	2017 GREAT LAKES SR2440 ROLLOFF TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Approximate Measurements: 32 FT Shipping Length, 96 IN Shipping And Body Width, 5 FT Shipping Height. Location: Elkhorn, WI Serial: 1G9CD2428HS139579	
<b>Lot #</b>	87	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. Missing Items, Including: R/S Front Tire Spindle And Wheel, Transmission, Hood And Side Mirrors, P/S Hood Vent Grill, Misc Parts In Cab, Odometer Cover Is Cracked, Rust And Body Damage Throughout. Mileage Unavailable. Location: McComb, MS Serial: 1M2AG11C06M034015	
<b>Lot #</b>	88	
<b>Qty</b>	1	
<b>Title</b>	2013 HUSQVARNA PS-SV735-3031 MOWERS	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. NON RUNNER, FULL OPERATIONS NOT TESTED. DEAD BATTERIES, Oil Leaking Off Back Of Engine, Seat Upholstery Soiled, Both Tires Are Flat, Battery Terminals Are Corroded, Dried Grass Noted Under Mower Deck. Hours Unavailable. Location: Calumet, OK Serial: 4301602553	
<b>Lot #</b>	89	
<b>Qty</b>	1	
<b>Title</b>	2009 MACK GU813 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. Ignition Disassembled, Doors Do Not Latch, Missing Items, Including: Turbo To Stack Connection, Drive Shaft, All Mirrors, Hood Vent Grills, Bulldog Ornament From Hood, D/S Door Panel. Mileage Unavailable. Location: Weatherford, TX Serial: 1M2AX13C09M005275	

<b>Lot #</b>	90	
<b>Qty</b>	1	
<b>Title</b>	1999 CONVERTO EQUIPMENT TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Mismatched Tread Depths On Tires, Front R/S Tire Leaking Air, Rust Throughout, Vin Tag Not Located, Approximate Measurements: 28 FT Shipping Length, 96 IN Shipping Width, 3.3 FT Shipping Height. Location: Lakeville, IN Serial: 1C9LT3235X1087082	
<b>Lot #</b>	91	
<b>Qty</b>	1	
<b>Title</b>	1996 GALBREATH CT20 FLATBED TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Deck And Jack Mounting Bracket Are Rotten, Rusty Frame, Approximate Measurements: 37 Ft Shipping Length, 97 IN Shipping Weight, 2.9 FT Shipping Height. Location: Wittenberg, WI Serial: 1G9C12826TB157753	
<b>Lot #</b>	92	
<b>Qty</b>	1	
<b>Title</b>	2014 GREAT LAKES PUP ROLLOFF TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Brakes Are Caged, Emergency Glad Handle Hose Is Broken, Rust Throughout, Approximate Measurements: 28 Ft 4 IN Shipping Length, 100 IN Shipping Width, 4 FT 1 IN Shipping Height. Location: Wittenberg, WI Serial: 1G9CD2420ES139328	
<b>Lot #</b>	93	
<b>Qty</b>	1	
<b>Title</b>	2012 FREIGHTLINER M2 112 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Missing Exhaust Down Pipe, Tires Singled Out, D/S Rear Tire Shredded, Rear Axle Missing, Damaged Suspension, Fuze Cover Removed On P/S, D/S Seat Torn. Mileage Unavailable. Location: Weatherford, TX Serial: 1FVHC5DV0CHBV5982	
<b>Lot #</b>	94	
<b>Qty</b>	1	
<b>Title</b>	2011 LONGHORN TANKER TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. VIN Tag Not Located, P/S Tool Box Missing Handle And Will Not Stay Closed, P/S Hose Connections Are Rusted, Tires Worn, Approximate Measurements: 33 FT Length, 86 IN Width, 13 FT Height. Location: Calumet, OK Serial: 1L9BT41211G223402	
<b>Lot #</b>	95	
<b>Qty</b>	1	
<b>Title</b>	2002 CHEVROLET ASTRO VAN	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing 105,702 Miles. Location: Des Moines, IA Serial: 1GNEL19X52B132186	
<b>Lot #</b>	96	
<b>Qty</b>	1	
<b>Title</b>	1998 G&H 8530 FLATBED TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Rust Throughout, Jack Is Bent And Cover For Jack Is Missing, Approximate Measurements: 30 FT 7 IN Shipping Length, 94 IN Shipping Width, 3 Ft 1 In Shipping Height. Location: Wittenberg, WI Serial: 1G9CT302XWA116001	

<b>Lot #</b>	97	
<b>Qty</b>	1	
<b>Title</b>	2015 MACK GU533 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Missing Items, Including: Hood, Instrument Panels, Driver Door And Driver Seat, Engine Components, Transmission Controls And Batteries, Dash Apart. Mileage Unavailable. Location: Weatherford, TX Serial: 1M2AX33CXFM010488	
<b>Lot #</b>	98	
<b>Qty</b>	1	
<b>Title</b>	1995 GREAT LAKES ROLLOFF TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. VIN Tag Not Located, Missing Tail Lights, Rust Throughout, Approximate Measurements: 32 FT Shipping Length, 97 IN Shipping Height, 4 Ft 9 IN Shipping Height. Location: Wittenberg, WI Serial: 1G9CD2328SS139590	
<b>Lot #</b>	99	
<b>Qty</b>	1	
<b>Title</b>	1994 OTTAWA 30 YARD DOG	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. NON RUNNER, FULL OPERATIONS NOT TESTED. Missing Items, Including: Misc Engine Components, Fuel Tank, Most Glass Panels, Parking Brake, Engine And Axle Weight Tags Not Located, Can Not Raise Cab To See Engine, D/S Window Cracked, Steering Does Not Work, Rust And Body Damage Throughout. Mileage Unavailable; Showing 8,765 Hours. Location: Bardstown, KY Serial: 71692	
<b>Lot #</b>	101	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Missing Items, Including: Instrument Panel, Steering Wheel And Batteries, Hood Vent Covers, P/S Headlight, Bulldog Ornament, Driver Seat, Rear Tires Singled Out, Grill Hanging Down, Body Damage And Rust Throughout, Engine Tag Not Located. Mileage Unavailable. Location: Wetherford, TX Serial: 1M2AG11C87M067524	
<b>Lot #</b>	102	
<b>Qty</b>	1	
<b>Title</b>	1990 J&L 99.0.4 PNEUMATIC TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Heavy Wear And Tear, Missing Rear Mud Flap, Hatch Hinge Is Broken, Repair Welds To L/S Of V, Approximate Measurements: 13.6 Body Length, 96 IN Width, 29 FT Shipping Length, 12.6 FT Shipping Height. Location: Yermo, CA Serial: 1J9P4AA43L2001148	
<b>Lot #</b>	104	
<b>Qty</b>	1	
<b>Title</b>	2003 FORD F450 4X2 SERVICE TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Rust Throughout Bed Of Truck, Drivers Seat Torn. Showing: 407,138 Miles. Location: Jacksonville, FL Serial: 1FDXF46F33EA66951	
<b>Lot #</b>	105	
<b>Qty</b>	1	
<b>Title</b>	2007 KENWORTH T300 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE W/ FLUID, FULL OPERATIONS NOT TESTED. ABS And Check Transmission Warning Lights On Dash, Vin Tag Is Illegible, Known Transmission Issues- Can Not Return Back To Neutral From Drive Or Reverse, Rear Tires Singled Out, Mileage On Dash Is Not Accurate. Showing 179,000 Miles; 23,000 Hours. Location: Commerce City, CO Serial: 2NKMHZ7X87M205448	

<b>Lot #</b>	106	
<b>Qty</b>	1	
<b>Title</b>	1999 MACK MS250P SWEEPER	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. DASH APART, Cannot Open Engine Cab, Rear Tires Singled Out, No Axle Weight Tag. Mileage/Hours Unavailable. Location: Elgin, IL Serial: VG6M117B8XB202722	