





Printable Catalog


Title	NOVEMBER 13 12:00 CST	
Description	Closing Times TBD	
Date	Wed, Nov 13, 2019	
Starts at	12:00 PM	
Address	4747 NE 14th St, Des Moines, IA 50313 USA	
Categories		







Lot #	1	
Qty	1	
Title	2006 PETERBILT 357 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. UNIT IS IN ENGINE PROTECT MODE - RUNS BRIEFLY THEN SHUTS DOWN. Cummins ISL, Hendrickson Suspension, 22 FA, 46 RA, 228 WB, McNeilus Rear Mixer, Aluminum Fuel Tank, Side Mount Water Tank, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Check Engine Light Illuminated, Body Damage/Rust. Showing 73,823 Miles; 7,440 Hours. Location: Dallas, TX Serial: 1NPAL50X46D884654	







Lot #	2	
Qty	1	
Title	2006 STERLING L9500 DUMP TRUCK	
Des.	STARTED ON SITE- NOT ROAD TESTED. CAT C13, Eaton 8LL, Spring Suspension, 20 FA, 46 RA, 212 WB, 16ft 21-Ton Steel Dump Body, Aluminum Fuel Tank, Tarp System, Pusher Axle, Aluminum/Steel Wheels, 425/65R22.5; 11R24.5, PTO, AC, Air Leaks In Dash, Body Damage/Rust. Showing 816,476 Miles. Location: Punta Gorda, FL Serial: 2FZHAZDE36AV65725	







Lot #	3	
Qty	1	
Title	2000 MACK RD690S REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Mack EM7 300 HP, 8 Speed Manual, Hendrickson Suspension, 20 FA, 46 RA, 239 WB, 11 Yrd MTM Rear Mixer, 5.73 Ratio, 125 Gallon Water Tank, 3 Chutes, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, AC, Cruise Control, New Front And Rear Pedestals, Body Damage/Rust. Showing 262,843 Miles; 25,870 Hours. Location: Highland, IL Serial: 1M2P264C5YM030126	







Lot #	4	
Qty	1	
Title	2005 JOHN DEERE 624J WHEEL LOADER	
Des.	NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. UNIT WILL NOT MOVE. HOLE IN TORQUE CONVERTER CASE. DRIVE SHAFTS REMOVED. JD 6068H- 6 Cylinder 496 HP Diesel, Automatic Power Shift 4F/3R, Enclosed ROPS, 101in Bucket - 3.5 Yrd3 Capacity, AC/Heated Cab, Steel Wheels, 20.5R25, Body Damage/Rust. Showing 21,530 Hours. Location: Dallas, TX Serial: DW624JZ599755	







Lot #	5	
Qty	1	
Title	2004 INTERNATIONAL 7400 GARBAGE PACKER	
Des.	STARTED ON SITE - NOT ROAD TESTED. International DT466E, Automatic, Chalmers Suspension, 16 FA, 40 RA, 230 WB, 25 Yrd McNeilus Rear Loader, 2 Can Tippers, Steel Wheels, 315/80R22.5, PTO, AC, A/C Lines Have Been Cut, Oil Leaks - Oil In Water, Check Engine Light On, Check Electrical System Light Illuminated, Body Damage/Rust. Showing 240,841 Miles; 21,824 Hours. Location: High Point, NC Serial: 1HTWGADT64J093416	







Lot #	6	
Qty	1	
Title	2003 MACK CV713 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Mack E7-350 E-TECH LSR, Allison HD4560P Automatic, Camelback Suspension, 20 FA, 46 RA, 227 WB, Rear Mixer, Steel Fuel Tank, Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Electrical Warning W/ Audible Alarm, Body Damage/Rust. Showing 256,722 Miles; 29,004 Hours. Location: Abilene, TX Serial: 1M2AG11C53M002883	
Lot #	7	
Qty	1	
Title	1998 MACK RD688S DUMP TRUCK	
Des.	NON RUNNER. HAS BEEN SITTING FOR A LONG PERIOD. Needs A New Battery, No Coolant In Reservoir, Transmission Leaks Oil, Drivers Side Head Lights Removed, Various Body Damage/Rust. Showing 498,639 Miles. Location: Louisville, TN Serial: 1M2P267C3WM035169	
Lot #	9	
Qty	1	
Title	1999 INTERNATIONAL 2574 1 DUMP TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. ONLY RAN BRIEFLY DURING TEST - ENGINE HAS A HOLE. NO VISIBLE OIL ON DIPSTICK. Oil Seepage Residue At Engine Oil Pan, Rear Axles Leaking, Body Damage/Rust. Showing 478,542 Miles. Location: Hornell, NY Serial: 1HTGGAXT5XH608577	
Lot #	10	
Qty	1	
Title	2006 PETERBILT 357 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Cummins ISL, Eaton 9 Speed LL, Hendrickson Suspension, 22 FA, 46 RA, 223 WB, 11 Yrd McNeilus Rear Mixer, Aluminum Fuel Tank, 125 Gallon Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Dead Batteries, Body Damage/Rust. Showing 212,628 Miles; 6,565 Hours. Location: Dallas, TX Serial: 1NPAL50X56D884677	
Lot #	11	
Qty	1	
Title	2007 INTERNATIONAL 7400 GARBAGE PACKER	
Des.	NON RUNNER. BAD ENGINE. EGR COOLER BAD. DT466 (Oil Leaks Noted), Automatic, Hendrickson Suspension, 16 FA, 40 RA, 228 WB, 25 Yrd. McNeilus Rear Loader, Dual Can Tippers, Upper Winch, Steel Wheels, 315/80R22.5, PTO, AC, Body Damage/Rust. Showing 300,962 Miles; 20,349 Hours. Location: Douglasville, GA Serial: 1HTWGAAT17J429885	
Lot #	13	
Qty	1	
Title	2013 FREIGHTLINER M2 106 ROLL BACK TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. Cummins 6.7L Diesel, Automatic, Air Ride Suspension. 18 RA, 212 WB, 21.5ft Century Aluminum 2 Car Roll Back Body, 50 Gallon Fuel Tank, Winch Cable, Wheel Under Lift, 4 D-Rings, Left/Right Under Storage, Headache Rack, Aluminum Wheels, 255/70R22.5, PTO, AC, ABS Warning Light Illuminated, Rock Chip Damage On Front, Body Damage/Rust. Showing 495,186 Miles; 9,079 Hours. Location: Des Moines, IA Serial: 1FVACWDT1DHFA4098	







Lot #	14	
Qty	1	
Title	2000 MACK RD690S REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Mack EM7 300 E-TECH, T2080B 8 Speed Manual, Hendrickson Suspension, 20 FA, 46 RA, 236 WB, 11 Yrd Bridge Rear Mixer, 5.73 Ratio, 125 Gallon Water Tank, 3 Chutes, Slump Gauge, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, AC, Newer Front And Rear Pedestals, Body Damage/Rust. Showing 237,803 Miles; 20,292 Hours. Location: Highland, IL Serial: 1M2P264C6YM031897	
Lot #	16	
Qty	1	
Title	2008 KOMATSU WA320-6 WHEEL LOADER	
Des.	NO TITLE PER STATE REGULATIONS. NON RUNNER - BAD HYDRO PUMP. Komatsu D107E Diesel 128 HP, Hydrostatic 4F/4R, Enclosed ROPS, 106in Wide Bucket, AC/Heated Cab, Steel Wheels, 20.5R15, Warning Lights Illuminated - See Photos, Body Damage/Rust. Showing 25,597 Hours. Location: Dallas, TX Serial: 70023	
Lot #	17	
Qty	1	
Title	1987 GMC BRIGADIER DUMP TRUCK	
Des.	STARTED ON SITE NOT ROAD TESTED. GM6-71 7.0L 6 Cyl Diesel (Saturated In Oil- Source Unknown), Eaton 8LL Manual, Walking Beam Suspension, 17.5 FA, 18 RA, 234 WB, 16ft Valley Dump Body, Steel Wheels, 425/65R22.5; 1R22.5, Dual Steel Fuel Tanks, E-Brake, PS, Body Damage/Rust. Showing 102,974 Miles; 5,033 Hours. Location: Rochester, NY Serial: 1GDT9C4Z4HV507572	
Lot #	18	
Qty	1	
Title	2003 MACK CV713 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Mack AI-350 ASET, Allison 4560P Automatic, Camelback Suspension, 20 FA, 227 WB, 10.5 Yrd McNeilus Rear Mixer, Steel Fuel Tank, Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Audible Warning Alarm, High Oil Pressure, Dead Batteries, Body Damage/Rust. Showing 257,072 Miles; 26,627 Hours. Location: Abilene, TX Serial: 1M2AG11CX3M004709	
Lot #	19	
Qty	1	
Title	2005 SNRKL AERIAL LIFT	
Des.	NO TITLE PER STATE REGULATIONS. STARTED ON SITE- FULL OPERATIONS NOT TESTED. CONTROLS WORK FROM GROUND ONLY - WHEN USING CONTROLS FROM PLATFORM, UNIT SHUTS DOWN. Duetz Diesel, Steel Wheels, 15-19.5, Body Damage/Rust. Showing 7,792 Hours. Location: Dallas, TX Serial: 9306981093	
Lot #	21	
Qty	1	
Title	2004 INTERNATIONAL 7400 GARBAGE PACKER	
Des.	NON RUNNER. CRANKS BUT NO START. International DT466E, Automatic, Chalmers Suspension, 16 FA, 40 RA, 230 WB, 25 Yrd McNeilus Rear Loader, 2 Can Tippers, Steel Wheels, 315/80R22.5, PTO, AC, Backup Camera, A/C Lines Have Been Cut, Missing Driver's Side Door, Crack In Windshield, Body Damage/Rust. Showing 250,895 Miles; 28,330 Hours. Location: High Point, NC Serial: 1HTWGADT84J093398	







Lot #	22	
Qty	1	
Title	2006 PETERBILT 357 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. DRUM DID NOT SPIN. Cummins ISL, Eaton 9 Speed LL, Hendrickson Suspension, 22 FA, 46 RA, 225 WB, McNeilus Rear Mixer, Aluminum Fuel Tank, Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Right F/ Wheel Hub Seal Leaking, Body Damage/Rust. Showing 29,744 Miles; 8,083 Hours. Location: Dallas, TX Serial: 1NPAL50X06D884666	
Lot #	23	
Qty	1	
Title	2012 MACK CXU613 DAY CAB TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. RAN BRIEFLY THEN SHUT DOWN DUE TO NO WATER IN RADIATOR. TRUCK HAS WRECK DAMAGE TO DRIVER SIDE. Oil Seepage At Oil Pan, Driver Side Door Glass Broken, Damage Inside Steering Box, Radiator Damaged - Has No Water/Coolant In System, Several Warning Lights And Active Fault Codes - See Report, Various Body Damage/Rust. Showing 716,092 Miles (ECM); 19,092 Hours. Location: Byram, MS Serial: 1M1AW07Y8CM017396	
Lot #	24	
Qty	1	
Title	2000 MACK RD690S REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Mack EM7 300 HP, 8 Speed Manual, Hendrickson Suspension, 20 FA, 46 RA, 239 WB, 11 Yrd MTM Bridgmaster Rear Mixer, 5.73 Ratio, 125 Gallon Water Tank, 3 Chutes, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, AC, Cruise Control, Newer Front And Rear Pedestals, Body Damage/Rust. Showing 210,784 Miles; 22,162 Hours. Location: Highland, IL Serial: 1M2P264C0YM030129	
Lot #	25	
Qty	1	
Title	GROVE MZ48B AERIAL LIFT	
Des.	NO TITLE PER STATE REGULATIONS. NON RUNNER - CRANKS NO START. Wisconsin VH4D Gas, 42ft Platform Height, Steel Wheels, 305-70D16.5, Body Damage/Rust. Showing 3,592 Hours. Location: Dallas, TX Serial: 16497	
Lot #	26	
Qty	1	
Title	2002 MACK CV713 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. MISSING HYDRAULIC LINES FOR CHUTE - OIL DUMPING OUT. Mack EM7-300 E-TECH LSR, Eaton Fuller RTO14909ALL 9 Speed LL, Hendrickson Suspension, 20 FA, 46 RA, 236 WB, 11 Yrd McNeilus Rear Mixer, Aluminum Fuel Tank, Side Mount Water Tank, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Hub Leak At Left Front Tire, Dead Batteries, Body Damage/Rust. Showing 174,463 Miles; 19,495 Hours. Location: Abilene, TX Serial: 1M2AG12C52M001942	
Lot #	27	
Qty	1	
Title	1996 CASE 570LXT SKIP LOADERS	
Des.	NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. BAD SEAL LEAKS ON LEFT BUCKET CYLINDER AND RIGHT LIFT CYLINDER. Case 4-390 Diesel, Open ROPS, 92in Front Bucket, 85in Rear Attachment, Steel Wheels, 36x11; 19.5-24, Tires Dry Rot, Body Damage/Rust. Showing 2,514 Hours. Location: Dallas, TX Serial: JJG0223521	



Lot #	29	
Qty	1	
Title	2002 MACK RD6885 ROLLOFF TRUCK	
Des.	NON RUNNER. Mack E7 350 HP, 184560P, Hendrickson Suspension, 20 FA, 46 RA, 207 WB, 33.75ft Total Length, Dual Steel Fuel Tanks, Steel Wheels, 315/80R22.5, Body Damage/Rust. Showing 652,128 Miles. Location: Wittenburg, WI Serial: 1M2P267C32M064830	
Lot #	30	
Qty	1	
Title	1999 MACK RD690S REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Mack EM7-300 EUP, T2080B 8 Speed Manual, Hendrickson Suspension, 20 FA, 46 RA, 236 WB, 11 Yrd Bridge Mixer, 5.73 Ratio, 125 Gallon Water Tank, 3 Chutes, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, AC, Cruise Control, Newer Front And Rear Pedestals, Body Damage/Rust. Showing 61,315 Miles; 20,705 Hours. Location: Highland, IL Serial: 1M2P264C0XM029996	
Lot #	31	
Qty	1	
Title	2008 MACK CXU612 DAY CAB TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. REAR FRAME SLICED IN REAR, CRACK NOTED. Mack MP7 365 HP, Allison 4500HS GEN4, Air Ride Suspension, 198 WB, REPTO, 101 Gallon Fuel Tank, Steel Wheels, 11R22.5, Check Engine Light Illuminated, Crack In Frame, Frame Spliced In Rear, Body Damage/Rust. Showing 103,614 Miles; 18,323 Hours. Location: Buckeye, AZ Serial: 1M1AW01X18N001347	
Lot #	33	
Qty	1	
Title	2007 HEIL 1040 PNEUMATIC TRAILER	
Des.	Unit Had No Power To Check Lights, Right Front Axle Frame Cracked, Various Body Damage/Rust. Location: Mokena, IL Serial: 5HTSN422877T12628	
Lot #	34	
Qty	1	
Title	2006 PETERBILT 357 REAR MIXER	
Des.	STARTED ON SITE- NOT ROAD TESTED. MISSING WATER PUMP AND FAN ASSEMBLY. Cummins ISL, Eaton 9 Speed LL, Hendrickson Suspension, 18.74 FA, 46 RA, 228 WB, 10.5 Yrd McNeilus Rear Mixer, Aluminum Fuel Tank, 125 Gallon Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Dead Batteries, Body Damage/Rust. Showing 261,971 Miles; 27,016 Hours. Location: Dallas, TX Serial: 1NPAL50X66D649074	
Lot #	35	
Qty	1	
Title	2001 OSHKOSH 6X6 FRONT MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Front Discharge 11 YD Loadspan Mixer System, Air Lift Pusher Axle, Chalmers Suspension, Oil Seepage Noted At Engine Oil Pan, Fuse Panel Missing, Drive Axles Leaking At Forward Drive And Fluid Residue Noted At Rear Drive Pinion Seal Area, Air Leak Noted When Powered Down, Front Left Shock Leaking, Radio Inoperable, Various Body Damage/Rust. Showing 17,900 Hours; 3,663 Hours. Location: Farmington, NY Serial: 10TJPAE231S070674	







Lot #	36	
Qty	1	
Title	2005 VOLVO VHD64B REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Volvo D12 365 HP, 9LLRTO14909ALL, Spring Suspension, 20 FA, 46 RA, 214 WB, 11 Yrd MTM Mixer, Slump Gauge, Full Locking Rears, 4.89 Ratio, Steel Wheels, AC, PTO, Cruise Control, New Batteries, Body Damage/Rust. Showing 154,880 Miles. Location: St. Louis, MO Serial: 4V5KC9GF75N375506	
Lot #	37	
Qty	1	
Title	2000 CATERPILLAR 960F WHEEL LOADER	
Des.	NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. ENGINE BLOW BY. CAT, Automatic, Enclosed ROPS, 119x50in Bucket, AC/Heated Cab, Steel Wheels, 32.5R25, Oil Leak Noted, Front Edge Worn, Missing Both Sides Body Engine Covers, Dead Batteries, Body Damage/Rust. Showing 16,871 Hours. Location: Chesapeake, VA Serial: 6XL00196	
Lot #	38	
Qty	1	
Title	2005 INTERNATIONAL 5600i REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Cummins ISM 350 HP, Eaton 9 Speed LL, Bogey Suspension, 214 WB, 10.5 Yrd Beck Rear Mixer, Aluminum Fuel Tank, Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Right Rear Outer Tire Flat Off Rim, Body Damage/Rust. Showing 318,820 Miles; 26,450 Hours. Location: Brownwood, TX Serial: 1HTXHAHT25J138607	
Lot #	39	
Qty	1	
Title	2007 INTERNATIONAL 7400 GARBAGE PACKER	
Des.	STARTED ON SITE W/ STARTING FLUID - NOT ROAD TESTED. KNOWN ENGINE AND ELECTRICAL ISSUES. International DT466E, Automatic, Hendrickson Suspension, 228 WB, 25 Yrd McNeilus Rear Loader, L/R Steering, 2 Can Tippers, Steel Wheels, 315/80R22.5, PTO, AC, Backup Camera, Power Steering Oil Leaks, Missing Right Tail Light, Check Engine Light Illuminated, Dash/Odometer Not Working Properly, Body Damage/Rust. Mileage Unavailable. Location: Williamston, NC Serial: 1HTWGAAT87J425624	
Lot #	40	
Qty	1	
Title	1999 MACK RD690S REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Mack EM7-300 EUP, T2080B 8 Speed Manual, Hendrickson Suspension, 20 FA, 46 RA, 236 WB, 11 Yrd Bridge Mixer, 5.73 Ratio, 125 Gallon Water Tank, 3 Chutes, Slump Gauge, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, AC, Cruise Control, Newer Front And Rear Pedestals, Body Damage/Rust. Showing 35,721 Miles; 17,893 Hours. Location: Highland, IL Serial: 1M2P264C9XM029995	
Lot #	41	
Qty	1	
Title	1993 PETERBILT 379 EXT HOOD DAY CAB TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. Oil Residue At Top And Bottom Of Air Compressor and At Oil Pan, Damp Oil At Lower Left, Engine Hour Meter Inoperable, Power Steering Reservoir Hose Leaking, Oil Buildup At Rear Axle, Various Body Damage/Rust. Showing 1,338,255 Miles. Location: Hornell, NY Serial: 1XP5DB9X2PD325188	








Lot #	42	
Qty	1	
Title	2002 PETERBILT 357 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. CAT C10 320 HP, Eaton 9 Speed LL, Hendrickson Suspension, 18.74 FA, 46 RA, 225 WB, 10.5 Yrd Continental Rear Mixer, Aluminum Fuel Tank, Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, ABS Warning Light Illuminated, Body Damage/Rust. Showing 573,365 Miles; 4,775 Hours. Location: Dallas, TX Serial: 1NPALT0X92D570027	
Lot #	44	
Qty	1	
Title	2006 PETERBILT 357 REAR MIXER	
Des.	NON RUNNER. IGNITION MISSING. GEAR SHIFT DISASSEMBLED. Cummins ISL, Automatic, Walking Beam Suspension, 20 FA, 38 RA, 252 WB, 10.5 YRD. McNeilus Mixer, Side Mount Water Tank, 13,200 Lb. Bridge Axle, Aluminum Wheels, 425/65R22.5, Aluminum Fuel Tank, PTO, AC, Body Damage/Rust. Mileage Unavailable. Location: Des Moines, IA Serial: 1NPAL50X26D638105	
Lot #	45	
Qty	1	
Title	2001 FREIGHTLINER FL112 ROLLOFF TRUCK	
Des.	DOOR SWAP- CHECK FRAME FOR VIN. STARTED ON SITE- NOT ROAD TESTED. Cummins ISM, Manual, Spring Suspension, 264 WB, Double Frame, Steel Wheels, 315/80R22.5, PTO, AC, Body Damage/Rust. Showing 376,399 Miles. Location: Adel, GA Serial: 1FVHBGA881HJ65795	
Lot #	46	
Qty	1	
Title	1999 MACK RD690S REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Mack EM7 300-HP EUP, T2080B 8 Speed Manual, Hendrickson Suspension, 20 FA, 46 RA, 236 WB, 11 Yrd Bridge Mixer, 125 Gallon Water Tank, 5.73 Ratio, Slump Gauge, 3 Chutes, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, AC, Cruise Control, Body Damage/Rust. Showing 231,393 Miles; 22,372 Hours. Location: Highland, IL Serial: 1M2P264CXXM029990	
Lot #	47	
Qty	1	
Title	2005 MACK CV513 CAB & CHASSIS	
Des.	NON RUNNER. BAD ENGINE. MISSING SEVERAL COMPONENTS, INCLUDING: DRUM, DRIVERS SEAT, GEAR BOX, ENGINE FUEL PUMP, ENGINE ECM, REAR CHUTE, DRIVE LINE, AND HYDRAULIC CYLINDER. Mack AI-400 ASET Diesel, Eaton Fuller RTO14909ALL, Bogey Suspension, 20 FA, 38 RA, 248 WB, 10.5 Yrd McNeilus Rear Mixer Body, 150 Gallon Cross Mount Water Tank, Aluminum Fuel Tank, Bridge Axle, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Metal In Oil Pan, Oil Pan Loose On Engine, Body Damage/Rust. Mileage Unavailable. Location: Raleigh, NC Serial: 1M2AG02CX5M002020	
Lot #	49	
Qty	1	
Title	2003 FREIGHTLINER COLUMBIA 120 DAY CAB TRUCK	
Des.	NON RUNNER - NO ELECTRICAL POWER. COOLANT LEVEL VERY LOW IN RESERVOIR WITH DARK STAINS IN TANK. Oil Seepage Noted Around Air Compressor Area Of Engine And Oil Pan, Various Body Damage/Rust. Mileage Unavailable. Location: Brockport, NY Serial: 1FUJA6AV43LL89154	







Lot #	50	
Qty	1	
Title	2000 KENWORTH T800B REAR MIXER	
Des.	NON RUNNER - CRANKS NO START. CAT C10 305 HP, Eaton 9 Speed LL, Bogey Suspension, 20 FA, 46 RA, 225 WB, 10.5 Yrd McNeilus Rear Mixer, Aluminum Fuel Tank, 150 Gallon Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, Body Damage/Rust. Showing 27,280 Miles; 29,553 Hours. Location: Brownwood, TX Serial: 1NKDLT0X6YR853550	
Lot #	51	
Qty	1	
Title	2005 KOMATSU WA480 WHEEL LOADER	
Des.	NO TITLE PER STATE REGULATIONS. NON RUNNER - ENGINE SEIZED. Location: Miami, FL Serial: A37120	
Lot #	52	
Qty	1	
Title	2007 PETERBILT 357 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. BRAKE PEDAL IS FROZEN - CANNOT BE DRIVEN. NEEDS DRUM. CAT C13, Automatic, Hendrickson Suspension, 22 FA, 42 RA, 219 WB, 10.5 Yrd Continental Rear Mixer, 3 Chutes, Aluminum Fuel Tank, 90 Gallon Side Mount Water Tank, Aluminum/Steel Wheels, 445/65R22.5; 11R22.5, PTO, AC, Oil Leaks, Hydraulic Oil Leaks, Batteries Dead, Body Damage/Rust. Showing 197,485 Miles; 19,049 Hours. Location: Fort Myers, FL Serial: 1NPALFOX37D678099	
Lot #	53	
Qty	1	
Title	2004 INTERNATIONAL 7400 GARBAGE PACKER	
Des.	NON RUNNER. RELAY CLICK ONLY. International DT466E, Automatic, Chalmers Suspension, 222 WB, 20 Yrd McNeilus Rear Loader, 2 Can Tippers, Steel Wheels, 11R22.5, PTO, AC, A/C Lines Have Been Cut, Body Damage/Rust. Showing 332,258 Miles; 24,323 Hours. Location: High Point, NC Serial: 1HTWCAAN94J025841	
Lot #	54	
Qty	1	
Title	2007 PETERBILT 357 REAR MIXER	
Des.	NON RUNNER. Cummins ISL, Eaton 9 Speed LL, Hendrickson Suspension, 18.74 FA, 46 RA, 228 WB, 10.5 Yrd McNeilus Rear Mixer, Aluminum Fuel Tank, 125 Gallon Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 282,408 Miles. Location: Dallas, TX Serial: 1NPAL50X57D654347	
Lot #	55	
Qty	1	
Title	2003 MACK CV713 CAB & CHASSIS	
Des.	NON RUNNER - NO POWER TO UNIT. AIR BOX REMOVED AND IN CAB, EXHAUST TIPS HAVE BEEN CUT AND ARE IN CAB. Mack AI 350, Eaton Fuller Automatic, Hendrickson Suspension, 20 FA, 46 RA, 254 WB, 59 Gallon Dual Steel Fuel Tanks, 248in Back Cab To End Frame, Steel Wheels, 315/80R22.5, AC, Oil Seepage Noted, Body Damage/Rust. Mileage Unavailable. Location: Des Moines, IA Serial: 1M2AG11C33M007290	







Lot #	57	
Qty	1	
Title	2000 MACK CH613 DAY CAB TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. Mack E7-355/380 Reman, Fuller RTLO15610B Air Ride Suspension, 163 WB, Air Slide Fifth Wheel, Dual Aluminum Fuel Tanks, Aluminum/Steel Wheels, 11R22.5; 455/55R22.5, AC, Body Damage/Rust. Showing 422,587 Miles; 38,798 Hours. Location: Odessa, FL Serial: 1M1AA13Y6YW122914	
Lot #	58	
Qty	1	
Title	2000 INTERNATIONAL 5600i REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Cummins ISM 335 HP, Eaton 9 Speed LL, Hendrickson Suspension, 20 FA, 46 RA, 212 WB, 10.5 Yrd McNeilus Rear Mixer, Aluminum Fuel Tank, 125 Gallon Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 232,444 Miles; 24,149 Hours. Location: Amarillo, TX Serial: 1HTXHAHTXYJ005209	
Lot #	59	
Qty	1	
Title	2010 MACK STRAIGHT TRUCK	
Des.	NON RUNNER. TURNS OVER BUT DOES NOT START. MISSING FUEL INJECTORS AND CUPS. DRIVE SHAFT REMOVED. Mack MP8 415 HP, Automatic, Air Ride Suspension, 13.2 FA, 40 RA, 228 WB, 22.5ft Marion Box Body, 79 Gallon Aluminum Fuel Tank, Rear Lift, Steel/Aluminum Wheels, 11R22.5, AC, Hood Damage, Front Bumper Bent, Rear Lift Unknown Operating Condition, Body Damage/Rust. Showing 385,431 Miles; 9,999 Hours. Location: Des Moines, IA Serial: 1M2AW09C4AM012514	
Lot #	60	
Qty	1	
Title	2007 OSHKOSH F2346 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. NEEDS DRUM. Cummins ISM, Eaton 10 Speed, Chalmers Suspension, 23 FA, 46 RA, 207 WB, 10.5 Yrd McNeilus Rear Mixer, 3 Chutes, Aluminum Fuel Tank, 125 Gallon Side Mount Water Tank, Aluminum/Steel Wheels, 445/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 124,269 Miles; 10,669 Hours. Location: Punta Gorda, FL Serial: 10TDDAC307S092903	
Lot #	61	
Qty	1	
Title	2004 INTERNATIONAL 7400 GARBAGE PACKER	
Des.	NON RUNNER. ELECTRICAL PROBLEMS. International DT466E, Automatic, Chalmers Suspension, 16 FA, 40 RA, 230 WB, 25 Yrd McNeilus Rear Loader, 2 Can Tippers, Steel Wheels, 315/80R22.5, PTO, AC, Backup Camera, Body Damage/Rust. Showing 198,457 Miles; 20,703 Hours. Location: High Point, NC Serial: 1HTWGADT44J014762	
Lot #	62	
Qty	1	
Title	2009 MACK GU713 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Oil Leaking At Rear Seal And Transmission, Hydraulic Oil Buildup Forward Of Mixer, Various Body Damage/Rust. Showing 135,057 Miles; 13,618 Hours. Location: Richmond, VA Serial: 1M2AX04C59M005538	

Lot #	63	
Qty	1	
Title	2002 MACK CV713 CAB & CHASSIS	
Des.	STARTED ON SITE - RAN ROUGH. ENGINE BLOW BY. NOT ROAD TESTED. Mack E7-350 E-TECH LSR, Maxitorque T2090, Camelback Suspension, 16.54 FA, 44 RA, 265 WB, Double Frame, 81 Gallon Steel Fuel Tank, Tag Axle With Steel 11R22.5, 214in Back Cab To End Frame, Steel Wheels, 315/80R22.5, AC, Dead Batteries, Warning Lights Illuminated - See Photos, Body Damage/Rust. Showing 770,904 Miles; 39,708 Hours. Location: Des Moines, IA Serial: 1M2AG11C02M002336	
Lot #	64	
Qty	1	
Title	2007 CASE 821E WHEEL LOADER	
Des.	NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. DOES NOT MOVE - COMMUNICATION PROBLEM WITH TRANSMISSION AND ELECTRONICS. WILL NEED ECM OR WIRE HARNESS. Case Diesel, Automatic, Enclosed ROPS, AC/Heated Cab, 117x52in Bucket, Steel Wheels, 23.5-25, Warning Lights Illuminated - See Photos, Hydraulic Cylinders Leak, Bucket Poor Condition, Body Damage/Rust. Hours Unavailable. Location: Charlotte, NC Serial: N7F200475	
Lot #	65	
Qty	1	
Title	2000 VOLVO VNM64T DAY CAB TRUCK	
Des.	RUNNING CONDITION UNKNOWN - LESS KEY. Cummins N14 435 HP, Eaton 10 Speed, Air Ride Suspension, 12 FA, 40 RA, 165 WB, Air Slide Fifth Wheel, Dual Aluminum Fuel Tanks, Aluminum/Steel Wheels, 11R22.5; 455/55R22.5, AC, Body Damage/Rust. Mileage Unavailable. Location: Odessa, FL Serial: 4V4MD2JH4YN249300	
Lot #	66	
Qty	1	
Title	2006 PETERBILT 357 REAR MIXER	
Des.	NON RUNNER - CRANKS NO START. DRIVE SHAFT REMOVED. MIXER MOTOR DISASSEMBLED. Cummins ISL, Eaton 9 Speed LL, Hendrickson Suspension, 22 FA, 46 RA, 228 WB, 10.5 Yrd McNeilus Rear Mixer, Aluminum Fuel Tank, 125 Gallon Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Stop Engine Warning Light Illuminated, Check Engine Light Illuminated, No Oil On Dip Stick, Body Damage/Rust. Showing 52,043 Miles; 425 Hours. Location: Dallas, TX Serial: 1NPAL50X56D884663	
Lot #	67	
Qty	1	
Title	2001 HEIL 1040 CU FT PNEUMATIC TRAILER	
Des.	41ft Total Length, 96in Width, Aluminum Body Composition, 1040 Cubic Ft. Capacity, 3 Compartments, 2 Top Hatches, Aluminum/Steel Wheels, 295/75R22.5, Missing Several Components, Including: Rear Axle, Lower Hopper Gates And Tubes, And Left Side Fenders, Body Damage/Rust. Location: Houston, TX Serial: 5HTSN412217T08650	
Lot #	68	
Qty	1	
Title	2005 STERLING LT9500 REAR MIXER	
Des.	STARTED ON SITE- NOT ROAD TESTED. CAT C11, Eaton 8LL, Hendrickson Suspension, 20 FA, 46 RA, 208 WB, 10.5 Yrd Kimble Rear Mixer, Aluminum Fuel Tank, 125 Gallon Side Mount Water Tank, Two Chutes, Aluminum Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 116,668 Miles. Location: Davenport, FL Serial: 2FZHAZDE25AU83435	







Lot #	69	
Qty	1	
Title	2004 INTERNATIONAL 7400 GARBAGE PACKER	
Des.	STARTED ON SITE - NOT ROAD TESTED. International DT466E, Automatic, Chalmers Suspension, 16 FA, 20 RA, 230 WB, 25 Yrd McNeilus Rear Loader, 2 Can Tippers, Steel Wheels, 315/80R22.5, PTO, AC, A/C Lines Have Been Disconnected, Check Engine Light Illuminated, Body Damage/Rust. Showing 254,281 Miles; 12,300 Hours. Location: High Point, NC Serial: 1HTWGADT94J014756	
Lot #	70	
Qty	1	
Title	2002 INTERNATIONAL 5600i REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. DRUM THIN. Cummins ISM, Automatic, Hendrickson Suspension, 22 FA, 45 RA, 236 WB, 10.5 Yrd McNeilus Rear Mixer, Aluminum Fuel Tank, 150 Gallon Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 282,844 Miles; 24,020 Hours. Location: Amarillo, TX Serial: 1HTXLAHT12J027427	
Lot #	71	
Qty	1	
Title	1999 MACK RD688S CAB & CHASSIS	
Des.	ENGINE TURNS OVER. STEERING IS NOT CONNECTED. NO BATTERY CABLES. Mack E7-350 EUP, Maxitorque T2090 8 Speed, Camelback Suspension, 18 FA, 46 RA, 265 WB, Double Frame, 220in Back Cab To End Frame, Steel Fuel Tank, Spoke Wheels, 315/80R22.5, AC, Oil Seepage Noted, Damage To Hood And Bumper, Body Damage/Rust. Showing 517,158 Miles; 8,006 Hours. Location: Des Moines, IA Serial: 1M2P267C8XM047688	
Lot #	73	
Qty	1	
Title	2006 KENWORTH T300 COMPRESSOR UTILITY TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. COULD NOT GET AIR COMPRESSOR TO FUNCTION. CAT C7 Diesel, 6 Speed Manual, 276 WB, Rear Cummins Air Compressor - Showing 7,869 Hours, Steel Wheels, 11R22.5, AC, Air Compressor Missing Hoses, Body Damage/Rust. Showing 187,997 Miles. Location: Davenport, FL Serial: 2NKMHD7XX6M118376	
Lot #	74	
Qty	1	
Title	2003 MACK CV513 REAR MIXER	
Des.	STARTED ON SITE W/ STARTER FLUID AND JUMP - NOT ROAD TESTED. BAD ENGINE KNOCK, WILL NOT IDLE, ENGINE BLOW BY. Mack AT400, Eaton 9 Speed LL, Walking Beam Suspension, 20 FA, 38 RA, 252 WB, MTM Bridgemaster Rear Mixer, Aluminum Fuel Tank, Cross Mount Water Tank, 13,200 Lbs. Bridge Axle, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 209,219 Miles; 22,368 Hours. Location: Dallas, TX Serial: 1M2AG02C23M001490	
Lot #	75	
Qty	1	
Title	1999 VOLVO L90C WHEEL LOADER	
Des.	NO TITLE PER STATE REGULATIONS. STARTED ON SITE W/ A JUMP BUT SHUT DOWN BEFORE INSPECTION WAS COMPLETED. UNIT WOULD NOT MOVE WHEN TESTED. ENGINE BLOW BY. Many Lights Inoperable - See Report, Wipers Inoperable, Gauges Inoperable, Steering Column Held In Place Via Bungee Cord, Passenger Side Engine Cowl Support Struts Did Not Function, Various Body Damage/Rust. Showing 21,357 Hours. Location: Gary, IN Serial: L90CV62972	

Lot #	77	
Qty	1	
Title	2002 MACK MR688S GARBAGE PACKER	
Des.	NON RUNNER. CRANKS BUT NO START. DRIVE SHAFT REMOVED WITH TRUCK. CAB WOULD NOT JACK UP. Mack E7-300 EUP LSR, Allison HD4560P Automatic, Camelback Suspension, 197 WB, 25 Yrd McNeilus Rear Loader, 1 Can Tipper, Steel Wheels, 315/80R22.5, PTO, AC, Backup Camera, Needs An In Frame, Body Damage/Rust. Showing 229,311 Miles. Location: High Point, NC Serial: 1M2K195C52M019986	
Lot #	78	
Qty	1	
Title	2006 MACK CV713 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. London 10.5 YRD. Standard Mixer, Chalmers Suspension, Oil Leaking At Bottom Of Engine And Oil Pan, Electrical Warning Light Illuminated, Dead Battery, Hole In Dash From Removed Item, Rear Axles Leaking, Various Body Damage/Rust. Showing 185,009 Miles; 15,882 Hours. Location: Rochester, NY Serial: 1M2AG11C86M052648	
Lot #	79	
Qty	1	
Title	1995 INTERNATIONAL 4900 CAB & CHASSIS	
Des.	NON RUNNER. NO POWER TO IGNITION. International DT466 Diesel, Allison Automatic, Hendrickson Suspension, 20 FA, 40 RA, 204 WB, Double Frame, 174in Back Cab To End Frame, Steel Fuel Tank, Spoke Wheels, 315/80R22.5, PTO, Body Damage/Rust. Showing 308,908 Miles; 30,742 Hours. Location: Des Moines, IA Serial: 1HTSHAAT8SH636771	
Lot #	80	
Qty	1	
Title	2000 INTERNATIONAL 4400 SERVICE TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. HAS A WEAK MOTOR. AIR COMPRESSOR DID NOT FUNCTION. International DT466 Diesel, Automatic, Spring Suspension, 172 WB, 14ft Knapheide Body, Steel Wheels, 225/70R22.5, Body Damage/Rust. Showing 361,282 Miles; 22,485 Hours. Location: Kansas City, MO Serial: 1HTSCAAN3YH269321	
Lot #	81	
Qty	1	
Title	2002 HUSKY FW-21 FLATBED TRAILER	
Des.	28ft Total Length, 21ft Body Length - 16ft Flat, 5ft Slant, 96in Width, Tandem Axle, Steel Wheels, ST225/75R15, Body Damage/Rust. Location: Des Moines, IA Serial: 1N9FW2126A1054176	
Lot #	82	
Qty	1	
Title	2002 MACK CV513 REAR MIXER	
Des.	NON RUNNER. DRIVE LINE REMOVED. MTM Bridgmaster Mixer System, Cross Mount Water Tank, 11,020 Lb. Air Lift Pusher, Oil Leak At Oil Pan, Dead Batteries, Axles Removed, Dash Panel Missing, Various Body Damage/Rust. Mileage Unavailable. Location: Tahlequah, OK Serial: 1M2AG03C12M001204	
Lot #	83	
Qty	1	
Title	1981 INTERNATIONAL 1824 FLATBED TRUCK	
Des.	NON RUNNER. DT466, Manual, Spring Suspension, 172 WB, 14ft Flatbed, Steel Wheels, 10R22, Body Damage/Rust. Showing 84,539 Miles; 672 Hours. Location: Buckeye, AZ Serial: 1HTAA18E3BHA19224	







Lot #	84	
Qty	1	
Title	2004 WESTERN STAR 4900SA REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. MISSING UPPER HOPPER AND CHUTES. CAT C10, Eaton 8LL, Chalmers Suspension, 208 WB, 10.5 Yrd London Rear Mixer, Aluminum Fuel Tank, 125 Gallon Side Mount Water Tank, Two Chutes, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Hydraulic Leaking, Dead Batteries, Body Damage/Rust. Mileage Unavailable. Location: Orlando, FL Serial: 5KKHALAN94PM17527	
Lot #	85	
Qty	1	
Title	1995 FORD F800 STRAIGHT TRUCK	
Des.	UNIT STARTS W/ STARTING FLUID BUT WON'T STAY RUNNING. REAR BRAKES LOCKED UP. Cummins 5.9L Diesel, Automatic, Spring Suspension, 7 FA, 19 RA, 255 WB, Steel Fuel Tank, 296in Back Cab To End Frame, Steel Wheels, 11R22.5; 10R22.5, AC, Oil Seepage Noted, Broken Grill, Passenger Door Will Not Open, Body Damage/Rust. Showing 333,154 Miles. Location: Des Moines, IA Serial: 1FDNF80C2SVA46699	
Lot #	86	
Qty	1	
Title	2000 INTERNATIONAL 5600i REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Cummins ISM 305 HP, Eaton 9 Speed LL, Hendrickson Suspension, 20 FA, 46 RA, 212 WB, McNeilus Rear Mixer, Steel Fuel Tank, Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Dead Batteries, Body Damage/Rust. Showing 202,690 Miles; 22,943 Hours. Location: Amarillo, TX Serial: 1HTTGAHTXYJ004966	
Lot #	87	
Qty	1	
Title	2006 MACK CV713 CAB & CHASSIS	
Des.	NON RUNNER. TURBO AND AIR COMPONENTS MISSING. FRONT DRIVE AXLE DRIVE SHAFT YOKE MISSING - SEE PHOTOS. Mack AMI-370 ASET Remanufactured, Eaton T310 10 Speed, Spring/Camelback Suspension, 18 FA, 46 RA, Double Frame, Steel Fuel Tank, Rear Lift Axle, Steel Wheels, 11R22.5, PTO, AC, Large Hole In Cab, Driver's Side Hood Latch Missing, Driver Side Cab Door Does Not Latch, Window Crank Handles Missing, Various Body Damage/Rust. Mileage Unavailable. Location: Portland, MI Serial: 1M2AG11C66M043138	
Lot #	89	
Qty	1	
Title	1985 INTERNATIONAL 4400 TANK TRUCK	
Des.	NON RUNNER. BOTH ENGINE AND TRANSMISSION REMOVED. Spring Suspension, 187 WB, 50 Gallon Steel Fuel Tank, 13.75ft Body, Spoke Wheels, 11R22.5, Body Damage/Rust. Mileage Unavailable. Location: Kansas City, MO Serial: 1HTLDUXN1FHA20154	
Lot #	91	
Qty	1	
Title	2007 CHEVROLET TAHOE SUV	
Des.	STARTED ON SITE - NOT ROAD TESTED. GMC 5.3L V8 Gas, Automatic, Spring Suspension, 3.2 FA, 4.1 RA, 117 WB, Aluminum Wheels, 265/70R17, AC, PW, PL, PS, PM, Dead Batteries, Body Damage/Rust. Showing 305,831 Miles. Location: Groveland, FL Serial: 1GNFC13J57R116724	





Lot #	92	
Qty	1	
Title	2004 KENWORTH T800 REAR MIXER	
Des.	NON RUNNER. ENGINE PROBLEMS. INTAKE HOSE OFF TURBO. DRIVE SHAFT REMOVED WITH TRUCK. Cummins ISM, Automatic, Chalmers Suspension, 226 WB, 10.5 Yrd McNeilus Rear Mixer, Aluminum Fuel Tank, 125 Gallon Side Mount Water Tank, Three Chutes, Aluminum Wheels, 425/65R22.5; 11R22.5, PTO, AC, Oil Leak Noted, Missing Seats, Missing Rear Remote, Body Damage/Rust. Showing 258,774 Miles. Location: Groveland, FL Serial: 1NKDL00X44J057693	
Lot #	94	
Qty	1	
Title	2000 KENWORTH REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. London 11 YRD. Bridge Axle Mixer System, Side Mount Water Tank, Oil Leaking At Pan - Front To Rear, Various Body Damage/Rust. Showing 40,408 Miles; 3,603 Hours. Location: Rochester, NY Serial: 1NKDLAEX6YJ852703	
Lot #	95	
Qty	1	
Title	2002 INTERNATIONAL 4900 CAB & CHASSIS	
Des.	UNIT STARTED ON SITE W/ STARTING FLUID AND JUMP - WON'T STAY RUNNING. International DT466 Diesel, Automatic, Hendrickson Suspension, 220 WB, Double Frame, 186in Back Cab To End Frame, Steel Fuel Tank, Steel Wheels, 315/80R22.5, Dead Battery, Body Damage/Rust. Showing 276,327 Miles; 34,306 Hours. Location: Des Moines, IA Serial: 1HTSHAAR32H404275	
Lot #	96	
Qty	1	
Title	2001 FORD F350 PICKUP TRUCK	
Des.	STARTED AFTER LONG CRANK - SOME BLACK SMOKE OBSERVED UPON START UP. NOT ROAD TESTED. ENGINE STAGGER WHILE IDLING. Steering And Suspension Are Stiff And Make Noise, Service Engine Light Illuminated, Turbo Seals Leaking, Transmission Shifter Is Stiff And Needs Adjustment, Issues With Transmission And Oil Dip Sticks - See Report, Oil Leaks Noted, Various Body Damage/Rust. Showing 387,598 Miles.	
Lot #	97	
Qty	1	
Title	2005 NAVIGATOR RT5500 FORKLIFT	
Des.	NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. Kubota 4 Cyl. Diesel, Automatic, ROPS, 9.25ft Height, Six 48x2in Forks, Two Masts, Steel Wheels, 31x15.5-15 (Both Front Flat), Body Damage/Rust. Showing 653 Hours. Location: Lakeland, FL Serial: 07056S1311611	
Lot #	98	
Qty	1	
Title	2000 MACK RD690S REAR MIXER	
Des.	NON RUNNER. ENGINE HAS NO OIL PRESSURE. MTM 11 YD Bridgmaster Mixer System, Cross Mount Water Tank, Oil Leak At Oil Pan, City Horn Inoperable, No Tail Lights, Dead Batteries, Power Steering Gear Box Leaking, Various Body Damage/Rust. Showing 23,129 Miles; 6,037 Hours. Location: Tahlequah, OK Serial: 1M2P264C5YM031678	


Lot #	99	
Qty	1	
Title	2008 DODGE 1500 SLT QC PICKUP TRUCK	
Des.	NON RUNNER. BLOWN ENGINE. Chrysler 4.7L V8 Gas, Automatic, Spring Suspension, 142 WB, 6ft Body, Aluminum Wheels, 265/70R17, AC, PW, PL, PM, Body Damage/Rust. Showing 212,356 Miles. Location: Winter Springs, FL Serial: 1D7HA18N58S563363	
Lot #	100	
Qty	1	
Title	2001 OSHKOSH F2346 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Cummins ISM, Eaton 10 Speed, Hendrickson Suspension, 23 FA, 46 RA, 212 WB, 10.5 Yrd McNeilus Rear Mixer, Aluminum Fuel Tank, 125 Gallon Side Mount Water Tank, Three Chutes, Aluminum/Steel Wheels, 445/65R22.5; 12R22.5, PTO, AC, Oil Leak Noted, Body Damage/Rust. Showing 104,348 Miles; 14,426 Hours. Location: Orlando, FL Serial: 10TDDAC301S070424	
Lot #	102	
Qty	1	
Title	2006 INTERNATIONAL 5600i REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Cummins ISM 335 HP, Eaton 9 Speed LL, Hendrickson Suspension, 212 WB, 10.5 Yrd Schwing Stetter Rear Mixer, Aluminum Fuel Tank, Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, ABS Warning Light Illuminated, Dead Batteries, Body Damage/Rust. Showing 208,610 Miles; 17,343 Hours. Location: Stephenville, TX Serial: 1HTXHAHT46J375858	
Lot #	103	
Qty	1	
Title	2004 OSHKOSH F2346 CAB & CHASSIS	
Des.	STARTED ON SITE - NOT ROAD TESTED. MISSING SEVERAL COMPONENTS, INCLUDING: DRUM, GEAR BOX, WATER TANK, AND UPPER HOPPER. Cummins ISM, Eaton 10 Speed, Hendrickson Suspension, 23 FA, 46 RA, 214 WB, 11 Yrd McNeilus Rear Mixer, Aluminum Fuel Tank, Aluminum/Steel Wheels, 445/65R22.5; 12R22.5, PTO, AC, Check Engine Light Illuminated, Dash Apart, No Chutes, Odometer Blurry/Hard To Read, Body Damage/Rust. Showing 154,155 Miles; 15,356 Hours. Location: Groveland, FL Serial: 10TDDAC344S081544	
Lot #	104	
Qty	1	
Title	2004 FORD RANGER PICKUP TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. BRAKE PEDAL SOFT. Oil Leak Noted At Pan/Rear Seal, Transmission Leaking, Shift Indicator Does Not Work, ABS Warning Light Illuminated, Various Body Damage/Rust. Showing 166,133 Miles. Location: Defuniak Springs, FL Serial: 1FTYR44U84PB26195	
Lot #	105	
Qty	1	
Title	2004 MOFFETT M5500BS FORKLIFT	
Des.	NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. LESS KEYS. Kubota 4 Cyl. Diesel, Automatic, ROPS, 9.5ft Height, Four 48x1.5in Forks, 2 Masts, Steel Wheels, 31x15.5-15 (R/ Flat), Body Damage/Rust. Showing 4,122 Hours. Location: Lakeland, FL Serial: D290577	


Lot #	106	
Qty	1	
Title	2002 STERLING LT9500 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Cummins ISM 350 HP, Eaton 9 Speed LL, Bogey Suspension, 20 FA, 46 RA, 221 WB, 10.5 Yrd London Rear Mixer, 75 Gallon Steel Fuel Tank, Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Engine Warning Light Illuminated, Dead Batteries, No In Cab Mixer Controls, Stabilizers Missing, Crack In Mounting Plate And Bushing Cover, Body Damage/Rust. Showing 231,058 Miles; 28,893 Hours. Location: Stephenville, TX Serial: 2FZHAZA812AK53153	
Lot #	107	
Qty	1	
Title	2007 FORD EDGE SUV	
Des.	STARTED BUT RUNS POORLY - WILL NOT REV UP. Ford V6 3.5L Gas, Automatic, Spring Suspension, 111 WB, Aluminum Wheels, 245/60R18, AC, PW, PL, PS, PM, Warning Lights Illuminated - See Photos, Dead Batteries, Body Damage/Rust. Showing 274,779 Miles. Location: Fort Myers, FL Serial: 2FMDK49C17BB69531	
Lot #	108	
Qty	1	
Title	2005 STERLING L9500 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. ENGINE SKIP. AIR CLEANER ASSEMBLY OFF WITH TRUCK. CAT C11, Eaton 8LL, Chalmers Suspension, 20 FA, 46 RA, 221 WB, 10.5 Yrd McNeilus Rear Mixer, Aluminum Fuel Tank, 125 Gallon Side Mount Water Tank, 3 Chutes, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Valve Cover Loose On Engine, Check Engine Light Illuminated, Body Damage/Rust. Showing 304,591 Miles. Location: Kissimmee, FL Serial: 2FZHAZDL75AU91772	
Lot #	110	
Qty	1	
Title	2005 VOLVO VHD REAR MIXER	
Des.	STARTED ON SITE- NOT ROAD TESTED. ENGINE BLOW BY. SHIFTER WORN. AIR LEAK NOTED IN DASH. VE D12- 365 HP, RTO14909ALL 11 Speed, Spring Suspension, McNeilus Rear Mixer (Tag Missing), 125 Gallon Side Mount Water Tank (Sight Glass And Pressure Gauge Missing), Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Warning Lights Illuminated- Including: Brake ECU Light Illuminated, Body Damage/Rust. Showing 196,869 Miles. Location: Harrisburg, PA Serial: 4V5KC9GF35N374613	
Lot #	111	
Qty	1	
Title	1998 KENWORTH T800 CAB & CHASSIS	
Des.	STARTED ON SITE - NOT ROAD TESTED. Oil Seepage At Oil Pan - Front To Rear, City Horn Inoperable, Passenger Mirror Missing, Passenger Side Seat Missing, Various Body Damage/Rust. Showing 91,925 Miles; 11,022 Hours. Location: Brockport, NY Serial: 1NKDLAEX3WJ784888	
Lot #	113	
Qty	1	
Title	2005 MOFFETT M5000HF FORKLIFT	
Des.	NO TITLE PER STATE REGULATIONS. NON RUNNER - LESS KEYS. Showing 5,001 Hours. Location: Miami, FL Serial: E290277	

Lot #	114	
Qty	1	
Title	2000 KENWORTH T800 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Cummins ISM, Eaton 9 Speed LL, Bogey Suspension, 20 FA, 46 RA, 218 WB, McNeilus Rear Mixer, Aluminum Fuel Tank, Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Dead Batteries, Body Damage/Rust. Showing 252,880 Miles; 27,471 Hours. Location: Granbury, TX Serial: 1NKDL00X6YR844524	
Lot #	115	
Qty	1	
Title	2005 FORD F150 4X4 PICKUP TRUCK	
Des.	NON RUNNER. Ford V8 5.4L Gas, Automatic, Spring Suspension, 3.75 FA, 3.85 RA, 139 WB, 5ft Body, AC, PL, PS, PM, Dash Apart, Missing Fuel Tank Cap, Body Damage/Rust. Mileage Unavailable. Location: Fort Myers, FL Serial: 1FTPW14505KE67617	
Lot #	116	
Qty	1	
Title	2007 VOLVO VHD64B REAR MIXER	
Des.	NON RUNNER. MISSING ENGINE ECM. Volvo D12 365 HP, Automatic, Spring Suspension, 20 FA, 46 RA, 214 WB, McNeilus Rear Mixer, Aluminum Fuel Tank, 120 Gallon Side Mount Water Tank, Aluminum/Steel Wheels, 445/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Mileage Unavailable. Location: Odessa, FL Serial: 4V5KC9GFX7N469527	
Lot #	117	
Qty	1	
Title	1999 FREIGHTLINER FL70 WATER TRUCK	
Des.	NON RUNNER. Cummins ISB Diesel, 6 Speed Manual, Spring Suspension, 12 FA, 21 RA, 251 WB, Steel Wheels, 11R22.5, AC, Hose Off Turbo, Body Damage/Rust. Showing 168,538 Miles. Location: Fort Myers, FL Serial: 1FV6HFAA2XHA21464	
Lot #	118	
Qty	1	
Title	2000 MACK DM690S REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Mack EM7-300 EUP Remanufactured, Maxitorque T2080B 8 Speed LL, Camelback Suspension, 212 WB, 10.5 Yrd McNeilus Rear Mixer, Steel Fuel Tank, Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, Body Damage/Rust. Showing 60,943 Miles; 8,989 Hours. Location: Stephenville, TX Serial: 1M2B209C3YM026351	
Lot #	119	
Qty	1	
Title	2005 PETERBILT 357 CAB & CHASSIS	
Des.	NON RUNNER - ENGINE WILL NOT TURN OVER. CAT C11, Automatic, Hendrickson Suspension, 22 FA, 46 RA, 221 WB, Aluminum Wheels, 445/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 261,992 Miles. Location: Bonita Springs, FL Serial: 1NPALT0X25D831499	
Lot #	121	
Qty	1	
Title	2003 MOFFETT M5000HF FORKLIFT	
Des.	NO TITLE PER STATE REGULATIONS. UNIT STARTS BUT DOES NOT OPERATE OR MOVE. ALL HYDRAULIC HOSES DISCONNECTED/CAPPED. MISSING TILT CYLINDER. LESS KEYS. Kubota 4 Cyl. Diesel, Automatic, ROPS, 8ft Height, Four 50x2in Forks, Two Masts, Steel Wheels, 29x12.5-15, Body Damage/Rust. Showing 4,478 Miles. Location: Lakeland, FL Serial: C24081	

Lot #	122	
Qty	1	
Title	2000 STERLING LT9500 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Cummins ISM, Roadranger 9 Speed LL, Bogey Suspension, 20 FA, 46 RA, 221 WB, 10.5 Yrd London Rear Mixer, 75 Gallon Steel Fuel Tank, Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Dead Batteries, No In Cab Mixer Controls, Body Damage/Rust. Showing 242,921 Miles; 28,612 Hours. Location: Granbury, TX Serial: 2FZXEMCB4YAB91559	
Lot #	124	
Qty	1	
Title	2007 VOLVO VHD64 REAR MIXER	
Des.	NON RUNNER. MISSING TURBO. DRIVE LINE REMOVED WITH TRUCK. Volvo D12 365 HP, Eaton 8LL, Spring Suspension, 20 FA, 46 RA, 212 WB, 10.5 Yrd McNeilus Rear Mixer, 125 Gallon Side Mount Water Tank, Two Chutes, Aluminum Wheels, 445/65R22.5; 12R22.5, PTO, AC, Dash Apart, Body Damage/Rust. Mileage Unavailable. Location: Groveland, FL Serial: 4V5KC9GF17N488161	
Lot #	126	
Qty	1	
Title	2001 FREIGHTLINER FLD112 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. London 10.5 YD Mixer System, Chalmers Suspension, Oil Leak Noted At Pan, Both Rear Differentials Leaking, Concrete Build Up At Rear Of Mixer, Various Body Damage/Rust. Showing 211,135 Miles; 9,710 Hours. Location: Farmington, NY Serial: 1FVHAEAN01LJ41467	
Lot #	127	
Qty	1	
Title	2004 WESTERN STAR 4900SA CAB & CHASSIS	
Des.	NON RUNNER. BAD ENGINE. MISSING COMPONENTS INCLUDING DRUM, GEAR BOX, AND UPPER HOPPER. CAT C10 Diesel, Eaton 8LL, Chalmers Suspension, 208 WB, London Rear Mixer Body, 2 Chutes, 90 Gallon Side Mount Water Tank, Aluminum/Steel Wheels, 445/65R22.5; 11R22.5, PTO, AC, Dash Apart, Body Damage/Rust. Mileage Unavailable. Location: Fort Myers, FL Serial: 5KKHALAN24PM17529	
Lot #	129	
Qty	1	
Title	1997 MOFFETT M5000 FORKLIFT	
Des.	NO TITLE PER STATE REGULATIONS. NON RUNNER. MISSING IGNITION SWITCH. Lister Petter 4 Cyl. Diesel, Automatic, ROPS, 8ft Height, Two Masts, Left F/ Tire Missing, Right F/ Flat, Body Damage/Rust. Showing 3,372 Hours. Location: Lakeland, FL Serial: 6584	
Lot #	130	
Qty	1	
Title	2005 MACK CV713 REAR MIXER	
Des.	NON RUNNER - LESS KEYS. DRIVE SHAFT REMOVED. Mack AMI-370 ASET, Maxitorque T310MLR 10 Speed, Camelback Suspension, 20 FA, 46 RA, 227 WB, 10.5 Yrd McNeilus Rear Mixer, 75 Gallon Aluminum Fuel Tank, Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, No In Cab Mixer Controls, Body Damage/Rust. Mileage Unavailable. Location: Granbury, TX Serial: 1M2AG11C05M024695	

Lot #	131	
Qty	1	
Title	1999 FORD F250 EXT CAB PICKUP TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. Ford Triton V10 6.8L, Automatic, Spring Suspension, 4.41 FA, 5.53 RA, 142 WB, Bed Liner, Aluminum Wheels, LT235/85R16, AC, PW, PL, PS, PM, Airbag And Brake Warning Lights Illuminated, Cracked Windshield, Water In Driver Side Headlight, Dead Batteries, Body Damage/Rust. Showing 311,811 Miles. Location: Des Moines, IA Serial: 1FTNX21S5XEC40266	
Lot #	132	
Qty	1	
Title	2006 STERLING LT9500 REAR MIXER	
Des.	NON RUNNER. MISSING ENGINE ECM, DRIVE LINE, AND EXHAUST PIPES. CAT C13, Eaton 8LL, Hendrickson Suspension, 20 FA, 46 RA, 211 WB, 10.5 Yrd Kimble Rear Mixer, Aluminum Fuel Tank, 120 Gallon Side Mount Water Tank, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Mileage Unavailable. Location: Odessa, FL Serial: 2FZHAZDE46AW03611	
Lot #	134	
Qty	1	
Title	2001 FREIGHTLINER FLD112 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. London 10.5 Yrd. Standard Mixer System, Side Mount Water Tank, Oil Leak Noted At Engine Oil Pan - Front To Rear, Batteries Dead, Residue On Left Rear Shock, Holes Drilled In Center of Dash, Oil Residue At Bottom Of Rear Axle, Power Steering Reservoir Hose Leaking, Body Damage/Rust. Showing 280,634 Miles. Location: Brockport, NY Serial: 1FVHAEAN21LJ41468	
Lot #	135	
Qty	1	
Title	2005 OSHKOSH F2346 CAB & CHASSIS	
Des.	NON RUNNER. MISSING SEVERAL COMPONENTS, INCLUDING: ENGINE PARTS, EXHAUST MANIFOLD, TURBO, HOOD, DRUM, DRIVE SHAFT, WATER TANK, PTO AND PUMP, PT PUMP, CHUTES, AND TRANSFER CASE. Cummins ISM, Eaton 10 Speed, Chalmers Suspension, 23 FA, 46 RA, 209 WB, Aluminum Fuel Tank, Aluminum Wheels, 445/65R22.5, AC, Body Damage/Rust. Mileage Unavailable. Location: Odessa, FL Serial: 10TDDAC365S085144	
Lot #	136	
Qty	1	
Title	2007 CHEVROLET COLORADO PICKUP TRUCK	
Des.	STARTED ON SITE- NOT ROAD TESTED. ENGINE KNOCK. FUEL LEAK NOTED AT TOP OF TANK, FUEL SPRAYS WHILE RUNNING. BOX MISSING. FRONT CLIP COMPONENTS MISSING, INCLUDING: HEADLIGHTS, BUMPER, FENDERS, GRILL. Vortec 3.7L, Automatic, Spring Suspension, 124 WB, Aluminum Wheels, 275/75R15; 255/75R15, AC, PW, PL, PM, Check Engine Light Illuminated, Body Damage/Rust. Showing 167,481 Miles. Location: Des Moines, IA Serial: 1GCDT19E678136321	
Lot #	137	
Qty	1	
Title	1997 MOFFETT M5000 FORKLIFT	
Des.	NO TITLE PER STATE REGULATIONS. NON RUNNER. MISSING IGNITION SWITCH. Lister Petter 4 Cyl. Diesel, Automatic, ROPS, 8.5ft Height, Four 50x1.5in Forks, Two Masts, Steel Wheels, 29x12.5-15 (Right F/ Flat), Body Damage/Rust. Showing 3,904 Hours. Location: Lakeland, FL Serial: 6581	

Lot #	138	
Qty	1	
Title	2001 INTERNATIONAL F-2574 REAR MIXER	
Des.	NON RUNNER - CRANKS NO START. Cummins ISM 305 HP, Eaton 9 Speed LL, Hendrickson Suspension, 20 FA, 46 RA, 222 WB, 10.5 Yrd CBMW Rear Mixer, 67 Gallon Steel Fuel Tank, Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, Body Damage/Rust. Showing 265,045 Miles; 28,964 Hours. Location: San Angelo, TX Serial: 1HTGGAHT11H379577	

Lot #	140	
Qty	1	
Title	2005 STERLING LT9513 REAR MIXER	
Des.	NON RUNNER. MISSING ENGINE ECM. CAT C11, Automatic, Hendrickson Suspension, 20 FA, 46 RA, 208 WB, 10.5 Yrd Kimble Rear Mixer, Aluminum Fuel Tank, 125 Gallon Side Mount Water Tank, Single Chute, Aluminum Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Mileage Unavailable. Location: Davenport, FL Serial: 2FZHAZDE75AU19987	