



































## Printable Catalog








<b>Title</b>	JANUARY 17 12:00 CST	
<b>Description</b>	Closing Times TBD	
<b>Date</b>	Wed, Jan 17, 2024	
<b>Starts at</b>	12:00 PM	
<b>Address</b>	4747 NE 14th St, Des Moines, IA 50313 USA	
<b>Categories</b>		
<b>Lot #</b>	1	
<b>Qty</b>	1	
<b>Title</b>	2014 FREIGHTLINER 108SD CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Rust Throughout Unit. Showing: Mileage/Hours Unavailable. Location: Weatherford, TX Serial: 1FVHG5CY8EHFN0270	
<b>Lot #</b>	3	
<b>Qty</b>	1	
<b>Title</b>	2007 INTERNATIONAL PAYSTAR 5500i REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Engine Missing Fan Assembly, Coolant Leak Due To Missing Hose Clamp, Bad Wiring Harness, Grill Is Missing, Engine, Body And Weight Data Tags Not Located, Dash Components Loose/Missing, Fuze Box Cover On P/S Is Removed, Dried Concrete Covering Body. Showing 308,896 Miles; 31,401 Hours. Location: Pasadena, TX Serial: 1HTXLAHT07J459594	
<b>Lot #</b>	4	
<b>Qty</b>	1	
<b>Title</b>	2013 PETERBILT 348 CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Dash Partially De-assembled, Rust Throughout Unit. Showing: Mileage/Hours Unavailable. Location: Weatherford, TX Serial: 2NP3LN0X7DM209865	
<b>Lot #</b>	5	
<b>Qty</b>	1	
<b>Title</b>	2017 VOLVO VNL 6X4 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing 651,490 Miles; 14,827 Hours. Location: Des Moines, IA Serial: 4V4NC9EH1HN983371	
<b>Lot #</b>	6	
<b>Qty</b>	1	
<b>Title</b>	2013 FORD E-350 VAN BODY TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Battery Light On, Small Hail Dents On Cab. Showing: 185,334 Miles. Location: Des Moines, IA Serial: 1FDWE3FL0DDB20924	
<b>Lot #</b>	7	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CTP713 CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Dash Partially De-assembled, Rust Throughout Unit. Showing: Mileage/Hours Unavailable. Location: Weatherford, TX Serial: 1M2AT04C97M005132	

<b>Lot #</b>	9	
<b>Qty</b>	1	
<b>Title</b>	2015 FREIGHTLINER CASCADIA SLEEPER TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. One Inactive Fault, Coolant Level Low, Tank Fairing Missing Lower Molding On Left Side, Clean Idle Sticker Missing, Bunk Trim Not Mounted Properly And Broken, Windshield Chipped. Showing: 75,801 Miles; 19,840 Hours. Location: East Saint Louis, IL Serial: 3AKJGLD57FSGC2766	
<b>Lot #</b>	10	
<b>Qty</b>	1	
<b>Title</b>	2000 CATERPILLAR 928G WHEEL LOADER	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. Rust Throughout Unit, Seat Cover Completely Missing. Showing: Hours Unavailable. Location: Cowan, TN Serial: 6XR02201	
<b>Lot #</b>	12	
<b>Qty</b>	1	
<b>Title</b>	2014 INTERNATIONAL PROSTAR DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Window Has Chip, Paint Chips Throughout Unit. Showing: 384,272 Miles; 16,115 Hours. Location: Des Moines, IA Serial: 1HSDJSNR2EH033020	
<b>Lot #</b>	13	
<b>Qty</b>	1	
<b>Title</b>	2012 FREIGHTLINER M2 106 4X2 VAN BODY TRUCK	
<b>Des.</b>	STARTED ON SITE W/ FLUID, FULL OPERATIONS NOT TESTED. Front Bumper Rusted, Left Gate Went Down But Not Up. Showing: 232,673 Miles; 9,634 Hours. Location: Des Moines, IA Serial: 1FVACWDT4CDBD8207	
<b>Lot #</b>	14	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Dash De-assembled, Rust Throughout Unit. Showing: Mileage/Hours Unavailable. Location: Weatherford, TX Serial: 1M2AG11C86M042931	
<b>Lot #</b>	16	
<b>Qty</b>	1	
<b>Title</b>	2017 FREIGHTLINER CASCADIA SLEEPER TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Two Inactive Faults, Coolant Level Low, Frame Has Signs Of Rust, Dents In Bumper, Grille Cracked And Peeling, Paint Chips Throughout Unit, Quarter Fender Missing On Left Side, Windshield Cracked. Showing: 676,654 Miles; 19,862 Hours. Location: East Saint Louis, IL Serial: 3AKJGLDR0HSHC1970	
<b>Lot #</b>	17	
<b>Qty</b>	1	
<b>Title</b>	2009 MACK GU813 CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Rust Throughout Unit. Showing: Mileage/Hours Unavailable. Location: Weatherford, TX Serial: 1M2AX13C49M004419	








<b>Lot #</b>	19	
<b>Qty</b>	1	
<b>Title</b>	2014 MACK CXU613 6X4 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Missing Radio, Staining And Rock Chips Noted On Hood, Missing Paint On Top Of Cab, Rear Mud Flap Hangers Are Bent Up. Showing 449,174 Miles; 15,637 Hours. Location: Des Moines, IA Serial: 1M1AW09Y4EM039430	
<b>Lot #</b>	20	
<b>Qty</b>	1	
<b>Title</b>	2005 JOHN DEERE 1445 UTV	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. BRUSH ATTACHMENT DOES NOT SPIN, Rust Noted On Body, Headliner Missing From Interior, Glass Scratched. Showing 2,276 Hours. Location: Des Moines, IA Serial: TCCR758040052	
<b>Lot #</b>	24	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Dash De-assembled, Rust Throughout Unit. Showing: Mileage/Hours Unavailable. Location: Weatherford, TX Serial: 1M2AG11C46M035426	
<b>Lot #</b>	25	
<b>Qty</b>	1	
<b>Title</b>	2015 INTERNATIONAL 7400 SBA 6X4 GARBAGE PACKER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. NEEDS MOTOR MOUNT BEFORE DRIVING, MISSING 4 REAR TIRES, Oil Leak Reported- Oil Pan Covered In Oil, Check Engine Warning Light On Dash, 1 Active/5 Inactive Faults Detected- See ECM Report, Body Damage Throughout. Showing 135,031 Miles; 134,996 ECM; 14,066 Hours. Location: Minneapolis, MN Serial: 3HAWGAAT6FL653010	
<b>Lot #</b>	26	
<b>Qty</b>	1	
<b>Title</b>	2017 VOLVO VNL 6X4 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Some Staining To P/S Cloth Door Panel, Cup Holder Is Taped Up, Missing Switch From Center Dash, Area Of Rust On Cab Floor Between Seats. Showing 510,569 Miles; 12,457 Hours. Location: Des Moines, IA Serial: 4V4NC9EH9HN983389	
<b>Lot #</b>	27	
<b>Qty</b>	1	
<b>Title</b>	2004 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. No Power To Dash, Wires Are Cut And Missing, Parts Missing In Dash, Fuel Tank Missing Rear Strap, Step Broken, Right Side Suspension Cracked And Damaged, Right Side Door Will Not Open. Showing: Mileage/Hours Unavailable. Location: Mc Crory, AR Serial: 1M2AG11C14M013350	
<b>Lot #</b>	28	
<b>Qty</b>	1	
<b>Title</b>	2007 VOLVO VHD84B CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. OIL PAN SHOWS SIGNS OF PAST LEAKAGE, Missing Battery Box Cover, Dash Trim Loose And Missing, Paint Chips Throughout, Chrome Peeling, Rear Wheels Rusting, Multiple Codes. Showing: 447,944 Miles. Location: Byram, MS Serial: 4V5K99GG47N484595	








<b>Lot #</b>	30	
<b>Qty</b>	1	
<b>Title</b>	2012 PETERBILT 384 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. TRANSMISSION ISSUES, TRUCK WILL NOT ENGAGE DRIVE OR REVERSE, WILL NOT MOVE. Check Engine Light On, Six Active Faults / Five Inactive Faults, Interior Damage Noted, Air Tanks On Passenger Side Are Not Aligned And Bracket Is Broken, Damaged Noted Throughout Unit, Wiring For Rear Components Have Been Cut, Oil Leaks From The Front And Rear Engine Seals And Oil Pan, Accelerator Not Connected As It Won't Raise RPM, Tires Are Worn. Showing 334,233 Miles; 334,214 ECM; 23,770 Hours. Location: Mobile, AL Serial: 1NPVL79X2CD151725	
<b>Lot #</b>	31	
<b>Qty</b>	1	
<b>Title</b>	2016 FREIGHTLINER CASCADIA SLEEPER TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Two Inactive Faults, Both Axle Housing Have Rust In Pitting, Rear Cross Member Bent, Bottom Skirt On Sleeper Is Loose, Grille Is Cracked, Bumper Scratched, Paint Chips Throughout Unit. Showing: 560,081 Miles; 16,079 Hours. Location: East Saint Louis, IL Serial: 3AKJGLD68GSGY6538	
<b>Lot #</b>	32	
<b>Qty</b>	1	
<b>Title</b>	2008 MACK MRU613 GARBAGE PACKER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. DEAD BATTERIES, MISSING 4 REAR TIRES, Oil Leak Reported, Clutch Play Needs Attention, Tires Worn, L/S Of Bumper Is Bent, 'M' Missing From Mack Emblem On Front Grille, Radio Held In Place With Blue Substance, Shifter Boot Seal Is Cracked, Heil 612-3528 Garbage Packer With 28 YD Capacity. Showing 387,699 Miles; 33,126 Hours. Location: Saint Paul, MN Serial: 1M2AV02CX8M001329	
<b>Lot #</b>	33	
<b>Qty</b>	1	
<b>Title</b>	2004 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Rust Throughout Unit, Hood Missing, Steps Missing. Showing: Mileage/Hours Unavailable. Location: Carnesville, GA Serial: 1M2AG11C14M014059	
<b>Lot #</b>	34	
<b>Qty</b>	1	
<b>Title</b>	2015 MACK CXU613 6X4 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Areas Of Rust Noted, Switch Missing From Center Dash. Showing 475,509 Miles; 22,350 Hours. Location: Des Moines, IA Serial: 1M1AW07Y1FM046257	
<b>Lot #</b>	36	
<b>Qty</b>	1	
<b>Title</b>	2004 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. No Steps, Rust Throughout Unit. Showing: Mileage/Hours Unavailable. Location: Carnesville, GA Serial: 1M2P267C64M067370	
<b>Lot #</b>	37	
<b>Qty</b>	1	
<b>Title</b>	2008 MACK GU813 CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Rust Throughout Unit, Grille Peeling. Showing: Mileage/Hours Unavailable. Location: Carnesville, GA Serial: 1M2AX13C08M002066	

<b>Lot #</b>	38	
<b>Qty</b>	1	
<b>Title</b>	2013 PETERBILT 365 CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. FRONT-REAR AXLE REMOVED. Dash Partially De-Assembled. Rust Throughout Unit. Showing: Mileage/Hours Unavailable. Location: Carnesville, GA Serial: 1NPSL70X0DD184661	
<b>Lot #</b>	39	
<b>Qty</b>	1	
<b>Title</b>	2016 MACK CXU613 SLEEPER TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. OIL RESIDUE / SEEPAGE AROUND ROCKER COVER SEAL, Bottom Edge Of Grille Cracked, Paint Chips Throughout Unit, Mattress Missing, Windshield Chipped, Quarter Fender Broken, Fuse Panel Cover Missing, Right Side Fuel Tank Dented. Showing: 484,469 Miles; 14,957 Hours. Location: East Saint Louis, IL Serial: 1M1AW21Y9GM057528	
<b>Lot #</b>	41	
<b>Qty</b>	1	
<b>Title</b>	2002 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. LESS KEY, WILL NOT BUILD AIR BECAUSE AIR LINE HAS BEEN CUT IN DASH, Oil Line Leaking Oil Into Cab Because Oil Line Has Been Cut, Dash Components Are Missing, Dash Taped, Warning Lights On Dash, P/S Parking Lamp Is Missing, Body Damage And Rust Throughout. Showing 118,163 Miles; 39,459 Hours. Location: Concord, NC Serial: 1M2P267C32M064276	
<b>Lot #</b>	42	
<b>Qty</b>	1	
<b>Title</b>	2016 MACK CXU613 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. ENGINE WILL NOT TURN OVER DUE TO TRANSMISSION NOT INSTALLED. Various Components Are Not Installed, Crack Below P/S Headlight, Grade Gripper Malfunction Warning Message Displayed On Dash, ABS, Coolant Low And Electrical Malfunction Warning Lights On Dash, Misc. Parts In Cab. Showing 501,161 Miles; 13,307 Hours.	
<b>Lot #</b>	43	
<b>Qty</b>	1	
<b>Title</b>	2013 FREIGHTLINER 108SD DISTRIBUTOR TRUCK	
<b>Des.</b>	STARTED ONSITE W/JUMP AND STARTING FLUID, FULL OPERATIONS NOT TESTED. Showing 229,570 Miles; 1,045 Hours. Location: New Braunfels, TX Serial: 1FVAG0BS4DHFA8996	
<b>Lot #</b>	44	
<b>Qty</b>	1	
<b>Title</b>	2012 PETERBILT 348 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Check Engine Warning Light On Dash, D/S Hood Vent Grille Is Missing, Tail Lights Missing, Front Tires Are Low. Showing 238,339 Miles; 15,835 Hours. Location: Harrisburg, PA Serial: 2NP3LN0X2CM169080	
<b>Lot #</b>	46	
<b>Qty</b>	1	
<b>Title</b>	1999 KENWORTH W900L SLEEPER TRUCK	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Engine Tag Not Located, Misc. Parts In Cab, Upholstery Stained And Worn, Minor Scratches Throughout Body. Showing 131,285 Miles. Location: Carnesville, GA Serial: 1XKWDB9X3XR820495	








<b>Lot #</b>	47	
<b>Qty</b>	1	
<b>Title</b>	2003 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. KNOWN ENGINE ISSUE, Low Air Warning Light On Dash, Rear Tires Singled Out, Radio Is Missing. Showing 896,566 Miles, 36,902 Hours. Location: Harrisburg, PA Serial: 1M2AG11C33M007659	
<b>Lot #</b>	48	
<b>Qty</b>	1	
<b>Title</b>	2005 INTERNATIONAL DURASTAR 4300 CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. CRANKS BUT DOES NOT TURN OVER, ABS Light On, Front Bumper Has Paint Chipped And Rust. Showing: 496,088 Miles; 24,224 Hours. Location: Harrisburg, PA Serial: 1HTMMAAL85H101531	
<b>Lot #</b>	49	
<b>Qty</b>	1	
<b>Title</b>	2019 INTERNATIONAL LT625 6X4 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing 556,341 Miles; 12,175 Hours. Location: Des Moines, IA Serial: 3HCDZAPR4KL335059	
<b>Lot #</b>	50	
<b>Qty</b>	1	
<b>Title</b>	1994 FORD LNT8000 ATTENUATOR TRUCK	
<b>Des.</b>	STARTED ONSITE, FULL OPERATIONS NOT TESTED. Damage Throughout Interior, Rust Throughout Body, Grille Is Missing Pieces. Showing 167,379 Miles. Location: New Braunfels, TX Serial: 1FTYR82E3RVA48950	
<b>Lot #</b>	51	
<b>Qty</b>	1	
<b>Title</b>	2011 KENWORTH T300 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Power Train Malfunction And DEF Warning Lights On Dash, Tires Worn. Showing 56,944 Miles; 27,036 Hours. Location: Greenville, OH Serial: 2NKHHM7X2BM292776	
<b>Lot #</b>	52	
<b>Qty</b>	1	
<b>Title</b>	1996 TI-BROOK DUMP TRAILER	
<b>Des.</b>	APPROXIMATE MEASUREMENTS 48 FT LENGTH, 98 IN WIDTH, 13 FT HEIGHT, FULL OPERATIONS NOT TESTED. Wear Throughout Trailer. Location: Elgin, IL Serial: 1T9TAAZ22TB021004	
<b>Lot #</b>	53	
<b>Qty</b>	1	
<b>Title</b>	2008 KENWORTH T800 SLEEPER TRUCK	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Scratch On Front Right Fender. Showing: 185,606 Miles; 389.2 Hours. Location: Mc Crory, AR Serial: 1XKDDU9X18J218116	



<b>Lot #</b>	54	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Low Air And ABS Warning Lights On Dash, Missing Items, Including: Headlights, Bulldog Ornament, Grille Components, Rear Inner Tires, Switches From Center Dash. Showing 741,003 Miles; 36,574 Hours. Location: Greenville, OH Serial: 1M2AG11C06M043135	
<b>Lot #</b>	55	
<b>Qty</b>	1	
<b>Title</b>	2009 VOLVO VNL64T FLATBED TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Modified Tilt Flatbed, 4 Active/1 Inactive Faults Detected- See ECM Report, Oil Leak From Oil Pan, Low Beams And L/S Front Hazard Light INOP, Lock Cylinder Missing From Doors, Doghouse And Bumper Scratched, Paint Chipped And Scratched Throughout, Rust Throughout, Tires Worn. Showing 473,220 Miles; 473,220 ECM; 27,117 Hours. Location: Newberry, IN Serial: 4V5NC9EGX9N271266	
<b>Lot #</b>	56	
<b>Qty</b>	1	
<b>Title</b>	2014 MACK CXU613 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. ABS, Electrical Malfunction And ATC Warning Lights On Dash, D/S Mirror Broken And Repaired With Tape, Exhaust Stack Cover Is Dented, Body Damage Noted Throughout. Showing 762,216 Miles; 15,888 Hours. Location: Lexington, NE Serial: 1M1AW09Y2EM037630	
<b>Lot #</b>	57	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Frame Is Rusting. Showing: 647,541 Miles; 39,358 Hours. Location: Greenville, OH Serial: 1M2AG11C17M067624	
<b>Lot #</b>	59	
<b>Qty</b>	1	
<b>Title</b>	2001 EAST TRAILER DUMP TRAILER	
<b>Des.</b>	APPROXIMATE MEASUREMENTS 48 FT LENGTH, 98 IN WIDTH, 13 FT HEIGHT, FULL OPERATIONS NOT TESTED. Wear Throughout Trailer. Location: Elgin, IL Serial: 1E1U1X2801RH30164	
<b>Lot #</b>	62	
<b>Qty</b>	1	
<b>Title</b>	2006 ISUZU NPR FLATBED TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Right Door Does Not Open From The Out Side, Rust Throughout Unit. Showing: 318,005 Miles. Location: Buckeye, AZ Serial: JALB4B16267010040	
<b>Lot #</b>	63	
<b>Qty</b>	1	
<b>Title</b>	2012 PETERBILT 367 DAY CAB TRUCK	
<b>Des.</b>	STARTED ONSITE W/JUMP, FULL OPERATIONS NOT TESTED. Showing 683,853 Miles; 22,520 Hours. Location: New Braunfels, TX Serial: 1XPTP4EX9CD162680	

<b>Lot #</b>	64	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CT713 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Paint Chips Throughout, Frame Has Rust. Showing: 463,257 Miles; 25,236 Hours. Location: Elkhorn, WI Serial: 1M2AL02C67M006614	
<b>Lot #</b>	65	
<b>Qty</b>	1	
<b>Title</b>	2002 AMREP AMRTT26 ROLLOFF TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Leaks Oil By Front Of Hitch, Missing A Rear Tire, Rust Throughout Frame. Location: Buckeye, AZ Serial: 1A9TT262821077189	
<b>Lot #</b>	66	
<b>Qty</b>	1	
<b>Title</b>	2013 MAC DUMP TRAILER	
<b>Des.</b>	APPROXIMATE MEASUREMENTS 39 FT LENGTH, 96 IN WIDTH, FULL OPERATIONS NOT TESTED. Missing Hook Ups And King Pin, Could Not Open Rear Door. Location: Weatherford, TX Serial: 5MADN3927DC025810	
<b>Lot #</b>	67	
<b>Qty</b>	1	
<b>Title</b>	2013 PETERBILT 365 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Frame Has Rust, Paint Chips Throughout. Showing: 426,758 Miles; 1,924 Hours. Location: Elkhorn, WI Serial: 1NPSLP0X9DD191141	
<b>Lot #</b>	68	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CT713 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Frame Has Rust, Grille Has Rust, Paint Chips Throughout. Showing: 759,769 Miles. Location: Elkhorn, WI Serial: 1M2AL02C97M006607	
<b>Lot #</b>	71	
<b>Qty</b>	1	
<b>Title</b>	2003 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Grinding Noise Noted While In High Range, Unable To Use High Range, ABS And Electrical Malfunction Warning Lights On Dash, D/S Door Does Not Open, Engine Valve Cover Tag Is Missing, Bulldog Ornament And Several Tail Lights Are Missing. Showing 846,463 Miles; 43,270 Hours. Location: Wittenberg, WI Serial: 1M2AG11C83M003414	
<b>Lot #</b>	72	
<b>Qty</b>	1	
<b>Title</b>	2012 MACK GU813 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. DOES NOT DRIVE FASTER THAN 15 MPH, Engine And ABS Warning Lights On Dash, Rear Differential Is Missing Yoke For Drive Shaft, Bulldog Ornament Is Missing From Hood, Center Dash Top Panel Is Missing, Body Damage And Rust Throughout. Showing 491,471 Miles; 24,335 Hours. Location: Wittenberg, WI Serial: 1M2AX13C0CM017854	



<b>Lot #</b>	74	
<b>Qty</b>	1	
<b>Title</b>	2004 FORD F150 EXT CAB PICKUP TRUCK	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Damage To Hood, Trim Missing From Tail Gate, D/S Seat Torn, Body Damage Throughout. Mileage Unavailable. Location: Meridian, MS Serial: 2FTRX17W24CA60539	
<b>Lot #</b>	75	
<b>Qty</b>	1	
<b>Title</b>	2002 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Cab Roof Has Extreme Rust, Muffler Is Bent, Valve Cover Information Missing. Showing: 594,481 Miles; 34,880.9 Hours. Location: Wittenberg, WI Serial: 1M2P267C42M064917	
<b>Lot #</b>	76	
<b>Qty</b>	1	
<b>Title</b>	2004 INTERNATIONAL 7400 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Needs Ether To Start, Power Steering Does Not Work, Showing: 128,403 Miles; 3,295.1 Hours. Location: Wittenberg, WI Serial: 1HTWGADT14J087281	
<b>Lot #</b>	77	
<b>Qty</b>	1	
<b>Title</b>	2009 GALBREATH A5-OR-250 ROLLOFF TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Rust Throughout, Rear Mud Flap Frayed, Approximate Measurements: 29 FT Shipping/Body Length, 114 IN Shipping Width, 11.2 FT Shipping Height. Location: Elgin, IL Serial: 1G9F127259A157885	
<b>Lot #</b>	78	
<b>Qty</b>	1	
<b>Title</b>	2005 FREIGHTLINER M2112 CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Bumper Starting to Rust, Paint Chips Throughout Unit. Showing: Mileage/Hours Unavailable. Location: Sacramento, CA Serial: 1FVHC5CV65HN14219	
<b>Lot #</b>	80	
<b>Qty</b>	1	
<b>Title</b>	2000 KOMATSU FG25ST-14 FORKLIFT	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Tires Worn, Engine Cover Is Dented/Bent, Rust Noted, Safety Bar Bent, Brake Pedal Worn, Scratches, Scrapes, And Peeled Paint Throughout. Showing 6,905 Hours. Location: Newark, NJ Serial: 172207	
<b>Lot #</b>	82	
<b>Qty</b>	1	
<b>Title</b>	1993 INDESPENSION FLATBED TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. VIN Tag And Axle Weight Tag Not Located, Has A Bad Axle That Is Off Of The Ground, Front Of Trailer Is Broken, Tires Singled Out, Approximate Measurements: 20 FT Length, 96 IN Shipping Width, 4 FT Shipping Height. Location: Elkhorn, WI Serial: SCH273082P0000139	

<b>Lot #</b>	83	
<b>Qty</b>	1	
<b>Title</b>	2004 FORD F350 SERVICE TRUCK	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. ABS Warning Light On Dash, Reading Service Body, R/S Tool Box Is Missing A Door, Debris Left In Bed, Rust Throughout. Showing 209,223 Miles. Location: Harrisburg, PA Serial: 1FDSF35P64EA26217	