


























Printable Catalog







| | |
|--------------------|---|
| Title | DECEMBER 11 12:00 CST |
| Description | Closing Times TBD |
| Date | Wed, Dec 11, 2019 |
| Starts at | 12:00 PM |
| Address | 4747 NE 14th St, Des Moines, IA 50313 USA |
| Categories | |







| | | |
|--------------|--|---|
| Lot # | 1 |  |
| Qty | 1 | |
| Title | 2015 MACK CXU613 DAY CAB TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Mack MP8-445, Mack Maxitoque T310 W/P 10 Speed, Air Suspension, 12 FA, 20 RA, 187 WB, Engine Brake, 125 Gallon Aluminum Fuel Tank, Aluminum Wheels, 295/75R22.5, PTO, Rear Tires Worn, Body Damage/Rust. Showing 514,798 Miles. Location: Kansas City, MO Serial: 1M1AW07YXFM046953 | |
| Lot # | 2 |  |
| Qty | 1 | |
| Title | 2019 MACK GRANITE 648R TANK TRUCK | |
| Des. | NON RUNNER. HEAVY BODY DAMAGE FROM COLLISION AFFECTING ALL SIDES OF UNIT. HOOD COULD NOT BE OPENED FOR INSPECTION. Mileage Unavailable. Location: Union City, TN Serial: 1M2GR3GC6KM002526 | |
| Lot # | 3 |  |
| Qty | 1 | |
| Title | 1997 CATERPILLAR 938F WHEEL LOADER | |
| Des. | NO TITLE PER STATE REGULATIONS. UNIT STARTED ON SITE. ACCELERATOR PEDAL FROZEN, PARKING BRAKE INOPERABLE. LESS KEY. LESS BUCKET. CAT 149 HP, Power Shift 4F/3R, EROPS, Cab Heat/AC, 20.5R25 Tires, Hours Gauge Inop., Rear Grill Missing, Body Damage/Rust. Location: Pelham, AL Serial: 1KM02360 | |
| Lot # | 4 |  |
| Qty | 1 | |
| Title | 2001 MACK DM690S REAR MIXER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. EM7-300 E-TECH LSR, T2080B, Camelback Suspension, 222 WB, 10.5 Yrd CBMW Rear Mixer, Side Mount Water Tank, Steel Fuel Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Right Rear Outer Tire Flat Off Rim, Body Damage/Rust. Showing 194,786 Miles; 16,152 Hours. Location: Wichita Falls, TX Serial: 1M2B209C21M028453 | |
| Lot # | 5 |  |
| Qty | 1 | |
| Title | 2007 MACK MR 690S GARBAGE PACKER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. BODY ARM INOPERABLE. Active Fault Code - See Report, Oil Leak Noted, Interior Worn, Various Body Damage/Rust. Showing 385,822 Miles; 29,668 Hours. Location: St. Paul, MN Serial: 1M2K189C37M038757 | |








| | | |
|--------------|---|---|
| Lot # | 6 |  |
| Qty | 1 | |
| Title | 2001 MACK DM690S REAR MIXER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. EM7-300 E-TECH LSR, T2080B, Camelback Suspension, 20 FA, 44 RA, 222 WB, 10.5 Yrd Continental Rear Mixer, Side Mount Water Tank, Steel Fuel Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, Body Damage/Rust. Showing 282,261 Miles; 21,462 Hours. Location: Wichita Falls, TX Serial: 1M2B209C41M028423 | |
| Lot # | 7 |  |
| Qty | 1 | |
| Title | 2009 TRAVIS S96 OPEN TOP TRAILER | |
| Des. | 40ft Length, 102in Width, 154in Height. Location: Pochontas, AR Serial: 48X1P402991006802 | |
| Lot # | 8 |  |
| Qty | 1 | |
| Title | 2007 MACK CT713 CAB & CHASSIS | |
| Des. | NON RUNNER. MAJOR COMPONENTS MISSING, INCLUDING: RADIATOR ASSEMBLY, TURBO, INTAKE, IGNITION AND INSTRUMENT CLUSTER. ENGINE OIL PAN LOOSE. AMI-335 ASET, T310MLR, Camelback Suspension, AC, Body Damage/Rust. Mileage Unavailable. Location: Pelham, AL Serial: 1M2AL02C17M006410 | |
| Lot # | 9 |  |
| Qty | 1 | |
| Title | 1999 ISUZU NPR VAN BODY TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. KNOWN TRANSMISSION ISSUE - THIRD GEAR IS OUT. Isuzu 4HE1-TC Diesel, Automatic, Spring Suspension, 5.36 FA, 9.88 RA, 150 WB, 15.5ft Morgan Body, Lift Gate, Steel Wheels, LT215/85R16, AC, Lift Gate Inoperable, Missing AC Belt, Rock Chips In Windshield, Body Damage/Rust. Showing 235,570 Miles. Location: Des Moines, IA Serial: JALC4B149X7005387 | |
| Lot # | 10 |  |
| Qty | 1 | |
| Title | 2007 PETERBILT 357 REAR MIXER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Cummins ISL, Allison Automatic, 20 FA, 38 RA, 252 WB, 10.5 Yrd Schwing Rear Mixer, 85 Gallon Side Mount Water Tank, 57 Gallon Aluminum Fuel Tank, 12,500 Lbs Bridge Axle With No Wheels/Tires, Aluminum Wheels, 425/65R22.5, PTO, AC, ABS Warning Light Illuminated, Warning Lights Illuminated - See Photo, Body Damage/Rust, Showing 147,389 Miles; 18,241 Hours. Location: Des Moines, IA Serial: 1NPAL50X37D675830 | |
| Lot # | 12 |  |
| Qty | 1 | |
| Title | 2005 VOLVO L180E WHEEL LOADER | |
| Des. | NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. Volvo D12C Diesel, Volvo HTE220 4F/4R, Enclosed ROPS, 124in Bucket, Steel Wheels, 26.5R25, Body Damage/Rust. Showing 6,279 Hours. Location: Weatherford, TX Serial: L180EV6948 | |
| Lot # | 14 |  |
| Qty | 1 | |
| Title | 2001 MACK DM690S REAR MIXER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. EM7-300 E-TECH, T2080B, Camelback Suspension, 222 WB, 10.5 Yrd Continental Rear Mixer, Side Mount Water Tank, Steel Fuel Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 8,855 Miles; 18,931 Hours. Location: Wichita Falls, TX Serial: 1M2B209C31M027909 | |







| | | |
|--------------|--|---|
| Lot # | 18 |  |
| Qty | 1 | |
| Title | 2000 MACK DM690S REAR MIXER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. EM7-300 EUP, T2080B, Camelback Suspension, 212 WB, Side Mount Water Tank, Steel Fuel Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, Front Right Inner Tire Flat Off Rim, Body Damage/Rust. Showing 153,591 Miles; 2,578 Hours. Location: Wichita Falls, TX Serial: 1M2B209C5YM026478 | |
| Lot # | 19 |  |
| Qty | 1 | |
| Title | AL-JOHN 81K COMPACTOR | |
| Des. | NO TITLE PER STATE REGULATIONS. STARTED ON SITE FULL OPERATIONS NOT TESTED. HYDRAULIC AND OIL LEAKS NOTED. CAT, Hydrostatic, 144in Blade, Body Damage/Rust. Location: Byhalia, MS Serial: 13724 | |
| Lot # | 20 |  |
| Qty | 1 | |
| Title | 2005 VOLVO L150E WHEEL LOADER | |
| Des. | NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. KNOWN PROBLEMS WITH CENTER PINS AND CYLINDER SEALS. Volvo 9.4L Diesel, Volvo HTE210 4F/4R, Open ROPS, 124in Bucket, AC/Heated Cab, Steel Wheels, 26.5R25, Body Damage/Rust. Showing 32,757 Hours. Location: Houston, TX Serial: L150EV8832 | |
| Lot # | 21 |  |
| Qty | 1 | |
| Title | 2003 MACK CV713 ROLLOFF TRUCK | |
| Des. | NON RUNNER. DRIVE LINE REMOVED. Mack AI-350, Eaton 10 Speed, Spring Suspension, 20 FA, 40 RA, 264 WB, 28.5ft Body, Aluminum Fuel Tank, Engine Brake, Double Frame, Steel Wheels, 11R22.5, PTO, AC, Rear Tires Singled Out, Body Damage/Rust. Mileage Unavailable. Location: Morgantown, WV Serial: 1M2AG11C23M007278 | |
| Lot # | 22 |  |
| Qty | 1 | |
| Title | 2007 PETERBILT 357 REAR MIXER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Cummins ISL, Allison Automatic, 20 FA, 38 RA, 254 WB, 10.5 Yrd Schwing Rear Mixer, 65 Gallon Side Mount Water Tank, 57 Gallon Aluminum Fuel Tank, Pusher Axle, 12,500 Lbs Bridge Axle, Aluminum Wheels, 425/65R22.5, PTO, AC, Bridge Axle Has No Wheels/Tires, Oil Seepage Noted At Engine, Body Damage/Rust. Showing 145,667 Miles; 16,422 Hours. Location: Des Moines, IA Serial: 1NPAL50X17D699561 | |
| Lot # | 25 |  |
| Qty | 1 | |
| Title | 2006 FORD F550 4X4 MECHANICS TRUCK | |
| Des. | UNIT STARTED- NEEDS ALTERNATOR. Powerstroke Diesel, Auto, 6.5 FA, 13.66 RA, 165wb, Auto Crane 5005H, Miller Welder, Compressor, Knapheide Body, Rear Outriggers, PTO, Steel Wheels, 225/70R19.5, AC. Showing 52,476 Miles. Location: San Bernardino, CA Serial: 1FDAF57P96EA71448 | |
| Lot # | 26 |  |
| Qty | 1 | |
| Title | 2004 MACK DM REAR MIXER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. AMI-335 ASET, TM309M, Camelback Suspension, 212 WB, Side Mount Water Tank, Steel Fuel Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 199,266 Miles; 22,617 Hours. Location: Wichita Falls, TX Serial: 1M2B209C04M030061 | |







| | | |
|--------------|---|---|
| Lot # | 28 |  |
| Qty | 1 | |
| Title | 2007 HYUNDAI HL780-7A WHEEL LOADER | |
| Des. | NO TITLE PER STATE REGULATIONS. NON RUNNER - ENGINE OVERHEATED AND NO LONGER RUNS. FORKS NOT INCLUDED WITH UNIT. Cummins OSM11 Diesel, Powershift 4F/3R, Enclosed ROPS, 136in Bucket, Steel Wheels, 29.5R25, Body Damage/Rust. Showing 16,417 Hours. Location: Weatherford, TX Serial: LH0410071 | |
| Lot # | 29 |  |
| Qty | 1 | |
| Title | 2003 MACK CV713 ROLLOFF TRUCK | |
| Des. | NON RUNNER - MISSING TRANSMISSION. Mack AI-400 ASET, 20 FA, 272 WB, 35ft Body, Steel Wheels, 315/80R22.5; 11R22.5, Missing Passenger Seat, Tires Singled Out, Missing Driver's Side Rear Tire - See Photos, Body Damage/Rust. Mileage Unavailable. Location: Wittenberg, WI Serial: 1M2AG11C83M007107 | |
| Lot # | 30 |  |
| Qty | 1 | |
| Title | 2000 MACK DM REAR MIXER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. NO POWER STEERING. EM7-275 EUP, T2080B, Camelback Suspension, 213 WB, 10.5 Yrd McNeilus Rear Mixer, 125 Gallon Side Mount Water Tank, Steel Fuel Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Right Rear Outer Tire Flat Off Rim, Body Damage/Rust. Showing 184,175 Miles; 20,406 Hours. Location: Wichita Falls, TX Serial: 1M2B221C9YM026412 | |
| Lot # | 31 |  |
| Qty | 1 | |
| Title | 2004 WESTERN STAR CONSTELLATION VOLUMETRIC MIXERS | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Oil Leak Noted At Pan/Rear Seal, Chipped Windshield, Radiator Brace Under Engine Hood Broken, Right Rear Light Missing, PTO Leaking, PTO Control Box Is Missing Controls, Power Steering Leaking, Transmission Residue Noted At Rear, Needs New Battery, Various Body Damage/Rust. Showing 217,323 Miles; 19,342 Hours. Location: Antelope, CA Serial: 5KKHAECG64PM54030 | |
| Lot # | 32 |  |
| Qty | 1 | |
| Title | 2005 MACK CV713 CAB & CHASSIS | |
| Des. | NON RUNNER. DRIVE LINE REMOVED. Mack AMI-335, Eaton 10 Speed, Spring Suspension, 18 FA, 44 RA, 264 WB, 28.5ft Body, Double Frame, Aluminum Fuel Tank, Engine Brake, Steel Wheels, 11R22.5, PTO, AC, Dash Apart, Rear Tires Singled Out, Body Damage/Rust. Mileage Unavailable. Location: Morgantown, WV Serial: 1M2AG11C65M027911 | |
| Lot # | 33 |  |
| Qty | 1 | |
| Title | 2007 CASE 570MXT SKIP LOADERS | |
| Des. | NO TITLE PER STATE REGULATIONS. NON RUNNER. Case 4-39 75 HP, ROPS, Body Damage/Rust. Showing 9,524 Hours. Location: Spokane, WA Serial: JJG0380582 | |








| | | |
|--------------|--|---|
| Lot # | 34 |  |
| Qty | 1 | |
| Title | 2007 PETERBILT 357 REAR MIXER | |
| Des. | STARTED ON SITE W/ STARTING FLUID - NOT ROAD TESTED. WOULD NOT STAY RUNNING. Cummins ISL, Automatic, 20 FA, 38 RA, 256 WB, 10.5 Yrd Schwing Rear Mixer, 65 Gallon Side Mount Water Tank, 57 Gallon Aluminum Fuel Tank, 12,500 Lbs Bridge Axle, Aluminum Wheels, 425/65R22.5, PTO, AC, Bridge Axle Has No Wheels/Tires, Body Damage/Rust. Showing 131,903 Miles; 21,913 Hours. Location: Des Moines, IA Serial: 1NPAL50X97D675833 | |
| Lot # | 35 |  |
| Qty | 1 | |
| Title | 2015 CHEVROLET 3500 4X4 CREW CAB FLATBED TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. 6.6L Duramax, Allison Automatic, Spring Suspension, 5.6 FA, 9.75 RA, 172 WB, 8ft Body, Steel Wheels, 235/80R17, AC, Body Damage/Rust. Showing 237,491 Miles. Location: Newton, MS Serial: 1GB4KYC82FF119903 | |
| Lot # | 37 |  |
| Qty | 1 | |
| Title | 2005 MACK CV713 ROLLOFF TRUCK | |
| Des. | NON RUNNER. ENGINE LOCKED UP - DOES NOT TURN OVER. HOLE IN ENGINE BLOCK. DRIVE LINE REMOVED WITH TRUCK. MISSING COOLANT TANK. Mack AI-350 ASET, Eaton Fuller RTO14908LL, Hendrickson Suspension, 249 WB, Steel Wheels, 11R22.5, PTO, AC, Body Damage/Rust. Showing 681,429 Miles; 30,864 Hours. Location: Pelham, AL Serial: 1M2AG11C55M033795 | |
| Lot # | 38 |  |
| Qty | 1 | |
| Title | 1999 MACK DM REAR MIXER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. EM7-275 EUP, T2080B, Camelback Suspension, 204 WB, 10.5 Yrd McNeilus Rear Mixer, 125 Gallon Side Mount Water Tank, Steel Fuel Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 219,744 Miles; 24,048 Hours. Location: Wichita Falls, TX Serial: 1M2B221C7XM025273 | |
| Lot # | 39 |  |
| Qty | 1 | |
| Title | 2013 CHEVROLET 3500 4X4 CREW CAB FLATBED TRUCK | |
| Des. | STARTED ON SITE W/ A JUMP - NOT ROAD TESTED. 6.6L Duramax, Allison Automatic, Independent Suspension, 5.6 FA, 9.75 RA, 172 WB, 8ft Body, Dual Rear Tires, Steel Wheels, 235/80R17, AC, Check Engine Light Illuminated, Body Damage/Rust. Location: Newton, MS Serial: 1GB4KZC82DF144514 | |
| Lot # | 40 |  |
| Qty | 1 | |
| Title | 2004 MACK CV713 CAB & CHASSIS | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Mack AMI-370 ASET Diesel, Maxitorque T310 10 Speed, Camelback Suspension, 18 FA, 56 RA, 260 WB, 252in Back Cab To End Frame, Double Frame, Tag Axle With 275/70R22.5, 81 Gallon Steel Fuel Tank, Steel Wheels, 11R22.5, AC, ABS And Electrical Warning Lights Illuminated, Missing Oil Cap, Missing Front Bumper, Body Damage/Rust. Showing 570,533 Miles; 33,678 Hours. Location: Des Moines, IA Serial: 1M2AG11C54M014601 | |







| | | |
|--------------|---|---|
| Lot # | 41 |  |
| Qty | 1 | |
| Title | 1989 WHITE/GMC AUTOCAR BLOCK TRUCK | |
| Des. | STARTED ON SITE NOT ROAD TESTED. FULL OPERATIONS NOT TESTED. VARIOUS HYDRAULIC LEAKS NOTED. Cummins LTA10- 285 HP (Oil Leak Noted), Eaton Manual RTXF-11708LL, T-Ride Suspension, 20 FA, Smith True Crane, Air Lift Pusher Axle (Less Wheels/Tires), Steel Wheels, 445/65R22.5, 70 Gallon Aluminum Fuel Tank, PS, AC, AM/FM, Body Damage/Rust. Showing 380,032 Miles; 99,770 Hours. Location: Miami, FL Serial: 4V2RCBME8KU503736 | |
| Lot # | 42 |  |
| Qty | 1 | |
| Title | 2000 KENWORTH T800 REAR MIXER | |
| Des. | 10.5 YRD. McNeilus Mixer, Rear Drum/Shoot Controls Missing, Dash Gauges Missing, Speedometer Inop, AC inop, Body Damage/Rust. Showing 312,739 Miles; 418 Hours. Location: Brownwood, TX Serial: 1NKDLT0X5YS850938 | |
| Lot # | 45 |  |
| Qty | 1 | |
| Title | 1998 MACK RD688S ROLLOFF TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. CANNOT BE DRIVEN - HARD STEERING AND BRAKE PEDAL FROZEN. Mack E7-350, T2090, Camelback Suspension, 18 FA, 280 WB, Steel Wheels, 315/80R22.5, PTO, AC, Dead Batteries, New Turbo, Body Damage/Rust. Showing 403,659 Miles; 43,783 Hours. Location: Pelham, AL Serial: 1M2P267C9WM039274 | |
| Lot # | 46 |  |
| Qty | 1 | |
| Title | 2005 STERLING L9500 REAR MIXER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. DRIVE SHAFT REMOVED. MISSING ENGINE FAN BELT. CAT C11, Eaton 8LL, Chalmers Suspension, 20 FA, 46 RA, 225 WB, 10.5 Yrd McNeilus Rear Mixer, Aluminum Fuel Tank, 125 Gallon Side Mount Water Tank, Steel Wheels, 445/65R22.5; 11R22.5, PTO, AC, Check Engine Light Illuminated, No Chutes, A/C Compressor Locked Up Tight, Dead Batteries, Body Damage/Rust. Showing 228,981 Miles; 19,245 Hours. Location: Odessa, FL Serial: 2FZHAZDL55AU91771 | |
| Lot # | 47 |  |
| Qty | 1 | |
| Title | 2013 CHEVROLET 3500 4X4 CREW CAB FLATBED TRUCK | |
| Des. | STARTED ON SITE W/ A JUMP - NOT ROAD TESTED. 6.6L Duramax 8 Cyl, Allison Automatic, Spring Suspension, 5.6 FA, 9.75 RA, 172 WB, 8ft Body, Dual Rear Tires, Steel Wheels, 235/80R17, AC, Check Engine Light Illuminated, Body Damage/Rust. Showing 242,924 Miles. Location: Newton, MS Serial: 1GB4KZC85DF240492 | |
| Lot # | 50 |  |
| Qty | 1 | |
| Title | 2006 MACK CT713 REAR MIXER | |
| Des. | NON RUNNER - CRANKS NO START. BAD ENGINE. KNOWN SUSPENSION AND FRAME ISSUES. AMI-335 ASET, TM309M, Bogey Suspension, 223 WB, 10.5 YRD CBMW Rear Mixer, Side Mount Water Tank, Steel Fuel Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 223,942 Miles; 23,276 Hours. Location: Victoria, TX Serial: 1M2AL02C16M003439 | |







| | | |
|--------------|--|---|
| Lot # | 51 |  |
| Qty | 1 | |
| Title | 2014 CHEVROLET 2500 4X4 PICKUP TRUCK | |
| Des. | STARTED ON SITE W/ A Jump - NOT ROAD TESTED. 6.6L Duramax 8 Cyl, Allison Automatic, Spring Suspension, 5.2 FA, 6.2 RA, 154 WB, Steel Wheels, 265/70R17, AC, Body Damage/Rust. Showing 235,284 Miles. Location: Newton, MS Serial: 1GC1KVC83EF112485 | |
| Lot # | 52 |  |
| Qty | 1 | |
| Title | 1993 CATERPILLAR 928F WHEEL LOADER | |
| Des. | NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. CAT 3116 Diesel, Power Shift 4F/3R, Enclosed ROPS, 104in Bucket, Steel Wheels, 17.5R25, AC/Heated Cab, Body Damage/Rust. Showing 8,800 Hours. Location: West Columbia, TX Serial: 2XL00149 | |
| Lot # | 53 |  |
| Qty | 1 | |
| Title | 2000 MACK RD688S ROLLOFF TRUCK | |
| Des. | NON RUNNER. MISSING ENGINE ECM. Mack E7-350 EUP, Eaton RTOF14908LL, Camelback Suspension, 18 FA, 280 WB, PTO, AC, Winch Cable End Cut Off, Dash Apart, Wires Loose In Cab, Body Damage/Rust. Showing 389,856 Miles; 43,718 Hours. Location: Pelham, AL Serial: 1M2P267CXYM050044 | |
| Lot # | 54 |  |
| Qty | 1 | |
| Title | 2008 KENWORTH T800B REAR MIXER | |
| Des. | NON RUNNER. MISSING TRANSMISSION AND DASH. DRIVE SHAFT REMOVED. Paccar, Spring Suspension, 23 FA, 46 RA, 224 WB, 10.5 Yrd CBMW Rear Mixer, 56 Gallon Aluminum Fuel Tank, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, Water Tank Missing, Fuel Filter System Disassembled, Body Damage/Rust. Mileage Unavailable. Location: Victoria, TX Serial: 1NKDL50X98J237612 | |
| Lot # | 55 |  |
| Qty | 1 | |
| Title | 2000 PETERBILT 385 DAY CAB TRUCK | |
| Des. | STARTED ON SITE NOT ROAD TESTED. CAT C12, Eaton 13 Speed, Air Suspension, 12 FA, 40 RA, Aluminum Wheels, 11R22.5, PTO, AC, Body Damage/Rust. Showing 134,090 Miles; 1,413 Hours. Location: Sacramento, CA Serial: 1XPGDU9X1YS535377 | |
| Lot # | 56 |  |
| Qty | 1 | |
| Title | 2007 MACK CV713 CAB & CHASSIS | |
| Des. | NON RUNNER. Mack AI-350 ASET, Allison 4500RDS Automatic, Camelback Suspension, 245 WB, 216in Back Cab To End Frame, Double Frame, Steel Wheels, 275/80R22.5; 315/80R22.5, PTO, AC, Dash Apart, Less Keys, Body Damage/Rust. Mileage Unavailable. Location: Weatherford, TX Serial: 1M2AG11C47M067911 | |
| Lot # | 57 |  |
| Qty | 1 | |
| Title | 1984 HEIL PNEUMATIC TRAILER | |
| Des. | 40ft Total Length, 96in Width, Aluminum Body Composition, 1040 Cubic Ft. Capacity, 3 Compartments, 3 Top Hatches, 2 Hook Ups, Steel Wheels, 285/75R24.5, Body Damage/Rust. Location: San Antonio, TX Serial: 1HLS1M7B1E7T00359 | |







| | | |
|--------------|--|---|
| Lot # | 58 |  |
| Qty | 1 | |
| Title | 2007 PETERBILT 357 REAR MIXER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Cummins ISL, Allison Automatic, 20 FA, 38 RA, 252 WB, 10.5 Yrd Schwing Bridge Mixer, 65 Gallon Side Mount Water Tank, 57 Gallon Aluminum Fuel Tank, 12,500 Lbs Bridge Axle With 11R22.5, Aluminum Wheels, 425/65R22.5, PTO, AC, ABS Warning Light Illuminated, Oil Seepage Noted At Engine, Crack In Windshield, Missing Driver's Side Window Controls, Body Damage/Rust. Showing 193,263 Miles; 24,293 Hours. Location: Des Moines, IA Serial: INPAL50X17D699544 | |
| Lot # | 59 |  |
| Qty | 1 | |
| Title | 2014 GMC 2500 4X4 CREW CAB PICKUP TRUCK | |
| Des. | STARTED ON SITE W/ A JUMP - NOT ROAD TESTED. 6.6L Duramax, Allison Automatic, Spring Suspension, 5.2 FA, 6.2 RA, 154 WB, Steel Wheels, 275/65R18, AC, Check Engine Light Illuminated, Service Exhaust Light Illuminated, Missing Interior Driver's Side Door Handle, Crack In Windshield, Body Damage/Rust. Mileage Unavailable. Location: Newton, MS Serial: 1GT12ZC87EF168730 | |
| Lot # | 60 |  |
| Qty | 1 | |
| Title | 2004 VOLVO L50D WHEEL LOADER | |
| Des. | NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. TURBO LEAKING OIL THROUGH EXHAUST. Volvo TD40GJE Diesel, Hydrostatic Transmission Volvo Powershift 2F/2R, Enclosed ROPS, 90in Bucket, Steel Wheels, 17.5-25, Dead Batteries, Body Damage/Rust. Showing 20,104 Hours. Location: Weatherford, TX Serial: L50DP70132 | |
| Lot # | 61 |  |
| Qty | 1 | |
| Title | 1999 VOLVO WG64 ROLLOFF TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Volvo VE D12 Diesel, Eaton Fuller, Spring Suspension, 276 WB, 27ft Body, Aluminum Fuel Tank, Steel Wheels, 315/80R22.5, PTO, AC, Body Damage/Rust. Mileage Unavailable. Location: Denver, CO Serial: 4VHJCCGF9XN862740 | |
| Lot # | 62 |  |
| Qty | 1 | |
| Title | 2007 KENWORTH T800B REAR MIXER | |
| Des. | NON RUNNER. MISSING IGNITION AND VARIOUS ENGINE PARTS. DRIVE SHAFT REMOVED. Cummins ISL, Spring Suspension, 23 FA, 46 RA, 227 WB, CBMW Rear Mixer, Side Mount Water Tank, 56 Gallon Aluminum Fuel Tank, Steel Wheels, 425/65R22.5; 11R22.5, Some Parts In Cab, Body Damage/Rust. Mileage Unavailable. Location: Victoria, TX Serial: 1NKDL50X67J207661 | |
| Lot # | 63 |  |
| Qty | 1 | |
| Title | 2014 CHEVROLET 2500 4X4 CREW CAB PICKUP TRUCK | |
| Des. | STARTED ON SITE NOT ROAD TESTED. 6.6L Duramax, Allison Automatic, Spring Suspension, 5.6 FA, 6.2 RA, 168 WB, Steel Wheels, 285/70R17, AC, Traction Control Light Illuminated, Body Damage/Rust. Showing 227,009 Miles. Location: Newton, MS Serial: 1GC1KVC81EF172653 | |








| | | |
|--------------|---|---|
| Lot # | 64 |  |
| Qty | 1 | |
| Title | 2005 FREIGHTLINER M2106 CAB & CHASSIS | |
| Des. | RUNNING CONDITION PENDING. Mercedes-Benz OM 906 LA 260 HP, Automatic, Spring Suspension, 10 FA, 46 RA, 177 WB, 166in Back Cab To End Frame, 80 Gallon Aluminum Fuel Tank, Steel Wheels, 255/70R22.5; 11R22.5, AC, Oil Seepage Noted At Engine, Missing Driver's Side Door Handle, Driver's Side Headlight, And Driver Side Door Panel, Rock Chip In Windshield, Stack Rusted, Body Damage/Rust. Mileage Unavailable. Location: Des Moines, IA Serial: 1FVACXCS55HN20578 | |
| Lot # | 65 |  |
| Qty | 1 | |
| Title | 1982 HEIL PNEUMATIC TRAILER | |
| Des. | 40ft Total Length, 96in Width, Aluminum Body Composition, 1040 Cubic Ft. Capacity, 3 Compartments, 3 Top Hatches, 2 Hook Ups, Steel Wheels, 285/75R24.5, Right Front Outer Tire Flat Off Rim, Body Damage/Rust. Location: San Antonio, TX Serial: 1HLS1M7B9C7T00056 | |
| Lot # | 66 |  |
| Qty | 1 | |
| Title | 2004 INTERNATIONAL 5500i 6X4 REAR MIXER | |
| Des. | NON RUNNER - CRANKS NO START. Cummins ISM, Eaton 9 Speed LL, Hendrickson Suspension, 20 FA, 46 RA, 236 WB, CBMW Rear Mixer, Side Mount Water Tank, Aluminum Fuel Tank, Steel Wheels, 425/65R22.5; 11R22.5, AC, Body Damage/Rust. Showing 4,534 Miles; 318 Hours. Location: Victoria, TX Serial: 1HTXLAHT14J025261 | |
| Lot # | 67 |  |
| Qty | 1 | |
| Title | 2006 MACK CHN613 DAY CAB TRUCK | |
| Des. | STARTED ON SITE- NOT ROAD TESTED. Mack AC-427, Eaton Fuller FRO15210C 10 Speed, Air Ride Suspension, 12 FA, 40 RA, 170 WB, Manual Fifth Wheel, Dual Aluminum Fuel Tanks, Steel Wheels, 11R22.5, AC, ABS Warning Light Illuminated, Electrical Warning Lights Illuminated, Exhaust Temperature Light Was Illuminated But Went Off When Truck Warmed, Body Damage/Rust. Showing 776,641 Miles; 35,347 Hours. Location: Des Moines, IA Serial: 1M1AJ06Y86N004792 | |
| Lot # | 68 |  |
| Qty | 1 | |
| Title | 1991 CATERPILLAR 936E WHEEL LOADER | |
| Des. | NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. STEERING COLUMN LOOSE. DIFFICULTY SHIFTING. CAT 3304 Diesel, 4F/4R, Enclosed ROPS, 106in Bucket, Steel Wheels, 20.5R25, Heated Cab, Body Damage/Major Rust. Showing 1,518 Hours. Location: Victoria, TX Serial: 4SB02215 | |
| Lot # | 69 |  |
| Qty | 1 | |
| Title | 2005 FREIGHTLINER FL112 ROLLOFF TRUCK | |
| Des. | ENGINE STARTED W/ A JUMP BUT IS MISSING VARIOUS PARTS. NOT ROAD TESTED. Mercedes-Benz MBE 410 HP Diesel, Eaton 10 Speed, Spring Suspension, 20 FA, 35.5ft Body, Double Frame, Wet Kit, 100 Gallon Fuel Tank, Steel Wheels, 11R24.5; 11R22.5, PTO, AC, Missing Doors, Hood, And Various Other Parts, Needs New Tires, Body Damage/Rust. Showing 778,827 Miles. Location: Mc Crory, AR Serial: 1FVHC5CV05HN14233 | |








| | | |
|--------------|--|---|
| Lot # | 70 |  |
| Qty | 1 | |
| Title | 2005 PETERBILT 357 REAR MIXER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Cummins ISL, Allison Automatic, 20 FA, 38 RA, 251 WB, 10.5 Yrd Schwing STM Rear Mixer, 65 Gallon Side Mount Water Tank, 46 Gallon Aluminum Fuel Tank, Bridge Axle With 11R22.5, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, ABS Warning Light Illuminated, Check Engine Warning Illuminated, Body Damage/Rust. Showing 210,853 Miles; 8,847 Hours. Location: Des Moines, IA Serial: 1NPAL50X05D876680 | |
| Lot # | 71 |  |
| Qty | 1 | |
| Title | 2013 CHEVROLET 3500 4X4 CREW CAB SERVICE TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. 6.6L Duramax, Allison Automatic, Spring Suspension, 5.6 FA, 9.75 RA, 172 WB, 8ft Body, Steel Wheels, 235/80R17, AC, Interior Door Handle Inoperable, Body Damage/Rust. Showing 219,978 Miles. Location: Newton, MS Serial: 1GB4KZC85DF148119 | |
| Lot # | 72 |  |
| Qty | 1 | |
| Title | 2011 FRIGHTLINER M2106 CAB & CHASSIS | |
| Des. | NON RUNNER. ENGINE MISSING PARTS. MISSING FUEL TANK. LESS KEYS. Cummins ISC Diesel, Automatic, 18 FA, 46 RA, 227 WB, 210in Back Cab To End Frame, Double Frame, Steel Wheels, 295/75R22.5, AC, Transmission Selector Dismantled, Wheel Liner In Cab Of Truck, Inner Wheels Only, Body Damage/Rust. Mileage Unavailable. Location: Des Moines, IA Serial: 1FVHCYBS0BDAU2873 | |
| Lot # | 73 |  |
| Qty | 1 | |
| Title | 1979 HEIL PNEUMATIC TRAILER | |
| Des. | 40ft Total Length, 96in Width, Aluminum Body Composition, 1040 Cubic Ft. Capacity, 3 Compartments, 3 Top Hatches, 2 Hook Ups, Steel Wheels, 285/75R24.5, Body Damage/Rust. Location: San Antonio, TX Serial: 930731 | |
| Lot # | 74 |  |
| Qty | 1 | |
| Title | 2000 MACK DM690S REAR MIXER | |
| Des. | NON RUNNER. CRACKED FRAME RAIL. FUEL TANK MISSING. Mack EM7-275 EUP, T2080, Camelback Suspension, 207 WB, CBMW Rear Mixer, Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, Less Keys, Dash Apart, Body Damage/Rust. Showing 214,522 Miles; 12,079 Hours. Location: Victoria, TX Serial: 1M2B221C3YM027541 | |
| Lot # | 75 |  |
| Qty | 1 | |
| Title | 2013 FORD F250 4X4 CREW CAB PICKUP TRUCK | |
| Des. | STARTED ON SITE NOT ROAD TESTED. 6.7L Power Stroke, Automatic, Spring/Air Suspension, 5.4 FA, 6.1 RA, 172 WB, Steel Wheels, 265/70R17, AC, Traction Control Light Illuminated, Body Damage/Rust. Showing 222,550 Miles. Location: Newton, MS Serial: 1FT7W2BT0DEA16983 | |
| Lot # | 76 |  |
| Qty | 1 | |
| Title | 1980 MICHIGAN 175C WHEEL LOADER | |
| Des. | NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. KNOWN TRANSMISSION ISSUE. LESS BUCKET. Cummins 310 HP Diesel, Clark Countershaft Type Powershift 4F/4R, Enclosed ROPS, 119in Bucket, Steel Wheels, 29.5-25, Right Rear Tire Flat, Body Damage/Rust. Showing 6,523 Hours. Location: Weatherford, TX Serial: 490A278CAC | |








| | | |
|--------------|--|---|
| Lot # | 79 |  |
| Qty | 1 | |
| Title | 1996 PETERBILT 385 DAY CAB TRUCK | |
| Des. | STARTED ON SITE NOT ROAD TESTED. Cummins M11, Eaton 13 Speed, Air Suspension, 12 FA, 40 RA, Aluminum Wheels, 11R22.5, 100 Gallon Aluminum Fuel Tank, PTO, AC, Body Damage/Rust. Showing 493,289 Hours. Location: Sacramento, CA Serial: 1XPGD99X8TD411097 | |
| Lot # | 80 |  |
| Qty | 1 | |
| Title | 2007 MACK CTP713 CAB & CHASSIS | |
| Des. | NON RUNNER. MISSING DRIVE SHAFT. LESS BATTERIES AND KEYS. Mack MP7, Allison 4500RDS Automatic, Camelback Suspension, 18 FA, 46 RA, 240 WB, 228in Back Cab To End Frame, 50 Gallon Steel Fuel Tank, Steel Wheels, 295/75R22.5; 275/80R22.5, PTO, Missing Instrument Cluster and Door Lock, Hood Broken Off Hinges, Body Damage/Rust. Mileage Unavailable. Location: Weatherford, TX Serial: 1M2AT13C87M003105 | |
| Lot # | 81 |  |
| Qty | 1 | |
| Title | 1979 HEIL PNEUMATIC TRAILER | |
| Des. | 40ft Total Length, 96in Width, Aluminum Body Composition, 1040 Cubic Ft. Capacity, 3 Compartments, 3 Top Hatches, 2 Hook Ups, Steel Wheels, 285/75R24.5, Body Damage/Rust. Location: San Antonio, TX Serial: 930737 | |
| Lot # | 82 |  |
| Qty | 1 | |
| Title | 2005 MACK CV713 REAR MIXER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Mack AMI-335 ASET, T310MLR Manual, Camelback Suspension, 20 FA, 46 RA, 220 WB, 11 Yrd McNeilus Rear Mixer, 125 Gallon Side Mount Water Tank, Steel Fuel Tank, Tag Axle, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Windshield Cracked, Body Damage/Rust. Showing 254,992 Miles; 22,607 Hours. Location: Des Moines, IA Serial: 1M2AG11C05M022462 | |
| Lot # | 83 |  |
| Qty | 1 | |
| Title | 2013 FORD F250 4X4 CREW CAB PICKUP TRUCK | |
| Des. | STARTED ON SITE W/ A JUMP - NOT ROAD TESTED. 6.7L Power Stroke, Automatic, Spring/Air Suspension, 5.94 FA, 6.1 RA, 156 WB, Steel Wheels, 285/70R17, AC, Body Damage/Rust. Showing 291,209 Miles. Location: Newton, MS Serial: 1FT7W2BT9DEA16982 | |
| Lot # | 84 |  |
| Qty | 1 | |
| Title | 1998 CATERPILLAR 928G WHEEL LOADER | |
| Des. | NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. STEERING COLUMN LOOSE. CAT 3116 125 HP, 4F/3R, Enclosed ROPS, 100in Bucket, Steel Wheels, 20.5R25, AC/Heated Cab, Less Keys, Left Front Tire Low, Body Damage/Rust. Showing 14,380 Hours. Location: Pearland, TX Serial: 6XR01219 | |

| | | |
|--------------|--|---|
| Lot # | 85 |  |
| Qty | 1 | |
| Title | 2009 MACK MRU613 GARBAGE PACKER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. DOES NOT MOVE. DRIVE SHAFT REMOVED WITH TRUCK. AIR LEAK AT BRAKE VALVE. Mack MP7, Allison 4500RDS Automatic, Camelback Suspension, 20 FA, 46 RA, 189 RA, 40 Yrd Hercules EZ Pack Front Loader, Tag Axle, Steel Wheels, 315/80R22.5, PTO, AC, Backup Camera, Manifold Fittings Missing, Check Engine Light Illuminated, Parts Missing For Catalytic Converter Muffler, Body Damage/Rust. Mileage Unavailable. Location: Hope Mills, NC Serial: 1M2AV02C79M004948 | |
| Lot # | 86 |  |
| Qty | 1 | |
| Title | 2005 MACK DM690S REAR MIXER | |
| Des. | NON RUNNER. BAD ENGINE. MISSING RADIATOR AND INSTRUMENT PANEL. DRUM THIN. FRAME RAILS SEVERELY RUSTED - NEED REPLACED. Mack AMI-300, Maxitorque ES, Camelback Suspension, 20 FA, 46 RA, 208 WB, 10.5 Yrd CBMW Rear Mixer, Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, Body Damage/Rust. Mileage Unavailable. Location: Corpus Christi, TX Serial: 1M2B209C25M030614 | |
| Lot # | 87 |  |
| Qty | 1 | |
| Title | 2012 FORD F250 4X4 CREW CAB PICKUP TRUCK | |
| Des. | STARTED ON SITE W/ A JUMP - NOT ROAD TESTED. 6.7L Power Stroke, Automatic, Spring Suspension, 5.6 FA, 6.1 RA, 172 WB, Steel Wheels, 275/70R17, AC, Body Damage/Rust. Showing 304,269 Miles. Location: Newton, MS Serial: 1FT7W2BT3CEB86043 | |
| Lot # | 88 |  |
| Qty | 1 | |
| Title | 2002 PETERBILT 330 CAB & CHASSIS | |
| Des. | NON RUNNER. BAD IGNITION SWITCH. DRIVE SHAFT REMOVED. Cummins ISC, Automatic, Spring Suspension, 16 FA, 40 RA, 233 WB, 213in Back Cab To End Frame, Double Frame, Aluminum Fuel Tank, Steel Wheels, 315/80R22.5; 295/75R22.5, PTO, Transmission Controls Missing, Body Damage/Rust. Showing 38,317 Miles; 33,182 Hours. Location: Weatherford, TX Serial: 2NPNLZ9X13M589898 | |
| Lot # | 89 |  |
| Qty | 1 | |
| Title | 1978 HEIL PNEUMATIC TRAILER | |
| Des. | 40ft Total Length, 98in Width, Aluminum Body Composition, 1040 Cubic Ft. Capacity, 3 Compartments, 3 Top Hatches, 2 Hook Ups, Steel Wheels, 11R24.5, Body Damage/Rust. Location: San Antonio, TX Serial: 930118 | |
| Lot # | 90 |  |
| Qty | 1 | |
| Title | 2007 KENWORTH T800B REAR MIXER | |
| Des. | NON RUNNER. MISSING COMPONENTS, INCLUDING: IGNITION, FAN ASSEMBLY, MANIFOLD, TURBO, DRIVE SHAFT, WATER TANK, AND OTHER VARIOUS PARTS. DRUM FULL OF CONCRETE. Cummins ISL 350 HP, Eaton 9 Speed LL, Spring Suspension, 20 FA, 46 RA, 231 WB, CBMW Rear Mixer, Aluminum Fuel Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, Body Damage/Rust. Mileage Unavailable. Location: San Antonio, TX Serial: 1NKDL50X77J207670 | |

| | | |
|-------|---|---|
| Lot # | 91 |  |
| Qty | 1 | |
| Title | 2006 MACK CHN613 DAY CAB TRUCK | |
| Des. | STARTED ON SITE W/ STARTING FLUID - NOT ROAD TESTED. UNIT WOULD NOT STAY RUNNING. Mack AC-427 ASET Diesel, Spicer LLPSO150-10S 9 Speed, Air Ride Suspension, 12 FA, 40 RA, 200 WB, Stationary Fifth Wheel, Aluminum Fuel Tank, Wet Kit, Steel Wheels, 275/80R22.5; 11R22.5, AC, Dead Batteries, Body Damage/Rust. Showing 658,556 Miles; 33,108 Hours. Location: Des Moines, IA Serial: 1M1AJ06Y26N005792 | |
| Lot # | 92 |  |
| Qty | 1 | |
| Title | 2005 VOLVO L180E WHEEL LOADER | |
| Des. | NO TITLE PER STATE REGULATIONS. NON RUNNER. HYDRAULIC PUMP BAD. LESS KEYS. Volvo D12C LC E2 Diesel, Volvo HTE220 4F/4R, Enclosed ROPS, 124in Bucket, AC/Heated Cab, Steel Wheels, 26.5R25, Left Rear Tire Flat, Body Damage/Rust. Showing 3,834 Hours. Location: Dickinson, TX Serial: L180EV7056 | |
| Lot # | 93 |  |
| Qty | 1 | |
| Title | 1989 MACK DM690S ROLLOFF TRUCK | |
| Des. | NON RUNNER. FUEL PUMP NEEDS REPLACED. UNIT HAS BEEN SITTING FOR AN EXTENDED PERIOD OF TIME. Dead Batteries, Undercarriage Covered In Oil - Unable To Identify Source, Evidence Of Oil Leaks Noted At Valve Cover And Oil Pan, Driver's Door Window And Handle Broken, Passenger Door Will Not Open, Tail Roller Seized, Driver's Side Wheel Seal Steer Leaking, Power Steering Leaking, Dash Missing Components, Various Body Damage/Rust. Showing 182,150 Miles; 3,340 Hours. Location: Holden, LA Serial: 1M2B183C0KM005247 | |
| Lot # | 95 |  |
| Qty | 1 | |
| Title | 2005 CHEVROLET 3500 SERVICE TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Oil Leak At Oil Pan, Speed Sensor Shaft Fault, AC Leaking, Coolant Appears Dark In Color, Interior Worn, Various Body Damage/Rust. Showing 32,683 Miles; 2,197 Hours. Location: Holden, LA Serial: 1GBJC34285E106381 | |
| Lot # | 96 |  |
| Qty | 1 | |
| Title | 1998 PETERBILT 357 CAB & CHASSIS | |
| Des. | STARTED AND RAN BRIEFLY WITH STARTING FLUID - NOT ROAD TESTED. LESS BATTERIES. Cummins L10 300 HP, Spring Suspension, 18 FA, 40 RA, 258 WB, 225in Back Cab To End Frame, Double Frame, 89 Gallon Aluminum Fuel Tank, Steel Wheels, 315/80R22.5, PTO, Front Right Tire Flat Off Rim, Body Damage/Rust. Showing 735,872 Miles; 5,987 Hours. Location: Weatherford, TX Serial: 1NPAL50X4WD455238 | |
| Lot # | 97 |  |
| Qty | 1 | |
| Title | 1979 HEIL JET 25-25 PSI PNEUMATIC TRAILER | |
| Des. | 40ft Total Length, 96in Width, Aluminum Body Composition, 1040 Cubic Ft. Capacity, 3 Compartments, 3 Top Hatches, 2 Hook Ups, Steel Wheels, 285/75R24.5, Body Damage/Rust. Location: San Antonio, TX Serial: 930738 | |








| | | |
|--------------|---|---|
| Lot # | 98 |  |
| Qty | 1 | |
| Title | 2005 INTERNATIONAL 5500 REAR MIXER | |
| Des. | NON RUNNER. MISSING COMPONENTS, INCLUDING: DRIVE SHAFT, BATTERY BOX, STEERING BOX, AND PTO. LESS KEYS. FRAME HEAVILY RUSTED. BAD SUSPENSION. Cummins ISM 320, Automatic, Hendrickson Suspension, 237 WB, 10.5 Yrd Beck Rear Mixer, Side Mount Water Tank, Aluminum Fuel Tank, Steel Wheels, 425/65R22.5; 11R22.5, Battery Box Wires Cut, Body Damage/Rust. Mileage Unavailable. Location: San Antonio, TX Serial: 1HTXLAHTX5J132097 | |
| Lot # | 99 |  |
| Qty | 1 | |
| Title | 2013 CHEVROLET 3500 4X4 FLATBED TRUCK | |
| Des. | NON RUNNER. 6.6L Duramax, Allison Automatic, Spring Suspension, 5.6 FA, 9.75 RA, 8ft Body, Steel Wheels, 265/70R17, AC, Body Damage/Rust. Showing 249,625 Miles. Location: Newton, MS Serial: 1GB4KZC84DF134793 | |
| Lot # | 100 |  |
| Qty | 1 | |
| Title | 2005 VOLVO L150E WHEEL LOADER | |
| Des. | NO TITLE PER STATE REGULATIONS. NON RUNNER. BAD TRANSMISSION PUMP. FUEL FILTER HOUSING REMOVED. LESS KEYS. Volvo 9.4L Diesel, Volvo HTE210 4F/4R, Enclosed ROPS, 124in Bucket, AC/Heated Cab, Steel Wheels, 26.5R25, Left R/ Tire Flat, Body Damage/Rust. Showing 15,589 Hours. Location: San Leon, TX Serial: L150EV8839 | |
| Lot # | 101 |  |
| Qty | 1 | |
| Title | 1980 HEIL JET 25-25 PSI PNEUMATIC TRAILER | |
| Des. | 40ft Total Length, 96in Width, Aluminum Body Composition, 1040 Cubic Ft. Capacity, 3 Top Hatches, 2 Hook Ups, Steel Wheels, 285/75R24.5, Body Damage/Rust. Location: San Antonio, TX Serial: 931040 | |
| Lot # | 102 |  |
| Qty | 1 | |
| Title | 2007 MACK CT REAR MIXER | |
| Des. | NON RUNNER. MISSING CAB, TRANSMISSION, AND WATER TANK. BAD FRAME. Mack AMI-335 ASET Diesel, Camelback Suspension, 212 WB, CBMW Rear Mixer, Steel Wheels, 425/65R22.5; 11R22.5, Body Damage/Rust. Mileage Unavailable. Location: San Antonio, TX Serial: 1M2AL02C17M004592 | |
| Lot # | 104 |  |
| Qty | 1 | |
| Title | 2001 MACK RD688S CAB & CHASSIS | |
| Des. | NON RUNNER - CRANKS NO START. NO BATTERIES. Mack E7-350 E-TECH LSR, Maxitorque T2090 9 Speed, Camelback Suspension, 18 FA, 240in Back Cab To End Frame, Double Frame, Steel Fuel Tank, Steel Wheels, 315/80R22.5, PTO, AC, Hub Cap On Left Front Wheel Broken, Body Damage/Rust. Showing 338,447 Miles; 20,708 Hours. Location: Weatherford, TX Serial: 1M2P267C41M061840 | |
| Lot # | 105 |  |
| Qty | 1 | |
| Title | 2007 SURE PULL GOOSENECK TRAILER | |
| Des. | 20ft Length, 102in Width, Spring Suspension, Steel Wheels, 235/85R16, One Wood Board Broken, No Dove Tail, Body Damage/Rust. Location: Newton, MS Serial: 1J9FG25297J143419 | |




| | | |
|--------------|---|---|
| Lot # | 106 |  |
| Qty | 1 | |
| Title | 2000 MACK RD690S REAR MIXER | |
| Des. | UNIT STARTED ON SITE BUT DOES NOT DRIVE - WILL NOT BUILD OIL PRESSURE. MTM 11 YRD. Bridgmaster Mixer, Cross Mount Water Tank, Oil Seepage Noted At Oil Pan, City Horn Inoperable, Missing Seats, Left Rear Wheel Seal Leaking, Various Body Damage/Rust. Showing 24,398 Miles; 2,272 Hours. Location: Tahlequah, OK Serial: 1M2P264C5YM031681 | |
| Lot # | 107 |  |
| Qty | 1 | |
| Title | 2016 FORD F250 4X4 CREW CAB PICKUP TRUCK | |
| Des. | NON RUNNER. MAJOR BODY DAMAGE FROM COLLISION. 6.7L Power Stroke, Automatic, Spring Suspension, 4.8 FA, 6.1 RA, 156 WB, Aluminum Wheels, 275/70R18, Body Damage/Rust. Mileage Unavailable. Location: Newton, MS Serial: 1FT7W2B65GEB91583 | |
| Lot # | 108 |  |
| Qty | 1 | |
| Title | 1986 KOMATSU WA250 WHEEL LOADER | |
| Des. | NO TITLE PER STATE REGULATIONS. RUNNING CONDITION UNKNOWN - LESS KEY. UNIT IS RED TAGGED. Komatsu 56D105-1 Diesel, Enclosed ROPS, 105in Bucket, Steel Wheels, 20.5R25, Body Damage/Rust. Showing 6,454 Hours. Location: Shiner, TX Serial: 10021 | |
| Lot # | 109 |  |
| Qty | 1 | |
| Title | 2013 EXMARK Z SERIES MOWERS | |
| Des. | NO TITLE PER STATE REGULATIONS. STARTED ON SITE W/ JUMP - NOT ROAD TESTED. UNIT HAS AN ISSUE WITH DRIVE MOTOR OR THE BRAKES ARE LOCKED UP - SEE VIDEO. Location: Newton, MS Serial: 880331 | |
| Lot # | 110 |  |
| Qty | 1 | |
| Title | 2006 MACK DM690S REAR MIXER | |
| Des. | NON RUNNER. MISSING CAB. Mack AMI-335 ASET, Maxitorque TM309M ES, Bogey Suspension, 222 WB, Side Mount Water Tank, Steel Fuel Tank, Steel Wheels, 425/65R22.5; 11R22.5, Body Damage/Rust. Mileage Unavailable. Location: San Antonio, TX Serial: 1M2B209C76M030741 | |
| Lot # | 111 |  |
| Qty | 1 | |
| Title | 2015 CHEVROLET 2500 4X4 CREW CAB PICKUP TRUCK | |
| Des. | NON RUNNER. MAJOR BODY DAMAGE FROM COLLISION - AIRBAGS DEPLOYED. 6.6L Duramax, Allison Automatic, Spring Suspension, 154 WB, AC, Missing Wheels, Body Damage/Rust. Mileage Unavailable. Location: Newton, MS Serial: 1GC1KUE82FF640172 | |
| Lot # | 112 |  |
| Qty | 1 | |
| Title | 2003 STERLING M8500 CAB & CHASSIS | |
| Des. | STARTED ON SITE NOT ROAD TESTED. INTAKE WARNING LIGHT ILLUMINATED. CAT 3126 Diesel (Seepage Noted), Automatic, 15.66 FA, 40 RA, 234 WB, 210in Back Cab To End Frame, Dual Steel Fuel Tanks, Steel Wheels, 315/80R22.5; 11R22.5 (Rears Singled Out), AC, Body Damage/Rust. Showing 484,253 Miles; 33,831 Hours. Location: Des Moines, IA Serial: 2FZHANAK83AL09045 | |

| | | |
|--------------|---|---|
| Lot # | 114 |  |
| Qty | 1 | |
| Title | 2008 KENWORTH T800B REAR MIXER | |
| Des. | NON RUNNER. HAS FIRE DAMAGE. MISSING COMPONENTS. Cummins ISL Diesel, Spring Suspension, 228 WB, CBMW Rear Mixer, Side Mount Water Tank, Aluminum Fuel Tank, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, Front Tires Flat, Body Damage/Rust. Mileage Unavailable. Location: San Antonio, TX Serial: 1NKDL50X18J237622 | |
| Lot # | 115 |  |
| Qty | 1 | |
| Title | 2001 INTERNATIONAL 4700 VAC TRUCK | |
| Des. | NON RUNNER. International DT466 Diesel, Spring Suspension, 216 WB, , 25ft Body, Dual 50 Gallon Fuel Tanks, Steel Wheels, 11R22.5, Body Damage/Rust. Mileage Unavailable. Location: Denver, CO Serial: 1HTSCAAL21H352422 | |
| Lot # | 116 |  |
| Qty | 1 | |
| Title | 2006 KAWASAKI 90ZV WHEEL LOADER | |
| Des. | NO TITLE PER STATE REGULATIONS. NON RUNNER. NO ENGINE. NO TRANSMISSION. Enclosed ROPS, 119in Bucket, Steel Wheels, 26.5-25, Missing Left Front Tire, Body Damage/Rust. Showing 15,575 Hours. Location: Georgetown, TX Serial: 90C5-5005 | |
| Lot # | 117 |  |
| Qty | 1 | |
| Title | 2009 FREIGHTLINER CASCADIA 125 SLEEPER TRUCK | |
| Des. | NON RUNNER. ENGINE LOCKED UP. Detroit Diesel, Eaton 10 Speed, Air Ride Suspension, 12 FA, 40 RA, 228 WB, Air Slide Fifth Wheel, Dual Aluminum Fuel Tanks, 56in Sleeper Area, Aluminum/Steel Wheels, 11R22.5, AC, Body Damage/Rust. Showing 883,109 Miles; 29,752 ECM Hours. Location: Concord, NC Serial: 1FUJGLDR59LAL2959 | |
| Lot # | 119 |  |
| Qty | 1 | |
| Title | 2008 FORD F450 SD SERVICE TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Ford Power Stroke Diesel, Automatic, Spring Suspension, 6 FA, 12 RA, 165 WB, 13ft Auto Crane Body, L/R Side Body Storage, Steel Wheels, 225/70R19.5, AC, Body Damage/Rust. Showing 270,819 Miles. Location: Pelham, AL Serial: 1FDXF46R78ED91037 | |
| Lot # | 120 |  |
| Qty | 1 | |
| Title | 2008 KENWORTH T800B CAB & CHASSIS | |
| Des. | NON RUNNER. MISSING SEVERAL COMPONENTS, INCLUDING: IGNITION, INSTRUMENT PANEL, MANIFOLD, TURBO, ALTERNATOR, CHUTES, EXHAUST, TRANSMISSION CONTROLS, SEATS, AND DRIVE SHAFT. Cummins ISL, Spring Suspension, 22 FA, 46 RA, 227 WB, 221in Back Cab To End Frame, Double Frame, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, Body Damage/Rust. Mileage Unavailable. Location: San Antonio, TX Serial: 1NKDL50X58J237610 | |
| Lot # | 121 |  |
| Qty | 1 | |
| Title | 2009 GMC C5500 STAKE BODY TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Several Lights/Light Functions Inoperable - See Report, Various Body Damage/Rust. Showing 180,619 Miles. Location: Butler, KY Serial: 1GDG5C1919F410939 | |

| | | |
|--------------|--|---|
| Lot # | 122 |  |
| Qty | 1 | |
| Title | 2001 MACK DM690S REAR MIXER | |
| Des. | NON RUNNER. MISSING TURBO AND DRIVE SHAFT. FRAME SWOLLEN. Mack EM7-275, Maxitorque 8 Speed, Camelback Suspension, 208 WB, 10.5 Yrd CBMW Rear Mixer, Side Mount Water Tank, Steel Fuel Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Mileage Unavailable; Showing 5,240 Hours. Location: San Antonio, TX Serial: 1M2B221C41M028641 | |
| Lot # | 123 |  |
| Qty | 1 | |
| Title | 2004 FORD 550 SERVICE TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. AUTO CRANE CABLE OFF PULLEYS. Ford Power Stroke Diesel, Automatic, Spring Suspension, 6 FA, 13.5 RA, 165 WB, 11ft Auto Crane Body, L/R Side Body Storage, R/ Outriggers, Steel Wheels, 225/70R19.5, AC, Dead Batteries, Check Engine Light Illuminated, Missing Diesel Fuel Tank Cap, Cracked Windshield, Body Damage/Rust. Showing 384,562 Miles. Location: Pelham, AL Serial: 1FDAF56P74EA17032 | |
| Lot # | 124 |  |
| Qty | 1 | |
| Title | 1996 CATERPILLAR 988F WHEEL LOADER | |
| Des. | NO TITLE PER STATE REGULATIONS. NON RUNNER. UNIT IS CARCASS ONLY - HAS BEEN SEPARATED IN TWO PIECES. Hours Unavailable. Location: Georgetown, TX Serial: 2ZR00514 | |
| Lot # | 129 |  |
| Qty | 1 | |
| Title | 2006 CHEVROLET C4500 STAKE BODY TRUCK | |
| Des. | STARTED ON SITE NOT ROAD TESTED. LEAKS NOTED AT BRAKE MASTER CYLINDER, COOLANT RESERVOIR, TRANSMISSION. Showing 317,304 Miles. Location: Carrollton, MI Serial: 1GBE4C1246F416137 | |
| Lot # | 131 |  |
| Qty | 1 | |
| Title | 2001 CHEVROLET 2500 4X4 PICKUP TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. KNOWN TRANSMISSION ISSUE - WILL NOT SHIFT INTO GEAR. GM 6.0L Gas, Automatic, Spring Suspension, 4.5 FA, 6.084 RA, 132 WB, 8ft Body, Steel Wheels, LT265/75R16, AC, PW, PL, PM, Airbag, Brake, And ABS Warning Lights Illuminated, Body Damage/Rust. Showing 321,795 Miles. Location: Des Moines, IA Serial: 1GCHK24U71E157809 | |
| Lot # | 132 |  |
| Qty | 1 | |
| Title | 2006 KAWASAKI 95ZV WHEEL LOADER | |
| Des. | NO TITLE PER STATE REGULATIONS. NON RUNNER. BAD TRANSMISSION. MISSING ALTERNATOR. Cummins QSX15 Diesel, Full Power Shift 4F/3R, Enclosed ROPS, 132in Bucket, Steel Wheels, 26.5-25, AC Pump Disconnected, Missing Right Side Tires, Body Damage/Rust. Showing 18,122 Hours. Location: Georgetown, TX Serial: 97C5-5046 | |
| Lot # | 133 |  |
| Qty | 1 | |
| Title | 2007 ELGIN PELICAN SWEEPER | |
| Des. | NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. 4 Cyl Turbo Diesel, Automatic, Straight Suspension, Steel Fuel Tank, Steel Wheels, 11R22.5; 9R17.5, After Market AC, Dual Rear Tires, Interior Rough Shape, Body Damage/Rust. Showing 17,361 Miles; 4,660 Hours. Location: Avondale, LA Serial: P4988D | |

| | | |
|--------------|---|---|
| Lot # | 134 |  |
| Qty | 1 | |
| Title | 2005 OSHKOSH F2346 REAR MIXER | |
| Des. | NON RUNNER- ENGINE APART - COMPONENTS MISSING, INCLUDING VALVE COVER. DASH APART - COMPONENTS MISSING. Cummins ISM Diesel, Automatic, Chalmers Suspension, 22 FA, 46 RA, 216 WB, 10.5 Yrd McNeilus Rear Mixer, Aluminum Fuel Tank, 110 Gallon Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5 (Rears Singled Out), PTO, AC, Body Damage/Rust. Mileage Unavailable. Location: Des Moines, IA Serial: 10TDDAC345S084199 | |
| Lot # | 135 |  |
| Qty | 1 | |
| Title | 2002 FORD F550 SD SERVICE TRUCK | |
| Des. | NON RUNNER. KNOWN ENGINE PROBLEMS. CRANE INOPERABLE. Ford Power Stroke Diesel, Automatic, Spring Suspension, 6 FA, 13.5 RA, 165 WB, 11ft Auto Crane Body, L/R Side Body Storage, R/ Outriggers, Steel Wheels, 225/70R19.5, AC, Body Damage/Rust. Showing 404,315 Miles. Location: Pelham, AL Serial: 1FDAF56F92EC59180 | |
| Lot # | 136 |  |
| Qty | 1 | |
| Title | 2005 INTERNATIONAL 5500i CAB & CHASSIS | |
| Des. | NON RUNNER. BODY DAMAGE FROM ROLL OVER. MISSING ENGINE, TRANSMISSION, AND REAR AXLES. DASH APART. MISSING SEATS AND OTHER COMPONENTS FROM CAB. Location: Pasadena, TX Serial: 1HTXLAHT35J025280 | |
| Lot # | 137 |  |
| Qty | 1 | |
| Title | 2006 MACK CT713 REAR MIXER | |
| Des. | NON RUNNER. FIRE DAMAGE. AMI-335 ASET, T309M 9 Speed, Walking Beam Suspension, 219 WB, 10.5 YRD. CBMW Rear Mixer, Side Mount Water Tank, Steel Wheels, 11R22.5, Steel Fuel Tank, Body Damage/Rust. Mileage Unavailable. Location: San Antonio, TX Serial: 1M2AL02C26M003434 | |
| Lot # | 138 |  |
| Qty | 1 | |
| Title | 1990 LUFKIN DUMP TRAILER | |
| Des. | 38ft Length, 101in Width, Steel Body Composition, Lift Cylinder, Tarp System, Rear Gate, Steel Wheels, 285/75R24.5, Fifth Wheel Chained As If Lift Cylinder Drifts, Body Damage/Rust. Location: San Antonio, TX Serial: 1L01C3828L1088699 | |
| Lot # | 139 |  |
| Qty | 1 | |
| Title | 1986 HOBBS DUMP TRAILER | |
| Des. | BAD GLAD HANDS. PLUGS MISSING. FRAME BENT. 31ft Length, 96in Width, Aluminum Body Composition, Lift Cylinder, Tarp System, Rear Gate, Steel Wheels, 11R24.5, Body Damage/Rust. Location: San Antonio, TX Serial: 1H5D0302XGM008401 | |
| Lot # | 140 |  |
| Qty | 1 | |
| Title | 1995 CATERPILLAR 988F WHEEL LOADER | |
| Des. | NO TITLE PER STATE REGULATIONS. NON RUNNER. UNIT HAS BEEN PARTED OUT. LESS BUCKET. CAT 3408 Diesel, 4F/3R, Steel Wheels, 65/35-33, Passenger Side Tire Flat, Body Damage/Rust. Showing 42,611 Hours. Location: Georgetown, TX Serial: 8YG0944 | |

| | | |
|--------------|---|---|
| Lot # | 141 |  |
| Qty | 1 | |
| Title | 2004 FORD F450 FLATBED TRUCK | |
| Des. | GEAR SELECTION OFF- STARTS IN NEUTRAL, SHIFTER LOOSE. NOT ROAD TESTED. 6.0L V8 Diesel (Oil Seepage Noted), Automatic (Known Issues), Spring Suspension, 194 WB, 14ft Body W/ Hydraulic Lift Gate- Inop, Underside Storage, Headache Rack, Steel Wheels, 225/70R19.5, AC, Dead Battery, Body Damage/Rust. Showing 290,597 Miles. Location: Des Moines, IA Serial: 1FDXF46P14ED21235 | |
| Lot # | 142 |  |
| Qty | 1 | |
| Title | 2011 FORD F750 STAKE BODY TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. VALVE COVER LOOSE ON ENGINE. INTAKE REMOVED WITH UNIT. Cummins ISB, Automatic, Spring Suspension, 12 FA, 21 RA, 281 WB, 26ft Steel Body, Steel Wheels, 11R22.5, AC, Dead Batteries, Missing Both Seats, Left Side Door Glass Broken, Check Engine Light Illuminated, Body Damage/Rust. Showing 199,279 Miles. Location: Pelham, AL Serial: 3FRWF7FE7BV124378 | |
| Lot # | 143 |  |
| Qty | 1 | |
| Title | 2005 FSL1627 FLATBED TRAILER | |
| Des. | BAD HUBS. 18ft Length, 78in Width, Steel Composition, Wood Decking, Fold Down Ramps, Steel Wheels, 235/85R16, Pintle Hitch, Body Damage/Rust. Location: Kansas City, MO Serial: 47SS162T051021502 | |
| Lot # | 144 |  |
| Qty | 1 | |
| Title | 1996 GALBREATH AP2A ROLLOFF TRAILER | |
| Des. | MISSING HYDRAULIC CONTROL VALVE ASSEMBLY. MISSING SLIDING BLOCK ROLLER WHEEL FOR CABLE. AIR LINES CUT. 33ft Length, Steel Composition, Spring Suspension, Steel Wheels, 11R22.5, Many Welded Repairs To Tongue, Missing Tarp. Location: Pelham, AL Serial: 1G9L12326TB157632 | |
| Lot # | 145 |  |
| Qty | 1 | |
| Title | 2004 FORD F350 SERVICE TRUCK | |
| Des. | NON RUNNER. INTAKE PARTS DAMAGED AND/OR MISSING. LESS KEYS. Ford 6.0L Diesel, Automatic, Spring Suspension, 4.85 FA, 9.75 RA, 176 WB, 9.5ft General Body, Steel Wheels, 235/85R16, AC, Dash Apart, Body Damage/Rust. Mileage Unavailable. Location: Weatherford, TX Serial: 1FDWW36P84EA02680 | |
| Lot # | 146 |  |
| Qty | 1 | |
| Title | INGERSOLL RAND SSR EP 150 AIR COMPRESSOR | |
| Des. | NO TITLE PER STATE REGULATIONS. NON RUNNER. MISSING ENGINE. Location: Godley, TX Serial: F39154U04346 | |
| Lot # | 147 |  |
| Qty | 1 | |
| Title | 1985 TCM FG15N15 FORKLIFT | |
| Des. | NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. NO SIDE SHIFT. Ford 4 Cyl Gas, 2 Speed, Open ROPS, 7.25ft Height, Two 36x5in Forks, Single Mast, Steel Wheels, 6.5-10, Body Damage/Rust. Showing 4,593 Hours. Location: Pelham, AL Serial: 4235024 | |

| | | |
|--------------|---|---|
| Lot # | 148 |  |
| Qty | 1 | |
| Title | 2009 TOYOTA 8FGU25 FORKLIFT | |
| Des. | NO TITLE PER STATE REGULATIONS. STARTED ON SITE FULL OPERATIONS NOT TESTED. Toyota 4Y-ECS 118 HP, ROPS, Solid Wheels, Rotator Attachment, Body Damage/Rust. Location: Spokane, WA Serial: 85GU2519495 | |
| Lot # | 149 |  |
| Qty | 1 | |
| Title | 1999 YALE GLC050 FORKLIFT | |
| Des. | NO TITLE PER STATE REGULATIONS. NON RUNNER. LESS KEYS. LESS FORKS. LP, ROPS, Solid Wheels, Body Damage/Rust. Location: Spokane, WA Serial: E187V09028W | |
| Lot # | 150 |  |
| Qty | 1 | |
| Title | 1974 HYSTER S50C FORKLIFT | |
| Des. | NO TITLE PER STATE REGULATIONS. CRANKS- WONT START. Location: Seattle, WA Serial: C2D16734 | |