



























## Printable Catalog








<b>Title</b>	DECEMBER 13 12:00 CST
<b>Description</b>	Closing Times TBD
<b>Date</b>	Wed, Dec 13, 2023
<b>Starts at</b>	12:00 PM
<b>Address</b>	4747 NE 14th St, Des Moines, IA 50313 USA
<b>Categories</b>	








<b>Lot #</b>	1	
<b>Qty</b>	1	
<b>Title</b>	2004 INTERNATIONAL 7600 DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. LEAK AT THE REAR OF ENGINE OIL PAN, 1 ACTIVE FAULT DETECTED, Rear Fender Cracked In Center, Grille Loose, Air Pressure Gauge Hanging From Under Dash, Missing Hood Vents, Paint Chips And Cracks Throughout Hood. Showing: 185,095 Miles; 9,101 Hours. Location: Salem, OR Serial: 1P98D4626TS075162	
<b>Lot #</b>	2	
<b>Qty</b>	1	
<b>Title</b>	2007 KENWORTH W900 REAR MIXER	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Non Running Due To Parts Being Removed From Unit, Bumper Bent On Left Side, Paint Peeling And Rusting On Deck, Interior Missing Passenger Seat, Missing Dash Buttons. Showing: Mileage/Hours Unavailable. Location: Eugene, OR Serial: 1NKWL00X07R163377	
<b>Lot #</b>	4	
<b>Qty</b>	1	
<b>Title</b>	2013 MACK CHU613 6X4 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. CHECK ENGINE LIGHT ON, Builds Air Slowly. Showing: 670,511 Miles; 11,535 Hours. Location: Des Moines, IA Serial: 1M1AN07Y9DM011787	
<b>Lot #</b>	5	
<b>Qty</b>	1	
<b>Title</b>	1996 INTERNATIONAL 4300 ATTENUATOR TRUCK	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. DEAD BATTERIES, UNABLE TO START AND TEST. OIL LEAKS FROM FRONT ENGINE SEAL, OIL PAN, AND TRANSMISSION PTO. Interior Upholstery Is Dirty And Torn, Mat Floor Covering Worn Holes And Rusted Hole Through Floor Pan. Rust And Cracks Noted Throughout Unit. Showing 310,289 Miles. Location: New Braunfels, TX Serial: 1HTSCABM9TH379014	
<b>Lot #</b>	6	
<b>Qty</b>	1	
<b>Title</b>	2007 KENWORTH W900 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. UNABLE TO READ ENGINE INFO. DROP AXLE HAS NO WHEELS OR TIRES. Check Engine And ABS Light Is On, Interior Stained, Passenger Seat Is Missing, Door Panels Scratched And Stained, Bumper Has Damage On Left Side, Rust Noted Throughout Body Of Unit. Showing 186,958 Miles; 1,451 Hours. Location: Hood River, OR Serial: 1NKWL00X07J159375	







<b>Lot #</b>	7	
<b>Qty</b>	1	
<b>Title</b>	1988 DRESSER CRANE	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. UNABLE TO START AND TEST-NO POWER. BATTERIES WEAK-NOT HOLDING CHARGE. Hydraulics Inoperative, Glass Cracked/Broken In Cab, Interior Dirty And Worn, Various Chips And Scratches Throughout Unit, Tires Have Heavy Wear-Dry Rot. Showing 3430 Hours. Location: Georgetown, TX Serial: 9833	
<b>Lot #</b>	8	
<b>Qty</b>	1	
<b>Title</b>	2005 INTERNATIONAL 7600 DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. ABS LIGHT ACTIVE, TWO ACTIVE FAULTS DETECTED - SEE ECM REPORT. Holes In Hood, Chrome Peeling/Paint Faded And Cracked, Two Tires Worn, Bumper Bent, Bed Is Cracked And Rusted, Holes Drilled In Center Of Dash, Rear Mud Flap Damaged. Showing 430,710 Miles 430,700 ECM Miles 23,849 Hours. Location: Salem, OR Serial: 1HTWXSBT15J042965	
<b>Lot #</b>	9	
<b>Qty</b>	1	
<b>Title</b>	2007 KENWORTH W900 REAR MIXER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. UNABLE TO START AND TEST. NO DOOR VIN TAG. Drop Has No Wheels Or Tires, Has Been Wrecked, Driver Side Door And Mirror Damaged, Bumper Damaged On Left Side. Mileage Unavailable. Location: Hood River, OR Serial: 1NKWL00X77J159373	
<b>Lot #</b>	11	
<b>Qty</b>	1	
<b>Title</b>	2015 MACK CXU613 6X4 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Areas Of Rust Noted, Switch Missing From Center Dash. Showing 475,509 Miles; 22,350 Hours. Location: Des Moines, IA Serial: 1M1AW07Y1FM046257	
<b>Lot #</b>	12	
<b>Qty</b>	1	
<b>Title</b>	2005 MACK CV513 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. ABS LIGHT IS ON. No Inside Door Handle But Is Ordered And Will Be Installed, Interior Is Worn, Stereo Display Out And Has No Knob, Rock Chips And Scratches Noted Throughout The Body. Showing 247,617 Miles, 25,527 Hours. Location: Wisner, NE Serial: 1M2AG02C15M002262	
<b>Lot #</b>	13	
<b>Qty</b>	1	
<b>Title</b>	1981 GALION 150FA CRANE	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. UNABLE TO START AND TEST-NO POWER. BATTERIES WEAK-NOT HOLDING CHARGE, FULL OPERATIONS NOT TESTED. Various Chips And Scratches Throughout Paint, Front Tires Off Rim And Rotten, Interior Dirty And Worn, Cab Glass Cracked, Hydraulics Have Dry Rot-Inoperative. Showing 6642 Hours. Location: Georgetown, TX Serial: DG9192	
<b>Lot #</b>	14	
<b>Qty</b>	1	
<b>Title</b>	2009 FREIGHTLINER FLD120SD REAR MIXER	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. MULTIPLE COMPONENTS ARE MISSING, Including: P/S Seat, Barrel, Hood, Dash, Gauges And Other Dash Components, Oil Leak Is Reported, Power Steering Hoses Are Leaking, Interior Door Panels Are Worn and Stained. Mileage Unavailable; Showing 1,421 Hours. Location: Salem, OR Serial: 1FVSALCV69DAF5902	








<b>Lot #</b>	15	
<b>Qty</b>	1	
<b>Title</b>	1997 KENWORTH T800B DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Hood Has Damage On Left Corner, Interior Speaker Over Dash Is Missing, Bumper Has Bent Corner, Damage Noted On Doors Of Unit. Showing 189,723 Miles, 4,648 Hours. Location: Salem, OR Serial: 1NKDX20X4VR740917	
<b>Lot #</b>	17	
<b>Qty</b>	1	
<b>Title</b>	2006 FREIGHTLINER FLD120SD REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. OIL RESIDUE / BUILD UP ON BOTH SIDES OF ENGINE, OIL LEAK RS REAR OF ENGINE, OIL RESIDUE / LEAKAGE AROUND OIL PAN SEAL, Grille Dented, Cab Marker Lights Inoperable, Door Panels Worn Loose, Seat Stained And Worn, Dash Air Vent Held With Tape, Rust And Paint Chips Throughout Unit. Showing: 205,087 Miles; 2,232 Hours. Location: Sunnyside, WA Serial: 1FVMALDL56DW00278	
<b>Lot #</b>	18	
<b>Qty</b>	1	
<b>Title</b>	2018 MACK CXU613 6X4 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE W/ FLUID, FULL OPERATIONS NOT TESTED. D/S Steps Are Bent Near Fuel Tank. Showing 583,717 Miles; 14,485 Hours. Location: Des Moines, IA Serial: 1M1AW09Y7JM089071	
<b>Lot #</b>	20	
<b>Qty</b>	1	
<b>Title</b>	2012 CATERPILLAR 336EL EXCAVATOR	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. KNOWN HYDRAULIC ISSUES- HYD. OIL SAMPLES CAME BACK SHOWING DIRT AND ALUMINUM CONTAMINATION. Exterior Has Scratches/Scrapes And Rust Noted Throughout Unit, Right Side Engine Access Panel Is Dented, Radio Has No Power To Head Unit/Inoperable And Is Missing A Button. Showing 12,203 Hours. Location: Brooklyn, IA Serial: YEP00250	
<b>Lot #</b>	21	
<b>Qty</b>	1	
<b>Title</b>	2002 MACK RD690S 6X4 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Electrical Fault, Bumper Bent On Right Side, Rock Chips And Scratches Throughout Unit, Left Fender Cracked, Seat Worn, No Stereo. Showing: 183,625 Miles; 21,276 Hours. Location: Wisner, NE Serial: 1M2P264C52M034152	
<b>Lot #</b>	22	
<b>Qty</b>	1	
<b>Title</b>	2005 INTERNATIONAL 7600 DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. OIL PAN LEAKING. Two Active Faults Detected - See ECM Report, Bed Cracked Over Axles, Rust Noted On Tailgate, Hood Has Holes In It, Drivers Side Door Missing Frame Around Exterior Door Handle, Grille Loose/Damaged, Multiple Tires Worn. Showing 463,983 Miles 463,972 ECM Miles 25,809 Hours. Location: Salem, OR Serial: 1HTWXSBT85J143906.	
<b>Lot #</b>	25	
<b>Qty</b>	1	
<b>Title</b>	2014 MACK CXU613 6X4 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Missing Radio, Staining And Rock Chips Noted On Hood, Missing Paint On Top Of Cab, Rear Mud Flap Hangers Are Bent Up. Showing 449,174 Miles; 15,637 Hours. Location: Des Moines, IA Serial: 1M1AW09Y4EM039430	

<b>Lot #</b>	26	
<b>Qty</b>	1	
<b>Title</b>	2005 PETERBILT 357 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. 11 YRD. Continental Mixer- Replaced In 2019- Invoice Attached. CHECK ENGINE LIGHT ILLUMINATED. Hood Is Cracked And Worn, Paint Scratched And Cracked Throughout Unit, Rust Throughout Unit, Passenger Side Mirror Cracked, Air Leak Under Hood, PS Cooler Dented, Windshield Chipped. Showing: 68,882 Miles; 14,682 Hours. Location: Clinton, NC Serial: 1NPAL0EX95D846587	
<b>Lot #</b>	27	
<b>Qty</b>	1	
<b>Title</b>	2008 HITACHI EX1200 BE-5C EXCAVATOR	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. ENGINE OIL AND HYDRAULIC FLUID LEAKING UNDER CHASSIS, HYDRAULIC FLUID LEAKING OUT OF DRIVES ON TRACKS, Some Tracks Are Broken, Controls And Gauges Worn And Damaged, Seat Stained And Worn, Rust And Dents Throughout Unit. Showing: 5,016 Hours. Location: Columbia, VA Serial:FF018F0003089	
<b>Lot #</b>	28	
<b>Qty</b>	1	
<b>Title</b>	2010 INTERNATIONAL WORKSTAR 7400 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Warning Lights On Dash, Rear Tires Singled Out, Dash Apart On P/S, Rust Throughout. Showing 258,992 Miles; 21,494 Hours. Location: Bardstown, KY Serial: 1HTWCAAN9AJ314486	
<b>Lot #</b>	29	
<b>Qty</b>	1	
<b>Title</b>	2005 INTERNATIONAL WORKSTAR 7600 6X4 DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Power Steering Reservoir Leaking, Seats And Headliner Worn And Stained, Body Damage And Rust Noted Throughout. Showing 478,135 Miles; 487,128 ECM; 2,488 Hours. Location: Salem, OR Serial: 1HTWXSBT85J010675	
<b>Lot #</b>	30	
<b>Qty</b>	1	
<b>Title</b>	2005 PETERBILT 357 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. IN FRAME ENGINE OVERHAUL REPORT INCLUDED. 11 YRD. Continental Mixer, CHECK ENGINE LIGHT ILLUMINATED. Fuel Tank Dented On Passenger Side, Windshield Cracked. Showing: 163,847 Miles; 17,860 Hours. Location: Clinton, NC Serial: 1NPAL0EX25D846589	
<b>Lot #</b>	32	
<b>Qty</b>	1	
<b>Title</b>	2018 KENWORTH T680 6X4 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE W/ FLUID, FULL OPERATIONS NOT TESTED. Missing Cab Steps On D/S. Showing 651,342 Miles; 14,450 Hours. Location: Des Moines, IA Serial: 1XKYD49X6JJ212710	
<b>Lot #</b>	33	
<b>Qty</b>	1	
<b>Title</b>	2013 FREIGHTLINER M2 112 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, CNG ENGINE WITH TANKS REMOVED, Engine Tag Not Located, Rear Tires Singled Out, Dash Apart On P/S, D/S Seat Is Torn. Mileage Unavailable. Location: Bardstown, KY Serial: 1FVXG1DX3DHFF0388	








<b>Lot #</b>	34	
<b>Qty</b>	1	
<b>Title</b>	1984 FORD L-9000 REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Air Leak Noted, Passenger Door Difficult To Open Due To Dents, Tag Axle Could Not Be Lowered Due To Hitting Chute, Rust Noted. Showing: 221,604 Miles; 5,412 Hours. Location: Clinton, NC Serial: 1FDYY90W1EVA06058	
<b>Lot #</b>	35	
<b>Qty</b>	1	
<b>Title</b>	1997 KOMATSU PC650 EXCAVATOR	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. NON RUNNER, FULL OPERATIONS NOT TESTED. UNABLE TO START/TEST-NO POWER. BATTERIES WEAK-NOT HOLDING CHARGE. Hydraulic Hoses Have Dry Rot, Various Chips And Scratches Throughout Unit, Missing Windshield/Back Glass Cracked And Broken, Interior Dirty And Worn, Side Panels Bent And Dented. Showing 15,252 Hours. Location Georgetown, TX Serial: 10702	
<b>Lot #</b>	36	
<b>Qty</b>	1	
<b>Title</b>	1996 KENWORTH T800B DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Oil Leak Reported, Interior Rear Wall Rusted/Cracked Behind D/S Seat, Headliner And Seats Worn And Stained, Heat Shielding Loose On P/S Hood, Body Damage And Rust Noted. Showing 105,209 Miles; 4,154 Hours. Location: Salem, OR serial: 1NKDX20X2TS727413	
<b>Lot #</b>	37	
<b>Qty</b>	1	
<b>Title</b>	2007 INTERNATIONAL PAYSTAR DF567 REAR MIXER	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Bad Engine, Missing The Following Parts: Power Steering Hose, Brake Pedal, Chutes, Rear Chute, Drive Line Removed And Damaged, Drum Is Thin, Body And Hood Damaged, Flats Tires. Showing: 245,585 Miles; 25,942 Hours. Location: Duluth, GA Serial: 1HTXHAHT67J526586	
<b>Lot #</b>	38	
<b>Qty</b>	1	
<b>Title</b>	2004 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. L/S STEER AXLE HUB AND SPINDLE ARE MISSING, DASH TAKEN APART, Engine Components Are Missing, Fuel Tank Removed On L/S Of Truck, VIN Tag And Engine Tag Illegible. Mileage Unavailable. Location: Newark, NJ Serial: 1M2AG11C04M017177	
<b>Lot #</b>	39	
<b>Qty</b>	1	
<b>Title</b>	2017 VOLVO VNL 6X4 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Some Staining To P/S Cloth Door Panel, Cup Holder Is Taped Up, Missing Switch From Center Dash, Area Of Rust On Cab Floor Between Seats. Showing 510,569 Miles; 12,457 Hours. Location: Des Moines, IA Serial: 4V4NC9EH9HN983389	
<b>Lot #</b>	40	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CT713 6X4 REAR MIXER	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. HOLE IN ENGINE BLOCK. Missing The Following Parts: Air Compressor, Right Door, Rear Remote, Dash Parts, Steering Column Apart, Flat Tires, Odometer Would Not Illuminate. Showing: Mileage/Hours Unavailable. Location: Jacksonville, FL Serial: 1M2AL02C47M007373	








<b>Lot #</b>	42	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CT713 6X4 REAR MIXER	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Missing The Following Parts: Coolant Tank, Oil Filter Housing, Coolant Pipes, Hydraulic P/T Pump, Rear Chute, Rear Remote, Dash Is Torn Apart, Fan Hub Is Off, Odometer Would Not Illuminate. Showing: Mileage/Hours Unavailable. Location: Jacksonville, FL Serial: 1M2AL02C17M007346	
<b>Lot #</b>	43	
<b>Qty</b>	1	
<b>Title</b>	1999 MACK RD688S 6X4 DUMP TRUCK	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Engine Would Not Turn Over, Clicking Noise Coming From Starter, Hydraulic Leaks. Showing: 602,323 Miles; 17,676 Hours. Location: Duluth, GA Serial: 1M2P267C4XM045999	
<b>Lot #</b>	44	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Missing Items, Including: Fuses And Relays, HVAC, Bulldog Ornament, Grill, Mirrors, And Multiple Rear Tires, Dash Apart On P/S. Mileage Unavailable. Location: Serial: 1M2AG11C26M037983	
<b>Lot #</b>	45	
<b>Qty</b>	1	
<b>Title</b>	1993 CATERPILLAR 325L EXCAVATOR	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. UNABLE TO START AND TEST, NO BATTERIES-NO POWER. Hydraulic Hoses Have Dry Rot-Inoperative, Right Side Panel Is Missing, Interior Is Dirty And Worn, Various Chips And Scratches Throughout Paint, Boom And Dipper Arm Patched And Welded, Rust Noted Throughout The Body. Showing 21707 Hours. Location: Georgetown, TX Serial: 8NK00430	
<b>Lot #</b>	46	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CT713 6X4 REAR MIXER	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. DEAD BATTERIES, Oil Leak Noted From R/S Of Engine And Front Engine Seal, Steering Gear Box And Power Steering Hoses Leaking, R/S Of Dash Disassembled And Holes Drilled In Center, Coolant Reservoir Cap Missing, Engine Air Filter Cover Is Split, Components Have Been Removed From Rear Mixer, Body Damage Throughout. Mileage Unavailable. Location: Gainesville, FL Serial: 1M2AL02C27M007355	
<b>Lot #</b>	47	
<b>Qty</b>	1	
<b>Title</b>	2018 MACK CXU613 6X4 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. CHECK ENGINE LIGHT ON, Damage To Hood And Bumper. Showing: 310,729 Miles; 11,894 Hours. Location: Des Moines, IA Serial: 1M1AW07Y1JM088288	
<b>Lot #</b>	48	
<b>Qty</b>	1	
<b>Title</b>	2005 KENWORTH T300 4X2 GARBAGE PACKER	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. NO BATTERIES, Dashboard Taken Apart, Missing Ignition, No Left Fuel Tank. Showing: 244,715 Miles; 3,650.8 Hours. Location: Newark, NJ Serial: 2NKMHD7X75M079373	








<b>Lot #</b>	49	
<b>Qty</b>	1	
<b>Title</b>	2004 MACK DM688S 6X4 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Oil Pan And Front Engine Seal Leaking Oil, PTO Engine Has Leak In Front, Transmission Bottom Cover Is Leaking, Air Leaking Under Cab, Air Brake And ABS Warning Lights On Dash, Muffler Burst, D/S Door Key Lock And Vent Release Are Removed, Tires Worn, Gauge Removed From Dash R/S, Dash Panel And Lower Trim Around Ash Tray Is Broken, Body Damage Noted, McNeilus Rear Mixer With 10.5 Cu Yd Capacity. Showing 312,993 Miles; 31,590 Hours. Location: Gainesville, FL Serial: 1M2B212C84M005036	
<b>Lot #</b>	50	
<b>Qty</b>	1	
<b>Title</b>	2003 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Missing Multiple Components, Including: ECU, Hood, Engine Parts, Mirrors, And P/S Seat, Engine Is Not Secure, Dash Is Apart, Tail Lights Are Damaged, Rust Throughout. Mileage Unavailable. Location: Henderson, NC Serial: 1M2P267C23M067123	
<b>Lot #</b>	51	
<b>Qty</b>	1	
<b>Title</b>	JOHN DEERE 690ELC EXCAVATOR	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. NON-RUNNER, FULL OPERATIONS NOT TESTED. BATTERIES WEAK COULD NOT START, Rust And Paint Chips Throughout Unit. Showing: 9,773 Hours. Location: Georgetown, TX Serial: DW69CEL554278	
<b>Lot #</b>	52	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CT713 6X4 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. COOLANT IS LEAKING FROM BYPASS HOSE, STEERING GEAR IS LEAKING, ENGINE OIL LEAK REPORTED, ABS Warning Light On Dash, Missing All Parts For Rear Chute, P/S Dash Panel, And Vent From Hood, Mixer INOP, Radio Loose In Slot And Low Volume, D/S Seat Torn, Various Body Damage Throughout. Showing 306,743 Miles; 28,517 Hours. Location: Orlando, FL Serial: 1M2AL02C87M007361	
<b>Lot #</b>	54	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CT713 6X4 REAR MIXER	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. KNOWN MOTOR AND TRANSMISSION ISSUES, Engine Is Leaking Oil, Dash Is Cracked And Missing Components, Holes Drilled into Center Of Dash, Inside Cab Mixer Controller Is Disassembled, Grill Is Missing On D/S, P/S Door Seal Is Damaged, Rear Tire Coming Off Of Rim, Body Damage Noted Throughout. Mileage Unavailable. Location: Orlando, FL Serial: 1M2AL02C16M002971	
<b>Lot #</b>	55	
<b>Qty</b>	1	
<b>Title</b>	2017 MACK CXU613 6X4 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Paint Dulled, Some Residue From Removed Logos, Small Tear In D/S Seat. Showing 631,133 Miles; 14,580 Hours. Location: Des Moines, IA Serial: 1M1AW09Y2HM084242	








<b>Lot #</b>	56	
<b>Qty</b>	1	
<b>Title</b>	2006 KOMATSU WA-200 WHEEL LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, MISSING BATTERIES, KNOWN BAD TRANSMISSION, Interior Doors, Rear Brake Light Lens And Back Up Lights Are Missing Trim, Step Ladder Is Damaged, Rear Grill Is Bent, Peeling Paint Noted On Rear Engine Compartment. Hours Unavailable. Location: Montgomery, AL Serial: KMTWA052J01068018	
<b>Lot #</b>	57	
<b>Qty</b>	1	
<b>Title</b>	2016 FREIGHTLINER 108SD CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Missing P/S Front Tire, Rear Mud Flaps Have Been Removed, Engine Tag Not Located, Rust Throughout. Showing 244,878 Miles. Location: Pelham, AL Serial: 1FVAG0CY2GHHG5467	
<b>Lot #</b>	58	
<b>Qty</b>	1	
<b>Title</b>	2005 MACK DM688S REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Engine And Transmission Are Covered In Oil- Engine Bay And Surrounding Components Covered In Oil, Oil Residue And Leakage Noted In Steering Sector, Gauge Blank Is Missing From Dash, Overhead Storage Panels Are Broken, D/S Seat Worn/Torn, Body Damage Noted. Showing 348,304 Miles; 348,304 ECM; 28,442 Hours. Location: Tampa, FL Serial: 1M2B212C55M005061	
<b>Lot #</b>	60	
<b>Qty</b>	1	
<b>Title</b>	1977 CATERPILLAR 977L TRACK LOADER	
<b>Des.</b>	NOT TITLED PER STATE REGULATION. NON-RUNNER, FULL OPERATIONS NOT TESTED. Seat Torn, Fuel Cap Missing, Rust Throughout Unit. Showing: Hours Unavailable. Location: San Antonio, TX Serial: 14X1100	
<b>Lot #</b>	62	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CT713 6X4 REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Multiple Oil Leaks, 6 Inactive Faults Detected- See ECM Report, Only Half Of The Rear Controller Buttons Are Functional, Steering Gear Box Is Leaking, Dash Is Broken In The Center, Rust Noted In Several Areas. Showing 335,224 Miles; 335,224 ECM; 29,255 Hours. Location: Tampa, FL Serial: 1M2AL02C86M002966	
<b>Lot #</b>	63	
<b>Qty</b>	1	
<b>Title</b>	2016 VOLVO VNM64T DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Body Damage On Hood, D/S Seat Torn And Taped. Showing 110,300 Miles. Location: Harrisburg, PA Serial: 4V4MC9EG7GN938307	
<b>Lot #</b>	64	
<b>Qty</b>	1	
<b>Title</b>	2007 KOMATSU WA430-6 FEL WHEEL LOADER	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. DEAD BATTERIES WILL NOT START, FULL OPERATIONS NOT TESTED. BAD DIFFERENTIAL. Body Damage Noted Throughout, Glass Is Cracked, Front Left Fender Damaged, Lines are Leaking, Worn Tires. Hours Unavailable. Location: San Antonio, TX Serial: 65174	
















<b>Lot #</b>	65	
<b>Qty</b>	1	
<b>Title</b>	2007 INTERNATIONAL PAYSTAR 5500i 6X4 REAR MIXER	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. NO CRANK, Weight, Engine And Body Data Tags Not Located, Missing Items, Including: Grill, D/S Hood Mirror, Radio, Some Switches In Center Dash Area, Dried Concrete Covering Body, Rust Throughout. Showing 324,622 Miles; 32,457 Hours. Location: Pasadena, TX Serial: 1HTXLAHT77J459589	
<b>Lot #</b>	66	
<b>Qty</b>	1	
<b>Title</b>	1996 PIONEER TRUCKWELD PUP DUMP TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Rust On Frame Rails And Crossmembers, Reverse Light Cracked. Location: Salem, OR Serial: 1P98D4626TS075162	
<b>Lot #</b>	68	
<b>Qty</b>	1	
<b>Title</b>	2005 INTERNATIONAL PAYSTAR 5500i 6X4 REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. Engine Tag Is Illegible, Body Tag Not Located, Rear Tires Are Singled Out And Missing Lug Nuts, Missing Items, Including: Front Grill, Radio And D/S Hood Mirror, Rust And Body Damage Throughout. Showing 242,938 Miles; 29,202 Hours. Location: Pasadena, TX Serial: 1HTXLAHT25J132093	
<b>Lot #</b>	70	
<b>Qty</b>	1	
<b>Title</b>	2006 INTERNATIONAL PAYSTAR 5500i 6X4 REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Axle Weight And Body Data Tags Not Located, Engine Tag Is Illegible, Rear Tires Singled Out And Missing Lug Nuts, Grill Is Missing, Mixer Chute Covered In Dried Concrete, Interior Soiled, Rust And Body Damage Throughout. Showing 335,401 Miles; 33,566 Hours. Location: Pasadena, TX Serial: 1HTXLAHT86J322921	
<b>Lot #</b>	71	
<b>Qty</b>	1	
<b>Title</b>	2018 FREIGHTLINER CASCADIA 126 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Cracked Windshield. Showing 758,109 Miles; 17,383 Hours. Location: Weatherford, TX Serial: 3AKJHLDR0JSHM7928	
<b>Lot #</b>	72	
<b>Qty</b>	1	
<b>Title</b>	2006 KAWASAKI 90ZV FEL WHEEL LOADER	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. NON-RUNNER, UNIT DISASSEMBLED-WILL NOT START/RUN. Right Front Tire And Wheel Removed, Interior Is Dirty/Worn, Various Chips/Scratches Noted Throughout Body Of Unit, Various Panels/Parts Removed. Showing 18,227 Hours. Location: Georgetown, TX Serial:90C5-5002	
<b>Lot #</b>	74	
<b>Qty</b>	1	
<b>Title</b>	2007 INTERNATIONAL PAYSTAR 5500i 6X4 REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. Body Information And Axle Weight Tags Not Located, Engine Tag Is Illegible, Plastic Laminate Peeling Away From Center Dash, Rust And Body Damage Throughout. Showing 359,704 Miles; 33,650 Hours. Location: Pasadena, TX Serial: 1HTXLAHTX7J459585	








<b>Lot #</b>	75	
<b>Qty</b>	1	
<b>Title</b>	2018 INTERNATIONAL LT625 SLEEPER TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing 490,071 Miles; 15,043 Hours. Location: Jacksonville, FL Serial: 3HSDZAPR1JN055204	
<b>Lot #</b>	76	
<b>Qty</b>	1	
<b>Title</b>	1984 CATERPILLAR D8K DOZER-CRAWLER	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. NON-RUNNER, FULL OPERATIONS NOT TESTED. HYDRAULIC LEAKS UNDER FRONT CYLINDERS. Batteries Bad, Tail Lights/Windows Smashed Out, Heavy Rust Noted Throughout Unit. Hours: 2476. Location: Marine On St. Croix, MN Serial: 77V-2813	
<b>Lot #</b>	77	
<b>Qty</b>	1	
<b>Title</b>	2023 MAS 750 FUEL TRAILER	
<b>Des.</b>	12,500 LB. Capacity, 19ft Length, 6.8ft Width. Location: Weatherford, TX Serial: 3M7TZ2028PU000132	
<b>Lot #</b>	78	
<b>Qty</b>	1	
<b>Title</b>	2007 INTERNATIONAL PAYSTAR 6X4 5500i REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. Axle Weight Tag And Body Information Tags Not Located, Engine Tag Is Illegible, Grill And Grill Bars Are Missing, D/S Seat Torn And Arm Rest Taped Up, P/S Seat And Radio Are Missing. Showing 312,081 Miles; 31,635 Hours. Location: Pasadena, TX Serial: 1HTXLAHT57J459588	
<b>Lot #</b>	79	
<b>Qty</b>	1	
<b>Title</b>	1996 PIONEER TRUCKWELD DUMP TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Dents In Box Walls, Rust In Various Areas. Showing: 100,112 Miles On Hubodometer. Location: Salem, OR Serial: 1P98D4624TS075130	
<b>Lot #</b>	80	
<b>Qty</b>	1	
<b>Title</b>	1997 CATERPILLAR 938F FEL WHEEL LOADER	
<b>Des.</b>	NOT TITLED PER STATE REGULATION. NON-RUNNER, FULL OPERATIONS NOT TESTED. UNIT WAS USED FOR SAVAGE PARTS, Rust Throughout Unit. Showing: Hours Unavailable. Location: San Antonio, TX Serial: 1KM02420	
<b>Lot #</b>	81	
<b>Qty</b>	1	
<b>Title</b>	2007 INTERNATIONAL PAYSTAR 5500i REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. Engine, VIN And Body Information Tags Not Located, Rear Tires Are Singled Out And Missing Lug Nuts On Both Sides, Grill Missing From Front, Radio And Some Switches Missing From Dash, Body Damage Throughout. Showing 327,747 Miles; 32,798 Hours. Location: Pasadena, TX Serial: 1HTXLAHT27J459595	

<b>Lot #</b>	82	
<b>Qty</b>	1	
<b>Title</b>	1984 CATERPILLAR D-10 DOZER-CRAWLER	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. NON-RUNNER, FULL OPERATIONS NOT TESTED. Batteries Are Weak And Wont Hold Charge, Seat Is Worn, Rust And Scratches Throughout Unit. Showing: Hours Unavailable. Location: Georgetown, TX Serial: 116B	
<b>Lot #</b>	83	
<b>Qty</b>	1	
<b>Title</b>	2019 FREIGHTLINER CASCADIA 126 SLEEPER TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing 458,106 Miles; 13,320 Hours. Location: Lakeville, IN Serial: 1FUJHHRXKLN7584	
<b>Lot #</b>	84	
<b>Qty</b>	1	
<b>Title</b>	2006 INTERNATIONAL PAYSTAR 5500i 6X4 REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. POWER STEERING IS BAD, Axle Weight Tag And Body Information Tag Not Located, Engine Tag Is Illegible, Missing Radio And P/S Seat From Interior, Holes Drilled Into Center Dash Area, Small Tear In D/S Seat. Showing 250,954 Miles; 26,719 Hours. Location: Pasadena, TX Serial: 1HTXLAHT26J322932	
<b>Lot #</b>	85	
<b>Qty</b>	1	
<b>Title</b>	2018 SIDUMPR SDR 240-73 SIDE DUMP TRAILER	
<b>Des.</b>	APPROXIMATE MEASUREMENT 42 FT LENGTH, 102 IN WIDTH, 110 IN HEIGHT, FULL OPERATIONS NOT TESTED. Location: Ankeny, IA Serial: 1D9FS4020JC688026	
<b>Lot #</b>	86	
<b>Qty</b>	1	
<b>Title</b>	2006 INTERNATIONAL PAYSTAR 5500i 6X4 REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Rear Tires Are Singled Out And Missing Lug Nuts, Front D/S Tire Missing Lug Nuts, Axle Weight Tag Not Located, Grill Missing, CBMW Rear Mixer Drum With 10.5 Cubic Yard Capacity, D/S Seat Tattered, Part Of Dash And Seat Are Missing On P/S. Showing 304,091 Miles; 32,687 Hours. Location: Pasadena, TX Serial: 1HTXLAHT56J322939	
<b>Lot #</b>	87	
<b>Qty</b>	1	
<b>Title</b>	2019 INTERNATIONAL 4300 VAN BODY TRUCK	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. ENGINE OIL LEAK AT THE REAR OF OIL PAN, TRANSMISSION PAN IS COVERED WITH OIL RESIDUE, REAR WHEEL SEALS LEAKING, Box Has Multiple Dents And Scratches, Drivers Seat Torn, Bumper Has Scratches. Showing: Mileage/Hours Unavailable. Location: Adel, GA Serial: 3HAMMMMLXKL696823	
<b>Lot #</b>	88	
<b>Qty</b>	1	
<b>Title</b>	1969 CATERPILLAR D6C DOZER-CRAWLER	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. NON-RUNNER, FULL OPERATIONS NOT TESTED. NO POWER, Heavy Wear On Blades, Hydraulics Inoperable, Rust Throughout Unit, Seat Is Missing Its Bottom. Showing: Hours Unavailable. Location: Georgetown, TX Serial: 10K2174	

<b>Lot #</b>	89	
<b>Qty</b>	1	
<b>Title</b>	2016 PETERBILT 587 SLEEPER TRUCK	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Engine Not Started Due To No Oil Pressure. Showing 915,035 Miles; Location: Foristell, MO Serial: 1XP4DP9X3GD224234	
<b>Lot #</b>	90	
<b>Qty</b>	1	
<b>Title</b>	2007 INTERNATIONAL PAYSTAR 5500i REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. Axle Weight Tag Not Located, Engine Tag Illegible, Grill Missing Components, Rear Tires Singled Out And And Missing Lug Nuts, Rear Tires Flat And Off Rim On Both Sides, Radio Missing From Dash And Air Vents Broken/Missing On P/S. Showing 316,873 Miles; 34,603 Hours. Location: Pasadena, TX Serial: 1HTXLAHT77J459592	
<b>Lot #</b>	91	
<b>Qty</b>	1	
<b>Title</b>	2009 CLEMENTS DUMP TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Tires Singled Out On Front L/S Axle, Rust Throughout, VIN Tag Plate Not Located, Approximate Measurements: 40 FT Body Length, 41 FT Shipping Length, 96 IN Width, 11.7 FT Height. Location: Elgin, IL Serial: 5C2BB37B79M007370	
<b>Lot #</b>	92	
<b>Qty</b>	1	
<b>Title</b>	TEREX TR45 OFF HIGHWAY-DUMP TRUCK	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. NON-RUNNER, FULL OPERATIONS NOT TESTED. NO ENGINE, Hydraulics Inoperative, Rust Throughout Unit, Interior Dirty And Worn, Paint Chipped Throughout. Showing: Hours Unavailable. Location: Georgetown, TX Serial: T7811033	
<b>Lot #</b>	94	
<b>Qty</b>	1	
<b>Title</b>	2006 INTERNATIONAL PAYSTAR 5500i 6X4 REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Engine, Axle Weight And Body Tags Not Located, R/S Front Tire Hub Plug Is Missing, Grill And P/S Seat Are Missing, Dried Concrete Is Covering Rear End. Mileage Unavailable; Showing 32,959 Hours. Location: Pasadena, TX Serial: 1HTXLAHT16J322923	
<b>Lot #</b>	95	
<b>Qty</b>	1	
<b>Title</b>	2017 KENWORTH T680 6X4 SLEEPER TRUCK	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. WILL NOT MOVE DUE TO FRONT/REAR PROBLEM, Check Engine Warning Light And Regen Inhibit Switch Active Message Displayed On Dash, Very Hard Steering, Sleeper Mattress Is Missing. Showing 666,670 Miles. Location: Powell, TN Serial: 1XKYDP9XXHJ144312	
<b>Lot #</b>	96	
<b>Qty</b>	1	
<b>Title</b>	1985 ETNYRE TR6 TANKER TRAILER	
<b>Des.</b>	APPROXIMATE MEASUREMENTS 42 FT LENGTH, 8 FT WIDTH, 11.3 FT HEIGHT, FULL OPERATIONS NOT TESTED. Has Minor Rust Throughout Unit. Location: East Petersburg, PA Serial: 1E9T42205FE007011	

<b>Lot #</b>	97	
<b>Qty</b>	1	
<b>Title</b>	2006 INTERNATIONAL PAYSTAR 5500i 6X4 REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. No Oil On Dipstick, Axle Weight Tag And Body Information Tag Not Located, Rear Tires Singled Out And Missing Lug Nuts, Grill Components Missing, Radio And Gauges Missing From Center Of Dash, Trim Missing From Odometer Gauges. Showing 330,795 Miles; 36,104 Hours. Location: Pasadena, TX Serial: 1HTXLAHT86J322935	
<b>Lot #</b>	98	
<b>Qty</b>	1	
<b>Title</b>	1996 EUCLID R40C OFF HIGHWAY-DUMP TRUCK	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. NON RUNNER, FULL OPERATIONS NOT TESTED. UNABLE TO START AND TEST-NO POWER. BATTERIES WEAK-NOT HOLDING CHARGE. Drive Line And Wheels Removed, Various Chips And Scratches Noted Throughout Unit, Interior Dirty And Worn. Location: Georgetown, TX Serial: 404TDC76431.	
<b>Lot #</b>	99	
<b>Qty</b>	1	
<b>Title</b>	2016 CATERPILLAR CT660 3 AXLE 2-7KGAL CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, UNIT INOPERABLE - SIGNIFICANT DAMAGE NOTED THROUGHOUT UNIT. Unit Parked Over A Year, Involved In A Significant Collision / Apparent Roll Over Damage, No Power Available, Only Two Batteries Equipped. Last Known Mileage: 30,940 Miles. Location: Waco, TX Serial: 3HTJGKT6GN749253	
<b>Lot #</b>	100	
<b>Qty</b>	1	
<b>Title</b>	2007 INTERNATIONAL PAYSTAR 5500i REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. Oil Leak Noted From Back Of Head, L/S Front Tire And Rear Tires Missing Lug Nuts, Rear Tires Singled Out, Missing Battery Box Cover, Axle Weight Tag And Body Tags Not Located, Engine Tag Is Illegible, Parts Missing From P/S Dash. Showing 313,421 Miles; 29,499 Hours. Location: Pasadena, TX Serial: 1HTXLAHT87J459584	
<b>Lot #</b>	101	
<b>Qty</b>	1	
<b>Title</b>	2002 FORD F250 4X4 SERVICE TRUCK	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. CATALYTIC CONVERTER HAS BEEN CUT OFF, Low Fuel And ABS Warning Lights On Dash, Lift Gate And Pony Motor Are INOP, Body Rust Noted, Service Body Is Missing Door On P/S, D/S Seat Torn. Showing 81,986 Miles. Location: Des Moines, IA Serial: 1FDNF21S82EC80851	
<b>Lot #</b>	102	
<b>Qty</b>	1	
<b>Title</b>	2007 INTERNATIONAL PAYSTAR 5500i 6X4 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Axle Weight And Body Information Tags Not Located, Engine Tag Is Illegible, Plastic Laminate Peeling Away From Dash, Radio Missing From Center Dash And Vent Is Taped Up. Showing 332,230 Miles; 34,599 Hours. Location: Pasadena, TX Serial: 1HTXLAHT37J459590	

<b>Lot #</b>	103	
<b>Qty</b>	1	
<b>Title</b>	2012 DODGE RAM 1500 CREW CAB PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Catalytic Converter Missing, Bumper Has Chips, Drivers Floor Mat Worn, Interior Dirty And Stained, Windshield Has Crack, Rock Chips And Scratches Throughout Unit. Showing: 182,911 Miles; 6,148 Hours. Location: Richland, WA Serial: 1C6RD6GT2CS265033	
<b>Lot #</b>	104	
<b>Qty</b>	1	
<b>Title</b>	2012 GREAT DANE FRP-3012 DRY VAN TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Air Ride Control Box Broken, 7-Way Box Broken And Repaired With Silicone, Body Damage Noted, Approximate Measurements: 53 FT Shipping Length, 103 IN Shipping Width, 12 FT Shipping Height. Location: Yermo, CA. Serial: 1GRAA061XCB708594	
<b>Lot #</b>	105	
<b>Qty</b>	1	
<b>Title</b>	2007 TEREX TA30 WATER TRUCK	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. NON-RUNNER, FULL OPERATIONS NOT TESTED. Batteries Weak, Missing Front Drive Axle, Windshield Cracked, Interior Dirty And Worn, Paint Scratched Throughout Unit. Showing: Hours Unavailable. Location: Georgetown, TX Serial:A8941223	
<b>Lot #</b>	106	
<b>Qty</b>	1	
<b>Title</b>	2006 INTERNATIONAL PAYSTAR 5500i 6X4 REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Weight And Body Tags Not Located, Engine Tag Is Illegible, Front R/S Tire Is Missing Five Lug Nuts And Rear Tires Are Singled Out, Dried Concrete Covering Body, P/S Fuze Box Cover Removed, Rust And Body Damage Throughout. Showing 331,160 Miles; 34,221 Hours. Location: Pasadena, TX Serial: 1HTXLAHT36J322938	
<b>Lot #</b>	107	
<b>Qty</b>	1	
<b>Title</b>	1999 FORD F450 SUPER DUTY SERVICE TRUCK	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. UNIT WOULD NOT STAY RUNNING UNLESS CONNECTED TO CHARGING DEVICE, Oil Leak Noted On P/S Of Engine, Missing Oil Dipstick, Holes Drilled Into Center Dash, Interior Soiled, Interior Door Panels Have Broken Door Knobs, Seats Worn And Stained, Floor Mat Torn, Rust Noted Throughout. Showing 6,861 Miles. Location: Salem, OR Serial: 1FDXF46F8XEB09069	
<b>Lot #</b>	108	
<b>Qty</b>	1	
<b>Title</b>	2003 FORD PICKUP TRUCK	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. OIL LEAK BUILDUP AT BOTTOM OF ENGINE / OIL PAN AND TRANSMISSION, Bed Removed, Driver Door And Fender Dented, Front Bumper Dented, Rust Throughout Unit, Interior Worn And Stained, Seat Torn. Showing: Mileage/Hours Unavailable. Location: San Antonio, TX Serial: 1FDWF36F83EB13980	
<b>Lot #</b>	109	
<b>Qty</b>	1	
<b>Title</b>	TENNANT 800D SWEEPER	
<b>Des.</b>	NOT TITLED PER STATE REGULATION. NON-RUNNER, FULL OPERATIONS NOT TESTED. Windows Broken, Hood Dented, Headliner And Carpet Torn. Showing: Hours Unavailable. Location: San Antonio, TX Serial: 800-4337	

<b>Lot #</b>	110	
<b>Qty</b>	1	
<b>Title</b>	2007 INTERNATIONAL PAYSTAR 5500i REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Engine Missing Fan Assembly, Coolant Leak Due To Missing Hose Clamp, Bad Wiring Harness, Grill Is Missing, Engine, Body And Weight Data Tags Not Located, Dash Components Loose/Missing, Fuze Box Cover On P/S Is Removed, Dried Concrete Covering Body. Showing 308,896 Miles; 31,401 Hours. Location: Pasadena, TX Serial: 1HTXLAHT07J459594	
<b>Lot #</b>	111	
<b>Qty</b>	1	
<b>Title</b>	1981 REEDRILL PNEUMATIC DRILL MISC	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. NON-RUNNER, FULL OPERATIONS NOT TESTED. Seats And Gauges Non Operational, Some Parts Have been Removed, Rust Throughout Unit. Showing: Hours Unavailable. Location: San Antonio, TX Serial: 1060171	
<b>Lot #</b>	112	
<b>Qty</b>	1	
<b>Title</b>	2004 FORD F150 XLT PICKUP TRUCK	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. TRIED TO START LEFT ON CHARGER FOR 20 MIN., WOULD TURN OVER BUT NOT START. Showing 340,954 Miles. Location: Cowan, TN Serial: 1FTRW12W54KA12281	
<b>Lot #</b>	113	
<b>Qty</b>	1	
<b>Title</b>	2015 PETERBILT 365 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. ABS LIGHT ON, Unit Does Not Build Secondary Air. Showing: 216,366 Miles; 19,722 Hours. Location: Conroe, TX Serial: 1NPSX7EX6FD273408	
<b>Lot #</b>	114	
<b>Qty</b>	1	
<b>Title</b>	1996 FORD F450 SERVICE TRUCK	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Batteries Weak And Will Not Hold Charge, Windshield Cracked, Chips And Scratches Throughout Unit, Dash Broken On Both Sides, Seat Torn, Interior Dirty And Stained. Showing: Mileage/Hours Unavailable. Location: Georgetown, TX Serial: 1FDLF47FXTEB17522	
<b>Lot #</b>	115	
<b>Qty</b>	1	
<b>Title</b>	TENNANT 800D SWEEPER	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. NON-RUNNER, FULL OPERATIONS NOT TESTED. Interior Split/Torn, Rust And Body Damage Throughout Unit. Hours Unavailable. Location: San Antonio, TX Serial: 800-1386	
<b>Lot #</b>	116	
<b>Qty</b>	1	
<b>Title</b>	2015 PETERBILT 365 REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. Missing Chutes, Unit Does Not Build Air Due To Missing Adapter At Air Dryer, Cracked Windshield. Showing 216,192 Miles; 19,876 Hours. Location: Conroe, TX Serial: 1NPSX7EX4FD273410	

---

**Lot #** 117  
**Qty** 1  
**Title** ALLMAND NITE-LIGHT PRO LIGHT TOWER  
**Des.** NO TITLE PER STATE REGULATIONS. UNKNOWN RUNNING CONDITION, FULL OPERATIONS NOT TESTED. Rust Noted, Tires Blown. Showing 2,306 Hours. Location: Buckeye, AZ Serial: 9906NL0P08




---

**Lot #** 118  
**Qty** 1  
**Title** 2015 PETERBILT 365 REAR MIXER  
**Des.** NON RUNNER, FULL OPERATIONS NOT TESTED. WILL NOT CRANK, ABS And Traction Control Warning Lights On The Dash, Continental Rear Mixer Attachment. Showing 220,817 Miles; 23,230 Hours. Location: Conroe, TX Serial: 1NPSX7EX3FD273401




---

**Lot #** 119  
**Qty** 1  
**Title** 1993 G&H 1700 ROLLOFF TRAILER  
**Des.** FULL OPERATIONS NOT TESTED. Approximate Measurements: 20 FT Body Length, 20 FT Container Rails, 102 IN Width. Location: Buckeye, AZ Serial: 1G9PT3326PA116026




---

**Lot #** 120  
**Qty** 1  
**Title** 1981 TENNANT SWEEPER  
**Des.** NOT TITLED PER STATE REGULATIONS. NON-RUNNER, FULL OPERATIONS NOT TESTED. Interior Split/Tore, Scratches On Body Throughout Unit. Hours Unavailable. Location: San Antonio, TX Serial:T8354E156

