





























Printable Catalog






Title	DECEMBER 27 12:00 CST
Description	Closing Times TBD
Date	Wed, Dec 27, 2023
Starts at	12:00 PM
Address	4747 NE 14th St, Des Moines, IA 50313 USA
Categories	

Lot #	1	
Qty	1	
Title	2018 MACK GU713 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing: 55,935 Miles; 4,793 Hours. Location: Des Moines, IA Serial: 1M2AX04C2JM038193	
Lot #	2	
Qty	1	
Title	2004 INTERNATIONAL DURASTAR 4400 6X4 KNUCKLEBOOM TRUCK	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. CRANK-NO START, NEEDS BATTERIES, Copma 2000 Model 80 Knuckleboom Attachment Has Plastic In System From Bag Sucked Into Hydraulic Tank, Body Covered With Asphalt, Axle Weight Tag Not Located, Rust Throughout. Showing 376,747 Miles; 14,576 Hours. Location: Cleveland, OH Serial: 1HTMSAAR44J079531	
Lot #	3	
Qty	1	
Title	2019 INTERNATIONAL LT62F DAY CAB TRUCK	
Des.	STARTED ONSITE, FULL OPERATIONS NOT TESTED. Showing 606,619 Miles 14,382 Hours. Location: Des Moines, IA Serial: 3HCDZAPR7KL334455	
Lot #	4	
Qty	1	
Title	2004 MACK CV713 CAB & CHASSIS	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. NO POWER, Dash Is Apart And Is Missing Components, Missing Items, Including: Mirrors, Dash, And Drive Shaft, Clutch Play Needs Attention, Tires Worn, Body Damage Throughout. Mileage Unavailable. Location: Salem, OR Serial: 1M2AG12C24M010942	
Lot #	5	
Qty	1	
Title	2023 KENWORTH T880 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Engine Tag Not Located. Showing 19,284 Miles; 277 Hours. Location: Des Moines, IA Serial: 1NKZXKEX5PJ172967	
Lot #	6	
Qty	1	
Title	2000 FORD F350 SERVICE TRUCK	
Des.	STARTED ON SITE W/JUMP, FULL OPERATIONS NOT TESTED. TRANSMISSION DOES NOT SWITCH GEARS, Reading Service Body, Rust And Body Damage Throughout. Showing 265,538 Miles. Location: Harrisburg, PA Serial: 1FDWF36F7YEB70226	








Lot #	7	
Qty	1	
Title	1984 WALKER TANKER TRAILER	
Des.	FULL OPERATIONS NOT TESTED. Dents And Rust Noted, Approximate Measurements: 45 FT Shipping Length, 100 IN Shipping Width, 11 FT Shipping Height. Location: Winesburg, OH Serial: 1W9S72AW9E0007123	
Lot #	8	
Qty	1	
Title	2019 INTERNATIONAL LT625 6X4 DAY CAB TRUCK	
Des.	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. NEEDS BATTERIES, Windshield Chipped. Showing 590,084 Miles; 13,262 Hours. Location: Des Moines, IA Serial: 3HCDZAPR9KL334649	
Lot #	9	
Qty	1	
Title	2006 STERLING LT9500 REAR MIXER	
Des.	STARTED ONSITE, FULL OPERATIONS NOT TESTED. FRONT GRILLE BROKEN/MISSING PIECE. Showing 297,388 Miles 30,368 Hours. Location: Des Moines, IA Serial: 2FZHAZDL96AW30124.	
Lot #	10	
Qty	1	
Title	2009 FREIGHTLINER M2 106 CAB & CHASSIS	
Des.	STARTED ON SITE. FULL OPERATIONS NOT TESTED. Engine Tag Not Visible, Showing: 136,598.5 Miles. Location: Sacramento, CA Serial: 1FVFCYBS79HAD1861	
Lot #	11	
Qty	1	
Title	2008 FORD F450 SERVICE TRUCK	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Brake, ABS And Engine Warning Light On Dash And Check Brake System Warning Message Is Displayed, Interior Is Worn, Soiled And Missing Carpet, Rust Throughout. Showing 123,065 Miles. Location: Des Moines, IA Serial: 1FDXF46R08EE18207	
Lot #	12	
Qty	1	
Title	1989 BRENNER TANKER TRAILER	
Des.	FULL OPERATIONS NOT TESTED. Minimal Rust, Newer Tires, Trailer Capacity 7000 LBS, Two Compartments. Approximate Measurements 35 FT Length. Location: Newberry, IN Serial: 10BFZ7213KF0A1525	
Lot #	13	
Qty	1	
Title	2005 STERLING LT9500 REAR MIXER	
Des.	STARTED ONSITE, FULL OPERATIONS NOT TESTED. Needs Injectors, Front Grille Cracked/Broken. Showing 318,680 Miles 26,552 Hours. Location: Des Moines, IA Serial: 2FZHAZDL05AU06240.	
Lot #	14	
Qty	1	
Title	2019 INTERNATIONAL LT625 6X4 DAY CAB TRUCK	
Des.	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Showing 646,331 Miles 13,998 Hours. Location: Des Moines, IA Serial: 3HCDZAPR6KL118774	








Lot #	15	
Qty	1	
Title	2015 KENWORTH T370 CAB & CHASSIS	
Des.	STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. Warning Lights On Dash, Tires Are Singled Out On Rear Axle. Mileage Unavailable. Location: McComb, MS Serial: 2NKHHJ7X8FM426484	
Lot #	16	
Qty	1	
Title	2007 ISUZU NPR SERVICE TRUCK	
Des.	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Body Damage Above D/S Headlight, Front Bumper Is Dented, Rust Throughout. Showing 121,356 Miles. Location: Elkhorn, WI Serial: 4KLC4B1U47J803851	
Lot #	17	
Qty	1	
Title	2005 STERLING LT9500 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. DASH IS BROKEN, GLASS MISSING FROM D/S DOOR, D/S Seat Is Torn, McNeilus Rear Mixer Drum. Showing 309,254 Miles; 26,090 Hours. Location: Des Moines, IA Serial: 2FZHAZDL75AU06235	
Lot #	18	
Qty	1	
Title	2019 INTERNATIONAL LT625 6X4 DAY CAB TRUCK	
Des.	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. PAINT IS MISSING FROM THE TOP OF CAB. Showing 635,690 Miles; 14,336 Hours. Location: Des Moines, IA Serial: 3HCDZAPR5KL334650.	
Lot #	19	
Qty	1	
Title	1973 BUTLER TANKER TRAILER	
Des.	FULL OPERATIONS NOT TESTED. Minimal Rust, Needs Tires, Two Compartments, Rear Axle Weight 5400 LBS, Trailer Capacity 6500 LBS. Location: Newberry, IN Serial: 3870310	
Lot #	20	
Qty	1	
Title	2014 KENWORTH T370 CAB & CHASSIS	
Des.	STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. Warning Lights On Dash, Misc. Parts On P/S Of Cab, Switches Missing From Center Of Dash, Rust Throughout. Mileage Unavailable. Location: McComb, MS Serial: 2NKHHJ7X6EM410914	
Lot #	21	
Qty	1	
Title	2005 STERLING LT9500 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Inside D/S Door Handle Is Broken, Windshield Is Chipped, Doors Have Been Swapped Previously. Showing 283,477 Miles; 26,619 Hours. Location: Des Moines, IA Serial: 2FZHAZDE26AW30144	








Lot #	23	
Qty	1	
Title	2019 INTERNATIONAL LT625 6X4 DAY CAB TRUCK	
Des.	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Engine Warning Light On Dash, Refill DEF Torque Derate 25% Warning Message Displayed, Batteries Will Need Replaced, Cracked Windshield, Rock Chips On Hood. Showing 629,753 Miles; 14,565 Hours. Location: Des Moines, IA Serial: 3HCDZAPR6KL118788	
Lot #	24	
Qty	1	
Title	2007 MACK CV713 CAB & CHASSIS	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. Missing Items, Including: Batteries, Bulldog Ornament, P/S Hood Mirror, D/S Seat, And Rear Inner Tires, Dash Apart On P/S, Odometer Cover Is Cracked. Mileage Unavailable. Location: Meridian, MS Serial: 1M2AG11C97M059853	
Lot #	25	
Qty	1	
Title	2005 STERLING LT9500 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Door Tags Missing- Serial Number Not Located. Showing 321,930 Miles; 31,849 Hours. Location: Des Moines, IA Serial: 2FZHAZDL25AU06241	
Lot #	26	
Qty	1	
Title	2017 MACK GU713 DUMP TRUCK	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. EATS System Fault Alert Warning Message Displayed On Dash, Reiten Dump Body, Body Information Tag Not Located. Showing 431,306 Miles; 15,677 Hours. Location: Des Moines, IA Serial: 1M2AX07C7HM036364	
Lot #	27	
Qty	1	
Title	2018 JOHN DEERE 444K WHEEL LOADER	
Des.	NOT TITLED PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. Hydraulic Oil Leak, Bucket Will Not Stay Up Due To Leaks. Showing: 17,198 Hours. Location: Marshville, NC Serial: 1DW444KZCJF689872	
Lot #	28	
Qty	1	
Title	2019 INTERNATIONAL LT625 6X4 DAY CAB TRUCK	
Des.	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Showing 653,772 Miles; 13,875 Hours. Location: Des Moines, IA Serial: 3HCDZAPR2KL118786	
Lot #	29	
Qty	1	
Title	2006 STERLING LT9500 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Engine Tag Not Located, McNeilus Rear Mixer Drum With 11 YD Capacity, Bar Broken On Grille, D/S Door Panel Broken Near Top, Holes Drilled Into Center Of Dash. Showing 297,381 Miles; 30,328 Hours. Location: Des Moines, IA Serial: 2FZHAZDL86AW30129	








Lot #	30	
Qty	1	
Title	2007 MACK CV713 CAB & CHASSIS	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Cab Has Been Painted, Missing Items, Including: Tag Axle Tires, Rear Inner Tires, Hood Mirrors, Gear Shift, Engine Fan, Radiator Support, And Various Engine Components, Dash Is Apart And Missing Components, Crack In Odometer Cover, Hoses Cut In Engine, Engine Tag Not Located. Mileage Unavailable. Location: McCrory, AR Serial: 1M2AG11C77M048897	
Lot #	31	
Qty	1	
Title	2007 PETERBILT 379 6X4 TRI AXLE DAY CAB TRUCK	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. ENGINE IS LOCKED UP, Oil Leak From Front Engine Seal And Oil Pan, Emblem Missing On R/S, Tires Worn, Interior Soiled, Body Damage Throughout. Showing 530,719 Miles; 530,719 ECM; 12,401 Hours. Location: East Wenatchee, WA Serial: 1XP5D40X47D689184	
Lot #	33	
Qty	1	
Title	2015 VOLVO VHD REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Oil Leaks From PTO, Rear Engine Seal, And Oil Pan, Engine And ABS Warning Lights On Dash, 6 Active Faults Found, Hood Fiberglass Is Chipped, Grille Broken On L/S, Bumper Is Bent And Dented. Showing 222,263 Miles; 23,721 Hours. Location: Converse, TX Serial: 4V5KC9DF4FN184891	
Lot #	34	
Qty	1	
Title	2019 INTERNATIONAL LT625 6X4 DAY CAB TRUCK	
Des.	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Showing 580,545 Miles; 12,901 Hours. Location: Des Moines, IA Serial: 3HCDZAPR1KL334645	
Lot #	35	
Qty	1	
Title	2011 FREIGHTLINER M2 106 CAB & CHASSIS	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. ABS And Brake Air Warning Lights On Dash, Freightliner Emblem, Hood Mirrors And Lower Piece Of Front Bumper Are Missing From Front End, D/S Headlight Is Out Of Place And Both Headlights Missing Molding, Rear Tires Are Singled Out, Tires Worn, HVAC Vents Have Been Removed From Dash, Climate Control Knob And Cup Holder Paneling Is Breaking Away From Dash On P/S, Rust Throughout. Showing 177,557 Miles; 1,338 Hours. Location: Cowan, TN Serial: 1FVACXBS0BDBD1821	
Lot #	36	
Qty	1	
Title	2013 JOHN DEERE 624K WHEEL LOADER	
Des.	NO TITLE PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. LEAKS OIL, SERVICE ALERTS INDICATOR AND TRANSMISSION INFORMATION INDICATOR, Surface Rust Noted Throughout Unit, Front Left Tire Has Cuts In The Sidewall, Entry Step Brackets Bent, Radio INOP, Showing 16,254 Hours. Location: Memphis, TN Serial: 1DW624KZHCE649960	








Lot #	37	
Qty	1	
Title	2015 VOLVO VHD REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. ENGINE DOES NOT STAY RUNNING, Oil Leaks From PTO Shaft And Oil Pan, DPF Fail Code Due To Faulty Exhaust After Treatment Fuel Supply, Engine And ABS Warning Lights On Dash, 3 Active Faults Found, Windshield Is Cracked, Interior Upholstery Is Soiled And Stained, Bumper Dented, Bent And Cracked. Showing 218,145 Miles; 20,742 Hours. Location: Converse, TX Serial: 4V5KC9DF9FN192260	
Lot #	38	
Qty	1	
Title	2013 CATERPILLAR P9000 FORKLIFT	
Des.	NO TITLE PER STATE REGULATIONS. STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. LP TANK TO BE REMOVED PRIOR TO SALE. Heavy Rust Throughout, Missing Floor Panel, Load Backrest Is Bent. Showing 16,989 Hours. Location: Des Moines, IA Serial: AT29D50237	
Lot #	39	
Qty	1	
Title	2019 INTERNATIONAL LT625 6X4 DAY CAB TRUCK	
Des.	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. BATTERIES WILL NEED REPLACED. Fault Code Warning Light On Dash. Showing 617,156 Miles; 13,554 Hours. Location: Des Moines, IA Serial: 3HCDZAPR7KL118783	
Lot #	40	
Qty	1	
Title	2007 VOLVO VHD84B CAB & CHASSIS	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. STOP ENGINE WARNING MESSAGE DISPLAYED ON DASH, CRANK-NO START, Rust Throughout, Gouges In Rear Tire, Interior Is Worn. Showing 593,958 Miles. Location: East Dublin, GA Serial: 4V5K99GG67N482962	
Lot #	41	
Qty	1	
Title	2014 VOLVO VHD REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Active Faults Detected, Including: DPF FAIL: SA 16 DTC U029E00- LOST COMMUNICATION WITH NOX SENSOR B, SA 16 DTC P113000-After Treatment Air Purge Valve Stuck On DEF System, Oil Leaks From Rear Engine Seal And Oil Pan, Check Engine Light On, Windshield Is Cracked, Bumper Dented, Grille Broken On L/S, Driver Door Has Rusted Hole, Beck Rear Mixer. Showing 207,131 Miles; 24,098 Hours. Location: Converse, TX Serial: 4V5KC9DFXEN175093	
Lot #	42	
Qty	1	
Title	2016 JOHN DEERE 326E SKID LOADER	
Des.	NOT TITLED PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. REAR WARNING LIGHTS AND TAILLIGHTS DO NOT WORK - THERE IS AN AFTER MARKET WARNING LIGHT ON THE REAR OF THE VEHICLE THAT WORKS WITH A CIGARETTE LIGHTER PLUG. There Is A Gap Between The Muffler And Exhaust Pipe In The Engine Compartment, Rubber Boot On Right Side Control Lever Is Torn, Scuffs Noted On Exterior Throughout Unit, Corner Is Bent On Right Side Lift Arm. Showing 8171 Hours. Location: Doswell, VA Serial: 1T0326EJCFJ290997	








Lot #	43	
Qty	1	
Title	2013 CATERPILLAR 2P5000 FORKLIFT	
Des.	NO TITLE PER STATE REGULATIONS. STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. LP TANK TO BE REMOVED PRIOR TO SALE. ENGINE RUN ON, Engine Congestion, Dash Display INOP, Rust Throughout, Broken Dash Panel To L/S Of Steering Wheel. Hours Unavailable. Location: Des Moines, IA Serial: AT3535134	
Lot #	44	
Qty	1	
Title	2019 INTERNATIONAL LT625 6X4 DAY CAB TRUCK	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing 532,715 Miles; 11,920 Hours. Location: Des Moines, IA Serial: 3HCDZAPR7KL334651	
Lot #	45	
Qty	1	
Title	2015 VOLVO VHD REAR MIXER	
Des.	NON RUNNER. FULL OPERATIONS NOT TESTED. BATTERIES DEAD. OIL LEAKAGE AROUND FRONT/REAR SIDE OF ENGINE. OIL PAN SEAL LEAKING. OIL RESIDUE/LEAKAGE ON TOP/RIGHT SIDE OF TRANSMISSION. 6 Tires Showing Wear, Right Side Of Grille Cracked/Broken, Dents And Scratches Throughout Unit, Left Side Inner Courtesy Light Lens Missing, Panel Around Air Brake Release Valve Missing, Windshield Cracked, Clean Idle Sticker Missing, Headliner Stained, Rear Wall Interior Stained/Damaged From Driver Seat. Mileage Unavailable. Location: Hockley, TX Serial:4V5KC9DF9FN913693	
Lot #	46	
Qty	1	
Title	2004 MACK RD688S CAB & CHASSIS	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, ECU IS MISSING, ENGINE APART-Components Are Missing And Some Parts Are In Cab, Mirrors And Grille Are Missing, Dash Apart, Rust Throughout. Mileage Unavailable. Location: Henderson, NC Serial: 1M2P267C44M067593	
Lot #	47	
Qty	1	
Title	2004 YALE GLP060TGEUAE087 FORKLIFT	
Des.	NO TITLE PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. Idles Rough, Leaks Oil. Showing 2,318 Hours. Location: Butler, KY Serial: A875B28771B	
Lot #	48	
Qty	1	
Title	2007 CASE 430 SKID LOADER	
Des.	NO TITLE PER STATE REGULATIONS. STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. MAIN DRIVE MOTORS AND PUMP ARE FAILING- Metal In System, Bucket Tilt INOP, Engine Tag Not Located, Warning Lights Illuminated, Rust And Body Damage Throughout. Showing 1,795 Hours. Location: Cleveland, OH Serial: N6M442385	
Lot #	49	
Qty	1	
Title	2014 KENWORTH T800 REAR MIXER	
Des.	NON RUNNER. FULL OPERATIONS NOT TESTED. BATTERIES ARE DEAD. Leaking Oil, Coolant Level Low, Oil Residue/Seepage From Power Steering, Tires Worn, Missing Clean Idle Sticker, Missing Left Side Inner Door Panel And Courtesy Light, Windshield Cracked, Scratches, Paint Chipping, And Rust Throughout. Location: Hockley, TX Serial: 1NKDLP0X1EJ417674	








Lot #	50	
Qty	1	
Title	2018 MACK CXU613 DAY CAB TRUCK	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Damage To Bumper And Paint Is Flaking. Showing 346,115 Miles; 12,885 Hours. Location: Des Moines, IA Serial: 1M1AW07YXJM088287	
Lot #	51	
Qty	1	
Title	2004 MACK RD688S CAB & CHASSIS	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, NO COOLANT IN ENGINE, Missing Items, Including: Alternator, Fuse And Relays, Windshield, P/S Interior Door Panel, Door Window Glass, Bulldog Ornament, HVAC, And ECU, Dash Is Apart, Grille Is Missing Bars, Rust Throughout. Mileage Unavailable. Location: Henderson, NC Serial: 1M2P296C54M067430	
Lot #	52	
Qty	1	
Title	1993 HYSTER S70XL2 FORKLIFT	
Des.	NO TITLE PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. Exhaust Needs Work. Showing 7,385 Hours. Location: Butler, KY Serial: D004V07176P	
Lot #	53	
Qty	1	
Title	2014 KENWORTH T800 REAR MIXER	
Des.	NON RUNNER. FULL OPERATIONS NOT TESTED. BATTERIES DEAD. Leaking Oil, Oil Residue/Seepage Around Rear Side Of Transmission, Paint Chips Around Headlights/Grille/Fenders, Tires Worn, Clean Idle Sticker Missing, Hood Latch Broken, Fenders Fiberglass Broken, Fender Panel Bent/Bolts Missing, Missing Door Panel And Courtesy Light, Interior Torn/Stained. Mileage Not Available. Location: Hockley, TX Serial: 1NKDLP0X7EJ417677	
Lot #	54	
Qty	1	
Title	2016 BOBCAT T770 COMPACT TRACK LOADER	
Des.	NO TITLE PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. L/S Track Has Gouged Tread, Rust And Body Damage Throughout. Showing 2,934 Hours. Location: Weatherford, TX Serial: AT6312821	
Lot #	55	
Qty	1	
Title	2000 MACK CH613 DAY CAB TRUCK	
Des.	STARTED ON SITE W/ FLUID, FULL OPERATIONS NOT TESTED. Interior Dirty And Worn, Holes In Floor. Showing 118,382.4 Miles; 26,400.1 Hours. Location: Des Moines, IA Serial: 1M1AA18Y0YW126000	
Lot #	56	
Qty	1	
Title	2005 MACK CV713 CAB & CHASSIS	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. AIR LEAK, Low Air Warning Light On Dash, Missing Bulldog Ornament And P/S Hood Vent Grille, Odometer Cover Is Cracked, Holes Drilled In Dash. Showing 784,161 Miles; 35,431 Hours. Location: Newark, NJ Serial: 1M2AG11C75M021339	








Lot #	57	
Qty	1	
Title	2017 PETERBILT 567 6X4 REAR MIXER	
Des.	STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. MISSING BATTERIES, Check Engine Warning Light On Dash, McNeilus Rear Mixer Drum Does Not Spin, Center Dash Is Broken, P/S Dash Is Missing Panel. Showing 143,456 Miles; 16,915 Hours. Location: Conroe, TX Serial: 1NPCXKEX4HD420559	
Lot #	58	
Qty	1	
Title	2003 YALE GLP050ZG FORKLIFT	
Des.	NO TITLE PER STATE REGULATIONS. STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Engine Idles Low And Rough And Dies Easily While Operating, Have To Use Throttle To Get Significant Movement, Engine Hour Meter Is Illegible. Hours Unavailable. Location: Henderson, KY Serial: A875B20712Z	
Lot #	60	
Qty	1	
Title	2011 INTERNATIONAL TRANSTAR 8600 DAY CAB TRUCK	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. Rear Tires Singled Out. Miles Unavailable. Location: Walford, IA Serial: 1HSHXSJR1BJ433676	
Lot #	61	
Qty	1	
Title	2018 PETERBILT 567 6X4 REAR MIXER	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. CRANKS- NO START, ABS, BRAKE AIR AND TRACTION CONTROL WARNING LIGHTS ON DASH, Primary Air Pressure Low Warning Message Displayed On Dash, Rear L/S Tire Seal Is Leaking, Body Damage To Front Grille, Crack In Center Dash, McNeilus Rear Mixer Drum. Showing 138,801 Miles. Location: Conroe, TX Serial: 1NPCXKEXXJD450428	
Lot #	62	
Qty	1	
Title	2012 FORD F450 CAB & CHASSIS	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Rust Throughout. Mileage Unavailable. Location: Attleboro, MA Serial: 1FDUF4GY6CEB51575	
Lot #	63	
Qty	1	
Title	2000 MCCLAIN E-Z PACK WALKING FLOOR TRAILER	
Des.	FULL OPERATIONS NOT TESTED. VIN Tag Not Located, Tears In Tarp, Rust And Dents Throughout, Approximate Measurements: 48 FT Length, 98.5 IN Width, 13 FT Height. Location: Elgin, IL Serial: 1M9BD4823Y2309050	
Lot #	64	
Qty	1	
Title	2011 LEDWELL LOWBOY TRAILER	
Des.	FULL OPERATIONS NOT TESTED. Approximate Measurements: 53 FT Overall Length, 26 FT Bed Length, 7 FT Beavertail Length, 108 IN Width. Location: Elkhorn, WI Serial: 1L9GA73A8BL033770	








Lot #	65	
Qty	1	
Title	2017 PETERBILT 567 REAR MIXER	
Des.	STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. DEAD BATTERIES, Check Engine And High Soot Level Warning Lights On Dash, McNeilus Rear Mixer W/ 11 YD Capacity. Showing 143,012 Miles; 3,004 Hours. Location: Conroe, TX Serial: 1NPCXKEX3HD420567	
Lot #	66	
Qty	1	
Title	2013 PETERBILT 365 DAY CAB TRUCK	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, MISSING TRANSMISSION, Headlights Have Been Removed And Tail Lights Are Damaged, Door Missing From P/S Rear Storage. Mileage Unavailable. Location: Lakeville, IN Serial: 1XPSDP9X2DD195828	
Lot #	67	
Qty	1	
Title	2007 MACK CTP713 CAB & CHASSIS	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. Rust And Body Damage Throughout, D/S Hood Vent Grille Missing, P/S Tail Lights Are Damaged. Mileage Unavailable. Location: Attleboro, MA Serial: 1M2AT04C77M005033	
Lot #	68	
Qty	1	
Title	2009 FORD F150 PICKUP TRUCK	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Multiple Warning Lights On Dash, Including: ABS, Brake System, Check Engine and Tire Pressure Low Warning. Showing 170,384 Miles. Location: Rochester, MN Serial: 1FTRF12W19KC52144	
Lot #	69	
Qty	1	
Title	2017 PETERBILT 567 REAR MIXER	
Des.	STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. AIR BAG UNIT FAULT WARNING MESSAGE DISPLAYED, CHECK ENGINE WARNING LIGHT ON, Center Dash Broken. Showing 163,954 Miles; 5,368 Hours. Location: Conroe, TX Serial: 1NPCXKEX1HD420583.	
Lot #	70	
Qty	1	
Title	2000 MCCLAIN E-Z PACK WALKING FLOOR TRAILER	
Des.	FULL OPERATIONS NOT TESTED. TARP IS MISSING, Tires Worn, Rust And Dents Throughout, Approximate Measurements: 48 FT Length, 98.5 IN Width, 13 FT Height. Location: Elgin, IL Serial: 1M9BD4825Y2309051	
Lot #	71	
Qty	1	
Title	2000 MACK CL713 DAY CAB TRUCK	
Des.	STARTED ON SITE W/JUMP, FULL OPERATIONS NOT TESTED. SPEEDOMETER REPLACED WITH 174,616 MILES. Batteries Tested Good, Shifts And Moves, ABS Light Is On, Air Builds And Brakes Release, Newer Tires On Front, Minimal Rust, Frame Solid, Missing Passenger Rear Mud Flap. Showing 41,261 Miles 56,710 Hours. Location: Ottawa Lake, MI Serial: 1M1AD62Y0YW009319	








Lot #	72	
Qty	1	
Title	2014 FREIGHTLINER M2 112 CAB & CHASSIS	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, COMPRESSED NATURAL GAS ENGINE- TANKS HAVE BEEN REMOVED, Engine Tag Not Located, Rear Tires Singled Out, Dash Components Missing On P/S. Mileage Unavailable. Location: Bardstown, KY Serial: 1FVHC5DX3EHFT0140	
Lot #	73	
Qty	1	
Title	2017 PETERBILT 567 6X4 REAR MIXER	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. ABS, Traction Control And Brake Air Warning Lights On Dash, Hood Will Not Open Due To Seized Hinge, Cracked Windshield, L/S Front Tire Has Leaking Seal. Showing 186,679 Miles. Location: Conroe, TX Serial: 1NPCXKEX3HD420584	
Lot #	74	
Qty	1	
Title	2005 OSHKOSH S2346 FRONT MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. TRUCK DOES NOT MOVE DUE TO KNOWN TRANSMISSION ISSUES, 5 Inactive Faults Detected- See ECM Report, Tires Worn, Steering Wheel Surfaces And Interior Side Panels Are Worn, Interior Moldings Are Cracked And Missing Pieces, Rust Noted. Showing 231,147 Miles; 233,603 ECM; 21,117 Hours. Location: Manchester, NH Serial: 10TFAAP255S085753	
Lot #	75	
Qty	1	
Title	1999 MCCLAIN E-Z PACK WALKING FLOOR TRAILER	
Des.	FULL OPERATIONS NOT TESTED. VIN Tag Not Located, Tears In Tarp, Rust Throughout, Approximate Measurements: 48 FT Length, 99 IN Width, 13 FT Height. Location: Elgin, IL Serial: 1M9BD4824X2309234	
Lot #	76	
Qty	1	
Title	2014 MACK CXU613 DAY CAB TRUCK	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. RADIATOR AND STEERING GEAR BOX ARE LEAKING AND NEED REPLACED, Air Restriction And Low Coolant Warning Lights On Dash, Rust Noted Throughout, Pin For Hood Safety Release Bent, Engine Tag Not Located. Showing 481,924 Miles; 16,858 Hours. Location: Coldwater, MI Serial: 1M1AW09Y7EM037638.	
Lot #	77	
Qty	1	
Title	2017 PETERBILT 567 6X4 REAR MIXER	
Des.	STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. LESS KEY, MISSING BATTERIES, Check Engine Warning Light And Call Truck Care Warning Message Displayed On Dash, McNeilus Rear Mixer Drum With 11 Cu Yd Capacity, Dash Is Broken Above Radio. Showing 145,329 Miles; 13,820 Hours. Location: Conroe, TX Serial: 1NPCXKEX7HD420569	
Lot #	78	
Qty	1	
Title	2013 FREIGHTLINER M2 112 CAB & CHASSIS	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Compressed Natural Gas Engine, Missing Items, Including: Dash Components, Engine Components, Tie Rod, D/S Hood Vent Grill, Hood Mirrors, And Rear Inner Tires, Dash Is Apart, Miscellaneous Parts Inside Of Cab. Mileage Unavailable. Location: Bardstown, KY Serial: 1FVXG1DX6DHFJ0875	







Lot #	79	
Qty	1	
Title	2018 ADDCO PTS2000 MASTER PORTABLE TRAFFIC SIGNAL SIGN BOARD	
Des.	NO TITLE PER STATE REGULATIONS. FULL OPERATIONS NOT TESTED. Portable Traffic Control Signals. Location: New Braunfels, TX Serial: 208324/1J9PT1419JD405545	
Lot #	80	
Qty	1	
Title	2018 FORD TRANSIT 350 VAN	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. TPMS Warning Light On Dash, Center Console Has Been Removed, Paint Damaged In Some Areas, Rear Interior Has Been Converted To A Wired Prisoner Containment Shell, Rust Throughout. Showing 131,519 Miles. Location: Des Moines, IA Serial: 1FTBW2YM9JKB37356	
Lot #	81	
Qty	1	
Title	2017 PETERBILT 567 REAR MIXER	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. CRANKS NO START, Warning Lights On Dash, Including: Check Engine, ABS, And Regen Warning, McNeilus Rear Mixer, Body Tag Not Located. Showing 183,742 Miles; 17,456 Hours. Location: Conroe, TX Serial: 1NPCXKEX8HD420550	
Lot #	82	
Qty	1	
Title	2014 MACK CXU613 CAB & CHASSIS	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Check Engine, ATC, ABS, And Electrical Malfunction Warning Lights On Dash, Rust Noted Throughout, Rear Tires Singled Out, Dash Menu Button INOP. Showing 718,927 Miles. Location: Coldwater, MI Serial: 1M1AW09Y3EM037619	
Lot #	83	
Qty	1	
Title	2007 MACK CTP713B CAB & CHASSIS	
Des.	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. DOES NOT DRIVE, BRAKES WILL NOT RELEASE, Low Voltage Warning Light On Dash, Missing Items, Including: Hood Mirrors, Bulldog Ornament, Mack Emblem On Grill, Rear Inner Tires, And Rear Poly Fenders, Cracks In Dash Above Steering Wheel, Evidence Of Rear Axle Hub Oil Leak On P/S, Rust Throughout. Showing 476,535 Miles; 40,337 Hours. Location: Lakeville, IN Serial: 1M2AT13C77M003208	
Lot #	84	
Qty	1	
Title	2018 ADDCO PTS2000 SLAVE PORTABLE TRAFFIC SIGNAL SIGN BOARD	
Des.	NO TITLE PER STATE REGULATIONS. FULL OPERATIONS NOT TESTED. Portable Traffic Control Signals. Location: New Braunfels, TX Serial: 208325	
Lot #	85	
Qty	1	
Title	2007 PETERBILT 357 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Engine And ABS Warning Lights On Dash, Transmission Box Control Has Busted Plastic On Top, Missing Heater Controls And P/S Seat, Schwing Rear Mixer Drum. Showing 192,961 Miles; 24,631 Hours. Location: Des Moines, IA Serial: 1NPAL50X07D675803	

Lot #	86	
Qty	1	
Title	2001 FORD E-250 VAN	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Rusty Bumper, Light Damage And Rust Noted Throughout Unit. Showing 92,445 Miles. Location: Des Moines, IA Serial: 1FTNS24L91HA76836	
Lot #	87	
Qty	1	
Title	2002 INTERNATIONAL 9100i 6X4 DAY CAB TRUCK	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. CRANK-NO START, STOP ENGINE WARNING LIGHT ON DASH, Known Transmission Problems, Rust Holes Noted In Cab Floor And Throughout, Dash Is Apart and Missing Components, Speedometer, RPM Tack, And Various Dash Functions INOP, Missing Mirrors, Blinker Lights, And Most Parts From Wet Kit. Mileage Unavailable. Location: Coldwater, MI Serial: 2HSCBAMR52C042379	
Lot #	88	
Qty	1	
Title	2007 MACK CV713 CAB & CHASSIS	
Des.	STARTED ON SITE w/JUMP. FULL OPERATIONS NOT TESTED. ABS Warning Light On Dash, Engine Tag Is Illegible, Hood, Fenders And Headlights Are Missing, Cab Steps Broken On D/S. Showing 691,543 Miles; 30,380 Hours. Location: Lakeville, IN Serial: 1M2AG11C57M065911	
Lot #	89	
Qty	1	
Title	2007 PETERBILT 357 REAR MIXER	
Des.	STARTED ON SITE W/JUMP, FULL OPERATIONS NOT TESTED. Missing Climate Controls And P/S Seat, Engine Tag Not Located, McNeilus Rear Mixer Drum. Showing 314,460 Miles; 4,142 Hours. Location: Des Moines, IA Serial: 1NPAL50X87D648719	
Lot #	90	
Qty	1	
Title	2019 ADDCO PTS2000 MASTER PORTABLE TRAFFIC SIGNAL SIGN BOARD	
Des.	NO TITLE PER STATE REGULATIONS. FULL OPERATIONS NOT TESTED. Missing Tail Lights. Location: New Braunfels, TX Serial: 208448/1J9PT1413KD405669	
Lot #	91	
Qty	1	
Title	2001 AMERICAN RESTROOM ENCLOSED TRAILER	
Des.	FULL OPERATIONS NOT TESTED. VIN Tag Not Located, Rust And Body Damage Throughout, Interior Soiled, Damage To Interior Ceiling, Approximate Measurements: 32 FT Body Length, 38 FT Overall Length, 96 IN Width, 10.5 FT Height. Location: Blue Springs, MO Serial: 1A9500R2611270122	
Lot #	92	
Qty	1	
Title	2012 MACK CXU613 DAY CAB TRUCK	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Check Engine Warning Light On Dash, Hood Is Damaged And Sitting Incorrectly, Quick Connects Are Missing From Pipes, Rust Noted. Showing 1,030,918 Miles; 27,910 Hours. Location: Cleveland, OH Serial: 1M1AW09Y1CM019701	

Lot #	93	
Qty	1	
Title	2007 PETERBILT 357 REAR MIXER	
Des.	STARTED ON SITE W/JUMP, FULL OPERATIONS NOT TESTED. Missing Climate Controls And P/S Seat, Engine Tag Not Located, McNeilus Rear Mixer Drum. Showing 356,745 Miles; 27,723 Hours. Location: Des Moines, IA Serial: 1NPAL50X87N648634	
Lot #	94	
Qty	1	
Title	2007 MACK CV713 CAB & CHASSIS	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. CRANKS-NO START, Engine Tag Illegible, R/S Rear Tire Has Mismatched Tread, Missing Items, Including: Headlights, Bulldog Ornament, Rear Inner Tires, Dash Apart On P/S, Rust Throughout. Showing 477,441 Miles; 39,619 Hours. Location: Lakeville, IN Serial: 1M2AG11C57M058134	
Lot #	95	
Qty	1	
Title	2004 STURDYWELD DS46TAL PUP DUMP TRAILER	
Des.	FULL OPERATIONS NOT TESTED. Regulator Cover Is Missing, Exterior And Tail Gate Are Scratched, Dented And Rusted, Approximate Capacity Of 33,001 LBS And Above. Location: Wapato, WA Serial: 5RETE04894S046117	
Lot #	96	
Qty	1	
Title	2001 AMERICAN RESTROOM ENCLOSED TRAILER	
Des.	FULL OPERATIONS NOT TESTED. Interior Ceiling Caving In, Flat Tires, Interior Soiled, VIN Tag Not Located, Approximate Measurements: 32 FT Body Length, 38 FT Overall Length, 96 In Width, 10.5 FT Height. Location: Blue Springs, MO Serial: 1A9500R2211270120	
Lot #	97	
Qty	1	
Title	2006 PETERBILT 357 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. McNeilus Rear Mixer Drum, Engine Tag Not Located, Climate Controls Missing From Dash. Showing 209,211 Miles; 7,924 Hours. Location: Des Moines, IA Serial: 1NPAL50X16D638080	
Lot #	98	
Qty	1	
Title	2015 MACK CXU613 DAY CAB TRUCK	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. HEAVY DAMAGE TO BODY, Missing Engine ECU. Mileage Unavailable. Location: East Dublin, GA Serial: 1M1AW09Y8FM045538	
Lot #	99	
Qty	1	
Title	2004 MACK CV713 CAB & CHASSIS	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. CRANKS BUT WILL NOT START, Warning Lights On Dash, Axle Weight Tag Is Illegible, Bulldog Ornament Missing, Rear Tires Are Singled Out And Wheel Missing On P/S Axle. Showing 663,211 Miles; 28,840 Hours. Location: Lakeville, IN Serial: 1M2AG11C54M014405	

Lot #	100	
Qty	1	
Title	1985 HOLDEN EQUIPMENT TRAILER	
Des.	NO TITLE PER STATE REGULATIONS. FULL OPERATIONS NOT TESTED. FLAT TIRES, Rust Throughout, Approximate Measurements: 14.1 FT Bed Length, 18.5 FT Shipping Length, 122 IN Wooden Deck Width, 76 IN Metal Deck Width, 3.4 FT Shipping Height, 2.1 FT Metal Deck Height, 3 FT Wooden Deck Height. Location: Des Moines, IA Serial: 850734	
Lot #	101	
Qty	1	
Title	2007 PETERBILT 357 REAR MIXER	
Des.	STARTED ON SITE. FULL OPERATIONS NOT TESTED. WILL NEED NEW BATTERIES. EXCESSIVE SMOKE. No Heater Controls, Missing Door Parts, Mixer Controls Missing, McNeilus Rear Mixer Drum, Showing 224,773 Miles And 2,710 Hours. Location: Des Moines, IA Serial: 1NPAL50X57D699580	
Lot #	102	
Qty	1	
Title	1993 GALBREATH AP-2A ROLLOFF TRAILER	
Des.	FULL OPERATIONS NOT TESTED. Missing Tail Lights And L/S Oil Hub Cap, Rust Throughout, Approximate Measurements: 22 FT Body Length, 32 FT Length, 96 IN Width. Location: Henderson, NC Serial: 1B9L1232XPB128643	
Lot #	103	
Qty	1	
Title	2007 VOLVO VNL64T DAY CAB TRUCK	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. FRONT ENGINE APART, ECU IS BAD, Tail Light And Mud Flaps Are Missing From Rear, D/S Interior Door Panel Is Missing, Switches Missing From Center Of Dash, Rust Throughout. Mileage Unavailable. Location: East Dublin, GA Serial: 4V4NC9GF37N461092	
Lot #	104	
Qty	1	
Title	2007 MACK CV713 CAB & CHASSIS	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Items Are Missing, Including: Fuel Cap On L/S Tank, Bulldog Ornament, P/S Mirror, D/S Far Left Tail Light And Reflector, And Components From P/S Of Dash. Mileage Unavailable. Location: Lakeville, IN Serial: 1M2AG12C97M065859	
Lot #	105	
Qty	1	
Title	2007 PETERBILT 357 REAR MIXER	
Des.	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. BRAKE PEDAL IS INOP, NO BRAKES, Engine Warning Light On Dash, Engine Tag Not Located, Peterbilt Emblem Is Missing From Hood, Rear Tires Are Singled Out, Missing P/S Seat McNeilus Rear Mixer Drum. Showing 140,122 Miles; 22,787 Hours. Location: Des Moines, IA Serial: 1NPAL50X87N648648	
Lot #	106	
Qty	1	
Title	2013 KENWORTH T300 DISTRIBUTOR TRUCK	
Des.	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. NEEDS BATTERIES, CHECK ENGINE WARNING LIGHT ON, Asphalt Build Up On Unit, Small Air Leak In Rear, Rust. Showing 108,877 Miles; 13,184 Hours. Location: Ottawa Lake, MI Serial: 2NKHLN9X4DM348477	

Lot #	107	
Qty	1	
Title	1992 CONVERTO PUP ROLLOFF TRAILER	
Des.	FULL OPERATIONS NOT TESTED. Jack Does Not Work Well, Rust Throughout, Approximate Measurements: 26.6 FT Shipping Length, 96 IN Shipping Width, 3.4 FT Shipping Height. Location: Wittenberg, WI Serial: 7499	
Lot #	108	
Qty	1	
Title	2012 VOLVO VNL64T DAY CAB TRUCK	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. BAD ECU, Hood Vent Grilles Are Missing On Both Sides, Switches Missing From Center Dash. Mileage Unavailable. Location: East Dublin, GA Serial: 4V4NC9EG1CN545952	
Lot #	109	
Qty	1	
Title	2005 MACK CV713 CAB & CHASSIS	
Des.	STARTED ON SITE W/JUMP, FULL OPERATIONS NOT TESTED. BRAKES WILL NOT RELEASE, Low Voltage Warning Light On Dash, Items Missing, Including: P/S Mirror, Bulldog Ornament, Switches From Center Dash, And Top Knob From Shifter. Showing 64,690 Miles; 33,894 Hours. Location: Lakeville, IN Serial: 1M2AG11C25M017800	
Lot #	110	
Qty	1	
Title	2012 WIL-RICH HIPPER ATTACHMENTS	
Des.	NO TITLE PER STATE REGULATIONS. FULL OPERATIONS NOT TESTED. Hoses Are Split And Rusted, Missing Tire And Remaining Tire Is Dry Rotted. Location: McCrory, AR Serial: 441449	
Lot #	111	
Qty	1	
Title	2012 FORD F450 SUPER DUTY FLATBED TRUCK	
Des.	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Rust Throughout, Engine Tag Not Located. Showing 238,505 Miles. Location: Lakeville, IN Serial: 1FDUF4GY4CEC56809	
Lot #	112	
Qty	1	
Title	WHISPERWATT DCA-25SSIU GENERATOR	
Des.	NO TITLE PER STATE REGULATIONS. STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Approximate Measurements: 12.5 FT Length, 74 IN Width, 5.4 FT Height. Showing 16,209.4 Hours. Location: Des Moines, IA Serial: 7103828	
Lot #	113	
Qty	1	
Title	2005 MACK CHN613 DAY CAB TRUCK	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. KNOWN ENGINE PROBLEMS, Low Air And ABS Warning Lights On Dash, Rear Tires Are Singled Out, Missing P/S Seat And P/S Interior Door Panel, Rust Throughout, Has Callahan Lift. Showing 766,223 Miles; 61,722 Hours. Location: East Dublin, GA Serial: 1M1AJ06Y55N001377	

Lot #	114	
Qty	1	
Title	2004 MACK CV713 CAB & CHASSIS	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. AIR PRESSURE IS NOT BUILDING TO RELEASE BRAKES, Low Air, ABS And Electrical Malfunction Warning Lights On Dash, Missing Items, Including: Headlights, Hood Mirrors, Bulldog Ornament, Tail Lights, Rear Inner Tires, And P/S Seat, Dash Missing Components On P/S. Showing 526,799 Miles; 48,014 Hours. Location: Lakeville, IN Serial: 1M2AG11CX4M010382	
Lot #	115	
Qty	1	
Title	1993 LINCOLN IDEALARC DC600 WELDER	
Des.	NOT TITLED PER STATE REGULATIONS. NON-RUNNER, FULL OPERATIONS NOT TESTED. Approximate Measurements: 2.5 FT Height (Welder Only), 22.25 IN Width, 39 IN Depth, 522 LBS Weight. Location: Walford, IA Serial: AC597834	
Lot #	117	
Qty	1	
Title	2007 UTILITY TS2CHA CURTAINSIDE VAN TRAILER	
Des.	FULL OPERATIONS NOT TESTED. Approximate Measurements: 53 FT Length, 102 IN Width, 12 FT 9 IN Height. Location: Morgantown, WV Serial: 1UYTS25377A022301	
Lot #	118	
Qty	1	
Title	2004 MACK CV713 DAY CAB TRUCK	
Des.	STARTED ON SITE, R/R FOUNDATION BRAKE RETURN SPRING BROKEN/MISSING, BRAKE SHOES OFF CAM, BINDING AGAINST BRAKE DRUM AND WHEEL ROTATION NOT OPERATIONAL. Engine Oil Leaks Noted At Oil Pan Railer, Drive Housing, Engine Coolant Low, Body Damage/Rust. Showing 628,850 Miles; 22,385 Hours. Location: Buckhannon, WV Serial: 1M2AG11Y64M014912	
Lot #	119	
Qty	1	
Title	2013 MACK GU813 CAB & CHASSIS	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. ABS Warning Light On Dash, Missing Items, Including: Hydraulic Tank For PTO, Bulldog Ornament And Rear Inner Tires. Showing 497,511 Miles; 16,085 Hours. Location: Collinsville, IL Serial: 1M2AX13C5DM021304	
Lot #	120	
Qty	1	
Title	1987 G&H 8540 FLATBED TRAILER	
Des.	FULL OPERATIONS NOT TESTED. VIN Tag Not Located, Rust Throughout, Approximate Measurements: 37 FT Shipping Length, 28 FT Bed Length, 96 IN Shipping Width, 4.2 FT Shipping Height. Location: Carnesville, GA Serial: 87070720	