




























## Printable Catalog








<b>Title</b>	FEBRUARY 14 12:00 CST
<b>Description</b>	Closing Times TBD
<b>Date</b>	Wed, Feb 14, 2024
<b>Starts at</b>	12:00 PM
<b>Address</b>	4747 NE 14th St, Des Moines, IA 50313 USA
<b>Categories</b>	








<b>Lot #</b>	1	
<b>Qty</b>	1	
<b>Title</b>	2016 VOLVO VHD REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. D/S Seat Is Taped Up, Beck Industrial Rear Mixer Drum With 10.5 YD Capacity. Showing 148,399 Miles; 17,169 Hours. Location: Converse, TX Serial: 4V5KC9DF7GN967964	
<b>Lot #</b>	3	
<b>Qty</b>	1	
<b>Title</b>	2014 MACK CHU613 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Bumper Dented. Showing 364,441 Miles; 17,265 Hours. Location: Des Moines, IA Serial: 1M1AN07YXEM016904	
<b>Lot #</b>	4	
<b>Qty</b>	1	
<b>Title</b>	2005 CHEVROLET SILVERADO 3500 FLATBED TRUCK	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Axle Weight Tag Not Located, Damaged Trim On Flatbed, Steering Column Missing Components. Mileage Unavailable. Location: Alvin, TX Serial: 1GBJC34U45E115483	
<b>Lot #</b>	5	
<b>Qty</b>	1	
<b>Title</b>	2011 INTERNATIONAL WORKSTAR 7400 SBA 6X4 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. Rear Tires Are Singled Out, Missing Items, Including: Mirrors, Headlights, Interior Components, Dash Apart, Rust Throughout. Mileage Unavailable. Location: Kingdom City, MO Serial: 1HTWGAZT7BJ291346	
<b>Lot #</b>	6	
<b>Qty</b>	1	
<b>Title</b>	2013 CLARK C30 FORKLIFT	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. NON-RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, No Power, Rust Throughout, Scratches, Scrapes And Peeling Paint, Fuse Box Cover Missing, Rubber Pad Of Break Pedal Missing, Rubber Pad Of Clutch Pedal Worn, Trim Cover Broken On Steering Column, Plate On Top Of Counterweight Is Bent. Hours Unavailable. Location: Newark, NJ. Serial: P232D00139882-MP	
<b>Lot #</b>	7	
<b>Qty</b>	1	
<b>Title</b>	2019 REITNOUER MAXMISER CURTAINSIDE VAN TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Some Damage To Front Plate Where Hook Ups Are, Approximate Measurements: 53 FT Length, 108 IN Width, 13.6 FT Height. Location: Lakeville, IN Serial: 1RNF53A24KR045581	








<b>Lot #</b>	8	
<b>Qty</b>	1	
<b>Title</b>	2013 MACK GU713 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Check Engine, Electrical Malfunction, And Coolant Level Low Warning Lights On Dash, Missing Items, Including: Bulldog Ornament, Grille, And D/S Hood Vent Grille, Holes Drilled Into Center Of Dash. Showing 302,247 Miles; 13,806 Hours. Location: Des Moines, IA Serial: 1M2AX04C2DM013878	
<b>Lot #</b>	9	
<b>Qty</b>	1	
<b>Title</b>	2014 VOLVO VHD REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Grille Is Missing, Beck Industrial Rear Mixer Drum With 10.5 YD Capacity. Showing 261,771 Miles; 22,428 Hours. Location: Converse, TX Serial: 4V5KC9DF4EN174232	
<b>Lot #</b>	10	
<b>Qty</b>	1	
<b>Title</b>	2018 MACK CXU613 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Showing 323,337 Miles; 12,040 Hours. Location: Des Moines, IA Serial: 1M1AW07Y2JM088283	
<b>Lot #</b>	12	
<b>Qty</b>	1	
<b>Title</b>	1973 GALION T-580A MOTOR GRADERS	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. Rust Throughout. Showing 858.2 Hours. Location: Greenville, OH Serial: CC-04952	
<b>Lot #</b>	13	
<b>Qty</b>	1	
<b>Title</b>	1993 OSHKOSH VAN TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Body Damage Throughout, Interior Walls Are Damaged, Approximate Measurements: 48 FT Length, 102 IN Width, 13.6 FT Shipping Height. Location: Blue Springs, MO Serial: 4MLT1482XPB768046	
<b>Lot #</b>	14	
<b>Qty</b>	1	
<b>Title</b>	2005 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. CRANK- No Start, Electrical Malfunction Warning Light On Dash, Engine Tag Is Illegible, Missing Items, Including: Bulldog Ornament, Hood Vent Grilles From Both Sides, And P/S Tail Light, Odometer Cover Cracked. Showing 542,049 Miles; 27,972 Hours. Location: Des Moines, IA Serial: 1M2AG11C15M030604	
<b>Lot #</b>	16	
<b>Qty</b>	1	
<b>Title</b>	2015 VOLVO VHD REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Beck Industrial Rear Mixer With 10.5 YD Capacity. Showing 190,858 Miles; 21,957 Hours. Location: Converse, TX Serial: 4V5KC9DF3FN192271	








<b>Lot #</b>	17	
<b>Qty</b>	1	
<b>Title</b>	2011 MACK GU713 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Missing Items, Including: Bulldog Ornament, Rear Inner Tires, And D/S Seat. Showing 528,553 Miles; 26,044 Hours. Location: Serial:	
<b>Lot #</b>	18	
<b>Qty</b>	1	
<b>Title</b>	2014 MACK CXU613 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing 427,261 Miles; 18,984 Hours. Location: Des Moines, IA Serial: 1M1AW07Y7EM037481	
<b>Lot #</b>	19	
<b>Qty</b>	1	
<b>Title</b>	1989 MONON MS3-30-ST-45W VAN TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. R/S Swing Door Is Missing, Body Damage And Rust Throughout, Approximate Measurements: 45 FT Body Length, 102 IN Width, 13.6 FT Shipping Height. Location: Blue Springs, MO Serial: 1NNVS4520KM133615	
<b>Lot #</b>	21	
<b>Qty</b>	1	
<b>Title</b>	2008 CATERPILLAR 216B SKID LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Arms And Bucket Attachment Are Missing. Hours Unavailable. Location: Buckeye, AZ Serial: CAT0216BPRLL07431	
<b>Lot #</b>	23	
<b>Qty</b>	1	
<b>Title</b>	2013 MACK GU813 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. WILL NOT CRANK, Chipped Windshield, Check Engine Warning Light On Dash, Wiper Fluid Low Warning Message Displayed, Rear Tires Singled Out And 2 Different Sizes, Missing Items, Including: Headlights, D/S Hood Vent Grille, Bulldog Ornament, Trim Components, And Engine Turbo Components, Interior Soiled. Showing 499,416 Miles; 7,348 Hours. Location: Des Moines, IA Serial: 1M2AX13C2DM019624	
<b>Lot #</b>	24	
<b>Qty</b>	1	
<b>Title</b>	2015 VOLVO VHD REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Check Engine Warning Light On Dash, Beck Industrial Rear Mixer Drum With 10.5 YD Capacity, D/S Interior Door Panel Missing Upper Components. Showing 197,936 Miles; 19,569 Hours. Location: Converse, TX Serial: 4V5KC9DF6FN192278	
<b>Lot #</b>	25	
<b>Qty</b>	1	
<b>Title</b>	2018 MACK CXU613 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing 358,154 Miles; 13,685 Hours. Location: Des Moines, IA Serial: 1M1AW07Y6JM088285	

<b>Lot #</b>	26	
<b>Qty</b>	1	
<b>Title</b>	2004 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Low Air And ABS Warning Lights On Dash, Engine Tag Not Located, Missing Items, Including: Bulldog Ornament, P/S Headlight, D/S Tail Lights, And D/S Interior Door Panel. Showing 462,092 Miles; 23,393 Hours. Location: Des Moines, IA Serial: 1M2AG11C24M010957	
<b>Lot #</b>	27	
<b>Qty</b>	1	
<b>Title</b>	2013 MAC DUMP TRAILER	
<b>Des.</b>	APPROXIMATE MEASUREMENTS 39 FT LENGTH, 96 IN WIDTH, FULL OPERATIONS NOT TESTED. Rear Door Missing. Location: Weatherford, TX Serial: 5MADN3927CD025807	
<b>Lot #</b>	28	
<b>Qty</b>	1	
<b>Title</b>	AXLE PARTS-HD	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. Pulled From 2010 Mack LEU613. Location: Martinsville, VA Serial: 19978	
<b>Lot #</b>	29	
<b>Qty</b>	1	
<b>Title</b>	2005 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. Engine Turns Over But Does Not Start, Low Air, ABS, And Electrical Malfunction Warning Lights On Dash, Missing Items, Including: Bulldog Ornament, Hood Vent Grille On Both Sides, Dash Components, Engine Components, Turbo, Top Of Shifter, And Tail Light On D/S, Steering Unattached From Truck. Showing 813,399 Miles; 35,273 Hours. Location: Des Moines, IA Serial: 1M2AG11C45M029463	
<b>Lot #</b>	30	
<b>Qty</b>	1	
<b>Title</b>	1996 BOBCAT 853 SKID LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, BUCKET ATTACHMENT IS MISSING, Serial And Engine Tags Not Located, Body Damage Throughout. Showing 532.9 Hours. Location: Buckeye, AZ Serial: 512821366	
<b>Lot #</b>	31	
<b>Qty</b>	1	
<b>Title</b>	2015 VOLVO VHD REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Check Engine Warning Light On Dash, Grille Is Missing, Beck Industrial Rear Mixer Drum With 10.5 YD Capacity. Showing 191,414 Miles; 18,693 Hours. Location: Converse, TX Serial: 4V5KC9DF4FN913701	
<b>Lot #</b>	32	
<b>Qty</b>	1	
<b>Title</b>	2003 KENWORTH T800 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. ENGINE TURNS OVER BUT DOES NOT START, Most D/S Tail Lights Are Missing, Components Missing And Holes Drilled Into Center Dash. Showing 969,193 Miles; 4,720 Hours. Location: Des Moines, IA Serial: 1NKDLB0X73J389508	








<b>Lot #</b>	33	
<b>Qty</b>	1	
<b>Title</b>	2017 MACK CXU613 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing 373,497 Miles; 15,681 Hours. Location: Des Moines, IA Serial: 1M1AW07Y2HM082994	
<b>Lot #</b>	34	
<b>Qty</b>	1	
<b>Title</b>	AXLE PARTS-HD	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. Pulled From 2012 Mack MRU613. Location: Martinsville, VA Serial: 20702	
<b>Lot #</b>	38	
<b>Qty</b>	1	
<b>Title</b>	2000 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Tail Lights Are Missing, Dash Is Taped On P/S, Rust Throughout. Showing 768,754 Miles; 7,582 Hours. Location: Rochester, MN Serial: 1M2P267C5YM048959	
<b>Lot #</b>	39	
<b>Qty</b>	1	
<b>Title</b>	2014 VOLVO VHD REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. STOP ENGINE WARNING LIGHT ON DASH, Low System Air Pressure Fault Message Displayed, Grille Missing, Beck Industrial Rear Mixer Drum With 10.5 YD Capacity. Showing 204,934 Miles; 23,568 Hours. Location: Converse, TX Serial: 4V5KC9DF8EN175092	
<b>Lot #</b>	40	
<b>Qty</b>	1	
<b>Title</b>	2017 MACK CXU613 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Scratch From Mirror Down. Showing 439,457 Miles; 15,141 Hours. Location: Des Moines, IA Serial: 1M1AW09Y8HM082995	
<b>Lot #</b>	41	
<b>Qty</b>	1	
<b>Title</b>	1998 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Front Left Fender Damage, Rust Throughout Frame And Wheels. Showing: 158,510 Miles; 940 Hours. Location: Rochester, MN Serial: 1M2P267C8WM036530	
<b>Lot #</b>	43	
<b>Qty</b>	1	
<b>Title</b>	1976 CATERPILLAR 980B WHEEL LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. UNABLE TO LIFT BOOM OR TILT BUCKET, Very Weak Hydraulics, Warning Lights On Dash, Damage and Cracks In Tire Treads, Rust Throughout. Showing 5,253 Hours. Location: Wittenberg, WI Serial: 89P4959	









<b>Lot #</b>	44	
<b>Qty</b>	1	
<b>Title</b>	2014 MACK GU813 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. Check Engine And Electrical Malfunction Warning Lights On Dash, Engine In Derate- Reduced Power Mode, Missing Items, Including: Valve Cover Bolts, Air Filter, Front Bumper, Mud Flaps, Damaged Radiator. Showing 357,519 Miles; 18,461 Hours. Location: Wittenberg, WI Serial: 1M2AX13C3EM025286	
<b>Lot #</b>	47	
<b>Qty</b>	1	
<b>Title</b>	2014 KENWORTH T400 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Check Engine, Stop Engine And Coolant Level Low Warning Lights On Dash, Engine Parts Removed And In Cab, P/S Tail Light Is Missing, Dash Apart. Showing 327,085 Miles; 15,746 Hours. Location: Wittenberg, WI Serial: 1NKBX2EX0EJ401585	
<b>Lot #</b>	48	
<b>Qty</b>	1	
<b>Title</b>	2018 MACK CXU613 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Showing 243,967 Miles; 7,780 Hours. Location: Des Moines, IA Serial: 1M1AW07Y3JM088289	
<b>Lot #</b>	49	
<b>Qty</b>	1	
<b>Title</b>	AXLE PARTS-HD	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. Pulled From 2010 Mack MRU613. Location: Martinsville, VA Serial: 12088	
<b>Lot #</b>	50	
<b>Qty</b>	1	
<b>Title</b>	2008 KENWORTH T800 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, NO CRANK, D/S Seat And Side Mirrors Are Missing, Front Tires Are Flat, Center Dash Panel Is Disconnected. Mileage Unavailable. Location: Wittenberg, WI Serial: 1NKDLU0X58J213396	
<b>Lot #</b>	52	
<b>Qty</b>	1	
<b>Title</b>	2014 FREIGHTLINER CASCADIA 125 6X4 SLEEPER TRUCK	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. ENGINE IS LOCKED UP, SERPENTINE BELT IS OFF OF ENGINE, Scuffed Paint On P/S Fender. Showing 930,504 Miles. Location: Harrisburg, PA Serial: 3AKJGLD50ESFY2176	
<b>Lot #</b>	53	
<b>Qty</b>	1	
<b>Title</b>	2007 FREIGHTLINER M2 112 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. STARTER IS INOP, Heavy Coolant Leak Reported, Items Missing, Including: Both Headlights, Both Hood Mirrors, P/S Mud Flap Bracket And Mud Flap, Misc. Parts In Cab, Body Damage Throughout. Showing 443,839 Miles. Location: Wittenberg, WI Serial: 1FVMC7CV77HW57984	








<b>Lot #</b>	54	
<b>Qty</b>	1	
<b>Title</b>	2014 VOLVO VHD REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Check Engine Warning Light On Dash, Oil Leak From Rear Engine Seal And PTO, Windshield Is Cracked On D/S, Missing Items, Including: Grille And Volvo Emblem, P/S Seat, Misc. Parts In Cab. Showing 225,281 Miles; 23,285 Hours. Location: Luling, TX Serial: 4V5KC9DF6EN156721	
<b>Lot #</b>	55	
<b>Qty</b>	1	
<b>Title</b>	2000 MACK CH613 DAY CAB TRUCK	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. Missing Hood Mirrors, Dash Apart On P/S, Rust Throughout. Showing 445,540 Miles; 24,814 Hours. Location: Elkhorn, WI Serial: 1M1AA13Y5YW125156	
<b>Lot #</b>	57	
<b>Qty</b>	1	
<b>Title</b>	AXLE PARTS-HD	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. Pulled From 2010 Mack MRU613. Location: Martinsville, VA Serial: 19660	
<b>Lot #</b>	58	
<b>Qty</b>	1	
<b>Title</b>	2007 TRAVIS WALKING FLOOR TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. LEAF SPRING IS CRACKED IN HALF, Approximate Measurements: 48 FT Shipping Length, 100 IN Shipping Width, 12 FT 11 IN Shipping Height. Location: Wittenberg, WI Serial: 48XAR494171005445	
<b>Lot #</b>	59	
<b>Qty</b>	1	
<b>Title</b>	2013 FORD F350 4X4 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. NO BATTERY, Missing Items, Including: Front End Assembly, Grille Assembly, Headlight Assemblies, Hood, Fenders, P/S Interior Door Panel, Interior Components And Bed, Windshield Is Cracked. Mileage Unavailable. Location: Kalkaska, MI Serial: 1FD8W3H69DEA52355	
<b>Lot #</b>	60	
<b>Qty</b>	1	
<b>Title</b>	2002 INTERNATIONAL F2654 VAC TRUCK	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. DEAD BATTERIES, Oil Leak At Front And Rear Of Oil Pan, Rear Tail Light Is Loose, Hole In D/S Rubber Floor Mat, Interior Soiled And Trash Left Behind, Headliner Is Dirty And Sagging, Rust Throughout. Showing 124,549 Miles; 7,680 Hours. Location: Kalkaska, MI Serial: 1HTGHADT12H502167	
<b>Lot #</b>	61	
<b>Qty</b>	1	
<b>Title</b>	2014 VOLVO VHD REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Grille Trim, Oil Fill Cap And P/S Seat Are Missing, Windshield Is Cracked, Oil Leak From PTO, D/S Door Has Broken Key Hole, Engine Tag Illegible, Beck Industrial Rear Mixer Drum With 10.5 YD Capacity. Showing 220,007 Miles; 21,705 Hours. Location: Luling, TX Serial: 4V5KC9DF0EN172395	








<b>Lot #</b>	62	
<b>Qty</b>	1	
<b>Title</b>	2008 MACK GU713 CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Door Pin Missing Will Not Latch, Dash Partially Removed. Showing: Miles/Hours Unavailable. Location: Courtice, ON Serial: 1M2AX07C18M002288	
<b>Lot #</b>	63	
<b>Qty</b>	1	
<b>Title</b>	2002 MACK CH613 DAY CAB TRUCK	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. CRACK IN ENGINE BLOCK, D/S Cab Steps Are Bent, Engine Tag Is Illegible, Dash Apart On P/S, Rust Throughout. Mileage Unavailable. Location: Elkhorn, WI Serial: 1M1AA18Y42W148590	
<b>Lot #</b>	65	
<b>Qty</b>	1	
<b>Title</b>	2014 FREIGHTLINER M2 112 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Compressed Natural Gas Engine- Tanks Have Been Drained And Removed, Engine Tag Not Located, Hood Mirrors Are Missing, Rear Tires Singled Out, Body Damage Throughout. Mileage Unavailable. Location: Bardstown, KY Serial: 1FVXG1DX9DHFJ0871	
<b>Lot #</b>	66	
<b>Qty</b>	1	
<b>Title</b>	1986 MACK R686ST VAC TRUCK	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. DEAD BATTERIES, Oil Leak Noted On P/S And Rear Of Engine, Rust Noted Throughout, Broken Dash, Tires Worn. Showing 278,977 Miles. Location: Kalkaska, MI Serial: 1M2N179YXGA001791	
<b>Lot #</b>	67	
<b>Qty</b>	1	
<b>Title</b>	2004 TRAVIS S/102 WALKING FLOOR TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Holes Noted On Sides, Tarp Is Missing, Rust Throughout, Approximate Measurements: 48 FT Length, 98 IN Width, 12.10 FT Shipping Height. Location: Wittenberg, WI Serial: 48XAR504741002726	
<b>Lot #</b>	68	
<b>Qty</b>	1	
<b>Title</b>	2005 MACK RD690S CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Center Of Steering Wheel Missing, Body Damage And Rust Throughout. Showing 593,230 Miles; 39,004 Hours. Location: Harrisburg, PA Serial: 1M2AG11C15M020672	
<b>Lot #</b>	69	
<b>Qty</b>	1	
<b>Title</b>	2014 VOLVO VHD REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Cracked Windshield, Oil Leaking From PTO And Oil Pan, DPF Fail, Steps Have Broken Weld, Missing Items, Including: Volvo Emblem, Grille Trim, Hood Mirrors, P/S Seat, Misc. Parts In Cab, Beck Industrial Rear Mixer Drum With 10.5 YD Capacity. Showing 217,055 Miles; 24,269 Hours. Location: Luling, TX Serial: 4V5KC9DF4EN172397	



<b>Lot #</b>	70	
<b>Qty</b>	1	
<b>Title</b>	1988 MACK RW753 DAY CAB TRUCK	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. DEAD BATTERY, Oil Leak From P/S Of Oil Pan And Rear Engine Seal, Rear Of Transmission, And Front Of Differential, Headliner Is Loose And Stained, Tires Are Worn. Showing 125,927 Miles. Location: Kalkaska, MI Serial: 1M2AY38Y5JM001451	
<b>Lot #</b>	73	
<b>Qty</b>	1	
<b>Title</b>	2001 INTERNATIONAL 4700 4X2 VAC TRUCK	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, WRECKED AND HAS FRAME DAMAGE, Hood Does Not Open, Missing Items, Including: Rear Differential, Rear Axle, And D/S Door Latch, 2000 Glendale Welding Co. Vac Attachment. Showing 355,551 Miles; 2,474 Hours. Location: Buckeye, AZ Serial: 1HTSCAAL81H355602	
<b>Lot #</b>	75	
<b>Qty</b>	1	
<b>Title</b>	2021 COTTRELL ROLLBACK BODY	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. FULL OPERATIONS NOT TESTED. 2021 Cottrell Roll Off Trailer- Bed Only. Location: Summerville, SC Serial: G001660906	
<b>Lot #</b>	76	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CT713 REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. ABS Warning Light On Dash, McNeilus Rear Mixer Drum With 11 YD Capacity, Dried Concrete On Body. Showing 200,547 Miles; 42,660 Hours. Location: Des Moines, IA Serial: 1M2AL02C77M003172	
<b>Lot #</b>	77	
<b>Qty</b>	1	
<b>Title</b>	2022 ISUZU NRR CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Missing Diesel Fuel Cap. Showing 90,555 Miles. Location: Summerville, SC Serial: JALE5W164N7300232	
<b>Lot #</b>	78	
<b>Qty</b>	1	
<b>Title</b>	2007 INTERNATIONAL 9200i SBA 6X4 DAY CAB TRUCK	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, NO CRANK, R/S Rear Tire Is Flat, Belt Missing From Engine, D/S Hood Mirror And Rear Mud Flaps Are Missing, Dash Apart On P/S. Mileage Unavailable. Location: Alvin, TX Serial: 2HSCEAHR87C463702	
<b>Lot #</b>	79	
<b>Qty</b>	1	
<b>Title</b>	2009 SURE-TRAC UTILITY TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. R/S Front Tire Is Missing And R/S Rear Tire Is Flat And Off Bead, Rust Throughout, VIN Tag Not Located, Approximate Measurements: 23.5 FT Shipping Length, 102 IN Shipping Width, 7.8 FT Shipping Height. Location: Des Moines, IA Serial: 5JWU202491023569	

<b>Lot #</b>	81	
<b>Qty</b>	1	
<b>Title</b>	2001 BENLEE 4ALROP25 ROLLOFF TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Tires Worn, Rust Noted On Frame, Wheels And Axles, Approximate Measurements: 20 FT Length. Location: Kalkaska, MI Serial: 1B9N125481B180805	
<b>Lot #</b>	82	
<b>Qty</b>	1	
<b>Title</b>	1999 CUSCO VAC TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Missing 16 Wheels And Tires Across 6 Axles, Rust Noted Throughout, Approximate Measurements: 53 FT Length. Location: Kalkaska, MI Serial: 2C9T05468XC005100	
<b>Lot #</b>	84	
<b>Qty</b>	1	
<b>Title</b>	2002 LINCOLN SA-250 ARC WELDER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. NON RUNNER, FULL OPERATIONS NOT TESTED. Exterior Damage Throughout, Perkins KR70418U Engine. Showing 2,403 Hours. Location: Buckeye, AZ Serial: U1020627517	
<b>Lot #</b>	85	
<b>Qty</b>	1	
<b>Title</b>	2005 STERLING AT9500 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. DASH IS BROKEN, Brake Warning Light On Dash, Front End Damage. Showing 325,616 Miles; 15,812 Hours. Location: Converse, TX Serial: 2FWJA3DE25AV18700	
<b>Lot #</b>	86	
<b>Qty</b>	1	
<b>Title</b>	2006 GMC C5500 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Dash Apart On P/S, Various Rust Throughout. Mileage Unavailable. Location: Cowan, TN Serial: 1GDE5C1226F401785	
<b>Lot #</b>	88	
<b>Qty</b>	1	
<b>Title</b>	2022 ISUZU NRR CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing 104,808 Miles. Location: Summerville, SC Serial: JALE5W168N7300086	
<b>Lot #</b>	89	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. Missing Items, Including: Bulldog Ornament, Engine Components, Some Tail Lights, And Center Of Steering Wheel, Rust Throughout. Mileage Unavailable. Location: Carnesville, GA Serial: 1M2AG11C66M034875	
<b>Lot #</b>	90	
<b>Qty</b>	1	
<b>Title</b>	2000 LINCOLN SA-250 ARC WELDER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. NON RUNNER, FULL OPERATIONS NOT TESTED. Damage Throughout, Perkins CE70262 Engine. Showing 1,887 Hours. Location: Buckeye, AZ Serial: U1000702606	

<b>Lot #</b>	92	
<b>Qty</b>	1	
<b>Title</b>	1998 FORD AT9513 LUBE TRUCK	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. DEAD BATTERIES, Oil Leak Reported At Front Of Engine, Between Engine And Transmission, And Rear Of Oil Pan, Hood And Bumper Are Damaged On D/S, Headliner Is Dirty And Sagging, Tires Worn, Rust Throughout. Showing 600,825 Miles. Location: Kalkaska, MI Serial: 1FTYY96B6WVA21780	
<b>Lot #</b>	94	
<b>Qty</b>	1	
<b>Title</b>	JOHN DEERE 640 BUCKET ATTACHMENTS	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. FULL OPERATIONS NOT TESTED. VIN Tag Is Illegible, Approximate Measurements: 11.75 FT Length, 74 IN Width. Location: Des Moines, IA Serial: 105703	
<b>Lot #</b>	95	
<b>Qty</b>	1	
<b>Title</b>	2010 VOLVO VNL64T CAB & CHASSIS	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. BAD BATTERIES, MOTOR LOCKED UP, Windshield Is Cracked, Only 1 Fuel Tank On P/S, Rust And Body Damage Throughout. Mileage Unavailable. Location: Luling, TX Serial: 4V5NC9EGXAN287956	
<b>Lot #</b>	96	
<b>Qty</b>	1	
<b>Title</b>	1999 LINCOLN SA-250 ARC WELDER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. NON RUNNER, FULL OPERATIONS NOT TESTED. Damage Throughout. Showing 5,610 Hours. Location: Buckeye, AZ Serial: U1990606432	
<b>Lot #</b>	97	
<b>Qty</b>	1	
<b>Title</b>	2007 PETERBILT 357 CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Dash De-assembled, Rust Throughout Unit. Showing: Mileage/Hours Unavailable. Location: Weatherford, TX Serial: 1NPAL00X77D744599	
<b>Lot #</b>	98	
<b>Qty</b>	1	
<b>Title</b>	1989 FREIGHTLINER FLD120 LUBE TRUCK	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. DEAD BATTERIES, Oil Leak Noted Around Oil Pan, Hood Damage Is Noted, Rear Tire Has Damaged Side Wall, Headliner Is Stained And Sagging, Rust Throughout. Showing 6,745 Miles; 26,213 Hours. Location: Kalkaska, MI Serial: 1FUZYCYB1KH341872	
<b>Lot #</b>	99	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Dash De-Assembled, Rust Throughout Unit. Showing: Mileage/Hours Unavailable. Location: Weatherford, TX Serial: 1M2AG11C37M067527	

<b>Lot #</b>	100	
<b>Qty</b>	1	
<b>Title</b>	JOHN DEERE FORKS ATTACHMENTS	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. FULL OPERATIONS NOT TESTED. VIN TAG NOT LOCATED, Rust Throughout, Approximate Measurements: 4.17 FT Length, 49 IN Width. Location: Des Moines, IA Serial: 80070	
<b>Lot #</b>	101	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Dash De-assembled, Rust Throughout Unit. Showing: Mileage/Hours Unavailable. Location: Weatherford, TX Serial: 1M2AG11C87M038993	
<b>Lot #</b>	102	
<b>Qty</b>	1	
<b>Title</b>	1989 LINCOLN SA-250 ARC WELDER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. NON RUNNER, FULL OPERATIONS NOT TESTED. Lincoln SA-250 Arc Welder With Perkins Engine. Hours Unavailable. Location: Buckeye, AZ Serial: A1153677	
<b>Lot #</b>	103	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CTP713B CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Hood Missing, Dash De-assembled, Rust Throughout Unit. Showing: Mileage/Hours Unavailable. Location: Weatherford, TX Serial: 1M2AT13C27M003102	
<b>Lot #</b>	104	
<b>Qty</b>	1	
<b>Title</b>	GARDNER DENVER AIR COMPRESSOR	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. NON RUNNER, FULL OPERATIONS NOT TESTED. Tires Are Missing, Serial Tag Not Located. Showing 5,822 Hours. Location: Buckeye, AZ Serial: 722116	
<b>Lot #</b>	105	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. Warning Lights On Dash, Rear Tires Are Singled Out, Missing Items, Including: Grille, Bulldog Ornament, D/S Hood Vent Grille, D/S Rear Mud Flap, Switches From Dash And Steering Wheel Center. Showing 650,141 Miles; 35,810 Hours. Location: Commerce City, CO Serial: 1M2AG11C16M035450	
<b>Lot #</b>	106	
<b>Qty</b>	1	
<b>Title</b>	1999 FORD F250 EXT CAB PICKUP TRUCK	
<b>Des.</b>	NON RUNNER, FULL OPERATIONS NOT TESTED. Roof Is Rusted Out Above Windshield, Tail Gate Has Been Replaced And Is Missing Trim, D/S Rear Tire Is Flat And Damaged. Showing 230,821 Miles. Location: Buckeye, AZ Serial: 1FTNX20L3XEE66090	

---

**Lot #** 107  
**Qty** 1  
**Title** FLYGT 5700W WELL PUMP  
**Des.** NO TITLE PER STATE REGULATIONS. FULL OPERATIONS NOT TESTED. Approximate Measurements: 31.25 FT Length, 20 IN Opening. Location: Des Moines, IA Serial: 2102040-9600



---

**Lot #** 108  
**Qty** 1  
**Title** 1998 GMC C7500 FUEL & LUBE TRUCK  
**Des.** NON RUNNER, FULL OPERATIONS NOT TESTED. Dash Apart And Components Are Missing, Valew Lube Truck Body, Various Rust Throughout. Showing 159,889 Miles. Location: Buckeye, AZ Serial: 1GDM7H1J9WJ850064

