





























Printable Catalog








Title	MARCH 13 12:00 CST
Description	Closing Times TBD
Date	Wed, Mar 13, 2024
Starts at	12:00 PM
Address	4747 NE 14th St, Des Moines, IA 50313 USA
Categories	








Lot #	1	
Qty	1	
Title	2007 MACK CTP713 REAR MIXER	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. KNOWN ENGINE ISSUES, Low Brake System Air Pressure Warning Message Displayed On Dash, Drive Shaft Removed And With Truck, McNeilus Rear Mixer Drum With 10.5 YD Capacity. Showing 197,905 Miles. Location: Raleigh, NC Serial: 1M2AT04C97M006717	
Lot #	2	
Qty	1	
Title	2012 PETERBILT 348 CAB & CHASSIS	
Des.	NON-RUNNER, FULL OPERATIONS NOT TESTED. Warning Lights On, Chrome On Grille Peeling. Showing: Mileage/Hours Unavailable. Location: BLUE SPRINGS, MO Serial: 2NP3LN0X4CM149249	
Lot #	3	
Qty	1	
Title	2014 CHEVROLET 2500 HD SILVERADO 4X4 CREW CAB PICKUP TRUCK	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Paint Chips On The Hood, L/S Bumper Dented, Bent, And Chrome Peeling, Tail Gate Scratched, Rust Visible, Scratches And Scrapes Throughout, Steering Wheel Worn, Brake Pedal Pad Missing. Showing: 123,932 Miles. Location: Lakeland, WA. Serial: 1GC1KVCG0EF179004.	
Lot #	4	
Qty	1	
Title	2017 PETERBILT 365 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing: 82,633 Miles; 8,667 Hours. Location: Zebulon, NC Serial: 1NPSL70X0HD447995	
Lot #	5	
Qty	1	
Title	2005 MACK CV713 CAB & CHASSIS	
Des.	NON-RUNNER, FULL OPERATIONS NOT TESTED. Rust Throughout Unit. Showing: Mileage/Hours Unavailable. Location: BLUE SPRINGS, MO Serial: 1M2AG11C75M017811	
Lot #	6	
Qty	1	
Title	2007 MACK CV513 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. DRUM WILL NOT TURN, Low Air Warning Light On Dash, Missing Items, Including: Bulldog Ornament, P/S Hood Vent Grille, And Fill Plug For Mixer Gear Box, Continental Rear Mixer Drum With 11 YD Capacity. Showing 143,679 Miles; 19,927 Hours. Location: Raleigh, NC Serial: 1M2AG02C77M003192	








Lot #	7	
Qty	1	
Title	2011 PETERBILT 389 DAY CAB TRUCK	
Des.	STARTED ON SITE W/JUMP POST INSPECTION, FULL OPERATIONS NOT TESTED. 2 Active Faults/ 3 Inactive Faults - See ECM Report, Tires Worn. Showing: 576,177 Miles; 576,178 EMC; 184,417 Hours. Location: St Cloud, MN. Serial: 1XPXPBEX3BD116508.	
Lot #	9	
Qty	1	
Title	2017 PETERBILT 365 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Check Engine Light On. Showing: 88,558 Miles; 9,019 Hours. Location: Zebulon, NC Serial: 1NPSL70X6HD447998	
Lot #	10	
Qty	1	
Title	2011 FORD F250 XL PICKUP TRUCK	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Oil Leakage Around The Oil Pan Seal, L/S Of Bed Has A Large Dent/Scratches, L/S Bumper Bend Down, R/S Bumper Scratched/Dented, Tailgate Dented And Scratched, R/R Wheel Is Mismatched (Black), Steering Wheel Worn. Showing: 179,685 Miles. Location: Lakeland, MN. Serial: 1FTBF2AT1BEC07305.	
Lot #	11	
Qty	1	
Title	2005 INTERNATIONAL PAYSTAR 5600 6X4 REAR MIXER	
Des.	STARTED ON SITE W/JUMP, FULL OPERATIONS NOT TESTED. Hole In The Mixer Drum, Engine Skip, Oil Leaks, Broken Battery Cable, Missing Body Tag, Scrapes/Scratches Throughout, Rust Visible. Showing: 243,843 Miles; 29,072 Hours. Location: Duluth, GA. Serial: 1HTXHAHT55J139802.	
Lot #	12	
Qty	1	
Title	2008 FREIGHTLINER M2 CAB & CHASSIS	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Warning Lights On. Showing: 553,969 Miles; 29,847 Hours. Location: Sacramento, CA Serial: 1FVHC5CV38HZ21953	
Lot #	13	
Qty	1	
Title	2005 STERLING LT9500 DAY CAB TRUCK	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. TRANSMISSION STUCK IN HIGH GEAR, Oil Leak From The Oil Pan, Power Steering Is Leaking From Gear Box, Dash Is Cracked And Held Up By A Bungee Cord, VIN Tag Illegible, Body Damage Throughout. Mileage Unavailable. Location: Mankato, MN Serial: 2FWJAZDE65AV37463	
Lot #	14	
Qty	1	
Title	2017 PETERBILT 365 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Check Engine Light On. Showing: 85,914 Miles; 9,088 Hours. Location: Zebulon, NC Serial: 1NPSL70X9HD448000	









Lot #	15	
Qty	1	
Title	2007 MACK CTP713 CAB & CHASSIS	
Des.	NON-RUNNER, FULL OPERATIONS NOT TESTED. Outer Wheels Only, Rust Throughout Unit. Showing: Mileage/Hours Unavailable. Location: DES MOINES, IA Serial: 1M2AT04C87M003727	
Lot #	16	
Qty	1	
Title	2005 INTERNATIONAL PAYSTAR 5600 6X4 REAR MIXER	
Des.	STARTED ON SITE W/JUMP, FULL OPERATIONS NOT TESTED. Hard Starting, Front Bumper Bent, Paint Scratched, Rust Visible, Warning Lights On, McNeilus Drum - 10.5 Cubic Yard Capacity. Showing: 232,139 Miles; 26,176 Hours. Location: Duluth, GA. Serial: 1HTXHAHT75J028068.	
Lot #	17	
Qty	1	
Title	2009 FORD F250 SUPER DUTY 4X4 PICKUP TRUCK	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. TPMS Warning Light On Dash, Oil Leak Reported, Body Damage And Rust Noted Throughout, Eagle Lift Gate On Rear. Showing 135,795 Miles. Location: Des Moines, IA Serial: 1FTSF21R09EA90783	
Lot #	18	
Qty	1	
Title	2012 MACK GU813 CAB & CHASSIS	
Des.	NON-RUNNER, FULL OPERATIONS NOT TESTED. Rust Throughout Frame And Wheels. Showing: 481,072 Miles. Location: Elk Horn, WI Serial: 1M2AX13C9CM017853	
Lot #	19	
Qty	1	
Title	2017 PETERBILT 365 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Coolant Light On. Showing: 87,352 Miles; 9,750 Hours. Location: Zebulon, NC Serial: 1NPSL70X8HD447999	
Lot #	20	
Qty	1	
Title	2005 MACK CX613 DAY CAB TRUCK	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Tank On Passenger Side Is For Hydraulic Oil, Fifth Wheel Is Laying On The Back Of The Frame. Showing: 457,323 Miles; 19,406 Hours. Location: COLLINSVILLE, IL Serial: 1M1AE06Y85N022440	
Lot #	21	
Qty	1	
Title	2008 INTERNATIONAL PAYSTAR 5600 6X4 REAR MIXER	
Des.	NON-RUNNER, FULL OPERATIONS NOT TESTED. Computer Hardness Disconnected, Missing: Fuel Cap, Wipers, Misc Dash Items, Air Filter, Cam Sensors, Rear Remote. Showing: Mileage/Hours Unavailable. Location: Byron, GA Serial: 1HTXHAHT18J690796	








Lot #	22	
Qty	1	
Title	2003 MACK CV713 CAB & CHASSIS	
Des.	NON-RUNNER, FULL OPERATIONS NOT TESTED. Turns Over But Will Not Start. Showing: 382,984 Miles.	
Lot #	23	
Qty	1	
Title	2009 FORD F-350 4X4 PICKUP TRUCK	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Lift Gate INOP, Severe Rust And Body Damage Noted, Wench On Front End. Showing 219,308 Miles. Location: Des Moines, IA Serial: 1FTWF31R59EA98160	
Lot #	24	
Qty	1	
Title	2017 PETERBILT 365 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Check Engine Light On. Showing: 76,846 Miles; 9,464 Hours. Location: Zebulon, NC Serial: 1NPSL70X2HD447996	
Lot #	25	
Qty	1	
Title	2001 MACK RD688S CAB & CHASSIS	
Des.	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Warning Lights On, Rust Throughout Frame And Wheels. Showing: 212,128 Miles; 49,459 Hours.	
Lot #	26	
Qty	1	
Title	2007 INTERNATIONAL PAYSTAR 5600 6X4 REAR MIXER	
Des.	NON-RUNNER. FULL OPERATIONS NOT TESTED. MISSING ENGINE ECU AND REAR COLLECTOR, McNeilus Mixer. Miles/Hours Unavailable. Location: College Park, GA. Serial: 1HTXHAHTX7J478946.	
Lot #	27	
Qty	1	
Title	2003 MACK CH612 DAY CAB TRUCK	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. Rear Of Cab Damaged From Wreck, D/S Door Is Jammed, Ignition Switch Is Disconnected, Tagged Out, VIN Tag Not Located. Mileage Unavailable. Location: Mulberry, FL Serial: 1M1AA09Y23W027471	
Lot #	28	
Qty	1	
Title	2002 MACK RD688S CAB & CHASSIS	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Warning Lights On, Rust Throughout Frame And Wheels. Showing: 843,246 Miles; 8,421 Hours.	
Lot #	29	
Qty	1	
Title	2019 PETERBILT 365 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Regen And Check Engine Light On, Heavy Spot On Drum. Showing: 62,133 Miles; 6,885 Hours. Location: Zebulon, NC Serial: 1NPSL70X8KD603160	








Lot #	30	
Qty	1	
Title	2001 CASE CX210 EXCAVATOR	
Des.	NO TITLE PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. ENGINE OVERHEATS A FEW MINUTES AFTER STARTING, Coolant System Known To Be Contaminated With Oil, Coolant Level Is Low, Body Damage Noted Throughout, Missing Hydraulic Oil Gauge. Showing 6,213 Hours. Location: Des Moines, IA Serial: DAC0721149	
Lot #	31	
Qty	1	
Title	2007 MACK CT713 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Oil Pan Has Wet Oil Present At The Rear And Along The Right Side Of Gasket Line, Transmission Has Fluid At The Bottom Of The Housing, Has Rust Hole And Rust Along Cab, Windshiel Cracked, Holes At The Bottom Of The D/S Door Panel, P/S Hood Breather Is Missing The Cover, Muffler Heat Shroud Has A Hole. Tires Worn. Showing: 267,112 Miles; 31,831 Hours. Location: Harlingen, TX. Serial: 1M2AL02C07M006866.	
Lot #	32	
Qty	1	
Title	2001 INTERNATIONAL F-4900 CAB & CHASSIS	
Des.	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Rust Throughout Frame And Wheels. Showing: 23,114 Miles; 4,322 Hours. Location: LAKEVILLE, IN Serial: 1HTSHAAR51H369768	
Lot #	33	
Qty	1	
Title	1997 KENWORTH T800 DAY CAB TRUCK	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing: 69,900 Miles. Location: Salem, OR Serial: 1XKDP20X4VR749185	
Lot #	34	
Qty	1	
Title	2019 PETERBILT 365 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Check Engine Light On. Showing: 61,244 Miles; 6,053 Hours. Location: Zebulon, NC Serial: 1NPSL70X5KD603164	
Lot #	35	
Qty	1	
Title	2001 KENWORTH T800 CAB & CHASSIS	
Des.	NON-RUNNER, FULL OPERATIONS NOT TESTED. Could Not Get Unit To Crank Over, Rust Throughout Frame And Wheels. Showing: 13,209 Miles; 10,119 Hours. Location: LAKEVILLE, IN Serial: 1NKDXBTX51J872511	
Lot #	36	
Qty	1	
Title	2007 MACK CT713 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Front Of The Oil Pan Is Leaking From The Oil Pan Gasket, The Transmission Is Missing A View/Cover Plate And The Bottom Has Oil On It, Has Tears In the D/S Door Panel, Windshield Cracked, Front Bumper Is Bent On The Left Side, Grille Is Missing A Cross Bar, Paint Chipped And Scraped, Missing Face Place On Shifter, Both Headlights Fogged, Rust Hole And Rusted Metal On Cab, Tires Worn. Showing: 306,371 Miles; 31,208 Hours. Location: Harlingen, TX. Serial: 1M2AL02C97M006865.	








Lot #	37	
Qty	1	
Title	2008 CATERPILLAR 330DL EXCAVATOR	
Des.	NOT TITLED PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. Tooth Missing On Table, Rust Throughout Unit. Showing: 15,523 Hours. Location: Mulberry, FL Serial: MWP03131	
Lot #	38	
Qty	1	
Title	2012 FREIGHTLINER M2 106 CAB & CHASSIS	
Des.	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Warning Lights On, Rust Throughout Frame. Showing: 234,984 Miles; 9,837 Hours. Location: GREENVILLE, OH Serial: 1FVHCYBS7CHBJ6736	
Lot #	39	
Qty	1	
Title	2019 PETERBILT 365 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Check Engine Light On. Showing: 60,011 Miles; 6,549 Hours. Location: Zebulon, NC Serial: 1NPSL70X3KD603163	
Lot #	41	
Qty	1	
Title	2007 MACK CV713 REAR MIXER	
Des.	NON-RUNNER, FULL OPERATIONS NOT TESTED. Oil Leak On The Right Side Of The Engine Above The Oil Pan, Batteries Fully Discharged, D/S Hood Breather Is Missing The Cover, Fiberglass Chipped And Cracked On The Hood, P/S Blinker Loose And Hanging, Seats Torn, Soiled Interior, Tires Worn. Showing: 267,468 Miles. Location: Harlingen, TX. Serial: 1M2AG11C97M067340.	
Lot #	42	
Qty	1	
Title	2005 MACK CV713 CAB & CHASSIS	
Des.	NON-RUNNER, FULL OPERATIONS NOT TESTED. Batteries Are Dead, Engine Has Bad Misfire, Did Not Try To Start Due To Causing More Damage. Showing: 859,507 Miles; 47,502 Hours. Location: GREENVILLE, OH Serial: 1M2AG11C15M018369	
Lot #	43	
Qty	1	
Title	2012 JOHN DEERE 333D SKID LOADER	
Des.	NOT TITLED PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing: 3,728 Hours. Location: Converse, TX Serial: 1T0333DMTCD218922	
Lot #	44	
Qty	1	
Title	2019 PETERBILT 365 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Check Engine Light On. Showing: 56,854 Miles; 6,159 Hours. Location: Zebulon, NC Serial: 1NPSL70X1KD603162	








Lot #	45	
Qty	1	
Title	2006 MACK CV713 CAB & CHASSIS	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Rust Throughout Frame And Wheels. Showing: 703,954 Miles; 35,546 Hours. Location: GREENVILLE, OH Serial: 1M2AG11C26M053195	
Lot #	46	
Qty	1	
Title	2006 MACK CT713 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Low Air And ABS Warning Lights On Dash, Radio Missing, Odometer Cover is Cracked, Engine Tag Is Worn Off, Mixer Data Tag Is Missing. Showing 280974 Miles; 33,944 Hours. Location: Eagle Pass, TX Serial: 1M2AL03C96M003865	
Lot #	47	
Qty	1	
Title	2013 KOMATSU WA380-7 WHEEL LOADER	
Des.	NOT TITLED PER STATE REGULATIONS. NON-RUNNER, FULL OPERATIONS NOT TESTED. NO KEY, Rust Throughout Unit. Showing: Hours Unavailable. Location: Mulberry, FL Serial: A64324	
Lot #	48	
Qty	1	
Title	2004 MACK CV713 CAB & CHASSIS	
Des.	NON-RUNNER, FULL OPERATIONS NOT TESTED. Just The PTO, No Pump. Showing: Mileage/Hours Unavailable.	
Lot #	49	
Qty	1	
Title	2019 PETERBILT 365 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Heavy Spot On Drum, Regen And Check Engine Light On. Showing: 50,174 Miles; 6,685 Hours. Location: Zebulon, NC Serial: 1NPSL70XXKD603161	
Lot #	50	
Qty	1	
Title	ZF GEAR DRIVES PARTS-HD	
Des.	QTY 5 Selling all together, McNeilus ZF Gear Drives, recently removed from operating mixer trucks. Housby can also offer these or other ZF gear drives rebuilds for \$2,750.00. Contact Randy at 515-299-6257. Location: Des Moines, IA	
Lot #	51	
Qty	1	
Title	2006 MACK CT713 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Radio Missing From Dash, Odometer Cover Is Cracked, Engine Tag Is Worn Off, Mixer Data Plate Is Missing. Showing 309,452 Miles; 35,887 Hours. Location: Eagle Pass, TX Serial: 1M2AL03C36M003862	








Lot #	52	
Qty	1	
Title	2005 MACK CV713 CAB & CHASSIS	
Des.	NON-RUNNER, FULL OPERATIONS NOT TESTED. Engine Block Has A Hole In It, Transmission Has Been Removed, Dash Removed. Showing: Mileage/Hours Unavailable. Location: Bardstown, KY Serial: 1M2AG11CX5M033081	
Lot #	53	
Qty	1	
Title	2013 KAWASAKI 70ZV-2 WHEEL LOADER	
Des.	NOT TITLED PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. Hydraulic Oil Leak, No Front Windshield Glass Missing. Showing: 13,214 Hours. Location: Mulberry, FL Serial: 70C5-5634	
Lot #	54	
Qty	1	
Title	2016 PETERBILT 365 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Coolant Light On. Showing: 96,743 Miles; 12,283 Hours. Location: Zebulon, NC Serial: 2NPSL70X4GM348606	
Lot #	55	
Qty	1	
Title	2012 PETERBILT 337 CAB & CHASSIS	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Front Bumper Is Damaged And Hanging Down On D/S, Dash Apart And Components Are Missing, Body Damage Throughout. Mileage Unavailable. Location: Summerville, SC Serial: 2NP2HN7XXCM135634	
Lot #	56	
Qty	1	
Title	2006 MACK CT713 REAR MIXER	
Des.	NON-RUNNER, FULL OPERATIONS NOT TESTED. Missing Water Tank, No Power To The Cab. Location: Eagle Pass, TX Serial: 1M2AL02C26M003837	
Lot #	58	
Qty	1	
Title	2005 MACK CV713 CAB & CHASSIS	
Des.	NON-RUNNER, FULL OPERATIONS NOT TESTED. Rust Throughout Frame And Wheels, Interior Burnt. Showing: Mileage/Hours Unavailable. Location: Cowan, TN Serial: 1M2AG11CX5M023103	
Lot #	59	
Qty	1	
Title	2016 PETERBILT 365 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Coolant Light On. Showing: 89,431 Miles; 11,028 Hours. Location: Zebulon, NC Serial: 1NPSL70XXGD351466	
Lot #	60	
Qty	1	
Title	2005 VOLVO L60E WHEEL LOADER	
Des.	NOT TITLED PER STATE REGULATIONS. NON-RUNNER, FULL OPERATIONS NOT TESTED. Rust Throughout Frame And Wheels. Showing: Hours Unavailable. Location: INDIANAPOLIS, IN Serial: L60EV60661	








Lot #	61	
Qty	1	
Title	2005 MACK DM688S REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Holes Drilled Into Center Dash, Engine Tag Not Located, Mixer Data Tag Is Missing. Showing 36,177 Miles; 30,679 Hours. Location: Eagle Pass, TX Serial: 1M2B212C25M005115	
Lot #	62	
Qty	1	
Title	2002 KENWORTH T-400 CAB & CHASSIS	
Des.	NON-RUNNER, FULL OPERATIONS NOT TESTED. Rust Throughout Frame And Wheels, Chips Throughout Hood. Showing: 711,946 Miles; 5,266 Hours.	
Lot #	64	
Qty	1	
Title	2016 PETERBILT 365 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing: 142,507 Miles; 11,173 Hours. Location: Zebulon, NC Serial: 2NPSL70X0GM348604	
Lot #	65	
Qty	1	
Title	2006 INTERNATIONAL 7600 CAB & CHASSIS	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Warning Lights On, Rust Throughout Unit. Showing: 160,368 Miles; 13,044 Hours. Location: Cairo, GA Serial: 1HTWYSBT66J343150	
Lot #	66	
Qty	1	
Title	2006 MACK DM690S REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Engine Tag Is Illegible, Mixer Data Plate Not Located, Gauge Missing From Center Dash. Showing 161,456 Miles; 25,362 Hours. Location: Eagle Pass, TX Serial: 1M2B209C36M030784	
Lot #	67	
Qty	1	
Title	2003 KAWASAKI 80ZV WHEEL LOADER	
Des.	NOT TITLED PER STATE REGULATIONS. NON-RUNNER, FULL OPERATIONS NOT TESTED. Inoperable, Rust Throughout Unit. Showing: Hours Unavailable. Location: Sacramento, CA Serial: 80C4-5010	
Lot #	68	
Qty	1	
Title	2014 MACK GU813 CAB & CHASSIS	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Rust Visible, Paint Peelig/Chipped, ABS Light Illuminated. Showing: 171,510 Miles; 17,842 Hours. Location: Pelham, AL. Serial: 1M2AX13COEM026900.	







Lot #	69	
Qty	1	
Title	2016 PETERBILT 365 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Engine Oil Pan And Transmission Wet, 14.75 Cubic Yard Capacity, 1 Inactive Fault - See ECM Report, 3 Holes In Dash, D/S Step Is Loose, Broken Step To Catwalk, D/S Fender Scratched, Cement Stuck On The Hood, Rust Throughout, Bumper Dented In Center, D/S Headlight Cracked, Rear Bumper Bent, Mud Flaps Torn, 2 Lights Out On Rear End. Location: Zebulon, NC. Serial: 2NPSL70X6GM348607.	
Lot #	70	
Qty	1	
Title	TANDEM AXLE PARTS-HD	
Des.	Pulled From 2012 Autocar ACX64. Location: Martinsville, VA Serial: 12602	
Lot #	71	
Qty	1	
Title	2006 MACK CT713 REAR MIXER	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. ABS Warning Light On Dash, Mixer Data Plate Is Missing, Engine Tag Not Located, Water Tank Removed And With Truck. Showing 295,040 Miles; 32,945 Hours. Location: Maverick, TX Serial: 1M2AL03C06M004323	
Lot #	72	
Qty	1	
Title	2006 PETERBILT 357 CAB & CHASSIS	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Unit Would Not Power Up, No Drum Or Drum Motor. Showing: Mileage/Hours Unavailable. Location: Pelham, AL Serial: 1NPAL50X46D638154	
Lot #	73	
Qty	1	
Title	1997 JOHN DEERE 644G WHEEL LOADER	
Des.	NOT TITLED PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. Rust Throughout Bucket. Showing: Hours Unavailable. Location: Sacramento, CA Serial: DW644GD564187	
Lot #	74	
Qty	1	
Title	2009 PETERBILT 365 REAR MIXER	
Des.	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Middle Tail Light Missing On D/S, Engine Tag Worn Off, Holes Drilled Into Center Dash. Showing 89,948 Miles; 22,178 Hours. Location: Goliad, TX Serial: 1NPSL50X09D770854	
Lot #	75	
Qty	1	
Title	2006 MACK CV713 CAB & CHASSIS	
Des.	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Warning Lights On, Rust Throughout Frame And Wheels. Showing: Mileage/Hours Unavailable. Location: McComb, MS Serial: 1M2AG11C35M023265	

Lot #	77	
Qty	1	
Title	2008 KENWORTH T800 REAR MIXER	
Des.	STARTED ON SITE W/JUMP AND FLUID, FULL OPERATIONS NOT TESTED. Engine And Body Tags Not Located. Showing 289,405 Miles; 15,489 Hours. Location: Goliad, TX Serial: 1NKDL50X78J237608	
Lot #	78	
Qty	1	
Title	2002 FREIGHTLINER FL112 CAB & CHASSIS	
Des.	NON-RUNNER, FULL OPERATIONS NOT TESTED. Warning Lights On, Rust Throughout Frame And Wheels. Showing: 7,333 Hours; Mileage Unavailable. Location: McComb, MS Serial: 1FVHBGA872HJ67121	
Lot #	79	
Qty	1	
Title	2000 KAWASAKI 70C WHEEL LOADER	
Des.	NOT TITLED PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. Ring Gear Has A Bad Spot And Engine Won't Always Turn Over, Compartment Jammed. Showing: Hours Unavailable. Location: Sacramento, CA Serial: 70C3-5821	
Lot #	80	
Qty	1	
Title	2007 KENWORTH T800 REAR MIXER	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. CRANK- No Start, ABS Warning Light On Dash, Mixer Data Tag Not Located, Components Missing From Center Dash. Showing 295,119 Miles; 27,257 Hours. Location: Cuero, TX Serial: 1NKDL50X67J207658	
Lot #	81	
Qty	1	
Title	2017 MACK CXU613 DAY CAB TRUCK	
Des.	NON-RUNNER, FULL OPERATIONS NOT TESTED. Turbo Taken Apart, Missing Battery Box Cover, Most Of Dash, Door, Grille, Hood Are All Busted, Tires Rotting, Rust Throughout Frame And Wheels. Showing: Mileage/Hours Unavailable. Location: Meridian, MS Serial: 1M1AW07Y1HM079374	
Lot #	82	
Qty	1	
Title	2007 KENWORTH T800 REAR MIXER	
Des.	STARTED ON SITE W/JUMP, FULL OPERATIONS NOT TESTED. Check Engine Warning Light On Dash, Rear Tires Are Singled Out, Engine And VIN Tag Are Illegible, Mixer Data Plate Is Missing. Showing 125,681 Miles; 7,797 Hours. Location: Cuero, TX Serial: 1NKDL50XX7J207663	
Lot #	84	
Qty	1	
Title	2006 MACK CT713 REAR MIXER	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. Low Air Warning Light On Dash, Hood Removed- With Truck, Dash Apart On P/S, Body Tag Not Located. Showing 337,515 Miles; 37,189 Hours. Location: San Antonio, TX Serial: 1M2AL02C56M003833	

Lot #	85	
Qty	1	
Title	2020 PETERBILT 567 CAB & CHASSIS	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. UNIT PARTED OUT AND MISSING MANY COMPONENTS, Tires Removed With Truck, Windshield Smashed, Holes In Transmission And Oil Pan, Dash Apart. Mileage Unavailable. Location: Austin, TX Serial: 1NPCLK0X3LD673156	
Lot #	86	
Qty	1	
Title	2014 MACK GU813 REAR MIXER	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. Missing Items, Including: Both Sides Hood Vent Grilles, D/S Headlight, And D/S Tail Light. Mileage Unavailable. Location: San Antonio, TX Serial: 1M2AX13C8EM023744	
Lot #	88	
Qty	1	
Title	2014 MACK GU813 REAR MIXER	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. Electrical Malfunction Warning Light On Dash. Showing 179,211 Miles; 4,111 Hours. Location: San Antonio, TX Serial: 1M2AX13CXEM023745	
Lot #	89	
Qty	1	
Title	2003 FORD F750 CAB & CHASSIS	
Des.	NON-RUNNER, FULL OPERATIONS NOT TESTED. Showing: 562,991 Miles. Location: Weatherford, TX Serial: 3FDXF75N03MB01840	
Lot #	90	
Qty	1	
Title	2014 MACK GU813 REAR MIXER	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. Missing Hood Vent Grilles On Both Sides, Switches Missing From Center Dash. Showing 200,082 Miles; 19,100 Hours. Location: San Antonio, TX Serial: 1M2AX13C7EM023749	
Lot #	92	
Qty	1	
Title	2015 VOLVO VHD REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Warning Lights On, Paint Chips Throughout Unit. Showing: 212,892.8 Miles; 19,895.5 Hours. Location: Luling, TX Serial: 4V5KC9DF4FN192277	
Lot #	94	
Qty	1	
Title	2009 PETERBILT 365 REAR MIXER	
Des.	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. ABS Warning Light On Dash, Engine Tag Worn And Illegible, Beck Industrial Rear Mixer Drum With 10.5 YD Capacity. Showing 243,947 Miles; 21,045 Hours. Location: Austin, TX Serial: 1NPSL50X29D770855	

Lot #	95	
Qty	1	
Title	2007 INTERNATIONAL 4200 ATTENUATOR TRUCK	
Des.	NON-RUNNER, FULL OPERATIONS NOT TESTED. Windshield Is Shattered, Has Rust Throughout Unit, Drivers Side Tire Flat, Clear Coat On Cab Peeling Off. Showing: 40,558 Miles; 11,553 Hours. Location: Carteret, NJ Serial: 1HTMPAFM57H449606	
Lot #	96	
Qty	1	
Title	2009 KENWORTH T800 REAR MIXER	
Des.	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. ABS And Coolant Level Low Warning Lights On Dash, Hydraulic Leak Reported, Rear Tires Are Singled Out. Showing 309,525 Miles; 9,840 Hours. Location: Austin, TX Serial: 1NKDL50XX9J237636	
Lot #	99	
Qty	1	
Title	2007 KENWORTH T-800 REAR MIXER	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. MISSING IGNITION SWITCH, LESS KEY, Engine Tag Not Located, Rear Tires Are Singled Out, Center Dash Broken, Beck Industrials Rear Mixer Drum With 10.5 YD Capacity. Mileage Unavailable. Location: Austin, TX Serial: 1NKDL50X17J207681	
Lot #	100	
Qty	1	
Title	1997 TOWMASTER T20 FLATBED TRAILER	
Des.	FULL OPERATIONS NOT TESTED. Approximate Measurements: 30 FT Length, 102 IN Width, Tires Worn, Scratches, Paint Chips, And Rust Throughout, L/S Of Ramp Has Cracks/Broken Welds, 2 Tail Lights Missing. Location: Lakeland, MN. Serial: 4KNFT222XVL161268.	
Lot #	101	
Qty	1	
Title	2007 GMC W4500 STAKE BODY TRUCK	
Des.	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Body And Frame Have Rust Throughout. Showing: 12,849 Miles. Location: Carteret, NJ Serial: 4KDC4B1U87J800799	
Lot #	102	
Qty	1	
Title	2007 KENWORTH T800 REAR MIXER	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. Check Engine Warning Light On Dash, Engine Tag Not Located, Rear Tires Singled Out. Showing 296,186 Miles; 13,938 Hours. Location: Austin, TX Serial: 1NKDL50X77J207684	
Lot #	105	
Qty	1	
Title	2009 KENWORTH T800 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. ABS, Coolant Level Low, DEF Lamp And Check Engine Warning Lights On Dash, Rear Tires Are Singled Out, Beck Industrial Rear Mixer Drum With 10.5 YD Capacity. Showing 440,247 Miles; 7,565 Hours. Location: Austin, TX Serial: 1NKDL50X49J237633	

Lot #	108	
Qty	1	
Title	2014 MACK GU813 REAR MIXER	
Des.	NON-RUNNER, FULL OPERATIONS NOT TESTED. Side Mount Water Tank, Warning Lights On. Showing: Mileage: Unavailable. Location: Austin, TX Serial: 1M2AX13C3EM023747	
Lot #	109	
Qty	1	
Title	1995 TOWMASTER FLATBED TRAILER	
Des.	FULL OPERATIONS NOT TESTED. VIN PLATE MISSING, Approximate Measurements: 30 FT Length, 96 IN Width, Tires Worn, Scratches, Paint, Chips, Rust Throughout, Rear Cross-Member Between Rear Ramps Bent Up. Location: Lakeland, MN. Serial: 4KNFC2320SL160611.	
Lot #	110	
Qty	1	
Title	1995 FORD L8000 DUMP TRUCK	
Des.	STARTED ON SITE W/JUMP POST INSPECTION, FULL OPERATIONS NOT TESTED. Leakage Around Rear Side Of Fuel Pump Assembly, Oil Residue Around Oil Pan Seal, L/S Rocker Panel Rusted Through, Paint Chips/Scrapes/Scratches Throughout, Peeling Around Grille And Headlights, Steps Bent. Rust Visible. Showing: 367,925 Miles; 1,430 Hours. Location: Lakeland, MN. Serial: 1FTYR82E4SVA62779.	
Lot #	111	
Qty	1	
Title	2008 KENWORTH T800 REAR MIXER	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. MISSING IGNITION SWITCH, Engine Tag Is Worn And Illegible, Beck Industrial Rear Mixer Drum With 10.5 YD Capacity. Mileage Unavailable. Location: Austin, TX Serial: 1NKDL50X08J237613	
Lot #	112	
Qty	1	
Title	1995 YALE GDP080 FORKLIFT	
Des.	NOT TITLED PER STATE REGULATION. STARTED ON SITE, FULL OPERATIONS NOT TESTED. Battery Missing, Electrical Issues. Showing: 11,574 Hours. Location: Byron, GA Serial: D567658	
Lot #	113	
Qty	1	
Title	2011 FORD E-150 VAN	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. TPMS Warning Light On Dash, Rust Throughout. Showing 111,471 Miles. Location: Des Moines, IA Serial: 1FTNE1EW4BDA25778	
Lot #	114	
Qty	1	
Title	2008 KENWORTH T800 REAR MIXER	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Air Leak And Breaks Do Not Charge Up, Beck Industrial Rear Mixer With 10.5 YD Drum Capacity, Engine Tag Illegible. Showing: 254,512 Miles; 22,526 Hours. Location: Austin, TX. Serial: 1NKDL50X48J237632.	

Lot #	115	
Qty	1	
Title	1978 KARL KOOL TANKER TRAILER	
Des.	FULL OPERATIONS NOT TESTED. Dents And Rust Throughout Unit, Paint Chips Through Unit, No Power To Unit, Approximate Measurements 40 FT Length, 96 IN Width, 140 IN Height. Location: Coldwater, MI Serial: CTK6908	
Lot #	116	
Qty	1	
Title	2006 INTERNATIONAL CF600 4X2 VAN BODY TRUCK	
Des.	STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. Must Use Button To Start, Windshield Cracked, Weight And Engine Tags Not Located. Showing 130,321 Miles. Location: Weatherford, TX Serial: 3HAJFAVK66L219376	
Lot #	117	
Qty	1	
Title	2006 MACK CT713 REAR MIXER	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. Engine Cranks But Does Not Start, P/S Hood Vent Grille Is Missing, Rear Tires Are Singled Out, Odometer Cover Is Broken, Dash Apart And Missing Components, Engine Tag Not Located, Axle Weight Tag Is Illegible. Showing 388,541 Miles; 31,993 Hours. Location: Austin, TX Serial: 1M2AL02C96M003835	
Lot #	118	
Qty	1	
Title	1998 OSHKOSH FF-115 6x6 WATER TRUCK	
Des.	STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. Tagged Out, Accelerator Sticks, A/C And Sprayers INOP, Engine And Body Tags Not Found. Showing 105,114 Miles; 4,506 Hours. Location: Mulberry, FL Serial: 10TDCKY32WS064147	
Lot #	119	
Qty	1	
Title	1999 FORD ECONOLINE 250 VAN	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Heavy Rust Noted Throughout, Torn Upholstery Noted. Showing 79,966 Miles. Location: Des Moines, IA Serial: 1FTNE24L2XHC27869	
Lot #	120	
Qty	1	
Title	2009 PETERBILT 365 REAR MIXER	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. Did Not Take Jump, Engine Tag Not Located, Rear Tires Are Singled Out, Beck Industrails Rear Mixer Drum With 10.5 YD Capacity. Mileage Unavailable. Location: Austin, TX Serial: 1NPSL50X99D770853	