





## Printable Catalog


<b>Title</b>	APRIL 24 12:00 CST
<b>Description</b>	Closing Times TBD
<b>Date</b>	Wed, Apr 24, 2024
<b>Starts at</b>	12:00 PM
<b>Address</b>	4747 NE 14th St, Des Moines, IA 50313 USA
<b>Categories</b>	








<b>Lot #</b>	1	
<b>Qty</b>	1	
<b>Title</b>	2009 MACK GU713 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. 10.5 Cubic Yard Capacity McNeilus Drum, Missing Inside Mixer Control, Heavy Spot In Drum, Hydraulic Oil Leaks, Regen Problems, Smoke Out Exhaust When Running. Showing: 181,817 Miles. Location: Winston Salem, NC. Serial: 1M2AX04C99M005526.	








<b>Lot #</b>	2	
<b>Qty</b>	1	
<b>Title</b>	2007 VOLVO VNL DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED, 2 INACTIVE FAULTS (SEE ECM), OIL SEEPAGE ALONG SIDES OF CASE AND PAN, HEAVY FLUID SEEPAGE FROM R1 DIFFERENTIAL. Paint Chips, Scratches, Rust Throughout Unit, Hood Release Lever Broken. Showing: 710,509 Miles; 446 Hours. Location: Russellville, KY. Serial: 4V4NC9GF17N467389.	

<b>Lot #</b>	3	
<b>Qty</b>	1	
<b>Title</b>	2013 VOLVO VHD CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE W/JUMP, FULL OPERATIONS NOT TESTED. SCR Fault - Will Derate In 36 Minutes, Check Engine Light Illuminated. Showing: 164,234 Miles. Location: Kingsville, OH. Serial: 4V5KC9EG3DN569203.	









<b>Lot #</b>	4	
<b>Qty</b>	1	
<b>Title</b>	1999 INTERNATIONAL 4700 ATTENUATOR TRUCK	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. BAD BATTERIES, Dents, Scrapes And Rust Throughout Unit, Dent In Right Fuel Tank, Left Ladder Twisted. Showing: 329,074 Miles; 15,293 Hours. Location: Stephenson, VA. Serial: 1HTSCAAN1XH205115.	









<b>Lot #</b>	5	
<b>Qty</b>	1	
<b>Title</b>	2013 FREIGHTLINER COLUMBIA 120 GLIDER DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Unable To Obtain ECM, Break Issues - Air Leaks Out Side Of Pedal When Pushed, Steers Are Recaps, Rear Cross Member Bent, Rust Throughout, Tires Worn. Showing: 507,355 Miles. Location: Hamilton, MI. Serial: 1FVXA7A86DDFA2392.	









<b>Lot #</b>	6	
<b>Qty</b>	1	
<b>Title</b>	2004 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE W/JUMP AND FLUID, FULL OPERATIONS NOT TESTED. ABS Light Illuminated, Fuel Cap Missing, Front Bumper Missing. Showing: 677,531 Miles; 21,816 Hours. Location: Lakeville, IN. Serial: 1M2AG11C94M009711.	
<b>Lot #</b>	7	
<b>Qty</b>	1	
<b>Title</b>	2009 MACK GU713 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. KNOWN TURBO ISSUES, 10.5 Cubic Yard Capacity McNeilus Drum. Showing: 196,683 Miles. Location: Winston Salem, NC. Serial: 1M2AX04C49M005529.	
<b>Lot #</b>	8	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CXU613 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing: 507,582 Miles; 32,495 Hours. Location: Lakeville, MN. Serial: 1M1AK06Y26N013646.	
<b>Lot #</b>	9	
<b>Qty</b>	1	
<b>Title</b>	2013 MACK GU813 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE W/JUMP, FULL OPERATIONS NOT TESTED. Check Engine Light Illuminated, Front Tires Heavily Worn, Rust Visible. Showing: 295,622 Miles; 11,378 Hour. Location: Wittenberg, WI. Serial: 1M2AX18C8DM021094.	
<b>Lot #</b>	10	
<b>Qty</b>	1	
<b>Title</b>	1998 FORD F800 ATTENUATOR TRUCK	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Bad Batteries, Major Rust Noted, Hood Damaged. Showing: 212,411 Miles; 23,060 Hours. Location: Stephenson, VA. Serial: 1FDXF80E3WVA12142.	
<b>Lot #</b>	12	
<b>Qty</b>	1	
<b>Title</b>	2003 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Warning Lights Illuminated, Front End Damage. Showing: 796,384 Miles; 32,426 Hours. Location: Des Moines, IA. Serial: 1M2AG11CX3M006069.	
<b>Lot #</b>	13	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CTP REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. McNeilus 10.5 Cubic Yard Capacity. Showing: 168,120 Miles; 16,041 Hours. Location: Winston Salem, NC. Serial: 1M2AT04C67M006724.	









<b>Lot #</b>	14	
<b>Qty</b>	1	
<b>Title</b>	2016 FREIGHTLINER CASCADIA 113 DAY CAB TRUCK	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Catalytic Converter System Disconnected/Unplugged, Engine Oil Leaks Noted. Showing: 832,387 Miles. Location: Rose Hill, NC. Serial: 3AKJGBDV0GDHB8531.	
<b>Lot #</b>	15	
<b>Qty</b>	1	
<b>Title</b>	2009 MACK GU813 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Rust Throughout Unit. Showing: 601,102 Miles; 27,237 Hours. Location: ROCHESTER, MN Serial: 1M2AX13C29M002877	
<b>Lot #</b>	16	
<b>Qty</b>	1	
<b>Title</b>	2017 JOHN DEERE 324E SKID LOADER	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS, STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing: 4,950 Hours. Location: Des Moines, IA. Serial: 1T0324EKVGJ305191.	
<b>Lot #</b>	17	
<b>Qty</b>	1	
<b>Title</b>	2014 VOLVO VNL DAY CAB TRUCK	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Dash Disassembled, Ignition Switch Replaced, Body Damage Noted- Behind L/Rear Cab. Showing: 738,306 Miles. Location: Rose Hill, NC. Serial: 4V4NC9EG4EN164910.	
<b>Lot #</b>	18	
<b>Qty</b>	1	
<b>Title</b>	2006 VOLVO VHD CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. NO CLUSTER IN DASH, NO ECM, Missing Turbo And Exhaust Manifold, Rust Throughout Unit. Showing: Miles/Hours Unavailable. Location: Pelham, AL. Serial: 4V5KC9GFX6N430435.	
<b>Lot #</b>	19	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CTP713 REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/JUMP, FULL OPERATIONS NOT TESTED. MCNEILUS Drum W/ 10.5 Cubic Yard Capacity. Showing: 167,430 Miles; 6,340 Hours. Location: Indian Trail, NC. Serial: 1M2AT04C47M006723.	
<b>Lot #</b>	20	
<b>Qty</b>	1	
<b>Title</b>	2013 VOLVO VNM DAY CAB TRUCK	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Crank - No Start. Showing: 774,114 Miles. Location: Rose Hill, NC. Serial: 4V4MC9EG3DN141807	

<b>Lot #</b>	22	
<b>Qty</b>	1	
<b>Title</b>	2019 JOHN DEERE 325G SKID LOADER	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. NON-RUNNER, FULL OPERATIONS NOT TESTED. Oil Leakage Buildup At Bottom Of Engine, 1 Active Code & 9 Inactive Codes - See Photos, Tracks Show Excessive Wear, Front Step Plate Is Bent, Bottom Door Hinge Is Not Connected/Damaged, Door Glass Has Small Cracks Around The Bracket Hole, R/S Handle Is Bent, Front Of Roof Is Bent, Headliner Pulled Loose, Radio Damaged And Not Connected, Hand Throttle Knob Is Broken, Fan Shroud Cracked, Rear L/S Light Housing Is Loose And Missing Screws, Grille & Rear Bumper Disconnected, Engine Shock Is Not Connected And Damaged. Showing: 3,482 Hours. Location: Albertville, AL. Serial: 1T0325GJPKJ358728.	
<b>Lot #</b>	23	
<b>Qty</b>	1	
<b>Title</b>	2013 VOLVO VNM DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE W/JUMP, FULL OPERATIONS NOT TESTED. Showing: 755,275 Miles. Location: Rose Hill, NC. Serial: 4V4MC9EG4DN141802.	
<b>Lot #</b>	25	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CV513 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Heavy Spot In Drum, 11 Cubic Yard Continental Drum. Showing: 147,429 Miles; 21,525 Hours. Location: Raleigh, NC. Serial: 1M2AG02C47M003196.	
<b>Lot #</b>	26	
<b>Qty</b>	1	
<b>Title</b>	2013 MACK CXU613 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Warning Lights On. Showing: 508,803 Miles; 20,414 Hours. Location: DES MOINES, IA Serial: 1M1AW07YXDM034671	
<b>Lot #</b>	27	
<b>Qty</b>	1	
<b>Title</b>	2006 VOLVO VHD64B CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE W/JUMP, FULL OPERATIONS NOT TESTED. Warning Lights Illuminated, Dash Repaired With Tape. Showing: 249,382 Miles; 26,495 Hours. Location: Pelham, AL. Serial: 4V5KC9GF36N405165.	
<b>Lot #</b>	28	
<b>Qty</b>	1	
<b>Title</b>	2012 MACK GU700 KNUCKLEBOOM TRUCK	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. FUEL TANK COMPONENTS MISSING, DEF DISASSEMBLED AND PARTS MISSING, ENGINE FAN DISCONNECTED, COMPONENTS MISSING- PLEASE SEE PHOTOS. MILEAGE UNAVAILABLE. Location: Kuna, ID. Serial: 1M1AX09Y9CM012010.	
<b>Lot #</b>	29	
<b>Qty</b>	1	
<b>Title</b>	2008 OSHKOSH S SERIES FRONT MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Check Engine Light Illuminated. Showing: 47,025 Miles; 834 Hours. Location: Columbia, SC. Serial: 10TDAAC248S102852.	









<b>Lot #</b>	30	
<b>Qty</b>	1	
<b>Title</b>	2013 MACK CHU613 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Air Compressor INOP. Showing: 430,395 Miles; 15,772 Hours. Location: Des Moines, IA. Serial: 1M1AN07Y9DM012275.	
<b>Lot #</b>	31	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CV513 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Hydraulic Fluid And Oil Leaks, 11 Cubic Yard Continental Drum. Showing: 164,471 Miles; 21,973 Hours. Location: Raleigh, NC. Serial: 1M2AG02CX6M002066.	
<b>Lot #</b>	32	
<b>Qty</b>	1	
<b>Title</b>	2006 VOLVO VHD64B CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Missing Turbo And ECM. Showing: Miles/Hours Unavailable. Location: Pelham, AL. Serial: 4V5KC9GF66N430433.	
<b>Lot #</b>	34	
<b>Qty</b>	1	
<b>Title</b>	2016 MACK CXU613 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing: 619,313 Miles; 16,505 Hours. Location: Des Moines, IA Serial: 1M1AW09Y0GM078180	
<b>Lot #</b>	36	
<b>Qty</b>	1	
<b>Title</b>	2006 TEREX ADVANCE FRONT MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Hole In Mixer Drum, Less Terex Key, Engine Oil Leaks, Hydraulic Oil Leaks, Warning Lights Illuminated. Showing: 210,582 Miles; 21,371 Hours. Location: Statesville, NC. Serial: 5DG8AU5T660011165.	
<b>Lot #</b>	37	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CV513 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. 11 Cubic Yard Continental Drum. Showing: 164,093 Miles; 23,466 Hours. Location: Raleigh, NC. Serial: 1M2AG02C96M002074.	
<b>Lot #</b>	38	
<b>Qty</b>	1	
<b>Title</b>	2018 KENWORTH T680 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing 658,461 Miles; 14,674 Hours. Location: Des Moines, IA Serial: 1XKYD49X6JJ212707	
<b>Lot #</b>	39	
<b>Qty</b>	1	
<b>Title</b>	2006 VOLVO VHD64B CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Dash Disassembled/Wires Showing, Front P/S Tire Off Rim. Showing: Miles/Hours Unavailable. Location: Pelham, AL. Serial: 4V5KC9GF66N405158.	






<b>Lot #</b>	42	
<b>Qty</b>	1	
<b>Title</b>	2020 KENWORTH T680 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing 668,74 Miles; 14,089 Hours. Location: Des Moines, IA Serial: 1XKYD49X4LJ295508	
<b>Lot #</b>	43	
<b>Qty</b>	1	
<b>Title</b>	2005 MACK CV513 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Hydraulic Oil Leaks, Thin Drum, Body Damage, 10.5 Cubic Yards McNeilus Drum. Showing: 197,419 Miles; 23,412 Hours. Location: Raleigh, NC. Serial: 1M2AG02C35M001985.	
<b>Lot #</b>	44	
<b>Qty</b>	1	
<b>Title</b>	2014 MACK GU713 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Warning Lights Illuminated, Right Exterior Door Handle Broken, Rust Throughout Unit. Showing: 482,954 Miles. Location: Dyersburg, TN. Serial: 1M2AX09C0EM019334.	
<b>Lot #</b>	45	
<b>Qty</b>	1	
<b>Title</b>	2007 TEREX ADVANCE FRONT MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. 11 Cubic Yard Capacity. Showing: 121,852 Miles; 16,409 Hours. Location: Statesville, NC. Serial: 5DG8AU5T570012132.	
<b>Lot #</b>	46	
<b>Qty</b>	1	
<b>Title</b>	2017 VOLVO VNL DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing: 685,482 Hours, 15,297 Hours Location: Des Moines, IA Serial: 4V4NC9EH9HN983392	
<b>Lot #</b>	48	
<b>Qty</b>	1	
<b>Title</b>	2014 MACK GU713 CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. MISSING: TRANSMISSION, REAR ENGINE COVER, DASH, DOOR, FUEL TANK, HOOD, ENGINE PARTS, OIL PAN, DRIVE SHAFT. Showing: Miles/Hours Unavailable. Location: Ellenwood, GA. Serial: 1M2AX09C1EM019973.	
<b>Lot #</b>	50	
<b>Qty</b>	1	
<b>Title</b>	2018 MACK CXU613 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing: 686,570 Miles; 15,071 Hours. Location: Des Moines, IA Serial: 1M1AW09Y2JM089091	
<b>Lot #</b>	51	
<b>Qty</b>	1	
<b>Title</b>	2011 KENWORTH T400 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE W/JUMP, FULL OPERATIONS NOT TESTED. Showing: 590,948 KILOMETERS; 21,368 Hours. Location: Ellenwood, GA. Serial: 2NKBL59X7BM291887.	





<b>Lot #</b>	52	
<b>Qty</b>	1	
<b>Title</b>	2008 ADVANCE MIXER FD5000 FRONT MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. 11 Cubic Yard Terex Drum, Warning Lights Illuminated. Showing: 173,804 Miles; 18,690 Hours. Location: Raleigh, NC. Serial: 5DG8AU5T880012501.	
<b>Lot #</b>	54	
<b>Qty</b>	1	
<b>Title</b>	2018 KENWORTH T680 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing 704,227 Miles; 16,787 Hours. Location: Des Moines, IA Serial: 1XKYD49X7JJ212716	
<b>Lot #</b>	55	
<b>Qty</b>	1	
<b>Title</b>	2007 INTERNATIONAL DF567 REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/JUMP, FULL OPERATIONS NOT TESTED. THIN DRUM. BAD IDLER WHEEL NOTED FOR McNeilus Drum, Oil Leaks Noted. Showing: 186,895 Miles; 20,782 Hours. Location: Duluth, GA. Serial: 1HTXHAHTX7J526607.	
<b>Lot #</b>	56	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. ENGINE PARTS IN CAB, Rust Throughout Unit, Dash Disassembled. Showing: Mileage/Hours Unavailable. Location: Carnesville, GA Serial: IM2AG11C37M065793	
<b>Lot #</b>	58	
<b>Qty</b>	1	
<b>Title</b>	2019 INTERNATIONAL LT625 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing: 542,847 Miles; 13,371 Hours. Location: Des Moines, IA. Serial: 3HCDZAPR8KL334464.	
<b>Lot #</b>	59	
<b>Qty</b>	1	
<b>Title</b>	2006 INTERNATIONAL 4400 6X4 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Check Engine And Check AC Lights Illuminated, Shifts Rough, 1 Active Fault - See ECM Report, Rust Throughout, Headliner Missing, Marker Light Cover Missing On P/S, Paint Peeling, Tires Worn. Showing: 615,070 Miles; 615,056 ECM; 37,917 Hours. Location: Tampa, FL. Serial: 1HTMSAAR96H250509.	
<b>Lot #</b>	60	
<b>Qty</b>	1	
<b>Title</b>	2006 OSHKOSH S SERIES FRONT MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. 11 Cubic Yard Oshkosh Drum. Showing: 162,280 Miles; 22,424 Hours. Location: Raleigh, NC. Serial: 10TDAAC256S089817.	
<b>Lot #</b>	61	
<b>Qty</b>	1	
<b>Title</b>	2007 INTERNATIONAL DF567 REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/JUMP, FULL OPERATIONS NOT TESTED. Thin Drum, Hole In Drum, McNeilus Body. Showing: 255,131 Miles; 28,268 Hours. Location: Duluth, GA. Serial: 1HTXHAHT07J526583.	

<b>Lot #</b>	62	
<b>Qty</b>	1	
<b>Title</b>	2016 VOLVO VNL DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing: 702,979 Miles; 9,010 Hours. Location: Des Moines, IA Serial: 4V4NC9EH1GN953415	
<b>Lot #</b>	65	
<b>Qty</b>	1	
<b>Title</b>	2015 CHEVROLET EXPRESS CUTAWAY G3500 VAN BODY TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing: 200,092 Miles. Location: Des Moines, IA Serial: 1GB3G2CG6F1230825	
<b>Lot #</b>	66	
<b>Qty</b>	1	
<b>Title</b>	2019 INTERNATIONAL DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Windshield Chipped. Showing: 521,731 Miles; 12,681 Hours. Location: Des Moines, IA Serial: 3HCDZAPR3KL118781	
<b>Lot #</b>	67	
<b>Qty</b>	1	
<b>Title</b>	2013 PETERBILT 384 CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Showing: Miles/Hours Unavailable. Location: McCrory, AR. Serial: 1NPVL79X8DD181328.	
<b>Lot #</b>	68	
<b>Qty</b>	1	
<b>Title</b>	2007 ADVANCE MIXER FD5000 FRONT MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. THIN DRUM- 11 Cubic Yard Capacity Terex Drum, Oil Leaks Noted. Showing: 151,739 Miles; 16,510 Hours. Location: Raleigh, NC. Serial: 5DG8AU5TX70012076.	
<b>Lot #</b>	70	
<b>Qty</b>	1	
<b>Title</b>	2019 INTERNATIONAL LT625 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE W/FLUID, FULL OPERATIONS NOT TESTED. Showing: 564,416 Miles; 12,668 Hours. Location: Des Moines, IA. Serial: 3HCDZAPR2KL334461.	
<b>Lot #</b>	71	
<b>Qty</b>	1	
<b>Title</b>	2010 VOLVO VNL CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. DASH WIRES CUT AND MISSING/BROKEN PARTS, No Fuel Tank On Left Side. Showing: Miles/Hours Unavailable. Location: Mc Crory, AR. Serial: 4V5NC9EG4AN287953.	
<b>Lot #</b>	74	
<b>Qty</b>	1	
<b>Title</b>	2019 INTERNATIONAL LT625 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Warning Lights Illuminated. Showing: 554,717 Miles; 13,161 Hours. Location: Des Moines, IA. Serial: 3HCDZAPR5KL118782.	



<b>Lot #</b>	75	
<b>Qty</b>	1	
<b>Title</b>	2001 KENWORTH T800 CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Crank - No Start, Rust Throughout Unit. Showing: 151,872 Miles. Location: San Angelo, TX. Serial: 1XKDDU9X41R874611.	
<b>Lot #</b>	79	
<b>Qty</b>	1	
<b>Title</b>	2012 PETERBILT 384 CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Warning Lights Illuminated. Showing: 388,813 Miles; 24,439 Hours. Location: Luling, TX. Serial: 1NPVL79X1CD151733.	
<b>Lot #</b>	80	
<b>Qty</b>	1	
<b>Title</b>	INTERNATIONAL HOOD ASSEMBLY PARTS-HD	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. Pulled From 2012 International 7400. Location: Des Moines, IA Serial: 15835	
<b>Lot #</b>	81	
<b>Qty</b>	1	
<b>Title</b>	2003 CHEVROLET 2500HD EXT CAB PICKUP TRUCK	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Engine Missing Front Of Air Intake, Tailgate Removed And In Bed, Dents And Scratches Throughout Unit, Tires Are Worn. Showing: 344,064 Miles; 7,985 Hours. Location: Hartville, MO Serial: 1GCHK29G93E208457	
<b>Lot #</b>	83	
<b>Qty</b>	1	
<b>Title</b>	2015 KENWORTH T370 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Check Engine Light Illuminated. Showing: 134,726 Miles; 4,091 Hours. Location: Luling, TX. Serial: 2NKHHM5H0FM426069.	
<b>Lot #</b>	85	
<b>Qty</b>	1	
<b>Title</b>	2002 CATERPILLAR 3406 GENERATOR	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. NON-RUNNER, FULL OPERATIONS NOT TESTED. NO FUEL SOURCE, Damage To Door And Side. Showing: Hours Unavailable. Location: Buckeye, AZ. Serial: 8FR03151.	
<b>Lot #</b>	86	
<b>Qty</b>	1	
<b>Title</b>	2019 INTERNATIONAL LT62F DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Warning Lights On. Showing: 609,429 Hours, 13,714 Hours Location: Des Moines, IA Serial: 3HCDZAPR8KL118775	
<b>Lot #</b>	87	
<b>Qty</b>	1	
<b>Title</b>	2010 MACK GU813 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE W/JUMP, FULL OPERATIONS NOT TESTED. Paint Chips And Scratches, Rust Visible. Showing: 590,121 Miles; 25,899 Hours. Location: Weatherford, TX. Serial: 1M2AX13CXAM012075.	

<b>Lot #</b>	89	
<b>Qty</b>	1	
<b>Title</b>	2000 CHEVROLET K2500 PICKUP TRUCK	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Battery Dead, Replacement Tailgate, Dash Is Disassembled, Door Panel Missing Parts, Tires Worn. Showing: 234,388 Miles. Location: Hartville, MO. Serial: 1GCGK24R0YR101110.	
<b>Lot #</b>	91	
<b>Qty</b>	1	
<b>Title</b>	2007 KENWORTH T300 CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Dash Is Damaged And Panels Are Loose, Rust Throughout Unit. Showing: 624,444 Miles. Location: Weatherford, TX. Serial: 2NKMLZ9X07M165314.	
<b>Lot #</b>	92	
<b>Qty</b>	1	
<b>Title</b>	2006 INTERNATIONAL RF027 TANK TRUCK	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. DRIVE SHAFT NOT CONNECTED. OIL PAN, BLOCK AND L/S HOSES COVERED IN OIL. R/S HAS OIL ABOVE PAN GASKET LINE. ENGINE LEAKS, EXTENT UNKNOWN. FUEL TANKS RUSTY, R/S TANK LEAKS. Showing: Miles/Hours Unavailable. Location: Cleveland, OH. Serial: 1HSHXHR96J249012.	
<b>Lot #</b>	93	
<b>Qty</b>	1	
<b>Title</b>	2002 CATERPILLAR 3406 GENERATOR	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. NON-RUNNER, FULL OPERATIONS NOT TESTED. NO FUEL SOURCE, Rust Throughout Unit, Dented. Showing: Hours Unknown. Location: Buckeye, AZ. Serial: 8FR02504.	
<b>Lot #</b>	94	
<b>Qty</b>	1	
<b>Title</b>	2011 VOLVO VNL DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing: 464,057 Miles; 30,940 Hours. Location: Converse, TX Serial: 4V4NC9DG6BN533229	
<b>Lot #</b>	97	
<b>Qty</b>	1	
<b>Title</b>	1992 ACCURATE AC50 ROLLOFF TRAILER	
<b>Des.</b>	FULL OPERATIONS NOT TESTED. Hydraulic Cylinders Are Leaking, Rust Throughout The Bed And Chassis. Approximate Measurements: 35 FT Length, 98 IN Width. Location: El Dorado, AR Serial: 1A9503525N4194885	
<b>Lot #</b>	98	
<b>Qty</b>	1	
<b>Title</b>	2017 FREIGHTLINER CASCADIA 113 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. SHOWING 1 ACTIVE/28 INACTIVE FAULTS (SEE ECM REPORT). Showing: 352,409 Miles; 146,565 Hours. Location: Amarillo, TX. Serial: 1FUJGBDV8HLJD2486.	

<b>Lot #</b>	99	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Cracks And Paint Chips Throughout Unit. Showing: Mileage/Hours Unavailable. Location: Weatherford, TX Serial: 1M2AG11C37M068810	
<b>Lot #</b>	100	
<b>Qty</b>	1	
<b>Title</b>	2000 EXMARK L225KC604 MOWERS	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. Engine Runs Rough. Showing: Hours Unknown. Location: Des Moines, IA Serial: 220842	
<b>Lot #</b>	102	
<b>Qty</b>	1	
<b>Title</b>	2014 PETERBILT 579 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE W/JUMP, FULL OPERATIONS NOT TESTED. Showing: 633,264 Miles; 8,949 Hours. Location: Weatherford, TX. Serial: 1XPBD49X1ED236529.	
<b>Lot #</b>	104	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Cracks And Paint Chips Throughout Unit. Showing: Mileage/Hours Unavailable. Location: Weatherford, TX Serial: 1M2AG11C27M038990	