





Printable Catalog


| | | |
|--------------------|-------------------------------------------|--|
| Title | MAY 13 12:00 CDT | |
| Description | Closing Times TBD | |
| Date | Wed, May 13, 2020 | |
| Starts at | 12:00 PM | |
| Address | 4747 NE 14th St, Des Moines, IA 50313 USA | |
| Categories | | |








| | | |
|--------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Lot # | 1 | |
| Qty | 1 | |
| Title | 2000 KOMATSU WA250-3MC WHEEL LOADER |  |
| Des. | STARTED ON SITE - FULL OPERATIONS NOT TESTED. Komatsu S6D102E Diesel, Automatic, 108in Bucket, Steel Wheels, 20.5R25, AC/Heated Cab, Warning Lights Active, Rust. Showing 11,417 Hours. Location: Des Moines, IA Serial: A71018 | |







| | | |
|--------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Lot # | 2 | |
| Qty | 1 | |
| Title | 2004 MACK CV713 REAR MIXER |  |
| Des. | STARTED ON SITE - NOT ROAD TESTED. ENGINE BLOW BY. 100 FA, MTM Bridgemaster Mixer System, Cross Mount Water Tank, 13,200 Lbs Bride Axle. Oil Seepage At Oil Pan, Active Fault Codes - See Report, Shifter Cap Missing, Interior Worn, Various Body Damage/Rust. Showing 153,093 Miles; 20,115 Hours. Location: Streamwood, IL Serial: 1M2AG11C84M009389 | |







| | | |
|--------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
| Lot # | 3 | |
| Qty | 1 | |
| Title | 2000 MACK CX613 CAB & CHASSIS |  |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Mack E7-460 E-TECH, Eaton Fuller RTX16709H 9 Speed, Air Ride Suspension, 242 WB, Pusher Axle, Double Frame, Aluminum Fuel Tank, Steel Wheels, 315/80R22.5; 255/70R22.5; 11R22.5, AC, Rust. Showing 955,482 Miles; 42,966 Hours. Location: Des Moines, IA Serial: 1M1AE07Y3YW002237 | |







| | | |
|--------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| Lot # | 4 | |
| Qty | 1 | |
| Title | 2003 INTERNATIONAL 4300 MECHANICS TRUCK |  |
| Des. | STARTED ON SITE W/ STARTING FLUID - NOT ROAD TESTED. DID NOT GET CRANE TO OPERATE. International DT466 Diesel, 6 Speed Manual, Spring Suspension, 8 FA, 17.5 RA, 187 WB, 11ft MIT Dominator Service Body, MIT 3820 Mechanic Crane, Body Storage, Steel Wheels, 11R22.5, AC, Pintle Hitch, ABS Light Illuminated, Body Damage/Rust. Showing 273,079 Miles. Location: Waterloo, NE Serial: 1HTMMAAM03H603343 | |








| | | |
|--------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| Lot # | 5 | |
| Qty | 1 | |
| Title | 2014 JOHN DEERE 310SK BACKHOE |  |
| Des. | NOT TITLED PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. Some Black Smoke At Start Up - Clear At Operating Temp, Rust On Hydraulic Steel Lines, Tires Worn, Various Rust. See Attached Report For Additional Specifications. Showing 2,156 Hours. Location: Gillette, WY Serial: 1T0310SKPDE252734 | |







| | | |
|--------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| Lot # | 6 |  |
| Qty | 1 | |
| Title | 2005 FREIGHTLINER M2 ROLLOFF TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Mercedes Benz MBE 450, Eaton Fuller Auto 6, Hendrickson Suspension, 9.072 FA, 20 RA, Wet Kit, 80 Gallon Aluminum Fuel Tank, Steel/Aluminum Wheels, 315/80R22.5, PTO, AC, Needs New Tires And Batteries, Rust. Showing 404,635 Miles. Location: Sacramento, CA Serial: 1FVHC7CV75HV32997 | |
| Lot # | 7 |  |
| Qty | 1 | |
| Title | 2015 MACK CXU613 DAY CAB TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Mack MP8-445C, Maxitorque T310 W/P 10 Speed, Air Ride Suspension, 12 FA, 40 RA, 189 WB, Engine Brake, 100 Gallon Aluminum Fuel Tank, Aluminum Wheels, 295/75R22.5, 455/50R22.5, PTO, AC. Showing 431,350 Miles. Location: St. Louis, MO Serial: 1M1AW07Y4FM046950 | |
| Lot # | 8 |  |
| Qty | 1 | |
| Title | 1997 MACK RD688 DUMP TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Mack E7, Eaton 8LL, Hendrickson Suspension, 242 WB, 18ft Aluminum Dump Body, Dual Aluminum Fuel Tanks, Tarp System, Two Pusher Axles, Steel Wheels, 425/65R22.5, 11R22.5, PTO, AC, Bad Rear Rear End - Oil Leaks, Left Rear Tire Flat, Mileage Incorrect, Rust. Showing 84,283 Miles; 49,535 Hours. Location: Princeton, WV Serial: 1M2P270C6VM032460 | |
| Lot # | 9 |  |
| Qty | 1 | |
| Title | 2013 JOHN DEERE 210G LC EXCAVATOR | |
| Des. | NOT TITLED PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. Fluid Residue On Lower Engine Hoses, Dried Fluid Residue On Hydraulic Mounting Pins, Minor Rust. Showing 5,796.2 Hours. See Attached Report For Additional Specifications. Location: Epping, ND Serial: 1FF210GXPDE521135 | |
| Lot # | 10 |  |
| Qty | 1 | |
| Title | 2003 KENWORTH T800 REAR MIXER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. CAT C12, Eaton 8LL, Chalmers Suspension, 204 WB, 10.5 Yrd Kimble Rear Mixer, 125 Gallon Side Mount Water Tank, Aluminum Fuel Tank, Three Chutes, Steel Wheels, 425/65R22.5, 11R24.5, PTO, AC, Rust. Showing 2,294 Miles; 22,633 Hours. Location: Louisville, TN Serial: 1NKDLU0X53J703488 | |
| Lot # | 11 |  |
| Qty | 1 | |
| Title | 2005 PETERBILT 357 CAB & CHASSIS | |
| Des. | STARTED ON SITE NOT ROAD TESTED. CAT C11, Automatic, Hendrickson Suspension, 22 FA, 46 RA, 218 WB, 205 Cab To Frame End, Aluminum Wheels, 445/65R22.5; 11R22.5, AC, Dead Batteries. Showing 232,285 Miles; 9,967 Hours. Location: Tampa, FL Serial: 1NPALT0X65D864781 | |
| Lot # | 12 |  |
| Qty | 1 | |
| Title | 2010 IMT 14-98 KNUCKLEBOOM TRUCK | |
| Des. | NOT TITLED PER STATE REGULATIONS. 23.25ft Total Length, 18.5ft Body Length, 94in Width, Rear Gate, IMT 14/98 Series Knuckleboom W/ Steel Galbreath Debris Body, Rust. Location: Des Moines, IA Serial: 1050240 | |







| | | |
|--------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| Lot # | 13 |  |
| Qty | 1 | |
| Title | 2015 MACK CXU613 DAY CAB TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Mack MP8-445C, Maxitorque T310 W/P 10 Speed, Air Ride Suspension, 12 FA, 40 RA, 189 WB, Engine Brake, 125 Gallon Aluminum Fuel Tank, Aluminum Wheels, 295/75R22.5; 455/50R22.5, PTO. Showing 502,990 Miles. Location: St. Louis, MO Serial: 1M1AW07Y6FM046951 | |
| Lot # | 14 |  |
| Qty | 1 | |
| Title | 2007 TEREX FDB4000 FRONT MIXER | |
| Des. | NON RUNNER. Cummins ISM 400, Automatic, Air Ride Suspension, 186 WB, 11 Yrd Terex Front Mixer, 250 Gallon Cross Mount Water Tank, Aluminum Fuel Tank, Extra Jump Seat, Two Chutes, Pusher Axle, Aluminum Wheels, 445/65R22.5, PTO, AC, Rust. Showing 193,797 Miles. Location: South Bethlehem, NY Serial: 5DG8AU4T570012018 | |
| Lot # | 15 |  |
| Qty | 1 | |
| Title | 1995 INTERNATIONAL 4700 MECHANICS TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. International DT466 190 HP Diesel, 6 Plus Transmission, Spring Suspension, 10.86 FA, 21 RA, 188 WB, 11ft Knapheide Service Body W/ Liftmoore 6036 Service Crane, 3ft Steel Platform, Steel Wheels, 11R22.5, Pintle Hitch, Dead Batteries, Body Damage/Rust. Showing 213,424 Miles. Location: Waterloo, NE Serial: 1HTSCAAP1SH663411 | |
| Lot # | 17 |  |
| Qty | 1 | |
| Title | 2004 MACK CV713 6X6 REAR MIXER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. ENGINE BLOW BY. MTM Bridgemaster Mixer System, Cross Mount Water Tank. Air Leak Under Cab When Shut Down, Front Axle Leaking, Window Crank Missing From Passenger Side, Interior Worn, Tires Worn, Various Body Damage/Rust. Showing 161,070 Miles; 21,016 Hours. Location: Lake Bluff, IL Serial: 1M2AG11C14M009380 | |
| Lot # | 18 |  |
| Qty | 1 | |
| Title | 2005 PETERBILT 357 CAB & CHASSIS | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. COOLANT TANK LEAKING. CAT C11, Automatic, Hendrickson Suspension, 22 FA, 46 RA, 218 WB, 212in Back Cab To End Frame, Aluminum Fuel Tank, Steel/Aluminum Wheels, 445/65R22.5; 11R22.5, AC, Engine Oil Leaks, Frame Rust. Showing 203,276 Miles; 4,197 Hours. Location: Tampa, FL Serial: 1NPALT0X75D831482 | |
| Lot # | 19 |  |
| Qty | 1 | |
| Title | 2012 MACK LEU613 GARBAGE PACKER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. REAR SUSPENSION WORN OUT. Mack MP7, Automatic, Camelback Suspension, 187 WB, 25 Yrd Heil Dual Body Packer Rear Loader, L/R Steering, Steel Wheels, 315/80R22.5, PTO, AC, Dead Batteries, Rust. Showing 107,669 Miles; 13,221 Hours. Location: Townsend, DE Serial: 1M2AU02C4CM006621 | |








| | | |
|--------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| Lot # | 20 |  |
| Qty | 1 | |
| Title | 2007 MACK CTP713 HOOKLIFT TRUCK | |
| Des. | NON RUNNER. ENGINE AND DASH MISSING PARTS. HEAVY CAB DAMAGE - UNABLE TO OPEN DOORS. Mack MP7, Automatic, Air Ride Suspension, 274 WB, 214in Back Cab To End Frame, Double Frame, Dual Aluminum Fuel Tanks, Two Pusher Axles W/O Wheels/Tires, Steel Wheels, 315/80R22.5, No Windshield, No Hood, Interior Worn/Parts In Cab, Body Damage/Rust. Mileage Unavailable. Location: Des Moines, IA Serial: 1M2AT04CX7M001736 | |
| Lot # | 21 |  |
| Qty | 1 | |
| Title | 2000 KOMATSU WA250-3MC WHEEL LOADER | |
| Des. | STARTED ON SITE - FULL OPERATIONS NOT TESTED. Komatsu S6D102E, Automatic, 108in Bucket, Steel Wheels, 20.5R25, AC/Heated Cab, Rust. Showing 14,183 Hours. Location: Des Moines, IA Serial: A71019 | |
| Lot # | 22 |  |
| Qty | 1 | |
| Title | 2003 FREIGHTLINER FL112 ROLLOFF TRUCK | |
| Des. | NON RUNNER. Cummins ISM 400 HP Diesel, Eaton Fuller Auto 6, Hendrickson Suspension, 9.072 FA, 20 RA, Wet Kit, 80 Gallon Aluminum Fuel Tank, Steel Wheels, 315/80R22.5, PTO, AC, Dash Apart, Rust. Mileage Unavailable; Showing 527 Hours. Location: Sacramento, CA Serial: 1FVHBGA803HK46499 | |
| Lot # | 23 |  |
| Qty | 1 | |
| Title | 2012 PETERBILT 386 DAY CAB TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. BRAKE PEDAL DOES NOT RETURN AFTER DEPRESSING. Minor Oil Residue At Passenger Rear Of Oil Pan, DPF Failed Due To After Treatment Fault(s), Check Engine Light Illuminated, Low Coolant Light Illuminated, Active Fault Codes - See Report, Tail Lights Wires Disconnected, Passenger Side Seat Removed, Dash Switches Worn/Damaged, Windshield Cracked, Various Body Damage/Rust. Showing 379,291 Miles; 252,453 ECM Miles; 12,824 Hours. Location: Mokena, IL Serial: 1XPHD49X3CD148637 | |
| Lot # | 24 |  |
| Qty | 1 | |
| Title | 1995 INTERNATIONAL 4700 SERVICE TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. International DT466 190 HP Diesel, 6 Plus Transmission, Spring Suspension, 10.86 FA, 21 RA, 188 WB, 11ft Knapheide Service Body, 2.75ft Steel Platform, Steel Wheels, 11R22.5, Cracked Windshield, Body Damage/Rust. Showing 253,225 Miles. Location: Waterloo, IA Serial: 1HTSCAAP3SH663412 | |
| Lot # | 25 |  |
| Qty | 1 | |
| Title | 2013 JOHN DEERE 310SK BACKHOE | |
| Des. | NOT TITLED PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. Front Loader Bucket Hydraulics Made Noise While Operating, Loader Bucket Articulation Noisy, Mesh Grill Slightly Pushed In, Minor Body Damage/Rust. See Attached Report For Additional Specifications. Showing 2,760 Hours. Location: Cheyenne, WY Serial: 1T0310SKCDE245344 | |







| | | |
|--------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| Lot # | 26 |  |
| Qty | 1 | |
| Title | 2003 KENWORTH T800 REAR MIXER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. CAT C12, Eaton 8LL, Chalmers Suspension, 204 WB, 10.5 Yrd Kimble Rear Mixer, 125 Gallon Side Mount Water Tank, Aluminum Fuel Tank, Steel Wheels, 425/65R22.5; 11R24.5, PTO, AC, Dead Batteries, Hydraulic Pump Oil Leaks, No Chutes, Rust. Showing 62,934 Miles; 19,766 Hours. Location: Louisville, TN Serial: 1NKDLU0X43J389302 | |
| Lot # | 27 |  |
| Qty | 1 | |
| Title | 2006 PETERBILT 357 CAB & CHASSIS | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. CAT C11, Automatic, Hendrickson Suspension, 22 FA, 46 RA, 218 WB, 212in Back Cab To End Frame, Aluminum Fuel Tank, Aluminum Wheels, 445/65R22.5; 11R22.5, AC, Air Leaks At Frame Rail, Engine Oil Leaks, Dead Batteries, Body Damage/Rust. Showing 272,707 Miles; 27,371 Hours. Location: Tampa, FL Serial: 1NPALT0X16D890593 | |
| Lot # | 29 |  |
| Qty | 1 | |
| Title | 2013 JOHN DEERE 210G LC EXCAVATOR | |
| Des. | NOT TITLED PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. Wet Residue On Center Gear And Frame, Minor Rust And Caked Mud. See Attached Report For Additional Specifications. Showing 4,071 Hours. Location: Gillette, WY Serial: 1FF210GXLDE521659 | |
| Lot # | 30 |  |
| Qty | 1 | |
| Title | 2014 MACK CXU613 DAY CAB TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Mack Reman MP8-445C, Maxitorque T310 W/P 10 Speed, Air Suspension, 12 FA, 40 RA, 185 WB, Engine Brake, 125 Gallon Aluminum Fuel Tank, Aluminum Wheels, 295/75R22.5; 455/50R22.5, PTO. Showing 587,352 Miles. Location: St. Louis, MO Serial: 1M1AW07Y1EM038691 | |
| Lot # | 33 |  |
| Qty | 1 | |
| Title | 1997 PETERBILT 357 WATER TRUCK | |
| Des. | NON RUNNER. CLUTCH THROW OUT BEARING BROKEN. TRANSMISSION OUTPUT SHAFT YOLK BROKEN. ENGINE LEAKS NOTED. STEERING GEAR BOX LEAK. ENGINE WIRING DAMAGE. CAT 3306, Eaton Manual, 20 FA, 23 RA, Aluminum Wheels, 445/65R22.5 (Flat Tires), Aluminum Fuel Tank, PTO, AC. Showing 307,368 Miles. Location: San Bernardino, CA Serial: 1NPALA0X7VN428746 | |
| Lot # | 34 |  |
| Qty | 1 | |
| Title | 2004 MACK CV713 6X6 REAR MIXER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. MTM Bridgmaster Mixer System, Cross Mount Water Tank. Oil Seepage At Bottom Of Block/Oil Pan And Right Side Near Oil Fill Tube, Window Crank Missing From Driver's Side, Windshield Chipped, Steer Axle Leaking, Various Body Damage/Rust. Showing 246,950 Miles; 26,543 Hours. Location: Lake Bluff, IL Serial: 1M2AG11C34M009381 | |







| | | |
|--------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| Lot # | 35 |  |
| Qty | 1 | |
| Title | 2005 MACK CV713 CAB & CHASSIS | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Mack AMI-335 ASET, Eaton Fuller 9 Speed LL, Hendrickson Suspension, 20 FA, 46 RA, 249 WB, 252in Back Cab To End Frame, 13,200 Lbs Bridge Axle, Aluminum Fuel Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Dash Missing Panels/Components - See Photos, Body Damage/Rust. Showing 128,457 Miles; 20,060 Hours. Location: Elgin, IL Serial: 1M2AG11C35M017532 | |
| Lot # | 36 |  |
| Qty | 1 | |
| Title | 2014 FORD F150 EXT CAB PICKUP TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Ford 5.0L Gas, Automatic, Spring Suspension, 3.45 FA, 3.85 RA, 145 WB, Two Storage Boxes, Alloy Wheels, 245/7R17, AC, PW, PL, PM, Check Engine Light Illuminated. Showing 86,683 Miles. Location: Waterloo, NE Serial: 1FTFX1CF9EKD76218 | |
| Lot # | 37 |  |
| Qty | 1 | |
| Title | 2001 VOLVO L90D WHEEL LOADER | |
| Des. | NOT TITLED PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. Oil Leak On Left Side OF Engine, Horn Inop, Several Lights Inop, Corner Seam Of Rear Window Duct Taped, Wiper Removed, Various Body Damage/Rust. Showing 22,968 Hours. Location: Hampshire, IL Serial: 64500 | |
| Lot # | 39 |  |
| Qty | 1 | |
| Title | 2015 MACK CXU613 DAY CAB TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Mack MP8-445C, Maxitorque T310 W/P 10 Speed, Air Ride Suspension, 12 FA, 40 RA, 185 WB, Engine Brake, 100 Gallon Fuel Tank, Aluminum Wheels, 295/75R22.5; 455/50R22.5, PTO, AC. Showing 514,447 Miles. Location: St Louis, MO Serial: 1M1AW07Y1FM046954 | |
| Lot # | 41 |  |
| Qty | 1 | |
| Title | 1997 NEW HOLLAND 555E 4X4 BACKHOE | |
| Des. | STARTED ON SITE - FULL OPERATIONS NOT TESTED. New Holland Diesel, 4 Speed Manual, 88in Front Bucket, 23in Rear Bucket, Steel Wheels, 12x16.5; 19.5L-24, AC/Heated Cab, Rust. Showing 3,558 Hours. Location: Des Moines, IA Serial: 031005960 | |
| Lot # | 42 |  |
| Qty | 1 | |
| Title | 2003 KENWORTH T800 REAR MIXER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. CAT C12, Eaton 8LL, Chalmers Suspension, 204 WB, 10.5 Yrd Kimble Rear Mixer, 125 Gallon Side Mount Water Tank, Aluminum Fuel Tank, Three Chutes, Steel Wheels, 425/65R22.5; 11R24.5, PTO, AC, Rust. Showing 230,576 Miles; 22,516 Hours. Location: Louisville, TN Serial: 1NKDLU0X03J389300 | |
| Lot # | 43 |  |
| Qty | 1 | |
| Title | 2009 VOLVO VNL64T CAB & CHASSIS | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Leak At Left Side Of Oil Pan, Marker Lights Will Not Turn Off, Driver Side Mirrors Missing/Damaged, Hole In Bottom Of Secondary Tank On Passenger Side Rear - Used As Water Tank, Dump Bed Cylinder Leaking, Active Fault Codes - See Report, Transmission Leaking At PTO, Various Body Damage/Rust. Showing 474,778 Miles; 22,749 Hours. Location: Columbus, IN Serial: 4V5NC9EG79N271273 | |







| | | |
|--------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| Lot # | 44 |  |
| Qty | 1 | |
| Title | 2019 PETERBILT 520 GARBAGE PACKER | |
| Des. | FIRE DAMAGE. NON RUNNER. ECM DAMAGE. Cummins ISL12, Automatic, Hendrickson Suspension, 20 FA< 46 RA, 205 WB, 28 YRD. Heil Front Loader, Aluminum Wheels, 315/80R22.5, PTO, AC, Less Batteries, Drive Line Removed W/ Unit. Mileage Unavailable. Location: Jacksonville, FL Serial: 3BPDL70X3KF161851 | |
| Lot # | 45 |  |
| Qty | 1 | |
| Title | 2013 LINK BELT 210X3 EXCAVATOR | |
| Des. | NOT TITLED PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. ENGINE HISSES UPON START UP. Check Engine Light Illuminated, Windshield Wiper Broken Off, Suspension Worn, Interior Worn, Dried Fluid And Discoloration At Upper Cylinder, Noise From Undercarriage Wear, Various Body Damage/Rust. See Attached Report For Additional Specifications. Showing 5,698.8 Hours. Location: Epping, ND Serial: EHDK3-7568 | |
| Lot # | 46 |  |
| Qty | 1 | |
| Title | 2013 FORD F150 XL EXT CAB 4X4 PICKUP TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. ROUGH IDLES. ENGINE NOISE. Ford 5.0L Gas, Automatic, Spring Suspension, 3.9 FA, 3.85 RA, 163 WB, Long Bed, Alloy Wheels, 265/70R17, AC, PW, PL, PS, PM, Check Engine Light Illuminated, Dead Batteries, Body Rust. Showing 128,318 Miles. Location: Waterloo, NE Serial: 1FTFX1EF7DKF43154 | |
| Lot # | 47 |  |
| Qty | 1 | |
| Title | 2012 PETERBILT 386 DAY CAB TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Oil Seepage Noted On Drivers Side Of Engine Above Oil Pan And At Front Of Oil Pan, DPF Failed Due To After Treatment Fault(s), Check Engine Light Illuminated, Active Fault Codes - See Report, Windshield Chipped, Power Mirrors Inop, Power Steering Leaking, Passenger Seat Removed, Interior Worn, Various Body Damage/Rust. Showing 425,899 Miles; 151,406 ECM Miles; 13,990 Hours. Location: Mokena, IL Serial: 1XPHD49X6CD148664 | |
| Lot # | 50 |  |
| Qty | 1 | |
| Title | 2005 PETERBILT 357 REAR MIXER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. ENGINE BLOW BY. Cummins ISL Diesel, Eaton 9 Speed LL, Hendrickson Suspension, 22 FA, 46 RA, 224 WB, 11 Yrd McNeilus Rear Mixer, 125 Gallon Side Mount Water Tank, 50 Gallon Aluminum Fuel Tank, Steel Wheels, 385/65R22.5; 11R22.5, PTO, AC, Rust. Showing 48,450 Miles; 9,856 Hours. Location: Dallax, TX Serial: 1NPAL50X05D884648 | |
| Lot # | 51 |  |
| Qty | 1 | |
| Title | 2005 PETERBILT 357 CAB & CHASSIS | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. CAT C11, Automatic, Hendrickson Suspension, 22 FA, 46 RA, 215 WB, 205in Back Cab To End Frame, Aluminum Fuel Tank, Aluminum Wheels, 425/65R22.5; 11R22.5, AC, Air Leak At Frame Rail, Body Damage/Rust. 311,400 Miles; 9,777 Hours. Location: Tampa, FL Serial: 1NPALT0X65D831473 | |








| | | |
|--------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| Lot # | 52 |  |
| Qty | 1 | |
| Title | 2002 OSHKOSH S-2346 FRONT MIXER | |
| Des. | RUNNING CONDITION UNKNOWN. MISSING BATTERY CABLE AND BATTERIES. LESS KEY. Cummins ISM 350, Automatic, Chalmers Suspension, 22 FA, 46 RA, 196 WB, 11 Yrd Oshkosh Front Mixer, 200 Gallon Cross Mount Water Tank, Aluminum Fuel Tank, Tag Axle, Two Chutes, Aluminum/Steel Wheels, 445/65R22.5; 11R24.5, PTO, AC, Body Damage/Rust. Mileage Unavailable. Location: South Bethelham, NY Serial: 10TFAAC282S074652 | |
| Lot # | 53 |  |
| Qty | 1 | |
| Title | 2004 JOHN DEERE 544J WHEEL LOADER | |
| Des. | NOT TITLED PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. John Deere 6 Cyl Diesel, Automatic, Enclosed ROPS, 99x49in Bucket, Steel Wheels, 20.5R25, AC/Heated Cab, Rust. Showing 13,587 Hours. Location: Raleigh, NC Serial: DW544JZ593283 | |
| Lot # | 55 |  |
| Qty | 1 | |
| Title | 2012 PETERBILT 386 DAY CAB TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. BLOW BY. Oil Seepage Noted On Both Sides Of Engine/Oil Pan, Low Fuel Warning Illuminated, Rear Cross Member Bent, Windshield Chipped, Hood Safety Stay Removed, Steer Axle Brakes Worn, Power Steering Leaking, Passenger Side Seat Missing, Interior Worn, City Horn Inop, Body Damage/Rust. Showing 325,912 Miles; 14,069 Hours. Location: Mokena, IL Serial: 1XPHD49X3CD148640 | |
| Lot # | 56 |  |
| Qty | 1 | |
| Title | 2007 INTERNATIONAL 7400 GARBAGE PACKER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. COULD NOT MOVE - UNIT BLOCKED IN. International DT466E, Automatic, Hendrickson Suspension, 16 FA, 40 RA, 228 WB, 25 Yrd Heil Rear Loader, Two Can Tippers, L/R Steering, Steel Wheels, 315/80R22.5, PTO, AC, Backup Camera, Engine Oil Leaks, Dead Batteries, Rust. Showing 184,509 Miles; 24,099 Hours. Location: Street, MD Serial: 1HTWGAZT57J562637 | |
| Lot # | 57 |  |
| Qty | 1 | |
| Title | 2013 LINK BELT 210X3 EXCAVATOR | |
| Des. | NOT TITLED PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. Repairs Present On Roof Panel And Junction Block, Main Boom Cylinder Wet At Bottom, Dried Fluid Seepage/Discoloration On Some Cylinder End Caps And Pins, Undercarriage Noisy, One Bucket Deflector Broken, Interior Worn, Various Body Damage/Rust. See Attached Report For Additional Specifications. Showing 5,512.5 Hours. Location: Epping, ND Serial: EHDK3-7341 | |
| Lot # | 59 |  |
| Qty | 1 | |
| Title | 2006 PETERBILT 357 CAB & CHASSIS | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. CAT C9, Automatic, Hendrickson Suspension, 22 FA, 46 RA, 220 WB, 212in Back Cab To End Frame, Aluminum Fuel Tank, Aluminum Wheels, 445/65R22.5; 11R22.5, AC, Missing HVAC Controls, Body Damage/Rust. Showing 173,683 Miles; 30,178 Hours. Location: Tampa, FL Serial: 1NPALF0X96N633760 | |







| | | |
|--------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| Lot # | 60 |  |
| Qty | 1 | |
| Title | 2012 FORD F150 XL EXT CAB PICKUP TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Ford 5.0L Gas, Automatic, Spring Suspension, 3.45 FA, 3.8 RA, 145 WB, Alloy Wheels, 245/70R17, AC, PW, PL, PM, Body Rust. Showing 133,369 Miles. Location: Waterloo, NE Serial: 1FTFX1CF2CKD69852 | |
| Lot # | 61 |  |
| Qty | 1 | |
| Title | 2013 CATERPILLAR 14M MOTOR GRADER | |
| Des. | NOT TITLED PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. Windshield Cracked, Service Indicator Light Illuminated, Tires Worn, Rust. See Attached Report For Additional Specifications. Showing 4,393 Hours. Location: Gillette, WY Serial: R9J01091 | |
| Lot # | 63 |  |
| Qty | 1 | |
| Title | 2012 PETERBILT 386 DAY CAB TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Oil Seepage Noted At Oil Pan And Drain Plug, Rear Cross Member Bent/Damaged, Passenger Side Mirror Cracked, Passenger Side Seat Missing, Interior Worn, Various Body Damage/Rust. Showing 392,537 Miles; 13,073 Hours. Location: Mokena, IL Serial: 1XPHD49XXCD148649 | |
| Lot # | 64 |  |
| Qty | 1 | |
| Title | 2008 FORD F150 EXT CAB PICKUP TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Ford 4.6L Gas, Automatic, Spring Suspension, 3.45 FA, 3.8 RA, 145 WB, Long Bed, Steel Wheels, 235/75R17, AC, PW, PL, PM, Tire Pressure Light Illuminated, Rust. Showing 90,599 Miles. Location: Waterloo, NE Serial: 1FTRX12W68FB59589 | |
| Lot # | 66 |  |
| Qty | 1 | |
| Title | 2006 PETERBILT 357 REAR MIXER | |
| Des. | NON RUNNER. ENGINE LOCKED UP. Cummins ISL, Eaton 8 Speed LL, Hendrickson Suspension, 22 FA, 46 RA, 224 WB, McNeilus Rear Mixer, Side Mount Water Tank, Aluminum Fuel Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Filler Call Missing, Chute Ram Disconnected, Body Damage/Rust. Showing 103,539 Miles; 5,208 Hours. Location: Dallas, TX Serial: 1NPAL50XX6D884657 | |
| Lot # | 67 |  |
| Qty | 1 | |
| Title | 2006 PETERBILT 357 CAB & CHASSIS | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. ENGINE SKIP. CAT C9, Automatic, Hendrickson Suspension, 22 FA, 44 RA, 218 WB, 212in Back Cab To End Frame, Aluminum Fuel Tank, Aluminum Wheels, 445/65R22.5; 11R22.5, AC, Body Damage/Rust. Showing 178,098 Miles; 28,347 Hours. Location: Tampa, FL Serial: 1NPALF0X36N633785 | |
| Lot # | 68 |  |
| Qty | 1 | |
| Title | 2008 FREIGHTLINER M2106 GARBAGE PACKER | |
| Des. | NON RUNNER. FIRE DAMAGE TO BODY. HOLE IN LEFT SIDE BODY. MISSING HYDRAULIC VALVES AND HOSES. Cummins ISC Diesel, Automatic, Hendrickson Suspension, 14.6 FA, 46 RA, 226 WB, 25 Yrd McNeilus Rear Packer, Two Can Tippers, Steel Wheels, 315/80R22.5, PTO, AC, Missing Fan Shroud, Top Valve Cover Loose, Body Damage/Rust. Mileage Unavailable. Location: Faiburn, GA Serial: 1FVHCYBS28HZ17627 | |








| | | |
|--------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| Lot # | 69 |  |
| Qty | 1 | |
| Title | 2014 CATERPILLAR D6T XW DOZER-CRAWLER | |
| Des. | NOT TITLED PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. One Joystick Button Missing, Small Puff Of Black Smoke At Startup - Clear At Operating Temp, Dried Mud On Undercarriage, Various Rust. See Attached Report For Additional Specifications. Showing 2,383 Hours. Location: Gillette, WY Serial: RCW01578 | |
| Lot # | 70 |  |
| Qty | 1 | |
| Title | 1999 VOLVO WG64 ROLLOFF TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Oil Leak At Pan/Rear Seal And Left Rear Of Block, Fluid Seepage At Front Drive Shaft, Fluid Seepage At Power Steering Reservoir, Fluid Leaks At Hydraulics, Passenger Mirror Wiring Broken, Spot Mirrors Cracked, Several Lights Inoperable - See Report, City Horn Inop, Various Body Damage/Rust. Showing 395,161 Miles; 1,541 Hours. Location: Indianapolis, IN Serial: 4VHJCCJF8XN866738 | |
| Lot # | 71 |  |
| Qty | 1 | |
| Title | 2006 FREIGHTLINER M2112 DAY CAB TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Oil Leak At Oil Pan And Right Side Fitting, City Horn Inop, Active Fault Codes - See Report, Rear Inner Tires/Wheels Missing, Various Body Damage/Rust. 331,725 Miles; 14,374 Hours. Location: Indianapolis, IN Serial: 1FUJC5CV26HV90723 | |
| Lot # | 72 |  |
| Qty | 1 | |
| Title | 2010 FORD F150 XL EXT CAB PICKUP TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Ford 4.6L Gas, Automatic, Spring Suspension, 3.45 FA, 3.8 RA, 145 WB, Storage Box, Steel Wheels, 245/70R17, AC, PW, PL, PM, Tire Pressure Light Illuminated, Body Damage/Rust. Showing 112,490 Miles. Location: Waterloo, NE Serial: 1FTEX1C89AFB98889 | |
| Lot # | 73 |  |
| Qty | 1 | |
| Title | 2000 CASE 621C WHEEL LOADER | |
| Des. | NOT TITLED PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. ACCELERATOR PEDAL STICKS. LOW HYDRAULIC OIL. Case Cummins 6 Cyl Diesel, Automatic, Enclosed ROPS, 101x48in Bucket, Steel Wheels, 20.5R25, AC/Heated Cab, Lift Cylinders Leak, Hydraulic Leaks, Flat Tire, Dead Batteries, Rust. Showing 1,487 Hours. Location: Raleigh, NC Serial: JEE0124960 | |
| Lot # | 74 |  |
| Qty | 1 | |
| Title | 2002 KENWORTH T800 REAR MIXER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. CAT C12, Eaton 8LL, Chalmers Suspension, 204 WB, 10.5 Yrd Kimble Rear Mixer, 125 Gallon Side Mount Water Tank, Aluminum Fuel Tank, Three Chutes, Steel Wheels, 425/65R22.5; 11R24.5, PTO, AC, Fuel Line Leaks, Hydraulic Pump Leaks, Rust. Showing 6,620 Miles; 8,670 Hours. Location: Louisville, TN Serial: 1NKDLU0XX2J703484 | |








| | | |
|-------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| Lot # | 75 |  |
| Qty | 1 | |
| Title | 2006 KENWORTH W900B CAB & CHASSIS | |
| Des. | STARTED ON SITE, NOT ROAD TESTED. TRANSMISSION COATED IN OIL. LEAKS NOTED AT OIL PAN AND L/SIDE VALVE COVER. Cummins ISM 10.8L 320 HP, OD, Cruise, Eaton RTO14909ALL-9LL, Chalmers Suspension, 20 FA, 46 RA, 248 WB, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, Power Steering, AM/FM/CD, Power/Heated Mirrors, Inactive Fault Codes 654-5, 655-5, 653-5 Noted On ECM, ABS Warning Light Illuminated, Body Damage/Rust. Showing 144,514 Miles' 26,543 Hours. Location: Mokena, IL Serial: 1NKWL00X96R125340 | |
| Lot # | 77 |  |
| Qty | 1 | |
| Title | 2013 CATERPILLAR 279C2 SKID LOADER | |
| Des. | NOT TITLED PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. Glass Roof Weather Stripping Repaired With Caulk, One Overhead Fixture Missing In Cabin, One Light Lens Cover Broken, Rust. See Attached Report For Additional Specifications. Showing 2,309.6 Hours. Location: Gillette, WY Serial: 0KWB01047 | |
| Lot # | 78 |  |
| Qty | 1 | |
| Title | 2008 FORD F150 EXT CAB PICKUP TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. ROUGH IDLE. Ford 4.6L Gas, Automatic, Spring Suspension, 3.45 FA, 3.8 RA, 145 WB, Steel Wheels, 245/70R17, AC, PW, PL, PM, ABS Warning Light Illuminated, Body Damage/Rust. Showing 114,593 Miles. Location: Waterloo, NE Serial: 1FTRX12W28FB59590 | |
| Lot # | 79 |  |
| Qty | 1 | |
| Title | 2004 MACK CX613 DAY CAB TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. SMOKE NOTED FROM EXHAUST STACK. Oil Leaks At Pan/Rear Seal And Both Sides Of Block, Front Drive Leaking, Transmission Leaking, Active Fault Code - See Report, Several Lights Inoperable - See Report, Windshield Chipped, Tires Worn, Missing Right Side Spot Mirror, Various Body Damage/Rust. Showing 547,409 Miles; 29,628 Hours. Location: Indianapolis, IN Serial: 1M1AE06YX4N019084 | |
| Lot # | 80 |  |
| Qty | 1 | |
| Title | 2005 YALE GDP155CANPBV147 FORKLIFT | |
| Des. | NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. Perkins 4 Cyl Diesel, Automatic, Open ROPS, 12.25ft Height, Sixteen 48x1.5in Forks, Two Masts, Steel Wheels, 8.25-15, Seat Torn, Rust. Showing 9,348 Hours. Location: Lakeland, FL Serial: B878V01791C | |
| Lot # | 81 |  |
| Qty | 1 | |
| Title | 2014 CATERPILLAR D6T XW DOZER-CRAWLER | |
| Des. | NOT TITLED PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. Thick Mud Dried On Undercarriage And Other Components, Uneven Grousers, Rust. Showing 2,151 Hours. See Attached Report For Additional Specifications. Location: Epping, ND Serial: RCW01590 | |








| | | |
|--------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| Lot # | 82 |  |
| Qty | 1 | |
| Title | 2005 INTERNATIONAL 5600i 6X4 REAR MIXER | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. ENGINE IN POOR CONDITION - USES OIL. BLOW BY. Cummins ISM 305 HP, Eaton 8LL, Chalmers Suspension, 20 FA, 46 RA, 212 WB, 10.5 Yrd McNeilus Rear Mixer, 125 Gallon Side Mount Water Tank, Aluminum Fuel Tank, Three Chutes, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Dead Batteries, Rust. Showing 151,579 Miles; 18,279 Hours. Location: Louisville, TN Serial: 1HTXHAHT25J150613 | |
| Lot # | 83 |  |
| Qty | 1 | |
| Title | 2005 PETERBILT 357 CAB & CHASSIS | |
| Des. | STARTED ON SITE- BRAKE PEDAL FROZEN. CAT C11, Automatic, Hendrickson Suspension, 22 FA, 46 RA, 218 WB, 208 Cab To Frame End, Aluminum Wheels, 445/65R22.5; 12R22.5, AC, Dead batteries. Showing 282,100 Miles; 1,035 Hours. Location: Tampa, FL Serial: 1NPALT0X35D831513 | |
| Lot # | 85 |  |
| Qty | 1 | |
| Title | 2001 JOHN DEERE 5444H WHEEL LOADER | |
| Des. | NOT TITLED PER STATE REGULATIONS. NON RUNNER. TRANSMISSION GEAR SHIFTER MISSING OFF OF STEERING COLUMN. LESS KEY. John Deere 6 Cyl Diesel, Automatic, Enclosed ROPS, 99x45in Bucket, Steel Wheels, 20.5R25, AC, Flat Tire, Rust. Showing 13,762 Hours. Location: Winston Salem, NC Serial: DW544HX580240 | |
| Lot # | 86 |  |
| Qty | 1 | |
| Title | 2002 FREIGHTLINER FL112 ROLLOFF TRUCK | |
| Des. | NON RUNNER. DASH APART/MISSING. UNABLE TO ASSESS SYSTEMS. DATA PLATES MISSING. DRIVE LINE REMOVED. DRIVER DOOR MISSING. Oil Leaks Around Pan/Bottom Of Block, Hole In Middle Of Oil Filler Tube, Red Fluid Seeping From Fitting Next To Front Left Side Of Pan, Power Steering Leak Around Reservoir/Lines, Interior Heavily Worn, Inner Tires Missing At Rear Drives, Rear Differentials Leaking, Hydraulics Leaks Throughout System, Transmission Covered In Oil, Body Damage/Rust. Mileage Unavailable. Location: Indianapolis, IN Serial: 1FVHBGA8X2HJ67159 | |
| Lot # | 87 |  |
| Qty | 1 | |
| Title | 2004 MACK CH613 DAY CAB TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Heavy Oil Residue Covering Both Sides Of Engine, Oil Leak At Pan/Rear Seal And Front Cover, City Horn Inop, Hydraulic Tank Damaged, Accessory Drive Belts Worn, Cat Walk Damaged, Power Steering Leaking, Windshield Chipped, Dash Cover Removed On Right Side, Left Rear Drive Shock Leaking, Door Panels Damaged/Missing Parts, Various Body Damage/Rust. Showing 39,798 Miles; 1,617 Hours. Location: Melvindale, MI Serial: 1M1AA18Y84N156829 | |
| Lot # | 88 |  |
| Qty | 1 | |
| Title | 2008 FORD F150 EXT CAB PICKUP TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Ford 4.6L Gas, Automatic, Spring Suspension, 3.45 FA, 3.8 RA, 145 WB, Short Bed, Steel Wheels, 245/70R17, AC, PW, PL, PM, Rust. Showing 150,641 Miles. Location: Waterloo, NE Serial: 1FTRX12W48FB59588 | |





| | | |
|--------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| Lot # | 90 |  |
| Qty | 1 | |
| Title | 2003 KENWORTH T800 REAR MIXER | |
| Des. | NON RUNNER. CRANKS NO START. CAT C12, Eaton 8LL, Chalmers Suspension, 204 WB, 10.5 Yrd Kimble Rear Mixer, 125 Gallon Side Mount Water Tank, Aluminum Fuel Tank, Three Chutes, Steel Wheels, 425/65R22.5; 11R24.5, PTO, AC, Left Door Damaged, Rust. Showing 47,717 Miles; 10,333 Hours. Location: Louisville, TN Serial: 1NKDLU0X23J389301 | |
| Lot # | 91 |  |
| Qty | 1 | |
| Title | 2007 PETERBILT 357 CAB & CHASSIS | |
| Des. | NON RUNNER. MISSING ENGINE FUEL PUMP. DRIVE LINE REMOVED WITH TRUCK. CAT C9, Automatic, Hendrickson Suspension, 20 FA, 46 RA, 228 WB, 218in Back Cab To End Frame, Double Frame, Pusher Axle, Aluminum Fuel Tank, Aluminum/Steel Wheels, 445/65R22.5; 11R22.5, AC, Missing Right Door Latch, Rust. Mileage Unavailable. Location: Tampa, FL Serial: 1NPALFEX17D648429 | |
| Lot # | 92 |  |
| Qty | 1 | |
| Title | 2010 FORD F150 XLT EXT CAB 4X4 PICKUP TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Ford Triton 5.4L V8, Automatic, Spring Suspension, 3.75 FA, 3.85 RA, 145 WB, 6ft Box, Alloy Wheels, 265/70R17, AC, PW, PL, PM, Brake Light Illuminated - Check Brake System Reading On Dash, Check Fuel Fill Inlet Reading On Dash, ABS Warning Light Illuminated, Body Damage/Rust. Showing 261,835 Miles. Location: Waterloo, NE Serial: 1FTFX1EV6AFB98887 | |
| Lot # | 93 |  |
| Qty | 1 | |
| Title | 2013 CATERPILLAR D6TXW DOZER-CRAWLER | |
| Des. | NOT TITLED PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. Some Exhaust Smoke At Start Up And Until Unit Warmed, One Tie Down Strap And Exterior Bracket Damaged, Minor Rust. See Attached Report For Additional Specifications. Showing 4,117.9 Hours. Location: Epping, ND Serial: CAT00D6TVRCW01370 | |
| Lot # | 94 |  |
| Qty | 1 | |
| Title | 2004 HEIL BULK 1040 CU FT PNEUMATIC TRAILER | |
| Des. | CRACKS IN TANK - SEE PHOTOS. No Power To Check Lights, Front Post Missing Hose Hook, Landing Gear Crank Stowage Hook Bent, Several Repair Welds Throughout Tank, Tires Worn, Various Body Damage/Rust. Location: Mokena, IL Serial: 5HTSN432447T10062 | |
| Lot # | 95 |  |
| Qty | 1 | |
| Title | 2005 MACK CHN613 DAY CAB TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. DEAD BATTERIES - DO NOT TAKE CHARGE. Oil Leak At Pan, Active Fault Codes - See Report, Coolant Reservoir Empty - Dark Staining Inside, Right Fuel Tank Missing Cap, PTO Handle Broken Off, Turn Signals Inop., Horn Taped In Place - See Photos, Various Body Damage/Rust. Showing 721,743 Miles; 38,979 Hours. Location: Melvindale, MI Serial: 1M1AJ06Y75N001381 | |
| Lot # | 96 |  |
| Qty | 1 | |
| Title | 2004 HYSTER H60XM FORKLIFT | |
| Des. | NOT TITLED PER STATE REGULATIONS. NON RUNNER. BATTERIES AND FUEL LINE REMOVED. Automatic, Two Forks, 28x9-15/7.00; 6.5x10/5.00, Seat Torn, Body Damage/Rust. Hours Unavailable. Location: Seattle, WA Serial: H177B53280B | |

| | | |
|--------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| Lot # | 97 |  |
| Qty | 1 | |
| Title | 2006 JOHN DEERE 700J PIPE LAYER | |
| Des. | NOT TITLED PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. Dash Missing Switch, Hour Meter Inop, Seat Torn, One External Hydraulic Latch Control Broken, Grill Damaged, Side Engine Panel Missing, Various Body Damage/Rust. See Attached Report For Additional Specifications. Hours Unavailable. Location: Epping, MD Serial: T0700JX123798 | |
| Lot # | 98 |  |
| Qty | 1 | |
| Title | 2005 INTERNATIONAL 5600I 6X4 REAR MIXER | |
| Des. | NON RUNNER. DRUM FULLY LOADED WITH CEMENT. BODY DAMAGE - HAS BEEN ROLLED OVER ON LEFT SIDE. MISSING DRIVER'S SEAT. Cummins ISM 320 HP, Eaton 8LL, Chalmers Suspension, 20 FA, 46 RA, 212 WB, 10.5 Yrd McNeilus Rear Mixer, 125 Gallon Side Mount Water Tank, Aluminum Fuel Tank, Three Chutes, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 151,558 Miles; 18,349 Hours. Location: Louisville, TN Serial: IHTXHAHT45J150550 | |
| Lot # | 99 |  |
| Qty | 1 | |
| Title | 1985 INTERNATIONAL 5070 4X4 CAB & CHASSIS | |
| Des. | NON RUNNER. DASH APART, COMPONENTS MISSING. Cummins L10, Allison, Spring Suspension, 192 WB, Steel Wheels, Body Damage/Rust. Mileage Unavailable. Location: Miami, FL Serial: 2HTTNKCT4FCA14748 | |
| Lot # | 100 |  |
| Qty | 1 | |
| Title | 2010 FORD F150 XLT EXT CAB 4X4 PICKUP TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Ford 5.4L Gas, Automatic, Spring Suspension, 3.75 FA, 3.85 RA, 145 WB, 6.5ft Box, Alloy Wheels, 265/70R17, AC, PW, PL, PM, Check Engine Light Illuminated, Left Rear Door Does Not Open, Body Damage/Rust. Showing 176,749 Miles. Location: Waterloo, NE Serial: 1FTFX1EV2AKC52645 | |
| Lot # | 102 |  |
| Qty | 1 | |
| Title | 2001 MACK RD688S ROLLOFF TRUCK | |
| Des. | NON RUNNER. KNOWN ENGINE ISSUES. DRIVE SHAFT REMOVED. Oil Leak At Fill Tube, Dipstick Missing, Windshield Chipped, Rear Tarp Frame Mountings Broken/Missing, Hydraulic Tank Missing Cap, Tires Worn, Drop Axle Missing Tires/Wheels, PTO Leaking, Front Drive Leaking, Various Body Damage/Rust. Showing 378,699 Miles; 6,432 Hours. Location: Indianapolis, IN Serial: 1M2P267C81M056785 | |
| Lot # | 103 |  |
| Qty | 1 | |
| Title | 2006 VOLVO VNL64T DAY CAB TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. ENGINE SKIP. Volvo VTC D12, Eaton 10 Speed, Air Ride Suspension, Air Slide Fifth Wheel, Dual Aluminum Fuel Tanks, Wet Kit, Aluminum/Steel Wheels, 275/80R22.5; 295/75R22.5, PTO, AC, Dead Batteries, Dash Inoperable, Rust. Mileage Unavailable. Location: Ellenwood, GA Serial: 4V4NC9GF26N426381 | |

| | | |
|--------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| Lot # | 104 |  |
| Qty | 1 | |
| Title | 2002 FORD F150 PICKUP TRUCK | |
| Des. | NON RUNNER. LESS KEYS. DEAD BATTERIES. Oil Leaks At Top Of Block And Oil Pan, Differential Leaking, Transmission Leaking, Interior Worn, Various Body Damage/Rust. Mileage Unavailable. Location: Indianapolis, IN Serial: 1FTRF17252NB75109 | |
| Lot # | 106 |  |
| Qty | 1 | |
| Title | 2004 HEIL BULK 1040 CU FT PNEUMATIC TRAILER | |
| Des. | No Power To Check Lights, Front Hose Post Damaged And Missing Hose Hook, Gauge Box Door Missing Latch - Held Closed W/ Bungee, Storage Tube Door And Latch Missing, Storage Tube Forward Mount Bent, Sensor Hanging From Rear Undercarriage, Cracks And Weld Repairs Throughout, Various Body Damage/Rust. Location: Mokena, IL Serial: 5HTSN432047T10060 | |
| Lot # | 107 |  |
| Qty | 1 | |
| Title | 2006 MACK CV713 CAB & CHASSIS | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. DRIVE SHAFT REMOVED. DASH APART. LEFT REAR SUSPENSION NOT ATTACHED. Mack AI-350 ASET, Allison 4500RDS Automatic, Hendrickson Suspension, 18 FA, 46 RA, 270 WB, 227in Back Cab To End Frame, Dual 81 Gallon Aluminum Fuel Tanks, Double Frame, Steel Wheels, 315/80R22.5, PTO, Warning Lights Active, No Battery Box Cover, No Heater Controls, Dead Batteries, Rear Tires Outers Only, Body Damage/Rust. Showing 649,019 Miles; 28,456 Hours. Location: Des Moines, IA Serial: 1M2AG11C46M052436 | |
| Lot # | 108 |  |
| Qty | 1 | |
| Title | 2005 FORD F150 XL EXT CAB PICKUP TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. ROUGH IDLE. Ford Triton V8 4.6L Gas, Automatic, Spring Suspension, 3.45 FA, 3.8 RA, 145 WB, Storage Box, Steel Wheels, 245/70R17, AC, Several Warning Lights Illuminated, Including: Check Engine, Battery, And Brake Lights, Tailgate Does Not Go Down, Body Damage/Rust. Showing 89,557 Miles. Location: Waterloo, NE Serial: 1FTRX12W55FA98571 | |
| Lot # | 109 |  |
| Qty | 1 | |
| Title | 1998 SULLIVAN 185 AIR COMPRESSOR | |
| Des. | STARTS AND RUNS - FULL OPERATIONS NOT TESTED. John Deere, Steel Wheels, ST205/75R15, Pintle Hitch, Body Damage/Rust. Showing 1,024 Hours. Location: Des Moines, IA Serial: 004-127118 | |
| Lot # | 111 |  |
| Qty | 1 | |
| Title | 2009 CATERPILLAR GC20K LP FORKLIFT | |
| Des. | NOT TITLED PER STATE REGULATIONS. NON RUNNER. KNOWN PROBLEMS WITH PROPANE VALVE TO RUN ENGINE. LESS PROPANE TANK. Mitsubishi 4 Cyl Gas, Automatic, Open ROPS, 6.75ft Height, Two 42x4in Forks, Two Masts, Steel Wheels, 21x7x15, Forks Removed With Machine, Rust. Showing 10,844 Hours. Location: Fairburn, GA Serial: AT82C-90788 | |
| Lot # | 112 |  |
| Qty | 1 | |
| Title | 2000 FORD F150 XL PICKUP TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Ford 4.2L Gas, Automatic, Spring Suspension, 2.95 FA, 3.8 RA, 139 WB, Long Bed, Steel Wheels, 255/70R16, AC, Dead Batteries, Body Damage/Rust. Showing 67,319 Miles. Location: Waterloo, NE Serial: 1FTZF1726YKB14118 | |

| | | |
|--------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| Lot # | 113 |  |
| Qty | 1 | |
| Title | 1990 INTERNATIONAL 4700 FLATBED TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. International DT360 170 Diesel, 5 Speed Transmission W/ Two Speed Rear End, Spring Suspension, 12 FA, 21 RA, 188 WB, 14ft Steel Omaha Standard Flatbed Body, Two Left Side Toolboxes, Steel/Spoke Wheels, 11R22.5, Pintle Hitch, Missing Batter Box Cover, Rust. Showing 222,734 Miles. Location: Waterloo, NE Serial: 1HTSCZWP6LH225332 | |
| Lot # | 114 |  |
| Qty | 1 | |
| Title | 1997 HEIL BULK PNEUMATIC TRAILER | |
| Des. | 1040 Cubic Ft Capacity. Landing Gear Crank Handle Held On W/ Bungee Cord, Mudflap Brackets Bent On Both Sides, Ladder Bottom Rung Cracked Off On Forward Tube, Gauge Box Lid Held Closed W/ Bungee, Several Rips Noted In Metal, Various Body Damage/Rust. Location: Oak Creek, WI Serial: 5HTSN4224V7T04491 | |
| Lot # | 115 |  |
| Qty | 1 | |
| Title | 2006 MACK CV713 CAB & CHASSIS | |
| Des. | NON RUNNER. MISSING COMPONENTS, INCLUDING: TRANSMISSION, CLUTCH, #1 AND 2 INJECTORS, INTAKE HOSE AND PIPE, REAR REAR HUBS, BRAKE DRUMS, AND TIRES. Mack AMI-370 ASET, Camelback Suspension, 262 WB, Double Frame, Steerable Pusher Axle, Steel Fuel Tank, Steel Wheels, 315/80R22.5, AC, Interior Worn/Passenger Seat Not Attached, Body Damage/Rust. Mileage Unavailable. Location: Chesapeake, VA Serial: 1M2AG11C36M035448 | |
| Lot # | 116 |  |
| Qty | 1 | |
| Title | 2004 FORD F250 EXT CAB XL PICKUP TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. REAR DOORS WILL NOT OPEN. Ford Triton V8 5.4L Gas, Automatic, Spring Suspension, 4.1 FA, 6.084 RA, 158 WB, Long Bed, Steel Wheels, 235/85R16, AC, Body Damage/Rust. Showing 180,063 Miles. Location: Waterloo, NE Serial: 1FTNX20L64ED82065 | |
| Lot # | 117 |  |
| Qty | 1 | |
| Title | 1998 SULLIVAN 185 AIR COMPRESSOR | |
| Des. | STARTS AND RUNS - FULL OPERATIONS NOT TESTED. Diesel, Steel Wheels, ST205/75D15, Pintle Hitch, Body Damage/Rust. Showing 734 Hours. Location: Des Moines, IA Serial: 004-127117 | |
| Lot # | 118 |  |
| Qty | 1 | |
| Title | 1998 GMC C7500 CONTAINER DELIVERY TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. HARD STEERING. TRANSMISSION PUSH BUTTON HARD TO GET IN GEAR. CAT 3126, Automatic, Spring Suspension, 12 FA, 21 RA, 186 WB, 8,000 Lbs Capacity Waste Equipment Body, Steel Wheels, 11R22.5, PTO, AC, Dead Batteries, Dash Apart/Broken - Instrument Cluster Inoperable, Rust. Showing 189,172 Miles. Location: Fairburn, GA Serial: 1GDM7H1C6WJ521114 | |
| Lot # | 119 |  |
| Qty | 1 | |
| Title | 2006 MACK CV713 DAY CAB TRUCK | |
| Des. | NON RUNNER. MISSING SEVERAL COMPONENTS, INCLUDING: ENGINE CYLINDER HEAD, TRANSMISSION, HOOD, FLYWHEEL, CLUTCH, AND DASH. Mack AMI-370 ASET, Camelback Suspension, 269 WB, Dual Steel Fuel Tanks, Reman Rear Gears, Steel Wheels, 11R22.5, AC, Rust. Mileage Unavailable. Location: Pelham, AL Serial: 1M2AG11CX6M040789 | |

| | | |
|-------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| Lot # | 120 |  |
| Qty | 1 | |
| Title | 2003 FORD F150 XL EXT CAB PICKUP TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. ENGINE TICKS. EXHAUST LEAK. Ford 4.2L Gas, Automatic, Spring Suspension, 2.95 FA, 3.2 RA, 139 WB, Long Bed W/ Bed Liner, Steel Wheels, 255/70R16, AC, Service Engine Soon Light Illuminated, ABS Light Illuminated, Dead Batteries, Rust. Showing 190,822 Miles. Location: Waterloo, NE Serial: 1FTRX17203NB56191 | |
| Lot # | 122 |  |
| Qty | 1 | |
| Title | 2000 CORN HUSKER 800R END PUP TRAILER | |
| Des. | 43.5ft Total Length, 14ft East Aluminum Dump Body, 96in Width, 54in Sides, Air Ride Suspension, Tri-Axle, Rear Gate, Spoke Wheels, 11R22.5, Pitnlr Hitch, Rust. Location: Waterloo, NE Serial: 1T91C1932Y0007665 | |
| Lot # | 123 |  |
| Qty | 1 | |
| Title | 1999 MACK RD688S CAB & CHASSIS | |
| Des. | NON RUNNER. MISSING SEVERAL COMPONENTS, INCLUDING: BATTERIES, ALTERNATOR BELT, ENGINE FUEL PUMP, LEFT REAR REAR DRUM/WHEEL HUB/TIRES. CABLES CUT. BAD ENGINE OIL LEAKS. DASH APART. Mack E7-350 EUP, Mack T2090 9 Speed, Camelback Suspension, 284 WB, Double Frame, Steerable Pusher Axle, Steel Fuel Tank, Steel Wheels, 315/80R22.5, PTO, AC, Missing Door Hinge, Interior Worn, Body Damage/Rust. Mileage Unavailable; Showing 2,626 Hours. Location: Chesapeake, VA Serial: 1M2P267C7XM043597 | |
| Lot # | 124 |  |
| Qty | 1 | |
| Title | 1998 FORD F150 PICKUP TRUCK | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. BRAKES SOFT. Ford 4.2L Gas, Automatic, Spring Suspension, 2.95 FA, 3.6 RA, 139 WB, Long Bed, Steel Wheels, 235/70R16, AC, Dead Batteries, Body Damage/Rust. Showing 160,546 Miles. Location: Waterloo, NE Serial: 1FTZF1723WKB36591 | |
| Lot # | 125 |  |
| Qty | 1 | |
| Title | 1975 HOMEMADE FLATBED TRAILER | |
| Des. | NOT TITLED PER STATE REGULATIONS. 28ft Length, 18ft Main Deck, 4ft Dove Tail, 6ft Tongue, 3ft Folding Ramps, 96in Width, Spring Suspension, Wood Decking, Spoke Wheels, 8-14.5, Pintle Hitch, Rust. Location: Waterloo, NE Serial: 29006639 | |
| Lot # | 126 |  |
| Qty | 1 | |
| Title | 2011 CATERPILLAR 2P5000 FORKLIFT | |
| Des. | NOT TITLED PER STATE REGULATIONS. NON RUNNER. LESS FORKS. Nissan K25L, ROPS, 7.00-12; 6.00-9, Heavy Rust. Hours Unavailable. Location: Sacramento, CA Serial: AT3530995 | |
| Lot # | 128 |  |
| Qty | 1 | |
| Title | 2008 FORD F150 XL PICKUP TRUCK | |
| Des. | STARTS AND RUNS BRIEFLY BEFORE SHUTTING DOWN. NOT ROAD TESTED. HEAVY REAR BODY/AXLE/FRAME DAMAGE. Ford 4.2L Gas, Automatic, Spring Suspension, 3.15 FA, 3.8 RA, 145 WB, 8ft Box W/ Liner, Steel Wheels, 235/70R17, AC, Dead Batteries, Warning Lights Active, Flat Tires, Rear Glass Broken Out, Body Damage/Rust. Showing 232,633 Miles. Location: Selkirk, NY Serial: 1FTRF12298KD97394 | |

| | | |
|--------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Lot # | 129 |  |
| Qty | 1 | |
| Title | 2005 CATERPILLAR P5000 FORKLIFT | |
| Des. | NOT TITLED PER STATE REGULATIONS. NON RUNNER. LESS FORKS. ROPS, 7.00-12, 6.00-9, Heavy Rust. Hours Unavailable. Location: Sacramento, CA Serial: AT3504382 | |
| Lot # | 130 |  |
| Qty | 1 | |
| Title | 2007 FREIGHTLINER FL120 CAB & CHASSIS | |
| Des. | NON RUNNER. MISSING TRANSMISSION SHIFTER AND IGNITION SWITCH. MISSING ENGINE OIL FILTER HOUSING. Mercedes-Benz OM 460, Hendrickson Suspension, 18 FA, 46 RA, 268 WB, Steel Wheels, 315/80R22.5, PTO, AC, Interior Worn, Parts In Cab, Rust. Mileage Unavailable. Location: Pelham, AL Serial: 1FVHC5CV97HZ21888 | |
| Lot # | 131 |  |
| Qty | 1 | |
| Title | 2000 FORD CROWN VICTORIA P73 CAR | |
| Des. | STARTED ON SITE - NOT ROAD TESTED. Ford 4.6L Gas, Automatic, Spring Suspension, 2.585 FA, 2.677 RA, Roof Mounted Light Bar, Steel Wheels, 225/60R16, AC, PW, PL, PM, Dead Batteries. Showing 110,352 Miles. Location: Waterloo, NE Serial: 2FAFP73W5YX198625 | |
| Lot # | 132 |  |
| Qty | 1 | |
| Title | 2005 CHEVROLET 2500HD PICKUP TRUCK | |
| Des. | UNKNOWN RUNNING CONDITION - BATTERY CABLES CUT. GMC 6.0L Gas, Automatic, Spring Suspension, 4.41 FA, 6.084 RA, 134 WB, 8ft Box W/ Liner, Steel Wheels, 245/75R16, AC, Rust. Mileage Unavailable. Location: Bethlehem, NY Serial: 1GCHC24U75E274888 | |