



## Printable Catalog

<b>Title</b>	MAY 30 12:00 CDT	
<b>Description</b>	Closing Times TBD	
<b>Date</b>	Wed, May 30, 2018	
<b>Starts at</b>	12:00 PM	
<b>Address</b>	4747 NE 14th St, Des Moines, IA 50313 USA	
<b>Categories</b>		


---

<b>Lot #</b>	3	
<b>Qty</b>	1	
<b>Title</b>	2007 CAT 906 WHEEL LOADER	
<b>Des.</b>	THIS UNIT RUNS. BUCKET CONTROLS INOPERABLE, HYDRAULIC LEAKS NOTES. CAT 3044C Diesel, Hydrostatic, EROPS, Cab Heat/AC (AC Diverters Removed), 12.5R20 Tires, Hydraulic Cap Missing, Radiator Fan Fin Damaged, Windows Broken, Hood Latch Broken, Door Latch Inoperable, Body Damage Throughout. Showing 3,052 Hours. Location: Chicago, IL Serial: 0MER02803	


---

<b>Lot #</b>	4	
<b>Qty</b>	1	
<b>Title</b>	2005 KENWORTH T800 CAB & CHASSIS	
<b>Des.</b>	THIS UNIT RUNS. AIR LEAK. BRAKES INOPERABLE. CAT C13, Fuller 8LL, Chalmers Suspension, 20 FA, 46 RA, 256 WB, Double Frame, Steel Wheels, 315/80R22.5, Aluminum Fuel Tank 100 Gallon Total, PTO, AC, Multiple Check Engine Lights Illuminated. Showing 397,711 Miles; 1,622 Hours. Location: Willow Park, TX Serial: 1NKDLU0X15J108253	


---








<b>Lot #</b>	6	
<b>Qty</b>	1	
<b>Title</b>	2008 STERLING ACTERRA CAB & CHASSIS	
<b>Des.</b>	THIS UNIT RUNS. DOES NOT BUILD AIR PRESSURE. Cummins ISC, Allison 3000, Torsion Bar Suspension, 18 FA, 46 RA, 228 WB, Double Frame, Steel Wheels, 315/80R22.5, Aluminum Fuel Tank 80 Gallon Total, PTO, AC, Drive Shaft Removed W/ Truck, Odometer Inoperable. Location: Willow Park, TX Serial: 2FZHATBS38AY43712	








---








<b>Lot #</b>	7	
<b>Qty</b>	1	
<b>Title</b>	2002 VOLVO L220E WHEEL LOADER	
<b>Des.</b>	THIS UNIT RUNS. Volvo D12CLBE2- 352 HP (S/N: 11127482), Volvo HTE 305, EROPS, 6.8 YRD3 Bucket Capacity, 135in Bucket Width, 29.5R25 Tires, Oil Seepage Noted At Top And Bottom Of Engine, Speedometer Error Displayed, Hydraulic Oil Leak On Cab, Axle Leak. Showing 25,631 Hours. Location: Montrose, PA Serial: EV2071	








---








<b>Lot #</b>	8	
<b>Qty</b>	1	
<b>Title</b>	1986 MACK DM DUMP TRUCK	
<b>Des.</b>	THIS UNIT RUNS. PTO DID NOT ENGAGE- DUMP BODY INOPERABLE. EM6-237, TRL1078, Camelback Suspension, 19.729 FA, 46 RA, 178 WB, 65,780 GVWR, 10 Yard Heil Steel Dump Body, Steel/Spoke Wheels, 425/65R22.5; 10R20, Steel Fuel Tank 50 Gallon Total, Power Steering, L/Headlight Removed, Wipers Inoperable, Body Damage Throughout. Showing 161,635 Miles. Location: Algonquin, IL Serial: 1M2E126CXGA003911	

<b>Lot #</b>	11	
<b>Qty</b>	1	
<b>Title</b>	1996 VOLVO L12C WHEEL LOADER	
<b>Des.</b>	THIS UNIT RUNS. Volvo TD73KDE Diesel (S/N: 11030196), 23.5R25AH Tires (Tires Have Dry Rot), Oil Leak Noted At Engine Front And Rear, Body Damage. Showing 19,538 Hours. Location: Bremen, IN Serial: L120CV61545	
<b>Lot #</b>	13	
<b>Qty</b>	1	
<b>Title</b>	ALLISON HT740RS TRANSMISSION PARTS-HD	
<b>Des.</b>	Mack Application, Running Take Out Transmission. Location: Des Moines, IA Serial: U2359	
<b>Lot #</b>	14	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. AMI-370 ASET, T310 10 Speed, Camelback Suspension, 18 FA, 40 RA, 287 WB, 245 Cab To Frame End, Double Frame, Steel Wheels, 315/80R22.5, Steel Fuel Tank 75 Gallon Total. Showing 463,786 Miles. Location: Houston, TX Serial: 1M2AG11C17M048927	
<b>Lot #</b>	15	
<b>Qty</b>	1	
<b>Title</b>	1999 KOMATSU HD465 OFF HIGHWAY-DUMP TRUCK	
<b>Des.</b>	THIS UNIT RUNS. Komatsu Diesel, Automatic, Cab Heat/AC, Steel Wheels, 24.00R35, Wheel Seal Leaks, Engine Oil Leak, Chain Is Off L/Tailgate Side. Showing 154,932 Miles. Location: Manheim, PA Serial: 4669	
<b>Lot #</b>	16	
<b>Qty</b>	1	
<b>Title</b>	2001 DAEWOO FORKLIFT	
<b>Des.</b>	NON RUNNER. DRIVE AXLES PULLED. DaeWoo 80 HP, 2 T F/R, ROPS, 7.50R16; 7.00R12 Tires. Showing 195 Hours. Location: Willow Park, TX Serial: C9-00784	
<b>Lot #</b>	18	
<b>Qty</b>	1	
<b>Title</b>	2007 STERLING ACTERRA CAB & CHASSIS	
<b>Des.</b>	THIS UNIT RUNS. DOES NOT BUILD AIR PRESSURE. MBE900, Allison Automatic, Hendrickson Suspension, 16 FA, 40 RA, 230 WB, Double Frame, Steel Wheels, 315/80R22.5, Dual Aluminum Fuel Tanks 100 Gallon Total, PTO, AC, Drive Shaft Removed W/ Truck. Showing 241,441 Miles; 951 Hours. Location: Willow Park, TX Serial: 2FZHCHDJ47AY90354	
<b>Lot #</b>	19	
<b>Qty</b>	1	
<b>Title</b>	2012 HITACHI ZX200LC-3 EXCAVATOR	
<b>Des.</b>	THIS UNIT RUNS. Isuzu AI-4HK1X 164 HP, Hydrostatic, 1.2 YRD. Bucket, 177,32in Tracks, EROPS, Cab Heat/AC. Showing 6,055 Hours. Location: Medley, FL Serial: 1FFAST0XLA0320776	








<b>Lot #</b>	21	
<b>Qty</b>	1	
<b>Title</b>	2005 FORD F150 PICKUP TRUCK	
<b>Des.</b>	THIS UNIT RUNS. TRANSMISSION HAS NO REVERSE. 4.6L Gasoline, Automatic, Spring Suspension, 8ft Box, Steel Wheels, 245/75R17, AC, Warning Lights Illuminated, Rust/Body Damage Throughout, L/Fender Removed, Dead Batteries. Showing 112,800 Miles. Location: Thomasville, PA Serial: 1FTRF14W85NA35535	
<b>Lot #</b>	22	
<b>Qty</b>	1	
<b>Title</b>	2002 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	THIS UNIT RUNS. E7-350 EUP LSR, T2090 9 Speed, Camelback Suspension, 18 FA, 44 RA, 265 WB, Double Frame, Steel Wheels, 315/80R2205; 11R22.5, Steel Fuel Tank 85 Gallon Total, PTO, AC, L/Door Swapped. Showing 300,155 Miles; 6,758 Hours. Location: Willow Park, TX Serial: 1M2P267C02M064168	
<b>Lot #</b>	23	
<b>Qty</b>	1	
<b>Title</b>	2009 JOHN DEERE CT315 SKID LOADER	
<b>Des.</b>	THIS UNIT RUNS. John Deere, Hydrostatic, ROPS. Showing 30 Hours. Location: Medley, FL Serial: T0315TA175171	
<b>Lot #</b>	24	
<b>Qty</b>	1	
<b>Title</b>	1999 INGERSOL RAND SD100D ROLLER	
<b>Des.</b>	THIS UNIT RUNS. Cummins B3.9-C Diesel, Automatic, 84in Drum Width, 59in Drum Diameter, 128in WB, OROPS, Steel Wheels, 23.1R26. Showing 1,007 Hours. Location: Manheim, PA Serial: 168979	
<b>Lot #</b>	26	
<b>Qty</b>	1	
<b>Title</b>	1999 PETERBILT 357 CAB & CHASSIS	
<b>Des.</b>	RUNS ROUGH- BRIEFLY. CAT C13, Eaton 10 Speed, Ridewell Suspension, 16 FA, 46 RA, 260 WB, Steel Wheels, 315/80R22.5, Aluminum Fuel Tank 80 Gallon Total, PTO, AC, Less Batteries. Showing 873,027 Miles; 4,238 Hours. Location: Willow Park, TX Serial: 1NPALU0X9XD494869	
<b>Lot #</b>	27	
<b>Qty</b>	1	
<b>Title</b>	2005 JOHN DEERE 450C LC EXCAVATOR	
<b>Des.</b>	THIS UNIT RUNS. JD 6125H Diesel 316 HP, Automatic, EROPS, Cab AC, Steel Wheels, 214R36, 141in Width, Bucket Removed, R/Arm Cylinder Leak. Showing 13,090 Hours. Location: Annville, PA Serial: FF450CX091699	
<b>Lot #</b>	28	
<b>Qty</b>	1	
<b>Title</b>	2009 VOLVO VNL SLEEPER TRUCK	
<b>Des.</b>	THIS UNIT RUNS. Cummins ISX 500 HP, RTLO-18913A, Air Ride Suspension W/ Dump, 13.2 FA, 40 RA, 230 WB, 3.55 Ratio, 68in Sleeper, Hi-Rise Double Bunk, Air Slide 5th Wheel, Inter Axle Lock, Aluminum Wheels, 295/75R22.5, Dual Aluminum Fuel Tanks, AC, Rear Climate Control, Rear Outlets, PL, PW, Heated/Power Mirror, Air Ride Seats, Aux Power Unit. Showing 891,333 Miles. Location: Des Moines, IA Serial: 4V4NC9TJ09N278438	








<b>Lot #</b>	30	
<b>Qty</b>	1	
<b>Title</b>	2002 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. TURBO REMOVED- IN CAB. E7-350 EUP LSR, T2090, Camelback Suspension, 18 FA, 44 RA, 265 WB, Double Frame, Steel Wheels, 315/80R22.5, Steel Fuel Tank 75 Gallon Total, PTO, AC. Mileage Unavailable. Location: Willow Park, TX Serial: 1M2P267C22M064706	
<b>Lot #</b>	31	
<b>Qty</b>	1	
<b>Title</b>	2006 JOHN DEERE 310SG BACKHOE	
<b>Des.</b>	THIS UNIT RUNS. HYDRAULIC PUMP WEAK. JD 4045T 91 HP, Full-Power-Shifted Helical Cut Gear 4 Speed, 1.3 YRD3 Rear Bucket (92in Width), ROPS, 11R16; 19.5R25 Tires, Hour Meter Removed. Hours Unavailable. Location: Medley, FL Serial: T0310SG956408	
<b>Lot #</b>	32	
<b>Qty</b>	1	
<b>Title</b>	2008 VOLVO DD24 ROLLER	
<b>Des.</b>	THIS UNIT RUNS. Cummins A1700 32 HP Diesel, Hydrostatic, 2,725 GVWR, 8ft Length, 51in Width, 47in Working Width, 30 Degree Articulation Angle, 68 Gallon Water Tank, 10.6 Gallon Fuel Tank, 7.1 Gallon Hydraulic Tank, ROPS, Serial Tag Removed. Showing 2,641 Hours. Location: Manheim, PA Serial: 198789	
<b>Lot #</b>	35	
<b>Qty</b>	1	
<b>Title</b>	2006 FREIGHTLINER ST120 DAY CAB TRUCK	
<b>Des.</b>	THIS UNIT RUNS. MBE 4000, Eaton Fuller FRO-14210B, Air Ride Suspension, 40 RA, 190 WB, Aluminum Wheels, 295/75R22.5; 275/80R22.5, Aluminum Fuel Tank, AC, Dead Batteries. Showing 695,307 Miles; 20,966 Hours. Location: Des Moines, IA Serial: 1FUJBBCV26PV56059	
<b>Lot #</b>	36	
<b>Qty</b>	1	
<b>Title</b>	2008 VOLVO MC330 ASPHALT TRANSFER CONVEYOR	
<b>Des.</b>	THIS UNIT RUNS. Cummins, Chain Drive, Left/Right Steering, Steel Wheels, 16.00R24, Upper Guide Rails Removed For Transport. Showing 2,981 Hours. Location: Harrisburg, PA Serial: 198163	
<b>Lot #</b>	37	
<b>Qty</b>	1	
<b>Title</b>	ALLISON HT740RS TRANSMISSION PARTS-HD	
<b>Des.</b>	Mack Engine Application, Running Take Out Transmission. Location: Des Moines, IA Serial: U2290	
<b>Lot #</b>	38	
<b>Qty</b>	1	
<b>Title</b>	2005 INTERNATIONAL 7400 CAB & CHASSIS	
<b>Des.</b>	THIS UNIT RUNS. DT570, Allison Automatic, Hendrickson Suspension, 14 FA, 40 RA, 224 WB, Double Frame, Steel Wheels, 315/80R22.5, Steel Fuel Tank 70 Gallon Total, PTO, AC, Drive Shaft Pulled. Showing 129,868 Miles; 693 Hours. Location: Willow Park, TX Serial: 1HTWGZR85J050663	

<b>Lot #</b>	39	
<b>Qty</b>	1	
<b>Title</b>	2006 CAT 420E BACKHOE	
<b>Des.</b>	THIS UNIT RUNS. CAT C4.4 DIT 101 HP, Diesel, ROPS, 1.3 YRD3 F/Bucket Capacity, 89in Width (Buckled And Rusted), 12.5/80R18; 19.5R24 Tires, Warning Light Illuminated, Rear Bucket (Buckled And Rusted), Hydraulic Leak Noted At Rear Arm (Worn Hose), Steering Column Loose, Rear Actuator And Bucket Bushings Worn/Loose, Cab Glass Removed, L/Side Panel Storage Box Door Removed. Showing 908 Hours. Location: Odessa, FL Serial: CAT0420EPHLS02163	
<b>Lot #</b>	40	
<b>Qty</b>	1	
<b>Title</b>	2004 JET P29045 GRAIN TRAILER	
<b>Des.</b>	42ft Length, 95in Width, Steel Composition, Tarp, Steel Wheels, 245/75R24.5. Location: Des Moines, IA Serial: 5JNGS40214H000130	
<b>Lot #</b>	42	
<b>Qty</b>	1	
<b>Title</b>	1996 MACK RD686S CAB & CHASSIS	
<b>Des.</b>	THIS UNIT RUNS. EM6-300, Manual 6 Speed TRXL107, Camelback Suspension, 252 WB, 219 Cab To Frame, Double Frame, Steel Wheels, 11R24.5, Steel Fuel Tank 75 Gallon Total. Showing 807,261 Miles; 658 Hours. Location: Harrisburg, PA Serial: 1M2P138C7FA012222	
<b>Lot #</b>	43	
<b>Qty</b>	1	
<b>Title</b>	1988 VOLVO DUMP TRUCK	
<b>Des.</b>	THIS UNIT RUNS. Cummins, Eaton 10 Speed, Hendrickson Suspension, 212 WB, Dump Body, Tarp System, Non Steer Pusher Axle, Spoke Wheels, 315/80R22.5; 11R22.5, Aluminum Fuel Tank, PTO (Inoperable, Has Air Leak), AC. Showing 235,319 Miles. Location: Medley, FL Serial: 4V2SCBJE6JV500578	
<b>Lot #</b>	44	
<b>Qty</b>	1	
<b>Title</b>	2006 VOLVO VHD64F DAY CAB TRUCK	
<b>Des.</b>	NON RUNNER. NO POWER TO DASH. Volvo D12- 465 HP, 10 Speed, Torsion Bar Suspension, 14.6 FA, 46 RA, 194 WB, 118in Cab To Axle, Air Slide 5th Wheel, Wet Kit, Steel Wheels, 11R22.5, Aluminum Fuel Tank 95 Gallon Total, PTO, AC. Showing 2,673 Hours; Mileage Unavailable. Location: Willow Park, TX Serial: 4V4KC9GH46N428847	
<b>Lot #</b>	45	
<b>Qty</b>	1	
<b>Title</b>	2004 FORD F350 STAKE BODY TRUCK	
<b>Des.</b>	NON RUNNER. 6.0L V8 Turbo Diesel, Automatic, Spring Suspension, 4.8 FA, 9.45 RA, 141 WB, 111in Stake Body, Lift Gate, Steel Wheels, 235/85R16, Steel Fuel Tank 35 Gallon Total, AC. Mileage Unavailable. Location: Harrisburg, PA Serial: 1FDWF37P54EB70744	
<b>Lot #</b>	47	
<b>Qty</b>	1	
<b>Title</b>	2008 VOLVO DD24 ROLLER	
<b>Des.</b>	THIS UNIT RUNS. Cummins A1700 32 HP Diesel, Hydrostatic, 2,725 GVWR, 8ft Length, 51in Width, 47in Working Width, 30 Degree Articulation Angle, 68 Gallon Water Tank, 10.6 Gallon Fuel Tank, 7.1 Gallon Hydraulic Tank, ROPS. Showing 2,041 Hours. Location: Manheim, PA Serial: 198788	







<b>Lot #</b>	48	
<b>Qty</b>	1	
<b>Title</b>	2004 GMC T7500 SWEEPER	
<b>Des.</b>	NON RUNNER. Duramax 7.8L, Automatic, Spring Suspension, 12 FA, 21 RA, 128 WB, Steel Wheels, 11R22.5 (Flat Tires), Steel Fuel Tank 50 Gallon Total, PTO, Odometer Removed. Location: Bardstown, KY Serial: 1GDM7F1354F520962	
<b>Lot #</b>	50	
<b>Qty</b>	1	
<b>Title</b>	2007 INTERNATIONAL 7400 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. KNOWN ELECTRICAL ISSUES. DT570, Allison Automatic, Hendrickson Haulmax Suspension, 16 FA, 40 RA, 228 WB, Steel Wheels, 315/80R22.5 (Rears Singled Out), Steel Fuel Tank 60 Gallon Total, PTO, AC. Showing 132,756 Miles. Location: Willow Park, TX Serial: 1HTWGAZT27J431522	
<b>Lot #</b>	52	
<b>Qty</b>	1	
<b>Title</b>	2002 INTERNATIONAL 4300 VAC TRUCK	
<b>Des.</b>	STARTED/RAN W/ STARTING FLUID. DT-466, Automatic, Spring Suspension, 12 FA, 20 RA, Steel Wheels, 11R22.5, PTO, Warning Lights Illuminated. Showing 469,904 Miles; 471 Hours. Location: Houston, TX Serial: 1HTMMAAN82H540774	
<b>Lot #</b>	53	
<b>Qty</b>	1	
<b>Title</b>	2006 FORD ESCAPE HYBRID SUV	
<b>Des.</b>	NON RUNNER. BAD ENGINE. Ford Hybrid 2.3L Gasoline, Automatic, Spring Suspension, Steel Wheels, 235/70R16, AC, PW, PL, PM, PS, Warning Lights Illuminated. Showing 234,372 Miles. Location: Manheim, PA Serial: 1FMCU96HX6KB58986	
<b>Lot #</b>	54	
<b>Qty</b>	1	
<b>Title</b>	2002 KENWORTH T800 CAB & CHASSIS	
<b>Des.</b>	THIS UNIT RUNS. CAT C15- 410 HP, RTO16908LLT, Air Ride Suspension, 229 WB, 229 Cab To Frame, 4.63 Ratio, Tag Axle, Steel Wheels, 11R22.5, Aluminum Fuel Tank 100 Gallon Total, AC. Showing 571,913 Miles; 26,207 Hours. Location: Harrisburg, PA Serial: 1NKDLB0X32J890975	
<b>Lot #</b>	55	
<b>Qty</b>	1	
<b>Title</b>	2002 CATERPILLAR 928G WHEEL LOADER	
<b>Des.</b>	STARTS WITH JUMP. CAT 3116T- 125 HP, 4 Speed Forward/3 Speed Reverse, 100in Bucket Width, 2.2 YRD3 Bucket Capacity, EROPS, Can Heat/AC, Oil Leak Noted At Main Hydraulic Cylinders, Broken Front Window, Body Damage Throughout, Serial Tag Not Located. Hours Unavailable. Location: Salem, OR Serial: 6XR03397	
<b>Lot #</b>	58	
<b>Qty</b>	1	
<b>Title</b>	1999 GETMAN 2-500 UNDERGROUND MINING BOOM TRUCK	
<b>Des.</b>	THIS UNIT RUNS. LIQUID EXPLOSIVE TANK EMPTY. Duetz Diesel, Automatic, Front/Rear Outriggers, Steel Wheels, 12.00R20, Engine Cover Would Not Come Off, Dead Batteries. Showing 21,733 Hours. Location: Thomasville, PA Serial: 6603	



<b>Lot #</b>	62	
<b>Qty</b>	1	
<b>Title</b>	1998 VOLVO WG64 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. IGNITION REMOVED. DASH APART. AXLES PULLED. COMPRESSOR APART- COMPONENTS REMOVED. BELT MISSING. Volvo D12- 345 HP, Fuller 9 Speed, Torsion Bar Suspension, 18 FA, 46 RA, 251 WB, Double Frame, Steel Wheels, 315/80R22.5, Steel Fuel Tank 75 Gallon Total, PTO, AC, Less Batteries. Mileage Unavailable. Location: Willow Park, TX Serial: 4VHJCCGF9WN861862	
<b>Lot #</b>	63	
<b>Qty</b>	1	
<b>Title</b>	2000 CASE 621C XT WHEEL LOADER	
<b>Des.</b>	THIS UNIT RUNS. Case 6T-590- 139 HP, 4 Speed Forward/3 Reverse, 99in Bucket Width, EROPS, Oil Leak Noted At Main Hydraulic Cylinder. Showing 7,640 Hours. Location: Salem, OR Serial: JEE0129722	
<b>Lot #</b>	64	
<b>Qty</b>	1	
<b>Title</b>	2006 INGERSOL RAND TAR BUGGU HT250 MISC	
<b>Des.</b>	NON RUNNER. FLYWHEEL REMOVED. PROPANE TANK MISSING. Briggs & Stratton Gasoline, Hot Tank, 7 Spray Jets, Steel Wheels, 225/75R15. Location: Harrisburg, PA Serial: SE1FS10167S94465	
<b>Lot #</b>	65	
<b>Qty</b>	1	
<b>Title</b>	2004 FORD F450XL SERVICE TRUCK	
<b>Des.</b>	NON RUNNER. 6.0L V8 Turbo Diesel, Manual 6 Speed, Spring Suspension, 6 FA, 12 RA, Steel Wheels, 225/70R19.5, Steel Fuel Tank, AC. Showing 87,721 Miles. Location: Sacramento, CA Serial: 1FDXF46P54EA99654	
<b>Lot #</b>	66	
<b>Qty</b>	1	
<b>Title</b>	2001 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. E7-350 EUP, T2090 9 Speed, Camelback Suspension, 18 FA, 4.64 Ratio, 288 WB, 242 Cab To Frame, Double Frame, Wet Kit, Tag Axle, Steel Wheels, 255/70R22.5; 315/80R22.5, Steel Fuel Tank 75 Gallon Total, PTO, AC, Body Damage Throughout. Showing 56,625 Miles; 220 Hours. Location: Summerville, NC Serial: 1M2P267C91M061509	
<b>Lot #</b>	68	
<b>Qty</b>	1	
<b>Title</b>	2002 SMC1000 SMC1000 SIGN BOARD	
<b>Des.</b>	PANEL MISSING INSIDE MESSAGE BOARD. UNKNOWN RUNNING CONDITION. Steel Wheels, 235/75R15. Location: Harrisburg, PA Serial: 3234	
<b>Lot #</b>	69	
<b>Qty</b>	1	
<b>Title</b>	2002 FORD F350 PICKUP TRUCK	
<b>Des.</b>	NON RUNNER. ENGINE OIL LEAK NOTED. 7.3L Turbo Diesel, Manual 5 Speed, Spring Suspension, 4.55 FA, 6.82 RA, 141 WB, 9ft Reading Body W/ Side Storage, Steel Wheels, 265/75R16, Body Damage Throughout. Showing 212,215 Miles. Location: Harrisburg, PA Serial: 1FDSF34F62EC14788	

<b>Lot #</b>	71	
<b>Qty</b>	1	
<b>Title</b>	1994 CATERPILLAR D4 DOZER-CRAWLER	
<b>Des.</b>	NON RUNNER. ENGINE SEIZED. CAT 3204 90 HP, Planetary Powershift 3 Speed Forward/3 Speed Reverse, 127in Blade Width, 35.7in Height, EROPS, 6ft 6in Track Gauge, Left Side Hydraulic Cylinder Leak, Dead Batteries, Serial Tag Not Located. Showing 5,262 Hours. Location: Salem, OR Serial: 9GJ00625	
<b>Lot #</b>	74	
<b>Qty</b>	1	
<b>Title</b>	2001 FORD F650 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. KNOWN ELECTRICAL ISSUES. CAT 3126/C7, Automatic, Spring Suspension, 8.5 FA, 17.5 RA, 158 WB, Double Frame, Steel Wheels, 11R22.5, Steel Fuel Tank 50 Gallon Total. Showing 571,334 Miles. Location: Willow Park, TX Serial: 3FDWF652X1MA60447	
<b>Lot #</b>	75	
<b>Qty</b>	1	
<b>Title</b>	2014 CATERPILLAR 242D SKID LOADER	
<b>Des.</b>	THIS UNIT RUNS. CAT C3.3B DIT Turbo 74.3 HP Diesel, 33/12R20 Tires (Poor Condition), Hydraulic Cup Link Broken, Dip Stick Tube Bracket Broken, Engine Cover Dented/Has Hole, R/Rear Wheel Bent, Less Battery, Front Step Damaged, Hand Rail Bent. Showing 4,198 Hours. Location: Albertville, AL Serial: DZT1020	
<b>Lot #</b>	77	
<b>Qty</b>	1	
<b>Title</b>	1998 FORD F150 PICKUP TRUCK	
<b>Des.</b>	THIS UNIT RUNS. 4.6L, Automatic, Spring Suspension, Steel Wheels, AC, L/Front Tire Missing. Showing 67,835 Miles. Location: San Bernardino, CA Serial: 1FTZX17W6WKB24015	
<b>Lot #</b>	78	
<b>Qty</b>	1	
<b>Title</b>	2002 VOLVO VHD64F CAB & CHASSIS	
<b>Des.</b>	STARTED/RAN BRIEFLY BEFORE SHUTTING DOWN- WOULD NOT RE-START. DASH APART-COMPONENTS REMOVED. VE D7- 300 HP, RTO11909ALL 9 Speed, T-Ride Suspension, 20 FA, 40 RA, 2.48 WB, 4.33 Ratio, Steel Wheels, 385/65R22.5; 11R22.5. Showing 365,000 Miles. Location: Buckeye, AZ Serial: 4V5KC9HE32N334758	
<b>Lot #</b>	79	
<b>Qty</b>	1	
<b>Title</b>	2000 CASE 95XT SKID LOADER	
<b>Des.</b>	UNKNOWN RUNNING CONDITION- DEAD BATTERIES. Case 4T-390- 85 HP Diesel, 0.71 YRD3 Bucket, 30/10R20 Tires, Hydraulic Leaks Noted, Joy Stick Button Missing. Hours Unavailable. Location: Salem, OR Serial: JAF0299412	
<b>Lot #</b>	80	
<b>Qty</b>	1	
<b>Title</b>	1979 DORSEY OPEN TOP TRAILER	
<b>Des.</b>	30ft Length, 96in Width, Aluminum Composition, Lift Cylinder, 6 Total Drain Valves, Tarp System, Spoke Wheels, 11R22.5. Location: Honey Brooke, PA Serial: HW13525	



<b>Lot #</b>	81	
<b>Qty</b>	1	
<b>Title</b>	1979 DORSEY OPEN TOP TRAILER	
<b>Des.</b>	28ft Length, 96in Width, Aluminum Composition, 4 Total Drain Valves, Dump Cylinder, Tarp System, Spoke Wheels, 11R22.5. Location: Honey Brook, PA Serial: HW13524	
<b>Lot #</b>	82	
<b>Qty</b>	1	
<b>Title</b>	2001 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. HOOD MISSING. E7-350 EUP, T2090 9 Speed, Camelback Suspension, 18 FA, 262 WB, 248 Cab To Frame, Steel Wheels, 315/80R22.5, AC. Showing 29,718 Miles; 2,405 Hours. Location: Harrisburg, PA Serial: 1M2P267C31M057570	
<b>Lot #</b>	83	
<b>Qty</b>	1	
<b>Title</b>	1991 MACK MIDLINER VAN BODY TRUCK	
<b>Des.</b>	THIS UNIT RUNS. Mack Engine, Mack Automatic, Spring Suspension, 212 WB, 24ft AMI Body, Lift Gate, Steel Wheels, 255/70R22.5, AC, Exhaust Leak Noted At Turbo, L/Side Body Damage. Showing 195,205 Miles; 3,043 Hours. Location: Concord, NC Serial: VG6M117B3MB200873	
<b>Lot #</b>	84	
<b>Qty</b>	1	
<b>Title</b>	1995 PCS 71SMC SIGN BOARD	
<b>Des.</b>	UNKNOWN RUNNING CONDITION- LESS BATTERIES. Steel Wheels, 235/75R15. Location: Harrisburg, PA Serial: 00841	
<b>Lot #</b>	86	
<b>Qty</b>	1	
<b>Title</b>	JOHN DEERE GATOR ATV	
<b>Des.</b>	UNKNOWN RUNNING CONDITION- DEAD BATTERY. CAB FRAME DAMAGE. John Deere Engine, ROPS, 25R13.9 Tires- Flat Tires, Body Damage Throughout. Showing 1,779 Hours. Location: Salem, OR Serial: V006X4D002404	
<b>Lot #</b>	87	
<b>Qty</b>	1	
<b>Title</b>	2001 WACKER LTN6L LIGHT TOWER	
<b>Des.</b>	UNKNOWN RUNNING CONDITION- GENERATOR APART. Isuzu 3 Cylinder Diesel, Steel Wheels, 205/75R15. Showing 847 Hours. Location: Harrisburg, PA Serial: 5AJLS1613XB000179	