



## Printable Catalog

<b>Title</b>	JULY 8 12:00 CDT	
<b>Description</b>	Closing Times TBD	
<b>Date</b>	Wed, Jul 8, 2020	
<b>Starts at</b>	12:00 PM	
<b>Address</b>	4747 NE 14th St, Des Moines, IA 50313 USA	
<b>Categories</b>		


---

<b>Lot #</b>	1	
<b>Qty</b>	1	
<b>Title</b>	2002 MACK CV513 REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Mack EM7-300, Mack T2070, Walking Beam Suspension, 20 FA, 38 RA, 250 WB, 10.5 Yrd MTM Bridgmaster Rear Mixer, 70 Gallon Side Mount Water Tank, Aluminum Fuel Tank, 11,020 Lbs Steerable Pusher Axle With Steel Wheels 255/70R22.5, 13,200 Lbs Bridge Axle With Steel Wheels 11R22.5, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Rust. Showing 206,606 Miles; 23,826 Hours. Location: Omaha, NE Serial: 1M2AG03C12M001266	


---

<b>Lot #</b>	3	
<b>Qty</b>	1	
<b>Title</b>	2004 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Mack AI-400, Maxitorque 7 Speed, Camelback Suspension, 234 WB, 17.75ft Frame Length, Double Frame, Engine Brake, Dual Aluminum Fuel Tank, Aluminum/Steel Wheels, 11R22.5, PTO, AC, Less Tail Lights, Rust. Showing 621,718 Miles; 27,069 Hours. Location: Kansas City, MO Serial: 1M2AG11C84M009957	


---







<b>Lot #</b>	4	
<b>Qty</b>	1	
<b>Title</b>	2000 CATERPILLAR 980G WHEEL LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. BLOW BY NOTED. HYDRAULIC LEAK NOTED AT L/STEER ARM. CAT 3406DITA- 323 HP, 4F/4R, 135in Bucket, EROPS, Cab Heat/AC, Steel Wheels, 26.5R25, Body Damage/Rust. Showing 52,583 Hours. Location: San Antonio, TX Serial: 02KR03934	




---






<b>Lot #</b>	5	
<b>Qty</b>	1	
<b>Title</b>	2007 KENWORTH T800 REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. CAT C13, Eaton 8LL, Chalmers Suspension, 20 FA, 44 RA, 240 WB, 10 Yrd Kimble Rear Mixer, Conveyor Belt, Rear Outriggers, 150 Gallon Side Mount Water Tank, Pusher Axle, Three Chutes, Aluminum Fuel Tank, 33ft Total Length, 13ft Height, Aluminum Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 195,001 Miles; 18,839 Hours. Location: Buckhannon, WV Serial: 1NKDLU0X67J196722	








---

<b>Lot #</b>	6	
<b>Qty</b>	1	
<b>Title</b>	2010 FORD F150 4X4 CREW CAB PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE, NOT ROAD TESTED. 4.6L Gas, Automatic, Spring Suspension, 145 WB, 6.5ft Box, Steel Wheels, 245/70R17, AC, PW, PL, PM, Warning Lights Illuminated, Body Damage/Rust. Showing 215,846 Miles. Location: Des Moines, IA Serial: 1FTFW1E84AFC30877	

<b>Lot #</b>	7	
<b>Qty</b>	1	
<b>Title</b>	1996 MACK CL713 DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Mack E7-400, Eaton 8LL, Camelback Suspension, 248 WB, 17ft Aluminum J & J Dump Body, 30ft Total Length, 11.5ft Height, Tarp System, Pusher Axle, Aluminum Fuel Tank, Aluminum/Steel Wheels, 425/65R22.5; 11R24.5, PTO, AC, Body Lift Cylinder Leaks, Oil Leaks, Body Damage/Rust. Showing 689,983 Miles; 22,046 Hours. Location: Bluefield, VA Serial: 1M2AD38C2TW004346	
<b>Lot #</b>	8	
<b>Qty</b>	1	
<b>Title</b>	1994 MACK CH613 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Mack E7-350, Eaton 9 Speed, Air Ride Suspension, 174 WB, Air Slide Fifth Wheel, 23.5ft Length, 10.5ft Height, Dual 90 Gallon Aluminum Fuel Tanks, Aluminum/Steel Wheels, 11R22.5, AC, Dead Batteries, Electronic Malfunction Light Illuminated, Seat Torn, Rust. Showing 43,717 Miles; 15,045 Hours. Location: York, PA Serial: 1M2AA13Y0RW039783	
<b>Lot #</b>	9	
<b>Qty</b>	1	
<b>Title</b>	2008 FREIGHTLINER M206 FLATBED TRUCK	
<b>Des.</b>	STARTED ON SITE W/ JUMP - NOT ROAD TESTED. DARK GRAY SMOKE VISIBLE WHEN PERFORMING SNAP TEST. Dead Batteries, Dash Missing Lower Blower Motor Assembly Cover, Interior Worn, Various Body Damage/Rust. Showing 93,033 Miles; 4,842 Hours. Location: Wayne, MI Serial: 1FVHCYBS48HZ57501	
<b>Lot #</b>	10	
<b>Qty</b>	1	
<b>Title</b>	2013 FORD F250 PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. TPMS Light Illuminated, Right Headlight Lens Cracked, Left Tail Light Lens Damaged, Interior Worn, Various Body Damage/Rust. Showing 159,761 Miles; 8,992 Hours. Location: Twinsburg, OH Serial: 1FT7X2A67DEA87316	
<b>Lot #</b>	11	
<b>Qty</b>	1	
<b>Title</b>	2005 OSHKOSH F2346 6X6 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. BAD REAR BRAKE CHAMBER. Cummins ISM, Automatic, Chalmers Suspension, 23 FA, 46 RA, 212 WB, 214in Back Cab To End Frame, Aluminum Fuel Tank, Aluminum/Steel Wheels, 445/65R22.5; 11R22.5, PTO, AC, Check Engine Light Illuminated, Left Front Tire Flat, Rust. Showing 201,842 Miles; 12,348 Hours. Location: Tampa, FL Serial: 10TDDAC385S084173	
<b>Lot #</b>	13	
<b>Qty</b>	1	
<b>Title</b>	2001 MACK RD690S REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Mack EM7-275, Mack T2070, Walking Beam Suspension, 20 FA, 38 RA, 249 WB, 10.5 Yrd MTM Bridgmaster Rear Mixer, 75 Gallon Side Mount Water Tank, Aluminum Fuel Tank, 11,020 Lbs Steerable Pusher Axle With Steel Wheels 255/70R22.5, 13,200 Lbs Bridge Axle With Steel Wheels 11R22.5, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 225,374 Miles; 22,944 Hours. Location: Omaha, NE Serial: 1M2P289C41M033349	







<b>Lot #</b>	14	
<b>Qty</b>	1	
<b>Title</b>	1996 MACK RD688S WATER TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Mack E7-400, Mack T2180 18 Speed, Camelback Suspension, 207 WB, 14ft Body With 3,000 Gallon Plastic Water Tank, Pony Motor - Starts And Runs, Steel Wheels, 11R24.5, PTO, AC, Dead Batteries, Interior Worn, Rust. Showing 405,382 Miles; 21,797 Hours. Location: Jacksonville, FL Serial: 1M2P270Y8TM028502	
<b>Lot #</b>	17	
<b>Qty</b>	1	
<b>Title</b>	2011 PETERBILT 365 REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. MISSING WATER TANK. Cummins ISM, Eaton 8LL, Hendrickson Suspension, 22 FA, 46 RA, 225 WB, 10.5 Yrd McNeilus Rear Mixer, Aluminum Fuel Tank, Three Chutes, 31.25ft Total Length, 12ft Height, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 178,312 Miles; 14,147 Hours. Location: Mabscott, WV Serial: 1NPSL00X9BD115102	
<b>Lot #</b>	18	
<b>Qty</b>	1	
<b>Title</b>	2003 VOLVO VNL64T CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Volvo D12 345 HP, Meritor 10 Speed, Spring Suspension, 13.2 FA, 40 RA, 207 WB, Steel Fuel Tank, Steel Wheels, 11R22.5, AC, Dead Batteries, Rust. Showing 485,112 Miles. Location: Starke, FL Serial: 4V5NC9GF43N337824	
<b>Lot #</b>	19	
<b>Qty</b>	1	
<b>Title</b>	2008 FORD SUPER DUTY EXT CAB PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE, NOT ROAD TESTED. 5.4L Gas, Automatic, Spring Suspension, 4.1 FA, 6.262 RA, 162 WB, 8ft Box, Steel Wheels, 265/70R17, AC, PW, PL, PM, Check Engine Light Illuminated, Body Damage/Rust- TailGate Broken. Showing 139,535 Miles. Location: Des Moines, IA Serial: 1FTWX30518EB67677	
<b>Lot #</b>	20	
<b>Qty</b>	1	
<b>Title</b>	1999 MACK CH613 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Mack E7-460 EUP, Maxitorque T2130 13 Speed Extended Range Splitter, Air Ride Suspension, 210 WB, Air Slide Fifth Wheel, Dual Aluminum Fuel Tanks, Pusher Axle W/ Aluminum Wheels 315/80R22.5, Aluminum Wheels, 315/80R22.5; 11R24.5, PTO, AC, Warning Lights Active, Rear Dual Fender Damaged/Scuffed. Showing 78,427 Miles; 13,855 Hours. Location: Des Moines, IA Serial: 1M2AA18Y3XW113056	
<b>Lot #</b>	21	
<b>Qty</b>	1	
<b>Title</b>	2006 FORD F550 DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. BAD IDLER PULLEY - FAN BELT MAKES NOISE. Ford Power Stroke, Automatic, Spring Suspension, 6.5 FA, 13.66 RA, 165 WB, 12ft Steel Crysteel Dump Body W/ Fold Down Sides, Tarp System, 21.75ft Total Length, 7.5ft Height, Steel Wheels, 225/70R19.5, AC, ABS Light Illuminated, Seat Torn, Rust. Showing 210,385 Miles. Location: Buckhannon, WV Serial: 1FDAF57P56EA28161	








<b>Lot #</b>	23	
<b>Qty</b>	1	
<b>Title</b>	2003 FREIGHTLINER FL112 ROLLOFF TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Cummins ISM 330 HP, Eaton 8LL, Hendrickson Suspension, 20 FA, 46 RA, 265 WB, Rear Roll Off Body, Steel Wheels, 315/80R22.5; 425/65R22.5, PTO, AC, Rust. Showing 63,313 Miles; 454,632 ECM Miles; 39,285 Hours. Location: Tampa, FL Serial: 1FVHBGA823HK61408	
<b>Lot #</b>	24	
<b>Qty</b>	1	
<b>Title</b>	1996 CATERPILLAR 980G WHEEL LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. UNIT DOES NOT TRAVEL. HYDRAULIC AND BRAKE WARNINGS ACTIVE. CAT 3406 Diesel, 4F/4R, Enclosed ROPS, 138in Bucket Width, Steel Wheels, 26.5-25, AC/Heated Cab, Engine Hour Meter Error, Body Damage/Rust. Hours Unavailable. Location: San Antonio, TX Serial: 9CM00347	
<b>Lot #</b>	25	
<b>Qty</b>	1	
<b>Title</b>	2005 MACK CV513 REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Mack AMI-370, Mack TM308M, Walking Beam Suspension, 20 FA, 38 RA, 250 WB, 11 Yrd MTM Bridgmaster Rear Mixer, 125 Gallon Cross Mount Water Tank, Aluminum Fuel Tank, Dual 11,020 Lbs Air Lift Steerable Pusher Axles With Steel Wheels 255/70R22.5, 13,200 Lbs Bridge Axle With Steel Wheels 11R22.5, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Rust. Showing 209,694 Miles; 24,133 Hours. Location: Omaha, NE Serial: 1M2AG02C85M002260	
<b>Lot #</b>	26	
<b>Qty</b>	1	
<b>Title</b>	2012 FORD F250 PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. COOLANT DISCOLORED. OIL LEVEL EXTREMELY LOW. Oil Residue On Bottom Of Oil Fill Cap, Active Fault - See Report, TPMS Light Illuminated, Tailgate Cap Missing, Tires Worn - One Tire Appears To Be Spare, Interior Worn, Body Damage/Rust. Showing 166,540 Miles. Location: Twinsburg, OH Serial: 1FT7X2A60CEB86882	
<b>Lot #</b>	27	
<b>Qty</b>	1	
<b>Title</b>	2005 OSHKOSH F2346 6X6 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. ENGINE SKIP. Cummins ISM, Automatic, Chalmers Suspension, 20 FA, 46 RA, 212 WB, Aluminum Fuel Tank, Steel Wheels, 11R22.5, PTO, AC, Oil Leaks, Rust. Showing 91,694 Miles; 8,031 Hours. Location: Tampa, FL Serial: 10TDDAC335S084274	
<b>Lot #</b>	28	
<b>Qty</b>	1	
<b>Title</b>	2007 INTERNATIONAL 7400 GARBAGE PACKER	
<b>Des.</b>	STARTED ON SITE - WILL NOT MOVE. BAD FRONT REAR GEAR. CAN TIPPER TO BE REMOVED PRIOR TO SALE. International DT466E, Automatic, Hendrickson Suspension, 228 WB, 25 Yrd Heil Rear Loader, 32ft Length, 11ft Height, Steel Wheels, 315/80R22.5, PTO, AC, Backup Camera, Missing Both Side Mirrors, Check AC Light Illuminated, ABS Light Illuminated, Broken Right Door Latch, Body Rust Holes. Showing 228,615 Miles; 21,449 Hours. Location: Millsboro, DE Serial: 1HTWGAZT67J562629	

<b>Lot #</b>	29	
<b>Qty</b>	1	
<b>Title</b>	2006 VOLVO VHD REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Volvo D12 365 HP, Eaton Fuller, Hendrickson Suspension, 20 FA, 46 RA, 223 WB, 10.5 Yrd Kimble Rear Mixer, Dual 150 Gallon Side Mount Water Tanks, Aluminum Fuel Tank, Tag Axle, Three Chutes, 37.5ft Total Length, 12ft Height, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Check Engine Light Illuminated, Front Cover Oil Leaks, Warning Lights Active, Rust. Showing 75,336 Miles. Location: Mabscott, WV Serial: 4V5KC9GF46N442855	
<b>Lot #</b>	30	
<b>Qty</b>	1	
<b>Title</b>	2008 FREIGHTLINER M206 FLATBED TRUCK	
<b>Des.</b>	NON RUNNER. CRANKS NO START. Active Fault Codes - See Report, Engine Protect Light Illuminated, ECM And Dash Mileage Do Not Match - Possible ECM Replacement, Residue Noted At Bottom Of Rear Differential Housing And Service Plug, Interior Worn/Seats Torn, Body Damage/Rust. Showing 83,847 Miles; 18,268 ECM Miles; 5,115 Hours. Location: Wayne, MI Serial: 1FVHCYBS28HZ57500	
<b>Lot #</b>	32	
<b>Qty</b>	1	
<b>Title</b>	2008 KENWORTH T800 WIDE HOOD DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Cummins SX 600, 18 Speed Manual, Air Ride Suspension, 20 FA, 46 RA, 236 WB, Air Slide Fifth Wheel, 120 Gallon Aluminum Fuel Tank, 20,000 Lbs Pusher Axle With Aluminum Wheels 425/65R22.5, Aluminum Wheels, 425/65R22.5; 11R22.5, PTO, AC, Check Engine Light Illuminated, Coolant Light Illuminated. Showing 726,628 Miles; 23,749 Hours. Location: Des Moines, IA Serial: 1XKDP4TX08J219080	
<b>Lot #</b>	33	
<b>Qty</b>	1	
<b>Title</b>	2004 FORD F450 STAKE BODY TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Oil Residue On Upper Right Side Of Engine Around Oil Fill Tube And Right Bank Valve Cover, Deck Joists Heavily Rusted, Interior Worn, Various Body Damage/Rust. Showing 68,557 Miles; 8,660 Hours. Location: Twinsburg, OH Serial: 1FDXF46S84ED38201	
<b>Lot #</b>	34	
<b>Qty</b>	1	
<b>Title</b>	2010 FORD F150 4X4 EXT CAB PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE, NOT ROAD TESTED. 4.6L Gas, Automatic, Spring Suspension, 3.75 FA, 3.8 RA, 145 WB, Aluminum Wheels, 245/75R17, AC, PW, PL, PM, Body Damage/Rust. Showing 228,650 Miles. Location: Des Moines, IA Serial: 1FTEX1EW2AKE15816	
<b>Lot #</b>	35	
<b>Qty</b>	1	
<b>Title</b>	2007 VOLVO VHD64B CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. BAD ENGINE ECM. Volvo D12 365 HP, Eaton 8LL, Spring Suspension, 20 FA, 46 RA, 250 WB, Pusher Axle, Steel Wheels, 275/80R22.5, AC, Seats Ripped. Mileage Unavailable. Location: Starke, FL Serial: 4V5KC9GF77N479691	
<b>Lot #</b>	36	
<b>Qty</b>	1	
<b>Title</b>	1988 MACK DM690S WATER TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Oil Leaks At Lower Right Side Front To Rear, Oil Pan/Rear Seal Area, Hood Damaged, Interior Worn, Various Body Damage/Rust. Showing 202,958 Miles; 2,720 Hours. Location: Twinsburg, OH Serial: 1M2B201C5JW002798	







<b>Lot #</b>	37	
<b>Qty</b>	1	
<b>Title</b>	2002 MACK CV513 REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. COULD NOT GET BRIDGE AXLE TO GO DOWN. Mack EM7-300, Mack T2070, Walking Beam Suspension, 20 FA, 38 RA, 250 WB, MTM Bridgemaster Rear Mixer, 80 Gallon Side Mount Water Tank, Aluminum Fuel Tank, 11,020 Lbs Steerable Pusher Axle With Steel Wheels 255/70R22.5, 13,200 Lbs Bridge Axle With Steel Wheels 11R22.5, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Rust. Showing 240,560 Miles; 23,910 Hours.	
<b>Lot #</b>	38	
<b>Qty</b>	1	
<b>Title</b>	2005 INTERNATIONAL 4300 DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. ENGINE SKIP. ENGINE BLOW BY. NEEDS CLUTCH. International DT466E, 6 Speed Manual, Spring Suspension, 11 FA, 21 RA, 189 WB, 16ft Steel Baker Dump Body, Steel Fuel Tank, Tarp System, 25.5ft Total Length, 8.5ft Height, Steel Wheels, 11R22.5, PTO, AC, ABS Light Illuminated, Seat Torn, Rust. Showing 337,717 Miles; 17,694 Hours. Location: Buckhannon, WV Serial: 1HTMMAAN35H152436	
<b>Lot #</b>	39	
<b>Qty</b>	1	
<b>Title</b>	2007 ETNYRE BLACKHAWK LOWBOY TRAILER	
<b>Des.</b>	SOLD WITH: 2007 ETNYRE FLIP AXLE (S/N: 1E92972857E111263) VIN TAG FOUND ON UNIT. 58ft Total Length, 48ft Trailer Length, 102in Width, Tri-Axle with Pin on 4th Axle, Adjustable King Pin Setting, Outriggers, D-Rings, Wood Decking, Steel Wheels, 255/70R22.5. Location: Des Moines, IA Serial: 1E92972837E111262	
<b>Lot #</b>	41	
<b>Qty</b>	1	
<b>Title</b>	2006 KENWORTH T800 REAR MIXER	
<b>Des.</b>	NON RUNNER. TRANSMISSION BROKEN IN HALF. MIXER FULL OF CONCRETE. DRIVE LINE REMOVED WITH TRUCK. CAT C13 430, Eaton 9LL, Chalmers Suspension, 20 FA, 46 RA, 240 WB, 10 Yrd Phoenix Rear Mixer, Conveyor Belts, Rear Outriggers, 40ft Length, 12ft Height, Pusher Axle, 150 Gallon Side Mount Water Tank, Aluminum Fuel Tank, Three Chutes, Aluminum Wheels, 425/65R22.5; 11R22.5, PTO, AC, Rust. Showing 100,406 Miles; 877 Hours. Location: Bridgeport, WV Serial: 1NKDLU0X96J136884	
<b>Lot #</b>	42	
<b>Qty</b>	1	
<b>Title</b>	2005 OSHKOSH F2346 6X6 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. LESS KEYS. REAR SUSPENSION CRACKED BEAM. Cummins ISM, Automatic, Chalmers Suspension, 23 FA, 46 RA, 212 WB, 214in Back Cab To End Frame, Aluminum Fuel Tank, Aluminum/Steel Wheels, 385/65R22.5; 11R22.5, PTO, AC, Dead Batteries, Rust. Showing 227,898 Miles; 27,343 Hours. Location: Tampa, FL Serial: 10TDDAC385S084304	
<b>Lot #</b>	43	
<b>Qty</b>	1	
<b>Title</b>	2009 FORD F150 PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Tailgate Won't Open, Tire Pressure Fault - See Photos, Fuel Filler Door Missing, Missing Both Front Hubcaps, Interior Worn, Various Body Damage/Rust. Showing 122,969 Miles. Location: Twinsburg, OH Serial: 1FTRF12809KB97865	
















<b>Lot #</b>	44	
<b>Qty</b>	1	
<b>Title</b>	2005 VOLVO L150E WHEEL LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. NON RUNNER. MISSING: TURBO, RADIATOR AND INSTRUMENT PANEL. L/Front TIRE FLAT. VE D9A LB E2- 287 HP, 4F/4R, 123in Bucket, EROPS, Steel Wheels, 26.6R25, Body Damage/Rust. Showing 21,703 Hours. Location: Freeport, TX Serial: 110241-8885	
<b>Lot #</b>	46	
<b>Qty</b>	1	
<b>Title</b>	2011 INTERNATIONAL 9900ix DAY CAB TRUCK	
<b>Des.</b>	NON RUNNER. BAD ENGINE - HOLE IN BLOCK. DRIVE LINE REMOVED. Cummins ISX 500 HP, Eaton 18 Speed, Air Ride Suspension, 220 WB, Air Slide Fifth Wheel, Wet Kit, Dual Aluminum Fuel Tank, 25.5ft Length, 10.75ft Height, Aluminum Wheels, 11R24.5, PTO, AC, Rust. Showing 334,871 Miles; 15,005 Hours. Location: Bridgeport, WV Serial: 3HSCKAPR2BN282807	
<b>Lot #</b>	47	
<b>Qty</b>	1	
<b>Title</b>	1997 VOLVO WG64 ROLLOFF TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Cummins M11 280 HP, Eaton 8LL, Hendrickson Suspension, 18 RA, 45 RA, 254 WB, Accurate Roll Off Body- 60,000 LB. Capacity, Non Steer Pusher Axle- 255/70R22.5, Spoke Wheels, 315/80R22.5, PTO, AC, Odometer Inoperable, Tarp Removed. Mileage Unavailable. Location: Durham, NC Serial: 4VHJCAPE0VR856665	
<b>Lot #</b>	49	
<b>Qty</b>	1	
<b>Title</b>	2001 MACK RD690S REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Mack EM7-275, Mack T2070, Walking Beam Suspension, 20 FA, 38 RA, 250 WB, 10.5 Yrd MTM Bridgmaster Rear Mixer, 70 Gallon Side Mount Water Tank, Aluminum Fuel Tank, 11,020 Lbs Steerable Pusher Axle With Steel Wheels 255/70R22.5, 13,200 Lbs Bridge Axle With Steel Wheels 11R22.5, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Rust. Showing 220,413 Miles; 24,653 Hours. Location: Omaha, NE Serial: 1M2P289C21M033351	
<b>Lot #</b>	50	
<b>Qty</b>	1	
<b>Title</b>	2011 CHEVROLET SILVERADO PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE, NOT ROAD TESTED. 5.3L FFV, Automatic, Spring Suspension, 133 WB, 3.3 FA, 3.75 RA, Steel Wheels, 245/70R17, AC, PW, PL, M, Radio Removed, Cracked Windshield, Rearview Mirror Missing, Body Damage/Rust. Showing 202,308 Miles. Location: Des Moines, IA Serial: 1GCNCSE05BZ308927	
<b>Lot #</b>	51	
<b>Qty</b>	1	
<b>Title</b>	2007 KENWORTH W900B CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE W/ JUMP START - NOT ROAD TESTED. BLOW BY. Oil Leaks Noted - See Report, Hydraulic Leaks, Check Engine Light Illuminated, Air Leak At Uncapped Hose Near Rear, Wires Hanging From Rear End, ECM Connection Not Found In Dash, Power Windows Only Function Intermittently, Dead Batteries, Interior Worn, Various Body Damage/Rust. Showing 188,472 Miles; 19,740 Hours. Location: Mokena, IL Serial: 1NKWL00X47J169911	







<b>Lot #</b>	53	
<b>Qty</b>	1	
<b>Title</b>	2005 KENWORTH W900 REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Cummins ISM, Eaton 8LL, Chalmers Suspension, 20 FA, 46 RA, 251 WB, 11 Yrd McNeilus Rear Mixer, 150 Gallon Side Mount Water Tank, Aluminum Fuel Tank, Three Chutes, Steel/Aluminum Wheels, 425/65R22.5; 295/75R22.5, PTO, AC, Rust. Showing 40,632 Miles. Location: Duluth, GA Serial: 1NKWL0EX95R104897	
<b>Lot #</b>	54	
<b>Qty</b>	1	
<b>Title</b>	1992 FORD F700 DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE, NOT ROAD TESTED. 6.6L Diesel, 6 Speed Manual, Spring Suspension, 9 FA, 19 RA, 154 WB, 10ft Heil Steel Body, Spoke Wheels, 11R22.5, Steel Fuel Tank, PTO, Body Damage/Rust. Showing 123,926 Miles; 1,889 Hours. Location: Des Moines, IA Serial: 1FDXK74P8NVA26618	
<b>Lot #</b>	55	
<b>Qty</b>	1	
<b>Title</b>	2005 HEIL BULK 1040 CU FT PNEUMATIC TRAILER	
<b>Des.</b>	Skin Has Gouging, Several Welded Repairs, Storage Tube Missing Cap, Tires Worn, Body Damage/Rust. Location: Mokena, IL Serial: 5HTSN422957T10660	
<b>Lot #</b>	56	
<b>Qty</b>	1	
<b>Title</b>	1995 MACK CS300P WATER TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Mack Renault 6 Cyl, 6 Speed Manual, Spring Suspension, 195 WB, 14ft Morgan Body, 1,000 Gallon Plastic Water Tank - No Hoses And No Pump, 25.5ft Total Length, 9ft Height, Steel Wheels, 11R22.5, Seat Torn. Showing 26,848 Miles; 747 Hours. Location: Harrisburg, PA Serial: VG6BA09B6SB701106	
<b>Lot #</b>	57	
<b>Qty</b>	1	
<b>Title</b>	2009 FORD EXPEDITION SUV	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Ford Triton 5.4L Gas, Automatic, Spring Suspension, 3.3 FA, 4.25 RA, 119 WB, Aluminum Wheels, 255/70R18, AC, PW, PL, PS, PM, Dead Batteries, Rust. Showing 158,423 Miles. Location: Pasadena, TX Serial: 1FMFU19539LA09768	
<b>Lot #</b>	58	
<b>Qty</b>	1	
<b>Title</b>	2012 FORD F250 PICKUP TRUCK	
<b>Des.</b>	NON RUNNER. ENGINE OIL DISCOLORED ON DIPSTICK. Check Engine Light Illuminated, Oil Light Illuminated, Battery Light Illuminated, Interior Worn, Tires Worn, Various Body Damage/Rust. Showing 173,602 Miles. Location: Findlay, OH Serial: 1FT7X2A62CEB81621	
<b>Lot #</b>	59	
<b>Qty</b>	1	
<b>Title</b>	2005 OSHKOSH F2346 6X6 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. BAD STARTER AND CABLES. Cummins ISM, Automatic, Chalmers Suspension, 23 FA, 46 RA, 212 WB, 214in Back Cab To End Frame, Aluminum Fuel Tank, Aluminum/Steel Wheels, 445/65R22.5; 11R22.5, PTO, AC, Rust. Showing 84,644 Miles; 18,670 Hours. Location: Tampa, FL Serial: 10TDDAC335S084338	














<b>Lot #</b>	61	
<b>Qty</b>	1	
<b>Title</b>	2000 MACK RD690S REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. AIR HOPPER AND HYDRAULIC CHUTE WOULD NOT GO UP. Mack EM7-275, Mack T2070, Walking Beam/Camelback Suspension, 20 FA, 38 RA, 250 WB, 90 Gallon Side Mount Water Tank, Aluminum Fuel Tank, 11,020 Lbs Air Lift Pusher Axle With Steel Wheels 255/70R22.5, 13,200 Lbs Bridge Axle With Steel Wheels 11R22.5, Aluminum/Spoke Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 232,735 Miles; 21,963 Hours. Location: Omaha, NE Serial: 1M2P289C3YM031179	
<b>Lot #</b>	62	
<b>Qty</b>	1	
<b>Title</b>	2008 GMC SIERRA 1500 PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. GMC 5.3L Gas, Automatic, Spring Suspension, 3.95 FA, 3.95 RA, 144 WB, 6.5ft Box W/ Bed Liner, Aluminum Wheels, 265/70R17, AC, PW, PL, PM, Check Engine Light Illuminated, Body Damage/Rust. Showing 221,776 Miles. Location: Buckhannon, WV Serial: 1GTEK19J28Z150586	
<b>Lot #</b>	63	
<b>Qty</b>	1	
<b>Title</b>	2009 AUTOCAR WX64 GARBAGE PACKER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. DO NOT DRIVE. BAD HYDRAULIC LEAK. ENGINE BLOW BY. Cummins ISM 350, Automatic, Hendrickson Suspension, 20 FA, 46 RA, 184 WB, 40 Yrd EZ Pack, Front Loader, Tag Axle, Steel Wheels, 315/80R22.5, PTO, AC, Backup Camera, Could Not Jack Cab - Body Arms Down, Rust. Showing 305,931 Miles; 22,593 Hours. Location: High Point, NC Serial: 5VCACLKF49H209693	
<b>Lot #</b>	64	
<b>Qty</b>	1	
<b>Title</b>	2016 CATERPILLAR 938M WHEEL LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED ON SITE - NOT ROAD TESTED. COOLANT LOW. Tires Have Chunks Missing/Slices In Tread - See Photos, Top Front Lights Missing, Various Body Damage/Rust. Showing 15,128 Hours. Location: Albertville, AL Serial: J3R02917	
<b>Lot #</b>	65	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK DM690S REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Mack AMI-335 ASET, TM309 9 Speed, Camelback Suspension, 216 WB, 10.5 Yrd McNeilus Rear Mixer, 90 Gallon Side Mount Water Tank, Steel Fuel Tank, One Chute, Steel Wheels, 425/65R22.5; 275/80R22.5, PTO, AC, Rust. Showing 164,123 Miles; 17,259 Hours. Location: Duluth, GA Serial: 1M2B209C66M030780	
<b>Lot #</b>	66	
<b>Qty</b>	1	
<b>Title</b>	2007 CASE 430 SKID LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. 4 Cylinder 2239, Family III 445/M2. Tier 2 Certified, 70in Bucket- 0.6 YRD 3 Capacity, OROPS, Steel Wheels, 305/70R16.5. Showing 3,887 Hours. Location: Des Moines, IA Serial: N7M454271	

<b>Lot #</b>	67	
<b>Qty</b>	1	
<b>Title</b>	2000 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. MISSING IGNITION. Mack E7-350, Eaton 9 Speed LL, Camelback Suspension, 268 WB, 220in Back Cab To End Frame, Dual Aluminum Fuel Tanks, Double Frame, Steel Wheels, 315/80R22.5, AC, Rust. Showing 916,969 Miles; 32,607 Hours. Location: Houston, TX Serial: 1M2P267C8YM052617	
<b>Lot #</b>	69	
<b>Qty</b>	1	
<b>Title</b>	1997 MACK RD690S DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Oil Leak At Lower Left Side Of Engine, Tarp System Inop, Left Front Shock Leaking, Various Body Damage/Rust. Showing 249,590 Miles; 18,821 Hours. Location: Calera, AL Serial: 1M2P264C5VM023981	
<b>Lot #</b>	70	
<b>Qty</b>	1	
<b>Title</b>	2009 CHEVROLET SILVERADO 1500 4X4 EXT CAB PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. GMC 5.3L Gas, Automatic, Spring Suspension, 3.95 FA, 3.95 RA, 145 WB, 6.5ft Box W/ Liner, Aluminum Wheels, 265/70R17, AC, PW, PL, PM, Rust. Showing 256,235 Miles. Location: Mabscott, WV Serial: 1GCEK29JX9Z192981	
<b>Lot #</b>	71	
<b>Qty</b>	1	
<b>Title</b>	1988 PETERBILT 379 WINCH TRUCK	
<b>Des.</b>	STARTED ON SITE W/ STARTING FLUID - NOT ROAD TESTED. CLUTCH WORN. BRAKES LOCKED UP - WILL NOT MOVE. Cummins Big Cam IV, Two Stick Duplex Transmission, Walking Beam Suspension, 226 WB, Manual Fifth Wheel, Braden Rear Winch, Dual Aluminum Fuel Tanks, Aluminum/Steel Wheels, 11R24.5, PTO, Dead Batteries, Hub Cab Leaking, Body Damage/Rust. Showing 82,721 Miles. Location: Pasadena, TX Serial: 1XP5D29X0JD261787	
<b>Lot #</b>	72	
<b>Qty</b>	1	
<b>Title</b>	2012 INTERNATIONAL PROSTAR DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. ENGINE WARNING ILLUMINATED. International Maxxforce 450 HP, Eaton 10 Speed, Air Ride Suspension, 13.22 FA, 40 RA, 189 WB, Manual Fifth Wheel, Wet Kits, Dual Aluminum Fuel Tanks, Aluminum/Steel Wheels, 11R24.5, PTO, AC, ABS Warning Light Illuminated. Showing 248,369 Miles; 11,855 Hours. Location: Tyler, TX Serial: 1HSDJSJR9CJ102511	
<b>Lot #</b>	73	
<b>Qty</b>	1	
<b>Title</b>	2000 MACK RD690S REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. ENGINE BLOW BY. Mack EM7-275, Mack T2070, Walking Beam Suspension, 20 FA, 38 RA, 250 WB, 10.5 Yrd MTM Bridgemaster Rear Mixer, 75 Gallon Side Mount Water Tank, Aluminum Fuel Tank, 11,020 Lbs Air Lift Pusher Axle With Steel Wheels 255/70R22.5, 13,200 Lbs Bridge Axle With Steel Wheels 11R22.5, Aluminum/Spoke Wheels, 425/65R22.5; 11R22.5, PTO, AC, Oil Leaks, Body Damage/Rust. Showing 268,019 Miles; 9,538 Hours. Location: Omaha, NE Serial: 1M2P289C1YM031178	








<b>Lot #</b>	74	
<b>Qty</b>	1	
<b>Title</b>	2011 FORD F250 PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. COOLANT APPEARS DISCOLORED. Oil Residue On Upper Right Side Of Engine, Active Fault - See Report, TPMS Light Illuminated, Interior Worn, Tires Worn, Various Body Damage/Rust. Showing 191,481 Miles; 10,120 Hours. Location: Twinsburg, OH Serial: 1FTBF2A68BEC37170	
<b>Lot #</b>	75	
<b>Qty</b>	1	
<b>Title</b>	2007 PETERBILT 357 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. CAT C9, Automatic, Hendrickson Suspension, 22 FA, 44 RA, 218 WB, 206in Back Cab To End Frame, Aluminum Fuel Tank, Aluminum Wheels, 445/65R22.5; 11R22.5, AC, Oil Leaks At Extra Oil Filter, Frame Rust, Right Rear Tire Singled Out, Rust. Showing 192,058 Miles; 22,592 Hours. Location: Tampa, FL Serial: 1NPALF0X57N657944	
<b>Lot #</b>	76	
<b>Qty</b>	1	
<b>Title</b>	STEEL DUMP BODY	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. 18ft Steel Dump Box, 2ft Over Cab Length, 92in Width, Lift Cylinder, Rust. Location: Des Moines, IA Serial: 3122382	
<b>Lot #</b>	77	
<b>Qty</b>	1	
<b>Title</b>	2004 MACK DM690S REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Mack AMI-300 ASET, Mack T309M 9 Speed, 218 WB, 10.5 Yrd McNeilus Rear Mixer, 90 Gallon Side Mount Water Tank, Three Chutes, Aluminum/Steel Wheels, 425/65R22.5; 295/75R22.5, PTO, AC, Dead Batteries, Body Damage/Rust. Showing 122,566 Miles; 16,201 Hours. Location: Duluth, GA Serial: 1M2B209C94M030043	
<b>Lot #</b>	78	
<b>Qty</b>	1	
<b>Title</b>	2015 MACK MRU688S GARBAGE PACKER	
<b>Des.</b>	NON RUNNER. TRUCK HEAVILY BURNED IN FIRE. MISSING SEVERAL COMPONENTS. Walking Beam Suspension, 216 WB, 40 Yrd New Way Front Loader, Double Frame, Steel Wheels, 315/80R22.5, PTO, Body Damage/Rust. Mileage Unavailable. Location: Bardstown, KY Serial: 1M2AV04C1FM012598	
<b>Lot #</b>	80	
<b>Qty</b>	1	
<b>Title</b>	2007 CHEVROLET EXPRESS VAN BODY TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. LIFT GATE INOP. ENGINE OIL LEAKS. BOX FULL - SEE PHOTOS. GMC V8, Automatic, Spring Suspension, 4.3 FA, 8.6 RA, 160 WB, 14ft B And B Body, Tommy Lift Gate, Steel Wheels, 225/75R16, AC, Dead Batteries, Body Damage/Rust. Showing 350,843 Miles. Location: Garner, NC Serial: 1GBJG31U271112262	
<b>Lot #</b>	81	
<b>Qty</b>	1	
<b>Title</b>	2011 CHEVROLET SILVERADO 1500 4X4 PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. GMC 5.3L V8, Automatic, Spring Suspension, 3.95 FA, 3.95 RA, 134 WB, 8ft Box W/ Liner, Aluminum Wheels, 265/70R17, AC, PW, PL, PM, Body Damage/Rust. Showing 252,951 Miles. Location: Buckhannon, WV Serial: 1GCNKPE01BZ304910	








<b>Lot #</b>	82	
<b>Qty</b>	1	
<b>Title</b>	2005 INTERNATIONAL 5500i CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. ENGINE PARTED OUT. BAD FRAME. TRANSMISSION CONTROLS MISSING. UNIT RED TAGGED. Cummins ISM, Automatic, 20 FA, 46 RA, 236 WB, Body Damage/Rust. Mileage Unavailable. Location: Pasadena, TX Serial: 1HTXLAHTX5J132102	
<b>Lot #</b>	83	
<b>Qty</b>	1	
<b>Title</b>	1983 CATERPILLAR 950B WHEEL LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. Hydraulic Oil Leaks Surrounding Articulating Knuckle In Center Of Vehicle, Several Oil Leaks - See Report, Left Steering Cylinder And Bucket Tilt Hydraulic Cylinder Leaking Front Shaft Seals, Lights Inop., Tires Worn, Body Damage/Rust. Showing 5,112 Hours. Location: Miami, FL Serial: 22Z00925	
<b>Lot #</b>	84	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CH613 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Mack AC-427, Spicer LLPSO150-10S, Air Ride Suspension, 12 FA, 44 RA, 196 WB, Air Slide Fifth Wheel, Aluminum Fuel Tank, Steel Wheels, 11R22.5, AC, Warning Lights Active, Rust. Showing 692,954 Miles; 31,586 Hours. Location: Des Moines, IA Serial: 1M1AJ06Y46N005793	
<b>Lot #</b>	85	
<b>Qty</b>	1	
<b>Title</b>	2001 MACK RD690S REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. TRUCK WONT MOVE. AIR HOPPER WONT GO UP. Mack EM7-275, Mack T2070, Walking Beam Suspension, 20 FA, 38 RA, 250 WB, 10.5 Yrd MTM Bridgmaster Rear Mixer, 70 Gallon Side Mount Water Tank, Aluminum Fuel Tank, 11,020 Lbs Steerable Pusher Axle With Steel Wheels 255/70R22.5, 13,200 Lbs Bridge Axle With Steel Wheels 11R22.5, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Transmission Possibly Stuck Between High And Low Range - Could Not Confirm, Body Damage/Rust. Showing 235,153 Miles; 24,221 Hours. Location: Omaha, NE Serial: 1M2P289C01M033350	
<b>Lot #</b>	86	
<b>Qty</b>	1	
<b>Title</b>	2011 FORD F150 PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Tailgate Removed, Right Front Strut Assembly Collapsed, Tires Worn, Interior Worn, Various Body Damage/Rust. Showing 157,376 Miles. Location: Findlay, OH Serial: 1FTNF1CF2BKD53258	
<b>Lot #</b>	87	
<b>Qty</b>	1	
<b>Title</b>	ALUMINUM DUMP BODY	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. 16.5ft Length, 97in Width, Aluminum Composition, Tarp System. Location: Des Moines, IA Serial: UNIT 30	








<b>Lot #</b>	89	
<b>Qty</b>	1	
<b>Title</b>	2005 MACK CV713 REAR MIXER	
<b>Des.</b>	NON RUNNER. ENGINE APART - SOME PARTS IN CAB. OIL PAN LOOSE ON ENGINE. MISSING COOLANT TANK. Mack AMI-335 ASET, Eaton Fuller RTO14908LL, Hendrickson Suspension, 231 WB, 11 Yrd McNeilus Rear Mixer, 125 Gallon Side Mount Water Tank, Aluminum Fuel Tank, Three Chutes, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Rear Tires Flat, Rust. Showing 262,664 Miles; 28,083 Hours. Location: Duluth, GA Serial: 1M2AG11C85M016036	
<b>Lot #</b>	90	
<b>Qty</b>	1	
<b>Title</b>	2007 ADVANCE FD6000 FRONT MIXER	
<b>Des.</b>	NON RUNNER. BAD ENGINE. CAT C13, Automatic, Air Ride Suspension, 22 FA, 46 RA, 208 WB, 11 Yrd Terex Front Mixer, 200 Gallon Cross Mount Water Tank, Dual Pusher Axles, Tag Axle, Aluminum Fuel Tank, Three Chutes, 41ft Length, 12.75ft Height, Aluminum Wheels, 445/65R22.5; 11R22.5, PTO, AC, Missing Exhaust Pipe, Fan Hub, And Blade, Body Damage/Rust. Showing 136,643 Miles; 15,970 Hours. Location: Bridgeport, WV Serial: 5DG8AC6G170000569	
<b>Lot #</b>	91	
<b>Qty</b>	1	
<b>Title</b>	2006 PETERBILT 357 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. CAT C9, Automatic, Hendrickson Suspension, 22 FA, 44 RA, 220 WB, 214in Back Cab To End Frame, Aluminum Fuel Tank, Aluminum/Steel Wheels, 445/65R22.5; 11R22.5, AC, Right Front Tire Poor Condition, Rust. Showing 205,781 Miles; 23,882 Hours. Location: Tampa, FL Serial: 1NPALFOX86N652493	
<b>Lot #</b>	92	
<b>Qty</b>	1	
<b>Title</b>	2004 INTERNATIONAL 4300 MECHANICS TRUCK	
<b>Des.</b>	STARTED ON SITE W/ STARTING FLUID - NOT ROAD TESTED. NO BRAKES. BOOM DOES NOT FUNCTION. BODY BENT. LESS DASH CLUSTER. International DT466 Diesel, Automatic, Air Ride Suspension, 9.35 FA, 17.64 RA, 151 WB, IMT DOM-2-11 Service Body W/ Boom, R/ Outriggers, Aluminum Wheels, 255/70R22.5, AC, Body Missing Storage Box Doors, Dead Batteries, Only One Rear Outrigger Attached, Body Damage/Rust. Mileage Unavailable. Location: Des Moines, IA Serial: 1HTMMAAL24H653041	
<b>Lot #</b>	93	
<b>Qty</b>	1	
<b>Title</b>	2008 AUTOCAR WXL64 GARBAGE PACKER	
<b>Des.</b>	NON RUNNER. CLICK NOISE ONLY. KNOWN TRANSMISSION PROBLEMS. MISSING RELAYS. DRIVE SHAFT REMOVED WITH TRUCK. MISSING AIR CLEANER. Cummins ISM 320 HP, Automatic, Hendrickson Suspension, 20 FA, 46 RA, 210 WB, 28 Yrd Heil Side Loader, L/R Steering, Steel Wheels, 315/80R22.5, PTO, AC, Backup Camera, Right Side Tires Flat, Missing Hydraulic Tank Cap, Missing Diesel Fuel Tank Cap, Body Damage/Rust. Showing 37,664 Miles. Location: Americus, GA Serial: 5VCHC6BE68H205764	
<b>Lot #</b>	94	
<b>Qty</b>	1	
<b>Title</b>	2009 FORD F150 PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Tires Worn, Various Body Damage/Rust. Showing 137,179 Miles. Location: Findlay, OH Serial: 1FTRF12869KB97871	








<b>Lot #</b>	95	
<b>Qty</b>	1	
<b>Title</b>	1996 MACK DM690S CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. HEATER CORE DISCONNECTED FROM ENGINE. Mack EM7-300 MECH, T2070, Camelback Suspension, 204 WB, 216in Back Cab To End Frame, Dual Steel Fuel Tanks, Spoke Wheels, 385/65R22.5; 11R22.5, PTO, AC, Air Leaks In Dash, Broken Door Handle, Dead Batteries, Body Damage/Rust. Showing 393,710 Miles; 11,744 Hours. Location: Brooksville, FL Serial: 1M2B209C1TM017916	
<b>Lot #</b>	96	
<b>Qty</b>	1	
<b>Title</b>	2007 INTERNATIONAL 9200i DAY CAB TRUCK	
<b>Des.</b>	NON RUNNER. NO TRANSMISSION COMMUNICATION. ENGINE WONT CRANK. Cummins ISM 370HP, Auto Shift Trans, Air Ride Suspension, 12 FA, 40 RA, 190 WB, Steel Wheels, 295/75R22.5, Dual Aluminum Fuel Tanks, AC, Active Fault Code 128 F06, Body Damage/Rust. Showing 679,597 KM; 24,932 Hours. Location: Tampa, FL Serial: 2HSCEAHR07C496807	
<b>Lot #</b>	97	
<b>Qty</b>	1	
<b>Title</b>	2010 MACK GU713 REAR MIXER	
<b>Des.</b>	NON RUNNER. DRIVE SHAFT REMOVED. MISSING DASH COMPONENTS. Mack MP7-365, Mack TM308M 9 Speed, Walking Beam Suspension, 18.74 FA, 38 RA, 248 WB, 11 Yrd MTM Rear Mixer, Tag Axle Mixer System, Double Frame, 100 Gallon Cross Mount Water Tank, 70 Gallon Aluminum Fuel Tank, 11,020 Lbs Air Lift Steerable Pusher Axle With Steel Wheels 255/70R22.5, 11,020 Air Lift Steerable Tag Axle With Steel Wheels 255/70R22.5, Aluminum/Steel Wheels, 385/65R22.5; 11R22.5, PTO, AC, Driver's Door Apart, Rust. Mileage Unavailable. Location: Omaha, NE Serial: 1M2AX04C3AM009236	
<b>Lot #</b>	98	
<b>Qty</b>	1	
<b>Title</b>	2000 FORD F550 4X4 SERVICE TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. ENGINE SKIP. Ford Power Stroke Diesel, Automatic, Spring Suspension, 6 FA, 13.5 RA, 141 WB, 9ft Auto Crane Service Body, Body Storage, 19.5ft Total Length, 7.25ft Height, Steel Wheels, 225/70R19.5, AC, Door Panel Removed, Broken Right Door Handle, Rust. Showing 199,210 Miles. Location: Buckhannon, WV Serial: 1FDAF57F8YED67832	
<b>Lot #</b>	99	
<b>Qty</b>	1	
<b>Title</b>	RED-D-ARC GX300 WELDER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. TURNS OVER BUT DOES NOT START. Koehler Engine, Body Damage/Rust. Showing 2,232 Hours. Location: Des Moines, IA Serial: N/A	
<b>Lot #</b>	100	
<b>Qty</b>	1	
<b>Title</b>	2007 CHEVROLET SILVERADO 2500 PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Oil In Coolant, Check Engine Light Illuminated, TPMS Light Illuminated, Rear Seats Removed, Left Door Check Damaged, Left Mirror Cracked, Interior Worn, Tires Worn, Various Body Damage/Rust. Showing 162,641 Miles. Location: Findlay, OH Serial: 1GCHC29KX7E587377	














<b>Lot #</b>	101	
<b>Qty</b>	1	
<b>Title</b>	2005 INTERNATIONAL 5500i REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. BAD FRAME. BAD DRUM. Cummins ISM, Eaton 9 Speed LL, Hendrickson Suspension, 236 WB, Side Mount Water Tank, Aluminum Fuel Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Tires Flat Off Rim, No Chutes, Dead Batteries, Body Damage/Rust. Showing 174,557 Miles; 18,633 Hours. Location: Pasadena, TX Serial: 1HTXL AHT55J155111	
<b>Lot #</b>	102	
<b>Qty</b>	1	
<b>Title</b>	MAGNAMAX 573RSL4032 SYNCHRONOUS AC GENERATOR	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. NON RUNNER. ENGINE APART. Parts Box Included, Rust. Location: Des Moines, IA Serial: WA-541285-0904	
<b>Lot #</b>	103	
<b>Qty</b>	1	
<b>Title</b>	2006 PETERBILT 357 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. CAT C9, Automatic, Hendrickson Suspension, 22 FA, 44 RA, 220 WB, 214in Back Cab To End Frame, Aluminum Fuel Tank, Aluminum Wheels, 445/65R22.5; 11R22.5, AC, Rust. Showing 311,686 Miles; 26,278 Hours. Location: Tampa, FL Serial: 1NPALF0X96N652499	
<b>Lot #</b>	104	
<b>Qty</b>	1	
<b>Title</b>	2016 JOHN DEERE 324K WHEEL LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. ENGINE HAS FIRE DAMAGE AT EXHAUST, TURBO, WIRE HARNESS, AND AIR CLEANER ASSEMBLY. RED SHUT DOWN LIGHT ILLUMINATED. John Deere 4 Cyl Diesel, Automatic, Enclosed ROPS, 84x37in Quick Disconnect Bucket, Steel Wheels, 160/70R20, AC/Heated Cabs, Dead Batteries, Dash Inoperable, Rust. Hours Unavailable. Location: Honeybrook, PA Serial: 1LU324KXKZB041039	
<b>Lot #</b>	105	
<b>Qty</b>	1	
<b>Title</b>	2004 FORD F350 PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE, NOT ROAD TESTED. 6.0L V8 Diesel, Automatic, Spring Suspension, 4.4 FA, 6.83 RA, 137 WB, 8ft Box, Steel Wheels, 265/75R16, AC, Body Damage/Rust Throughout. Showing 234,262 Miles. Location: Des Moines, IA Serial: 1FTSF30P04EE07587	
<b>Lot #</b>	106	
<b>Qty</b>	1	
<b>Title</b>	2011 KENWORTH T370 STRAIGHT TRUCK	
<b>Des.</b>	STARTED ON SITE, NOT ROAD TESTED. Paccar X-8 Diesel (Engine Tag Not Located), Automatic, Air Ride Suspension, 14 FA, 23 RA, 195 WB, 16.5ft Supreme Body, Left Gate, Steel Wheels, 11R22.5, AC, Check Engine Light Illuminated. Showing 295,765 Miles; 22,277 Hours. Location: Des Moines, IA Serial: 2NKHHN8X5BM282084	
<b>Lot #</b>	107	
<b>Qty</b>	1	
<b>Title</b>	2005 VOLVO VNL64T DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Oil Leaks/Seepage Noted - See Report, Several Active Faults - See Report, Residue Buildup On Inboard Side On Right Fuel Tank, Left Window Crank Missing, Interior Worn, Various Body Damage/Rust. Showing 974,067 Miles; 34,519 Hours. Location: Newberry, IN Serial: 4V4NC9GF25N374345	

<b>Lot #</b>	108	
<b>Qty</b>	1	
<b>Title</b>	BRUNNER FRABRICATION WET KIT MOUNT STORAGE BOXES MISC	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. 7ft Total Height, 5.5ft Body Height W/O Lights. Location: Des Moines, IA Serial: N/A	
<b>Lot #</b>	109	
<b>Qty</b>	1	
<b>Title</b>	2004 MACK DM690S REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. BAD FRAME. Mack AMI-335 ASET, TM309M Maxitorque 9 Speed, Bogey Suspension, 20 FA, 46.72 RA, 225 WB, Side Mount Water Tank, Steel Fuel Tank, Steel Wheels, 425/65R22.5; 11R22.5, AC, Rust. Showing 234,830 Miles; 25,884 Hours. Location: Harlingen, TX Serial: 1M2B209C14M030103	
<b>Lot #</b>	110	
<b>Qty</b>	1	
<b>Title</b>	2016 AUTOCAR ACX64 GARBAGE PACKER	
<b>Des.</b>	NON RUNNER. TRUCK HAS HEAVY FIRE DAMAGE INCLUDING CAB AND FRONT TIRES - SEE PHOTOS. Hendrickson Suspension, 215 WB, 28 Yrd Heil Side Loader, Double Frame, Steel Wheels, 315/80R22.5, Body Damage/Rust. Mileage Unavailable. Location: Bardstown, KY Serial: 5VCACRVF9GH220460	
<b>Lot #</b>	111	
<b>Qty</b>	1	
<b>Title</b>	2005 INTERNATIONAL 5500i CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. UNIT HAS BEEN PARTED OUT - COMPONENTS MISSING, INCLUDING PTO. Cummins ISM, Eaton 9 Speed, 20 FA, 46 RA, 236 WB, Brake Cans Opened, Body Damage/Rust. Mileage Unavailable. Location: Pasadena, TX Serial: 1HTXLAHT55J155108	
<b>Lot #</b>	112	
<b>Qty</b>	1	
<b>Title</b>	2003 FORD RANGER PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Ford 3.0L Gas, Automatic, Spring Suspension, 2.5 FA, 2.6 RA, 126 WB, 5.25ft Box W/ Liner, Steel Wheels, 225/70R15, AC, PW, PL, PM, Broken Rear Door Handles, Body Damage/Rust. Showing 176,733 Miles. Location: Sanford, FL Serial: 1FTYR44V53PA20780	
<b>Lot #</b>	113	
<b>Qty</b>	1	
<b>Title</b>	2001 MACK DM690S REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. CRACKED FRAME. Mack Reman, Maxitorque 8 Speed, Camelback Suspension, 22 FA, 46 RA, 215 WB, 10.5 Yrd Beck Rear Mixer, Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Dead Batteries, Rust. Showing 276,352 Miles; 26,704 Hours. Location: Fort Worth, TX Serial: 1M2B209C71M028142	
<b>Lot #</b>	116	
<b>Qty</b>	1	
<b>Title</b>	MAGNA 433RSL4019 SYNCHRONOUS AC GENERATOR	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. Location: Des Moines, IA Serial: WA-509955-0697	

<b>Lot #</b>	117	
<b>Qty</b>	1	
<b>Title</b>	2003 FORD F250 PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. MISSING BATTERIES. SMOKE OUT EXHAUST. Ford Power Stroke Diesel, Automatic, Spring Suspension, 5.2 FA, 6.084 RA, 156 WB, 6.5ft Box, Steel Wheels, 265/75R16, AC, PW, PL, PM, Body Damage/Rust. Showing 597,484 Miles. Location: Winter Park, FL Serial: 1FTNW21F83EA95627	
<b>Lot #</b>	119	
<b>Qty</b>	1	
<b>Title</b>	2009 MACK CHU613 DAY CAB TRUCK	
<b>Des.</b>	NON RUNNER. Active Fault Codes - See Report, Oil Leaks Around Transmission PTO, Front Of Engine, and Front Of Oil Pan, Windshield Chipped, Tires Worn, Various Body Damage/Rust. Showing 229,405 Miles; 16,272 Hours. Location: Tacoma, WA Serial: 1M1AN07Y09N004101	
<b>Lot #</b>	120	
<b>Qty</b>	1	
<b>Title</b>	OIL TANK WITH PUMP MISC	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. Location: Des Moines, IA Serial: 226607	
<b>Lot #</b>	121	
<b>Qty</b>	1	
<b>Title</b>	2007 INTERNATIONAL 5000S REAR MIXER	
<b>Des.</b>	NON RUNNER. FRAME AND SUSPENSION NOTED AS BAD. DRIVESHAFT MISSING. Cummins ISM, Automatic, Hendrickson Suspension, 236 WB, 10.5 YRD. Beck Mixer, Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R24.5, PTO, AC. Milage Unavailable. Location: San Antonio, TX Serial: 1HTXLAHT97J459593	
<b>Lot #</b>	122	
<b>Qty</b>	1	
<b>Title</b>	1993 FORD F350 SERVICE TRUCK	
<b>Des.</b>	STARTED ON SITE, LESS KEYS. BROKEN IGNITION. NOT ROAD TESTED. 5.8L V8, Automatic, Spring Suspension, 6.565 FA, 8.25 RA, 138 WB, 9ft Omaha Body, Steel Wheels, 215/85R16, Receiver Hitch, Rear ABS Light Illuminated, Rust. Showing 320,580 Miles. Location: Des Moines, IA Serial: 1FDKF37H4PNA51353	
<b>Lot #</b>	124	
<b>Qty</b>	1	
<b>Title</b>	2000 FORD F250 PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. DO NOT DRIVE - LOW BRAKE PEDAL. NO BOX. Ford Triton 5.4L Gas, Automatic, Spring Suspension, 3.65 FA, 6.084 RA, 137 WB, Steel Wheels, 235/85R16, AC, Dead Batteries, Brake Warning Light Illuminated, Interior In Poor Condition, Rust. Showing 268,667 Miles. Location: High Point, NC Serial: 1FTNF20L5YED61331	
<b>Lot #</b>	125	
<b>Qty</b>	1	
<b>Title</b>	2005 MACK DM690S REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. CLUTCH WORN OUT. LESS KEYS. Mack AMI-300 ASET, Maxitorque TM309 9 Speed, Camelback Suspension, 208 WB, 10.5 Yrd Beck Rear Mixer, Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Left Rear Fender Missing, Right Rear Tires Singled Out, ABS Light Illuminated, Rust. Showing 301,546 Miles; 30,508 Hours. Location: Austin, TX Serial: 1M2B209C15M030572	

<b>Lot #</b>	126	
<b>Qty</b>	1	
<b>Title</b>	2009 AUTOCAR ACX GARBAGE PACKER	
<b>Des.</b>	NON RUNNER. ELECTRONIC PARTS REMOVED. NO POWER TO TRUCK. Cummins ISL 345 HP, Allison Automatic, Hendrickson Suspension, 20 FA, 46 RA, 215 WB, 31 Yrd McNeilus Side Loader, Double Frame, 70 Gallon Aluminum Fuel Tank, Steel Wheels, 315/80R22.5, PTO, AC, Body Damage/Rust. Mileage Unavailable. Location: Bardstown, KY Serial: 5VCD6JFX9H208063	
<b>Lot #</b>	127	
<b>Qty</b>	1	
<b>Title</b>	2007 PETERBILT 357 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. MISSING TRANSMISSION, IGNITION SWITCH, AND DRIVE LINE. CAT C9, Hendrickson Suspension, 20 FA, 44 RA, 224 WB, 218in Back Cab To End Frame, Pusher Axle, Aluminum Fuel Tank, Aluminum Wheels, 425/65R22.5; 11R22.5, AC, Dead Batteries, Left Rear Tire Flat, Rust. Mileage Unavailable. Location: Tampa, FL Serial: 1NPALFEX77D731878	
<b>Lot #</b>	128	
<b>Qty</b>	1	
<b>Title</b>	OIL TANK WITH PUMP MISC	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. Location: Des Moines, IA Serial: 226608	
<b>Lot #</b>	129	
<b>Qty</b>	1	
<b>Title</b>	2006 HINO 268 STRAIGHT TRUCK	
<b>Des.</b>	NON RUNNER. BAD STARTER. BAD INJECTORS. DASH APART. Hino J08E-TA Diesel, Automatic, Spring Suspension, 10 FA, 19 RA, 254 WB, 24ft Supreme Body, 12.75ft Height, Left Side Door, Lift Gate, Steel Wheels, 11R22.5, AC, Minor Rust. Showing 466,748 Miles. Location: Stockbridge, GA Serial: 5PVNE8JT862S12138	
<b>Lot #</b>	130	
<b>Qty</b>	1	
<b>Title</b>	2004 FORD F150 XLT EXT CAB PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Ford 4.2L Gas, Automatic, Spring Suspension, 2.95 FA, 3.2 RA, 139 WB, Steel Wheels, 235/70R16, AC, ABS Warning Light Illuminated, Body Damage/Rust. Showing 195,699 Miles. Location: Columbus, NE Serial: 2FTRX17264CA65756	
<b>Lot #</b>	131	
<b>Qty</b>	1	
<b>Title</b>	1993 CHEVROLET C3500 SERVICE TRUCK	
<b>Des.</b>	NON RUNNER. CRANKS NO START. GM 5.7L Gas, 5 Speed Manual, Spring Suspension, 138 WB, 9ft Rawson Koenig Service Body, Body Storage, Steel Wheels, 225/75R16, AC, Dead Batteries, Rust. Showing 180,819 Miles. Location: Corpus Christi, TX Serial: 1GBJC34K6PE232953	
<b>Lot #</b>	132	
<b>Qty</b>	1	
<b>Title</b>	2004 MACK CH613 DAY CAB TRUCK	
<b>Des.</b>	NON RUNNER. ENGINE APART - SOME PARTS IN CAB. MISSING ENGINE ECM. Mack AC-427 ASET, T310 10 Speed, Air Ride Suspension, 204 WB, Air Slide Fifth Wheel, Dual Aluminum Fuel Tanks, Aluminum/Steel Wheels, 11R24.5, AC, Rear Tires Singled Out, Rust. Mileage Unavailable. Location: Orlando, FL Serial: 1M1AA18Y24N157099	

<b>Lot #</b>	133	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CT713 REAR MIXER	
<b>Des.</b>	NON RUNNER. BAD ENGINE, PARTED OUT. INSTRUMENT PANEL MISSING. Mack AI-350 ASET, Allison 4500RDS Automatic, Camelback Suspension, 213 WB, Beck Rear Mixer, Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, Rust. Mileage Unavailable. Location: San Antonio, TX Serial: 1M2AL02C46M003838	
<b>Lot #</b>	134	
<b>Qty</b>	1	
<b>Title</b>	1995 FORD F150 PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Ford 4.9L Gas, Automatic, Spring Suspension, 2.8 FA, 3.166 RA, 133 WB, 8ft Box, Steel Wheels, 235/75R15, AC, Tailgate Off - In Bed, Body Damage/Rust. Showing 137,026 Miles. Location: Columbus, NE Serial: 1FTDF15Y9SLB43213	
<b>Lot #</b>	135	
<b>Qty</b>	1	
<b>Title</b>	2007 INTERNATIONAL 4300 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. CRANKS - NO START. International DT466, Automatic, Spring Suspension, 152 WB, 136in Back Cab To End Frame, Steel Fuel Tank, Steel Wheels, 11R22.5, Rust. Showing 232,294 Miles; 9,958 Hours. Location: Pasadena, TX Serial: 1HTMMAAM27H414876	
<b>Lot #</b>	136	
<b>Qty</b>	1	
<b>Title</b>	OIL TANK MISC	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. Location: Des Moines, IA Serial: N/A	
<b>Lot #</b>	137	
<b>Qty</b>	1	
<b>Title</b>	2007 KENWORTH T800B REAR MIXER	
<b>Des.</b>	NON RUNNER. UNIT HAS BEEN WRECKED - FRAME BENT, HOOD DAMAGED. UNIT PARTIALLY PARTED OUT. INSTRUMENT PANEL MISSING. Cummins ISL, Eaton 10 Speed LL, Spring Suspension, 20 FA, 46 RA, 253 WB, CBMW Rear Mixer, Side Mount Water Tank, Aluminum Fuel Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Mileage Unavailable. Location: San Antonio, TX Serial: 1NKDL50X47J207674	
<b>Lot #</b>	138	
<b>Qty</b>	1	
<b>Title</b>	2007 FORD RANGER PICKUP TRUCK	
<b>Des.</b>	NON RUNNER. CRANKS NO START. BODY DAMAGE FROM COLLISION - AIRBAG DEPLOYED. STEERING COLUMN BROKEN. Ford 2.3L, Automatic, Spring Suspension, 2.1 FA, 2.55 RA, 112 WB, Steel Wheels, 225/70R15, AC, Check Engine Light Illuminated, Cracked Windshield, Tire Damaged - See Photos, Rust. Showing 161,638 Miles. Location: Corpus Christi, TX Serial: 1FTYR10DX7PA04723	
<b>Lot #</b>	139	
<b>Qty</b>	1	
<b>Title</b>	1993 CHEVROLET C3500 SERVICE TRUCK	
<b>Des.</b>	NON RUNNER. LESS KEYS. GM 454 Gas, 5 Speed Manual, Spring Suspension, 135 WB, 9ft Reading Service Body, Lift Gate, Body Storage, Steel Wheels, 225/75R16, AC, Interior Worn, Rust. Showing 228,381 Miles. Location: San Antonio, TX Serial: 1GBHC34N3PE104971	

<b>Lot #</b>	140	
<b>Qty</b>	1	
<b>Title</b>	HOMEMADE SPRAY UTILITY TRAILER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. NON RUNNER - ENGINE SEIZED. Intek Gas, Steel Wheels, SY/175/80D13, Rust. Location: Des Moines, IA Serial: N/A	
<b>Lot #</b>	141	
<b>Qty</b>	1	
<b>Title</b>	1998 FORD F150 PICKUP TRUCK	
<b>Des.</b>	NON RUNNER. ENGINE LOCKED UP. Ford Triton 4.6L, Automatic, Spring Suspension, 3.1 FA, 3.2 RA, 139 WB, Steel Wheels, 235/85R16, AC, Rear Door Won't Open. Showing 177,679 Miles. Location: Corpus Christi, TX Serial: 1FTZX1760WKB85344	
<b>Lot #</b>	142	
<b>Qty</b>	1	
<b>Title</b>	2000 INTERNATIONAL 4700 STRAIGHT TRUCK	
<b>Des.</b>	NON RUNNER. International T444E, Allison Automatic, Spring Suspension, 7 FA, 25 RA, 244 WB, 30.25ft Body, 12.5ft Height, 50 Gallon Steel Fuel Tank, Wet Kit, Steel Wheels, 11R22.5, PTO, Interior Worn, Rust. Showing 159,097 Miles. Location: Wittenberg, WI Serial: 1HTSCABM1YH229325	
<b>Lot #</b>	143	
<b>Qty</b>	1	
<b>Title</b>	2001 INTERNATIONAL 4700 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. NO POWER TO IGNITION. International DT444E, 6 Speed Manual, Spring Suspension, 152 WB, 162in Back Cab To End Frame, Steel Fuel Tank, Steel Wheels, 11R22.5, Rust. Showing 281,966 Miles. Location: Pasadena, TX Serial: 1HTSCABM61H402777	
<b>Lot #</b>	144	
<b>Qty</b>	1	
<b>Title</b>	RAMPS MISC	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. 65in Length, 16in Height, 19in Width, Rust. Location: Des Moines, IA Serial: NA	
<b>Lot #</b>	145	
<b>Qty</b>	1	
<b>Title</b>	2007 INTERNATIONAL 5000i REAR MIXER	
<b>Des.</b>	NON RUNNER. CRANKS NO START. BAD FRAME AND SUSPENSION. DRIVE SHAFT REMOVED. Cummins ISM, Automatic, Hendrickson Suspension, 236 WB, 10.5 Yrd Beck Rear Mixer, Side Mount Water Tank, Aluminum Fuel Tank, Steel Wheels, 425/65R22.5; 11R24.5, PTO, AC, Rust. Mileage Unavailable. Location: San Antonio, TX Serial: 1HTXLAHT17J459586	
<b>Lot #</b>	147	
<b>Qty</b>	1	
<b>Title</b>	1997 FORD F350 SERVICE TRUCK	
<b>Des.</b>	NON RUNNER. Ford Gas, 5 Speed Manual, Spring Suspension, 5 FA, 11 RA, 137 WB, 9ft Vara Service Body, Lift Gate, Champion Compressor - Non Runner, Body Storage, Steel Wheels, 225/75R16, AC, Body Damage/Rust. Mileage Unavailable. Location: San Antonio, TX Serial: 3FELF47GXVMA49885	



---

<b>Lot #</b>	148
<b>Qty</b>	1
<b>Title</b>	HEAVY EQUIP RIPPER ATTACHMENTS
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. 90in Length, 36in Width, Rust. Location: Des Moines, IA Serial: 26V2837

