



## Printable Catalog

<b>Title</b>	JULY 17 12:00 CDT	
<b>Description</b>	Closing Times TBD	
<b>Date</b>	Wed, Jul 17, 2019	
<b>Starts at</b>	12:00 PM	
<b>Address</b>	4747 NE 14th St, Des Moines, IA 50313 USA	
<b>Categories</b>		


---

<b>Lot #</b>	1	
<b>Qty</b>	1	
<b>Title</b>	2004 STERLING LT9500 REAR MIXER	
<b>Des.</b>	UNIT STARTED- DEAD BATTERIES. CAT C9 Diesel, Road Ranger RTO-9 MLL, Hendrickson Haulmax Suspension, 250 WB, 264 Cab To Frame End, 11 YRD. McNeilus Mixer, 150 Gallon Cross Mount Water Tank, Axle Lock, Air Lift Pusher Axle- 255/70R22.5, Bridge Axle, Aluminum Wheels, 425/65R22.5; 11R22.5, AC, Body Damage/Rust. Showing 104,425 Miles; 11,612 Hours. Location: Des Moines, IA Serial: 2FZHAZDA54AN21218	


---

<b>Lot #</b>	2	
<b>Qty</b>	1	
<b>Title</b>	2015 SMITH SX3-42-34 DUMP TRAILER	
<b>Des.</b>	REAR FRAME DAMAGE. AIR BAGS DO NOT HOLD AIR. 3RD AXLE MISSING. 42ft Length, 102in Width, Steel Composition, Lift Cylinder, Steel Wheels, 11R22.5 (Tires Missing), Tarp Missing, Body Damage/Rust. Location: Decatur, GA Serial: 1S9SS4238FL476044	


---








<b>Lot #</b>	3	
<b>Qty</b>	1	
<b>Title</b>	2009 MACK CXU613 DAY CAB TRUCK	
<b>Des.</b>	THIS UNIT RUNS- KNOWN TRANSMISSION ISSUE, DOES MOVE. MP8- 485 HP, Automatic, Air Suspension, 12 FA, 40 RA, 197 WB, Air Slide 5th Wheel, Aluminum Wheels, 11R22.5, 160 Gallon Total Dual Aluminum Fuel Tanks, AC. Showing 739,362 Miles; 20,989 Hours. Location: Des Moines, IA Serial: 1M1AW07Y89N009270	








---







<b>Lot #</b>	5	
<b>Qty</b>	1	
<b>Title</b>	1994 RED RIVER LB237 LIVE FLOOR TRAILER	
<b>Des.</b>	42ft Length, 96in Width, Tarp, Steel Wheels, 11R22.5, Body Damage/Rust. Location: Des Moines, IA Serial: 1R9LB422XR1051103	








---








<b>Lot #</b>	6	
<b>Qty</b>	1	
<b>Title</b>	1994 FORD CF7000 SWEEPER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. UNIT STARTED ON SITE- FULL OPERATIONS NOT TESTED. 5.9L Ford Diesel, Automatic, Spring Suspension, 12 FA, 21 RA, Johnston 605 Series Sweeper Body- Showing 3,887 Hours, Wet Kit, L/R Drive, Wet Kit, Steel Wheels, 11R22.5, PTO, Power Steering, Body Damage/Rust. Showing 27,600 Miles; 6,560 Hours. Location: Ankeny, IA Serial: 1FDXH70CXRVA17877	

<b>Lot #</b>	7	
<b>Qty</b>	1	
<b>Title</b>	2014 INTERNATIONAL WORKSTAR REAR MIXER	
<b>Des.</b>	THIS UNIT RUNS. Naivstar Maxxforce 390, Eaton Ultra Shift Plus, Hendrickson Suspension, 20 FA, 46 RA, 248 WB, 11 YRD Continental Paver Mixer, 150 Gallon Cross Mount Water Tank, Cable Controls, Aluminum/Steel Wheels, AC. Showing 83,016 Miles; 7,984 Hours. Location: Des Moines, IA Serial: 1HTGRSHTXEH485337	
<b>Lot #</b>	8	
<b>Qty</b>	1	
<b>Title</b>	2007 KENWORTH T880 DAY CAB TRUCK	
<b>Des.</b>	UNIT STARTED WHILE ON SITE, NOT ROAD TESTED. KNOWN BRAKE ISSUE. OIL LEAKS NOTED. ECM CONNECTION WAS NOT SECURE. Location: Mokena, IL Serial: 1XKDD09X07J179641	
<b>Lot #</b>	10	
<b>Qty</b>	1	
<b>Title</b>	2004 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	UNIT STARTED, MAJOR ENGINE OIL LEAKS, ENGINE SKIP- NOT ROAD TESTED. AI-300A ASET, Allison 4560P, Hendrickson Suspension, 250 WB, Double Frame, Steel Wheels, 11R22.5, Dual Steel Fuel Tanks, PTO, AC, Check Engine Light Illuminated, R/Door Wont Open, F/Bumper Missing, Body Damage/Rust. Showing 354,144 Miles; 33,702 Hours. Location: Pelham, AL Serial: 1M2AG12C74M011987	
<b>Lot #</b>	11	
<b>Qty</b>	1	
<b>Title</b>	2005 INTERNATIONAL 5600i REAR MIXER	
<b>Des.</b>	UNIT STARTED ON SITE- NOT ROAD TESTED. BELT SQUEAL AT IDLER PULLEY. Cummins ISM 305 HP, Eaton 9LL, Air Ride Suspension, 212 WB, 10.5 YRD. McNeilus Mixer, 150 Gallon Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 136,801 Miles; 15,423 Hours. Location: Wichita Falls, TX Serial: 1HTXHAHT25J178976	
<b>Lot #</b>	13	
<b>Qty</b>	1	
<b>Title</b>	2015 JET SDS453602A35 DUMP TRAILER	
<b>Des.</b>	REAR FRAME AND SUSPENSION DAMAGE, AIR LINES AND SHOCKS BROKEN. 45ft Length, 102in Width, Steel Composition, Lift Cylinder, Steel Wheels, 11R22.5, Body Damage/Rust. Location: Decatur, GA Serial: 5JNSS4739GH000549	
<b>Lot #</b>	14	
<b>Qty</b>	1	
<b>Title</b>	2001 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	UNIT STARTED- NOT ROAD TESTED. E7-350 EUP, RTOF14908LL, Hendrickson Suspension, 20 FA, 255 WB, Steel Wheels, 295/75R22.5; 12R22.5, Steel Fuel tank, PTO, AC, Warning Lights Illuminated, Body Damage/Rust. Showing 419,371 Miles; 21,435 Hours. Location: Des Moines, IA Serial: 1M2P267C31M057231	
<b>Lot #</b>	16	
<b>Qty</b>	1	
<b>Title</b>	1988 MACK R686ST DAY CAB TRUCK	
<b>Des.</b>	UNNIT STARTED ON SITE- NOT ROAD TESTED. EM6-300, TRXL-107 2 Stick, 12FA, 38 RA, 188wb, Camelback Suspension, Spoke Wheels, 11R22.5, Aluminum Headache Rack, AS 5th Wheel, A/C. Showing 143,775 Miles; 1,253 Hours. Location: Des Moines, IA Serial: 1M2N179Y0JW009909	








<b>Lot #</b>	17	
<b>Qty</b>	1	
<b>Title</b>	2012 JOHN DEERE 344J WHEEL LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. UNIT OPERATED WHILE ON SITE. ENGINE HAS LEAK FROM UNKNOWN SOURCE. Location: Henderson, KY Serial: 1LU344JXHZB030286	
<b>Lot #</b>	18	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CT713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. RADIATOR MISSING. AMI-335 ASET, T310MLR 10 Speed, Camelback Suspension, 20 FA, 46 RA, 205 WB, Steel Wheels, AC, Body Damage/Rust. Showing 272,852 Miles; 21,414 Hours. Location: Pelham, AL Serial: 1M2AL02C26M002221	
<b>Lot #</b>	20	
<b>Qty</b>	1	
<b>Title</b>	2015 MACK CXU613 DAY CAB TRUCK	
<b>Des.</b>	MAJOR FRAME AND BODY DAMAGE. ENGINE OIL PAN DAMAGED. NON RUNNER. LESS KEYS. MP7- 395 HP, Automatic, Air Ride Suspension, 12 FA, 40 RA, Air Slide 5th Wheel, Wet Kit, Aluminum Wheels, 11R22.5, Aluminum Fuel Tank, PTO, AC. Mileage Unavailable. Location: Concord, NC Serial: 1M1AW02Y5FM050304	
<b>Lot #</b>	22	
<b>Qty</b>	1	
<b>Title</b>	2009 MACK GU813 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. DASH APART. MP7, Allison Automatic, Camelback Suspension, 18 FA, 46 RA, 255 WB, 234 Cab To Frame End, Double Frame, Steel Wheels, 315/80R22.5, PTO, AC, Body Damage/Rust. Mileage Unavailable. Location: Des Moines, IA Serial: 1M2AX13C89M004410	
<b>Lot #</b>	23	
<b>Qty</b>	1	
<b>Title</b>	2000 MACK RD690S REAR MIXER	
<b>Des.</b>	UNIT STARTED ON SITE- NOT ROAD TESTED. EM7-300 EUP, T2080B, Beam Suspension, 20 FA, 248 WB, 11 Yrd McNeilus Mixer, Cross Mount Water Tank, Bridge Axle, Steel Wheels, 425/65R22.5; 11R22.5, PTO, Dead Batteries, Body Damage/Rust. Showing 224,032 Miles; 18,079 Hours. Location: Wichita Falls, TX Serial: 1M2P264C5YM030207	
<b>Lot #</b>	24	
<b>Qty</b>	1	
<b>Title</b>	1988 MACK R686ST DAY CAB TRUCK	
<b>Des.</b>	UNIT STARTED ON SITE- NOT ROAD TESTED. EM6-300, TRXL-107 2 Stick, 12FA, 38 RA, 188wb, Camelback Suspension, Spoke Wheels, 11R22.5, Aluminum Headache Rack, AS 5th Wheel, A/C. Showing 143,775 Miles; 1,253 Hours. Location: Des Moines, IA Serial: 1M2N179Y0JW009912	
<b>Lot #</b>	28	
<b>Qty</b>	1	
<b>Title</b>	2005 TYMCO DST-6 SWEEPER	
<b>Des.</b>	UNIT STARTED- NOT ROAD TESTED. CAB WOULD NOT TILT. PONY MOTOR RUNS BRIEFLY. MAJOR RUST. Cummins ISB Diesel, Automatic, 146 WB, L/R Steering (R/Accelerator Pedal Removed W/ Unit), John Deere Pony Motor (Leaks Noted, Runs Briefly, Showing 8,016 Hours), Steel Wheels, 11R22.5, AC, Drive Line Removed W/Unit, Dead Batteries, Body Damage. Showing 53,186 Miles. Location: Lakeland, FL Serial: 1FVAB6BV15DV11621	







<b>Lot #</b>	30	
<b>Qty</b>	1	
<b>Title</b>	2005 STERLING ACTERRA CAB & CHASSIS	
<b>Des.</b>	CRANKS- WONT START. CAT C7 Diesel, Automatic, Air Suspension, 12 FA, 46 RA, 195 WB, 180 Cab To Frame End, Steel Wheels, 255/70R22.5; 11R22.5, Steel Fuel Tank, AC, Heated Mirrors, Body Damage/Rust. Mileage Unavailable. Location: Des Moines, IA Serial: 2FZACHDC35AU15505	
<b>Lot #</b>	32	
<b>Qty</b>	1	
<b>Title</b>	1981 MACK R686ST DAY CAB TRUCK	
<b>Des.</b>	UNIT STARTED ON SITE- NOT ROAD TESTED. EM6-300 (ReMack in October 2007), TRXL-107 2 Stick, 12FA, 38 RA, 188wb, Double Frame, Camelback Suspension, Spoke Wheels, 11R22.5, PTO, Wet Kit, Aluminum Headache Rack, AS 5th Wheel, A/C. Showing 32,984 Miles; 122 Hours. Location: Des Moines, IA Serial: 1M2N179Y9BA075115	
<b>Lot #</b>	33	
<b>Qty</b>	1	
<b>Title</b>	1989 GALION 850B MOTOR GRADER	
<b>Des.</b>	UNIT STARTED ON SITE- FULL OPERATIONS NOT TESTED. Komatsu 6 Cylinder Diesel, Powershift 6 Speed Forward/3 Reverse, Cab Heat/AC, Steel Wheels, 14.00R24, Body Damage/Rust. Showing 8,443 Hours. Location: Des Moines, IA Serial: G580061U203607	
<b>Lot #</b>	36	
<b>Qty</b>	1	
<b>Title</b>	1992 MACK CH613 DAY CAB TRUCK	
<b>Des.</b>	TRAILER SOLD SEPARATE. UNIT STARTED ON SITE- NOT ROAD TESTED. HOOD CONDITION- POOR, RUSTED THROUGH IN SEVERAL SPOTS, FALLING APART. EM7-300, T2060, Spring Suspension, 215 WB, Adjustable 5th Wheel, Wet Kit, Steel Wheels, 11R24.5, Aluminum Fuel Tank, PTO, AC, Warning Lights Illuminated, Body Damage/Rust. Showing 390,585 Miles; 4,547 Hours. Location: Des Moines, IA Serial: 1M2AA12Y5NW017709	
<b>Lot #</b>	38	
<b>Qty</b>	1	
<b>Title</b>	2000 FREIGHTLINER FLD112SD CAB & CHASSIS	
<b>Des.</b>	UNIT STARTED ON SITE- NOT ROAD TESTED. CAT C10, Cruise, Allison Automatic, Air Suspension, 18 FA, 26 RA, 176 WB, 143 Cab To Frame End, Steel Wheels, 11R22.5, Steel Fuel Tank, AC, Body Damage/Rust. Showing 231,460 Miles; 307 Hours. Location: Des Moines, IA Serial: 1FUW6ECB9YPF91849	
<b>Lot #</b>	39	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CV713 REAR MIXER	
<b>Des.</b>	UNIT STARTED ON SITE- NOT ROAD TESTED. MIXER REMOVAL AVAILABLE, \$500 THROUGH HOUSBY. AMI-335 ASET, TM308M, Camelback Suspension, 214 WB, McNeilus Rear Mixer, Steel Wheels, 425/65R22.5; 11R24.5, PTO, AC, Body Damage/Rust. Showing 200,009 Miles; 17,776 Hours. Location: Des Moines, IA Serial: 1M2AG11C16M040714	

<b>Lot #</b>	40	
<b>Qty</b>	1	
<b>Title</b>	1999 INTERNATIONAL 9100 DAY CAB TRUCK	
<b>Des.</b>	UNIT STARTED W/ ETHER, SHUT DOWN AND WOULD NOT RESTART. Detroit Series 60- 365 HP (Leak Noted At F/Cover; Pan/Seal), E-Brake, Cruise, Spicer 10 Speed, Air Ride Suspension, 12.35 FA, 40 RA, Air Slide 5th Wheel, Steel Wheels, 11R22.5, Dual Steel Fuel Tanks, Power Steering, AC, AM/FM/CD, Dash Components Missing, Body Damage/Rust. Showing 943,377 Miles; 948,970 ECM; 41,463 Hours. Location: Melvindale, MI Serial: 2HSFRALR3XC075267	
<b>Lot #</b>	42	
<b>Qty</b>	1	
<b>Title</b>	2011 FORD F550 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. ENGINE STARTER MISSING. THROTTLE BODY HOSE MISSING. IGNITION SWITCH APART, WIRES UNDER DASH DISCONNECTED. 6.7L Diesel, Automatic, Spring Suspension, 7 FA, 14.706 RA, 165 WB, Steel Wheels, 225/70R19.5 (Flat), PTO, AC, Body Damage/Rust. Mileage Unavailable. Location: Pelham, AL Serial: 1FDGF5GT6BEA03349	
<b>Lot #</b>	43	
<b>Qty</b>	1	
<b>Title</b>	1998 INTERNATIONAL F5070 REAR MIXER	
<b>Des.</b>	UNIT STARTED ON SITE- NOT ROAD TESTED. Cummins ISM, Eaton 9LL, Hendrickson Suspension, 20 FA, 46 RA, 212 WB, McNeilus Rear Mixer (Tags Missing), Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, Steel Fuel Tank, PTO, AC, Body Damage/Rust. Showing 228,817 Miles; 22,249 Hours. Location: Amarillo, TX Serial: 1HTTGAHT8WJ000542	
<b>Lot #</b>	44	
<b>Qty</b>	1	
<b>Title</b>	2005 PETERBILT 385 DAY CAB TRUCK	
<b>Des.</b>	UNIT STARTED ON SITE- NOT ROAD TESTED. 5TH WHEEL REMOVED. CAT C13, Eaton Fuller 18 Speed, Air Suspension, 12 FA, 40 RA, Aluminum Wheels, 11R22.5, 80 Gallon Aluminum Fuel Tank, PTO, AC, Body Damage/Rust. Showing 460,115 Miles; 1,439 Hours. Location: Sacramento, CA Serial: 1XPGDU9X45D848147	
<b>Lot #</b>	45	
<b>Qty</b>	1	
<b>Title</b>	2011 INTERNATIONAL 7400 GARBAGE PACKER	
<b>Des.</b>	UNIT STARTED W/ JUMP. IHC MaxxForce (SN: 466HM2U3100525) Automatic, Spring Suspension, 10 FA, 23 RA, 217wb, Heil Rear Loader (Missing Tag) Backup Camera, Steel Wheels, 315/80R22.5, AC. Engine Warning Light On. Showing 227,491 Miles; 15,525 Hours. Location: Millsboro, DE Serial: 1HTWCAAN5BJ321226	
<b>Lot #</b>	46	
<b>Qty</b>	1	
<b>Title</b>	1995 INTERNATIONAL 4900 CAB & CHASSIS	
<b>Des.</b>	STARTED W/ JUMP- NOT ROAD TESTED. DT466, Automatic, Beam Suspension, 16 FA, 40 RA, Double Frame, Diff Lock, Steel Wheels, 315/80R22.5, PTO, AC, Body Damage/Rust. Showing 367,843 Miles; 31,281 Hours. Location: Des Moines, IA Serial: 1HTSHAAT2SH636765	
<b>Lot #</b>	48	
<b>Qty</b>	1	
<b>Title</b>	1998 FREIGHTLINER FLD112 DAY CAB TRUCK	
<b>Des.</b>	UNIT STARTED ON SITE- NOT ROAD TESTED. Cummins M11+, Rockwell 10 Speed, Air Ride Suspension, 12 FA, 40 RA, 160in WB, Steel Wheels, 1R22.5, Dual Fuel Tanks, Body Damage/Rust. Showing 750,272 Miles. Location: Buckeye, AZ Serial: 1FUY3MCB4WP899551	








<b>Lot #</b>	49	
<b>Qty</b>	1	
<b>Title</b>	2001 CATERPILLAR 416D BACKHOE	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. UNITS STARTED/OPERATED. CAT Engine, OROPS, Rear Outriggers, 12.5/80-18, 19.5L-24. Hour Meter Very Dim- Best Assessment Shows 1,745 Hours. Location: Odessa, FL Serial: BFP02093	
<b>Lot #</b>	50	
<b>Qty</b>	1	
<b>Title</b>	2002 KENWORTH T800 CAB & CHASSIS	
<b>Des.</b>	UNIT STARTED ON SITE- NOT ROAD TESTED. CAT C15- 490 HP (Oil Leaks Noted), Eaton 8LL, Chalmers Suspension, Double Frame, 20 FA, 40 RA, 261 WCB, Non Steer Pusher Axle, Steel Wheels, 315/80R22.5, Aluminum Fuel Tank, PTO, AC, Body Damage/Rust. Mileage Not Exact- Showing 70,792. Location: Harrisburg, PA Serial: 1NKDXBTX82J889644	
<b>Lot #</b>	51	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CV713 REAR MIXER	
<b>Des.</b>	UNIT STARTED ON SITE W/ JUMP, BAD BATTERIES. MIXER REMOVAL AVAILABLE, \$500 THROUGH HOUSBY. AMI-335 ASET, Cruise, TM308M, Camelback Suspension, 214 WB, Inter-Axle Lock, 10.5 YRD McNeilus Rear Mixer, 150 Gallon Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, AC, Body Damage/Rust. Showing 211,262 Miles; 20,092 Hours. Location: Des Moines, IA Serial: 1M2AG11CX6M040713	
<b>Lot #</b>	52	
<b>Qty</b>	1	
<b>Title</b>	2002 PETERBILT 385 DAY CAB TRUCK	
<b>Des.</b>	UNIT STARTED- NOT ROAD TESTED. CAT C12, 13 Speed Eaton Fuller, Aur Suspension, 12 FA, 40 RA, Aluminum Wheels, 11R22.5, 80 Gallon Aluminum Fuel Tank, PTO, AC, Body Damage/Rust. Showing 592,995 Miles; 9,620 Hours. Location: Sacramento, CA Serial: 1XPGDU9X42D583516	
<b>Lot #</b>	53	
<b>Qty</b>	1	
<b>Title</b>	1995 FRUEHAUF TANKER TRAILER	
<b>Des.</b>	42ft Length, 96in Width, Aluminum Composition, 3 L/Side Drain Valves, Steel Wheels, 11R22.5, Body Damage/Rust. Location: Wichita Falls, TX Serial: 4J8B04227ST012914	
<b>Lot #</b>	54	
<b>Qty</b>	1	
<b>Title</b>	2005 INTERNATIONAL 9200i CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. Cummins ISM, Automatic, Air Suspension, Aluminum Wheels, Body Damage/Rust. Mileage Unavailable. Location: Miami, FL Serial: 3HSCEAHRX5N004103	
<b>Lot #</b>	55	
<b>Qty</b>	1	
<b>Title</b>	2000 INTERNATIONAL F5070 REAR MIXER	
<b>Des.</b>	UNIT STARTED ON SITE- NOT ROAD TESTED. DOES NOT BUILD AIR PRESSURE (AIR TANK PLUG MISSING). DRIVE SHAFT MISSING. Cummins ISM 335 HP, Eaton 9LL, Hendrickson Suspension, 20 FA, 46 RA, 212 WB, 10.5 YRD. McNeilus Mixer, Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5 (R/Front Hub Plug Missing), PTO, Body Damage/Rust. Showing 105,712 Miles; 3,299 Hours. Location: Amarillo, TX Serial: 1HTTGAHT5YJ004468	

















<b>Lot #</b>	58	
<b>Qty</b>	1	
<b>Title</b>	2005 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. AMI-335 ASET, T310M 10 Speed, Camelback Suspension, 265 WB, Double Frame, Pusher Axle, Steel Wheels, Less Batteries, Body Damage/Rust. Mileage Unavailable. Location: Morgantown, WV Serial: 1M2AG11C25M025525	
<b>Lot #</b>	59	
<b>Qty</b>	1	
<b>Title</b>	2005 INTERNATIONAL 5600i REAR MIXER	
<b>Des.</b>	MIXER REMOVAL AVAILABLE, \$500 THROUGH HOUSBY. NON RUNNER. ENGINE PARTIALLY DISASSEMBLED- VALVE COVER LOOSE; AIR CLEANER MISSING. DASH APART- COMPONENTS MISSING. LESS KEYS. Cummins ISM, Cruise, Automatic, Hendrickson Suspension, 20 FA, 46 RA, 212 WB, 232 Cab To Frame End, 10.5 YRD Continental Mixer (Drum Hatch Off), 100 Gallon Side Mount Water Tank, Power Divider Lock, Steel Wheels, 295/75R22.5; 11R24.5, Air Ride Seat, Heated Mirrors, Less Batteries, Body Damage/Rust. Mileage Unavailable. Location: Des Moines, IA Serial: 1HTXHAHT75J128994	
<b>Lot #</b>	61	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK MR688S GARBAGE PACKER	
<b>Des.</b>	THIS UNIT STARTED W/ JUMP & FLUID. MACK AI-350 (SN: 28267YP1) Automatic, Camelback Suspension (SUSPENSION ISSUE- CENTER R/S BROKEN) 46 RA, 214wb, 32 YRD Heil 612-3204 (SN: FP5801544) Rear Loader, Backup Camera, Steel Wheels, 315/80R22.5, 11R22.5. Warning Lights On, Known Problems w/ Trunnion Tube & Rocker. Showing 242,630 Miles. Location: Millsboro, DE Serial: 1M2K189C97M036558	
<b>Lot #</b>	62	
<b>Qty</b>	1	
<b>Title</b>	2001 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	UNIT STARTED ON SITE- BAD TRANSMISSION AND REAR END. E7-350 EUP, T2090, Camelback Suspension, 18 FA, 265 WB, Double Frame, Steel Wheels, 315/80R22.5, PTO, AC, Body Damage/Rust. Showing 145,065 Miles. Location: Summerville, SC Serial: 1M2P267C71M055420	
<b>Lot #</b>	64	
<b>Qty</b>	1	
<b>Title</b>	2009 MACK CHU613 DAY CAB TRUCK	
<b>Des.</b>	UNIT RUNS. Mack MP8 415HP, Maxitorque 10 Speed, Camelback Suspension, 220in WB, 14.32 FA, 38 RA, Dual Aluminum Fuel Tanks, Wet Kit, Manual Fifth Wheel, Dead Batteries, ABS and Check Engine Lights Illuminated, Low Coolant Warning, Body Damage/Rust. Showing 417983 Miles. Location: Houston, TX Serial: 1M1AN09Y39N004638	
<b>Lot #</b>	65	
<b>Qty</b>	1	
<b>Title</b>	2008 CASE 445SSL SKID LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. UNIT OPERATED WHILE ON SITE. ENGINE & UNDERCARRIAGE COVERED IN OIL RESIDUE. Tires in Poor Condition. Location: Henderson, KY Serial: N7M454555	
<b>Lot #</b>	66	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. MISSING: TRANSMISSION, RADIATOR EXPANSION TANK, AIR CHARGE COOLER, TURBO, #1 INJECTOR, VALVE COVERS AND ROCKER ARMS.	


<b>Lot #</b>	67	
<b>Qty</b>	1	
<b>Title</b>	1998 WESTERN STAR 4900 REAR MIXER	
<b>Des.</b>	UNIT STARTED/RAN ON SITE. BAD WATER PUMP. Cummins M11- 330 HP, Eaton 9LL, Bogey Suspension, 20 FA, 46 RA, 252 WB, 11 YRD. Rex 750 Mixer, Side Mount Water Tank, Bridge Axle, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, Aluminum Fuel Tank, PTO, AC, Dead Battery, Body Damage/Rust. Showing 182,658 Miles; 14,473 Hours. Location: Tuttle, OK Serial: 2WLPCDPF1WK950167	
<b>Lot #</b>	68	
<b>Qty</b>	1	
<b>Title</b>	2001 MACK CH613 DAY CAB TRUCK	
<b>Des.</b>	UNIT STARTED ON SITE- NOT ROAD TESTED. E7-427 E-TECH LSR, Fuller RTLO16913A, Air Ride Suspension, 12.86 FA, 38 RA, 218 WB, Air Slide 5th Wheel, Aluminum Wheels, 1R24.5, Dual Aluminum Fuel Tanks, AC, Body Damage/Rust. Showing 77,685 Miles; 34,416 Hours. Location: Amarillo, TX Serial: 1M1AA18Y31W142861	
<b>Lot #</b>	69	
<b>Qty</b>	1	
<b>Title</b>	2004 GMC C7500 KNUCKLEBOOM TRUCK	
<b>Des.</b>	UNIT STARTED ON SITE- NOT ROAD TESTED. 6.6L Duramax, 6 Speed Manual, Spring Suspension, 12 FA, 21 RA, Auto Gru Grapple, F/Outriggers, Aluminum Wheels, 11R22.5, PTO, Pintle Hitch, Dash PCS Missing, Body Damage/Rust. Showing 183,505 Miles. Location: San Bernardino, CA Serial: 1GDM7C13X4F510328	
<b>Lot #</b>	71	
<b>Qty</b>	1	
<b>Title</b>	2004 INTERNATIONAL 5600i REAR MIXER	
<b>Des.</b>	NON RUNNER. MIXER REMOVAL AVAILABLE, \$500 THROUGH HOUSBY. Cummins ISM, Automatic, Hendrickson Suspension, 212 WB, Power Divide Lock, 10.5 YRD McNeilus Mixer, Side Mount Water Tank, Steel Wheels, 425/65R22.5, 11R22.5, PTO, AC, Body Damage/Rust. Mileage Unavailable. Location: Des Moines, IA Serial: 1HTXHAHT45J039528	
<b>Lot #</b>	72	
<b>Qty</b>	1	
<b>Title</b>	1999 MACK CH613 SLEEPER TRUCK	
<b>Des.</b>	UNIT STARTED ON SITE- NOT ROAD TESTED. E7-350 EUP, Fuller RTX13609B, Spring Suspension, 204 WB, 36in Sleeper, Air Slide 5th Wheel, Aluminum Wheels, 11R22.5, Aluminum Fuel Tank, AC, Body Damage/Rust. Showing 258,273 Miles; 41,328 Hours. Location: Amarillo, TX Serial: 1M2AA13Y2XW098802	
<b>Lot #</b>	74	
<b>Qty</b>	1	
<b>Title</b>	2001 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. COOLANT NOT PRESENT IN ENGINE. MISSING COMPONENTS, INCLUDING: RADIATOR EXPANSION TANK, AIR CHARGE COOLER HOSES, KEYS AND HOOD. E7-350 EUP, T2090, Camelback Suspension, 18 FA, 268 WB, Double Frame, Pusher Axle, Steel Wheels, 315/80R22.5, Steel Fuel Tank, PTO, AC, Body Damage/Rust. Showing 560,417 Miles; 2,554 Hours. Location: Harrisburg, PA Serial: 1M2P267C91M061493	





<b>Lot #</b>	75	
<b>Qty</b>	1	
<b>Title</b>	1999 KENWORTH W900 REAR MIXER	
<b>Des.</b>	NON RUNNER. Cummins ISM 305 HP, Eaton Fuller, Chalmers Suspension, 20 FA, 46 RA, 251 WB, 11 YRD. McNeulus Mixer, Cross Mount Water Tank, Bridge Axle, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, Body Damage/Rust. Showing 195,791 Miles; 5,053 Hours. Location: Tuttle, OK Serial: INKWL00X2XR827811	
<b>Lot #</b>	76	
<b>Qty</b>	1	
<b>Title</b>	2000 MACK CH613 DAY CAB TRUCK	
<b>Des.</b>	UNIT STARTED ON SITE- NOT ROAD TESTED. E7-355/380 EUP, Fuller RTAO16710CAS, Air Ride Suspension, 12 FA, 40 RA, 186 WB, Wet Kit, Aluminum Wheels, 11R24.5, Aluminum Fuel Tank, AC, Body Damage/Rust. Showing 329,892 Miles; 40,454 Hours. Location: Amarillo, TX Serial: 1M1AA13Y1YW119578	
<b>Lot #</b>	77	
<b>Qty</b>	1	
<b>Title</b>	1997 MACK CH613 SLEEPER TRUCK	
<b>Des.</b>	TRAILER NOT INCLUDED IN SALE. UNIT STARTED ON SITE- NOT ROAD TESTED. E7-350, Fuller RTX13609B, Air Ride Suspension, 204 WB, 36in Sleeper, Air Slide 5th Wheel, Steel Wheels, 11R22.5, Aluminum Fuel Tank, PTO, AC, Body Damage/Rust. Showing 206,355 Miles; 31,125 Hours. Location: Amarillo, TX Serial: 1M1AA13Y1VW071933	
<b>Lot #</b>	80	
<b>Qty</b>	1	
<b>Title</b>	2001 INTERNATIONAL 9200i DAY CAB TRUCK	
<b>Des.</b>	TRAILER NOT INCLUDED IN SALE. UNIT STARTED ON SITE- NOT ROAD TESTED. Cummins ISM 370 HP, , Eaton 10 Speed, 205 WB, Air Ride Suspension, 205 WB, Air Slide 5th Wheel, Wet Kit, Aluminum Wheels, 11R24.5, Aluminum Fuel Tank, AC, R/Rear Stabilizer Bar Missing, Body Damage/Rust. Showing 89,571 Miles. Location: Amarillo, TX Serial: 2HSCEAHR71C021114	
<b>Lot #</b>	81	
<b>Qty</b>	1	
<b>Title</b>	1999 MUSTANG 2040 SKID LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. NON RUNNER. LESS ATTACHMENT. Yanmar 4TE88-MS- 42 HP Diesel, Automatic, 5,450 Lb Capacity, OROPS, Steel Wheels, 12R16.5, Body Damage/Rust. Hours Unavailable. Location: Des Moines, IA Serial: SJ99A000201	
<b>Lot #</b>	82	
<b>Qty</b>	1	
<b>Title</b>	2004 PETERBILT 357 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. TURBO DISASSEMBLED. LESS BATTERIES AND BATTERY BOX. CAT C10- 305 HP, Manual, Hendrickson Suspension, 22 FA, 46 RA, 219 WB, Aluminum Wheels, 425/6R22.25; 11R22.5 (Rears Singled Out, Flat)Aluminum Fuel Tank, Body Damage/Rust. 221,487 Miles; 3,657 Hours. Location: Houston, TX Serial: 1NPALT0X04D817339	
<b>Lot #</b>	83	
<b>Qty</b>	1	
<b>Title</b>	2007 CHEVROLET C6500 STRAIGHT TRUCK	
<b>Des.</b>	UNIT STARTED- WAS NOT ROAD TESTED. Box Damage Noted, Oil Seepage at Pan & Rear Seal, Transmission Leaks. Location: Des Moines, IA Serial: 1GBJ6C1G97F408153	

<b>Lot #</b>	84	
<b>Qty</b>	1	
<b>Title</b>	2002 MACK CH613 DAY CAB TRUCK	
<b>Des.</b>	NON RUNNER. NO POWER TO CAB. Mack Remanufactured Engine, Maxitorque Transmission, Camelback Suspension, Wet Kit, 12 FA, 197in WB, Dual Aluminum Fuel Tanks, Aluminum Wheels, 11R22.5, AC, Body Damage/Rust. Mileage Unavailable. Location: Houston, TX Serial: 1M1AA14Y52W148359	
<b>Lot #</b>	85	
<b>Qty</b>	1	
<b>Title</b>	2002 INTERNATIONAL 4400 SERVICE TRUCK	
<b>Des.</b>	UNIT STARTED ON SITE- NOT ROAD TESTED. TITLE MARKED AS MILEAGE IN EXCESS OF MECHANICAL LIMITS. DT466 Diesel, Eaton Fuller, 8 FA, 17.5 RA, 194 WB, Rawson Koenig Body (S/N: 102744), Dayton Compressor, Midwestern Manufacturing Crane, Aluminum Wheels, 11R22.5, PTO, AC, Body Damage/Rust. Showing 399,952 Miles. Location: Denver, CO Serial: 1HTMKAAM52H389020	
<b>Lot #</b>	86	
<b>Qty</b>	1	
<b>Title</b>	2004 PETERBILT 357 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. ENGINE LOCKED UP. CAT C10- 335 HP, Automatic, Hendrickson Suspension, 36 RA, 238 WB, Steel Wheels, 425/65R22.5; 11R22.5, AC, Body Damage/Rust. Showing 213,146 Miles; 3,118 Hours. Location: Houston, TX Serial: 1NPALT0X24D828679	
<b>Lot #</b>	90	
<b>Qty</b>	1	
<b>Title</b>	2004 PETERBILT 357 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. ENGINE LOCKED UP. CAT C10- 305 HP, Allison Automatic, Hendrickson Suspension, 22 FA, 46 RA, 220 WB, Steel Wheels, 425/65R22.5; 11R22.5, AC, Body Damage/Rust. Showing 34,943 Miles; 4,874 Hours. Location: Houston, TX Serial: 1NPALT0X84D826838	
<b>Lot #</b>	91	
<b>Qty</b>	1	
<b>Title</b>	1999 INTERNATIONAL 4700 VAC TRUCK	
<b>Des.</b>	NON RUNNER- WOULD NOT RESPOND TO JUMP. ENGINE APPEARS TO BE DRY OF ALL FLUIDS. MISSING DRIVE SHAFT. DASH APART- COMPONENTS MISSING. Location: Elgin, IL Serial: 1HTSCAAN8XH603289	
<b>Lot #</b>	92	
<b>Qty</b>	1	
<b>Title</b>	2000 INTERNATIONAL 9200i DAY CAB TRUCK	
<b>Des.</b>	TRAILER NOT INCLUDED IN SALE. NON RUNNER. FAN BLADES AND BELT BROKEN/MISSING. LESS KEYS. Cummins ISM, Eaton 10 Speed, Air Ride Suspension, 12 FA, 40 RA, 205 WB, Wet Kit, Aluminum/Steel Wheels, 11R24.5 (Hub Cap Missing), Dual Aluminum Fuel Tanks, Rear Stabilizer Bar Missing, Body Damage/Rust. Showing 915,736 Miles. Location: Amarillo, TX Serial: 3HSFMAHR3YN036749	
<b>Lot #</b>	93	
<b>Qty</b>	1	
<b>Title</b>	1996 AMERICAN RDS301 ROLLOFF TRAILER	
<b>Des.</b>	BRAKE AIR LINES ARE BROKEN, BRAKES INOPERABLE. 32ft Length, 96in Width, 30,000 Lb. Capacity, Steel Composition, Steel Wheels, 11R22.5, Body Damage/Rust. Location: Denver, CO Serial: 1A9232585T0074596	

<b>Lot #</b>	94	
<b>Qty</b>	1	
<b>Title</b>	2005 VOLVO VHD CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. BAD ENGINE. TRANSMISSION COMPONENTS MISSING. DASH COMPONENTS MISSING, INCLUDING INSTRUMENT PANEL. Volvo ISL 330 HP, Allison Automatic, T-Ride Suspension, 20 FA, 46 RA, 249 WB, Steel Wheels, Body Damage/Rust. Showing 1,457 Hours. Location: Houston, TX Serial: 4V5KC9LF65N368505	
<b>Lot #</b>	95	
<b>Qty</b>	1	
<b>Title</b>	2001 CHEVROLET 1500 PICKUP TRUCK	
<b>Des.</b>	NON RUNNER. BAD TRANSMISSION. 4.8L V8, Automatic, Spring Suspension, 3.925 FA, 3.75 RA, 133 WB, Steel Wheels, 265/75R16, AC, Body Damage/Rust. Mileage Unavailable. Location: Des Moines, IA Serial: 1GCEK14V61E246714	
<b>Lot #</b>	96	
<b>Qty</b>	1	
<b>Title</b>	2005 FREIGHTLINER M2106 STAKE BODY TRUCK	
<b>Des.</b>	NON RUNNER. RADIATOR MISSING. Mercedes Benz MBE 900 Diesel, Automatic, Spring Suspension, Double Frame, Steel Wheels, 11R22.5, Aluminum Fuel Tank, AC, Body Damage/Rust. Location: Sacramento, CA Serial: 1FVACXCS55HU32422	
<b>Lot #</b>	97	
<b>Qty</b>	1	
<b>Title</b>	2005 HOMEMADE ROLLOFF TRAILER	
<b>Des.</b>	22ft Length, 96in Width, Steel Wheels, 255/70R22.5, Pintle Hitch, Body Damage/Rust. Location: Cedar Rapids, IA Serial: 1G9CD22215S139485	
<b>Lot #</b>	98	
<b>Qty</b>	1	
<b>Title</b>	2005 FORD F350 SERVICE TRUCK	
<b>Des.</b>	NON RUNNER. 5.4L Triton, Automatic, Spring Suspension, 3.95 FA, 9.75 RA, 141 WB, 9ft Stahl Body, Auto Crane- 6,600 Lb. Capacity (Crane- Inoperable), Steel Wheels, 235/85R16, AC, Body Damage/Rust. Mileage Unavailable. Location: Weatherford, TX Serial: 1FDWF36595EB41989	
<b>Lot #</b>	99	
<b>Qty</b>	1	
<b>Title</b>	1997 FORD F250 PICKUP TRUCK	
<b>Des.</b>	NON RUNNER. 7.3L Diesel, Automatic, Spring Suspension, 4.6 FA, 6.084 RA, 133 WB, Steel Wheels, 235/85R16, AC, Body Damage/Rust. Mileage Unavailable. Location: Mayfield, KY Serial: 1FTHF26F2VED05132	
<b>Lot #</b>	100	
<b>Qty</b>	1	
<b>Title</b>	1999 MCCLAIN WALKING FLOOR TRAILER	
<b>Des.</b>	5TH WHEEL KING PIN MISSING. Location: Elgin, IL Serial: 1M9BD4828X2309320	

<b>Lot #</b>	101	
<b>Qty</b>	1	
<b>Title</b>	2001 CHEVROLET 1500 CREW CAB SERVICE TRUCK	
<b>Des.</b>	UNIT STARTED ON SITE- NOT ROAD TESTED. 8.1L V8, Automatic, Spring Suspension, 167 WB, Knapheide Body, Steel Wheels, 215/85R16, AC, PL, Body Damage/Rust. Showing 266,715 Miles. Location: Des Moines, IA Serial: 1GBJC33G21F141998	

<b>Lot #</b>	102	
<b>Qty</b>	1	
<b>Title</b>	1984 CLARK FORKLIFT	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED W/ STARTING FLUID. AIR CLEANER MISSING. 4 Cylinder Gasoline, Automatic, 87in Mast Height, 5in Fork Width, ROPS, Steel Wheels, 7.00R12; 8.25R15, Dead Battery, Body Damage/Rust. Showing 662 Miles. Location: Decatur, GA Serial: C500YS80	

<b>Lot #</b>	103	
<b>Qty</b>	1	
<b>Title</b>	2000 HYSTER H50XM FORKLIFT	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. CRANKS- WONT START. LESS PROPANE TANK. IGNITION DAMAGE, KEY MISSING. GM 4 Cylinder Gasoline, Automatic, 86in Mast Height, 2 Forks- 48in Length (5in Width), ROPS, Steel Wheels, 8.15R15; 6.0R9, Body Damage/Rust. Hours Unavailable. Location: Concord, NC Serial: H177B22172X	