





Printable Catalog


Title	JULY 29 12:00 CDT	
Description	Closing Times TBD	
Date	Wed, Jul 29, 2020	
Starts at	12:00 PM	
Address	4747 NE 14th St, Des Moines, IA 50313 USA	
Categories		







Lot #	2	
Qty	1	
Title	2000 KENWORTH W900 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. CANNOT MOVE - LEAK IN AIR TANK, CANT BUILD AIR PRESSURE OR RELEASE AIR BRAKE. Oil Leaks/Residue - See Report, Missing Right Front And Left Rear Corner Lights, Gauge Blanks Missing At Dash, Rear Drive Axle Has Oil Residue, Tires Worn, Various Body Damage/Rust. Showing 460,843 Miles; 3,998 Hours. Location: Colorado Springs, CO Serial: INKWL00X1YR862423	

Lot #	3	
Qty	1	
Title	2005 MACK CV713 ROLLOFF TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. Mack AMI-370, Maxitorque 8 Speed, Camelback Suspension, 267 WB, Double Frame, Dual Steel 75 Gallon Fuel Tanks, Tarp System, Steel Wheels, 315/80R22.5; 11R22.5, PTO, AC, Hood Doesn't Latch, Hydraulic Leaks, Tarp Arm Bent, Hydraulic Hoses Hang Low Under Truck, Body Damage/Rust. Showing 835,680 Miles; 3,784 Hours. Location: Kansas City, MO Serial: 1M2AG11CX5M032156	








Lot #	4	
Qty	1	
Title	2007 INTERNATIONAL 7400 GARBAGE PACKER	
Des.	STARTED ON SITE - NOT ROAD TESTED. ENGINE SKIP. International DT466E, Automatic, Hendrickson Suspension, 16 FA, 40 RA, 227 WB, 25 Yrd Heil Rear Loader, Two Can Tippers, Steel Wheels, 315/80R22.5, PTO, AC, Backup Camera, Rear Blade Worn Out, Levers To Control Tail Gate Angle Blade Inoperable, Check Engine Light Illuminated, Body Damage/Rust. Showing 215,460 Miles; 27,893 Hours. Approximate Dimensions: 35.5ft Total Length, 11.5ft Height. Location: Wilmington, NC Serial: 1HTWGAZT07J501888	

Lot #	5	
Qty	1	
Title	2009 GREAT DANE SSL-1314-01053 VAN TRAILER	
Des.	53ft Length, 102in Width, Air Ride Suspension, Swing Door, Translucent Roof, Logistic Posts, Wood Floor, Scuff Plate, Threshold Plate, Stainless Steel Rear, Aluminum Wheels, 275/80R22.5, Rust. Location: Ankeny, IA Serial: 1GRAA06209B700912	

Lot #	6	
Qty	1	
Title	2015 GMC SIERRA 3500 PICKUP TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. HEAVY FRONT END DAMAGE FROM COLLISION. GM Duramax 6.6L, Allison Automatic, Spring Suspension, 5.5 FA, 7.05 RA, 168 WB, 8ft Box, Steel Wheels, 265/70R18E, AC, Rust. Showing 117,813 Miles. Location: Commerce City, CO Serial: 1GT421C85FF177989	







Lot #	7	
Qty	1	
Title	2003 OSHKOSH S SERIES FRONT MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Cummins ISM 350, Allison Automatic, Air Ride Suspension, 22 FA, 42 RA, 198 WB, 11 Yrd Oshkosh Front Mixer, 200 Gallon Cross Mount Water Tank, Aluminum Fuel Tank, Two Chutes, Pusher Axle, 34.5ft Total Length, 13ft Height, Aluminum Wheels, 445/65R22.5, Rust. Showing 105,096 Miles; 12,906 Hours. Location: Harrisburg, PA Serial: 10TFAAC233S076312	
Lot #	8	
Qty	1	
Title	2011 DODGE RAM 5500 MECHANICS TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. OUTRIGGERS MISSING. BATTERY TERMINALS CORRODED. Interior Worn, Various Body Damage/Rust. Showing 254,840 Miles. Location: Ostrander, OH Serial: 3D6WA7EL3BG500245	
Lot #	10	
Qty	1	
Title	2014 FREIGHTLINER 114SD DAY CAB TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. Data Port Wiring Faulty - Could Not Obtain Data, Rear Differentials Leaking, Various Body Damage/Rust. Showing 396,160 Miles; 10,286 Hours. Location: Tell City, IN Serial: 3AKJG3DV0EDGA1051	
Lot #	12	
Qty	1	
Title	2007 INTERNATIONAL 7400 VAC TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. International DT466, Allison Automatic, Walking Beam Suspension, 20 FA, 40 RA, 240 WB, Vac-Con Dual Engine Combination Sewer Vacuum, Steel Debris Tank, Poly Water Tanks, Hydraulic Telescoping Boom, Hydraulic Hose Reel With 1in Hose, 3 Stage Fan With Centrifugal Separator, Wireless Remote, Steel Wheels, 425/65R22.5; 11R22.5, AC, Backup Camera, Rear Fender Bent, Check AC Light Illuminated, Rust. Showing 56,454 Miles; 8,752 Hours. Location: Des Moines, IA Serial: 1HTWGAAT97J453271	
Lot #	13	
Qty	1	
Title	2007 VOLVO VHD84 CAB & CHASSIS	
Des.	STARTED ON SITE - NOT ROAD TESTED. Volvo D12 365HP, Eaton 9 Speed LL, Spring Suspension, 20 FA, 46 RA, 250 WB, 259in Back Cab To End Frame, Pusher Axle, Steel Wheels, 425/65R22.5; 11R22.5, AC, Check Engine Light Illuminated, ECU Maintenance Required, Body Damage/Rust. Showing 220,549 Miles. Location: Medina, OH Serial: 4V5K99GF67N481673	
Lot #	14	
Qty	1	
Title	1998 KENWORTH W900 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Oil Leaks/Residue - See Report, Wet Oil Covering Right Side Of Transmission Housing, Oil Leak At Rear Drive Axle, Right Seat Removed, Various Body Damage/Rust. Showing 413,655 Miles; 1,441 Hours. Location: Colorado Springs, CO Serial: 1NKWL90X5WR759460	
Lot #	15	
Qty	1	
Title	2002 FREIGHTLINER FL112 ROLLOFF TRUCK	
Des.	NON RUNNER. FUEL WATER SEPARATOR PARTS MISSING. MISSING ALTERNATOR. BRAKE CHAMBERS CAGED. Cummins ISM, Automatic, Hendrickson Suspension, 2.2 FA, 4.4 RA, 238 WB, 60,000 Lbs G & H Rear Roll Off Body, Steel Wheels, 11R22.5, PTO, AC, Body Damage/Rust. Showing 748,577 Miles; 39,163 Hours. Location: Elgin, IL Serial: 1FVHBGA8X2HK11581	

Lot #	16	
Qty	1	
Title	2003 OSHKOSH S SERIES FRONT MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. ENGINE BLOW BY. BAD ENGINE NOISE. Cummins ISM 350 HP, Automatic, Air Ride Suspension, 22 FA, 42 RA, 197 WB, 11 Yrd Oshkosh Front Mixer, 200 Gallon Cross Mount Water Tank, Pusher Axle, Aluminum Fuel Tank, 34ft Total Length, 13ft Height, Aluminum Wheels, 445/65R22.5, PTO, AC, Check Engine Light Illuminated, No Chutes, Dead Batteries, Rust. Showing 96,089 Miles; 14,147 Hours. Location: Harrisburg, PA Serial: 10TFAAC273S076314	
Lot #	17	
Qty	1	
Title	2006 PETERBILT 357 CAB & CHASSIS	
Des.	STARTED ON SITE - NOT ROAD TESTED. CAT C9, Automatic, Hendrickson Suspension, 22 FA, 44 RA, 218 WB, 214in Back Cab To End Frame, Aluminum Fuel Tank, Aluminum Wheels, 445/65R22.5; 11R22.5, AC, Dead Batteries, Frame Rust. Showing 153,466 Miles; 23,811 Hours. Location: Tampa, FL Serial: 1NPALF0X66N633831	
Lot #	18	
Qty	1	
Title	2009 DODGE RAM 4500 SERVICE TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. Cummins 6.7L Diesel, Automatic, Spring Suspension, 7 FA, 12 RA, 171 WB, 13ft Titan Service Body W/ Liner, SHD-43 American Eagle Air Compressor - Starts And Runs, Body Storage, Steel Wheels, 225/70R19.5, AC, Dead Batteries, Check Engine Light Illuminated, Rust. Showing 228,837 Miles. Location: Columbus, OH Serial: 3D6WC66L29G548171	
Lot #	19	
Qty	1	
Title	2005 INTERNATIONAL 7400 GARBAGE PACKER	
Des.	STARTED ON SITE - NOT ROAD TESTED. BROKEN REAR SUSPENSION. ENGINE RUNS POORLY - ENGINE SKIP, ENGINE WILL NOT REV UP. International DT466E Reman, Automatic, Chalmers Suspension, 16 FA, 40 RA, 228 WB, 25 Yrd McNeilus Rear Loader, Single Can Tipper, Upper Winch, Steel Wheels, 315/80R22.5, PTO, AC, Check Engine Light Illuminated, Dead Batteries, Body Damage/Rust. Showing 366,315 Miles. Approximate Dimensions: 34.5 Total Length, 12ft Height. Location: Douglasville, GA Serial: 1HTWGAAT95J138564	
Lot #	20	
Qty	1	
Title	2008 DRESSA TD-15M DOZER-CRAWLER	
Des.	NO TITLE PER STATE REGULATIONS. NON RUNNER. ELECTRICAL PROBLEMS. BLOWN TRANSMISSION LINE. UNIT HAS BEEN SITTING FOR AN EXTENDED PERIOD. Cummins Diesel, Automatic, Enclosed ROPS, 155in Bucket, Steel Wheels, 156x37, AC/Heated Cab, Body Damage/Rust. Showing 8,920 Hours. Location: Lugoff, SC Serial: 4950014P033542	
Lot #	21	
Qty	1	
Title	2006 VOLVO VHD84 CAB & CHASSIS	
Des.	STARTED ON SITE W/ STARTING FLUID - NOT ROAD TESTED. BROKEN LEFT REAR SPRING. Volvo D12-365, Eaton 9 Speed LL, Spring Suspension, 20 FA, 46 RA, 250 WB, 259in Back Cab To End Frame, 70 Gallon Aluminum Fuel Tank, Pusher Axle, Steel Wheels, 425/65R22.5; 11R22.5, AC, Rust. Showing 89,281 Miles. Location: Medina, OH Serial: 4V5K99GF36N398927	

Lot #	22	
Qty	1	
Title	2012 FORD F250 EXT CAB PICKUP TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. Ford 6.2L Gas, Automatic, Spring Suspension, 4.25 FA, 6.1 RA, 158 WB, 8.25ft Box, Storage Boxes, Steel Wheels, 245/75R17, AC, Dead Batteries, Rust. Showing 141,318 Miles. Location: Columbus, OH Serial: 1FT7X2A69CEB86881	
Lot #	23	
Qty	1	
Title	2006 KENWORTH T800 DAY CAB TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. Tri-Axle, 46,000 Lbs Rear Axles, Oil Leak At Pan/Block/Valve Cover, Radiator Seal Rubber Torn, Rust Damage Near Pusher Axle Mounts, Bolts Missing Out Of Cross Member, Tires Worn, Interior Worn, Various Body Damage/Rust. Showing 556,025 Miles; 20,470 Hours. Location: Waterville, ME Serial: 1XKDPBTX46J157457	
Lot #	24	
Qty	1	
Title	2007 GMC SIERRA 3500 FLATBED TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. GMC Vortec 6.0L, Automatic, Spring Suspension, 4.5 FA, 8.6 RA, 140 WB, 9.5ft Aluminum Flatbed, Aluminum Toolboxes, 6 D-Rings, Headache Rack, Receiver Hitch, Steel Wheels, 215/85R16, AC, Dead Batteries, Rust. Showing 120,359 Miles. Location: Columbus, OH Serial: 1GDJC34KX7E533653	
Lot #	25	
Qty	1	
Title	2009 GREAT DANE CLD131401053 VAN TRAILER	
Des.	53ft Length, 102in Width, Air Ride Suspension, Swing Door, Translucent Roof, Logistic Posts, Wood Floor, Scuff Plate, Threshold Plate, Stainless Steel Rear, Side Skirts, Tire Inflation System, Aluminum Wheels, 445/50R22.5, Rust. Location: Ankeny, IA Serial: 1GRAA06219B705472	
Lot #	26	
Qty	1	
Title	1997 KENWORTH W900 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Oil Leaks/Residue Noted - See Report, AC Not Cold, No VIN Tag Located On Unit, Front Drive Axle Leaks Oil, Various Body Damage/Rust. Showing 443,837 Miles; 9,274 Hours. Location: Colorado Springs, CO Serial: 1NKWL90X4VR743006	
Lot #	27	
Qty	1	
Title	2000 MACK RD688S ROLLOFF TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. MISSING LEFT SIDE STEERING BOX, HOOD, AND BUMPER. Mack E7-350, Eaton 8 Speed LL, Hendrickson Suspension, 266 WB, Rear Roll Off Body, Steel Wheels, 295/75R22.5, PTO, AC, Rear Tires Singled Out, Dash Panels Loose, Body Damage/Rust. Showing 149,006 Miles; 20,923 Hours, Location: Elkhart, IN Serial: 1M2P267C7YM055623	
Lot #	28	
Qty	1	
Title	1999 MACK MR688S GARBAGE PACKER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Mack E7-300, Automatic, Camelback Suspension, 214 WB, Hercules Packer, Steel Spoke Wheels, 385/65R22.5; 11R22.5, PTO, Backup Camera, Several Cracks And Crack Welds Throughout Body, Bent, And Cracked, Less Door Locks, Body Damage/Rust. Showing 582,334 Miles; 37,382 Hours. Location: Street, MD Serial: 1M2K195C3XM014583	








Lot #	29	
Qty	1	
Title	2007 PETERBILT 357 CAB & CHASSIS	
Des.	STARTED ON SITE - NOT ROAD TESTED. ENGINE SKIP. CAT C9, Automatic, Hendrickson Suspension, 20 FA, 44 RA, 218 WB, 206in Back Cab To End Frame, Double Frame, Pusher Axle W/ No Wheels/Tires, Aluminum Fuel Tank, Steel Wheels, 425/65R22.5, AC, Oil Leaks, Check Engine Light Illuminated/Flashing, Seats Torn, Frame Rust. Showing 249,723 Miles; 25,474 Hours. Location: Tampa, FL Serial: INPALFEXX7N677258	
Lot #	30	
Qty	1	
Title	2006 OSHKOSH S2146 FRONT MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. UNIT UNABLE TO BUILD AIR PRESSURE, PRESSURE RELAY SWITCH REMOVED. Tail Lights Removed, Oil Residue Noted - See Report, Concrete Residue Covering Controls, Interior Worn, Various Body Damage/Rust. Showing 262,231 Miles; 26,244 Hours. Location: Colorado Springs, CO Serial: 10TMAAC276S089947	
Lot #	32	
Qty	1	
Title	2000 MACK CX713 VAC TRUCK	
Des.	Mack E7-310/330, Eaton Fuller 10 Speed, Air Ride Suspension, Rear Gate, 4000 Gallon Tank, 2in Jurop Pump. Showing 827,881 Miles; 31,640 Hours. Location: Columbia, MO Serial: 1M1AE06Y5YW004279	
Lot #	33	
Qty	1	
Title	2006 VOLVO VHD84 CAB & CHASSIS	
Des.	STARTED ON SITE - NOT ROAD TESTED. BAD ALTERNATOR. Volvo D12-365, Eaton 9 Speed LL, Spring Suspension, 20 FA, 46 RA, 250 WB, 259in Back Cab To End Frame, 70 Gallon Aluminum Fuel Tank, Pusher Axle, Steel Wheels, 425/65R22.5; 11R22.5, AC, Dead Batteries, ECU Maintenance Required, Rust. Showing 215,136 Miles. Location: Medina, OH Serial: 4V5K99GF66N398937	
Lot #	35	
Qty	1	
Title	2000 WESTERN STAR 4900 DAY CAB TRUCK	
Des.	STARTED ON SITE- NOT ROAD TESTED. CAT 14.6L, Eaton 13 Speed, Air Ride Suspension, 12 FA, 40 RA, 229 WB, Air Slide Fifth Wheel, Dual Aluminum Fuel Tanks, Wet Kit, Aluminum Wheels, 11R22.5, PTO, AC, Rust. Showing 706,610 Miles. Location: Marietta, OH Serial: 2WKEDDCJ8YK961804	
Lot #	36	
Qty	1	
Title	1999 INTERNATIONAL 4700 FLATBED TRUCK	
Des.	NON RUNNER. CRANKS NO START. MISSING FUEL RETURN LINE. International DT466E, Spicer 6 Speed, Spring Suspension, 236 WB, 20ft Steel Body, Sullair 260 Air Compressor - Starts But Does Not Build Air, Headache Rack, Under Storage, Steel Wheels, 11R22.5, AC, Pintle Hitch, Body Damage/Rust. Showing 253,284 Miles. Location: Leander, TX Serial: IHTSCAAP0XH649622	
Lot #	39	
Qty	1	
Title	2000 FREIGHTLINER FL80 ROLLOFF TRUCK	
Des.	NON RUNNER. MISSING: ROLLOFF SYSTEM VALVE, ENGINE HVAC BOX, STARTER, DASH COMPONENTS. HOOD BROKEN. Cummins ISC, Eaton Manual, Chalmers Suspension, 44 RA, Galbreath Rolloff Body, Steel Wheels, 315/80R22.5, Body Damage/Rust. Showing 28,789 Miles; 4,463 Hours. Location: Buckeye, AZ Serial: 1FVXJLCB4YHF82456	


Lot #	40	
Qty	1	
Title	2009 MACK LEU613 GARBAGE PACKER	
Des.	STARTED ON SITE - NOT ROAD TESTED. REGEN PROBLEMS. Mack MP7, Automatic, Camelback Suspension, 18 FA, 46 RA, 193 WB, 40 Yrd E Z Pack Front Loader, L/R Steering, Tag Axle, Steel Wheels, 315/80R22.5, PTO, AC, Backup Camera, Warning Lights Active, Rust. Showing 362,121 Miles; 26,283 Hours. Approximate Dimensions: 33.5ft Total Length, 12.5ft Height. Location: Elizabeth City, NC Serial: 1M2AU02C39M003170	
Lot #	41	
Qty	1	
Title	2006 VOLVO VHD84 CAB & CHASSIS	
Des.	STARTED ON SITE - NOT ROAD TESTED. CLUTCH IS LOCKED UP. Volvo D12 365, Eaton 9 Speed LL, Spring Suspension, 20 FA, 46 RA, 250 WB, 259in Back Cab To End Frame, Aluminum Fuel Tank, Pusher Axle, Steel Wheels, 425/65R22.5; 11R22.5, AC, Dead Batteries, Check Engine Fault, Warning Lights Active, No Passenger Seat, Rust. Showing 228,434 Miles. Location: Medina, OH Serial: 4V5K99GF96N398933	
Lot #	42	
Qty	1	
Title	2015 FORD F250 EXT CAB PICKUP TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. Ford 6.2L Gas, Automatic, Spring Suspension, 4.25 FA, 6.1 RA, 158 WB, 8.25ft Box, Storage Box, Steel Wheels, 245/75R17, AC, Dead Batteries, Rust. Showing 155,363 Miles. Location: Columbus, OH Serial: 1FT7X2A68FEA47457	
Lot #	43	
Qty	1	
Title	2004 OSHKOSH S2146 FRONT MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. ABS Light Illuminated, Lift Cylinders Seeping At Cylinder Seal, Missing Taillights, Front Drive Axle Leaking Oil, Concrete Residue Covering Controls And Surrounding Areas, Interior Worn, Various Body Damage/Rust. Showing 307,661 Miles; 31,914 Hours. Location: Colorado Springs, CO Serial: 10TMAAC264S082498	
Lot #	44	
Qty	1	
Title	2002 INTERNATIONAL 4700 SERVICE TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. SHUTS DOWN ON ENGINE WARNING. International DT466E Diesel, Automatic, Spring Suspension, 188 WB, 14ft Body, Lift Gate, Body Storage, Steel Wheels, 11R22.5, AC, Missing Rear Body Door, Warning Lights Active, Body Damage/Rust. Showing 59,929 Miles; 1,167 Hours. Location: Pelham, AL Serial: 1HTSCAAL42H516545	
Lot #	45	
Qty	1	
Title	2006 PETERBILT 357 CAB & CHASSIS	
Des.	STARTED ON SITE - NOT ROAD TESTED. FRAME CRACKED/RUSTED. CAT C9, Automatic, Hendrickson Suspension, 22 FA, 44 RA, 218 WB, 206in Back Cab To End Frame, Aluminum Fuel Tank, Aluminum Wheels, 445/65R22.5; 11R22.5, AC, Oil Leaks, Frozen Right Door Latch, Rear Tires Singled Out, Rust. Showing 229,724 Miles; 21,852 Hours. Location: Tampa, FL Serial: 1NPALF0X86D633819	




Lot #	48	
Qty	1	
Title	2006 CATERPILLAR 950H WHEEL LOADER	
Des.	NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. BAD CENTER PIVOT PINS. BUCKET CYLINDER LEAKS. LESS KEYS. CAT Diesel, Automatic, Enclosed ROPS, 114x54in Bucket, Steel Wheels, 23.5R25, AC/Heated Cab, Rust. Showing 19,160 Hours. Location: Lugoff, SC Serial: K5K00873	
Lot #	49	
Qty	1	
Title	2009 GREAT DANE SSL-1314-02053 VAN TRAILER	
Des.	53ft Length, 102in Width, Air Ride Suspension, Roll Up Door, Translucent Roof, Logistics Posts, Wood Floor, Scuff Plate, Threshold Plate, Stainless Steel Rear, Aluminum Wheels, 295/75R22.5, Rust. Location: Ankeny, IA Serial:1GRAA06249B700900	
Lot #	50	
Qty	1	
Title	2006 INTERNATIONAL 5600i REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. BAD DRUM - LOTS OF CONCRETE BUILT UP, MISSING MIXER CONTROLS. Cummins ISM, Eaton 8LL, Chalmers Suspension, 222 WB, 11 Yrd McNeilus Rear Mixer, 150 Gallon Side Mount Water Tank, Aluminum Fuel Tank, Two Chutes, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Check Engine Light Illuminated, Dead Batteries, Rust. Showing 242,497 Miles; 23,007 Hours. Location: Byron, GA Serial: 1HTXHAHT06J308187	
Lot #	51	
Qty	1	
Title	2006 MACK CT713 ROLLOFF TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. Mack AMI-370 ASET, Mack T310M, Camelback Suspension, 18 FA, 46 RA, 274 WB, Rear Homemade Roll Off Body, Heil 4 Stage Cylinder, Pusher Axle, Steel Wheels, 315/80R22.5, PTO, AC, Back Up Camera, Body Damage/Rust. Showing 735,991 Miles; 28,793 Hours. Approximate Dimensions: 37.25ft Length, 11.25ft Height. Location: Wilmington, NC Serial: 1M2AL02C76M001260	
Lot #	52	
Qty	1	
Title	1999 FORD F350 GARBAGE PACKER	
Des.	TITLE STATES: TOTAL CLAIM LOSS, SALVAGE REBUILT. CRANKS-WONT START. AXLES REMOVED FROM REAR END. Ford Power Stroke, Automatic, Spring Suspension, 4.85 FA, 8.6 RA, 166 WB, 6 Yrd New Way Rear Loader, Single Can Tipper, Steel Wheels, 235/85R16, PTO, AC, Rust. Showing 194,653 Miles; 3,817 Hours. Location: Greenville, NC Serial: 1FDWF36F9XEB40272	
Lot #	53	
Qty	1	
Title	2016 MACK MRU613 CAB & CHASSIS	
Des.	NON RUNNER. TRUCK FLIPPED IN ACCIDENT. ENGINE BLOCK DAMAGE. BENT FRAME. MISSING SEVERAL COMPONENTS, INCLUDING: FUEL TANK, BODY ECM, DRIVE SHAFT, AND WIPERS. DAMAGE TO CATALYTIC CONVERTER AND MUFFLERS, CAB DOES NOT JACK. BATTERY CABLES CUT. Mack MP7, Automatic, Camelback Suspension, 20 FA, 46 RA, 189 WB, Heil Front Loader, Tag Axle, Steel Wheels, 315/80R22.5, PTO, AC, Missing Door, Body Damage/Rust. Mileage Unavailable. Approximate Dimensions: 28.75ft Total Length, 10.25ft Height. Location: Nashville, TN Serial: 1M2AV04C7GM016124	








Lot #	54	
Qty	1	
Title	2004 OSHKOSH S SERIES 6X6 FRONT MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. PARKING BRAKE VALVE WOULD NOT RELEASE. Oil Leak At Pan/Rear Seal, Headlights Inop., Outer Hub Seal Seeping, Brakes Worn, Interior Worn, Various Body Damage/Rust. Showing 221,356 Miles; 18,036 Hours. Location: Sanbornton, NH Serial: 10TFAWE204S082063	
Lot #	55	
Qty	1	
Title	1998 INTERNATIONAL 4700 SERVICE TRUCK	
Des.	NON RUNNER. COMPONENTS MISSING, INCLUDING: FUEL PUMP AND HOOD. ECU DISCONNECTED. COMPRESSOR NON RUNNING. DT466, 6 Speed Manual, Spring Suspension, 254 WB, Ingersoll Rand Compressor- Showing 10,702 Hours, Steel Wheels, 11R22.5, Dual Steel Fuel Tanks, Body Damage/Rust. Showing 179,549 Miles. Location: Leander, TX Serial: 1HTSCAAL9WH583003	
Lot #	56	
Qty	1	
Title	2016 CHEVROLET SILVERADO 1500 PICKUP TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. POWER STEERING INOPERABLE. Service Power Steering Displayed On Dash, Various Body Damage/Rust. Showing 97,501 Miles. Location: Ostrander, OH Serial: 1GCNCNEC3GZ210708	
Lot #	57	
Qty	1	
Title	2005 PETERBILT 357 CAB & CHASSIS	
Des.	NON RUNNER. BROKEN ENGINE FAN HUB. MISSING BATTERIES. CAT C11, Automatic, Hendrickson Suspension, 22 FA, 46 RA, 220 WB, 206in Back Cab To End Frame, Aluminum Fuel Tank, Aluminum Wheels, 445/65R22.5; 11R22.5, AC, Dash Would Not Power Up, Frame Rust. Showing 224,182 Miles; 5,540 Hours. Location: Tampa, FL Serial: 1NPALT0X95D864791	
Lot #	58	
Qty	1	
Title	1998 GENIE Z-45/25 AERIAL LIFT	
Des.	NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATION NOT TESTED. Steel Wheels, 14-17.5, Rust. Showing 1,296 Hours. Location: Des Moines, IA Serial: Z45-10088	
Lot #	59	
Qty	1	
Title	2003 FREIGHTLINER COLUMBIA DAY CAB TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. ENGINE MISS. Detroit Diesel 500 HP, Eaton Fuller 9 Speed, Air Ride Suspension, 12 FA, 40 RA, 190 WB, Engine Brake, Dual Aluminum Fuel Tanks, Steel Wheels, 11R22.5, AC, Rust. Showing 504,659 Miles; 17,392 Hours. Location: Commerce City, CO Serial: 1FUJA6CG03PK74820	
Lot #	60	
Qty	1	
Title	2008 STERLING L7500 DISTRIBUTOR TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. Mercedes MBE 900, 6 Speed Manual, Spring Suspension, 12 FA, 21 RA, 197 WB, 2,000 Gallon Etnyre Distributor Body, Steel Wheels, 11R22.5, PTO, AC, Dead Batteries, Rust. Showing 7,522 Miles; 504 Hours. Location: Columbus, OH Serial: 2FZAASDJ38AY43788	








Lot #	62	
Qty	1	
Title	2003 MACK CV713 REAR MIXER	
Des.	NON RUNNER. CRANKS - NO START. WIRE HARNESS/ECM PROBLEMS. Mack AMI Diesel, Automatic, Camelback Suspension, 20 FA, 46 RA, 229 WB, 10.5 Yrd McNeilus Rear Mixer, 300 Gallon Cross Mount Water Tank, Aluminum Fuel Tank, Three Chutes, Pusher Axle, 29.5 Total Length, 12.25ft Height, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Dead Batteries, Dash HVAC Apart, Missing Diesel Fuel Tank Cap, Rust. Showing 241,605 Miles; 21,928 Hours. Location: Harrisburg, PA Serial: 1M2AG11C43M004169	
Lot #	63	
Qty	1	
Title	2007 MACK CV713 ROLLOFF TRUCK	
Des.	NON RUNNER. NO TRANSMISSION. Mack AI Diesel, Camelback Suspension, 266 WB, Rear Roll Off Body, Double Frame, Wet Kit, Steel Fuel Tank, Steel Wheels, PTO, AC, Body Damage/Rust. Mileage Unavailable. Location: Summerville, SC Serial: 1M2AG11C17M064397	
Lot #	64	
Qty	1	
Title	2012 FREIGHTLINER M2 106 GARBAGE PACKER	
Des.	CRANKS- WONT START. Cummins ISC, Automatic, Spring Suspension, 16 FA, 40 RA, 246 WB, G S Products Side Loader, L/R Steering, Steel Wheels, 315/80R22.5, PTO, AC, Body Damage/Rust. Showing 256,555 Miles. Location: Hope Mills, NC Serial: 1FVHCYBS1CHBJ9499	
Lot #	65	
Qty	1	
Title	2004 MACK CV713 CAB & CHASSIS	
Des.	STARTED ON SITE W/ ETHER - NOT ROAD TESTED. LOW FUEL. Mack AI-350, 10 Speed Manual, Camelback Suspension, 18 FA, 238 WB, 27ft Length, Double Frame, Wet Kit, Steel Fuel Tank, Steel Wheels, 315/80R22.5, PTO, AC, Rust. Showing 498,290 Miles. Location: Greenville, OH Serial: 1M2AG11C64M010802	
Lot #	66	
Qty	1	
Title	1996 INTERNATIONAL 4700 SERVICE TRUCK	
Des.	NON RUNNER. LESS: FUEL SOLENOID AND HOOD. COMPRESSOR INOPERABLE. International DT466, 6 Speed Manual, Spring Suspension, 254 WB, Steel Wheels, 11R22.5, Dual Steel Fuel Tanks, Body Damage/Rust. Showing 287,004 Miles. Location: Leander, TX Serial: 1HTSCAAL9TH320912	
Lot #	67	
Qty	1	
Title	2009 CIMLINE MATRIX 1500 TAR POT ASPHALT EQUIP	
Des.	NO TITLE PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. Diesel, Steel Wheels, 235/80R16, Rust. Showing 570 Hours. Location: Des Moines, IA Serial:	
Lot #	68	
Qty	1	
Title	2012 FORD F250 EXT CAB PICKUP TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. BAD STEERING. Ford 6.2L Gas, Automatic, Spring Suspension, 4.25 FA, 6.1 RA, 158 WB, 8.25ft Box, Storage Boxes, Steel Wheels, 245/75R17, AC, Dead Batteries, Rust. Showing 137,611 Miles. Location: Columbus, OH Serial: 1FT7X2A60CEB86879	








Lot #	70	
Qty	1	
Title	2003 OSHKOSH S SERIES 6X6 FRONT MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Oil Leak At Pan/Rear Seal, Interior Worn, Body Damage/Rust. Showing 152,303 Miles; 20,964 Hours. Location: Sanbornton, NH Serial: 10TFawe213S076318	
Lot #	71	
Qty	1	
Title	1991 KENWORTH T600 DAY CAB TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. DOES NOT DRIVE - REAR BRAKES LOCKED UP. Oil Leak At Pan/Rear Seal And Right Side Of Block, Tires Worn, Interior Worn, Various Body Damage/Rust. Showing 963,825 Miles. Location: Laporte, CO Serial: 1XKADB9X4MS553558	
Lot #	73	
Qty	1	
Title	2005 GREAT DANE 7411T-SSL101A VAN TRAILER	
Des.	53ft Length, 102in Width, Air Ride Suspension, Swing Door, Translucent Roof, Logistic Posts, Wood Floor, Scuff Plate, Aluminum Wheels, 295/75R22.5, Rust. Location: Ankeny, IA Serial: 1GRAA06235T520750	
Lot #	74	
Qty	1	
Title	1990 KENWORTH W900 REAR MIXER	
Des.	STARTED ON SITE W/ JUMP START - NOT ROAD TESTED. Heavy Oil Residue On Lower Left Side And Bottom Of Engine, Steering Wheel Missing Horn Cap, HVAC Control Head Damaged, Dead Batteries, Left Rear Tire Flat, Interior Worn, Various Body Damage/Rust. Showing 110,968 Miles; 1,612 Hours. Location: Laramie, WY Serial: 1NKWL50X8LS545690	
Lot #	75	
Qty	1	
Title	2002 MACK RD688S ROLLOFF TRUCK	
Des.	NON RUNNER. NO ENGINE. LESS HOOD. Eaton Fuller RTOF14908LL, Camelback Suspension, 266 WB, Double Frame, Steel Fuel Tank, Steel Wheels, PTO, AC, Body Damage/Rust. Mileage Unavailable. Location: Summerville, SC Serial: 1M2P267CX2M063030	
Lot #	76	
Qty	1	
Title	2007 INTERNATIONAL 7400 GARBAGE PACKER	
Des.	NON RUNNER. BROKEN ENGINE FRONT COVER. NO TRANSMISSION COMMUNICATION. International DT466E, Automatic, Hendrickson Suspension, 16 FA, 40 RA, 228 WB, Heil Rear Loader, Dual Can Tippers, Steel Wheels, 315/80R22.5, PTO, AC, Backup Camera, Rust. Showing 268,790 Miles. Approximate Dimensions: 34ft Total Length, 11ft Height. Location: Conway, SC Serial: 1HTWGAZT67J562615	
Lot #	77	
Qty	1	
Title	2005 MACK CV713 CAB & CHASSIS	
Des.	STARTED ON SITE - NOT ROAD TESTED. TRANSMISSION ISSUES - GRINDS AND FALLS OUT OF GEAR. MISSING HEADLIGHTS AND CLEARANCE LIGHTS. Mack AMI-370 Diesel, Eaton Fuller 8 Speed, Spring Suspension, 264 WB, Double Frame, Wet Kit - Pump Only, No Tank, Aluminum Fuel Tank, Steel Wheels, 315/80R22.5, PTO, AC, Rear Tires Singled Out, Missing Some Dash Panels/Controls, Front Service Brake Hose Missing, Body Damage/Rust. Showing 583,842 Miles; 37,887 Hours. Location: Johnston, NY Serial: 1M2AG11C15M020557	








Lot #	78	
Qty	1	
Title	2009 STERLING L7500 DISTRIBUTOR TRUCK	
Des.	STARTED ON SITE, NOT ROAD TESTED. Oil Residue Noted At Engine, Missing Data Plug, Slow Building Air Pressure- Leak Noted Under Hood And Cab, Dash Damage, Hood Damage, Body Damage. Showing 30,107 Miles; 29,002 ECM, 25 Hours. Location: Muskogee, OK Serial: 2FZAASDJ39AAD6364	
Lot #	79	
Qty	1	
Title	2008 FORD F350 SERVICE TRUCK	
Des.	NON RUNNER. Ford 6.4L Diesel, Automatic, Spring Suspension, 4.7 FA, 6.693 RA, 141 WB, SE Inc Utility Body, Steel Wheels, 275/65R18, AC, Body Damage/Rust. Showing 209,849 Miles. Location: San Bernardino, CA Serial: 1FDWFF34R08EC07159	
Lot #	80	
Qty	1	
Title	2010 FORD F150 PICKUP TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. Ford 4.6L Gas, Automatic, Spring Suspension, 3.3 FA, 3.8 RA, 145 WB, 8.25ft Box W/ Liner, Storage Box, Steel Wheels, 235/70R17, AC, Dead Batteries, Column Cover Removed, Rust. Showing 140,984 Miles. Location: Columbus, OH Serial: 1FTMF1CW3AKB46002	
Lot #	81	
Qty	1	
Title	1999 PETERBILT 357 CAB & CHASSIS	
Des.	STARTED ON SITE - NOT ROAD TESTED. BRAKE PEDAL VALVE RUSTED SOLID W/ BRAKES ON - UNIT WILL NOT MOVE. Cummins ISM Diesel, Automatic, Bogey Suspension, 20 FA, 46 RA, 245 WB, 212in Back Cab To End Frame, Aluminum Fuel Tank, Steel Wheels, 425/65R22.5; 11R24.5, PTO, AC, Dead Batteries, Body Damage/Rust. Showing 284,715 Miles; 7,765 Hours. Location: San Antonio, TX Serial: 1NPAL90X6XD486726	
Lot #	82	
Qty	1	
Title	2005 INTERNATIONAL 4300 KNUCKLEBOOM TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. BOOM INOP - BAD HYDRAULIC LEAKS. International DT466E Diesel, Automatic, Spring Suspension, 305 WB, National Crane N50 Knuckleboom, 22ft Flatbed Body, F/Outriggers, Body Storage, Steel Wheels, 315/80R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 449,442 Miles; 25,827 Hours. Approximate Dimensions: 35ft Total Length, 9.5ft Height. Location: Conway, SC Serial: 1HTMMAAN65H105871	
Lot #	83	
Qty	1	
Title	1998 INTERNATIONAL 9200 DAY CAB TRUCK	
Des.	STARTED ON SITE, NOT ROAD TESTED. Detroit Series 60- 365 HP, Eaton Fuller 10 Speed, Air Ride Suspension, 12 FA, 40 RA, 169 WB, Air Slide 5th Wheel, Steel Wheels, 11R22.5, Dual Aluminum Fuel Tanks, AC, Dead Batteries. Showing 306,002 Miles. Location: Elkhart, IN Serial: 2HSFMALR2WC046792	
Lot #	84	
Qty	1	
Title	1995 UNIVERSAL ROLLOFF TRAILER	
Des.	24ft Length, Steel Composition, Spring Suspension, Tarp System, F/R Fenders, Steel Wheels, 255/70R22.5, Pintle Hitch, Front Locking Pin Mechanism Missing, Trap Arms Missing, Body Damage/Heavy Rust. Location: Portland, MI Serial: 2U9D33942S1004083	








Lot #	85	
Qty	1	
Title	1981 GREAT DANE DROP DECK TRAILER	
Des.	40ft Total Length, 30ft Lower Deck, 10ft Upper Deck, 96in Width, Steel Wheels, 275/70R22.5. Location: Lakeland, FL Serial: RDN8426BM030201	
Lot #	86	
Qty	1	
Title	2005 INTERNATIONAL 5500i REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. DRUM THIN. REAR SUSPENSION RUSTED OUT. MISSING BOTH SEATS. Cummins ISM, Eaton 9LL, Hendrickson Suspension, 20 FA, 46 RA, 236 WB, Rear Mixer, Side Mount Water Tank, Aluminum Fuel Tank, Steel Wheels, 11R22.5, PTO, Dead Batteries, Interior/Dash Apart, Body Damage/Rust. Showing 227,271 Miles; 24,473 Hours. Location: Pasadena, TX Serial: 1HTXLAHT05J025284	
Lot #	87	
Qty	1	
Title	2000 MACK RD688S ROLLOFF TRUCK	
Des.	NON RUNNER, STARTED/RAN BRIEFLY ON STARTING FLUID. Mack E7-350, T2090 9 Speed, Camelback Suspension, 18 FA, 46 RA, 267 WB, 60,000 Lbs Galbreath Roll Off Body, Tarp System, Steel Wheels, 315/80R22.5, PTO, AC, Rust. Showing 556,664 Miles; 6,242 Hours. Approximate Dimensions: 34.5ft Total Length, 10.25ft Height. Location: Gray Court, SC Serial: 1M2P267C3YM048961	
Lot #	88	
Qty	1	
Title	2007 FREIGHTLINER M2 106 GARBAGE PACKER	
Des.	NON RUNNER. BAD ENGINE - DOES NOT TURN OVER. DRIVE SHAFT REMOVED WITH TRUCK. Mercedes Benz MBE 900, Automatic, Hendrickson Suspension, 16 FA, 40 RA, 228 WB, 25 Yrd McNeilus Rear Loader, Dual Can Tippers, Steel Wheels, 315/80R22.5, PTO, AC, Warning Lights Active, Body Damage/Rust. Showing 251,831 Miles. Approximate Dimensions: 34.25ft Total Length, 11.5ft Height. Location: Hope Mills, NC Serial: 1FVHCYDJ97HY81258	
Lot #	89	
Qty	1	
Title	2006 MACK CV713 CAB & CHASSIS	
Des.	NON RUNNER. WIRES CUT AT BACK OF MOTOR - SEE PHOTOS. Mack AMI-370, Maxitorque 8 Speed, Spring/Camelback Suspension, 18 FA, 44 RA, Double Frame, Pusher Axle, Dual Steel Fuel Tanks, Steel Wheels, 315/80R22.5, PTO, AC, Driver's Door Sags - Difficult To Close, Driver's Door Missing Exterior Key Lock, Body Damage/Rust. Mileage Unavailable. Location: Portland, MI Serial: 1M2AG11C06M033043	
Lot #	90	
Qty	1	
Title	2009 DODGE RAM 1500 PICKUP TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. Chrysler 4.7L Gas, Automatic, Spring Suspension, 3.7 FA, 3.9 RA, 141 WB, 6ft Box W/ Liner, Aluminum Wheels, 265/70R17, AC, PW, PL, PM, Seat Torn, Rust. Showing 144,953 Miles. Location: Marietta, OH Serial: 1D3HB13P49S752708	
Lot #	91	
Qty	1	
Title	1999 OTTAWA C30 YARD DOG	
Des.	NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. CAT 3126, Automatic, Beam Suspension, 143 WB, Wet Kit, Steel Fuel Tank, Steel Wheels, 11R22.5, PTO, Rust. Showing 17,393 Miles; 1,737 Hours. Location: Tampa, FL Serial: 11VED15A0X000236	








Lot #	93	
Qty	1	
Title	2000 MACK RD688S CAB & CHASSIS	
Des.	STARTED ON SITE W/ A JUMP - NOT ROAD TESTED. Mack E7-350 EUP, T2090 9 Speed, Spring/Camelback Suspension, 16.54 FA, 46 RA, Double Frame, Steel Fuel Tank, Steel Wheels, 315/80R22.5, PTO, Dead Batteries, Cab Door Has Large Crack, Body Damage/Rust. Showing 647,301 Miles. Location: Portland, MI Serial: 1M2P267C9YM050942	
Lot #	94	
Qty	1	
Title	1998 FRUEHAUF DROP DECK TRAILER	
Des.	VIN TAG NOT LOCATED ON UNIT. 48ft Total Length, 37ft Lower Deck, 10ft Upper Deck, 96in Width, Steel Wheels, 215/75R17.5. Location: Lakeland, FL Serial: 1JJF482F2WS451112	
Lot #	95	
Qty	1	
Title	2008 KENWORTH T800 DAY CAB TRUCK	
Des.	NON RUNNER. LESS BATTERIES. AIR INTAKE DISASSEMBLED. FRONT DRIVE BELT DAMAGED. NO COOLANT IN RESERVOIR. DRIVE SHAFT REMOVED. Oil Leaks Noted, Dash Disassembled/Missing Parts, Exhaust Missing Top Stack, Missing Outer Drive Wheels, Missing One Headlight, Tires Worn, Interior Worn, Various Body Damage/Rust. Mileage Unavailable. Location: Dallas, TX Serial: 1XKDD49X98J214184	
Lot #	96	
Qty	1	
Title	1991 MITSUBISHI FUSO PAINT STRIPER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Mitsubishi Diesel, Automatic, Spring Suspension, 4.65 FA, 8 RA, 110 WB, 10.5ft Body, Graco Striper (Cranks, No Start) W/ Kohler Gas Engine, Steel Wheels, 215/85R16, Dead Batteries, Rust. Showing 66,526 Miles. Location: Columbus, OH Serial: JW6ADC1F0ML001456	
Lot #	97	
Qty	1	
Title	1999 GREAT DANE VAN TRAILER	
Des.	53ft Length, 102in Width, Stainless Steel Front, Plywood Lined, Scuff Plate, Translucent Roof, Logistic Posts, Sliding Tandems, Air Ride Suspension, Steel Wheels, 285/75R24.5, Rust. Location: Ankeny, IA Serial: 1GRAA062XXB019802	
Lot #	98	
Qty	1	
Title	2007 KENWORTH T800 REAR MIXER	
Des.	NON RUNNER. BAD ENGINE - PARTED OUT. REAR AXLE MISSING. PARTS IN CAB. Cummins ISL 350 HP, Allison Automatic, Spring Suspension, 20 FA, 46 RA, 229 WB, 10.5 Yrd Beck Rear Mixer, Side Mount Water Tank, Aluminum Fuel Tank, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, Rust. Mileage Unavailable. Location: San Antonio, TX Serial: 1NKDL50X67J207689	
Lot #	100	
Qty	1	
Title	2008 FREIGHTLINER M2 106 GARBAGE PACKER	
Des.	NON RUNNER. CRANKS NO START. Mercedes Benz MBE 900, Automatic, Spring Suspension, 13 FA, 40 RA, 243 WB, 29 YRD. GS Products Side Loader, L/R Side Steering, Steel Wheels, 315/80R22.5, PTO, AC, Missing Body Control Levers, Rust. Showing 193,257 Miles. Approximate Dimensions: 33ft Total Length, 12ft Height. Location: Hope Mills, NC Serial: 1FVHCYDJ98HZ04782	






Lot #	101	
Qty	1	
Title	2006 INTERNATIONAL 5600i CAB & CHASSIS	
Des.	STARTED ON SITE - NOT ROAD TESTED. CAN'T DRIVE - ENGINE HAS NO OIL PRESSURE. UPPER HOPPER UNBOLTED. RED SHUT DOWN LIGHT ILLUMINATED ON DASH. Cummins ISM 350 HP, Eaton 8LL, Chalmers Suspension, 221 WB, Aluminum Fuel Tank, Aluminum/Steel Wheels, 425/65R22.5; 11R2.5, PTO, AC, Check Engine Light Illuminated, Missing Air Charge Cooler Hoses, Missing Left Door Latch, Dead Batteries, Rust. Showing 219,643 Miles; 24,033 Hours. Location: Columbus, GA Serial: 1HTXHAHTX6J308181	
Lot #	102	
Qty	1	
Title	2003 CHEVROLET EXPRESS 2500 AWD VAN	
Des.	STARTED ON SITE - NOT ROAD TESTED. GM Vortec 5.3L Gas, Automatic, Spring Suspension, 3.6 FA, 4.38 RA, 134 WB, Steel Wheels, LT245/75R16, AC, Body Damage/Rust. Showing 55,212 Miles. Location: Des Moines, IA Serial: 1GCFH25T031215510	
Lot #	103	
Qty	1	
Title	1981 GREAT DANE GPD-42 DROP DECK TRAILER	
Des.	45ft Total Length, 34ft Lower Deck, 11ft Upper Deck, 96in Width, 80,000 Lb. Capacity, Spoke Wheels, 10R15, Lock Out On. Location: Lakeland, FL Serial: 1GRDN9020BM009601	
Lot #	104	
Qty	1	
Title	2007 CHEVROLET SILVERADO 2500 PICKUP TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. GM Vortec 6.0L Gas, Automatic, Spring Suspension, 4.2 FA, 6.084 RA, 132 WB, 8.25ft Box, Storage Box, Steel Wheels, 245/75R16, AC, Driver Door Doesn't Open From Inside, Rust. Showing 152,474 Miles. Location: Columbus, OH Serial: 1GCHC24K07E564164	
Lot #	105	
Qty	1	
Title	1999 MACK RD690S CAB & CHASSIS	
Des.	STARTED ON SITE - NOT ROAD TESTED. Mack EM7-300, Eaton 9 Speed LL, Bogey Suspension, 20 FA, 38 RA, 249 WB, 274in Back Cab To End Frame, Aluminum Fuel Tank, Steel Wheels, 425/65R22.5; 11R22.5, AC, Rust. Showing 229,843 Miles; 21,524 Hours. Location: Marietta, OH Serial: 1M2P264C5XM028164	
Lot #	106	
Qty	1	
Title	2005 MANAC 12248102 FLATBED TRAILER	
Des.	48ft Length, 102in Width, Sliding Tandem, Wood Deck, Steel Wheels, 11R24.5, Deck Worn, Rust. Location: Lakeland, FL Serial: 2M512146151102730	
Lot #	110	
Qty	1	
Title	2005 INTERNATIONAL 5500i REAR MIXER	
Des.	NON RUNNER. HARD CRANKS - NO START. MISSING BOTH SEATS. Cummins ISM, Eaton 9LL, Hendrickson Suspension, 236 WB, 10.5 Yrd TMMB Rear Mixer, Aluminum Fuel Tank, Steel Wheels, 11R22.5, PTO, AC, Dash Apart, Body Damage/Rust. Showing 282,762 Miles. Location: Pasadena, TX Serial: 1HTXLAHT15J155106	

Lot #	111	
Qty	1	
Title	1998 GREAT DANE GPD-248 DROP DECK TRAILER	
Des.	48ft Length, 38ft Lower Deck, 10ft Upper Deck, 96in Width, Wood Decking, Steel Wheels, 255/70R22.5, Various Body Damage/Rust. Location: Lakeland, FL Serial: 1GRDM9626WM046202	
Lot #	113	
Qty	1	
Title	2006 STERLING LT9500 CAB & CHASSIS	
Des.	NON RUNNER. HARD CRANKS, NO START. Mercedes OM460, Roadranger 9 Speed LL, Spring Suspension, 217 WB, 202in Back Cab To End Frame, Steel Wheels, 385/65R22.5; 11R22.5, AC, Rust. Mileage Unavailable. Location: San Antonio, TX Serial: 2FZHAZCV56AW99251	
Lot #	114	
Qty	1	
Title	1998 FORD ECOLINE E-250 VAN	
Des.	STARTED ON SITE - NOT ROAD TESTED. Ford Triton Gas, Automatic, Spring Suspension, 3.7 FA, 5.12 RA, 138 WB, Eaglelift Lift Gate, Steel Wheels, LT225/75R16, Body Damage/Rust. Showing 85,808 Miles. Location: Des Moines, IA Serial: 1FTNE24L1WHA13857	
Lot #	115	
Qty	1	
Title	1985 MILLER FLATBED TRAILER	
Des.	42ft Length, 96in Width, Wood Decking, Spoke Wheels, 11R22.5, Body Damage/Rust. Location: Lakeland, FL Serial: 1MLP24225FB923030	
Lot #	116	
Qty	1	
Title	2010 FORD F150 EXT CAB PICKUP TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. BAD BRAKES. Ford 4.6L Gas, Automatic, Spring Suspension, 3.45 FA, 3.8 RA, 145 WB, 6.5ft Box, Steel Wheels, 235/75R17, AC, PW, PL, PM, Rust. Showing 171,350 Miles. Location: Perrysburg, OH Serial: 1FTEX1C88AFB90833	
Lot #	117	
Qty	1	
Title	1996 FORD F450 DUMP TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. ASPHALT STUCK IN DUMP, RUST HOLES THROUGH DUMP. Ford 7.5L V8, 5 Speed Manual, Spring Suspension, 5 FA, 11 RA, 137 WB, 8.5ft Steel Dump Body, Steel Wheels, 235/85R16, PTO, Pintle Hitch, Dead Batteries, Rust. Showing 112,249 Miles. Location: Columbus, OH Serial: 1FDLF47G5TEA63281	
Lot #	118	
Qty	1	
Title	1996 INTERNATIONAL 5000 CAB & CHASSIS	
Des.	STARTED ON SITE - NOT ROAD TESTED. Cummins M11 280 HP, Eaton Fuller, Hendrickson Suspension, 20 FA, 46 RA, 248 WB, 243in Back Cab To End Frame, 80 Gallon Aluminum Fuel Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Bad Batteries, Engine Warning Light Illuminated, Rust. Showing 218,676 Miles. Location: Columbus, OH Serial: 2HTTWAHT5TC064292	

Lot #	119	
Qty	1	
Title	2001 CRONKHITE TANDEM AXLE EQUIPMENT TRAILER	
Des.	SOLD W/ SULLAIR 185 COMPRESSOR (S/N: 004-127119), STARTED ON SITE. SHOWING 495.6 Hours. 20ftx94in Trailer Deminsions, 16ftx75in Inside, Wood Decking, Steel Wheels, 225/75R15, Pintle Hitch. . Location: Des Moines, IA Serial: 47326202111110232 / 004-127119	
Lot #	122	
Qty	1	
Title	2005 ISUZU NQR CONTAINER DELIVERY TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. BRAKE PEDAL TO FLOOR; BAD BRAKE BOOSTER. Isuzu 4 Cyl, Automatic, Spring Suspension, 6.83 FA, 12.98 RA, 110 WB, Steel Wheels, 225/70R19.5, PTO, AC, Brake Warning Light Active, Rust. Showing 278,506 Miles; 3,778 Hours. Approximate Dimensions: 11.5ft Total Length, 7.5ft Height. Location: Fairburn, GA Serial: JALE5B16157900523	
Lot #	123	
Qty	1	
Title	1994 INTERNATIONAL 4900 DUMP TRUCK	
Des.	NON RUNNER. Oil Leaks Noted, Cracked Windshield, Drive Axle Leak, Seepage Noted At Engine, Body Damage. Showing 339,380 Miles. Location: Muskogee, OK Serial: 1HTSDAAN6RH579347	
Lot #	124	
Qty	1	
Title	1989 TRANSCRAFT TL 90K-45 FLATBED TRAILER	
Des.	45ft Length, 96in Width, Sliding Tandem, Wood Decking, Steel Wheels, 11R24.5, Missing One Hook Up, Decking Weathered, Rust. Location: Lakeland, FL Serial: 1TTF45206K1033045	
Lot #	125	
Qty	1	
Title	2011 FORD F250 EXT CAB PICKUP TRUCK	
Des.	NON RUNNER. STARTING SYSTEM FAULT. Ford 6.2L Gas, Automatic, Spring Suspension, 4.25 FA, 6.1 RA, 158 WB, 8ft Box, Storage Boxes, Steel Wheels, 265/70R17, AC, Rust. Showing 185,875 Miles. Location: Columbus, OH Serial: 1FT7X2A65BEA31355	
Lot #	126	
Qty	1	
Title	2007 STERLING ACTERRA CAB & CHASSIS	
Des.	STARTED ON SITE - NOT ROAD TESTED. CAT C7 Diesel, Allison Automatic, Turf Trac Suspension, 12 FA, 34 RA, 229 WB, 181 Back Cab To End Frame, 80 Gallon Aluminum Fuel Tank, Double Frame, Wet Kit, Steel Wheels, 11R22.5, PTO, AC, Rust. Showing 375,063 Miles. Location: Greenville, OH Serial: 2FZHCHDC17AY06704	
Lot #	128	
Qty	1	
Title	2000 G&H 8550 EQUIPMENT TRAILER	
Des.	44.75ft Total Length, 34.75 Body Length, 96in Width, 18 D-Rings, 9 Tie Down Winches; 8 W/ Straps, Steel Wheels, 235/85R16, Pintle Hitch, Tires Dry Rotted, Rust. Location: Elgin, IL Serial: 1G9CT4426YA116001	

Lot #	129	
Qty	1	
Title	2009 DODGE RAM 1500 QUAD CAB PICKUP TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. BAD TRANSMISSION. NO BATTERY. Hemi 5.7L Gas, Automatic, Spring Suspension, 3.7 FA, 3.9 RA, 143 WB, 6.5ft Box, Storage Box, Steel Wheels, 265/70R17, AC, PW, PL, Check Engine Light Illuminated, Rust. Showing 167,132 Miles. Location: Columbus, OH Serial: 1D3HB18T49S800682	
Lot #	132	
Qty	1	
Title	2006 FREIGHTLINER FLD120SD DAY CAB TRUCK	
Des.	NON RUNNER. FUEL FILTER HOUSING CAP MISSING. Mercedes OM460 450HP, Automatic, Hendrickson Suspension, 208 WB, Manual Fifth Wheel, Aluminum Fuel Tank, Wet Kit, Steel Wheels, 11R22.5, PTO, AC, Body Damage/Rust. Showing 313,936 Miles; 10,732 Hours. Location: Elgin, IL Serial: 1FUJALCV86DV62572	
Lot #	133	
Qty	1	
Title	1988 FRUEHAUF FLATBED TRAILER	
Des.	VIN TAG NOT LOCATED ON UNIT. 42ft Length, 96in Width, Steel Wheels, 11R22.5. Location: Lakeland, FL Serial: 1H5P0422XJM081002	
Lot #	134	
Qty	1	
Title	2004 INTERNATIONAL 7400 CAB & CHASSIS	
Des.	NON RUNNER. CRANKS NO START. International DT530, Allison Automatic, 16 FA, 40 RA, 228 WB, Double Frame, Wet Kit, 70 Gallon Steel Fuel Tank, Steel Wheels, 11R22.5, PTO, AC, Interior Worn, Body Damage/Rust. Showing 317,409 Miles; 30,823 Hours. Location: Greenville, OH Serial: 1HTWGADT04J014760	
Lot #	136	
Qty	1	
Title	1997 MACK RD6885 DUMP TRUCK	
Des.	NON RUNNER. E7-350, HD4560P, Camelback Suspension, 18 FA, 210 WB, Steel Wheels, 385/65R22.5; 11R22.5, Steel Fuel Tank, PTO, AC, Body, Driver Seat Missing, Drive Shaft Removed W/ Truck, Damage/Rust. Miles Unavailable. Location: Sacramento, CA Serial: 1M2P267C4VM030500	
Lot #	137	
Qty	1	
Title	2000 CHEVROLET 3500 STAKE BODY TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. GMC Vortec 5.7L, Automatic, Spring Suspension, 162 WB, 12ft Steel Stake Body, 6 D-Rings, Under Storage, Headache Rack, Steel Wheels, 225/75R16, AC, Service Engine Warning, AC Compressor Broken, Seat Torn, Rust. Showing 66,785 Miles. Location: Columbus, OH Serial: 1GBJC34R6YF421742	
Lot #	138	
Qty	1	
Title	2007 MACK CTP713 CAB & CHASSIS	
Des.	NON RUNNER. DASH APART. STEERING NOT HOOKED UP. MISSING TIE RODS AND TIE ROD TUBE. Mack MP7, Automatic, Camelback Suspension, 14.32 FA, 44 RA, 271 WB, 223in Back Cab To End Frame, Double Frame, Dual Aluminum Fuel Tanks, Steel Wheels, 315/80R22.5, Hood Broken - Cannot Stay Open, Body Damage/Rust. Mileage Unavailable. Location: Harrisburg, PA Serial: 1M2AT04C57M004382	

Lot #	139	
Qty	1	
Title	2004 HYSTER H60XM FORKLIFT	
Des.	NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. 4 Cyl Propane, Hydrostatic, ROPS, Two Forks, 28x9-15/7.00; 6.50x10/5.00, Rust. Showing 2,959 Hours. Location: Commerce City, CO Serial: H177B52359B	
Lot #	141	
Qty	1	
Title	1999 FORD F250 PICKUP TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. Ford 7.3L Diesel, Automatic, Spring Suspension, 3.95 FA, 5.246 RA, 137 WB, 8.25ft Box W/ Liner, Steel Fuel Tank, Aluminum Wheels, LT235/85R16, Warning Lights Illuminated, Rust. Showing 222,283 Miles. Location: Harrisburg, PA Serial: 1FTNF20F2XEB61399	
Lot #	142	
Qty	1	
Title	2000 VOLVO WG64 CAB & CHASSIS	
Des.	STARTED ON SITE - NOT ROAD TESTED. Cummins ISM 370, Eaton 8LL, Spring Suspension, 20 FA, 40 RA, 245 WB, 268in Back Cab To End Frame, Double Frame, Steel Fuel Tank, Steel Wheels, 315/80R22.5; 11R22.5, AC, Rust. Showing 53,497 Miles. Location: Columbus, OH Serial: 4V5JC2UF7YN870560	
Lot #	145	
Qty	1	
Title	1999 GMC C7500 STAKE BODY TRUCK	
Des.	NON RUNNER. LESS KEY. DRIVE SHAFT REMOVED WITH TRUCK. CAT 3126, Automatic, Spring Suspension, 11 FA, 19 RA, 18ft Steel Bed, 65in Stake Height, Thieman Lift Gate - Unknown Operational Condition, Steel Fuel Tank, Steel Wheels, 11R22.5; 315/80R22.5, PTO, AC, Hood Cable Stop On Passenger Side Broken, Latch That Secures Lift Gate Broken Off, Body Damage/Rust. Showing 339,087 Miles. Location: Portland, MI Serial: 1GDM7H1C7XJ505375	
Lot #	146	
Qty	1	
Title	2005 VOLVO VHD64B CAB & CHASSIS	
Des.	NON RUNNER. Volvo VE D12 395 HP, RTO-14909LL, Hendrickson Suspension, 20 FA, 44 RA, 248 WB, 230in Back Cab To End Frame, Double Frame, 75 Gallon Aluminum Fuel Tank, Tag Axle, Steel Wheels, 11R22.5, AC, Rust. Mileage Unavailable. Location: Harrisburg, PA Serial: 4V5KC9GG05N389241	
Lot #	147	
Qty	1	
Title	1990 MITSUBISHI FG25 FORKLIFT	
Des.	NO TITLE PER STATE REGULATIONS. NON RUNNER. Mitsubishi, Manual 2 Speed, ROPS, Two Forks, 7.00-12; 6.00-9/4.00, Body Damage/Rust. Hours Unavailable. Location: Sacramento, CA Serial: AF17A50029	
Lot #	148	
Qty	1	
Title	2002 MCCLAIN TT WALKING FLOOR TRAILER	
Des.	NO VIN TAG LOCATED ON UNIT. 48ft Length, 101in Width, Swing Door, Steel Wheels, 11R22.5, Rust. Location: Elgin, IL Serial: 1M9BD482122309023	

Lot #	149	
Qty	1	
Title	2005 CHEVROLET 2500HD EXT CAB 4X4 PICKUP TRUCK	
Des.	NON RUNNER. ENGINE HAS NO OIL PRESSURE. GMC 6.0L Gas, Automatic, Spring Suspension, 4.67 FA, 6.084 RA, 158 WB, 8ft Box W/ Liner, Aluminum Wheels, 265/75R16, AC, PW, PL, PM, Left Rear Door Won't Open, Flat Tires, Broken Tail Gate Handle. TITLE STATES: NOT ACTUAL MILEAGE. Showing 233,601 Miles. Location: Lugoff, SC Serial: 1GCHK29U15E248931	
Lot #	150	
Qty	1	
Title	1995 MACK DM690S CAB & CHASSIS	
Des.	NON RUNNER. CRANKS NO START. MISSING FRONT DRIVE AXLE AND DRIVE SHAFT. Mack EM7-300, Maxitorque 10 Speed, Camelback Suspension, 260 WB, 240in Back Cab To End Frame, Steel Wheels, 315/80R22.5, Rust. Showing 232,540 Miles; 2,521 Hours. Location: Elgin, IL Serial: 1M2B209C9SM017550	
Lot #	151	
Qty	1	
Title	1969 FRUEHAUF 460 CU FT PNEUMATIC TRAILER	
Des.	21ft Total Length, 14ft Trailer Length, 96in Width, Steel Composition, 460 Cu Ft Capacity, Single Compartment, Single Hatch, Three Hook Ups, Steel Wheels, 11R24.5, Heavy Rust. Location: Dallas, TX Serial: FRK351902	
Lot #	152	
Qty	1	
Title	1985 GMC GENERAL WATER TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. Cummins 350 HP, 8 Speed Manual W/ Deep Reduction, Spring Suspension, 12 FA, 38 RA, 204 WB, 5,200 Gallon United Water Tank Body, Steel Wheels, 11R22.5; 12R22.5, PTO, Dead Batteries, Seat Torn, Gauge Missing, Interior Damaged, Body Damage/Rust. Showing 656,795 Miles; 2,504 Hours. Location: Twinsburg, OH Serial: 1GDT9E4CXFV612377	
Lot #	156	
Qty	1	
Title	1990 FORD F250 PICKUP TRUCK	
Des.	STARTED ON SITE W/ A JUMP - NOT ROAD TESTED. Ford 5.8L Gas, Automatic, Spring Suspension, 3.065 FA, 6.084 RA, 133 WB, Steel Wheels, 235/85R16, Needs New Battery, Body Damage/Rust. Showing 60,972 Miles. Location: San Bernardino, CA Serial: 1FTHF25H7LPA58534	