



## Printable Catalog

<b>Title</b>	JULY 31 12:00 CDT	
<b>Description</b>	Closing Times TBD	
<b>Date</b>	Wed, Jul 31, 2019	
<b>Starts at</b>	12:00 PM	
<b>Address</b>	4747 NE 14th St, Des Moines, IA 50313 USA	
<b>Categories</b>		


---

<b>Lot #</b>	2	
<b>Qty</b>	1	
<b>Title</b>	2007 WESTERN STAR 4900 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. Detroit Series 60- 445 HP, Eaton 10 Speed, 12 FA, 40 RA, 218 WB, Air Slide 5th Wheel, Steel Wheels, 11R24.5, 120 Gallon Aluminum Fuel Tank, PTO, Climate Controls Missing, Body Damage/Rust. Showing 191,485 Miles. Location: Brownwood, TX Serial: 5KJJAECG37PX55199	


---

<b>Lot #</b>	4	
<b>Qty</b>	1	
<b>Title</b>	2011 PETERBILT 320 GARBAGE PACKER	
<b>Des.</b>	UNIT STARTED ON SITE- NOT ROAD TESTED. Cummins ISL, Allison Automatic, Spring Suspension, 245 WB, 31 YRD. McNeilus Side Loader, Steel Wheels, 315/80R22.5; 11R22.5, PTO, AC, Rear Camera, Body Damage/Rust. Showing 97,919 Miles. Location: Des Moines, IA Serial: 3BPZL50X2BF127426	


---

<b>Lot #</b>	5	
<b>Qty</b>	1	
<b>Title</b>	2000 VANTAGE DUMP TRAILER	
<b>Des.</b>	37ft Length, 102in Width, Aluminum Composition, Tarp System, Lift Cylinder, Steel Wheels, 1R24.5, Body Damage/Rust. Location: Stephenville, TX Serial: 4EPAA3720YAVA3126	


---







<b>Lot #</b>	7	
<b>Qty</b>	1	
<b>Title</b>	2004 MACK CX613 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. AC-427 ASET, Fuller FRO15210C, Air Ride Suspension, 12 FA, 40 RA, 176 WB, Wet Kit, Manual 5th Wheel, Aluminum Wheels, 11R22.5, 1260 Gallon Total Dual Aluminum Fuel Tanks, PTO, AC, Instrument Panel Inop., Body Damage/Rust. Showing 417,951 Miles; 21,301 Hours. Location: Abilene, TX Serial: 1M1AE06YX4N015892	








---

<b>Lot #</b>	8	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CV713 6X6 REAR MIXER	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. ENGINE BLOW BY. AMI-335, Eaton 9LL, Hendrickson Suspension, 18 FA, 46 RA, 236 WB, 10 YRD. MTM Bridgemaster Mixer, 125 Gallon Side Mount Water Tank, Bridge Axle, Steel Wheels, 385/65R22.5; 1R22.5, PTO, Body Damage/Rust. Showing 190,403 Miles; 18,588 Hours. Location: Algonquin, IL Serial: 1M2AG11C56M031806	








---





<b>Lot #</b>	10	
<b>Qty</b>	1	
<b>Title</b>	1991 VOLVO L90 WHEEL LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATION. UNIT OPERATED WHILE ON SITE. Oil & Hydraulic Leaks Noted. Location: Goshen, IN Serial: L90V/60888	

<b>Lot #</b>	12	
<b>Qty</b>	1	
<b>Title</b>	2001 INTERNATIONAL 4700 DUMP TRUCK	
<b>Des.</b>	UNIT STARTED ON SITE- NOT ROAD TESTED. Navistar T444, Automatic, Spring Suspension, 16 FA, 22 RA, 174 WB, Steel Dump Body, Front Mount Plow (In Body), Steel Wheels, 315/80R22.5; 11R22.5, PTO, Body Damage/Rust. Showing 86,780 Miles; 11,064 Hours. Location: Des Moines, IA Serial: 1HTSCABR31H400254	
<b>Lot #</b>	13	
<b>Qty</b>	1	
<b>Title</b>	1998 MACK RD690S CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. ENGINE BLOW BY. PTO SHAFT HOOKED TO HYDRAULIC PUMP. EM7-300, T2070, Walking Beam Suspension, 20 FA, 38 RA, 250 WB, Steel Disc Wheels, 425/65R22.5; 11R22.5, Aluminum Fuel Tank, PTO, AC Inop., Body Damage/Rust. Showing 193,719 Miles; 3,124 Hours. Location: Omaha, NE Serial: 1M2P264C8WM026407	
<b>Lot #</b>	14	
<b>Qty</b>	1	
<b>Title</b>	1994 FORD 5030 AG TRACTOR	
<b>Des.</b>	UNIT STARTED ON SITE. Ford D2454C Diesel (S/N: 389188 3B08), Steel Wheels, 16.9R24; TF9090. Showing 2,554 Hours. Location: Des Moines, IA Serial: BD39855	
<b>Lot #</b>	15	
<b>Qty</b>	1	
<b>Title</b>	2003 MACK CH613 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. AUDIBLE ALARM. EXHAUST AND TRANS TEMP GAUGES INOPERABLE. ENGINE BLOW BY SEEPING FROM LOWER MANIFOLD BOLTS. REAR WINDOW SHATTERED. E7-427, Eaton 13 Speed, Air Ride Suspension, 12 FA, 38 RA, 213 WB, Wet Kit, Air Slide 5th Wheel, Aluminum/Steel Wheels, 1R24.5, Dual Aluminum Fuel Tanks, PTO, AC, Warning Lights Illuminated, Body Damage/Rust. Showing 439,038 Miles; 14,437 Hours. Location: Brownwood, TX Serial: 1M1AA18Y93W150319	
<b>Lot #</b>	16	
<b>Qty</b>	1	
<b>Title</b>	2000 MACK RD690S REAR MIXER	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. AUDIBLE ELECTRONIC MALFUNCTION ALARM. EM7-300 EUP, T2070, Beam Suspension, 20 FA, 46 RA, 229 WB, 10.5 YRD. McNeilus Mixer, Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Warning Lights Illuminated, Body Damage/Rust. Showing 161,428 Miles; 21,274 Hours. Location: Abilene, TX Serial: 1M2P264C3YM031467	
<b>Lot #</b>	18	
<b>Qty</b>	1	
<b>Title</b>	2011 PETERBILT 320 GARBAGE PACKER	
<b>Des.</b>	UNIT STARTED ON SITE- NOT ROAD TESTED. Cummins ISL Diesel, Allison Automatic, Spring Suspension, 245 WB, 31 YRD. McNeilus Side Loader, Steel Wheels, 315/80R22.5, 11R22.5, PTO, AC, Rear Camera, Body Damage/Rust. Showing 105,470 Miles. Location: Des Moines, IA Serial: 3BPZL50X4BF127427	

<b>Lot #</b>	19	
<b>Qty</b>	1	
<b>Title</b>	2003 MACK RD688S DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. ELECTRONIC MALFUNCTION LIGHT ILLUMINATED. E7-350, Eaton 8LL, Camelback Suspension, 251 WB, 225 Cab To Frame End, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, Alum/Steel Fuel Tanks, AC, Body Damage/Rust. Showing 242,161 Miles; 19,521 Hours. Location: San Antonio, TX Serial: 1M2P267C03M065306	
<b>Lot #</b>	20	
<b>Qty</b>	1	
<b>Title</b>	2005 MACK CV713 6X6 REAR MIXER	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. AMI-335 ASET, Eaton Fuller 9LL, Hendrickson Suspension, 18.74 FA, 46 RA, 236 WB, Rear Canadian Spread Axle, 10 YRD MTM Bridgmaster Mixer (Discharge Hopper Missing), 125 Gallon Cross Mount Water Tank, Steel Wheels, 385/65R22.5; 11R22.5, Aluminum Fuel Tank, PTO, Body Damage/Rust. Showing 166,899 Miles; 19,789 Hours. Location: Algonquin, IL Serial: 1M2AG11C75M017551	
<b>Lot #</b>	21	
<b>Qty</b>	1	
<b>Title</b>	1998 MACK RD690S CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. DOES NOT BUILD AIR. PTO SHAT HOOKED TO HYDRAULIC PUMP. EM7-300, T2080B, Walking Beam Suspension, 20 FA, 38 RA, 250 WB, Steel Disc Wheels, 425/65R22.5; 11R22.5, Aluminum Fuel Tank, PTO, AC, Body Damage/Rust. Showing 162,807 Miles; 21,212 Hours. Location: Omaha, NE Serial: 1M2P264C7WM026401	
<b>Lot #</b>	23	
<b>Qty</b>	1	
<b>Title</b>	2009 JOHN DEERE 225D EXCAVATOR	
<b>Des.</b>	NO TITLE PER STATE REGULATION. UNIT STARTED WHILE ON SITE. LIMITED ACCESS TO ENGINE BAY. Location: Grand Junction, CO Serial: FF225DX501005	
<b>Lot #</b>	24	
<b>Qty</b>	1	
<b>Title</b>	2001 VANTAGE DUMP TRAILER	
<b>Des.</b>	37ft Length, 102in Width, Lift Cylinder, Tarp System, Aluminum Composition, Aluminum Wheels, 11r22.5, Body Damage/Rust. Location: Stephenville, TX Serial: 4EPAA37261AVA3976	
<b>Lot #</b>	25	
<b>Qty</b>	1	
<b>Title</b>	2018 FREIGHTLINER M2 CAB & CHASSIS	
<b>Des.</b>	SIGNIFICANT ROLL OVER DAMAGE. Location: Byram, MS Serial: 1FVACVFD6JHJP7467	
<b>Lot #</b>	26	
<b>Qty</b>	1	
<b>Title</b>	2003 MCCLAIN WALKING FLOOR TRAILER	
<b>Des.</b>	48ft Length, 102in Width, Steel Wheels, 425/65R22.5; 11R22.5, Body Damage/Rust. Location: Wittenberg, WI Serial: 1M9CD483832309051	








<b>Lot #</b>	27	
<b>Qty</b>	1	
<b>Title</b>	1994 MACK CH613 DAY CAB TRUCK	
<b>Des.</b>	UNIT STARTED- WAS NOT ROAD TESTED. Multiple Oil Leaks, Transmission Covered in Oil- Could Not Locate Source. Showing 49,729 Miles; Location States Odometer has Rolled Over. Location: Berlin, WI Serial: 1M1AA13Y4RW036261	
<b>Lot #</b>	28	
<b>Qty</b>	1	
<b>Title</b>	2003 INTERNATIONAL 5600i REAR MIXER	
<b>Des.</b>	UNIT STARTED ON SITE- NOT ROAD TESTED. Cummins ISM 320V, Eaton 9LL Speed, Chalmers Suspension, 212 WB, Rear Mixer (Info Tag Missing), Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5 (F/Axle Seal Leak), PTO, AC, Dead Batteries, Body Damage/Rust. Showing 272,806 Miles; 26,833 Hours. Location: Granbury, TX Serial: 1HTXHAHT83J068768	
<b>Lot #</b>	29	
<b>Qty</b>	1	
<b>Title</b>	1998 MACK RD690S CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. ENGINE BLOW BY. PTO SHAFT HOOKED TO HYDRAULIC PUMP. AIR LEAK. EM7-275, T2070, Walking Beam Suspension, 248 WB, Aluminum/Spoke Wheels, 425/65R22.5; 11R22.5, Aluminum Fuel Tank, PTO, AC, Body Damage/Rust. Showing 176,854 Miles; 22,242 Hours. Location: Omaha, NE Serial: 1M2P289C1WM025054	
<b>Lot #</b>	30	
<b>Qty</b>	1	
<b>Title</b>	2007 INTERNATIONAL 4300 FLATBED TRUCK	
<b>Des.</b>	UNIT STARTED ON SITE- NOT ROAD TESTED. DT466- 220 HP , Automatic, Spring Suspension, 220 WB, 19ft Body, 9 D-Rings, Aluminum/Steel Wheels, 11R22.5, Dual Steel Fuel Tanks, AC, Body Damage/Rust. Showing 292,795 Miles; 12,295 Hours. Location: Dallas, TX Serial: 1HTMMAAL67H438685	
<b>Lot #</b>	31	
<b>Qty</b>	1	
<b>Title</b>	2000 KENWORTH T800 DAY CAB TRUCK	
<b>Des.</b>	UNIT STARTED ON SITE- NOT ROAD TESTED. BRAKE CHAMBERS LOCKED UP- DOES NOT MOVE. CAT C10- 276 HP, Eaton 8LL, Chalmers Suspension, 56 FA, 40 RA, 226 WB, 234 Cab To Frame End, Aluminum Wheels, 425/65R22.5; 11R22.5, 75 Gallon Aluminum Fuel Tank, Dead Batteries, Body Damage/Rust. Showing 214,489 Miles; 2,664 Hours. Location: Dallas, TX Serial: 1NKDLT0X8YR853615	
<b>Lot #</b>	32	
<b>Qty</b>	1	
<b>Title</b>	2005 MACK CV713 6X6 REAR MIXER	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. ENGINE BLOW BY. AMI-335, Eaton 8LL, Chalmers Suspension, 18.74 FA, 46 RA, 236 WB, 10 YRD. MTM Bridgmaster Mixer, 125 Gallon Crossmount Water Tank, Steel Wheels, 385/65R22.5; 11R22.5, PTO, Body Damage/Rust. Showing 230,929 Miles; 23,059 Hours. Location: Algonquin, IL Serial: 1M2AG11C45M018480	
<b>Lot #</b>	33	
<b>Qty</b>	1	
<b>Title</b>	2007 STERLING LT9500 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE W/ STARTING FLUID AND JUMP- NOT ROAD TESTED. CHECK ENGINE AND ENGINE PROTECT LIGHTS ILLUMINATED. REAR AXLE MISSING. CAT C11- 335 HP, Roadranger 9LL, Spring Suspension, 217 WB, Steel Wheels, 385/65R22.5; 11R22.5, Aluminum Fuel Tank, AC, Body Damage/Rust. Showing 161,356 Miles; 19,941 Hours. Location: San Antonio, TX Serial: 2FZHAZDL17AX82268	

<b>Lot #</b>	34	
<b>Qty</b>	1	
<b>Title</b>	2007 STERLING ACTERRA GARBAGE PACKER	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. CAT C7, Automatic, Spring Suspension, 10 FA, 23 RA, 208 WB, 20 YRD. Heil Rear Loader, Single Can Tipper, Steel Wheels, 11R22.5, PTO, AC, Dash Held W/ Duct Tape, Body Damage/Rust. Showing 274,634 Miles. Location: Newport, NC Serial: 2FZACGDC67AY63797	
<b>Lot #</b>	35	
<b>Qty</b>	1	
<b>Title</b>	1999 CATERPILLAR 950G WHEEL LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATION. UNIT STARTED WHILE ON SITE. TIRES IN POOR CONDITION. Location: Grand Junction, CO Serial: 3JW00742	
<b>Lot #</b>	36	
<b>Qty</b>	1	
<b>Title</b>	1997 TRAVIS DUMP TRAILER	
<b>Des.</b>	38ft Length, 102in Width, Lift Cylinder, Tarp System, Aluminum Composition, Steel Wheels, 11R24.5, Body Damage/Rust. Location: Stephenville, TX Serial: 1T91F3825V1247391	
<b>Lot #</b>	37	
<b>Qty</b>	1	
<b>Title</b>	1998 MACK RD690S CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. AIR LEAK, DOES NOT BUILD AIR PRESSURE- BROKEN AIR FITTING AT TANK. PTO SHAFT HOOKED TO HYDRAULIC PUMP. EM7-275, T2070, Walking Beam Suspension, 20 FA, 38 RA. 248 WB, Aluminum/Spoke Wheels, 425/65R22.5; 11R22.5, Aluminum Fuel Tank, PTO, AC, Body Damage/Rust. Showing 169,868 Miles; 26,280 Hours. Location: Omaha, NE Serial: 1M2P289CXWM025053	
<b>Lot #</b>	38	
<b>Qty</b>	1	
<b>Title</b>	2009 MACK MRU613 GARBAGE PACKER	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. KNOWN REGEN ISSUE. MP7, Allison 4500RDS, Camelback Suspension, 18 FA, 46 RA, 189 WB, 40 YRD. EZ Pack Front Loader, Steel Wheels, Non Steer Tag Axle, 315/8R22.5 (L/Front Flat), Check Engine Light Illuminated, Body Damage/Rust. Showing 387,117 Miles; 17,141 Hours. Location: Elizabeth City, NC Serial: 1M2AV02C99M003395	
<b>Lot #</b>	39	
<b>Qty</b>	1	
<b>Title</b>	2001 INTERNATIONAL 9100i DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. BELT SQUEAL NOTED. Cummins N14, Eaton 10 Speed, Air Ride Suspension, 177 WB, Air Slide 5th Wheel, Wet Kit, Aluminum/Steel Wheels, 11R24.5, Dual Aluminum Fuel Tanks, PTO, AC, Body Damage/Rust. Showing 632,553 Miles. Location: Austin, TX Serial: 1HSCBAER71J021208	
<b>Lot #</b>	40	
<b>Qty</b>	1	
<b>Title</b>	2000 WESTERN STAR REAR MIXER	
<b>Des.</b>	UNIT STARTED ON SITE- NOT ROAD TESTED. OIL SEEPAGE NOTED AT FRONT HEAD GASKET. Cummins ISM 305V, Eaton 9LL Speed, Chalmers Suspension, 20 FA, 46 RA, 222 WB, 10.5 YRD. London Mixer, Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, Body Damage/Rust. Showing 234,407 Miles. Location: Brownwood, TX Serial: 2WLNCDPE7YK959876	







<b>Lot #</b>	41	
<b>Qty</b>	1	
<b>Title</b>	2005 VOLVO VHD64B REAR MIXER	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. DRUM DOES NOT SPIN. BAD CLUTCH SLAVE CYLINDER NOTED. MAJOR ENGINE BLOW BY. MAJOR ENGINE OIL LEAKS. SHIFTER WORN. VE D12- 365 HP, RTO-14909ALL 11 Speed, T-Ride Suspension, 20 FA, 46 RA, 215 WB, McNeilus Rear Mixer (Tag Missing), 125 Gallon Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, Aluminum Fuel Tank, PTO, AC, Warning Lights Illuminated, R/Door Wont Open, Cracked Windshield, Body Damage/Rust. Showing 194,867 Miles. Location: Harrisburg, PA Serial: 4V5KC9GF65N390823	
<b>Lot #</b>	44	
<b>Qty</b>	1	
<b>Title</b>	2007 INTERNATIONAL 5600i REAR MIXER	
<b>Des.</b>	NON RUNNER. ENGINE DISASSEMBLED. Cummins ISM, Eaton 8LL, Chalmers Suspension, 20 FA, 46 RA, 224 WB, 11 YRD. McNeilus Mixer, 125 Gallon Side Mount Water Tank, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, Aluminum Fuel Tank, PTO, AC, Dash Inop, Body Damage/Rust. Showing 23,384 Hours; Mileage Unavailable. Location: Duluth, GA Serial: 1HTXHAHT17J526608	
<b>Lot #</b>	45	
<b>Qty</b>	1	
<b>Title</b>	1998 MACK RD690S CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. ENGINE BLOW BY. AIR LEAK. BRAKES WONT RELEASE. EM7-275, T2070, Walking Beam Suspension, 30 FA, 38 RA, 248 WB, Aluminum/Spoke Wheels, 425/65R22.5; 11R22.5, Aluminum Fuel Tank, PTO, AC, Body Damage/Rust. Showing 156,377 Miles; 24,049 Hours. Location: Omaha, NE Serial: 1M2P289C6WM025051	
<b>Lot #</b>	46	
<b>Qty</b>	1	
<b>Title</b>	1993 PEERLESS TRL WALKING FLOOR TRAILER	
<b>Des.</b>	NO TRACTOR ON SITE TO TEST FUNCTIONALITY. BODY DAMAGE, HYD LEAK. Location: Watts, OK Serial: 1PLE04223PPB12873	
<b>Lot #</b>	47	
<b>Qty</b>	1	
<b>Title</b>	2008 CATERPILLAR AP655D PAVER	
<b>Des.</b>	NO TITLE PER STATE REGULATION. UNIT STARTED W/ JUMP WHILE ON SITE. Known Issues w/ Floor, Slats, Screed Bottom, & Bearings. Location: Grand Junction, CO Serial: GNZ00256	
<b>Lot #</b>	48	
<b>Qty</b>	1	
<b>Title</b>	2011 CHEVROLET SILVERADO 2500 4X4 PICKUP TRUCK	
<b>Des.</b>	UNIT STARTED ON SITE- NOT ROAD TESTED. RUNS ROUGH. 6.0L Gas, Automatic, Spring Suspension, 4.4 FA, 6.2 RA, 136 WB, 8ft Box, Reading Topper, Diesel Transfer Tank, Steel Wheels, 265/70R17, AC, Dead Battery, L/Door Handle Missing, Body Damage/Rust. Showing 64,800 Miles. Location: Concord, NC Serial: 1GC0KVC7BF178262	
<b>Lot #</b>	49	
<b>Qty</b>	1	
<b>Title</b>	2004 INTERNATIONAL 7600 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. DOG HOUSE MISSING. Cummins ISM, Eaton Fuller Manual, Hendrickson Suspension, 18 FA, 40 RA, 217 WB, 207 Cab To Frame End, Steel Wheels, 385/65R22.5; 11R22.5 (R/Front Flat), PTO, Body Damage/Rust. Showing 398,298 Miles; 31,212 Hours. Location: Leander, TX Serial: 1HTWYAHT04J093757	

















<b>Lot #</b>	50	
<b>Qty</b>	1	
<b>Title</b>	1997 VOLVO WG64 ROLLOFF TRUCK	
<b>Des.</b>	CRANKS- WONT START. FAN HUB BELT MISSING. Cummins M11- 280 HP, Fuller RTO11908LL, Hendrickson Suspension, 18 FA, 40 RA, 155 WB, 60,000 Lb. Capacity Body, Non Steer Pusher Axle, Spoke Wheels, 315/80R22.5, PTO, AC, Body Damage/Rust. Showing 182,617 Miles. Location: Concord, NC Serial: 4VHJCAPE5VR855768	
<b>Lot #</b>	51	
<b>Qty</b>	1	
<b>Title</b>	2010 FREIGHTLINER CASCADIA 125 DAY CAB TRUCK	
<b>Des.</b>	NON RUNNER- ENGINE BLOWN. DRIVE SHAFT MISSING. Detroit DD15 Diesel, Eaton 10 Speed, Air Ride Suspension, Air Slide 5th Wheels, Aluminum/Steel Wheels, 11R22.5 (Flat), Dual Aluminum Fuel Tanks, PTO, AC, Check Engine And Stop Engine Lights Illuminated, Body Damage/Rust. Showing 837,133 Miles; 20,241 Hours. Location: San Angelo, TX Serial: 1FUJGEDR8ASAV6422	
<b>Lot #</b>	52	
<b>Qty</b>	1	
<b>Title</b>	2000 KENWORTH T800 REAR MIXER	
<b>Des.</b>	CRANKS- WONT START. Cummins ISM 305V, Eaton 9LL Speed, Chalmers Suspension, 20 FA, 46 RA, 226 WB, 10.5 YRD. McNeilus Mixer, 150 Gallon Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, Body Damage/Rust. Showing 48,033 Miles; 3,333 Hours. Location: Brownwood, TX Serial: 1NKDL00X3YR866173	
<b>Lot #</b>	53	
<b>Qty</b>	1	
<b>Title</b>	2002 MACK CV513 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. ENGINE BLOW BY. EM7-300, T2070, Walking Beam Suspension, 20 FA, 40 RA, 250 WB, Air Lift Steer Pusher Axle, Aluminum/Steel Wheels, 25/65R22.5; 11R22.5, Aluminum Fuel Tank, Aluminum Fuel Tank, Body Damage/Rust. 216,461 Miles; 25,897 Hours. Location: Omaha, NE Serial: 1M2AG03C52M001268	
<b>Lot #</b>	54	
<b>Qty</b>	1	
<b>Title</b>	2013 FORD F150 4X4 PICKUP TRUCK	
<b>Des.</b>	UNIT STARTED ON SITE- NOT ROAD TESTED. 3.5L Eco Boost, Automatic, Spring Suspension, 3.75 FA< 3.85 RA, 145 WB, Steel Wheels, 265/70R17, AC, Body Damage/Rust. 187,992 Miles. Location: Morgantown, WV Serial: 1FTFX1ET7DKE89733	
<b>Lot #</b>	55	
<b>Qty</b>	1	
<b>Title</b>	1999 KENWORTH T800 DAY CAB TRUCK	
<b>Des.</b>	CRANKS- WONT START. Cummins N14, Eaton 10 Speed, Air Ride Suspension, 201 WB, Manual 5th Wheel, Steel Wheels, 11R24.5, Dual Aluminum Fuel Tanks, PTO, Body Damage/Rust. Showing 752,118 Miles. Location: Austin, TX Serial: 1XKDD69X6XR824362	
<b>Lot #</b>	56	
<b>Qty</b>	1	
<b>Title</b>	2007 VOLVO VHD64B REAR MIXER	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. ENGINE BLOW BY. BAD PTO SHAFT. SHIFTER BAD. DRUM NOTED AS THIN. VE D12- 365 HP, Manual, T-Ride Suspension, 22 FA., 46 RA, 210 WB, 11 YRD. McNeilus Rear Mixer, 125 Gallon Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, 75 Gallon Aluminum Fuel Tank, PTO, AC, Body Damage/Rust. Showing 145,697 Miles. Location: Harrisburg, PA Serial: 4V5KC9GF97N478008	








<b>Lot #</b>	57	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. AMI-335 ASET, T310, Camelback Suspension, 18 FA, 265 WB, Double Frame, Steel Wheels, 315/8R22.5, Steel Fuel Tank, PTO, AC, Driver Seat Missing, Body Damage/Rust. Mileage Unavailable. Location: Summerville, SC Serial: 1M2AG11C07M068828	
<b>Lot #</b>	58	
<b>Qty</b>	1	
<b>Title</b>	2002 MCCLAIN TT103SE WALKING FLOOR TRAILER	
<b>Des.</b>	48ft Length, 102in Width, Steel Wheels, Body Damage/Rust. Location: Mora, MN Serial: 1M9CD48322309125	
<b>Lot #</b>	60	
<b>Qty</b>	1	
<b>Title</b>	2012 CHEVROLET COLORADO EXT CAB 4X4 PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. 3.7L Gas, Automatic, Spring Suspension, 2.85 FA, 2.896 RA, 128 WB, 6ft Box, Steel Wheels, 325/75R16, AC, Dead Battery, Body Damage/Rust. Showing 179,351 Miles. Location: Pelham, NH Serial: 1GCJTBFE0C8111907	
<b>Lot #</b>	61	
<b>Qty</b>	1	
<b>Title</b>	2000 MACK RD690S CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. EM7-275, T2070, Walking Beam Suspension, 20 FA, 40 RA, 250 WB, Air Lift Steer Pusher Axle, Power Divider Lock, Spoke Wheels, 425/65R22.5; 11R22.5, AC, Power Steering, Body Damage/Rust. Showing 257,434 Miles; 26,183 Hours. Location: Omaha, NE Serial: 1M2P289C4YM031188	
<b>Lot #</b>	62	
<b>Qty</b>	1	
<b>Title</b>	2014 NISSAN FRONTIER EXT CAB 4X4 PICKUP TRUCK	
<b>Des.</b>	ROLLED OVER- MAJOR BODY DAMAGE. STARTED- ENGINE KNOCK, NOT ROAD TESTED. LESS BATTERY. 4.0L V8, Automatic, Spring Suspension, 3.296 FA, 5.69 RA, Aluminum Wheels, 265/75R16. Showing 139,501 Miles. TITLE READS HIGHER MILEAGE THAN ODOMETER. Location: Kansas City, MO Serial: 1N6AD0CW6EN762796	
<b>Lot #</b>	63	
<b>Qty</b>	1	
<b>Title</b>	2003 MACK CH613 DAY CAB TRUCK	
<b>Des.</b>	STARTED/RAN BRIEFLY, ENGINE SHUT DOWN AND WENT TO ENGINE PROTECT MODE. E7-400 E-TECH LSR, Spicer LPSO150-10S, Air Ride Suspension, 12 FA, 40 RA, 190 WB, Air Slide 5th Wheel, Wet Kit, Aluminum Wheels, 315/8R22.5; 11R22.5, Aluminum Fuel Tank, PTO, AC, Electrical Warning Light Illuminated, Body Damage/Rust. Showing 11,531 Miles; 34,679 Hours. Location: San Antonio, TX Serial: 1M1AA14Y13W153401	
<b>Lot #</b>	64	
<b>Qty</b>	1	
<b>Title</b>	2000 INTERNATIONAL 2574 REAR MIXER	
<b>Des.</b>	UNIT STARTED ON SITE- NOT ROAD TESTED. Cummins ISM 305V, Eaton 9LL Speed, Hendrickson Suspension, 222 WB, 10.5 YRD. Lone Star Mixer, 120 Gallon Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 220,791 Miles. Location: Brownwood, TX Serial: 1HTGGAHT2YH313629	










<b>Lot #</b>	65	
<b>Qty</b>	1	
<b>Title</b>	2004 INTERNATIONAL 7600 CAB & CHASSIS	
<b>Des.</b>	STARTED/RAN BRIEFLY- OPERATOR SHUT DOWN DUE TO ENGINE WARNING. Cummins ISM, Eaton 10LL, Hendrickson Suspension, 18 FA, 40 RA, 217 WB, 205 Cab To Frame End, Steel Wheels, 385/65R22.5; 11R22.5, AC, Check Engine And ABS Light Illuminated, Body Damage/Rust. Showing 10,222 Miles; 1,039 Hours. Location: San Antonio, TX Serial: 1HTWYAHT24J093758	
<b>Lot #</b>	66	
<b>Qty</b>	1	
<b>Title</b>	2007 STERLING ACTERRA GARBAGE PACKER	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. FRONT OIL HUB PLUGS MISSING. CAT C7, Automatic, Spring Suspension, 208 WB, 20 YRD. Heil Rear Loader, Single Can Tipper, Steel Wheels, 11R22.5, PTO, AC, Body Damage/Rust. Showing 296,787 Miles; 28,862 ECM. Location: Jacksonville, FL Serial: 2FZACGDC07AX45891	
<b>Lot #</b>	67	
<b>Qty</b>	1	
<b>Title</b>	1994 WG GMC SG64T DAY CAB TRUCK	
<b>Des.</b>	CRANKS- WONT START. TRANSMISSION STUCK IN GEAR. ENGINE EXHAUST PIP CUT OFF. CAT 3306, Meritor 10 Speed, Spring Suspension, 10 FA, 40 RA, 177 WB, Wet Kit, Stationary 5th Wheel, Aluminum Wheels, 11R22.5, Aluminum Fuel Tank, AC, Drive Line Removed W/ Truck, Body Damage/Rust. Mileage Incorrect- Showing 597 Miles. Location: Concord, NC Serial: 4V1JDBBEXRR826605	
<b>Lot #</b>	69	
<b>Qty</b>	1	
<b>Title</b>	2000 MACK RD690S CAB & CHASSIS	
<b>Des.</b>	UNIT STARTED ON SITE- NOT ROAD TESTED. ENGINE BLOW BY. EM7-275, T2070, Walking Beam Suspension, 20 FA, 40 RA, 250 WB, Air Lift Pusher Axle, Aluminum/Spoke Wheels, 425/65R22.5; 11R22.5, Aluminum Fuel Tank, PTO, AC, Hydraulic Leak Noted A Rear Of Truck (From Body Removal), Body Damage/Rust. Showing 271,758 Miles; 25,494 Hours. Location: Omaha, NE Serial: 1M2P289CXYM031180	
<b>Lot #</b>	70	
<b>Qty</b>	1	
<b>Title</b>	2004 INTERNATIONAL 7400 GARBAGE PACKER	
<b>Des.</b>	STARTED ON SITE- REAR END BAD, WONT MOVE. DT466E, Automatic, Spring Suspension, 205 WB, 20 YRD. Heil Rear Loader, Single Can Tipper, Steel Wheels, 11R22.5, PTO, AC, Dead Batteries, R/Window Inop., Body Damage/Rust. Showing 329,812 Miles; 29,193 Hours. Location: Newport, NC Serial: 1HTWCAAN34J092659	
<b>Lot #</b>	72	
<b>Qty</b>	1	
<b>Title</b>	2007 FORD 450 STAKE BODY TRUCK	
<b>Des.</b>	STARTS/RUNS BRIEFLY WITH A JUMP, RUNS ROUGH- MAJOR ENGINE OIL LEAKS WHILE RUNNING. 6.4L V8 Power Stroke Turbo Diesel, Automatic, Spring Suspension, 6 FA, 12 RA, 12ft Stake Body W/ Lift Gate, Steel Wheels, 225/75R19.5, PW, PL, PM, L/Door Lock Broken, Body Damage/Rust. Showing 472,430 Miles.	

<b>Lot #</b>	73	
<b>Qty</b>	1	
<b>Title</b>	2004 PETERBILT 357 REAR MIXER	
<b>Des.</b>	STARTED W/ JUMP- NOT ROAD TESTED. CAT C10, Eaton Fuller, Hendrickson Suspension, 22 FA, 46 RA, 226 WB, 11 YRD. McNeilus Mixer, 90 Gallon Side Mount Water Tank, Full Locking Rears, Steel Wheels, 425/65R22.5; 11R22.5, FEPTO, AC, Speedometer Missing, Body Damage/Rust. Showing 4,519.2 Hours. Location: Des Moines, IA Serial: 1NPALT0XX4D831166	
<b>Lot #</b>	74	
<b>Qty</b>	1	
<b>Title</b>	1979 TRAILMOBILE TANKER TRAILER	
<b>Des.</b>	42ft Length, 96in Width, 7,500 Gallon Capacity, Aluminum Composition, Single Top Hatch, Dual Hook Ups, Single Compartment, Steel Wheels, 11R24.5, Body Damage/Rust. Location: San Antonio, TX Serial: V40588	
<b>Lot #</b>	75	
<b>Qty</b>	1	
<b>Title</b>	2007 KENWORTH T800 DAY CAB TRUCK	
<b>Des.</b>	NON RUNNER. COMPONENTS MISSING, INCLUDING: OIL PAN, RIGHT SIDE STEERING COMPONENTS, TRANSMISSION, DRIVE SHAFT AND DASH COMPONENTS. CAT C13- 430 HP, Air Ride Suspension, 12 FA, 40 RA, 220 WB, Aluminum Wheels, 11R22.5 (Rears Singled Out), 135 Gallon Aluminum Fuel Tank, Body Damage/Rust. Mileage Unavailable. Location: Abilene, TX Serial: 1XKDDU9X97J171786	
<b>Lot #</b>	76	
<b>Qty</b>	1	
<b>Title</b>	2000 INTERNATIONAL 2574 REAR MIXER	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. DRUM DOES NOT SPIN. HEAVY OIL SEEPAGE NOTED AT BLOCK, CHECK OIL AND WATER LIGHTS ILLUMINATED. Cummins ISM 305V, Eaton 9LL, Beam Suspension, 222 WB, 10.5 YRD. McNeilus Mixer, 125 Gallon Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, Body Damage/Rust. Showing 333,439 Miles. Location: Brownwood, TX Serial: 1HTGGAHT8YH250309	
<b>Lot #</b>	77	
<b>Qty</b>	1	
<b>Title</b>	1999 MACK RD690S CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. ENGINE BLOW BY. PTO SHAFT HOOKED TO HYDRAULIC PUMP. AIR LEAK NOTED. EM7-275, T2070, Walking Beam Suspension, 20 FA, 38 RA, 250 WB, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 245,569 Miles; 26,494 Hours. Location: Omaha, NE Serial: 1M2P289C4XM027723	
<b>Lot #</b>	78	
<b>Qty</b>	1	
<b>Title</b>	AIRLIFT PUSHER AXLE	
<b>Des.</b>	Location: Omaha, NE Serial: 1	
<b>Lot #</b>	79	
<b>Qty</b>	1	
<b>Title</b>	2004 FREIGHTLINER COLUMBIA DAY CAB TRUCK	
<b>Des.</b>	UNABLE TO CONFIRM RUNNING CONDITION- KNOWN RADIATOR ISSUE. Multiple Oil Leaks. Rear Cross Member Damaged. Engine Fault 111-1. Location: Watts, OK Serial: 1FUJA6CKX4DN36513	

<b>Lot #</b>	80	
<b>Qty</b>	1	
<b>Title</b>	2005 VOLVO VHD64B REAR MIXER	
<b>Des.</b>	STARTED ON SITE- ACCELERATOR PEDAL DOESNT REV ENGINE. FUEL PANEL AND RELAY BOARD NOTED AS BAD. ENGINE BLOW BY. ECU COMMUNICATIONS KNOWN. SHIFTER WORN. VE D12- 365 HP, Eaton Fuller Manual, Spring Suspension, 20 FA, 46 RA, 215 WB, McNeilus Rear Mixer, 125 Gallon Side Mount Water Tank (Sight Glass And Pressure Knob Missing), Steel Wheels, 425/65R22.5; 11R22.5, Aluminum Fuel Tank, PTO, AC, Warning Lights Illuminated, Body Damage/Rust. Showing 190,359 Hours. Location: Harrisburg, PA Serial: 4V5KC9GF25N390852	
<b>Lot #</b>	81	
<b>Qty</b>	1	
<b>Title</b>	1999 PETERBILT 357 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. ENGINE PARTIALLY DISASSEMBLED. REAR AXLE AND SUSPENSION MISSING. Cummins ISM, Automatic, 20 FA, 210 WB, Steel Wheels, 425/65R22.5; 11R24.5, Body Damage/Rust. Showing 248,446 Miles; 8,057 Hours. Location: Leander, TX Serial: 1NPAL00X7XD486729	
<b>Lot #</b>	82	
<b>Qty</b>	1	
<b>Title</b>	POSI SILO HOPPER BOTTOM TRAILER	
<b>Des.</b>	NO TITLE PER STATE REGULATION. TARTED ON SITE- FRONT FRAME BENT. TIRES HAVE DRY ROT. 38ft Length, 102in Width, 5th Wheel Hitch, Posi Shell Covered System, 3 Cylinder Kubota Diesel, 3 Hopper Chutes, R/Outriggers, Dead Batteries, Body Damage/Rust. Showing 98 Hours. Location: Roseboro, NC Unit: 189043	
<b>Lot #</b>	84	
<b>Qty</b>	1	
<b>Title</b>	AIRLIFT PUSHER AXLE	
<b>Des.</b>	Location: Omaha, NE Serial: 2	
<b>Lot #</b>	85	
<b>Qty</b>	1	
<b>Title</b>	1997 MACK RD690S CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. DOES NOT BUILD AIR. PTO HOOKED TO HYDRAULIC PUMP. EM7-275, T2070, Walking Beam Suspension, 20 FA, 38 RA, 248 WB, Aluminum/Spoke Wheels, 425/65R22.5; 11R22.5, 50 Gallon Aluminum Fuel Tank, PTO, AC, Body Damage/Rust. Showing 27,562 Miles; 22,325 Hours. Location: Omaha, NE Serial: 1M2P289C0VM023746	
<b>Lot #</b>	86	
<b>Qty</b>	1	
<b>Title</b>	2010 INTERNATIONAL 7400 GARBAGE PACKER	
<b>Des.</b>	NON RUNNER- DID NOT START W/ STARTING FLUID. ENGINE OIL LEAKS NOTED. MaxxForce DT Diesel, Automatic, Spring Suspension, 10 FA, 23 RA, 205 WB, 20 YRD. Heil Rear Loader, Single Can Tipper, Steel Wheels, 11R22.5, PTO, AC, Dash Inoperable, Body Damage/Rust. Mileage Unavailable. Location: Newport, NC Serial: 1HTWCAAN2AJ245446	
<b>Lot #</b>	88	
<b>Qty</b>	1	
<b>Title</b>	2002 STERLING LT9500 REAR MIXER	
<b>Des.</b>	NON RUNNER. FUEL TANK DAMAGED. KNOWN ELECTRICAL ISSUES, INCLUDING: BROKEN CIRCUITS BREAKERS AND OPEN HARNESSSES. Cummins ISM 350V, 9LL Speed RoadRanger, Chalmers Suspension, 20 FA, 46 RA, 222 WB, 10.5 YRD. London Mixer, Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R22.5, PTO, Climate Controls Board Missing, Body Damage/Rust. Showing 338,755 Miles; 28,159 Hours. Location: Brownwood, TX Serial: 2FZHAZA832AK53154	

<b>Lot #</b>	89	
<b>Qty</b>	1	
<b>Title</b>	1999 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. E7-300 EUP, Allison HT740RS, Camelback Suspension, 18 FA, 260 WB, Double Frame, Steel Wheels, 315/80R22.5, Steel Fuel Tank, PTO, AC, Body Damage/Rust. Mileage Unavailable. Location: Summerville, SC Serial: 1M2P296C5XM043973	
<b>Lot #</b>	90	
<b>Qty</b>	1	
<b>Title</b>	AIRLIFT PUSHER AXLE	
<b>Des.</b>	Location: Omaha, NE Serial: 3	
<b>Lot #</b>	91	
<b>Qty</b>	1	
<b>Title</b>	2003 MACK CH613 DAY CAB TRUCK	
<b>Des.</b>	NON RUNNER. EXHAUST STACK MISSING. E7-400, Spicer 10 Speed, Air Ride Suspension, 12 FA, 40 RA, 189 WB, Air Slide 5th Wheel, Wet Kit, Aluminum Wheels, 11R22.5, PTO, AC, Body Damage/Rust. Showing 59,463 Miles; 36,193 Hours. Location: San Antonio, TX Serial: 1M1AA14Y73W153399	
<b>Lot #</b>	92	
<b>Qty</b>	1	
<b>Title</b>	1998 FORD E350 VAN BODY TRUCK	
<b>Des.</b>	STARTED ON SITE- RUNS ROUGH, NOT ROAD TESTED. BRAKES INOPERABLE. 7.3L Diesel, Automatic, Spring Suspension, 4.6 FA, 7.5 RA, 178 WN, Steel Wheels, 225/75R16, Body Damage/Rust. Showing 300,787 Miles. Location: Wittenberg, WI Serial: 1FDWE37F1WHB04901	
<b>Lot #</b>	93	
<b>Qty</b>	1	
<b>Title</b>	2004 STERLING LT9500 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER- MISSING TRANSMISSION AND FUEL TANK. CAT C10- 305 HP, Spring Suspension, 18 FA, 40 RA, 212 WB, 202 Cab To Frame End, Steel Wheels, 425/65R22.5; 11R22.5 (Rears Singled Out), Body Damage/Rust. Mileage Unavailable. Location: Cuero, TX Serial: 2FZHAZAN44AM08643	
<b>Lot #</b>	94	
<b>Qty</b>	1	
<b>Title</b>	2008 AUTOCAR WX64 GARBAGE PACKER	
<b>Des.</b>	NON RUNNER. COMPONENTS MISSING, INCLUDING: IGNITION SWITCH, FRONT PTO SHAFT, INTERIOR CONTROL PANELS W/ FUSES AND RELAYS, AND EXHAUST PIPE. Cummins ISM, Automatic, Hendrickson Suspension (L/Rear Bolts Loose), 20 FA, 46 RA, 189 WB, 40 YRD. EZ Pack Front Loader, Non Steer Tag Axle, Steel Wheels, 315/80R22.5, PTO, AC, Rear Camera, Body Damage/Rust. Mileage Unavailable. Location: Newport, NC Serial: 5V CDC6BE38H206658	
<b>Lot #</b>	95	
<b>Qty</b>	1	
<b>Title</b>	AIRLIFT PUSHER AXLE	
<b>Des.</b>	Location: Omaha, NE Serial: 4	

<b>Lot #</b>	96	
<b>Qty</b>	1	
<b>Title</b>	2011 GMC SIERRA 2500 EXT CAB 4X4 PICKUP TRUCK	
<b>Des.</b>	RUNS POORLY. WARNING LIGHTS ILLUMINATED. 6.0L, Automatic, Spring Suspension, 4.4 FA, 6.2 RA, 144.2 WB, 245/75R17, AC, Body Damage/Rust. Showing 251,645 Miles. Location: Commerce City, CO Serial: 1GT22ZCG8BZ406073	
<b>Lot #</b>	97	
<b>Qty</b>	1	
<b>Title</b>	2001 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. RUNS ROUGH. LESS HOOD. E7-350 E-TECH, RTOF14908LL, Hendrickson Suspension, 20 FA, 268 WB, 240 Cab To Frame End, Pusher Axle, Steel Wheels, 315/80R22.5 (Rears Singled Out), Steel Fuel Tank, L/Door Missing, Driver Seat Missing, R/Door Jammed, Body Damage/Rust. Showing 168,767 Miles; 39,657 Hours. Location: Des Moines, IA Serial: 1M2P267C71M058124	
<b>Lot #</b>	98	
<b>Qty</b>	1	
<b>Title</b>	AIRLIFT PUSHER AXLE	
<b>Des.</b>	Location: Omaha, NE Serial: 5	
<b>Lot #</b>	99	
<b>Qty</b>	1	
<b>Title</b>	2005 CHEVROLET COLORADO PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE- REVERSE INOPERABLE. DASH INOPERABLE. 3.5L 5 Cylinder, Automatic, Spring Suspension, 126 WB, Aluminum Wheels, 265/75R15, Dead Battery, Body Damage/Rust. Mileage Unavailable. Location: Wittenberg, WI Serial: 1GCDT136858275610	
<b>Lot #</b>	100	
<b>Qty</b>	1	
<b>Title</b>	2004 FORD F450 SERVICE TRUCK	
<b>Des.</b>	STARTED ON SITE- NOT ROAD TESTED. 6.0L V8 Power Stroke Diesel, Automatic, Spring Suspension, 6 FA, 11 RA, 141 WB, 10ft Rawson Koenig Body, Liftmoore 3200RRE Crane W/ Hand Controls, Steel Wheels, 225/70R19.5, AC, Cracked Windshield, Body Damage/Rust. Showing 231,660 Miles. Location: Houston, TX Serial: 1FDXF46P14EA84536	
<b>Lot #</b>	102	
<b>Qty</b>	1	
<b>Title</b>	AIRLIFT PUSHER AXLE	
<b>Des.</b>	Location: Omaha, NE Serial: 6	
<b>Lot #</b>	105	
<b>Qty</b>	1	
<b>Title</b>	AIRLIFT PUSHER AXLE	
<b>Des.</b>	Location: Omaha, NE Serial: 7	

---

<b>Lot #</b>	106
<b>Qty</b>	1
<b>Title</b>	2003 YALE FORKLIFT
<b>Des.</b>	NO TITLE PER STATE REGULATION. NON RUNNER. FORKS MISSING. Electric, ROPS, 24/7R15; 16/6R10.5 Tires, Body Damage/Rust. Hours Unavailable. Location: Wittenberg, WI Serial: ERC050ZGN48TE084

