



## Printable Catalog

<b>Title</b>	AUGUST 8 12:00 CDT	
<b>Description</b>	Closing Times TBD	
<b>Date</b>	Wed, Aug 8, 2018	
<b>Starts at</b>	12:00 PM	
<b>Address</b>	4747 NE 14th St, Des Moines, IA 50313 USA	
<b>Categories</b>		


---

<b>Lot #</b>	1	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	THIS UNIT RUNS. AMI-355 ASET. T310, Hendrickson Suspension, 18 FA, 242 WB, Double Frame, Aluminum/Steel Wheels, 385/65R22.5; 11R22.5, Dual Aluminum Fuel Tanks, PTO, AC. Showing 619,107 Miles; 27,502 Hours. Location: Des Moines, IA Serial: 1M2AG11C86M041066	


---

<b>Lot #</b>	2	
<b>Qty</b>	1	
<b>Title</b>	2005 MACK DM690S ROLLOFF TRUCK	
<b>Des.</b>	THIS UNIT RUNS. AMI-300 ASET, TM308- 8 Speed, Cruise, Camelback Suspension, 250 WB, Aluminum/Steel Wheels, 385/65R22.5; 11R22.5, Steel Fuel Tank, Power Steering, AM/FM/CD, Rear Axle Leak, Oil Seepage Noted At Oil Pan, Body Damage. Showing 458,959 Miles; 26,997 Hours. Location: Saint Paul, MN Serial: 1M2B209CX5M030408	


---








<b>Lot #</b>	4	
<b>Qty</b>	1	
<b>Title</b>	1998 KENWORTH T880 DAY CAB TRUCK	
<b>Des.</b>	THIS UNIT RUNS. ENGINE BLOW BY. ENGINE OIL LEAKS NOTED AT PAN REAR ENGINE MANIFOLD. Cummins M11- 400 HHP, OD, Cruise, 10 Speed Eaton FRO-15210C Manual, Air Ride Suspension, 12 FA, 40 RA, 52,000 GVWR, Air Slide 5th Wheel, Steel Wheels, 11R22.5, 150 Gallon Dual Aluminum Fuel Tanks, Power Steering, AC (Inop), AM/FM/CD (Inop), Heated Mirrors, Active Fault Code: 25-4, Body Damage. Showing 80,637 Miles; 525,680 ECM; 16,158 Hours. Location: Mokena, IL Serial: 1XKDD99X6WR780962	







---







<b>Lot #</b>	6	
<b>Qty</b>	1	
<b>Title</b>	2005 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. REMOVED: TURBO, INJECTORS, COMPUTER, RADIATOR, INTER COOLERS, AC CONDENSER, INSTRUMENT CLUSTER, BATTERIES. AI-400 ASET, T310M 10 Speed, Spring Suspension, 288 WB, Double Frame, Steel Wheels, 12R24.5 (Bad Tires), Aluminum Fuel Tank, PTO, Driver Seat Removed, Grille Removed. Mileage Unavailable. Location: Pelham, NH Serial: 1M2AG11CX5M015079	







---

<b>Lot #</b>	7	
<b>Qty</b>	1	
<b>Title</b>	2011 JOHN DEERE 444K WHEEL LOADER	
<b>Des.</b>	NO TITLE PER STATE REQUIREMENTS. PUSH BUTTON START CLICKS- WONT START. John Deere, Powershift PowerTech PSS 4045, 94in Bucket Width, 2.5 YRD3 Capacity, EROPS (Glass Missing), Steel Wheels, 17.5R25, R/Arm Cracked And Fixed, Door Broken. Showing 11,345 Hours. Location: Watts, OK Serial: DW444KZ628237	








<b>Lot #</b>	8	
<b>Qty</b>	1	
<b>Title</b>	1999 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	THIS UNIT RUNS. E7-350 EUP, T2090, Camelback Suspension, 18 FA, 264 WB, Double Frame, Pusher Axle (Wheels Removed), Steel Wheels, 315/80R22.5, 100 Gallon Steel Fuel Tank, PTO, Dash Damaged. Showing 479,500 Miles. Location: Bardstown, KY Serial: 1M2P267CXXM047689	
<b>Lot #</b>	9	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK DM690S ROLLOFF TRUCK	
<b>Des.</b>	THIS UNIT RUNS. AMI-300 ASET, T308- 8 Speed, Camelback Suspension, 250 WB, Aluminum Wheels, 385/65R22.5; 11R22.5, Steel Fuel Tank, AC, AM/FM/CD, Oil Seepage Noted At Oil Pan, Rust, Body Damage. Showing 528,119 Miles; 30,441 Hours. Location: Saint Paul, MN Serial: 1M2B209C86M030974	
<b>Lot #</b>	10	
<b>Qty</b>	1	
<b>Title</b>	1999 MACK CH613 DAY CAB TRUCK	
<b>Des.</b>	THIS UNIT RUNS. E7-330/350 EUP, Fuller RTX14609B, Air Ride Suspension, 198 WB, Steel Wheels, 275/80R22.5, Aluminum Fuel Tank, PTO, AC. Showing 239,332 Miles; 17,911 Hours. Location: Des Moines, IA Serial: 1M1AA12Y7XW102106	
<b>Lot #</b>	11	
<b>Qty</b>	1	
<b>Title</b>	1996 INTERNATIONAL 4900 STRAIGHT TRUCK	
<b>Des.</b>	THIS UNIT RUNS. DT 466, Eaton 6 Speed, Air Ride Suspension, 8 FA, 17.5 RA, 272wb, Steel Wheels, 295/75R22.5, 11R22.5, 25ft Body (13ft 4in Height) w/ Steel Floor, Rear Lift Gate (Inop) Rear Crank Down Dollies, Dual 75 Gallon Steel Tanks, AC. Showing 1,048,840 Miles. Location: Bardstown, KY Serial: 1HTSDAAL4TH409784	
<b>Lot #</b>	13	
<b>Qty</b>	1	
<b>Title</b>	2009 GMC C5500 STAKE BODY TRUCK	
<b>Des.</b>	THIS UNIT RUNS. Duramax V8 6.6L Diesel, OD, Cruise, Allison Automatic, Spring Suspension, 7 FA, 13.5 RA, 16ft Stake Body (96in Width, 60in Height), Thieman Lift Gate- 2,000 LB. Capacity, Aluminum Wheels, 245/70R19.5, 50 Gallon Fuel Tank, Power Steering, AC (Inop), AM/FM/CD, Power Mirrors, Multiple Warning Lights Illuminated- Service Oil; Engine, Fuel And Washer Fluid, Body Rails Bent/Missing. Showing 215,315 Miles. Location: Tampa, FL Serial: 1GDE5C1989F407799	
<b>Lot #</b>	16	
<b>Qty</b>	1	
<b>Title</b>	2009 FORD F750 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. BAD ENGINE. CAT C7, Automatic, Spring Suspension, 12 FA, 21 RA, 158 WB, Steel Wheels, 11R22.5; 275/80R22.5, PTO, AC. Showing 409,707 Miles. Location: Bardstown, KY Serial: 3FRWF75W89V158205	
<b>Lot #</b>	17	
<b>Qty</b>	1	
<b>Title</b>	2009 MACK MRU613 GARBAGE PACKER	
<b>Des.</b>	THIS UNIT RUNS. MP7, Allison 4500RDS, Camelback Suspension, 20 FA, 46 RA, 189 WB, 40 YRD. EZ Pack Front Loader, Non Steer Tag Axle, Steel Wheels, 315/80R22.5, PTO, AC, Rear Camera, ABS And Electronic Malfunction Warning Lights Illuminated, Regen Issue. Showing 252,692 Miles; 5,758 Hours. Location: Wilmington, NC Serial: 1M2AV02C59M004950	








<b>Lot #</b>	18	
<b>Qty</b>	1	
<b>Title</b>	2003 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	THIS UNIT RUNS. E7-350IEGR, T2090 9 Speed, Camelback Suspension, 18 FA, Double Frame, Tag Axle, Steel Wheels, 11R22.5; 315/80R22.5, Steel Fuel Tank, PTO. Showing 113,600 Miles; 26,643 Hours. Location: Greenville, OH Serial :1M2P267C13M066528	
<b>Lot #</b>	20	
<b>Qty</b>	1	
<b>Title</b>	2007 PETERBILT CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. ROLLED OVER. FUEL PUMP REMOVED. DASH APART- COMPONENTS MISSING. STEERING WHEEL REMOVED. Cummins, Automatic, Beam Suspension, Steel/Aluminum Wheels, 11R22.5/425/65R22.5, Less Keys, Seats Removed. Mileage Unavailable. Location: Des Moines, IA Serial: 1NPAL50X07N648630	
<b>Lot #</b>	21	
<b>Qty</b>	1	
<b>Title</b>	2009 VOLVO VNL64T DAY CAB TRUCK	
<b>Des.</b>	NON RUNNER. ENGINE PARTS REMOVED- IN CAB. FUEL TANK CAP MISSING. VE D13- 326 HP, Eaton 10 Speed, Air Ride Suspension, 12.5 FA, 40 RA, 171 WB, Air Slide 5th Wheel, Aluminum/Steel Wheels, 295/75R22.5, 240 Gallon Total Dual Aluminum Fuel Tanks. Mileage Unavailable. Location: Bastrop, TX Serial: 4V4NC9EG69N492044	
<b>Lot #</b>	22	
<b>Qty</b>	1	
<b>Title</b>	1993 MACK CL713 DAY CAB TRUCK	
<b>Des.</b>	NON RUNNER. IGNITION AND KEY REMOVED. MINOR CAB FIRE DAMAGE. E7-350, T2180B 18 Speed, Air Ride Suspension, 192 WB, Aluminum/Steel Wheels, 425/65R22.5; 255/70R22.5, Dual Aluminum Fuel Tanks, PTO, AC, Body Damage, Hole In Cab Floor, R/Dash Apart. Showing 856,253 Miles; 2,833 Hours. Location: Des Moines, IA Serial: 1M2AD09C9PW001432	
<b>Lot #</b>	23	
<b>Qty</b>	1	
<b>Title</b>	1996 INTERNATIONAL 4900 RENDERING TRUCK	
<b>Des.</b>	NON RUNNER. DT466, Eaton Fuller, Spring Suspension, 200 WB, 16ft Body, Steel Wheels, 275/80R22.5; 295/75R22.5, Steel Fuel Tank, PTO, AC, R/Rear Brakes Removed. Showing 81,186 Miles. Location: Des Moines, IA Serial: 1HTSDAAN9TH278918	
<b>Lot #</b>	24	
<b>Qty</b>	1	
<b>Title</b>	1999 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	THIS UNIT RUNS. E7-350 EUP, Fuller RTOF14908LL, Camelback Suspension, 20 FA, 255 Cab To Frame End, Double Frame, Dual Pusher Axles, Steel Wheels, 315/80R22.5; 11R22.5, 130 Gallon Dual Steel Fuel Tanks, PTO. Showing 160,689 Miles; 45,521 Hours. Location: Greenville, OH Serial: 1M2P267C6XM046863	








<b>Lot #</b>	25	
<b>Qty</b>	1	
<b>Title</b>	1998 MACK RD688S ROLLOFF TRUCK	
<b>Des.</b>	THIS UNIT RUNS. IGNITION SWITCH DOES NOT TURN UNIT OFF, SHUT DOWN UNDER HOOD. CAB NOT SECURELY MOUNTED ON CHASSIS. ENGINE OIL LEAK NOTED AT R/SIDE AND OIL PAN. SLIGHT ENGINE SMOKE NOTED AT OIL FILL TUBE. EM7-300, Cruise, T2070 7 Speed, Camelback Suspension, Mack 5.55 Rears, Galbreath Rolloff Body, Spoke Wheels, 385/65R22.5, Steel Fuel Tank, Power Steering, AC, AM/FM/CD, Rear Axle Leak, Body Damage. Showing 781,458 Miles; 17,946 Hours. Location: Minneapolis, MN Serial: 1M2B209C4WM022211	
<b>Lot #</b>	26	
<b>Qty</b>	1	
<b>Title</b>	2000 FORD F650XL SERVICE TRUCK	
<b>Des.</b>	THIS UNIT RUNS. CAT 3126, Automatic, 8.5 FA, 17.5 RA, 158 WB, IMT 5020 Crane, 13ft IMT Dominator Body, IMT Air Compressor, Side Storage, Steel Wheels, Aluminum Wheels, 295/75R22.5; 275/80R22.5, Dual Steel Fuel Tanks, AC, PW, PL. Showing 252,150 Miles. Location: Des Moines, IA Serial: 3FDNF65A5YMAO7930	
<b>Lot #</b>	27	
<b>Qty</b>	1	
<b>Title</b>	2009 HITACHI ZX450LC-3 EXCAVATOR	
<b>Des.</b>	HOUSBY ONLY TRANSPORT. NO TITLE PER STATE REQUIREMENTS. ATTACHMENTS NOT INCLUDED. UNDER CARRIAGE WORN. Isuzu 6WG1XDHA- 348 HP, 472in Total Length, 102,955.9 Operational Weight, 142in Width, EROPS. Showing 15,258.9 Hours. Location: Suwanee, GA Serial: 20186	
<b>Lot #</b>	28	
<b>Qty</b>	1	
<b>Title</b>	2005 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. HOOD REMOVED. AMI-335 ASET, T310, Hendrickson Suspension, 18 FA, 240 WB, Double Frame, Steel Wheels, 315/80R22.5; 11R22.5, Dual Aluminum Fuel Tanks, PTO, AC, Drive Shaft Removed W/ Truck. Mileage Unavailable. Location: Des Moines, IA Serial: 1M2AG11CX5M020797	
<b>Lot #</b>	29	
<b>Qty</b>	1	
<b>Title</b>	2007 VOLVO VNL DAY CAB TRUCK	
<b>Des.</b>	RUNS BRIEFLY/ROUGH. DEF FLUID IN FUEL TANK. VE D12- 365 HP, Eaton 10 Speed, Air Ride Suspension, 12.5 FA, 40 RA, 171 WB, Air Slide 5th Wheel, Aluminum/Steel Wheels, 11R22.5; 295/75R22.5, Dual Aluminum Fuel Tanks, AC. Showing 1,045,816 Miles. Location: Jackson, MS Serial: 4V4NC9GF07N467383	
<b>Lot #</b>	30	
<b>Qty</b>	1	
<b>Title</b>	1999 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	THIS UNIT RUNS. E7-350 EUP, T2090, Camelback Suspension, 18 FA, 46 RA, 260 WB, Double Frame, Steel Wheels, 275/80R22.5, 75 Gallon Steel Fuel Tank, PTO, AC. Showing 861,002 Miles; 43,392 Hours. Location: Greenville, OH Serial: 1M2P267C4XM046263	

<b>Lot #</b>	32	
<b>Qty</b>	1	
<b>Title</b>	1999 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	UNKNOWN RUNNING CONDITION- LESS KEYS. OIL LEAKS NOTED AT ENGINE AND PAN. E7-350 EUP, OD, Cruise, T2090, Camelback Suspension, 18 FA, 46 RA, 265 WB, Steel Wheels, 10R22.5; 315/80R22.5 (Rears Singled Out), 100 Gallon Steel Fuel Tank, AC, Heated Mirrors, Drive Shaft Removed W/ Truck, Exhaust Damage, Body Damaged Throughout. Showing 744,026 Miles; 799 Hours. Location: Elkhart, IN Serial: 1M2P267C5XM047695	
<b>Lot #</b>	34	
<b>Qty</b>	1	
<b>Title</b>	2007 FORD F550 SERVICE TRUCK	
<b>Des.</b>	THIS UNIT RUNS. 6.0L V8 Turbo Diesel, Automatic, Spring Suspension, 165 WB, Auto Crane 6006EH-6000lb Capacity, Reading Body w/ Bobcat Welder (Showing 263 Hours) Onan Gas Generator, Ingersoll Rand 2475 Compressor, Side Storage, Steel Wheels, 225/70R19.5, AC. Showing 97,621 Miles. Location: Des Moines, IA Serial: 1FDAF56P57EA13503	
<b>Lot #</b>	35	
<b>Qty</b>	1	
<b>Title</b>	2007 INTERNATIONAL 4300 STRAIGHT TRUCK	
<b>Des.</b>	THIS UNIT RUNS. DT466, Automatic, Spring Suspension, 188 WB, 146in Body Length (96in Width), Lift Gate, Steel Wheels, 11R22.5; 295/75R22.5, AC, AC Warning Light Illuminated. Showing 321,343 Miles; 16,646 Hours. Location: Houston, TX Serial: 1HTMMAAN27H404230	
<b>Lot #</b>	36	
<b>Qty</b>	1	
<b>Title</b>	2004 PETERBILT 357 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. ENGINE REMOVED. Allison Automatic, Hendrickson Suspension, Aluminum/Steel Wheels, 425/65R22.5; 12R22.5, Aluminum Fuel Tank. Showing 165,873 Miles; 7,796 Hours. Location: Des Moines, IA Serial: 1NPALTOX64D826837	
<b>Lot #</b>	37	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK MR688S GARBAGE PACKER	
<b>Des.</b>	THIS UNIT RUNS. AI300A ASET, OD, Cruise, Allison 4500RDS, Camelback Suspension, 210 WB, Heil Front Loader, Aluminum Wheels, 385/65R22.5; 11R22.5, Steel Fuel Tank, Power Steering, AM/FM/CD, Body Damage. Showing 355,860 Miles; 36,764 Hours. Location: Minneapolis, MN Serial: 1M2K195C46M032329	
<b>Lot #</b>	38	
<b>Qty</b>	1	
<b>Title</b>	2006 VOLVO VNL DAY CAB TRUCK	
<b>Des.</b>	THIS UNIT RUNS. OIL LEAKS NOTED AT L/LOWER ENGINE SIDE, ENGINE FRONT COVER, OIL PAN GASKET, REAR PAN GASKET AND REAR SEAL. VE D12 12.1L 365 HP, Cruise, 10 Speed Eaton Manual FR-14210B, Air Ride Suspension, 13.2 FA, 40 RA, Air Side 5th Wheel, Aluminum/Steel Wheels, 11R22.5; 275/80R22.5, 125 Gallon Dual Aluminum Fuel Tanks, Power Steering, AC, Dual Power Mirrors, Multiple Warning Lights Illuminated- See Photos, Horns Inoperable, Fog Lights Removed, Body Damage. Showing 737,910 Miles; 22,454 Hours. Location: Pocahontas, AR Serial: 4V4NC9GF86N414879	

<b>Lot #</b>	40	
<b>Qty</b>	1	
<b>Title</b>	2003 INTERNATIONAL 4400 CAB & CHASSIS	
<b>Des.</b>	THIS UNIT RUNS. DT466, Manual, Spring Suspension, 12 FA, 23 RA, 198 WB, 168 Cab To Frame End, Wet Kit, Steel Wheels, 11R22.5, 50 Gallon Steel Fuel Tank, PTO, AC. Showing 243,288 Miles; 6,280 Hours. Location: Greenville, OH Serial: 1HTMKAA93H560149	
<b>Lot #</b>	41	
<b>Qty</b>	1	
<b>Title</b>	2003 MACK MR688S GARBAGE PACKER	
<b>Des.</b>	THIS UNIT RUNS. E7-300 E-TECH LSR, OD, Cruise, Allison 4560P (Coated In Oil), Camelback Suspension, 20 FA, 40 RA, 210 WB, McNeilus Front Loader, Steel Wheels, 315/80R22.5, 55 Gallon Aluminum Fuel Tank, Power Steering, AC, AM/FM/CD, Leak Noted At Pan/Rear Seal, Residue Noted On Engine, Body Damage. Showing 28,132 Miles; 7,680 Hours. Location: Bloomfield, NM Serial: 1M2K195C73M021840	
<b>Lot #</b>	42	
<b>Qty</b>	1	
<b>Title</b>	2004 INTERNATIONAL 7400 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. DT530, Automatic, Hendrickson Suspension, 16 FA, 40 RA, 248 WB, Double Frame, R/Side Stand Up Door, Pusher Axle, Steel Wheels, 315/80R22.5; 295/75R22.5, 75 Gallon Steel Fuel Tank, AC. Mileage Unavailable. Location: Greenville, OH Serial: 1HTWGADT84J093787	
<b>Lot #</b>	44	
<b>Qty</b>	1	
<b>Title</b>	2002 INTERNATIONAL 7400 CAB & CHASSIS	
<b>Des.</b>	THIS UNIT RUNS. DT466, Automatic, Hendrickson Haulmaax Suspension, 191 WB, Steel Wheels, 315/8R222.5, AC. Showing 247,389 Miles; 1,335 Hours. Location: Des Moines, IA Serial: 1HTWGAAT92J039397	
<b>Lot #</b>	45	
<b>Qty</b>	1	
<b>Title</b>	1997 VOLVO WG64 ROLLOFF TRUCK	
<b>Des.</b>	UNKNOWN RUNNING CONDITION- DEAD BATTERIES. OIL LEAK NOTED AT MANIFOLD. MAJOR FRAME RUST. Cummins M11- 280 HP, E-Brake, OD, Cruise, Rockwell 9 Speed Manual, T-Ride Suspension, 12 FA, 40 RA, 52,000 GVWR, Aluminum/Steel Wheels, 295/75R22.5, 50 Gallon Aluminum Fuel Tank, Power Steering, AC, Hydraulic Oil Leak, Body Damage, Rust Throughout, Heavy Axle Build Up. Mileage Unavailable. Location: Holden, LA Serial: 4VHJCFPE5VR855296	
<b>Lot #</b>	46	
<b>Qty</b>	1	
<b>Title</b>	2004 FORD F150XL EXT CAB PICKUP TRUCK	
<b>Des.</b>	THIS UNIT RUNS. FRONT END DAMAGE- BOTH AIR BAGS DEPLOYED. 4.6L Gas, Automatic, 139wb, 3.1 FA, 3.2 RA, 6ft Body w/ Liner, Trailer Hitch, Steel Wheels, 235/85R16, AC. Dead Batteries, Body Damage Throughout, R/R Door Will Not Open. Showing 311,643 Miles. Location: Stockbridge, GA Serial: 2FTRX17W94CA50302	
<b>Lot #</b>	47	
<b>Qty</b>	1	
<b>Title</b>	2006 VOLVO VNL64T DAY CAB TRUCK	
<b>Des.</b>	THIS UNIT RUNS. VE D12- 365 HP, Eaton 10 Speed, Air Ride Suspension, 12.3 FA, 38 RA, 172 WB, Wet Kit, Air Slide 5th Wheel, Aluminum/Steel Wheels, 295/775R22.5, Dual Aluminum Fuel Tanks, AC, Hydraulic Tank Cap Missing. Showing 745,871 Miles. Location: Houston, TX Serial: 4V4NC9GF96N414891	

<b>Lot #</b>	48	
<b>Qty</b>	1	
<b>Title</b>	2004 PETERBILT 357 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. MISSING ENGINE PARTS. CAT C10, Eaton Fuller 9LL, Haulmax Suspension, 50 Gal Fuel Tank, 20 FA, 46 RA, Aluminum Wheels, 445/6522.5. Miles Unavailable. Location: Buckeye, AZ Serial: 1NPALT0X44D817330	
<b>Lot #</b>	49	
<b>Qty</b>	1	
<b>Title</b>	2005 INTERNATIONAL 7400 GARBAGE PACKER	
<b>Des.</b>	NON RUNNER. ENGINE APART- TOP HALF REMOVED. DT530, Cruise, Allison 4500RDS Automatic, Hendrickson Suspension, 272 WB, Dual Steering, R/Stand Up Door, Aluminum Wheels, 315/80R22.5; 11R22.5, Steel Fuel Tank, Power Steering, AC, AM/FM/CD, Drive Shaft Removed W/ Truck, Body Damage, R/Window Broken. Mileage Unavailable. Location: Saint Paul, MN Serial: 1HTWGADT25J027186	
<b>Lot #</b>	50	
<b>Qty</b>	1	
<b>Title</b>	2007 VOLVO VNL64T DAY CAB TRUCK	
<b>Des.</b>	THIS UNIT RUNS. VE D12, Meritor 10 Speed, Air Ride Suspension, 12.5 FA, 40 RA, 170 WB, Air Slide 5th Wheel, Aluminum/Steel Wheels, 295/75R22.5, 150 Gallon Total Dual Aluminum Fuel Tanks, AC, Side Repeater Right Open Circuit Warning Light Illuminated. Showing 1,037,590 Miles. Location: Bastrop, TX Serial: 4V4NC9GF47N467404	
<b>Lot #</b>	53	
<b>Qty</b>	1	
<b>Title</b>	2008 STERLING ACTERRA CAB & CHASSIS	
<b>Des.</b>	THIS UNIT RUNS. DOES NOT BUILD AIR PRESSURE. Cummins ISC, Allison 3000, Torsion Bar Suspension, 18 FA, 46 RA, 228 WB, Double Frame, Steel Wheels, 315/80R22.5, Aluminum Fuel Tank 80 Gallon Total, PTO, AC, Drive Shaft Removed W/ Truck, Odometer Inoperable. Location: Willow Park, TX Serial: 2FZHATBS38AY43712	
<b>Lot #</b>	54	
<b>Qty</b>	1	
<b>Title</b>	1992 GMC SIERRA SERVICE TRUCK	
<b>Des.</b>	THIS UNIT RUNS. 6.2L V8- 165 HP, OD, 4 Speed Automatic, Spring Suspension, 3.8 FA, 6.084 RA, 160 WB, 9,000 GVWR, 11ft Body (Heavy Rust- 60in Height, 91in Width), 1,000 LB. Capacity Tommy 440 Lift Gate, Steel Wheels, 225/75R16, 34 Gallon Fuel Gallon, AC (Inop), AM/FM/CD, Oil Leak Noted At Valve Covers/Pan, Heavy Build Up At Oil Pan And Rear Seal, Body Damage. Showing 151,203 Miles. Location: Mokena, IL Serial: 1GDJC34J3NE543218	
<b>Lot #</b>	56	
<b>Qty</b>	1	
<b>Title</b>	2007 PETERBILT 357 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. MISSING ENGINE COMPONENTS. IGNITION REMOVED. DRIVE LINE REMOVED. Cummins ISL, Allison Automatic, Beam Suspension, 20 FA, 44 RA, 256 WB, Aluminum Wheels, 11R22.5; 425/65R22.5. Mileage Unavailable. Location: Buckeye, AZ Serial: 1NPAL50X87D699573	
<b>Lot #</b>	57	
<b>Qty</b>	1	
<b>Title</b>	2000 MACK MR688S GARBAGE PACKER	
<b>Des.</b>	NON RUNNER. OIL LEAK AT ENGINE AND TRANSMISSION. E7-300 EUP, Allison HT740RS, Camelback Suspension, 20 FA, 46 RA, 156 WB, 20 YRD. Leach Rear Loader, Steel Wheels, 11R22.5, Steel Fuel Tank, Power Steering, Hydraulic Cab Lift Assist Inoperable, Rust Throughout, Steer Brake Coated In Oil. Showing 406,620 Miles; 26,165 Hours. Location: Grand Cane, LA Serial: 1M2K195C4YM014917	

<b>Lot #</b>	58	
<b>Qty</b>	1	
<b>Title</b>	2004 FORD F150XL EXT CAB PICKUP TRUCK	
<b>Des.</b>	THIS UNIT RUNS. DO NOT DRIVE- NO BRAKES. 4.6L Gas, Automatic, 3.1 FA, 3.2 RA, 139wb, 6ft Body w/ Liner, Trailer Hitch, Steel Wheels, 245/75R16, AC. Check Engine Light On, Hood Does Not Stay Up On Own, Dead Batteries, L/S Body Damage, R/R Door Doesn't Open. Showing 310,223 Miles. Location: Douglas, GA Serial: 2FTRX17W74CA50301	
<b>Lot #</b>	59	
<b>Qty</b>	1	
<b>Title</b>	2005 TRAVIS DUMP TRAILER	
<b>Des.</b>	40ft Length, Aluminum Composition, Steel Wheels, 11R22.5. Location: Des Moines, IA Serial: 48X1F402351003424	
<b>Lot #</b>	60	
<b>Qty</b>	1	
<b>Title</b>	1999 INTERNATIONAL 4700 DUMP TRUCK	
<b>Des.</b>	THIS UNIT RUNS. DT466, Automatic, Spring Suspension, 16 FA, 23 RA, 152 WB, Lift Cylinder, Steel Wheels, 315/80R22.5; 11R22.5, Steel Fuel Tank, PTO, AC, Pintle Hitch, AM/FM/CD. Showing 11,900 Miles; 1,749 Hours. Location: Des Moines, IA Serial: 1HTSCAAR6XH675332	
<b>Lot #</b>	61	
<b>Qty</b>	1	
<b>Title</b>	1999 MACK MR688S GARBAGE PACKER	
<b>Des.</b>	THIS UNIT RUNS. MAJOR AIR LEAK, BRAKES WILL NOT RELEASE. DOES NOT MOVE. E7-300 EUP, OD, Cruise, Allison HD4560P, Camelback Suspension, 18.74 FA, 46 RA, 197 WB, Heil Front Loader, Steel Wheels, 385/65R22.5; 11R22.5, Steel Fuel Tank, Power Steering, AM/CD/CD, Oil Seepage Noted At Oil Pan. Showing 42,058 Miles; 38,519 Hours. Location: Saint Paul, MN Serial: 1M2K195C0XM014590	
<b>Lot #</b>	64	
<b>Qty</b>	1	
<b>Title</b>	2006 PETERBILT 357 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. ENGINE COMPONENTS MISSING. IGNITION REMOVED. INTER AXLE AND DRIVE LINE REMOVED. EXHAUST REMOVED. Cummins ISL, Allison Automatic, Chalmers Suspension, 20 FA, 44 RA, 248 WB, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5 (Rears Singled Out), Dash Apart- Missing Components, Battery Box Cover Missing. Mileage Unavailable. Location: Buckeye, AZ Serial: 1NPAL00X06D648800	
<b>Lot #</b>	66	
<b>Qty</b>	1	
<b>Title</b>	1995 GMC 2500 4X4 PICKUP TRUCK	
<b>Des.</b>	THIS UNIT RUNS. KNOWN TRANSMISSION PROBLEM, MISSING RADIATOR CAP. 5.7L Gas, Automatic, 134wb, 8ft Body (Damaged Throughout) Thiemann Lift Gate, Trailer Hitch, Steel Wheels, 235/85R16, AC. Check Engine Light On, Dead Batteries, L/S Door Striker Welded. . Showing 220,210 Miles. Location: Warner Robins, GA Serial: 1GTGK24K5SE548761	
<b>Lot #</b>	67	
<b>Qty</b>	1	
<b>Title</b>	JOHN DEERE 2018 BRUSH CUTTER	
<b>Des.</b>	NO TITLE PER STATE REQUIREMENTS. 20ft Width. VIN Tag Removed. Location: Des Moines, IA Serial: N/A	

<b>Lot #</b>	68	
<b>Qty</b>	1	
<b>Title</b>	2009 FORD F750 CAB & CHASSIS	
<b>Des.</b>	THIS UNIT RUNS. Cummins ISB, Automatic, Spring Suspension, 196 WB, Steel Wheels, 295/75R22.5; 11R22.5, Steel Fuel Tank, AC. Showing 389,331 Miles. Location: Houston, TX Serial: 3FRWF75B09V114356	
<b>Lot #</b>	70	
<b>Qty</b>	1	
<b>Title</b>	2010 FORD F150 PICKUP TRUCK	
<b>Des.</b>	THIS UNIT RUNS. 4.6L Triton Gasoline, Automatic, Spring Suspension, 8ft Box, Steel Wheels, 245/70R17, AC, Warning Lights Illuminated. Showing 142,347 Miles. Location: Oklahoma City, OK Serial: 1FTMF1CW1AKE72025	
<b>Lot #</b>	71	
<b>Qty</b>	1	
<b>Title</b>	2006 CHEVROLET 4500 SERVICE TRUCK	
<b>Des.</b>	NON RUNNER. 6.6L Diesel, Automatic, Spring Suspension, 11ft Knapheide Body, Side Storage, Lift Gate, Steel Wheels, 225/70R19.5, AC, Power Mirrors. Showing 154,974 Miles. Location: Bastrop, TX Serial: 1GBE4C1266F405057	
<b>Lot #</b>	72	
<b>Qty</b>	1	
<b>Title</b>	2005 INTERNATIONAL PAYSTAR 5600i 6X4 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. DASH GAUGES MISSING. Cummins ISM, Allison Automatic, Hendrickson Haulmaax Suspension, 20 FA, 46 EA, 212 WB, Steel Wheels, 425/65R22.5; 11R22.5 (Rears Singled Out), 50 Gallon Fuel Tank. Mileage Unavailable. Location: Buckeye, AZ Serial: 1HTXHAHT95J128978	
<b>Lot #</b>	73	
<b>Qty</b>	1	
<b>Title</b>	1999 INTERNATIONAL 4700 CONTAINER DELIVERY TRUCK	
<b>Des.</b>	UNKNOWN RUNNING CONDITION- DEAD BATTERIES. KNOWN ENGINE ISSUES. DT466, Cruise, 4 Speed Allison AT545 Automatic, Spring Suspension, 4.10 Ratio, Steel Wheels, 1R22.5, 50 Gallon Steel Fuel Tank, Power Steering (Leak Noted At Reservoir), AM/FM/CD, Drive Shaft Removed W/ Truck, Rust, Body Damage. Showing 319,347 Miles; 21,002 Hours. Location: Minneapolis, MN Serial: 1HTSCAAM1XH605005	
<b>Lot #</b>	74	
<b>Qty</b>	1	
<b>Title</b>	2003 GMC 1500 EXT CAB PICKUP TRUCK	
<b>Des.</b>	THIS UNIT RUNS. BRAKE PEDAL VERY LOW. BRAKE LIGHT ILLUMINATED. 4.8L Gasoline, Automatic, Spring Suspension, 3.6 FA, 3.686 RA, 155 WB, 8ft Box W/ Liner, Steel Wheels, 245/75R16, Trailer Hitch, AC (Blower Motor Inops), PW, L/Front Fender And Door Damage. Showing 279,153 Miles. Location: Street, MD Serial: 1M1AA13Y31W144343	
<b>Lot #</b>	75	
<b>Qty</b>	1	
<b>Title</b>	1995 SUMMIT AD40 DUMP TRAILER	
<b>Des.</b>	40ft Length, 96in Width, Aluminum Composition, Lift Cylinder, 5 Total Drain Valves, Tarp System, Steel Wheels, 11R22.5. Location: Collinsville, OK Serial: 1S8AD4025S0008594	

<b>Lot #</b>	76	
<b>Qty</b>	1	
<b>Title</b>	2006 VOLVO VNL64T CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. VE D12- 365 HP, Eaton 10 Speed, Bogey Suspension, 13.2 FA, 40 RA, 216 WB, Aluminum/Steel Wheels, 11R22.5; 285/75R22.5, AC. Showing 363,373 Miles. Location: Houston, TX Serial: 4V5NC9GF66N414858	
<b>Lot #</b>	77	
<b>Qty</b>	1	
<b>Title</b>	2000 VE ENTERPRISES FRAC TANK	
<b>Des.</b>	NO TITLE PER STATE REQUIREMENTS. 47ft Length, 102in Width, 26,480 GVWR. Location: Holden, LA Serial: 5AGFT47135S312354	
<b>Lot #</b>	78	
<b>Qty</b>	1	
<b>Title</b>	2003 FORD F350 PICKUP TRUCK	
<b>Des.</b>	THIS UNIT RUNS. 7.3L Turbo Diesel, Automatic, Spring Suspension, 4.4 FA, 6.83 RA, 137 WB, Anthony Lift Gate, Steel Wheels, 265/75R16, AC. Showing 298,178 Miles. Location: Collinsville, OK Serial: 1FTSF30F43EA93979	
<b>Lot #</b>	79	
<b>Qty</b>	1	
<b>Title</b>	2006 CHEVROLET 4500 STAKE BODY TRUCK	
<b>Des.</b>	NON RUNNER. 6.6L V8 Turbo Diesel, Automatic, Spring Suspension, 7 FA, 13.5 RA, 178 WB, 14ft Rawson/Koenig Stake Body, Lift Gate, Steel Wheels, 245/75R19.5, AC, Power Mirrors, Less Keys. Mileage Unavailable. Location: Bastrop, TX Serial: 1GBE4C12X6F406146	
<b>Lot #</b>	80	
<b>Qty</b>	1	
<b>Title</b>	2007 INTERNATIONAL 4200 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. DT466- 215 HP, OD, Cruise, 5 Speed Automatic Automatic, Spring Suspension, Steel Wheels, 11R22.5, 50 Gallon Steel Fuel Tank, Power Steering, AM/FM, Seepage Noted At Engine, Oil Pan And Transmission, Rust, Body Damage. Showing 245,771 Miles; 15,906 Hours. Location: Minneapolis, MN Serial: 1HTMPAFM47H366538	
<b>Lot #</b>	81	
<b>Qty</b>	1	
<b>Title</b>	2002 FORD F550 SERVICE TRUCK	
<b>Des.</b>	THIS UNIT RUNS. 7.3L V8 Turbo Diesel, Automatic, Spring Suspension, 6 FA, 13.5 RA, 165 WB, Auto Crane, 11ft Service Body, R/Outriggers, Side Storage, Steel Wheels, 245/75R19.5, AC, Seat Belts Unbolted, Body Damage. Showing 234,307 Miles. Showing Pelham, AL Serial: 1FDAF56F22ED37556	
<b>Lot #</b>	82	
<b>Qty</b>	1	
<b>Title</b>	1974 BUTLER TANKER TRAILER	
<b>Des.</b>	40ft Length, 96in Width, 6,700 Gallon Capacity, Leaf Suspension, Steel Wheels, 11R22.5, Body Damage Throughout. Location: Des Moines, IA Serial: 3944325	