



## Printable Catalog

<b>Title</b>	AUGUST 12 12:00 CDT	
<b>Description</b>	Closing Times TBD	
<b>Date</b>	Wed, Aug 12, 2020	
<b>Starts at</b>	12:00 PM	
<b>Address</b>	4747 NE 14th St, Des Moines, IA 50313 USA	
<b>Categories</b>		


---

<b>Lot #</b>	1	
<b>Qty</b>	1	
<b>Title</b>	2009 MACK GU813 REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. DRIVE SHAFT REMOVED FOR TOW. Mack MP7, Eaton 8LL, Walking Beam Suspension, 20 FA, 44 RA, 228 WB, 11 Yrd Continental Rear Mixer, 150 Gallon Side Mount Water Tank, Aluminum Fuel Tank, Three Chutes, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC. Showing 96,386 Miles. Location: Concord, NC Serial: 1M2AX13C59M005000	


---

<b>Lot #</b>	3	
<b>Qty</b>	1	
<b>Title</b>	2005 CATERPILLAR 938GII WHEEL LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. FRONT END SEAL BAD. CAT 3126, Powershift 4F/3R, 105in Bucket Width, Steel Wheels, 20.5R25, Cab AC, Rust. Hours Unavailable. Location: Adel, GA Serial: RTB01219	


---




<b>Lot #</b>	4	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Mack AMI-335, Maxitorque, Hendrickson Suspension, 13 FA, 40 RA, 240 WB, 207in Back Cab To End Frame, Double Frame, Dual Aluminum Fuel Tanks, Steel Wheels, 315/80R22.5; 11R22.5, AC, Bent Bumper, Rust. Showing 422,615 Miles; 9,512 Hours. Location: Des Moines, IA Serial: 1M2AG11C46M041064	

---







<b>Lot #</b>	5	
<b>Qty</b>	1	
<b>Title</b>	2002 MACK RD688S ROLLOFF TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. MISSING DRIVE SHAFT. DASH APART. Mack E7-300, Allison Automatic, Hendrickson Suspension, 276 WB, 262in Back Cab To End Frame, Double Frame, Dual Steel Fuel Tank, Pusher Axle, Steel Wheels, 315/80R22.5, PTO, AC, Oil Seepage, Rears Outers Only, Differential Is Missing Piece, Rust. Showing 108,321 Miles; 11,922 Hours. Location: Des Moines, IA Serial: 1M2P267C32M062785	







---

<b>Lot #</b>	6	
<b>Qty</b>	1	
<b>Title</b>	2011 KENWORTH T800 DUMP TRUCK	
<b>Des.</b>	RUNNING CONDITION UNKNOWN. Cummins ISX 485, RTO16908LL, Hendrickson Suspension, 20 FA, 46 RA, 230 WB, 17ft Steel Dump Body, 58in Sides W/ 12in Wood Side Extensions, Air Lift Pusher Axle, 4.10 Ratio, Double Frame, Full Locking Rears, Spreader Pan, End Gate, Electric Roll Tarp, Engine Brake, 110 Gallon Aluminum Fuel Tank, Aluminum Wheels, 425/65R22.5; 11R24.5, Rust. Showing 386,665 Miles; 14,382 Hours. Location: Lee Summit, MO Serial: 1NKDX4TX4BJ277906	

<b>Lot #</b>	8	
<b>Qty</b>	1	
<b>Title</b>	2006 KENWORTH T800 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. ENGINE BLOW BY. CAT C13 ACERT, Eaton Fuller Automatic, Air Ride Suspension, 12 FA, 38 RA, 175 WB, Manual Fifth Wheel, Dual Aluminum Fuel Tanks, Aluminum Wheels, 275/80R22.5; 445/50R22.5, AC, Rust. Showing 734,415 Miles; 19,813 Hours. Location: Des Moines, IA Serial: 1XKDDU9X06J141350	
<b>Lot #</b>	9	
<b>Qty</b>	1	
<b>Title</b>	2012 INTERNATIONAL 7600 VAC TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. International MaxxForce 11, Allison Automatic, Hendrickson Suspension, 20 FA, 46 RA, 278 WB, Vactor 2100 Vac Body, Steel Wheels, 315/80R22.5; 11R22.5, PTO, AC, Rust. Showing 56,766 Miles; 10,599 Hours. Location: Des Moines, IA Serial: 1HTGRSHT1CJ598096	
<b>Lot #</b>	10	
<b>Qty</b>	1	
<b>Title</b>	2006 EAST FRAMELESS END DUMP TRAILER	
<b>Des.</b>	39ft Length, 8ft Width, 64in Sides, Aluminum Composition, Air Ride Suspension, Electric Tarp System, Two Way Gate, Coal Chute, Aluminum Wheels, 11R22.5, Rust. Location: Lee Summit, MO Serial: 1E1F9U28X6RL38216	
<b>Lot #</b>	11	
<b>Qty</b>	1	
<b>Title</b>	2011 CASE SV250 SKID LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. Oil Residue Noted At Engine, Bottom Skid Plate Wet W/ Fluid. Showing 4,319 Hours. Location: Ellenwood, GA Serial: NBM435234	
<b>Lot #</b>	12	
<b>Qty</b>	1	
<b>Title</b>	2011 KENWORTH T800 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. MISSING ENGINE AND TRANSMISSION. NO WHEELS OR TIRES. Hendrickson Suspension, 20 FA, 46 RA, 242 WB, 12,350 Lbs Air Lift Pusher Axle, Double Framed, Aluminum Wheels, 425/65R22.5; 11R24.5, Axle Splines Removed, Cab Worn/Full Of Parts, Rust. Mileage Unavailable. Location: Lee Summit, MO Serial: 1NKDXPTXXBJ292606	
<b>Lot #</b>	13	
<b>Qty</b>	1	
<b>Title</b>	1997 TRAILING TK100FG LOWBOY TRAILER	
<b>Des.</b>	Quad Axle. Unable To Test Lights, Frame Dented, Tires Worn, Various Body Damage/Rust. Location: Lincoln, KS Serial: 1TKJ05340VM038515	
<b>Lot #</b>	14	
<b>Qty</b>	1	
<b>Title</b>	2011 KENWORTH T800 DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. BAD BATTERIES. ENGINE BLOW BY. DRIVE LINE REMOVED. Cummins ISX 485, RTO16908LL, Hendrickson Suspension, 20 FA, 46 RA, 230 WB, 17ft Steel Dump Body, 58in Sides W/ 12in Wood Side Extensions, Air Lift Pusher Axle, 4.10 Ratio, Double Frame, Full Locking Rears, Spreader Pan, End Gate, Electric Roll Tarp, Engine Brake, 110 Gallon Aluminum Fuel Tank, Aluminum Wheels, 425/65R22.5; 11R24.5, Electric Motor For Tarp Removed, ABS Light Illuminated, Rust. Showing 44,099 Miles; 13,537 Hours. Location: Lees Summit, MO Serial: 1NKDX4TX8BJ277908	








<b>Lot #</b>	15	
<b>Qty</b>	1	
<b>Title</b>	1987 INTERNATIONAL 1954 KNUCKLEBOOM TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. International DT466 Diesel, Spicer Double Duty, Spring Suspension, 220 WB, 16ft Steel Flatbed Body, Hiab Knuckle Boom, Outriggers, Under Storage, Spoke Wheels, 295/75R22.5; 11R2.5, PTO, Broken Windshield, No Control Levers For Outriggers, Oil Seepage, Right Rear Outer Tires Only, Body Damage/Rust. Showing 237,251 Miles; 9,290 Hours. Location: Des Moines, IA Serial: 1HTLDTVN2HH523978	
<b>Lot #</b>	16	
<b>Qty</b>	1	
<b>Title</b>	2009 KENWORTH T800 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. CLUTCH IS SOFT, GRINDS GEARS. Cummins ISX 485ST, Eaton Fuller FRO17210C, Air Ride Suspension, 12.35 FA, 34 RA, 196 WB, 120 Gallon Aluminum Fuel Tank, Wet Kit, 3.42 Ratio, Aluminum Wheels, 11R22.5, AC, Dead Batteries, ABS Light Illuminated, Rust. Showing 692,965 Miles; 21,379 Hours. Location: Lee Summit, MO Serial: 1XKDD48X09J243074	
<b>Lot #</b>	17	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CTP713 REAR MIXER	
<b>Des.</b>	NON RUNNER. BAD ENGINE. TURBO OFF WITH TRUCK. HYDRAULIC HOSE DISCONNECTED. MISSING MIXER CONTROLS. DASH APART/MISSING PIECES. Mack MP7, Mack T310MLR, Walking Beam Suspension, 20 FA, 38 RA, 249 WB, 10.5 Yrd McNeilus Rear Mixer, 150 Gallon Cross Mount Water Tank, Aluminum Fuel Tank, Bridge Axle, Three Chutes, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Rust. Mileage Unavailable. Location: Concord, NC Serial: 1M2AT04CX7M006709	
<b>Lot #</b>	18	
<b>Qty</b>	1	
<b>Title</b>	2004 INTERNATIONAL 7400 GARBAGE PACKER	
<b>Des.</b>	CRANKS- WONT START. HYDRAULIC HOSES DISCONNECTED. International DT466E, Automatic, Chalmers Suspension, 16 FA, 40 RA, 230 WB, 25 Yrd McNeilus Rear Loader, Two Can Tippers, L/R Steering, Steel Wheels, 315/80R22.5, PTO, AC, Body Damage/Rust. Showing 191,523 Miles; 18,620 Hours. Approximate Measurements: 33ft Length, 11.5ft Height. Location: Williamston, NC Serial: 1HTWGADT24J032841	
<b>Lot #</b>	19	
<b>Qty</b>	1	
<b>Title</b>	2004 CATERPILLAR 938GII WHEEL LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. CAT 3126, Powershift 4F/3R, Enclosed ROPS, Steel Wheels, 20.5R25, AC, Hour Meter Inoperable, Body Damage/Rust. Hours Unavailable. Location: Adel, GA Serial: CRD00874	
<b>Lot #</b>	20	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	TITLE BRANDED SALVAGE. STARTED ON SITE - NOT ROAD TESTED. NO TRANSMISSION. DRIVE SHAFT REMOVED - IN CAB. Mack AMI-370 ASET, Camelback Suspension, 18 FA, 266 WB, 219in Back Cab To End Frame, Double Frame, 81 Gallon Steel Fuel Tank, Steel Wheels, 295/75R22.5; 285/75R22.5, PTO, AC, Right Rear Outer Wheels Only, Left Front Rear Axle Outer Wheel Only, Warning Lights Active, Rust. Showing 673,001 Miles; 32,462 Hours. Location: Des Moines, IA Serial: 1M2AG11C56M043017	







<b>Lot #</b>	21	
<b>Qty</b>	1	
<b>Title</b>	2002 MACK RD688S ROLLOFF TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. LESS HOOD. LESS DRIVERS SEAT. PTO DID NOT ENGAGE. Mack Reman, Eaton Fuller, Camelback Suspension, 17 FA, 44 RA, 253 WB, 214in Back Cab To End Frame, Double Frame, Dual Steel Fuel Tanks, Steel Wheels, 315/80R22.5, PTO, AC, Warning Lights Active, Rears Inner Wheels, Only, No Battery Box Cover, Flat Tire, Rust. Showing 753,221 Miles; 11,912 Hours. Location: Des Moines, IA Serial: 1M2P267C82M060918	
<b>Lot #</b>	24	
<b>Qty</b>	1	
<b>Title</b>	2000 LBT INC TANKER TRAILER	
<b>Des.</b>	42ft Length, 8ft Width, Aluminum Body, 58,000 Max PayLoad, 9,500 Gallon Capacity, Four Compartment-3,500; 1,000; 2,000; 3,000, Aluminum Wheels, 295/75R22.5. Location: Ankeny, IA Serial: 4J8T04224YT006503	
<b>Lot #</b>	25	
<b>Qty</b>	1	
<b>Title</b>	1999 KENWORTH T800 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. TITLE BRANDED REBUILT TX. CAT C12 430 HP, Engine Brake, Eaton Fuller, Air Ride Suspension, 239 WB, Air Slide Fifth Wheel, Winch Tractor Tail Roll, Dual Aluminum Fuel Tanks, Aluminum Wheels, 11R22.5, AC, Windshield Chipped, Rust. Showing 27,128 Miles. Location: Des Moines, IA Serial: 1NKDLU9X1XR794365	
<b>Lot #</b>	26	
<b>Qty</b>	1	
<b>Title</b>	2011 KENWORTH T800 DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. AIR LEAK IN CAB. COULD NOT GET BED TO RAISE. PUSHER AXLE WOULD NOT GO DOWN. Cummins ISX 485 HP, RTO16908LL, Hendrickson Suspension, 20 FA, 46 RA, 230 WB, 17ft Godwin Steel Dump Body, 58in Sides W/ 12in Wood Side Extensions, 20,000 Lbs Air Lift Pusher Axle, 4.10 Ratio, Double Frame, Full Locking Rears, Spreader Pan, End Gate, Electric Roll Tarp, Engine Brake, 110 Gallon Aluminum Fuel Tank, Aluminum Wheels, 425/65R22.5; 11R24.5, Missing Oil Fill Cap, Tarp Did Not Roll, Rust. Showing 305,111 Miles. Location: Lee Summit, MO Serial: 1NKDX4TX8BJ277925	
<b>Lot #</b>	27	
<b>Qty</b>	1	
<b>Title</b>	2006 EAST FRAMELESS END DUMP TRAILER	
<b>Des.</b>	39ft Length, 8ft Width, 64in Sides, Aluminum Composition, Air Ride Suspension, Electric Tarp System, Two Way Gate, Coal Chute, Aluminum Wheels, 11R22.5, Rust. Location: Lee Summit, MO Serial: 1E1F9U2816RL38217	
<b>Lot #</b>	28	
<b>Qty</b>	1	
<b>Title</b>	2004 STERLING LT9500 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. MISSING PARTS. DOOR SWAP CHECK FRAME FOR VIN. PARTS IN CAB. CAT C13, Automatic, Hendrickson Suspension, 20 FA, 46 RA, 250 WB, 11,020 Lbs Air Lift Pusher Axle W/ Steel Wheels 255/70R22.5, 13,200 Lbs Bridge Axle W/ Steel Wheels 11R22.5, 150 Gallon Cross Mount Water Tank, 70 Gallon Aluminum Fuel Tank, Aluminum Wheels, 425/65R22.5, Rust. Mileage Unavailable. Location: Edwardsville, KS Serial: 2FZMAZDE94AN39206	

<b>Lot #</b>	29	
<b>Qty</b>	1	
<b>Title</b>	2012 INTERNATIONAL 7600 VAC TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. International Maxxforce Diesel, Automatic, Hendrickson Suspension, 10,432 FA, 46 RA, 279 WB, Vactor 2100 Vac Body, Steel Wheels, 315/80R22.5; 11R22.5, PTO, AC, Rust. Showing 72,741 Miles; 8,603 Hours. Location: Des Moines, IA Serial: 1HTGRSHT8CJ598094	
<b>Lot #</b>	30	
<b>Qty</b>	1	
<b>Title</b>	1999 MACK MS 300P KNUCKLEBOOM TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. HAVE TO MANUALLY SHUT ENGINE OFF. INPUT SHAFT IN TRANSMISSION BROKEN - UNIT WON'T MOVE. Renault 6.2L Inline 6, 6 Speed Manual, Spring Suspension, 5.44 FA, 9.53 RA, 216 WB, Effer 16000 Knuckleboom, 26ft Flatbed, 75 Gallon Steel Fuel Tank, Steel Wheels, 11R22.5, PTO, AC, Rust. Showing 109,663 Miles. Location: Greenville, OH Serial: VG6M118B4XB303688	
<b>Lot #</b>	31	
<b>Qty</b>	1	
<b>Title</b>	2000 INTERNATIONAL F2674 CRANE TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. International DT530E 330 HP Diesel, Eaton Fuller 8LL, Hendrickson Suspension, 20 FA, 40 RA, 250 WB, Pioneer Series 3000 Boom, 22 Ton Capacity, 20ft Knapheide Flatbed, F/ Outriggers, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Loud Alarm Sounding - Crane Would Only Operate In Bypass Mode, Rust. Showing 43,837 Miles; 7,683 Hours. Location: Kansas City, KS Serial: 1HTGLADT6YH227791	
<b>Lot #</b>	32	
<b>Qty</b>	1	
<b>Title</b>	2008 ADVANCE 6250 SWEEPER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. BAD RADIATOR. Kubota Engine, Tear In Seat, Missing Tire, Body Damage/Rust. Hours Unavailable. Location: San Bernardino, CA Serial: 1954027	
<b>Lot #</b>	33	
<b>Qty</b>	1	
<b>Title</b>	2005 MACK CXN613 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE. Mack AC-460P, Eaton Automatic, Air Suspension, 12.35 FA, 40 RA, 182 WB, Air Slide 5th Wheel, Aluminum Wheels, 11R22.5, AC, Warning Light Illuminated. Showing 589,494 Miles; 21,382 Hours. Location Des Moines, IA Serial: 1M1AK07YX5N003881	
<b>Lot #</b>	34	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CTP713 REAR MIXER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Mack MP7, T310M, 20 FA, 38 RA, 243 WB, 10.5 Yrd McNeilus Rear Mixer, 150 Gallon Cross Mount Water Tank, Aluminum Fuel Tank, Bridge Axle, Three Chutes, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Seat Torn. Showing 118,459 Miles. Location: Summerville, SC Serial: 1M2AT04C47M006737	








<b>Lot #</b>	35	
<b>Qty</b>	1	
<b>Title</b>	2010 AUTOCAR WX64 GARBAGE PACKER	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. TAIL GATE LOCKS BROKEN. Cummins ISM-350, Automatic, Hendrickson Suspension, 20 FA, 46 RA, 186 WB, 40 Yrd EZ Pack Front Loader, Tag Axle, Steel Wheels, 315/80R22.5 (R/Front Flat), PTO, AC, Backup Camera, Dead Batteries, Rust. Odometer Noted As Incorrect: Showing 26,352 Miles; 32,148 Hours. Approximate Dimensions: 31.75ft Length, 12.5ft Height. Location: New Castle, DE Serial: 5VCACLKF3AH211102	
<b>Lot #</b>	36	
<b>Qty</b>	1	
<b>Title</b>	2003 CATERPILLAR 938G WHEEL LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED W/JUMP, FULL OPERATIONS NOT TESTED. CAT 3126DITA Engine, Powershift 4F/3R, 3.16 YRD3 Bucket Capacity, 106.56 Bucket Width, EROPS, 20.5R25 Tires- Flat, Body Damage/Rust. Hours Unavailable. Location: Adel, GA Serial: CRD00408	
<b>Lot #</b>	37	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. NO TRANSMISSION. NO DASH. Mack AMI-370, Camelback Suspension, 18 FA, 46 RA, 269 WB, 220in Back Cab To End Frame, Double Frame, Steel Fuel Tank, Steel Wheels, 315/80R22.5; 12R22.5, AC, Rears Outer Wheels Only, Oil Seepage, Body Damage/Rust. Mileage Unavailable. Location: Des Moines, IA Serial: 1M2AG11C56M043096	
<b>Lot #</b>	38	
<b>Qty</b>	1	
<b>Title</b>	2000 LBT INC TANKER TRAILER	
<b>Des.</b>	42ft Length, 8ft Width, Aluminum Body, 58,000 Max PayLoad, Four Compartment, 9,500 Gallon Capacity, Aluminum Wheels, 295/75R22.5. Location: Ankeny, IA Serial: 4J8T04220YT006501	
<b>Lot #</b>	39	
<b>Qty</b>	1	
<b>Title</b>	2007 KENWORTH T800 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. BAD BATTERIES. Cummins ISX 475ST, FRO17210C, Air Ride Suspension, 12 FA, 34 RA, 196 WB, Air Slide Fifth Wheel, Wet Kit, 150 Gallon Aluminum Fuel Tank, Aluminum Wheels, 11R22.5, AC, Rust Hole In Exhaust, Rust. Showing 672,138 Miles; 21,192 Hours. Location: Lee Summit, MO Serial: 1XKDD48X27J205651	
<b>Lot #</b>	40	
<b>Qty</b>	1	
<b>Title</b>	2002 KENWORTH T800 ROLLOFF TRUCK	
<b>Des.</b>	NON RUNNER. CAT C15, Eaton Fuller 9 Speed, Air Suspension, 270 WB, 3.90 Ratio, Engine Brake, 80 Gallon Fuel Tank, Wet Kit, Aluminum/Steel Wheels, 315/80R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Mileage Unavailable. Location: 1NKDLB9X92J897691	
<b>Lot #</b>	41	
<b>Qty</b>	1	
<b>Title</b>	2005 HINO 165 VAN BODY TRUCK	
<b>Des.</b>	STARTED ON SITE, NOT ROAD TESTED. KNOWN TRANSMISSION ISSUE, SHIFTS HARD. BAD BATTERIES. Hino J05D-TA, Automatic, Spring Suspension, 182 WB, 14.5ft Morgan Body, Waltco Lift Gate,- 1,600 Lb. Capacity, Steel Wheels, 225/70R19.5, AC, Warning Lights Illuminated, Body Damage/Rust. Showing 128,651 Miles. Truck Total Length- Approximately 24ft. Location: Kansas City, MO Serial: JHBNB6JK751S10137	

















<b>Lot #</b>	42	
<b>Qty</b>	1	
<b>Title</b>	1999 HEIL OLYMPIAN DUMP TRAILER	
<b>Des.</b>	Unable To Test Lights Due To No Power, Various Body Damage/Rust. Location: Salina, KS Serial: 1H9AACEG6X2270317	
<b>Lot #</b>	43	
<b>Qty</b>	1	
<b>Title</b>	2005 STERLING LT9500 DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. CAT C13, Roadrunner 8 Speed, 18 FA, 40 RA, 249 WB, 17ft Steel Dump Truck, Tarp System, 80 Gallon Aluminum Fuel Tank, Pusher Axle, Aluminum Wheels, 425/65R22.5; 11R22.5; 315/75R17.5, PTO, AC, Body Damage/Rust. Showing 370,852 Miles; 12,847 Hours. Location: Des Moines, IA Serial: 2FZHAZDE45AN88249	
<b>Lot #</b>	44	
<b>Qty</b>	1	
<b>Title</b>	2000 TRACKMOBILE 75TM RAIL EQUIPMENT	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. NON RUNNER. ENGINE TURNS OVER BUT DOESNT START. Horn Inop, Top Beacon Lamp Is Inop, Lift Cylinders Leaking, Interior Worn, Body Damage/Rust. Showing 498 Hours. Location: Coldwater, MI Serial: 685562J	
<b>Lot #</b>	45	
<b>Qty</b>	1	
<b>Title</b>	2007 INTERNATIONAL 8600 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Cummins ISM, Eaton 10 Speed, Air Ride Suspension, 12 FA, 40 RA, 184 WB, Air Slide Fifth Wheel, Dual Aluminum Fuel Tanks, Steel Wheels, 295/75R22.5, AC, Rust. Showing 361,224 Miles; 13,228 Hours. Approximate Dimensions: 289 Total Length, 126 Total Height. Location: Concord, NC Serial: 1HSHXAHR47J431797	
<b>Lot #</b>	46	
<b>Qty</b>	1	
<b>Title</b>	2007 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. UNIT CRANKS THEN DIES. NO OIL PRESSURE. ALL LINES CUT ON SHIFTER. Mack AMI 12.0L, 10 Speed Manual, Mack Suspension, 29ft Body Length, Double Frame, Dual Aluminum Fuel Tanks, Steel Wheels, 315/80R22.5, Less AC, Body Damage/Rust. Mileage Unavailable. Location: Luling, TX Serial: 1M2AG11C57M051099	
<b>Lot #</b>	47	
<b>Qty</b>	1	
<b>Title</b>	2004 CATERPILLAR TH103 TELEHANDLER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED/RAN BRIEFLY. KNOWN ENGINE AND TRANS ISSUES. HYDRAULIC LEAKS NOTED. CAT 3054 T- 105 HP, 4F/3R, 10,000 Lb. Capacity, 44ft Max Height, 28.8ft Max Forward Reach. Showing 6,083.2 Hours. Location: San Bernardino, CA Serial: 3PN01153	
<b>Lot #</b>	48	
<b>Qty</b>	1	
<b>Title</b>	1996 GMC C3500 FLATBED TRUCK	
<b>Des.</b>	NON RUNNER. RED TAGGED. BOTH SEATS MISSING. Holes In Frame Rail, Tires Worn, Right Steer Tire Flat, Interior Worn, Various Body Damage/Rust. Mileage Unavailable. Location: Columbus, OH Serial: 1GDKC34J5TJ516207	

Lot #	49	
Qty	1	
Title	2006 STERLING LT9500 REAR MIXER	
Des.	NON RUNNER. BAD DRUM. Mercedes Benz OM 460, Allison Automatic, Hendrickson Suspension, 20 FA, 46 RA, 250 WB, 11 YRD. MTM Bridgmaster Mixer, 150 Gallon Cross Mount Water Tank, 70 Gallon Aluminum Fuel Tank, 11,020 Lb. Air Lift Pusher Axle W/ Steel Wheels 255/70R22.5, Bridge Axle With Steel Wheels 11R22.5, Full Axle Lock, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Hose Loose On L/Engine Side, Body Damage/Rust. Showing 39,477 Miles; 18,376 Hours. Location: Edwardsville, KS Serial: 2FZMAZCVX6AW69659	
Lot #	50	
Qty	1	
Title	2008 ADVANCE 6340D SWEEPER	
Des.	NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. Kubota, Tear In Seat, Poor Condition, Body Damage/Rust. Hours Unavailable. Location: San Bernardino, CA Serial: 2058274	
Lot #	52	
Qty	1	
Title	2001 MACK RD688S CAB & CHASSIS	
Des.	STARTED ON SITE - NOT ROAD TESTED. Mack E7-350 HP, Eaton Fuller 8 Speed, Camelback Suspension, 272 WB, 229in Back Cab To End Frame, Double Frame, Dual Steel Fuel Tanks, Steel Wheels, 295/75R22.5; 11R22.5, PTO, AC, Right Rear Outer Wheels Only, Flat Tires, Body Damage/Rust. Showing 584,128 Miles. Location: Des Moines, IA Serial: 1M2P267C31M056208	
Lot #	53	
Qty	1	
Title	2007 KENWORTH T800 DAY CAB TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. PRODUCT BLOWER WILL BE REMOVED PRIOR TO SALE. Cummins ISX 475ST, FRO17210C, Air Ride Suspension, 12 FA, 34 RA, 196 WB, Air Slide Fifth Wheel, 3.55 Ratio, Aluminum Fuel Tank, Aluminum Wheels, 11R22.5; 455/55R22.5, PTO, AC, Drivers Door Panel Apart, Door Doesn't Shut Completely, Dead Batteries, Rust. Showing 928,570 Miles; 2,971 Hours. Location: Lee Summit, MO Serial: 1XKDD48X87J205654	
Lot #	54	
Qty	1	
Title	2007 CATERPILLAR 980H WHEEL LOADER	
Des.	NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. Multiple Minor Hydraulic Leaks Noted, AC Condenser Damaged, Surface Cracks At Bucket - See Photos, Intake Pipe Damaged At Top Of Engine, 12V Power Outlet Missing Socket On Dash, Oil Leaks, Interior Worn, Various Body Damage/Rust. Showing 56,374 Hours. Location: Rialto, CA Serial: JMS01952	
Lot #	55	
Qty	1	
Title	1999 KENWORTH T800 DUMP TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. CAT C12 295 HP, Eaton Fuller 8LL Speed, Chalmers Suspension, 17.5ft Steel Dump Body, 120 Gallon Aluminum Fuel Tank, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Pintle Hitch, Body Damage/Rust. Mileage Unavailable. Location: Des Moines, IA Serial: 1NKDLU0X1XR816717	

















<b>Lot #</b>	56	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. TURNS SLOWLY. Mack AMI 12.0L, 8 Speed Manual, Mack Suspension, 31.5ft Body Length, Double Frame, 130 Gallon Steel Fuel Tank, Steel Wheels, 315/80R22.5, Less AC, Body Damage/Rust. Mileage Unavailable. Location: Luling, TX Serial: 1M2AG11C66M043107	
<b>Lot #</b>	58	
<b>Qty</b>	1	
<b>Title</b>	1977 HEIL TANKER TRAILER	
<b>Des.</b>	Right Rear Inner Wheel Seal Leaking, Hole Worn Through Tube Holder, Various Body Damage/Rust. Location: Indianapolis, IN Serial: 928790	
<b>Lot #</b>	59	
<b>Qty</b>	1	
<b>Title</b>	2001 PETERBILT 385 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE, LESS KEYS. CAT C13, Eaton 8 Speed, Air Track Suspension, 12 FA, 40 RA, Fifth Wheel, Aluminum Fuel Tank, Engine Brake, Wet Kit, Aluminum Wheels, 11R22.5, PTO, AC, Rust. Showing 715,071 Miles. Location: San Bernardino, CA Serial: 1XPGDU9XX1D558327	
<b>Lot #</b>	60	
<b>Qty</b>	1	
<b>Title</b>	1989 CATERPILLAR 16G MOTOR GRADER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. NON RUNNER. Unable To Access Engine Bay, Various Minor Hydraulic Leaks, Interior Worn, Various Body Damage/Rust. Hours Unavailable. Location: Miami, FL Serial: 93U02779	
<b>Lot #</b>	61	
<b>Qty</b>	1	
<b>Title</b>	1999 GROVE MZ66DXT AERIAL LIFT	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED/RAN ROUGH. 60 HP, 15x19.5 Tires, Rust. Showing 3,379.4 Hours. Location: San Bernardino, CA Serial: 250865	
<b>Lot #</b>	62	
<b>Qty</b>	1	
<b>Title</b>	2001 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE W/ STARTING FLUID - FULL OPERATIONS NOT TESTED. Mack E7-350, Eaton Fuller 8 Speed, Camelback Suspension, 275 WB, 223in Back Cab To End Frame, Double Frame, Dual Steel Fuel Tanks, Steel Wheels, 295/75R22.5; 11R22.5, PTO, AC, Right Rear Outer Tires Only, Body Damage/Rust. Showing 19,087 Miles; 21,212 Hours. Location: Des Moines, IA Serial: 1M2P267C11M056207	
<b>Lot #</b>	63	
<b>Qty</b>	1	
<b>Title</b>	1994 KANN ROLLOFF TRAILER	
<b>Des.</b>	BRAKES LOCKED UP, WHEELS WILL NOT ROLL. MISSING TIRE AT RIGHT REAR. 20ft Length, 93in Width, Steel Composition, Spring Suspension, Steel Wheels, 255/70R22.5, F/R Fenders, Winches, S Cams Rusted, Various Body Damage/Rust. Location: Mora, MN Serial: 1K9SP2439RK007865	

<b>Lot #</b>	65	
<b>Qty</b>	1	
<b>Title</b>	2007 NAVIGATOR RT5500 FORKLIFT	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED ON SITE - FULL OPERATIONS NOT TESTED. LESS KEYS. Kubota 4 Cyl Diesel, Automatic, Open ROPS, 8.5ft Height, Four 48x2in Forks, Two Masts, Steel Wheels, 31x15.50-15, Flat Tire, Rust. Showing 2,143 Hours. Location: Pelham, AL Serial: 11066S1311885	
<b>Lot #</b>	66	
<b>Qty</b>	1	
<b>Title</b>	2011 KENWORTH T800 DAY CAB TRUCK	
<b>Des.</b>	UNKNOWN RUNNING CONDITION. UNIT WAS WRECKED - HOOD AND BUMPER DAMAGE. AIR LINES DISCONNECTED IN DASH. AIR LINES LOOSE UNDER HOOD. DASH LOOSE. Cummins ISX 485ST, FRO17210C, Air Ride Suspension, 12.35 FA, 34 RA, 196 WB, Air Slide Fifth Wheel, Wet Kit, 3.42 Ratio, 110 Aluminum Fuel Tank, Aluminum Wheels, 11R22.5; 445/55R22.5, Rear Axle Spline Removed, Less Keys, Rust. Mileage Unavailable. Location: Lee Summit, MO Serial: 1XKDD48X9BJ277939	
<b>Lot #</b>	67	
<b>Qty</b>	1	
<b>Title</b>	2012 FORD F250 EXT CAB 4X4 PICKUP TRUCK	
<b>Des.</b>	NON RUNNER. ENGINE TURNS OVER BUT DOESN'T START. Ford 6.2L Gas, Automatic, Spring Suspension, 141 WB, 6.75ft Box W/ Liner, Storage Box, Steel Wheels, 285/70R17, AC, PW, PL, PM, Body Damage/Rust. Showing 186,571 Miles. Location: Des Moines, IA Serial: 1FT7X2B66CEC15347	
<b>Lot #</b>	68	
<b>Qty</b>	1	
<b>Title</b>	2003 MACK CV713 DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Oil Seepage At Oil Pan, Electrical Warning Light Illuminated, Interior Worn, Body Damage/Rust. Showing 641,929 Miles; 26,958 Hours. Location: Columbus, OH Serial: 1M2AG10C93M008168	
<b>Lot #</b>	69	
<b>Qty</b>	1	
<b>Title</b>	2000 CHEVROLET 3500 SERVICE TRUCK	
<b>Des.</b>	NON RUNNER. HEAD OFF ENGINE - ENGINE PARTS IN BED. 5.7L Gas, Automatic, Spring Suspension, Steel Wheels, 245/75R16, AC, Body Damage/Rust. Showing 108,526 Miles. Location: San Bernardino, CA Serial: 1GBGC34R7YR228864	
<b>Lot #</b>	70	
<b>Qty</b>	1	
<b>Title</b>	2006 PETERBILT 357 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. LESS KEYS. CAT C9 (Engine Oil Leaks Noted, Oil Fill Cap Missing), Automatic, Hendrickson Suspension, 220 WB, 214in Cab To Frame End, Aluminum Wheels, 445/65R22.5; 11R22.5, Aluminum Fuel Tank, AC, Right Door Latch Broken, Missing Air Intake Hose, Frame Rust. Showing 201,788 Miles; 25,090 Hours. Location: Tampa, FL Serial: 1NPALFOX36N633771	
<b>Lot #</b>	71	
<b>Qty</b>	1	
<b>Title</b>	2009 KENWORTH T800 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. DRIVE CAM AND EQUIPMENT WILL BE REMOVED PRIOR TO SALE. Cummins ISX 485ST 485 HP, Eaton Fuller FRO17210C, Air Ride Suspension, 12.35 FA, 34 RA, 196 WB, Air Slide Fifth Wheel, Wet Kit, 3.42 Ratio, Aluminum Fuel Tank, Aluminum Wheels, 445/55R22.5, AC, Rock Chips In Windshield, Rust. Showing 725,586 Miles; 22,676 Hours. Location: Lee Summit, MO Serial: 1XKDD48X99J257667	








<b>Lot #</b>	72	
<b>Qty</b>	1	
<b>Title</b>	1978 KARI COOL TANKER TRAILER	
<b>Des.</b>	Stainless Steel Seams Are Separated On Left Side Of Tank, Various Body Damage/Rust. Location: Indianapolis, IN Serial: CTK7291	
<b>Lot #</b>	73	
<b>Qty</b>	1	
<b>Title</b>	1992 JLG SKYLIFT AERIAL LIFT	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. NON RUNNER. Ford 4 Cylinder Gas, 60ft Lift, 500lb Capacity, 14R17.5 Tires, Basket Damage, Rust. Location: San Bernardino, CA Serial: 12784	
<b>Lot #</b>	75	
<b>Qty</b>	1	
<b>Title</b>	2005 VOLVO L90E WHEEL LOADER	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. NON RUNNER. IGNITION SWITCH DISASSEMBLED. Oil Covering Right Side Of Engine Block From Top To Bottom, Windshield Not Properly Sealed, Hydraulic Oil Residue Noted At Various Hydraulic Connections, Heavy Corrosion/Rust On Several Components, Various Body Damage/Rust. Hours Unavailable. Location: Miami, FL Serial: L90EV66886	
<b>Lot #</b>	76	
<b>Qty</b>	1	
<b>Title</b>	2017 MACK CXU613 DAY CAB TRUCK	
<b>Des.</b>	NON RUNNER. BODY AND FRAME HEAVILY DAMAGED. ENGINE AND DASH MISSING COMPONENTS. Mack MP8-445, Automatic, Air Ride Suspension, 12 FA, 40 RA, 202 WB, Stationary Fifth Wheel, 125 Gallon Aluminum Fuel Tank, Aluminum Wheels, 295/75R22.5, AC, Left Front Tire Missing, Rust. Mileage Unavailable. Location: Des Moines, IA Serial: 1M1AW07Y0HM082881	
<b>Lot #</b>	77	
<b>Qty</b>	1	
<b>Title</b>	2010 FORD F350 PICKUP TRUCK	
<b>Des.</b>	NON RUNNER. LESS BOX. BRAKES INOP. 6.4L Diesel, 4 Speed Automatic, 4.7 FA, 6.693 RA, Steel Wheels, 275/65R18, Body Damage/Rust. Mileage Unavailable.	
<b>Lot #</b>	78	
<b>Qty</b>	1	
<b>Title</b>	1996 RANCO 10038477 BELLY DUMP TRAILER	
<b>Des.</b>	AIR LINES LEAK. 42.5ft Length, 102in Height, Steel Composition, Spring Suspension, 22 Cubic Yrd Capacity, Clam Gates, Roll Tarp, F/R Fenders, Tarp System, Wood Side Boards, Aluminum Wheels, 425/65R22.5, Tarp Partially Functional, Tires Worn, Various Body Damage/Rust. Location: San Bernardino, CA Serial: 1R9BSF205TL008919	
<b>Lot #</b>	79	
<b>Qty</b>	1	
<b>Title</b>	1997 FORD F350 XL SERVICE TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. PARKING BRAKE WILL NOT HOLD. Ford 5.8L Gas, 5 Speed Manual, Spring Suspension, 4 FA, 8.25 RA, 161 WB, 11ft Adkins Service Body, Body Storage, Steel Wheels, 215/85R16, AC, Dead Batteries, Seat Torn, Rust. Showing 127,574 Miles. Location: Chilhowie, VA Serial: 3FEKF37H0VMA65768	








<b>Lot #</b>	80	
<b>Qty</b>	1	
<b>Title</b>	2004 FREIGHTLINER FL112 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Mercedes Benz MBE 4000, Automatic, Hendrickson Suspension, 20 FA, 46 RA, 27.75ft Length, Double Frame, 80 Gallon Aluminum Fuel Tank, Steel Wheels, 315/80R22.5; 295/75R22.5, PTO, AC, Needs Batteries, Four Tires/Rims Missing, Instrument Cluster Inop, Interior Worn, Various Body Damage/Rust. Mileage Unavailable. Location: Westwego, LA Serial: 1FVHC5CVX4HN14190	
<b>Lot #</b>	81	
<b>Qty</b>	1	
<b>Title</b>	1975 GROVE RT620 CRANE	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. STARTED ON SITE, KNOWN BRAKE ISSUE. FULL OPERATIONS NOT TESTED. Cummins 8 Cylinder Diesel, Fuller Powershift 6 F/R, 28ft Max Working Height, 40,000 Lb. Capacity, Rust. Showing 3,533 Hours. Location: Sacramento, CA Serial: 34770	
<b>Lot #</b>	82	
<b>Qty</b>	1	
<b>Title</b>	1999 STERLING LT9500 DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. TRANSMISSION PROBLEMS. NO LEFT DOOR GLASS. HOLES IN BODY. AIR LEAK AT TRANSMISSION SHIFTER HOSE. CAT 3306, Eaton 10 Speed, Hendrickson Suspension, 14 FA, 40 RA, 222 WB, 18ft Steel Phase 2 Dump Box, Aluminum Fuel Tank, Pusher Axle, Steel Wheels, 315/80R22.5; 11R22.5, PTO, AC, Interior Worn, Rust. Showing 368,510 Miles. Location: Chillhowie, VA Serial: 2FZXKWYB9XAB44278	
<b>Lot #</b>	83	
<b>Qty</b>	1	
<b>Title</b>	2004 STI 6000 SERVICE BODY	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. SMC 6000 Crane; SN: 1836 6, R/ Outriggers, Body Storage, Rust. Location: Des Moines, IA Serial: 1734	
<b>Lot #</b>	84	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CHN613 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. Oil Residue Build Up Noted At Oil Pan Gasket Line, Active Fault Code - See Report, Coolant Overflow Reservoir Low On Coolant, Wet/Dirty Oil On PTO Unit, Driver Side Fuel Tank Missing Cap, Rear Reverse Light Missing, Power Mirror Switch Inop, AC Inop/Missing Control Knob, Interior Worn, Various Body Damage/Rust. Showing 389,096 Miles; 25,148 Hours. Location: Kuna, ID Serial: 1M1AJ06YX6N004938	
<b>Lot #</b>	85	
<b>Qty</b>	1	
<b>Title</b>	1988 FRUEHAUF FLATBED TRAILER	
<b>Des.</b>	FRAME CRACKED. VIN TAG NOT LOCATED ON UNIT. 42ft Length, 96in Width, Steel Wheels, 11R22.5. Location: Lakeland, FL Serial: 1H5P04226JM060101	
<b>Lot #</b>	86	
<b>Qty</b>	1	
<b>Title</b>	ROADRUNNER 5 X 12 DOUBLE DECK SCREEN	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. SERIAL TAG NOT LOCATED. Location: Buckeye, AZ Serial: 9602260	





<b>Lot #</b>	87	
<b>Qty</b>	1	
<b>Title</b>	2002 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. STEERING DIFFICULT TO TURN. Mack EM7-300, Allison Automatic, Camelback Suspension, 235 WB, 195in Back Cab To End Frame, Double Frame, Dual Steel Fuel Tanks, Steel Wheels, 315/80R22.5; 11R22.5, Truck Roof Caved In - See Photos, Warning Lights Active, Chip In Windshield, No Heater Controls, Body Damage/Rust. Showing 408,949 Miles; 33,956 Hours. Location: Des Moines, IA Serial: 1M2P264C22M033802	
<b>Lot #</b>	88	
<b>Qty</b>	1	
<b>Title</b>	2007 FORD F150 STX 4X4 PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. DO NOT DRIVE. BAD TRANSMISSION, NO REVERSE. VERY HARD POWER STEERING. Ford 4.6L Gas, Automatic, Spring Suspension, 3.4 FA, 3.5 RA, 126 WB, 6.5ft Box W/ Liner, Aluminum Wheels, 265/70R17, AC, PW, PL, PM, Oil Leaks, Check Engine Light Illuminated, Blower Motor Inop, Rust. Showing 300,403 Miles. Location: Concord, NC Serial: 1FTRF14W57KB62649	
<b>Lot #</b>	89	
<b>Qty</b>	1	
<b>Title</b>	2009 KENWORTH T800 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. BAD BATTERIES. Cummins ISX 485ST, FRO17210C, Air Ride Suspension, 12.35 FA, 34 RA, 196 WB, 3.42 Ratio, Engine Brake, Wet Kit, 120 Gallon Aluminum Fuel Tank, Aluminum Wheels, 11R22.5; 455/55R22.5, AC, Rust. Showing 670,281 Miles; 19,599 Hours. Location: Lee Summit, MO Serial: 1XKDD48X99J257670	
<b>Lot #</b>	90	
<b>Qty</b>	1	
<b>Title</b>	2007 FREIGHTLINER M2112 ROLLOFF TRUCK	
<b>Des.</b>	NON RUNNER. ENGINE BLOWN. Mercedes Benz MBE 4000, Eaton 10 Speed, Hendrickson Haulmaax Suspension, 18 FA, 46 RA, 254 WB, 60,000 Lbs Galbreath Roll Off Body, Engine Brake, 70 Gallon Aluminum Fuel Tank, Double Frame, Steel Wheels, 315/80R22.5, PTO, AC, Body Damage/Rust. Mileage Unavailable. Location: Bardstown, KY Serial: 1FVHC5CV87HZ21882	
<b>Lot #</b>	91	
<b>Qty</b>	1	
<b>Title</b>	COTTA ENGINES	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. OPERATION UNKNOWN. Cummins QSK19 Industrial Diesel, Cotta Transmission. Location: Des Moines, IA Serial: 185025	
<b>Lot #</b>	92	
<b>Qty</b>	1	
<b>Title</b>	1980 GREAT DANE DROP DECK TRAILER	
<b>Des.</b>	40ft Length, 30ft Lower Deck, 10ft Upper Deck, 96in Width, Wood Decking, 9 Ratchet Straps, Spoke Wheels, 10R15, Deck Heavily Weathered, Rust. Location: Lakeland, FL Serial: AM006401	
<b>Lot #</b>	93	
<b>Qty</b>	1	
<b>Title</b>	1978 KARI COOL CTK TANKER TRAILER	
<b>Des.</b>	ABS Lamp Needs Replaced - Held On W/ Zip Tie, Right Side Tank Cracked In Stainless Steel, Various Body Damage/Rust. Location: Indianapolis, IN Serial: CTK6952	

<b>Lot #</b>	94	
<b>Qty</b>	1	
<b>Title</b>	2000 MACK CH613 DAY CAB TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. AIR LEAK UNDER HOOD. Several Lights Inop -See Report, Less Triangles, Less Fire Extinguisher, Missing Washer Fluid Reservoir Cap, Power Mirrors Inop/Damaged, Dash Missing Components/Damaged, No Passenger Side Steps, Shock Leaking, Rear Differential Leaking, Seat Belts Missing/Inop, Wheel Seal Leaking, Interior Worn, Various Body Damage/Rust - See Report. Showing 887,925 Miles; 49,494 Hours. Location: Albertville, AL Serial: 1M1AA13Y0YW116719	
<b>Lot #</b>	96	
<b>Qty</b>	1	
<b>Title</b>	1998 FORD LT8513 DUMP TRUCK	
<b>Des.</b>	NON RUNNER. ENGINE MISSING VARIOUS PARTS. OIL DIP STICK BROKEN OFF. NO COOLANT. DASH APART. Oil Leak Noted At Oil Pan, Rear Seal, And Bottom Of Block, Coolant Cap Missing, Oil Residue On Front Drive Axle, Muffler Removed, Interior Torn Apart, Windshield Chipped, Left Rear Inner Wheel Seal Leaking, Dead Batteries, Interior Worn, Various Body Damage/Rust. Showing 345,087 Miles. Location: Hutchinson, KS Serial: 1FDZS86F7WVA05554	
<b>Lot #</b>	97	
<b>Qty</b>	1	
<b>Title</b>	2003 FORD F250 XL PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE W/ A JUMP - NOT ROAD TESTED. UNIT DOES NOT STAY RUNNING WHEN BOOST REMOVED. DASH INOP. Ford Power Stroke 6.0L Diesel, Automatic, Spring Suspension, 4.25 FA, 6.084 RA, 137 WB, 8ft Box W/ Liner, Steel Wheels, 235/70R16, AC, Dead Batteries, Several Warning Lights Active, Various Body Damage/Rust. Mileage Unavailable. Location: Des Moines, IA Serial: 1FTNF20P93EB66070	
<b>Lot #</b>	98	
<b>Qty</b>	1	
<b>Title</b>	1996 RANCO BELLY DUMP TRAILER	
<b>Des.</b>	44.75ft Length, 8ft Width, 102in Height, Steel Composition, Spring Suspension, 22 Cubic Yrd Capacity, Clam Gates, Roll Tarp, F/R Fenders, Tarp System, Steel Floor, Wood Side Boards, Aluminum Wheels, 425/65R22.5, Tires Worn, Various Body Damage/Rust. Location: San Bernardino, CA Serial: 1R9BSF209TL008924	
<b>Lot #</b>	99	
<b>Qty</b>	1	
<b>Title</b>	2006 VOLVO VNL64T DAY CAB TRUCK	
<b>Des.</b>	NON RUNNER. BATTERY/ELECTRICAL ISSUES. Heavy Oil Build Up Along Sides Of Engine And Near Fittings On Side Of Pan, Windshield Chipped/Cracked, Doghouse Cracked, Left Fog Light Missing, Tires Worn, Front Brake Linings Worn, Various Body Damage/Rust. Mileage Unavailable. Location: Butler, KY Serial: 4V4NC9GF06N414875	
<b>Lot #</b>	100	
<b>Qty</b>	1	
<b>Title</b>	1995 FORD F350 SERVICE TRUCK	
<b>Des.</b>	NON RUNNER. 5.8L V8 Gas, Manual, Spring Suspension, 137 WB, Steel Wheels. Mileage Unavailable. Location: Buckeye, AZ Serial: 2FDKF37H7SCA01383	
<b>Lot #</b>	101	
<b>Qty</b>	1	
<b>Title</b>	1996 HOMEMADE FLATBED TRAILER	
<b>Des.</b>	28ft Length, 101in Width, Tri Axle, 64in Tongue, Pintle Hitch. Location: Buckeye, AZ Serial: 1UN10FH36T1006744	



<b>Lot #</b>	102	
<b>Qty</b>	1	
<b>Title</b>	1998 FRUEHAUF DROP DECK TRAILER	
<b>Des.</b>	48ft Length, 38ft Lower Deck, 10ft Upper Deck, 96in Width, Wood Decking, Steel Wheels, 215/75R17.5, Missing Three Tires - See Photos, Deck Weathered, Rust. Location: Lakeland, FL Serial: 1JJF482FXWS451116	
<b>Lot #</b>	103	
<b>Qty</b>	1	
<b>Title</b>	ROCKFORD ENGINES	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. OPERATION UNKNOWN. Cummins QSK19 Industrial Engine, Rockford Power Take Off. Location: Des Moines, IA Serial: N/A	
<b>Lot #</b>	104	
<b>Qty</b>	1	
<b>Title</b>	2002 MACK RD688S CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. ENGINE MISSING PARTS. Mack E7-350, Eaton Fuller, Camelback Suspension, 258 WB, 216in Back Cab To End Frame, Double Frame, Steel Fuel Tank, Steel Wheels, 295/75R22.5; 11R22.5, Dead Batteries, Right Rear Outer Wheels Only, Rust. Mileage Unavailable. Location: Des Moines, IA Serial: 1M2P267C82M064239	
<b>Lot #</b>	105	
<b>Qty</b>	1	
<b>Title</b>	1999 FORD F250 EXT CAB 4X2 PICKUP TRUCK	
<b>Des.</b>	RUNNING CONDITION UNKNOWN - IGNITION SWITCH BROKEN. Ford 5.4L Gas, Automatic, Spring Suspension, 3.95 FA, 5.81 RA, 158 WB, 8ft Box, Chrome Wheels, 235/85R16, AC, Passenger Side Cab Door Window Broken, Body Damage/Rust. Showing 261,207 Miles. Location: Lee Summit, MO Serial: 1FTNX20L6XEE52829	
<b>Lot #</b>	106	
<b>Qty</b>	1	
<b>Title</b>	1986 MACK CS250P DUMP TRUCK	
<b>Des.</b>	STARTED ON SITE, NOT ROAD TESTED. Mack E3- 175 HP, Spicer 5552A 5 Speed, Spring Suspension, Steel Wheels. Mileage Unavailable. Showing 852 Hours. Location: Buckeye, AZ Serial: VG6BA02B8GB070411	
<b>Lot #</b>	107	
<b>Qty</b>	1	
<b>Title</b>	1980 GREAT DANE GPS-412 FLATBED TRAILER	
<b>Des.</b>	MISSING OUTER TIRES. 41ft Length, 96in Width, Sliding Front Axle, Wood Decking, Spoke Wheels, 11R22.5, Deck Weathered, Rust. Location: Lakeland, FL Serial: M24896	
<b>Lot #</b>	108	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CHN613 DAY CAB TRUCK	
<b>Des.</b>	NON RUNNER. TRUCK HAS BEEN WRECKED - CAB BENT, RIGHT DOOR WON'T OPEN, HOOD REMOVED W/ TRUCK, WINDSHIELD MISSING. ENGINE PARTS MISSING. DASH APART. NO COOLANT IN RADIATOR. MISSING COMPONENTS: CAT WALK, FIFTH WHEEL HITCH, BATTERIES, TAIL LIGHTS, AND INTERIOR COMPONENTS. Oil Seepage Noted At Oil Pan, Back Window Cracked, Exhaust Bent, Right Side Mirror Broken, Various Body Damage/Rust. Mileage Unavailable. Location: Emporia, KS Serial: 1M1AJ06Y06N001465	

<b>Lot #</b>	110	
<b>Qty</b>	1	
<b>Title</b>	2006 MACK CV713 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. ENGINE COMPONENTS MISSING. BATTERY CABLES MISSING. REAR DRIVE SHAFT MISSING. AMI-370 ASET, T310M, Camelback Suspension, 265 WB, Steel Wheels, 315/80R22.5 (Rears Singled Out), Dual Steel Fuel Tanks, PTO, AC, Broken Windshield. Mileage Unavailable. Location: Avondale, LA Serial: 1M2AG11C66M037002	
<b>Lot #</b>	111	
<b>Qty</b>	1	
<b>Title</b>	1994 CUMMINS K19 GENERATOR	
<b>Des.</b>	NO TITLE PER STATE REGULATIONS. UNKNOWN OPERATIONAL CONDITION. Location: Buckeye, AZ Serial: 37153483	
<b>Lot #</b>	112	
<b>Qty</b>	1	
<b>Title</b>	1990 MACK CH613 DAY CAB TRUCK	
<b>Des.</b>	NON RUNNER. MISSING BATTERIES. Oil Residue Build Up Noted At Pan, Bottom Of Block, And Rear Seal Area, Leak Noted On Transmission Housing, Rear Window Cracked, Various Body Damage/Rust. Showing 233,288 Miles. Location: Salina, KS Serial: 1M2AA05Y0LW001386	
<b>Lot #</b>	113	
<b>Qty</b>	1	
<b>Title</b>	1980 FONTAINE FLATBED TRAILER	
<b>Des.</b>	47ft Length, 96in Width, Spread Axle, Steel Wheels, 11R22.5. Location: Lakeland, FL Serial: 33905	
<b>Lot #</b>	115	
<b>Qty</b>	1	
<b>Title</b>	2004 FORD F250 PICKUP TRUCK	
<b>Des.</b>	STARTED ON SITE - NOT ROAD TESTED. RUNS ROUGH. AC INOP. EXHAUST LOUD. Ford 5.4L Gas, Automatic, Spring Suspension, 3.95 FA, 6.084 RA, 158 WB, 8ft Box, Aluminum Tool Boxes, Steel Wheels, 235/85R16, AC, Dead Batteries, Exterior Drivers Door Handle Broken, Right Cab Door Does Not Open, Tailgate Inop, Seats Torn, Rust. Showing 243,382 Miles. Location: Olathe, KS Serial: 1FTNX20L64ED53889	
<b>Lot #</b>	116	
<b>Qty</b>	1	
<b>Title</b>	1999 VOLVO WNM64T DAY CAB TRUCK	
<b>Des.</b>	TRAILER NOT INCLUDED IN SALE. NON RUNNER. Oil Leaks Noted At Engine, Bad Batteries, L/Hub Leaking, Body Damage/Rust. Showing 844,361 Miles; 7,775 Hours. Location: Salina, TX Serial: 4VG7DEPF0XN767880	
<b>Lot #</b>	117	
<b>Qty</b>	1	
<b>Title</b>	1990 GREAT DANE GPD-42 FLATBED TRAILER	
<b>Des.</b>	FRAME RUST/CRACKS. 48ft Length, 96in Width, Sliding Tandem, Wood Decking, Steel Wheels, 11R24.5. Location: Lakeland, FL Serial: 1D9A48A26L1052056	

<b>Lot #</b>	118	
<b>Qty</b>	1	
<b>Title</b>	1997 GMC 6500 CAB & CHASSIS	
<b>Des.</b>	NON RUNNER. ENGINE CLICKS BUT DOESN'T TURN OVER. CAT 6.6L, Automatic, Spring Suspension, 8.1 FA, 17.85 RA, 162 WB, 117in Back Cab To End Frame, Steel Fuel Tank, Steel Wheels, 295/75R22.5; 10R22.5, PTO, No Heater Controls, PTO Unknown Working Condition, Dash Missing Parts, Body Damage/Rust. Showing 478,367 Miles. Location: Des Moines, IA Serial: 1GDJ6H1J8VJ513731	
<b>Lot #</b>	120	
<b>Qty</b>	1	
<b>Title</b>	1999 MACK CH613 DAY CAB TRUCK	
<b>Des.</b>	NON RUNNER. BAD ENGINE. Mack E7-460, Eaton Fuller 10 Speed, Air Ride Suspension, 26.25ft Body Length, Wet Kit, Dual Aluminum Fuel Tanks, Steel Wheels, 315/80R22.5, AC, Interior Missing Some Components, Dead Batteries, Missing Four Tires/Rims, Body Damage/Rust. Showing 77,925 Miles; 14,908 Hours. Location: Westwego, LA Serial: 1M2AA18Y7XW114842	
<b>Lot #</b>	121	
<b>Qty</b>	1	
<b>Title</b>	1988 GREAT DANE FLATBED TRAILER	
<b>Des.</b>	VIN TAG NOT LOCATED ON UNIT. 45ft Length, 96in Width, Sliding Tandem, Wood Decking, Steel Wheels, 11R24.5, Missing Both Hook Ups, Rust Holes, Deck Weathered - Poor Condition. Location: Lakeland, FL Serial: 1GRDM9024JJ002301	
<b>Lot #</b>	122	
<b>Qty</b>	1	
<b>Title</b>	2002 FORD F150 PICKUP TRUCK	
<b>Des.</b>	NON RUNNER. LESS TRANSMISSION. MISSING ENGINE AND DASH PARTS. HEAVY BODY DAMAGE. Ford 4.2L Gas, Spring Suspension, 136 WB, 8ft Box W/ Liner, Steel Wheels, LT245/75R16, AC, Less Tailgate, Front And Rear Windows Broken, Body Damage/Rust. Mileage Unavailable. Location: Des Moines, IA Serial: 1FTRF172X2KA21223	