

Printable Catalog

Title	AUGUST 12TH 12:00 CST	
Description	Closing Times TBD	
Date	Wed, Aug 12, 2026	
Starts at	12:00 PM	
Address	4747 NE 14th St, Des Moines, IA 50313 USA	
Categories		

Lot #	1	
Qty	1	
Title	2012 PETERBILT 365 CNG CAB & CHASSIS	
Des.	SHOWING: MILES/HOURS UNAVAILABLE. NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEYS. Location: Hagerstown, NC Serial: 1NPSL20X2CD170553	



Lot #	1	
Qty	1	
Title	2014 MACK GU713 CAB & CHASSIS	
Des.	SHOWING 301,444 MILES; 14,624 HOURS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. Location: Des Moines, IA Serial: 1M2AX16C3EM026529	



Lot #	1	
Qty	1	
Title	2002 FORD F550 CAB & CHASSIS	
Des.	Showing: 277,659 Miles; Unknown.STARTED ON SITE, FULL OPERATIONS NOT TESTED. Missing Door Locks On Both Sides; Worn Tires; Heavy Rust Throughout Unit. Location: Buckeye, AZ Serial: 1FDAF56F32ED68394	



Lot #	1	
Qty	1	
Title	2012 INTERNATIONAL WORKSTAR 7500 CAB & CHASSIS	
Des.	Showing: 74,183 Miles; Unknown Hours.STARTED ON SITE W/JUMP & FLUID, FULL OPERATIONS NOT TESTED. Warning Lights Present; Worn Tires. Location: Middletown, DE Serial: 1HTWNAZT8CJ550109	



Lot #	1	
Qty	1	
Title	2000 LAYMOR 5800PN SWEEPER	
Des.	Showing: 2,376 Hours.NOT TITLED PER STATE REGULATIONS. NON-RUNNER, FULL OPERATIONS NOT TESTED. Less: Keys, L/S Panel Cover; Broken Water Tank; Worn Tires; Scratches & Rust Throughout Unit. Location: Richmond, VA Serial: 222136	



Lot #	1	
Qty	1	
Title	2000 HEIL TANKER TRAILER	
Des.	Approximately 42 FT Length, 98 IN WidthFULL OPERATIONS NOT TESTED. Missing Parts: L/S & R/S Side Skirts, Discharge Lines, Ladder, Stand Handle; Worn Tires & Vin Plate. Location: Mulberry, FL Serial: 5HTSN4324Y7T07930	



Lot #			
Qty	1		
Title	1974 SAMP ROLLOFF TRAILER		
Des.	Approximately 24.5 FT Length, 83 IN Width FULL OPERATIONS NOT TESTED. Worn Vin Tag; Less Tail Lights On Both Sides; Frayed Wires & Cut Air Hoses; Worn Tires, L/R Outer Tire Blown & Slashed Sidewall, Wheel Covers Have Warped Plastic On Both Sides. Location: Twin Falls, ID Serial: CP1019		
Lot #			
Qty	1		
Title	1994 KENWORTH T800 DAY CAB TRUCK		
Des.	Showing: 404,784 Miles; Unknown Hours.NON-RUNNER, FULL OPERATIONS NOT TESTED. Unit Inop; Oil Leak On P/S Of Engine & Filler Tube Areas, Transmission Covered In Fluid; Damage Present At: Front Clip, D/S Cab Fairing, Cab Interior Panels, Fuel Tanks Dented; Less Dash Covers/Wiring Exposed; Worn Tires; Rust Throughout. Location: Twin Falls, ID Serial: 1XKDD69XXRS625228		
Lot #			
Qty	1		
Title	2010 C&B CBQT UTILITY TRAILER		
Des.	Approximately 16 FT Length, 82 IN WidthFULL OPERATIONS NOT TESTED. Less: Vin Plate & Side Marker Lights Cover On Rear P/S; Flooring Damage: Warped Boards, Loose, Debris; Side Walls Bent On Both Sides; Worn Tires; Rust Throughout. Location: Twin Falls, ID Serial: 4JUBU1620AN034433		
Lot #			
Qty	1		
Title	2004 IMCO WALKING FLOOR TRAILER		
Des.	Approximately 53 FT Length, 102 IN WidthFULL OPERATIONS NOT TESTED. Doors Inop; Rust Throughout Unit, Cracked Welds; Body Damage Due To Corrosion; Worn Tires. Location: Spokane Valley, WA Serial: 1M9W534D341041004		
Lot #			
Qty	1		
Title	2007 MACK CV713 CAB & CHASSIS		
Des.	Showing: 806,120 Miles; 36,010 Hours.STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. Warning Lights Present; Missing Parts: Engine Parts, Passenger Seat, D/S Hood Vent, Axle Fenders On D/S; Fuse Panel Cover Removed, Part With Unit; Worn Tires; Rust Throughout. Location: McCrory, AR Serial: 1M2AG11C77M045997		
Lot #			
Qty	1		
Title	2017 INTERNATIONAL SF567 6X4 CAB & CHASSIS		
Des.	Mileage/Hours: Unknown.NON-RUNNER, FULL OPERATIONS NOT TESTED. Less: Keys, Batteries, Engine Parts, D/S Door, Grille, P/S Door Mirror, Fuse Panel Cover/Wiring Exposed; DS/ Fuel Tank Removed; Some Parts Inside Cab; Torn Driver Seat; Worn Tires. Location: Alvin, TX Serial: 3HAGRSNT6HL576379		