
























## Printable Catalog

<b>Title</b>	AUGUST 27TH 12:00 CST	
<b>Description</b>	Closing Times TBD	
<b>Date</b>	Wed, Aug 27, 2025	
<b>Starts at</b>	12:00 PM	
<b>Address</b>	4747 NE 14th St, Des Moines, IA 50313 USA	
<b>Categories</b>		
<b>Lot #</b>		
<b>Qty</b>	1	
<b>Title</b>	ARROW HAMMER D353 CONCRETE HAMMER	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. NEW BATTERIES, WILL NEED NEW CABLE. Showing: 2,495 Hours. Location: Ames, IA Serial: 02AA1107	
<b>Lot #</b>		
<b>Qty</b>	1	
<b>Title</b>	TRAFCON TC1-25S ARROW BOARD	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. 6 RECHARGEABLE BATTERIES. Showing: Hours Unknown. Location: Ames, IA Serial: 0600SL25098	
<b>Lot #</b>		
<b>Qty</b>	1	
<b>Title</b>	2017 MACK GU713 GRANITE ROLLOFF TRUCK	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Rolloff: Galbreath; Serial U5-EX-174 60,000LBS. Tarp: Pioneer; Serial RP4500. ROLLOFF HAS HIGH PITCHED NOISE COMING FROM PTO, SYSTEM DOES NOT ENGAGE. METAL SHAVINGS IN TRANSMISSION, Rt Tires Singled Out; Rt Front Rear Tread Separating, Warning Light: Check Engine. Showing: 330,533 Miles; 18,976 Hours. Location: Minneapolis, MN. Serial: 1M2AX04C7HM035252.	
<b>Lot #</b>		
<b>Qty</b>	1	
<b>Title</b>	INGERSOLL-RAND SSR-EP60 AIR COMPRESSORS	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. NON RUNNER, FULL OPERATIONS NOT TESTED. Showing: Hours Unknown. Location: Ames, IA Serial: F11768U95054	
<b>Lot #</b>		
<b>Qty</b>	1	
<b>Title</b>	ASPHALT FLEX KETTLE ASPHALT EQUIP	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. FUNCTIONAL, FULL OPERATIONS NOT TESTED. Showing: Hours Unknown. Location: Ames, IA Serial: 98835	
<b>Lot #</b>		
<b>Qty</b>	1	
<b>Title</b>	2014 INTERNATIONAL WORKSTAR 7400 6X4 MANUAL SIDE LOAD GARBAGE PACKER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Body: LaBrie EX; Serial EX13115UUA; Capacity 31Yd. TRANSMISSION ISSUE; HESITATION WHEN GEARS ENGAGED, Tires Singled Out, Warning Light: Check Engine. Showing: 157,502 Miles; 17,408 Hours. Location: Eagan, MN. Serial: 3HAWGAZT3EL790439.	

<b>Lot #</b>			
<b>Qty</b>	1		
<b>Title</b>	2005 PETERBILT 357 DAY CAB TRUCK		
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Showing: 286,989 Miles. Location: AMES, IA Serial: 1XPADU9X75N872734		
<hr/>			
<b>Lot #</b>			
<b>Qty</b>	1		
<b>Title</b>	2013 MACK GU713 ROLLOFF TRUCK		
<b>Des.</b>	STARTED ON SITE W/JUMP, FULL OPERATIONS NOT TESTED. Rolloff Body: Galbreath U5-EX-174; Serial 13H33829; Capacity 60,000. Rear Tires Singled Out, Warning Light: Check Engine. Showing: 352,255 Miles; 21,294 Hours. Location: Eagan, MN. Serial: 1M2AX04C3DM017499.		
<hr/>			
<b>Lot #</b>			
<b>Qty</b>	1		
<b>Title</b>	2012 INTERNATIONAL WORKSTAR 7400 SBA 6X4 REAR LOAD GARBAGE PACKER		
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. Body: Heil DuraPack 5000; Model 612-3201; Serial FP5020986; Capacity 20Yds. CRANK NO START, LESS FRONT GRILLE, Rear Tires Singled Out, Warning Lights: Check Engine and Low Coolant. Showing: 216,056 Miles; 24,866 Hours. Location: Eagan, MN. Serial: 1HTWGAAT6DJ157085.		
<hr/>			
<b>Lot #</b>			
<b>Qty</b>	1		
<b>Title</b>	2013 INTERNATIONAL WORKSTAR 7400 SBA 6X4 REAR LOAD GARBAGE PACKER		
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Body: Heil DuraPack 5000; Model 612-3201; Serial FP5021107; Capacity 20Yds. BAD CYLINDER, ROUGH IDLE, Rear Tires Singled Out, Fenders Cracked, Bumper Cracked/Bent/Rusted, Warning Lights: Check Engine, Body Rust. Showing: 181,875 Miles; 25,942 Hours. Location: Eagan, MN. Serial: 1HTWGAAT5DJ195567.		
<hr/>			
<b>Lot #</b>			
<b>Qty</b>	1		
<b>Title</b>	2011 INTERNATIONAL WORKSTAR 7400 SBA 6X4 REAR LOAD GARBAGE PACKER		
<b>Des.</b>	STARTED ON SITE W/JUMP, FULL OPERATIONS NOT TESTED. Body: Heil; Model 612-3201; Serial FP5020114; Capacity 20Yds. Rear Tires Singled Out, L/F Rear Tire Flat, Headlight Cover Cracked, Warning Lights: Check Engine. Showing: 47,353 Miles (Actual Mileage Unavailable); 20,154 Hours. Location: Eagan, MN. Serial: 1HTWGAATXBJ327817.		
<hr/>			
<b>Lot #</b>			
<b>Qty</b>	1		
<b>Title</b>	2014 MACK MRU613 FRONT LOAD GARBAGE PACKER		
<b>Des.</b>	STARTED ON SITE W/JUMP, FULL OPERATIONS NOT TESTED. Body: Heil; Model 612-3909; Serial HPE4955727; Capacity 28Yds. HYRAULIC LEAK FROM CAB TILT FITTING, Rear Tires Singled Out, Rust, Warning Lights: Check Engine. Showing: 389,750 Miles; 8,502 Hours. Location: Eagan, MN. Serial: 1M2AV02C8EM011143.		
<hr/>			
<b>Lot #</b>			
<b>Qty</b>	1		
<b>Title</b>	2005 INTERNATIONAL DURASTAR 4300 SBA 4X2 STRAIGHT TRUCK		
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. ROUGH IDLE, ENGINE OIL LEAK, Rt Front Tire Flat/Tire Off Bead, Rear Tires Singled Out. Showing: 341,465 Miles; 19,086 Hours. Location: Eagan, MN. Serial: 1HTMMAAL45H123378.		

<b>Lot #</b>	1	
<b>Qty</b>	1	
<b>Title</b>	2013 INTERNATIONAL DURASTAR 4300 SBA 4X2 CAB & CHASSIS	
<b>Des.</b>	STARTED ON SITE W/JUMP, FULL OPERATIONS NOT TESTED. RUNS ROUGH, LESS PASSENGER SEAT, P/S DASH COVER REMOVED/WIRING EXPOSED, Tread Separating On Right Rear Tires, Warning Lights On: Check Engine Light. Showing: 222,577 Miles; 9,721 Hours. Location: Minneapolis, MN. Serial: 1HTMMAAN2DH419466.	
<b>Lot #</b>	1	
<b>Qty</b>	1	
<b>Title</b>	2017 KENWORTH T880 6X4 REAR MIXER	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. STARTED ON SITE W/JUMP, MAJOR ENGINE OIL AND HYDRAULIC LEAKS. UNIT WILL NEED TOWED. Warning Lights On. Con-Tech Mixer Body. Showing: 182,476 Miles. Location: Hockley, TX. Serial: 1NKZLP0X6HJ156696.	
<b>Lot #</b>	1	
<b>Qty</b>	1	
<b>Title</b>	2016 KENWORTH T880 6X4 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. McNeilus Mixer Body. Rust, Warning Lights On. Showing: 193,162 Miles; 3,719 Hours. Location: Hockley, TX. Serial: 1NKZLP0X7GJ498432.	
<b>Lot #</b>	1	
<b>Qty</b>	1	
<b>Title</b>	2014 KENWORTH T800 6X4 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. McNeilus Mixer Body. Warning Lights On. Showing: 212,368 Miles; 2,870 Hours. Location: Hockley, TX. Serial: 1NKDLP0X6EJ417671.	
<b>Lot #</b>	1	
<b>Qty</b>	1	
<b>Title</b>	2015 MACK GU813 GRANITE REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/JUMP AND FLUID, FULL OPERATIONS NOT TESTED. Beck Mixer Body. Warning Lights On. Showing: 280,295 Miles; 19,753 Hours. Location: Hockley, TX. Serial: 1M2AX13C1FM028303.	
<b>Lot #</b>	1	
<b>Qty</b>	1	
<b>Title</b>	2016 KENWORTH T880 6X4 DAY CAB TRUCK	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. NO POWER, Center Dash Disassembled. Showing: Mileage/Hours Unavailable. Location: Hockley, TX. Serial: 1XKZDP9X9GJ120229.	
<b>Lot #</b>	1	
<b>Qty</b>	1	
<b>Title</b>	2017 CASE CX300D EXCAVATOR	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. NON-RUNNER, FULL OPERATIONS NOT TESTED. BAD WIRING HARNESS, BAD TEETH ON BUCKET, WIRING ISSUES/NO ELECTRICAL POWER, RUST THROUGHOUT UNIT. Showing: Hours Unavailable. Location: Amsterdam, OH. Serial: NFS7N1124.	
<b>Lot #</b>	1	
<b>Qty</b>	1	
<b>Title</b>	2013 MACK MRU600 FRONT LOAD GARBAGE PACKER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. COLLISION DAMAGE TO BOTH FRONT CORNERS OF CAB, BODY RUST THROUGHOUT UNIT, TIRES SINGLED OUT, REAR TIRES FLAT. Body: Heil Garbage Packer; Model 612-3528 Serial HPE4954522 Capacity 28Yds. Showing: 203,413 Miles; 25,576 Hours. Location: Minneapolis, MN. Serial: 1M2AV02CXDM009909.	

<b>Lot #</b>		
<b>Qty</b>	1	
<b>Title</b>	2015 VOLVO VHD 6X4 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Beck 10.5 Cubic Yd Mixer System: Serial B-14-29. Warning Lights On. Showing: 258,227 Miles; 24,190 Hours. Location: Converse, TX. Serial: 4V5KC9DF4FN184888.	
<hr/>		
<b>Lot #</b>		
<b>Qty</b>	1	
<b>Title</b>	2015 VOLVO VHD 6X4 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Beck 10.5 Cubic Yd Mixer System: Serial E-14-36. Warning Lights On. Showing: 235,468 Miles; 23,695 Hours. Location: Converse, TX. Serial: 4V5KC9DF2FN192259.	
<hr/>		
<b>Lot #</b>		
<b>Qty</b>	1	
<b>Title</b>	2015 VOLVO VHD 6X4 REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/JUMP, FULL OPERATIONS NOT TESTED. Beck 10.5 Cubic Yd Mixer System: Serial G-14-52. Warning Lights On. Showing: 277,112 Miles; 25,192 Hours. Location: Converse, TX. Serial: 4V5KC9DF5FN913688.	
<hr/>		
<b>Lot #</b>		
<b>Qty</b>	1	
<b>Title</b>	2015 VOLVO VHD 6X4 REAR MIXER	
<b>Des.</b>	STARTED ON SITE W/JUMP, FULL OPERATIONS NOT TESTED. Beck 10.5 Cubic Yd Mixer System: Serial H-14-04. COOLANT LEAK D/S ENGINE, Warning Lights On, Toggle Button On Dash Display Does Not Work. Showing: 223,273 Miles; Hours Unavailable. Location: Converse, TX. Serial: 4V5KC9DF8FN913703.	
<hr/>		
<b>Lot #</b>		
<b>Qty</b>	1	
<b>Title</b>	2018 KENWORTH T880 REAR MIXER	
<b>Des.</b>	STARTED ON SITE, FULL OPERATIONS NOT TESTED. CON-TECH Mixer System: Serial 110HZ1704766. D/S ENGINE SPRINGS BROKEN. Showing: 127,278 Miles; 3,517 Hours. Location: Converse, TX. Serial: 1NKZXKEX0JJ217398.	
<hr/>		
<b>Lot #</b>		
<b>Qty</b>	1	
<b>Title</b>	2015 VOLVO VNL64T 6X4 DAY CAB TRUCK	
<b>Des.</b>	NON-RUNNER, FULL OPERATIONS NOT TESTED. ENGINE CLICKS BUT NO START. Showing: 797,729 Miles. Location: Fayetteville, NC. Serial: 4V4NC9EG9FN915551.	
<hr/>		
<b>Lot #</b>		
<b>Qty</b>	1	
<b>Title</b>	2000 DAEWOO D30 FORKLIFT	
<b>Des.</b>	NOT TITLED PER STATE REGULATIONS. NON-RUNNER, FULL OPERATIONS NOT TESTED. LOTS OF WIRES MISSING AND CUT. Showing: 6,140 Hours. Location: Walford, IA Serial: 90-08174	