








Printable Catalog

Title	SEPTEMBER 10TH 12:00 CST
Description	Closing Times TBD
Date	Wed, Sep 10, 2025
Starts at	12:00 PM
Address	4747 NE 14th St, Des Moines, IA 50313 USA
Categories	

Lot #		
Qty	1	
Title	2002 BRAY SPORTSMAN CVT2468 DUMP BODY PUP TRAILER	
Des.	FULL OPERATIONS NOT TESTED. Approximate Measurements: 37 FT Length, 96 IN Width. Location: Atalissa, IA. Serial: 1BTDP1424GICGB288.	
Lot #		
Qty	1	
Title	2005 MACK CV713 GRANITE CAB & CHASSIS	
Des.	NON-RUNNER, FULL OPERATIONS NOT TESTED. Body Damage, Warning Lights On, P/S Dash Cover Removed; In Cab. Showing: 892,205 Miles; 44,388 Hours. Location: Cairo, GA. Serial: 1M2AG11C55M016088.	
Lot #		
Qty	1	
Title	1996 PETERBILT 330 4X2 CAB & CHASSIS	
Des.	STARTED ON SITE W/JUMP AND FLUID, FULL OPERATIONS NOT TESTED. Showing: 320,619 Miles. Location: Wittenberg, WI. Serial: 1XPNH7X4TN399781.	
Lot #		
Qty	1	
Title	2007 MACK CV713 GRANITE CAB & CHASSIS	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Warning Lights On; ABS, Rust On Body. Showing: 788,951 Miles; 39,112 Hours. Location: Kingsville, OH. Serial: 1M2AG11C27M067616.	
Lot #		
Qty	1	
Title	2013 INTERNATIONAL DF567 6X4 CAB & CHASSIS	
Des.	NON-RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, LESS IGNITION SWITCH, Dash Partially Disassembled. Showing: Mileage/Hours Unavailable. Location: Alvin, TX. Serial: 1HTXHSHT5DJ200408.	
Lot #		
Qty	1	
Title	2013 MACK CXU613 DAY CAB TRUCK	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. BAD CLUTCH; HARD TO GET INTO GEAR, Warning Lights On. Showing: 480,376 Miles. Location: Pomona, CA. Serial: 1M1AW09Y5DM030783.	

Lot #			
Qty	1		
Title	2007 MACK CV713 GRANITE CAB & CHASSIS		
Des.	NON-RUNNER, FULL OPERATIONS NOT TESTED. LESS IGNITION SWITCH, LESS KEY, LESS TRANSMISSION, DASH DISASSEMBLED, LESS D/S DOOR, Floor Cover Driveshaft and Transmission Stick Removed/In Cab, R/R Tire Missing Axles. Showing: Mileage/Hours Unavailable. Location: Harrisburg, PA. Serial: 1M2AG11CX7M067282.		
<hr/>			
Lot #			
Qty	1		
Title	2006 MACK CV713 GRANITE CAB & CHASSIS		
Des.	NON-RUNNER, FULL OPERATIONS NOT TESTED. ENGINE ROLLS OVER/DOES NOT START, LESS MANUAL TRANSMISSION/STICK IN CAB, REAR OF ENGINE IS CHAINED UP/PTO PUMP STILL WITH UNIT, LIFT AXLE IS CHAINED IN THE UP POSITION, D/S DOOR LATCH MECHANISM MISSING, Rust/Rust Holes in Various Areas. Showing: 818,236 Miles; 36,516 Hours. Location: Portland, MI. Serial: 1M2AG11C36M042920		
<hr/>			
Lot #			
Qty	1		
Title	2007 MACK CTP713 GRANITE CAB & CHASSIS		
Des.	NON-RUNNER, FULL OPERATIONS NOT TESTED. HVAC Controls Missing, Tires Singled Out. Showing: Mileage/Hours Unavailable. Location: Harrisburg, PA. Serial: 1M2AT04C67M003631.		
<hr/>			
Lot #			
Qty	1		
Title	2006 MACK CV713 GRANITE CAB & CHASSIS		
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. First Axle Singled Out, Right Front Tire Hub Has Hole. Showing: 353,864 Miles; 32,885 Hours. Location: Elkhorn, WI. Serial: 1M2AG11C96M048821.		
<hr/>			
Lot #			
Qty	1		
Title	2007 MACK CV713 GRANITE CAB & CHASSIS		
Des.	NON-RUNNER, FULL OPERATIONS NOT TESTED. LESS KEYS, FUSE BOX HAS PARTIALLY BEEN REMOVED. Showing: Mileage Unavailable; 1,764 Hours. Location: McComb, MS. Serial: 1M2AG11C47M064393.		
<hr/>			
Lot #			
Qty	1		
Title	2005 MACK CV713 GRANITE CAB & CHASSIS		
Des.	NON-RUNNER, FULL OPERATIONS NOT TESTED. LESS KEYS, DASH HAS BEEN REMOVED, REAR TIRES BLOWN OUT. Showing: Mileage/Hours Unavailable. Location: McComb, MS. Serial: 1M2AG11C15M030117.		
<hr/>			
Lot #			
Qty	1		
Title	2004 MACK CV713 GRANITE CAB & CHASSIS		
Des.	NON-RUNNER, FULL OPERATIONS NOT TESTED. CENTER AND P/S DASH COVER REMOVED, REAR TIRES SINGLED OUT. Showing: Mileage/Hours Unavailable. Location: Mulberry, FL. Serial: 1M2AG11CX4M010561.		