





Printable Catalog


Title	SEPTEMBER 13 12:00 CDT	
Description	Closing Times TBD	
Date	Wed, Sep 13, 2023	
Starts at	12:00 PM	
Address	4747 NE 14th St, Des Moines, IA 50313 USA	
Categories		


Lot #	1	
Qty	1	
Title	2009 MACK GU813 CAB & CHASSIS	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Rear Tires Singled Out, Rust Throughout. Showing 572,759 Miles; 30,030 Hours. Location: Rochester, MN Serial: 1M2AX13C79M002079	







Lot #	2	
Qty	1	
Title	2007 INTERNATIONAL 9200i SBA 6X4 DAY CAB TRUCK	
Des.	STARTED ON SITE W/ FLUID, FULL OPERATIONS NOT TESTED. Body Damage Noted. Showing 986,722 Miles; 32,176 Hours. Location: Buckeye, AZ Serial: 2HSCESBR87C463715	








Lot #	3	
Qty	1	
Title	2006 INTERNATIONAL WORKSTAR 7600 SBA 6X4 DUMP TRUCK	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. DEAD BATTERIES, Oil Leaks From Hydraulic Lines, Steps Bent On Both Sides, Tail Lights Broken Out, Headliner Dirty, Torn, And Sagging, Flooring Cracked And Torn, Body Damage And Rust Throughout. Mileage Unavailable. Location: New Braunfels, TX Serial: 1HTWYAHT26J396607	








Lot #	5	
Qty	1	
Title	2016 FREIGHTLINER M2 106 4X2 STRAIGHT TRUCK	
Des.	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. DOES NOT STAY RUNNING LONG WHEN IDLING, Windshield Has A Crack, Box Has Scratches And Spray Painted Graffiti On Side, Front P/S Bumper Pushed In, Multivans 26DF102102 Body. Showing 323,476 Miles; 5,301 Hours. Location: Elgin, IL Serial: 3ALACWDT8GDGV9147	








Lot #	6	
Qty	1	
Title	2005 CATERPILLAR 740 OFF HIGHWAY-DUMP TRUCK	
Des.	NO TITLE PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. Both Front And R/S Rear Tire Have Split Rims, Seat Tattered, Rust And Body Damage Throughout, Approximate Measurements: 37 FT Shipping Length, 144 IN Shipping Width, 12 FT Shipping Height. Showing 12,455 Hours. Location: Greenville, OH Serial: AD050675	









Lot #	9	
Qty	1	
Title	2014 FREIGHTLINER 114SD DUMP TRUCK	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. RESIDUE LEFT SIDE NEAR FUEL RAIL, Paint Chipped Throughout, Rust Throughout Unit, Stained Seat. Showing: 508,066 Miles / 16,386 Hours. Location: Tell City, IN Serial: 3ALHG3DV1EDGA1036	

Lot #	10	
Qty	1	
Title	2007 STERLING LT9500 CAB & CHASSIS	
Des.	STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. Multiple Air Leaks, Rear Tires Singled Out, Rust Throughout. Showing 580,068 Miles; 25,021 Hours. Location: Wittenberg, WI Serial: 2FZHAZDE87AY56822	
Lot #	11	
Qty	1	
Title	2018 JOHN DEERE 344L ARTICULATE WHEEL LOADER	
Des.	NO TITLE PER STATE REGULATIONS. NON RUNNER, FULL OPERATIONS NOT TESTED. FIRE DAMAGE, COMPONENTS REMOVED/DISCONNECTED. HYDRAULIC LINES DISCONNECTED UNDER CAB- SEE PHOTOS. Unknown Control Button Missing, Hydraulic Lines Disconnected Under Cab, R/S Door Handle Missing, Seepage At Suspension Plug On Front L/S Axle, Interior Stained, Body Damage, Scratched Paint And Rust Throughout. Hours Unavailable. Location: Owensboro, KY Serial: 1LU344LXKZB050915	
Lot #	14	
Qty	1	
Title	2007 INTERNATIONAL 9200i SBA 6X4 DAY CAB TRUCK	
Des.	STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. No Engine Tag Located, Damaged Paint On Rear P/S Of Cab. Showing 100,712 Miles; 34,275 Hours. Location: Buckeye, AZ Serial: 2HSCESBR37C463718	
Lot #	15	
Qty	1	
Title	2014 FREIGHTLINER 114SD DUMP TRUCK	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. TRANSMISSION LEAKING, RESIDUE IN OIL PAN, Tarp Is Torn, Paint Chipped Throughout, Rust Throughout Unit, Stained Seat, Windshield Has Cracks. Showing: 472,849 Miles / 14,142 Hours. Location: Tell City, IN Serial: 3ALHG3DV7EDGA1042	
Lot #	16	
Qty	1	
Title	2013 FORD F250 4X4 CAB & CHASSIS	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. TPMS Warning On Dash, Check Engine Warning Light Is Flashing, Oil Change Required Warning On Dash, Exhaust Leak Noted, P/S Mirror Cracked, Rust And Body Damage Throughout. Showing 129,646 Miles. Location: Wittenberg, WI Serial: 1FTBF2B68DEA02379	
Lot #	18	
Qty	1	
Title	2013 VOLVO VNL64T670 6X4 SLEEPER TRUCK	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Cummins ISX 14.9L - 450 HP, Eaton Fuller 10 Speed Automated Transmission, Air Ride Suspension, 12.5 FA, 40 RA, Aluminum/Steel Wheels, 11R22.5, Engine Brake, APU, Dual Aluminum Fuel Tank, 13 FT Body Height, Single Frame, AC. Showing 652,327 Miles. Location: Miami, FL Serial: 4V4NC9TGXDN132240	







Lot #	21	
Qty	1	
Title	2011 PETERBILT 386 DAY CAB TRUCK	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. AIR SLIDE AIR LINE IS BROKEN. Showing 340,923 Miles; 15,875 Hours. Location: Baytown, TX Serial: 1XPHD49X2BD130130	
Lot #	22	
Qty	1	
Title	2014 FREIGHTLINER 114SD DUMP TRUCK	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. TRANSMISSION LEAKING, Tarp Will Not Extend, Rust And Paint Chips Throughout Unit, Windshield Cracked. Showing: 452,070 Miles; 13,799 Hours. Location: Tell City, IN Serial: 3ALHG3DV5EDGA1038	
Lot #	23	
Qty	1	
Title	2013 MACK GU713 CAB & CHASSIS	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Engine Shutdown And Idle Shutdown Warnings On Dash, P/S Top Marker Light Loose, D/S Seat Torn, Interior Soiled. Showing 540,875 Miles; 25,405 Hours. Location: Des Moines, IA Serial: 1M2AX09C8DM015403	
Lot #	24	
Qty	1	
Title	2004 INTERNATIONAL DURASTAR 4300 SBA 4X2 VAN BODY TRUCK	
Des.	STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. Low Coolant Warning Light On Dash, Dash Apart On P/S, Rust Throughout. Showing 267,029 Miles; 11,249 Hours. Location: Des Moines, IA Serial: 1HTMMAAN84H679094	
Lot #	25	
Qty	1	
Title	2013 VOLVO VNL670 6X4 SLEEPER TRUCK	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. Cummins ISX15 L6, 14.9L Engine, Eaton Fuller FRO-16210C 10 Speed Transmission, Air Ride Suspension, 12,350 LB Front Axle, 19,000 LB Each Rear Axle, 275/80R22.5 Front Tire, 295/75R22.5 Rear Tire, Missing Hood And Front Bumper, Drive Shaft Removed W/ Truck, Odometer And Gauges Missing From Dash, Storage Space For Sleeper Broken/Torn. Mileage Unavailable. Location: Fairmont City, IL Serial: 4V4NC9TG0DN563735	
Lot #	26	
Qty	1	
Title	2009 INTERNATIONAL WORKSTAR 7400 6X4 CAB & CHASSIS	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Dash Apart On P/S, P/S Seat Torn, Interior Soiled. Showing 5,011 Miles; 17,401 Hours. Location: Des Moines, IA Serial: 1HTWGAZT79J130604	
Lot #	27	
Qty	1	
Title	2009 VOLVO VNL64T 6X4 DAY CAB TRUCK	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Oil Leaking At Bottom Of Engine/Oil Pan, D/S Floor Light Missing Bulb And Cover, Multiple Fault Codes, Windshield Has Chipped Glass, Rust And Body Damage Noted Throughout. Showing 955,252 Miles; 955,252 ECM; 31,779 Hours. Location: Butler, KY Serial: 4V4NC9EG59N274628	

Lot #	29	
Qty	1	
Title	2009 PETERBILT 365 CAB & CHASSIS	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Missing Heater Controls, Engine Tag Not Located, Black Spray Paint On Cab, P/S Rear Mud Flap Missing, D/S Seat Torn, Engine Warning, Exhaust Filter Full, And Low Coolant Warning Lights On Dash, Interior Soiled. Showing 596,166 Miles; 1,102 Hours. Location: Des Moines, IA Serial: 1NPSL00X99D784092	
Lot #	31	
Qty	1	
Title	2012 PETERBILT 320 6X4 REAR LOAD GARBAGE PACKER	
Des.	STARTED ON SITE W/ FLUID, FULL OPERATIONS NOT TESTED. Some Gauges On Dash Are INOP, McNeilus 2511 Rear Load Packer Body. Mileage Unavailable. Location: Des Moines, IA Serial: 3BPZL50X4CF158520	
Lot #	32	
Qty	1	
Title	2012 PETERBILT 348 CAB & CHASSIS	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Dash Apart, No Ignition, Tires Singled Out, D/S Seat Torn, Rust And Body Damage Throughout. Mileage Unavailable. Location: Des Moines, IA Serial: 2NP3LN0X3CM162865	
Lot #	33	
Qty	1	
Title	2001 MACK RD690S CAB & CHASSIS	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. DOES NOT DRIVE, Unit Will Not Build Air To Release Brakes, Missing Hood, Rust Throughout. Showing 49,366 Miles; 34,265 Hours. Location: Lakeville, IN Serial: 1M2P337CX1M032029	
Lot #	34	
Qty	1	
Title	2005 VOLVO VNL64T 6X4 DAY CAB TRUCK	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. OIL LEAKING FROM OIL PAN. Dash Is Broken, Held In By Straps And Screws. Interior Is Worn. Bumper Is Scratched And Scraped. Rusting On Fender. Windshield Has A Scrape. Showing 107,337 Miles; 1,070,337 ECM; 34,837 Hours. Location: Kingley Lake, FL Serial: 4V4NC9GF45N374346	
Lot #	35	
Qty	1	
Title	2004 NEW IDEA 6454 SILAGE UTILITY BALER	
Des.	NO TITLE PER STATE REGULATIONS. FULL OPERATIONS NOT TESTED. PTO Driven- No Engine, Rust Throughout. Location: Union City, TN Serial: HM44198	
Lot #	36	
Qty	1	
Title	2006 MACK CV713 CAB & CHASSIS	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Engine Intake Has Been Taken Apart, R/S Rear Tire Bald, R/S Front Tire Flat, Missing Items, Including: Front Bumper, Rear Outer Tires, Steering Column, Bulldog Ornament, Headlights, Cab Is Full Of Stuffed Animals. Mileage Unavailable. Location: Lakeville, IN Serial: 1M2AG11C96M037978	

Lot #	38	
Qty	1	
Title	2000 FORD ECONOLINE E250 VAN	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Rust And Body Damage Throughout. Showing 56,524 Miles. Location: Des Moines, IA Serial: 1FTNE24L5YHA03500	
Lot #	39	
Qty	1	
Title	2002 MACK RD688S CAB & CHASSIS	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, Missing Bulldog Ornament From Hood, Interior Soiled, Gauges Missing, Rust Throughout. Mileage Unavailable. Location: Kingsville, OH Serial: 1M2P267C82M062197	
Lot #	41	
Qty	1	
Title	1998 YALE GLP050 FORKLIFT	
Des.	NO TITLE PER STATE REGULATIONS. STARTED ON SITE, FULL OPERATIONS NOT TESTED. LP TANK TO BE REMOVED PRIOR TO SALE. Tires Have Scratches And Chunks Of Tread Missing, Seating Platform Has Chipped Off Metal, Seat Cushion Torn, Lever Cover Missing And Lever Platform Bowed, Rust And Body Damage Throughout. Showing 9,309 Hours. Location: East Dublin, GA Serial: E177B14667U	
Lot #	42	
Qty	1	
Title	2007 HINO 268 CAB & CHASSIS	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. ONLY MOVES IN REVERSE, Low Fuel And ABS Warning Lights On Dash, Rear Tires Singled Out, Dash Apart On P/S. Showing 584,640 Miles; 15,319.9 Hours. Location: Harrisburg, PA Serial: 5PVNE8JT372S50698	
Lot #	44	
Qty	1	
Title	AXLE SHAFT PARTS-HD	
Des.	NO TITLE PER STAT REGULATIONS. Various Sizes: 43 Spline Count At 35in Length W/ 8 Hole Flange; 43 Spline Count At 46in Length W/ 6 Hole Flange; 41 Spline Count At 38in Length W/ 8 Hole Flange. Location: Des Moines, IA. Serial: 18963, 18962, 18971, 18970, 18967, 18966, 18979, 18978	
Lot #	45	
Qty	1	
Title	2009 MACK GU713 CAB & CHASSIS	
Des.	STARTED ON SITE W/ JUMP AND FLUID, FULL OPERATIONS NOT TESTED. LESS KEY, D/S Seat Torn, Rust Throughout. Mileage Unavailable. Location: Attleboro, MA Serial: 1M2AX04C09M004961	
Lot #	46	
Qty	1	
Title	2004 DODGE RAM 2500 CREW CAB PICKUP TRUCK	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. EMC OUT, Missing Bed Liner, D/S Seat Torn, P/S Assist Grip Removed And In Seat, P/S Door Seal Tearing Away, Dents And Rust Throughout. Mileage Unavailable. Location: Buckeye, AZ Serial: 3D7KU28C74G227460	

Lot #	47	
Qty	1	
Title	1996 FORD CF7000 SWEEPER	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, DASH APART, Cab Would Not Lift To View Entire Engine, Both Seats Torn. Mileage Unavailable. Location: Elgin, IL Serial: 1FDXH70C5TVA04901	
Lot #	48	
Qty	1	
Title	1997 MACK RD688SX CAB & CHASSIS	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. Drive Shaft Removed And In Cab, D/S Seat Torn, Dash Cover Loose, Rust Throughout. Showing 420,933 Miles; 46,046 Hours. Location: Attleboro, MA Serial: 1M2P268C6VM029914	
Lot #	49	
Qty	1	
Title	1994 GALBREATH ROLLOFF TRAILER	
Des.	FULL OPERATIONS NOT TESTED. Vin Tag Not Located, Rust Throughout, Approximate Measurements: 33.5 FT Length, 102 IN Width, 5 FT Height. Location: Lakeville, IN Serial: 1G9L12327RB157079	
Lot #	50	
Qty	1	
Title	2004 DURABILT UTILITY PASTURE PUNCH ATTACHMENTS	
Des.	NO TITLE PER STATE REGULATIONS. FULL OPERATIONS NOT TESTED. Surface Rust And Dents Throughout. Location: Union City, TN Serial: B3784	
Lot #	51	
Qty	1	
Title	2012 MACK GU713 CAB & CHASSIS	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. No Fuel Tank On R/S, Hood Mirrors Missing, P/S Steps Bent, D/S Seat Tattered, Dash Cover Loose, Rust Throughout. Mileage Unavailable. Location: Attleboro, MA Serial: 1M2AX07C3CM013415	
Lot #	52	
Qty	1	
Title	2006 CHEVROLET COLORADO PICKUP TRUCK	
Des.	STARTED ON SITE W/ JUMP, FULL OPERATIONS NOT TESTED. TRANSMISSION ONLY HAS REVERSE, Door Hinge Broken, Body Damage And Surface Rust Noted Throughout Unit. Showing 168,380 Miles. Location: Des Moines, IA Serial: 1GCDDT146668259227	
Lot #	55	
Qty	1	
Title	2007 MACK CTP713 CAB & CHASSIS	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. Misc Parts In Cab, Dash Apart, P/S Hood Mirror Missing, Rust Throughout. Mileage Unavailable. Location: Attleboro, MA Serial: 1M2AT04C07M005164	
Lot #	56	
Qty	1	
Title	2005 NEW IDEA UTILITY HAY TEDDER ATTACHMENTS	
Des.	NO TITLE PER STATE REGULATIONS. FULL OPERATIONS NOT TESTED. All Sides Of Steel Tines And Frame Are Rusted. Location: Union City, TN Serial: 2010414	

Lot #	58	
Qty	1	
Title	2008 MACK GU813 CAB & CHASSIS	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. ENGINE DISASSEMBLED- Misc. Parts In Cab, No Fuel Tank On R/S, D/S Seat Torn, Rust Throughout. Mileage Unavailable. Location: Attleboro, MA Serial: 1M2AX13C68M001567	
Lot #	59	
Qty	1	
Title	2006 FORD F250 EXT CAB PICKUP TRUCK	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. ENGINE TURNS OVER BUT WILL NOT START, Missing Items, Including: Interior Seating, Tires, Lower Dash Apart, Tail Gate Does Not Pull Down, Check Engine Light On, Rust And Body Damage Throughout. Showing 300,933 Miles. Location: Newark, NJ Serial: 1FTSX21P66EC40595	
Lot #	60	
Qty	1	
Title	2005 CHEVROLET IMPALA CAR	
Des.	STARTED ON SITE, FULL OPERATIONS NOT TESTED. Rust And Body Damage Noted. Showing 198,391 Miles. Location: Des Moines, IA Serial: 2G1WF52E659138209	
Lot #	63	
Qty	1	
Title	1988 LEROI 185CFM AIR COMPRESSOR	
Des.	NO TITLE PER STATE REGULATIONS. UNKNOWN RUNNING CONDITION, FULL OPERATIONS NOT TESTED. Rust Throughout, Approximate Measurements: 12 FT Shipping Length, 72 IN Shipping Width, 4.75 Shipping Height, 3,420 GVW LBS. Location: Greenville, KY Serial: AC98X123	
Lot #	64	
Qty	1	
Title	2002 MCCLAIN MCTT118SW WALKING FLOOR TRAILER	
Des.	FULL OPERATIONS NOT TESTED. R/S Landing Gear Does Not Go Down, Vin Tag Not Located, Rust Throughout, Approximate Measurements: 48 FT Shipping Length, 102 IN Shipping Width, 12 FT 6 IN Shipping Height. Location: Wittenberg, WI Serial: 1M9CD483522309121	
Lot #	66	
Qty	1	
Title	2012 MACK GU713 CAB & CHASSIS	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. Rear Tires Singled Out, Hood Side Vents And P/S Window Crank Are Missing, Misc Parts In Cab, Dash Apart On P/S. Mileage Unavailable. Location: McComb, MS Serial: 1M2AX04C8CM011910	
Lot #	67	
Qty	1	
Title	2006 INTERNATIONAL DURASTAR 4300 SBA 4X2 STAKE BODY TRUCK	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. Rust Throughout. Mileage Unavailable. Location: Buckeye, AZ Serial: 1HTMMAAL46H342424	

Lot #	68	
Qty	1	
Title	1994 STARLITE UTILITY TRAILER	
Des.	FULL OPERATIONS NOT TESTED. VIN Tag Not Located, Rust Throughout, Approximate Measurements: 20 FT Shipping Length, 84 IN Shipping Width, 5 FT Shipping Height. Location: Rochester, MN Serial: 13YFS1829RC052043	
Lot #	69	
Qty	1	
Title	2011 MACK GU713 CAB & CHASSIS	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. Body Damage Throughout, Rear Tires Singled Out, Rear Tire Flat And Off Bead, P/S Seat Torn, Cab Cluttered. Mileage Unavailable. Location: McComb, MS Serial: 1M2AX04C9BM008819	
Lot #	70	
Qty	1	
Title	2006 MACK CV713 CAB & CHASSIS	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. DASH APART, Missing Hood Mirrors, Heavy Rust, Body Damage Throughout. Mileage Unavailable. Location: McComb, MS Serial: 1M2AG12C26M048478	
Lot #	71	
Qty	1	
Title	2003 FORD F650 SERVICE TRUCK	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. Debris In Bed, Rust And Body Damage Throughout, D/S Seat And Arm Rest Taped Up. Mileage Unavailable. Location: Carnesville, GA Serial: 3FDWF65H33MB06384	
Lot #	72	
Qty	1	
Title	2005 TRAIL KING LOWBOY TRAILER	
Des.	FULL OPERATIONS NOT TESTED. NO TIRES, Rust Throughout, Approximate Measurements: 48.3 FT Shipping Length, 102 IN Shipping Width, 4.7 FT Shipping Height. Location: Lakeville, IN Serial: 1TKA048265B041769	
Lot #	73	
Qty	1	
Title	2004 MACK CV713 CAB & CHASSIS	
Des.	NON RUNNER, FULL OPERATIONS NOT TESTED. LESS KEY, MISSING MULTIPLE ENGINE COMPONENTS- Misc Parts In Cab, Front Bumper Removed, Hood Vents Missing, Rear Tires Singled Out, Rust Throughout. Mileage Unavailable. Location: Jacksonville, FL Serial: 1M2AG11C04M013548	