





Printable Catalog


Title	SEPTEMBER 25 12:00 CDT	
Description	Closing Times TBD	
Date	Wed, Sep 25, 2019	
Starts at	12:00 PM	
Address	4747 NE 14th St, Des Moines, IA 50313 USA	
Categories		

Lot #	1	
Qty	1	
Title	2006 STERLING LT9500 REAR MIXER	
Des.	STARTED ON SITE- HYDRAULIC LINES UNHOOKED. BAD KING PINS. CAT C13 (Oil Leaks Noted), Allison Automatic, Hendrickson Suspension, 20 FA, 46 RA, 250 WB, 11 YRD. MTM Bridgemaster Mixer (Cab Mixer Controls Missing), 150 Gallon Cross Mount Water Tank, 11,020 Lb. Air Lift Pusher Axle, Bridge Axle, Full Locking Rears, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, AC, Body Damage/Rust. Showing 258,385 Miles; 19,838 Hours. Location: Kansas City, MO Serial: 2FZMAZDE86AW23861	







Lot #	2	
Qty	1	
Title	1997 MACK RD690 DUMP TRUCK	
Des.	STARTED ON SITE NOT ROAD TESTED. AIR LEAK NOTED IN DASH. EM7-300, T2070, Camleback Suspension, 216 WB, 16ft Rogers Body, Non Steer Pusher Axle (Less Tires), Steel Wheels, 425/65R22.5; 11R22.5, Steel Fuel Tank, PTO, AC, Broken Exhaust Pipe, Body Damage/Rust. Showing 283,773 Miles; 17,260 Hours. Location: Sylva, NC Serial: 1M2P264C8VM023652	

Lot #	3	
Qty	1	
Title	1995 CATERPILLAR 330B EXCAVATOR	
Des.	NOT TITLED PER STATE REGULATION. NON RUNNER. NO POWER TO IGNITION. NEEDS NEW UNDER CARRIAGE. CAT 3306 Diesel, EROPS, 48in Bucket, Cab Heat, AC, Body Damage/Rust. Showing 11,745 Hours. Location: Byhalia, MS Serial: 06DR00630	







Lot #	4	
Qty	1	
Title	2009 PETERBILT 320 GARBAGE PACKER	
Des.	STARTS WONT BUILD AIR PSI. Cummins ISM, Cruise, Allison 4500RDS Automatic, Hendrickson Haulmax Suspension, 20 FA, 46 RA, 216 WB, Double Frame, McNeilus 3147 Auto Reach Automated Side Loader, Wet Kit, Alum/Steel Wheels, 315/80R22.5; 11R22.5, FEPTO, AC, Rear Camera, AC, AM/FM, Power/Heated Mirrors, Body Damage/Rust. Showing 115,363 Miles; 3,496 Hours. Location: Ankeny, IA Serial: 3BPZL00X49F718158	


Lot #	5	
Qty	1	
Title	2005 MACK CV713 ROLLOFF TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. MISSING KEY. MISSING BODY CABLE CYLINDER. Mack AMI-335 ASET, TM308 - 8 Speed, Camelback Suspension, 275 WB, 60,000 Lb. Capacity Accurate Body, Non Steer Pusher Axle, Steel Wheels, 315/80R22.5, PTO, Missing Rear Lights, Electrical Malfunction Warning Light Illuminated, Body Damage/Rust. Mileage Unavailable. Location: Wilmington, NC Serial: 1M2AG11C15M020882	







Lot #	6	
Qty	1	
Title	2001 KENWORTH W900B REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. ENGINE MISS. Cummins ISM 320V 335 HP, RTO14909ALL, Chalmers Suspension, 20 FA, 46 RA, 248 WB, MTM Bridgemaster Mixer, 100 Gallon Cross Mount Water Tank, Aluminum Fuel Tank, 13,200 Lbs. Bridge Axle - 11r22.5 Steel Disc, Full Locking Rears, Aluminum/Steel Disc Wheels, 425/65R22.5; 11R22.5, AC, PTO, Body Damage/Rust. Showing 327,010 Miles; 7,618 Hours. Location: Pasco, WA Serial: 1NKWL00X81J879434	
Lot #	7	
Qty	1	
Title	2007 MACK MR688S GARBAGE PACKER	
Des.	STARTED ON SITE - NOT ROAD TESTED. DOES NOT MOVE. TRANSMISSION BAD. Mack AI-350 ASET (Oil Leak Noted), Allison 4500RDS Automatic, Camelback Suspension, 210 WB, 40 Yrd. McNeilus Front Loader, Steel Wheels, 315/80R22.5, AC, PTO, Backup Camera, Body Damage/Rust, Missing Right Door Latch. Showing 415,104 Miles; 4,532 Hours. Location: Williamston, NC Serial: 1M2K189C87M034705	
Lot #	8	
Qty	1	
Title	2005 STERLING LT9500 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Oil Residue Buildup At Oil Pan, Engine Oil Level Low, Active Fault Codes - See Report, Body Damage/Rust. Showing 244,673 Miles; 24,974 Hours. Location: Grimes, IA Serial: 2FZHAZDL45AU06242	
Lot #	10	
Qty	1	
Title	2006 STERLING LT9500 REAR MIXER	
Des.	STARTED ON SITE NOT ROAD TESTED. CAT C13, Allison Automatic, Hendrickson Suspension, 20 FA, 46 RA, 250 WB, 11 YRD. MTM Bridgemaster Mixer (Drum Noted At Thin, Chute Position Sensor Missing, Chute Raise Cylinder Hydraulic Line Missing), 150 Gallon Cross Mount Water Tank, 11,020 Lb. Air Lift Pusher Axle, Bridge Axle (Would Not Release), Full Locking Rears, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, AC, ABS Light Illuminated, Body Damage/Rust. Showing 198,655 Miles; 16,848 Hours. Location: Kansas City, MO Serial: 2FZMAZDE16AW23863	
Lot #	11	
Qty	1	
Title	2009 PETERBILT 320 GARBAGE PACKER	
Des.	STARTED ON SITE NOT ROAD TESTED. Cummins ISM, Cruise, Allison 4500RDS Automatic, Hendrickson Haulmax Suspension, 20 FA, 46 RA, 216 WB, Double Frame, McNeilus 3147 Auto Reach Automated Side Loader, Wet Kit, Alum/Steel Wheels, 315/80R22.5; 11R22.5, FEPTO, AC, Rear Camera, AC, AM/FM, Power/Heated Mirrors, Body Damage/Rust. Showing 32,506 Miles; 19,695 Hours. Location: Ankeny, IA Serial: 3BPZL00X09F718156	
Lot #	12	
Qty	1	
Title	2006 GMC 7500 ASPHALT EQUIP	
Des.	STARTED ON SITE - NOT ROAD TESTED. CAT, Spicer 7 Speed, Spring Suspension, 12.0 FA, 21.0 RA, 188 WB, Etnyre 2,000 Gallon Capacity Tank, Steel Wheels, 11R22.5, PTO, Body Damage/Rust. Showing 200,286 Miles. Location: Dallas, Texas Serial: 1GDM7C1C55F525076	

Lot #	13	
Qty	1	
Title	2001 MACK RD688S DUMP TRUCK	
Des.	STARTED ON SITE NOT ROAD TESTED. HARD BLACK TOP NOTED IN DUMP BODY. E7-400, Fuller RTOF14908LL, Camelback Suspension, 18 FA, 216 WB, 16ft Rodgers Body- Aluminum Composition, Non Steer Pusher Axle (Less Tires), Steel Wheels, 425/65R22.5; 11R22.5, Aluminum Fuel Tank, PTO, AC, Body Damage/Rust. Showing 383,633 Miles; 3,562 Hours. Location: Sylva, NC Serial: 1M2P267CX1M056769	
Lot #	14	
Qty	1	
Title	1999 KENWORTH T800 REAR MIXER	
Des.	STARTED ON SITE NOT ROAD TESTED. RUNS ROUGH. ENGINE BLOW BY. MIXER OPERATIONS UNKNOWN. Cummins ISM 305V 335 HP, RTO14908MLL, Chalmers Suspension, 20 FA, 46 RA, 250 WB, 5.38 Ratio, 11 YRD. MTM Mixer, 150 Gallon Cross Mount Water Tank, ZF Gear Box, Cable Controls, 13,200 Lb. Bridge Axle (Would Not Release), Full Locking Rears, Air Lift Pusher, Alum/Steel Disc Wheels, 425/65R22.5; 11R22.5, AC, Body Damage/Rust. Showing 35,847 Miles; 5,635 Hours. Location: Richland, WA Serial: 1NKWL00XXXR825983	
Lot #	15	
Qty	1	
Title	2010 FREIGHTLINER M2 106 GARBAGE PACKER	
Des.	STARTED ON SITE NOT ROAD TESTED. Cummins ISC, Automatic, Spring Suspension, 10 FA, 23 RA, 234 WB, G&S MSL Side Loader, L/R Steering, Steel Wheels, 11R22.5, PTO, AC, Rear Camera, Check Engine Light Illuminated, Dead Batteries, Body Damage/Rust. Showing 105,100 Miles. Location: New Bern, NC Serial: 1FVACXBS2AHZ90028	
Lot #	16	
Qty	1	
Title	2000 PETERBILT 357 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. CAT C10, Eaton 8 Speed LL, Hendrickson Suspension, 18.74 FA, 46 RA, 223 WB, 10.5 Yrd. CBMW Rear Mixer (Thin Drum), Side Mount Water Tank, Steel Wheels, 385/65R22.5; 11R22.5, Aluminum Fuel Tank, PTO, AC, No Key, Body Damage/Rust. Showing 80,233 Miles; 3,501 Hours. Location: Fort Worth, TX Serial: 1NPALT0X3YD519230	
Lot #	17	
Qty	1	
Title	2006 INTERNATIONAL 9900i DAY CAB TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. Cummins ISX 435HP, Eaton 10 Speed, Air Ride Suspension, 12 FA, 40 RA, 215 WB, Air Slide 5th Wheel, Wet Kit, Steel Wheels, 11R22.5, Aluminum Fuel Tank, PTO, AC, Body Damage/Rust. Showing 505,014 Miles; 23,099 Hours. Location: Tyler, TX Serial: 2H5CHAPR76C362819	
Lot #	18	
Qty	1	
Title	2006 STERLING LT9500 REAR MIXER	
Des.	STARTED ON SITE NOT ROAD TESTED. SLOW BUILDING AIR PSI. Mercedes Benz OM 460 LA, Allison Automatic, Hendrickson Suspension, 20 FA, 46 RA, 250 WB, 11 YRD. MTM Mixer, 150 Gallon Cross Mount Water Tank, 11,020 Lb. Air Lift Pusher Axle, Bridge Axle, Full Locking Rears, Alum/Steel Disc Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 225,928 Miles; 21,575 Hours. Location: Kansas City, MO Serial: 2FZMAZCV16AW69663	






Lot #	19	
Qty	1	
Title	2003 CATERPILLAR 242B SKID LOADER	
Des.	NOT TITLED PER STATE REGULATION. NON RUNNER - BAD ENGINE. LESS ATTACHMENT. CAT 3024C T, Body Damage/Rust. Showing 1,895 Hours. Location: Elizabeth City, NC Serial: BXM00606	
Lot #	20	
Qty	1	
Title	1993 INTERNATIONAL 4700 ASPHALT DISTRIBUTOR TRUCK	
Des.	STARTED ON SITE NOT ROAD TESTED. Navistar DTA-360, Spicer 5 Speed W/ 2 Speed Axle, Spring Suspension, 170 WB, 33,200 GVWR, Double Frame, 10ft 4in Rosco Asphalt Distributor Body, FEPTO, Wet Kit, Spoke Wheels, 11R22.5, 50 Gallon Steel Fuel Tank, AC, Body Damage/Rust. Showing 11,764 Miles. Location: Ankeny, IA Serial: 1HTSCPER0PH502523	
Lot #	21	
Qty	1	
Title	2005 INTERNATIONAL 4200 WATER TRUCK	
Des.	NON RUNNER. Oil Seepage At Left Side Of Pan, Transmission Covered In Oil, Body Damage/Rust. Showing 18,122 Miles. Location: Hutchinson, KS Serial: 1HTMPAFP75H166535	
Lot #	22	
Qty	1	
Title	1999 KENWORTH W900 REAR MIXER	
Des.	STARTED ON SITE NOT ROAD TESTED. Cummins ISM 305V 335 HP, RTO14908MLL, Chalmers Suspension, 20 FA, 46 RA, 250 WB, 5.38 Ratio, 11 YRD. MTM Mixer (Chute Position Sensor Missing), 150 Gallon Cross Mount Water Tank, ZF Gear Box, Cable Controls, 13,200 Lb. Bridge Axle (Would Not Release), Full Locking Rears, Air Lift Pusher, Alum/Steel Disc Wheels, 425/65R22.5; 11R22.5, AC, Engine Light Illuminated, Body Damage/Rust. Showing 298,989 Miles; 6,173 Hours. Location: Richland, WA Serial: 1NKWL00X6XR827794	
Lot #	23	
Qty	1	
Title	2011 PETERBILT 320 GARBAGE PACKER	
Des.	STARTED ON SITE NOT ROAD TESTED. Cummins ISL, Allison 4000RDS, Hendrickson Haulmax Suspension, 20 FA, 46 RA, 216 WB, 31 YRD. McNeilus 3147 Auto Reach Automated Side Loader, Wet Kit, Differential Lock, Steel Wheels, 315/80R22.5; 11R22.5, Aluminum Fuel Tank, FEPTO, AC, Rear Camera, Power/Heated Mirrors, AM/FM, Body Damage/Rust. Showing 94,794 Miles; 15,532 Hours. Location: Ankeny, IA Serial: 3BPZL50X9BF127424	
Lot #	24	
Qty	1	
Title	2004 STERLING LT9500 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. CAT C12, Roadranger 9 Speed LL, Hendrickson Suspension, 20 FA, 46 RA, 227 WB, 10.5 Yrd. Kimble Rear Mixer (Thin Drum), Side Mount Water Tank, Steel Wheels, 425/65R22.5; 11R24.5, Aluminum Fuel Tank, PTO, AC, Air Tank Rusted Through Pin Hole Leak, Body Damage/Rust. Showing 138,263 Miles; 17,279 Hours. Location: Fort Worth, TX Serial: 2FZHAZAS44AM89567	








Lot #	25	
Qty	1	
Title	1999 MACK RD688S DUMP TRUCK	
Des.	STARTED ON SITE NOT ROAD TESTED. BLUE SMOKE FROM EXHAUST. HARD BLACKTOP IN BODY. E7-400 (Oil Leaks), Eaton 8LL, Camelback Suspension, 214 WB, 16ft Rogers Body, Non Steer Pusher Axle, Aluminum Wheels, 385/65R22.5, PTO, AC, Body Damage/Rust. Showing 405,407 Miles; 18,623 Hours. Location: Sylva, NC Serial: 1M2P270C1XM047354	
Lot #	26	
Qty	1	
Title	2006 STERLING LT9500 REAR MIXER	
Des.	STARTED ON SITE NOT ROAD TESTED. CAT C13, Allison Automatic, Hendrickson Suspension, 20 FA, 46 RA, 250 WB, 11 YRD. MTM Bridgemaster Mixer, 150 Gallon Cross Mount Water Tank, 11,020 Lb. Air Lift Pusher Axle, Bridge Axle, Full Axle Lock, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, AC, Body Damage/Rust. Showing 177,226 Miles; 17,495 Hours. Location: Kansas City, MO Serial: 2FZMAZDE76AW23852	
Lot #	27	
Qty	1	
Title	2010 FREIGHTLINER M2 106 GARBAGE PACKER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Cummins, Automatic, Spring Suspension, 246 WB, 285 Yrd. G&S MSL Side Loader, L/R Steering, Steel Wheels, 315/80R22.5, PTO, AC, Backup Camera, Dead Batteries, Check Engine Light Illuminated, Body Damage/Rust. Showing 193,659 Miles. Location: New Bern, NC Serial: 1FVHCYBS8AHZ90054	
Lot #	28	
Qty	1	
Title	2010 PETERBILT 388 DAY CAB TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. Cummins ISX 485HP, 13 Speed, Air Ride Suspension, 12 FA, 40 RA, 231 WB, Air Slide 5th Wheel, Wet Kit, Aluminum Wheels, 11R24.5, Dual Aluminum Fuel Tanks, PTO, AC, Body Damage/Rust. Showing 39,194 Miles; 14,034 Hours. Location: Tyler, TX Serial: 1XPWD49X6AD795442	
Lot #	29	
Qty	1	
Title	1997 NUTTHALL LOWBOY TRAILER	
Des.	617in Total Length, 282in Body Length, 102in Body Width, Air Suspension, Steel Wheels, 255/70R22.5, Body Damage/Rust. Location: Fort Worth, TX Serial: 1N9FN483VA128101	
Lot #	30	
Qty	1	
Title	1998 KENWORTH W900B REAR MIXER	
Des.	NON RUNNER. NO BATTERIES. Cummins M-11 280E+ 335 HP, RTO114909MLL, Chalmers Suspension, 20 FA, 42.4 RA, 248 WB, 10.5 Yrd MTM Bridgemaster Mixer, 125 Gallon Cross Mount Water Tank, Aluminum Fuel Tank, 13,200 Lbs. Bridge Axle - 11r22.5 Steel Disc, Full Locking Rears, Aluminum/Steel Disc Wheels, 425/65R22.5; 11R22.5, AC, PTO, Body Damage/Rust, No Key, Missing Battery Box Cover. Showing 63,547 Miles; 9,393 Hours. Location: Pasco, WA Serial: 1NKWL90X7WR769505	






Lot #	31	
Qty	1	
Title	2009 PETERBILT 320 GARBAGE PACKER	
Des.	STARTED ON SITE NOT ROAD TESTED. Cummins ISM, Allion 400RDS Automatic, Hendrickson Haulmaxx Suspension, 20 FA, 40 RA, 226 WB, Double Frame, 31 YRD. McNeilus 3147 Auto Reach Automated Side Loader, Wet Kit, Differential Lock, Steel Wheels, 315/80R22.5; 11R22.5, FEPTO, AC, Rear Camera, AM/FM, Power/Heated Mirrors, Body Damage/Rust. Showing 120,158 Miles; 18,525 Hours. Location: Ankeny, IA Serial: 3BPZL00X19F719705	
Lot #	32	
Qty	1	
Title	2005 STERLING LT9500 REAR MIXER	
Des.	STARTED ON SITE. BAD BATTERIES. BAD RADIATOR. CAT C13, Allison Automatic, Hendrickson Suspension, 20 FA, 46 RA, 250 WB, 11 YRD. MTM Bridgemaster Mixer, 150 Gallon Cross Mount Water Tank, 11,020 Lb. Air Lift Pusher Axle, Bridge Axle, Full Locking Rears, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 239,417 Miles. Location: Kansas City, MO Serial: 2FZMAZDE65AU28288	
Lot #	33	
Qty	1	
Title	2006 INTERNATIONAL 9900I DAY CAB TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. Cummins ISX 435HP, Eaton 10 Speed, Air Ride Suspension, 12 FA, 40 RA, 215 WB, Air Slide 5th Wheel, Wet Kit, Steel Wheels, 11R22.5, Aluminum Fuel Tank, PTO, AC, Body Damage/Rust. Showing 475,148 Miles; 22,128 Hours. Location: Tyler, TX Serial: 2HSCHAPR26C32825	
Lot #	34	
Qty	1	
Title	1999 KENWORTH W900B REAR MIXER	
Des.	NON RUNNER - ENGINE LOCKED. Cummins ISM 305V, EF 9LL, Chalmers Suspension, 20 FA, 46 RA, 11 Yrd MTM Bridgemaster Mixer, 150 Gallon Cross Mount Water Tank, Aluminum Fuel Tank, 13,200 Lbs. Bridge Axle - 11R22.5 Steel Disc, Air Lift Pusher Axle - 255/70R22.5 Aluminum, Full Locking Rears, Aluminum/Steel Disc Wheels, 425/65R22.5; 11R22.5, AC, PTO, Body Damage/Rust. Showing 338,828 Miles; 1,845 Hours. Location: Pasco, WA Serial: 1NKWL00X1XR825984	
Lot #	35	
Qty	1	
Title	2010 FREIGHTLINER M2 106 GARBAGE PACKER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Cummins, Spring Suspension, 236 WB, 20 Yrd. G&S MSL Loader, R/L Steering, Steel Wheels, 315/80R22.5, PTO, AC, Missing Left Accelerator Pedal, Dead Batteries, Check Engine Light Illuminated, Body Damage/Rust. Showing 216,756 Miles. Location: New Bern, NC Serial: 1FVACXBS0AHZ90027	
Lot #	36	
Qty	1	
Title	1998 INTERNATIONAL 9400 WINCH TRUCK	
Des.	UNIT STARTED ON SITE - NOT ROAD TESTED. MISSING CLUTCH LINKAGE - WILL NOT MOVE. Oil Leaks At Front Cover, Left Side Of Block, And Pan/Rear Seal. Transmission Covered In Oil. Service Engine Light Illuminated. Other Warning Lights Illuminated - See Photos. Showing 788,922 Miles; 3,703 Hours. Location: Hutchinson, KS Serial: 2HSFHASR0WC038647	

Lot #	37	
Qty	1	
Title	2002 STERLING LT9501 TRI-AXEL DUMP TRUCK	
Des.	ENGINE BLOW BY. Engine Saturated W/ Oil. Rear Axle Leaks Noted. R/Side Body Rail Broken. Location: Evansville, IN Serial: 2FZHAZAS72AJ67423	
Lot #	38	
Qty	1	
Title	1998 KENWORTH W900 REAR MIXER	
Des.	STARTED ON SITE NOT ROAD TESTED. ENGINE SKIP. ENGINE BLOW BY. Cummins M11 280E+, RTO01909MLL, Chalmers Suspension, 20 FA, 42.4 RA, 250 WB, 11 YRD. MTM Bridgemaster Mixer, 125 Gallon Cross Mount Water Tank, Wet Kit, 13,200 Lb. Bridge Axle (Will Not Release), 11,020 Lb. Air Lift Pusher Axle, Full Locking Rears, Alum/Steel Disc Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 39,217 Miles; 8,142 Hours. Location: Richland, WA Serial: 1NKWL90X9WR769506	
Lot #	39	
Qty	1	
Title	2001 ETNYRE R50TL3 50 TON LOWBOY TRAILER	
Des.	Wooden Floor Boards Rotted Through In Several Places (See Photos), Body Damage/Rust. Location: Dunbar, WV Serial: 1E92769711E111202	
Lot #	40	
Qty	1	
Title	2006 STERLING LT9500 REAR MIXER	
Des.	STARTED ON SITE NOT ROAD TESTED. HEAD GASKET LEAK NOTED. FAN BLOWER MOTOR INOPERABLE. Mercedes Benz OM 460, Automatic, Hendrickson Suspension, 20 FA, 46 RA, 250 WB, 11 YRD. MTM Bridgemaster Mixer, 150 Gallon Cross Mount Water Tank, 11,020 Lb. Air Lift Pusher Axle, Bridge Axle, Full Axle Lock, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 279,421 Miles; 21,457 Hours. Location: Lee Summit, MO Serial: 2FZMAZCV66AW69657	
Lot #	41	
Qty	1	
Title	2001 MACK RD690S ROLLOFF TRUCK	
Des.	NON RUNNER - CLICKS BUT WILL NOT START. Mack E7 300 (Oil Leaks Noted), Automatic, Camelback Suspension, 268 WB, 60,000 Lb. Capacity Gilbreath Body, Steel Wheels, 315/80R22.5, AC, PTO, Body Damage/Rust. Showing 589,270 Miles; 25,645 Hours. Location: Greenville, NC Serial: 1M2P296C61M055167	
Lot #	43	
Qty	1	
Title	2011 PETERBILT 320 GARBAGE PACKER	
Des.	STARTED ON SITE NOT ROAD TESTED. Cummins ISL, Allison 4000RDS, Hendrickson Haulmax Suspension, 20 FA, 46 RA, 216 WB, 31 YRD. McNeilus Auto Reach Automated Side Loader, Wet Kit, Differential Lock, Steel Wheels, 315/80R22.5; 11R22.5, Aluminum Fuel Tank, FEPTO, AC, Rear Camera, Power/Heated Mirrors, AM/FM, Body Damage/Rust. Showing 94,258 Miles; 14,357 Hours. Location: Ankeny, IA Serial: 3BPZL50X0BF127425	






Lot #	44	
Qty	1	
Title	2006 INTERNATIONAL 9900I DAY CAB TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. Cummins ISX 435HP, Eaton 10 Speed, Air Ride Suspension, 12 FA, 40 RA, 216 WB, Air Slide 5th Wheel, Wet Kit, Steel Wheels, 11R22.5, Aluminum Fuel Tank, PTO, AC, Body Damage/Rust. Showing 534,987 Miles; 25,486 Hours. Location: Tyler, TX Serial: 2HSCHAPR76C362822	
Lot #	45	
Qty	1	
Title	1998 GMC C7500 FLATBED TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. CAT, 6 Speed Manual, Spring Suspension, 190 WB, 195in Body, Steel Wheels, 245/75R22.5, AC, Check Engine Light Illuminated, Body Damage/Rust. Showing 360,217 Miles. Location: Fort Worth, TX Serial: 1GDJ7H1C3WJ514334	
Lot #	46	
Qty	1	
Title	1999 KENWORTH W900 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. ENGINE BLOW BY. Cummins ISM 305V, RTO114909MLL, Chalmers Suspension, 20 FA, 46 RA, 250 WB, 11 Yrd MTM Bridgemaster Mixer, 150 Gallon Cross Mount Water Tank, Aluminum Fuel Tank, 13,200 Lbs. Bridge Axle - 11r22.5 Steel Disc, Airlift Pusher Axle With 255/70R22.5 Steel Disc, Full Locking Rears, Aluminum/Steel Disc Wheels, 425/65R22.5; 11R22.5, AC, PTO, Body Damage/Rust. Showing 47,522 Miles; 6,761 Hours. Location: Sunnyside, WA Serial: 1NKWL00X8XR825982	
Lot #	47	
Qty	1	
Title	2008 AUTOCAR WX64 GARBAGE PACKER	
Des.	STARTED ON SITE -NOT ROAD TESTED. Cummins ISM 320 HP, Automatic, Hendrickson Suspension, 20 FA, 46 RA, 187 WB, 40 Yrd. EZ Pack Front Loader, Non Steer Tag Axle, Steel Wheels, 315/80R22.5, AC, PTO, New Components Including Dash And Instruments, Speedometer, And Hour Meter, Body Damage/Rust. Showing 57,651 Miles; 1,715 Hours. Location: Whiteville, NC Serial: 5VCDC6BE78H205741	
Lot #	48	
Qty	1	
Title	2006 STERLING LT9500 REAR MIXER	
Des.	STARTED/RAN BRIEFLY. ENGINE PROTECTION LIGHT ILLUMINATED. DOES NOT BUILD AIR PSI. BAD DRUM. CAT C13, Allison Automatic, Hendrickson Suspension, 20 FA, 46 RA, 250 WB, 11 YRD. MTM Bridgemaster Mixer, 150 Gallon Cross Mount Water Tank, 11,020 Lb. Air Lift Pusher Axle, Bridge Axle, Full Axle Lock, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, AC, Check Engine Light Illuminated, Body Damage/Rust. Showing 253,883 Miles; 23,965 Hours. Location: Olathe, KS Serial: 2FZMAZCV66AW69660	
Lot #	49	
Qty	1	
Title	2002 STERLING LT9501 TRI-AXEL DUMP TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. ENGINE BLOW BY, Oil Seepage Noted At Left Front Corner And Right Rear Of Engine, Front Drive Axle Leaking, Minor Seepage At Rear Axle Service Plug, Ignition Will Not Shut Off Using Key, Body Damage/Rust. Location: Evansville, IN Serial: 2FZHAZAS22AJ67426	







Lot #	50	
Qty	1	
Title	1999 KENWORTH W900 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. ENGINE BLOW BY. Cummins ISM 305V 335 HP, EF 9LL, Chalmers Suspension, 20 FA, 46 RA, 250 WB, 11 Yrd MTM Bridgemaster Mixer, 150 Gallon Cross Mount Water Tank, Aluminum Fuel Tank, 13,200 Lbs. Bridge Axle With 11r22.5 Steel Disc, Airlift Pusher Axle With 255/70R22.5, Full Locking Rears, Aluminum/Steel Disc Wheels, 425/65R22.5; 11R22.5, AC, PTO, AC Compressor Missing Belt, Body Damage/Rust. Showing 15,993 Miles; 4,884 Hours. Location: Sunnyside, WA Serial: 1NKWL00X1XR827802	
Lot #	53	
Qty	1	
Title	1985 CHEVROLET C70 SERVICE TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. Oil Seepage Noted In Multiple Areas. Rear Diff Leaking. Hyrdraulic Oil Leaking On Boom And Controls. Dead Batteries. Body Damage/Rust. Showing 73,967 Miles; 1,326 Hours. Location: Hays, KS Serial: 1GBG7D1F6FV200160	
Lot #	54	
Qty	1	
Title	1995 KENWORTH W900 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. CAT 3176B, RTO14709MLL, Walking Beam/Hendrickson Suspension, 20 FA, 46 RA, 248 WB, 11 Yrd. MTM Bridgemaster Mixer, 125 Gallon Cross Mount Water Tank, Aluminum Fuel Tank, 13,000 Lbs. Bridge Axle With 11R22.5 Steel Disc, 11,020 Lbs. Air Lift Pusher Axle With 255/70R22.5 Steel Disc, Full Locking Rears, Steel Disc Wheels, 425/65R22.5; 11R22.5, PTO, AC, Pusher Axle Did Not Go Down, Engine Tag Painted Over, Body Damage/Rust. Showing 44,885 Miles; 922 Hours. Location: Parker, WA Serial: 1NKWXEEX8SS672550	
Lot #	55	
Qty	1	
Title	2007 AUTOCAR WX64 GARBAGE PACKER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Cummins ISL 330 HP (Oil Leak Noted), Automatic, Hendrickson Suspension, 20 FA, 46 RA, 194 WB, 30 Yrd. McNeilus Front Loader, Non Steer Tag Axle, Steel Wheels, 315/80R22.5, AC, PTO, Backup Camera, Both Cab Locks Are Broken, New Hour Meter, Body Damage/Rust. Showing 281,751 Miles; 195 Hours. Location: Wilmington, NC Serial: 5VCDC6MF07H204743	
Lot #	56	
Qty	1	
Title	2006 STERLING LT9500 REAR MIXER	
Des.	STARTED ON SITE NOT ROAD TESTED. BAD BATTERIES. CAT C13, Allison Automatic, Hendrickson Suspension, 20 FA, 46 RA, 250 WB, 11 YRD. MTM Bridgemaster Mixer, 150 Gallon Cross Mount Water Tank, 11,020 Lb. Air Lift Pusher Axle, Bridge Axle, Full Axle Lock, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, AC, Body Damage/Rust. Mileage Unavailable. Location: Kansas City, MO Serial: 2FZMAZDE36AW23847	
Lot #	57	
Qty	1	
Title	1998 VOLVO WG W/ CALLAHAN LIFT DAY CAB TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. Oil Leak Noted At Pan And Left Side Of Block, Transmission And Fuel Gauges Not Working, Body Damage/Rust. Mileage Unavailable. Location: Byram, MS Serial: 4VGJDEPF6WN860360	






Lot #	58	
Qty	1	
Title	2006 STERLING LT9500 REAR MIXER	
Des.	STARTED ON SITE NOT ROAD TESTED. MIXER FUNCTIONS UNKNOWN. Mercedes Benz OM 460, Automatic, Hendrickson Suspension (Suspension Leaks Noted), 20 FA, 46 RA, 250 WB, 11 YRD. MTM Bridgmaster Mixer, 150 Gallon Cross Mount Water Tank, 11,020 Lb. Air Lift Pusher Axle, Bridge Axle, Full Locking Rears, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 240,269 Miles; 17,601 Hours. Location: Kansas City, MO Serial: 2FZMAZCV46AW69656	
Lot #	59	
Qty	1	
Title	2013 FORD F150 LARIAT CREW CAB 4X4 PICKUP TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. Minor Oil Leak Residue Noted At Rear Seal Area And Transmission. Showing 141,980 Miles. Location: Vernon, CA Serial: 1FTFW1ET3DKE49684	
Lot #	60	
Qty	1	
Title	2011 ISUZU NPR NF2 54 FLATBED TRUCK	
Des.	R/Rear Wheels/Brake Seal Leak Noted, Body Damage/Rust. Showing 351,380 Miles; 10,135 Hours. Location: Tell City, IN Serial: JALC4W168B7001073	
Lot #	61	
Qty	1	
Title	1997 MACK RD690 DUMP TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. WILL NOT BUILD AIR PRESSURE. Mack EM7, Mack Transmission, Camelback Suspension, 216 WB, Spoke Wheels, 425/65R22.5; 11R22.5, PTO, AC, Dead Battery, No Tires On Non Steer Pusher Axle, Warning Lights Illuminated, Body Damage/Rust. Showing 263,431 Miles; 17,308 Hours. Location: Knoxville, TN Serial: 1M2P264C1VM023654	
Lot #	62	
Qty	1	
Title	1996 KENWORTH W900B REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Cummins M11 280E+, RTO14709MLL, Walking Beam/Hendrickson Suspension, 20 FA, 46 RA, 248 WB, 11 Yrd. MTM Bridgmaster Mixer, 125 Gallon Side Mount Water Tank, Aluminum Fuel Tank, 13,000 Lbs. Bridge Axle With 11R22.5 Steel Disc, 11,020 Lbs. Air Lift Pusher Axle With 255/70R22.5 Steel Disc, Full Locking Rears, Aluminum/Steel Disc Wheels, 425/65R22.5; 11R22.5, PTO, AC, Dead Batteries, Air Leak In Cab, Body Damage/Rust. Showing 81,956 Miles; 2,972 Hours. Location: Parker, WA Serial: 1NKWL90X0TS729562	
Lot #	63	
Qty	1	
Title	2007 INTERNATIONAL 7400 GARBAGE PACKER	
Des.	STARTED ON SITE - NOT ROAD TESTED. FRONT REAR ENGINE COVER CRACKED. DT466, Automatic, Hendrickson Suspension, 580 WB, 25 Yrd. Capacity McNeilus Rear Loader, 2 Can Tippers, Steel Wheels, 315/80R22.5, AC, PTO, Backup Camera, Oil Leaking, ABS Light Illuminated. Showing 236,206 Miles; 23,086 Hours. Location: New Bern, NC Serial: 3HTWGAAT97N472044	
Lot #	64	
Qty	1	
Title	2005 VOLVO VHD64B REAR MIXER	
Des.	STARTED ON SITE NOT ROAD TESTED. VE D12- 365 HP, RTO14909ALL, Spring Suspension, 20 FA, 46 RA, 214 WB, 11 YRD. MTM Mixer, Slump Gauge, Electronic Controls, Full Locking Rears, Steel Wheels, AC, Body Damage/Rust. Showing 56,783 Miles. Location: Saint Louis, MO Serial: 4V5KC9GF65N390840	

Lot #	65	
Qty	1	
Title	2003 MACK CV713 CAB & CHASSIS	
Des.	NON RUNNER - ENGINE TURNS OVER BUT WON'T START. MOTOR IS BLOWN. Mack E7-400 E-TECH LSR, Mack T310M 10 Speed, 265 WB, Double Frame, Dual Aluminum 80 Gallon Fuel Tanks, Aluminum/Steel Wheels, 315/80R22.5, AC, PTO, Body Damage/Rust. Mileage Unavailable. Location: Bardstown, KY Serial: 1M2AG11C83M002828	
Lot #	66	
Qty	1	
Title	1995 KENWORTH W900 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. CAT 3176 325 HP, RTO14709MLL, Walking Beam/Hendrickson Suspension, 20 FA, 46 RA, 248 WB, 11 Yrd. MTM Bridgemaster Mixer, 125 Gallon Cross Mount Water Tank, Aluminum Fuel Tank, 13,000 Lbs. Bridge Axle With 11R22.5 Steel Disc, 11,020 Lbs. Air Lift Pusher Axle With 255/70R22.5 Steel Disc, Full Locking Rears, Aluminum/Steel Disc Wheels, 425/65R22.5; 11R22.5, PTO, AC, Bridge Axle And Pusher Axle Do Not Go Down, Body Damage/Rust. Showing 209,857 Miles; 4,828 Hours. Location: Parker, WA Serial: 1NKWXEEX1SS672552	
Lot #	68	
Qty	1	
Title	2007 MACK CHN613 DAY CAB TRUCK	
Des.	NON RUNNER - ENGINE BLOWN. Oil Seepage In Several Places. Brake and Reverse Lights Do Not Work. Body Damage/Rust. Showing 431,033 Miles; 16,105 Hours. Location: Hays, KS Serial: 1M1AJ06YX7N007758	
Lot #	69	
Qty	1	
Title	1986 FORD F700 WATER TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. GM 8.2L Diesel, 5 Speed Manual, Spring Suspension, 175 WB, Steel Wheels, 11R20, PTO, Dead Batteries, Body Damage/Rust. Showing 132,694 Miles. Location: Fort Worth, TX Serial: 1FDXK84N2GVA14696	
Lot #	71	
Qty	1	
Title	2010 MACK MRU613 GARBAGE PACKER	
Des.	NON RUNNER. BAD ENGINE. Mack MP7, Automatic, Camelback Suspension, 208 WB, 30 Yrd. McNeilus Front Loader, Non Steer Pusher Axle, Steel Wheels, 315/80R22.5, PTO, AC, Rear Camera, Dash Is Apart, Body Damage/Rust. Mileage Unavailable. Location: Newmanstown, PA Serial: 1M2AV02C1AM006098	
Lot #	72	
Qty	1	
Title	2005 STERLING LT9500 REAR MIXER	
Des.	STARTED ON SITE NOT ROAD TESTED. MIXER FUNCTIONS UNKNOWN. DOES NOT BUILD AIR PSI- AIR COMPRESSOR DISCONNECTED. L/FRONT AXLE MISSING. CAT C13 (Oil Fill Cap Missing), Allison Automatic, Hendrickson Suspension, 20 FA, 46 RA, 250 WB, 11 YRD. MTM Bridgemaster Mixer, 150 Gallon Cross Mount Water Tank, 11,020 Lb. Air Lift Pusher Axle, Bridge Axle, Full Axle Lock, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, PTO, AC, Check Engine Light Illuminated, Body Damage/Rust. Showing 246,132 Miles; 21,005 Hours. Location: Kansas City, MO Serial: 2FZMAZDEX5AU28276	








Lot #	73	
Qty	1	
Title	2002 STERLING L7500 DUMP TRUCK	
Des.	STARTED ON SITE NOT ROAD TESTED. CAT 3126, Automatic, Spring Suspension, 16 FA, 23 RA, 156 WB, 9ft Heil Dump Body 5 YRD Capacity (3ft Sides), Wet Kit, Steel Wheels, 315/80R22.5; 11R22.5, FEPTO, AC, AM/FM/CASS, Pintle Hitch, Body Damage/Rust. Showing 59,674 Miles; 4,895 Hours. Location: Ankeny, IA Serial: 2FZAATAK02AJ83865	
Lot #	74	
Qty	1	
Title	2006 STERLING LT9500 REAR MIXER	
Des.	STARTED ON SITE NOT ROAD TESTED. BAD BATTERIES. KNOWN TRANSMISSION ISSUE. CAT C13, Allison Automatic, Hendrickson Suspension, 20 FA, 46 RA, 250 WB, 11 YRD. MTM Bridgemaster Mixer, 150 Gallon Cross Mount Water Tank, 11,020 Lb. Air Lift Pusher Axle, Bridge Axle, Full Axle Lock, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, AC, Body Damage/Rust. Showing 236,711 Miles; 23,008 Hours. Location: Kansas City, MO Serial: 2FZMAZDE96AW23853	
Lot #	75	
Qty	1	
Title	2004 FREIGHTLINER FL80 GARBAGE PACKER	
Des.	STARTED ON SITE - NOT ROAD TESTED. NEEDS MAJOR WORK DONE TO HOPPER. CAT 3126, Automatic, Spring Suspension, 10 FA, 23 RA, 205 WB, 20 Yrd. Heil Rear Loader, 1 Can Tipper, Steel Wheels, 315/80R22.5, PTO, AC, Body Ejector Blade Worn Out, 1 Can Tipper Missing Parts, Batteries Dead, Body Damage/Rust. Showing 322,286 Miles. Location: Wilmington, NC Serial: 1FVABTAK44HM50536	
Lot #	76	
Qty	1	
Title	2000 GMC C7500 CAB & CHASSIS	
Des.	UNIT STARTED ON SITE - NOT ROAD TESTED. CAT 3126, 5 Speed Manual, Spring Suspension, 11.000 FA, 19.000 RA, 161 WB, Steel/Aluminum Wheels, 11R22.5, PTO, AC, Water Tank Removed, Body Damage/Rust. Showing 33,711 Miles. Location: Fort Worth, TX Serial: 1GDL7H1C0YJ512438	
Lot #	77	
Qty	1	
Title	2005 FORD F450 SERVICE TRUCK	
Des.	CRANKS- WONT START. Oil Leaks Noted At Pan Seal, Rear Seal, Engine And Transmission. Seepage Noted At Brake Cylinder. Air Cooler Fins Bent. Showing 278,282 Miles. Location: Tell City, IN Serial: 1FDXF46P15ED07692	
Lot #	78	
Qty	1	
Title	1993 KENWORTH W900B REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Cummins L10 300 HP, EF 7LL, Walking Beam Suspension, 20 FA, 42.24 RA, 250 WB, 10.5 Yrd. MTM Bridgemaster Mixer, 125 Gallon Cross Mount Water Tank, Aluminum Fuel Tank, 13,200 Lbs. Bridge Axle With 11R22.5 Steel Disc, Air Lift Pusher Axle With No Wheels/Tires, Full Locking Rears, Aluminum/Steel Disc Wheels, 425/65R22.5; 11R22.5, PTO, Bridge Axle Did Not Go Back Up, Missing Fuel Cap, Body Damage/Rust, Battery Box Cover Missing. Showing 156,557 Miles; 8,851 Hours. Location: Pasco, WA Serial: 1NKWL50X3PS597914	






Lot #	79	
Qty	1	
Title	2006 INTERNATIONAL 4300 CONTAINER DELIVERY TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. International DT466E, Automatic, Spring Suspension, 153 WB, Steel Wheels, 11R22.5, AC, PTO, Pins For Leavers Have Been Removed And Disconnected, Body Is Broken, ABS Warning Light Illuminated, Body Damage/Rust. Showing 393,827 Miles. Location: Graham, NC Serial: 1HTMMAAL86H205051	
Lot #	80	
Qty	1	
Title	2004 STERLING LT9500 REAR MIXER	
Des.	STARTED ON SITE NOT ROAD TESTED. DOES NOT BUILD AIR PSI- SEE VIDEO. BAD BATTERIES. CAT C13, Allison Automatic, Hendrickson Suspension, 20 FA< 46 RA, 250 WB, 11 YRD. MTM Bridgmaster Mixer, 150 Gallon Cross Mount Water Tank, 11,020 Lb. Air Lift Pusher Axle, Bridge Axle, Alum/Steel Disc Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Location: Kansas City, MO Serial: 2FZMAZDE14AN39202	
Lot #	81	
Qty	1	
Title	1987 FORD F800 WATER TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. Oil Leak Noted At Rear Of Transmission. Body Damage/Rust. Showing 74,161 Miles; 7,532 Hours. Location: Grand Junction, CO Serial: 1FDXT84A4HVA67511	
Lot #	82	
Qty	1	
Title	1989 KENWORTH W900 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Cummins L10 300 HP, EF 7LL, Walking Beam Suspension, 20 FA, 38 RA, 260 WB, Cross Mount Water Tank, Aluminum Fuel Tank, 13,000 Lbs. Bridge Axle With 11R22.5 Steel Disc, Air Lift Pusher Axle With 255/70R22.5 Aluminum, Steel Disc Wheels, 425/65R22.5; 11R22.5, PTO, Dead Battery, Body Damage/Rust. Showing 72,573 Miles; 217 Hours. Location: Pasco, WA Serial: 1NKWL50X5KS527310	
Lot #	83	
Qty	1	
Title	2007 MACK MR688S GARBAGE PACKER	
Des.	STARTED ON SITE - NOT ROAD TESTED. BAD BATTERY. Oil Leaks Noted. Mack, Automatic, Camelback Suspension, 11.5 FA, 40 RA, 183 WB, 25 Yrd. EZ Pack Rear Loader, 1 Can Tipper, Upper Winch, Steel Wheels, 11R22.5, AC, PTO, Backup Camera, Missing Right Side Wiper Blade, Body Damage/Rust. Showing 282,380 Miles; 8,590 Hours. Location: Newmanstown, PA Serial: 1M2K189C57M036783	
Lot #	84	
Qty	1	
Title	2002 MACK RD688S CAB & CHASSIS	
Des.	STARTED ON SITE NOT ROAD TESTED. E7-350, T2090, Camelback Suspension, 293 WB., Double Frame, Steel Wheels, 315/80R22.5, Steel Fuel Tank, PTO, AC, Body Damage/Rust. Showing 742,546 Miles; 6,126 Hours. Location: Hampton, VA Serial: 1M2P267C12M064504	







Lot #	85	
Qty	1	
Title	2000 INTERNATIONAL 4700 DUMP TRUCK	
Des.	STARTED ON SITE NOT ROAD TESTED. T444E, Automatic, Spring Suspension, 16 FA, 23 RA, 152 WB, Double Frame, 9ft Dump Body (2.5ft Sides), Snow Plow, Wet Kit, Steel Wheels, 315/80R22.5; 11R22.5, FEPTO, AC, Pintle Hitch, AM/FM, Body Damage/Rust. Showing 62,302 Miles; 5,942 Hours. Location: Ankeny, IA Serial: 1HTSCABR8YH279389	
Lot #	86	
Qty	1	
Title	1989 KENWORTH W900B REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. NO DRUM. Cummins L10, RTO11707LL, Walking Beam Suspension, 18 FA, 38 RA, 260 WB, 150 Gallon Cross Mount Water Tank, Aluminum Fuel Tank, 13,000 Lbs. Bridge Axle With 11R22.5 Steel Disc, Air Lift Pusher Axle With 255/70R22.5 Aluminum, Steel Disc Wheels, 425/65R22.5; 11R22.5, PTO, Body Damage/Rust, Battery Box Cover Missing. Showing 43,280 Miles; 13,700 Hours. Location: Pasco, WA Serial: 1NKWL50X2KS520055	
Lot #	87	
Qty	1	
Title	2010 AUTOCAR ACX GARBAGE PACKER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Cummins ISL 365, Automatic, Hendrickson Suspension, EZ Pack 40 Yrd. Capacity Front Loader, 20 FA, 46 RA, 187 WB, Non Steer Tag Axle, Steel Wheels, 315/80R22.5, AC, PTO, Backup Camera, Dead Battery, Body Damage/Rust. Showing 268,055 Miles; 31,126 Hours. Location: Newport, NC Serial: 5VCACLJF9AH210764	
Lot #	88	
Qty	1	
Title	2006 STERLING LT9500 REAR MIXER	
Des.	STARTED/RAN BRIEFLY. ANTIFREEZE NOTED IN ENGINE. ENGINE SHUT DOWN WARNING ILLUMINATED. DOES NOT BUILD AIR PSI. CAT C13, Allison Automatic, Hendrickson Suspension, 20 FA, 46 RA, 250 WB, 11 YRD. MTM Bridgemaster Mixer, 150 Gallon Cross Mount Water Tank, 11,020 Lb. Air Lift Pusher Axle, Bridge Axle, Full Axle Lock, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, AC, Body Damage/Rust. Showing 253,883 Miles; 23,965 Hours. Location: Kansas City, MO Serial: 2FZMAZDE76AW23849	
Lot #	89	
Qty	1	
Title	1992 FORD F350 CLASS 2B SERVICE TRUCK	
Des.	Oil Leaks Noted At Engine And Power Steering Gear Box. Air Intake Tube Missing, Dash Loose; Missing Components, Radio Inop, AC Inop. Location: Evansville, IN Serial: 2FDLF47M3NCA13266	
Lot #	90	
Qty	1	
Title	2004 STERLING LT9500 REAR MIXER	
Des.	UNKNOWN RUNNING CONDITION BAD BATTERIES. CAT C13, Automatic, Hendrickson Suspension, 20 FA, 46 RA, 250 WB, 11 YRD. MTM Bridgemaster Mixer (Bolts Missing In Drum Hatch), 150 Gallon Cross Mount Water Tank, 11,202 Lb. Air Lift Pusher Axle, Bridge Axle, Alum/Steel Disc Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Mileage Unavailable. Location: Kansas City, KS Serial: 2FZMAZDE44AN39212	


Lot #	91	
Qty	1	
Title	2006 MACK MR688S GARBAGE PACKER	
Des.	STARTED ON SITE - NOT ROAD TESTED. ENGINE SKIP. HYDRAULIC OIL LEAKS. Mack, Automatic, Camelback Suspension, 214 WB, 31 Yrd. EZ Pack Rear Loader, 1 Can Tipper, Upper Winch, Non Steer Pusher Axle, Steel Wheels, 315/80R22.5, PTO, AC, Backup Camera, Electrical Warning Light Illuminated, ABS Warning Light Illuminated, Body Damage/Rust (Rust Holes On Body). Mileage Unavailable; Showing 20,683 Hours. Location: Newmanstown, PA Serial: 1M2K189CX6M029830	
Lot #	93	
Qty	1	
Title	1985 FRUEHAUF 24FT END DUMP TRAILER	
Des.	Hydraulic Hose Leaking. Body Damage/Rust. Location: Hays, KS Serial: 1H4D02328FF003002	
Lot #	94	
Qty	1	
Title	2002 MACK CV513 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. UNABLE TO GET MIXER SYSTEM TO FUNCTION. Mack E7 330/350, EF 9LL, Hendrickson Suspension, 20 FA, 38 RA, 250 WB, 11 Yrd MTM Bridgemaster Mixer, Cross Mount Water Tank, Aluminum Fuel Tank, 13,200 Lbs. Bridge Axle - 11R22.5 Steel Disc, Air Lift Pusher Axle- 255/70R22.5 Aluminum, Axle Lock, Aluminum/Steel Disc Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 313,894 Miles; 29,415 Hours. Location: Pasco, WA Serial: 1M2AG03C42M001116	
Lot #	95	
Qty	1	
Title	2004 MACK MR688S GARBAGE PACKER	
Des.	CRANKS- WONT START W/ STARTING FLUID. FUEL LINES DISCONNECTED AT PUMP, FUEL CAP MISSING. L/DOOR MISSING. AI-300 ASET, Allison 4560P, Camelback Suspension, 233 WB, 32 YRD. McNeilus Rear Loader (Info Tag Missing), Single Can Tipper, Steel Wheels, 315/8R22.5, PTO, AC, Body Damage/Rust. Showing 136,161 Miles; 3,869 Hours. Location: New Bern, NC Serial: 1M2K195C74M023766	
Lot #	96	
Qty	1	
Title	2006 STERLING LT9500 REAR MIXER	
Des.	NON RUNNER. CAT C13, Allison Automatic, Hendrickson Suspension, 20 FA, 46 RA, 250 WB, 11 ZYRD. MTM Bridgemaster Mixer, 150 Gallon Cross Mount Water Tank, 11,020 Lb. Air Lift Pusher Axle, Bridge Axle, Full Axle Lock, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, AC, Body Damage/Rust. Mileage Unavailable. Location: Kansas City, MO Serial: 2FZMAZDEX6AW23845	
Lot #	97	
Qty	1	
Title	1993 PETERBILT 357 DUMP TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. Oil Leaks Noted At Front Cover, Left Side Of Block, And Pan/Rear Seal, Right Side Of Fuel Tank Damaged, Turbo Makes A Whistling Noise, Body Damage/Rust. Showing 603,375 Miles; 11,263 Hours. Location: Wichita, KS Serial: 1XPAXB0X9PN328506	

Lot #	98	
Qty	1	
Title	2002 PETERBILT 357 REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Cummins ISL 310 HP, EF 9LL, Hendrickson Suspension, 20 FA, 34 RA, 260 WB, 10.5 Yrd MTM Bridgmaster Mixer, 150 Gallon Cross Mount Water Tank, Aluminum Fuel Tank, 13,000 Lbs. Bridge Axle With 11r22.5 Steel Disc, 11,020 Lbs. Air Lift Pusher Axle With 255/70R22.5 Steel Disc, Air Lift Pusher Axle With 255/70R22.5 Aluminum, Axle Lock, Aluminum/Steel Disc Wheels, 425/65R22.5; 11R22.5, PTO, AC, Rear Suspension Issues, Body Damage/Rust. Showing 214,574 Miles; 1,618 Hours. Location: Sunnyside, WA Serial: 1NPAL59X22D575133	
Lot #	99	
Qty	1	
Title	2005 INTERNATIONAL 7600 6X4 CAB & CHASSIS	
Des.	NON RUNNER. CAT C-11, Eaton Fuller Automatic, Spring Ride Suspension, 278 WB, Double Frame, Steel Wheels, 315/80R22.5; 11R22.5, Dual Steel Fuel Tanks, PTO, AC, Body Damage/Rust. Mileage Unavailable. Location: Norfolk, VA Serial: 1HTWYSAT25J145696	
Lot #	100	
Qty	1	
Title	2005 MACK CT713 REAR MIXER	
Des.	NON RUNNER. OIL LEAK NOTED AT ENGINE, REAR SEAL AND TRANSMISSION. COOLANT NOT PRESENT IN RESERVOIR. HOOD MISSING. LESS BATTERIES. AMI-335 ASET, TM308, 22 FA, 44 RA, 10.5 YRD. Terex Advance Mixer, Side Mount Water Tank, Aluminum Wheels, 425/65R22.5; 12R22.5, AC, Power Steering, Radio Removed W/ Truck, Body Damage/Rust. Mileage Unavailable. Location: Tampa, FL Serial: 1M2AL02C95M001162	
Lot #	101	
Qty	1	
Title	1998 PETERBILT 357 ROLLOFF TRUCK	
Des.	NON RUNNER. COULD NOT GET TO CRANK OVER JUMP AT STARTER. POWER STEERING LEAKING. CAT 3306, Eaton 8LL, Hendrickson Suspension, 18 FA, 44 RA, 257 WB, 60,000 Lbs. Capacity Gilbreath Body, Pusher Axle, Steel Wheels, 11R22.5, AC, PTO, No Key, Body Damage/Rust. Showing 898,319 Miles. Location: Piedmont, SC Serial: 1NPALA0XXWN462293	
Lot #	103	
Qty	1	
Title	2001 MACK MR690S GARBAGE PACKER	
Des.	TITLE BRANDED RECONSTRUCTED. STARTED ON SITE - NOT ROAD TESTED. BODY WILL NOT OPERATE - MISSING HYDRAULIC FILTER. Mack, Automatic, Camelback Suspension, 214 WB, 31 Yrd. EZ Pack Rear Loader, 1 Can Tipper, Upper Winch, Non Steer Pusher Axle, Steel Wheels, 315/80R22.5 (L/Front Flat), PTO, AC, Body Damage/Rust. Mileage Unavailable; Showing 35,985 Hours. Location: Newmantown, PA Serial: 1M2K185C91M008370	
Lot #	104	
Qty	1	
Title	2005 STERLING LT9500 REAR MIXER	
Des.	NON RUNNER. ENGINE DISASSEMBLED. CAT C13, Allison Automatic, Hendrickson Suspension, 20 FA, 46 RA, 250 WB, 11 YRD. MTM Bridgmaster Mixer, 150 Gallon Cross Mount Water Tank, 11,020 Lb. Air Lift Pusher Axle, Bridge Axle, Full Axle Lock, Aluminum/Steel Wheels, 425/65R22.5; 11R22.5, AC, Body Damage/Rust. Mileage Unavailable. Location: Kansas City, MO Serial: 2FZMAZDE45AU28287	

Lot #	105	
Qty	1	
Title	2000 CHEVROLET 3500HD FLATBED TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. Vortec 5.7L 8 Cyl Gasoline, 5 Speed Manual, Spring Suspension, 135 WB, 110in Body, Steel Wheels, 235/85R16, AC, Body Damage/Rust. Showing 122,325 Miles. Location: Fort Worth, TX Serial: 1GBJC34R4YF402686	
Lot #	106	
Qty	1	
Title	2004 MACK DM688S REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. Oil Leaks Noted At Side And Read Of Transmission And Both Sides Of Engine. Body Damage/Rust. Location: Ft. Myers, FL Serial: 1M2B212C74M005030	
Lot #	107	
Qty	1	
Title	2006 INTERNATIONAL 7400 GARBAGE PACKER	
Des.	NON RUNNER. CRANKS - WILL NOT START. International DT570, Automatic, Hendrickson Suspension, 254 WB, 25 Yrd. Heil Durapack 5000 Rear Loader, 1 Can Tipper, Steel Wheels, 315/80R22.5, AC, PTO, Backup Camera, Body Damage/Rust. Showing 265,239 Miles; 24,540 Hours. Location: Greenville, NC Serial: 1HTWGAZR66J224716	
Lot #	108	
Qty	1	
Title	1999 MACK RD688S CAB & CHASSIS	
Des.	STARTED ON SITE - NOT ROAD TESTED. ENGINE SKIP. E7-350 Reman (Oil Leak Noted), RTOF14908LL, Hendrickson Suspension, 20 FA, 265 WB, Double Frame, Steel Wheels, 12R22.5, Dual Steel Fuel Tanks, PTO, AC, No Key, Missing Several Components Including - Dash, Batteries, A/C Compressor, And Coolant Tank, Body Damage/Rust. Mileage Unavailable. Location: Concord, NC Serial: 1M2P267C6XM047897	
Lot #	109	
Qty	1	
Title	1996 PETERBILT 330 DUMP TRUCK	
Des.	STARTED ON SITE - NOT ROAD TESTED. Oil Seepage Noted At Pan. Clearance Inop., Tachometer Does Not Work, Body Damage/Rust. Showing 230,929 Miles; 3222 Hours. Location: Wichita, KC Serial: 1XPNFL9X5TN398070	
Lot #	110	
Qty	1	
Title	1996 MACK RD688S REAR MIXER	
Des.	STARTED ON SITE NOT ROAD TESTED. ENGINE BLOW BY. E7-350, EF 9LL, Walking Beam Suspension, 20 FA, 46 RA, 250 WB, 13 RD. Kimble Bridge Mixer System, 90 Gallon Cross Mount Water Tank, Dual 11,020 Lb. Air Lift Pusher Axles, Bridge Axle, Aluminum/Steel Disc Wheels, 425/65R22.5; 11R22.5, Aluminum Fuel Tank, PTO, AC, Body Damage/Rust. Showing 323,848 Miles; 14,327 Hours. Location: Richland, WA Serial: 1M2P267C9TM027220	
Lot #	112	
Qty	1	
Title	1995 TIMPTE 301A PUP TRAILER	
Des.	Oil Noted On Lower Part Of Hydraulic Piston. Oil Drips On Frame. Body Damage/Rust. Location: Telluride, CO Serial: 1TDE23625SC088104	

Lot #	113	
Qty	1	
Title	2008 FORD F350 SUPERDUTY MECHANICS TRUCK	
Des.	NON RUNNER. NO BATTERIES, INTAKE DISASSEMBLED. Ford 6.4L 8 Cyl Diesel, Automatic, Spring Suspension, 5,250 FA, 9,750 RA, 176 WB, 112in Body, Steel Wheels, 245/75R17, AC, PW, PL, PM, Air Compressor Included - Cranks But Wont Start, Check Engine Light Illuminated, Body Damage/Rust. Showing 210,145 Miles. Location: Fort Worth, TX Serial: 1FDWW36R58EE32352	
Lot #	114	
Qty	1	
Title	1996 MACK RD688S REAR MIXER	
Des.	STARTED ON SITE NOT ROAD TESTED. E7-350, EF 9LL, Walking Beam Suspension, 20 FA, 46 RA, 250 WB, 13 RD. Kimble Bridge Mixer System, 90 Gallon Cross Mount Water Tank, Dual 11,020 Lb. Air Lift Pusher Axles, Bridge Axle, Aluminum Wheels, 425/65R22.5; 11R22.5, Aluminum Fuel Tank, PTO, AC, Body Damage/Rust. Showing 282,539 Miles; 26,013 Hours. Location: Richland, WA Serial: 1M2P267C5TM024752	
Lot #	115	
Qty	1	
Title	2001 MACK LEU613 GARBAGE PACKER	
Des.	CRANKS WONT START. AIR HOSE OFF TURBO. AIR CLEANER MISSING. DUAL CAN TIPPERS MISSING. EM7-300 E-TECH LSR, Allison HD4560P, Camelback Suspension, 210 WB, 25 YRD. McNeilus Rear Loader, L/R Steering, Steel Wheels, 315/80R22.5, PTO, AC, Rear Camera, Dead Batteries, Body Damage/Rust. Showing 327,696 Miles; 8,868 Hours. Location: New Bern, NC Serial: 1M2AC07C71M005536	
Lot #	116	
Qty	1	
Title	1998 MACK DM690S CAB & CHASSIS	
Des.	NON RUNNER. WOULD NOT CRANK - HAS ELECTRICAL ISSUES, Oil Leaks Noted. EM7-300, T2070, Camelback Suspension, 245 WB, Double Frame, Steel Wheels, 315/80R22.5, Steel Fuel Tank, PTO, AC, Dash Is Apart, Missing R/Door Glass, Body Damage/Rust. Showing 892,598 Miles; 40,052 Hours. Location: Concord, NC Serial: 1M2B209C1WM023204	
Lot #	117	
Qty	1	
Title	1998 MACK RD688S ROLLOFF TRUCK	
Des.	NON RUNNER. ENGINE DOES NOT TURN OVER - LOCKED UP. DRIVE LINE REMOVED. FUEL CAP MISSING. DASH APART AND COMPONENTS MISSING. E7-350, Fuller RTOF14908LL, Camelback Suspension, 255 WB, 60,000 Lb. Capacity Galbreath Body, Steel Wheels, 315/80R22.5, PTO, AC, Missing Several Components Including Tail Lights, Body Damage/Rust. Showing 784,009 Miles; 37,743 Hours. Location: Concord, NC Serial: 1M2P267C9WM041140	
Lot #	118	
Qty	1	
Title	2002 MACK CV513 REAR MIXER	
Des.	UNKNOWN RUNNING CONDITION - NO BATTERIES. Mack E7 330/350, EF 9LL, Hendrickson Suspension, 20 FA, 38 RA, 250 WB, 11 Yrd MTM Bridgmaster Mixer, 125 Gallon Cross Mount Water Tank, Aluminum Fuel Tank, 13,200 Lbs. Bridge Axle With 11r22.5 Steel Disc, 11,020 Lbs. Air Lift Pusher Axle With 255/70R22.5 Steel Disc, Aluminum/Steel Disc Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Mileage Unavailable. Location: Pasco, WA Serial: 1M2AG03C62M001117	

Lot #	119	
Qty	1	
Title	2001 INTERNATIONAL 9200 DAY CAB TRUCK	
Des.	NON RUNNER. CAT C12, Meritor 10 Speed, Air Suspension, 12 FA, 52 RA, 209 WB, Dual Aluminum Fuel Tanks - 84 Gallons, Aluminum Wheels, 11R22.5, AC, PTO, Wet Kit, Body Damage/Rust. Showing 792,225 Miles. Location: Hampton, VA Serial: 2HSCEAXR81C002444	
Lot #	120	
Qty	1	
Title	2008 UTILITY TANKER TRAILER	
Des.	NOT TITLED PER STATE REGULATION. 147in Total Length, 84in Body Length, 84in Body Width, Steel Wheels, 7R15 (Both Dry Rotted), Hitch, Body Damage/Rust. Location: Fort Worth, TX Serial: N/A	
Lot #	121	
Qty	1	
Title	1997 VOLVO WG64F DUMP TRUCK	
Des.	NON RUNNER - DEAD BATTERIES. Oil Leaking At Oil Pan, Right Side Of Block, And Front Of Engine. Body Damage/Rust. Mileage Unavailable; Showing 1,584 Hours. Location: Hutchinson, KS Serial: 4VHJCCFE2VR857345	
Lot #	122	
Qty	1	
Title	2004 MACK DM690S REAR MIXER	
Des.	STARTED ON SITE - NOT ROAD TESTED. BAD TRANSMISSION- ONLY MOVES IN REVERSE. Oil Buildup Noted At Bottom Of Transmission, Oil Pan, And Hose/Pipe. Evidence Of Engine Blow By Noted At Oil Fill Tube (See Video). ABS Warning Light Illuminated. Electrical Malfunction Light Illuminated. Body Damage/Rust. Showing 206,843 Miles; 22,814 Hours. Location: Miami, FL Serial: 1M2B209C64M029948	
Lot #	123	
Qty	1	
Title	2008 MACK MR688S GARBAGE PACKER	
Des.	STARTED ON SITE - NOT ROAD TESTED. ENGINE ONLY RAN BRIEFLY - HAS NO COOLANT. HYDRAULIC LINES NOT CONNECTED. DRIVE LINE REMOVED. TRUCK WAS ROLLED ON RIGHT SIDE. BODY APART FROM CAB AND CHASSIS - BOTH MUST GO TOGETHER. Mack MP7, Automatic, Camelback Suspension, 212 WB, 28 Yrd. Heil Front Loader, Steel Wheels, 315/80R22.5 (R/Rear Flat With Bent Rim), PTO, AC, Missing Body Controls, Missing Head Lights, Frame Damage At Rear, Muffler Broken, Fuel Tank Damaged, Warning Lights Illuminated, Dead Batteries, Body Damage/Rust. Showing 382,039 Miles; 20,383 Hours. Location: Piedmont, SC Serial: 1M2AV04C98M001545	
Lot #	124	
Qty	1	
Title	1991 INTERNATIONAL 4700 CAB & CHASSIS	
Des.	STARTED ON SITE - NOT ROAD TESTED. Oil Seepage Noted Around Bottom Of Oil Pan. Showing 109,883 Miles; 6,171 Hours. Location: Grand Junction, CO Serial: 1HTGHN6R2MH392483	
Lot #	125	
Qty	1	
Title	2001 G&H 8530 ROLLOFF TRAILER	
Des.	38ft length, 96in Width, 20,000 Lb. Capacity, Steel Composition, Steel Wheels, 235/85R16, Pintle Hitch, Body Damage/Rust. Location: Summerville, SC Serial: 1G9CT37231A116002	

Lot #	126	
Qty	1	
Title	1998 FORD LT9511 REAR MIXER	
Des.	STARTED ON SITE NOT ROAD TESTED. HYDRAULIC REMOVED W/ TRUCK. Cummins M11 280E+, Eaton Fuller 9LL, Hendrickson Suspension, 20 FA, 40 RA, 248 WB, 11 YRD. MTM Bridgemaster Mixer, 150 Gallon Cross Mount Water Tank, Wet Kit, 11,020 Air Lift Pusher Axle, 11,020 Lb. Bridge Axle, Full Locking Rears, Alum/Steel Disc Wheels, 425/65R22.5; 11R22.5, PTO, AC, Body Damage/Rust. Showing 264,160 Miles; 22,779 Hours. Location: Richland, WA Serial; 1FDZZ96P6WVA38992	
Lot #	127	
Qty	1	
Title	2002 MACK MR688S GARBAGE PACKER	
Des.	NON RUNNER - KNOWN ENGINE PROBLEMS. MISSING PARTS. Mack E7-350 E-TECH LSR (Oil Leaks Noted), Allison HT740RS Automatic, Bogey Suspension, 179 WB, 28 Yrd. Heil Front Loader, Steer Tag Axle - No Tires, Steel Wheels, 315/80R22.5, PTO, AC, Missing Hydraulic Filter, Missing Front Forks, Missing Left Wiper Assembly, Body Damage/Rust. Showing 28,096 Miles; 3,717 Hours. Location: Wilmington, NC Serial: 1M2K195C92M019635	
Lot #	128	
Qty	1	
Title	1983 INTERNATIONAL FLATBED TRAILER	
Des.	Body Damage/Rust. Location: Hays, KS Serial: 1JK0DT203DA090007	
Lot #	130	
Qty	1	
Title	2005 MACK DM688S REAR MIXER	
Des.	NON RUNNER. NO POWER TO CHECK ELECTRICAL. Unit Has Been Sitting For Over One Year. Oil Seepage On Both Sides Of Engine, Coolant Not Visible In Reservoir, Drive Axle Pinion Leaks, Many Parts Removed, Two Rear Tires Flat, Body Damage/Rust. Mileage Unavailable. Location: Tampa, FL Serial: 1M2B212C95M005063	
Lot #	131	
Qty	1	
Title	1999 FLEMING FLATBED FLATBED TRAILER	
Des.	TRAILER IS MISSING ONE AXLE. 39ft Total Length, 30ft Body Length, 8ft Width, Spring Suspension, Steel Composition, Steel Wheels, 215/75R17.5, Pintle Hitch, Body Damage/Rust. Location: Buckeye, AZ Serial: 1F9FS3026X1025161	