



Housby Auctions (Marcus Bowersox)
4747 NE 14th St, Des Moines, IA 50313 USA
(515) 299-6265

VIN: 1FVKCYBS1BDAX3796

2011 FREIGHTLINER M2

SPECIFICATIONS	
MILEAGE	43,252 / 38,819 (ECM)
ENGINE HOURS	2,069
ENGINE	CUMMINS ISC 8.3L
FUEL / TANKS	DIESEL - 1 ALUM 80 GAL TOTAL
TRANSMISSION	ALLISON 6 SPD AUTO
DRIVE OPTS	POWER STEERING, OVERDRIVE, CRUISE
AXLE TYPE	TANDEM - F 16,000 LB / R 40,000 LB
GVWR	56,000
FRAME	STEEL
SUSPENSION	TUFTRAC
TIRE SIZE	F 315/80R22.5 / R 11R22.5
WHEELS	F STEEL / R STEEL
AIR COND	YES, OPERATIONAL
INTERIOR COLOR	GRAY
RADIO	AM/FM, OPERATIONAL
PASSENGER SEAT	STATIONARY
EXTERIOR COLOR	WHITE
BUMPER	PAINTED
COLLISION AVOIDANCE?	NO



BRAKES	
LEFT FRONT	RIGHT FRONT
COVERED	COVERED
LEFT REAR 1	RIGHT REAR 1
17	18
LEFT REAR 2	RIGHT REAR 2
18	19

TIRES & WHEELS			
LEFT FRONT		RIGHT FRONT	
13 / 32 STEEL		11 / 32 STEEL	
LEFT OUTER 1	LEFT INNER 1	RIGHT INNER 1	RIGHT OUTER 1
5 / 32 - STEEL	24 / 32 - STEEL	25 / 32 - STEEL	25 / 32 - STEEL
LEFT OUTER 2	LEFT INNER 2	RIGHT INNER 2	RIGHT OUTER 2
23 / 32 - STEEL	22 / 32 - STEEL	24 / 32 - STEEL	24 / 32 - STEEL
FRONT TIRES: 315/80R22.5		REAR TIRES: 11R22.5	

ADDITIONAL TIRE DETAIL
FRONT TIRES AND RLO1 ARE ROADMASTER BRAND. ALL OTHER TIRES ARE SUMITOMO BRAND TIRES.

GENERAL OBSERVATIONS

OIL MILKY?	NO	LIGHTS WORK?	YES - ALL
OIL LEAKS?	NO	WIPERS WORK?	YES
WATER LEAKS?	NO	GAUGES WORK?	YES - ALL
OIL IN COOLANT?	NO	AIR HORN WORKS?	YES
CLUTCH PLAY?	OK	CITY HORN WORKS?	YES
STARTS?	YES	DIESEL PARTICULATE FILTER	
DRIVES	YES	PASS	


WEAR & TEAR DETAIL

DIAGNOSTICS	ACTIVE FAULT: SPN 6912 FMI 7 (REMOTE START SWITCH STUCK IN CRANK MODULE HAS DETECTED INCORRECT RESPONSE FROM A MECHANICAL SYSTEM)
AIR COMPRESSOR	AUX COMPRESSOR IS INOPERABLE
HOOD / FENDER	LEFT FRONT CORNER CRACKED

FRONT BUMPER	PAINT CHIPPED, SCRATCHED - SMALL DENT ON RIGHT SIDE
INTERIOR	SURFACES AND UPHOLSTERY ARE DIRTY
HEADLINER	FABRIC LOOSE / STARTING TO SAG
REAR EQUIPMENT	PAINT FLAKING AND RUST FORMING AT VARIOUS AREAS
TIRES	1 MEASURES BELOW 10/32

REPORT VIDEOS

REPORT PHOTOS







Condition report only. National Inspection Services does not guarantee mechanical reliability.

© National Inspection Services
 101 W. Shrader St. Liberty, MO 64068
www.nationalinspect.com