



National Inspection Services  
# : **117293** on 02/14/2015  
VIN: **1M2P264C7RM015788** Unit: **233**

VOCON Marcus Bowersox  
4747 NE 14th St Des Moines, IA 50313 USA  
(515) 299-6265

## 1994 MACK RD690S

### RD690S Specifications

Mileage	127,484
Engine Hours	21137
Engine	Mack EM 7 300 HP
Fuel	Diesel 1 Alum Tanks 59 Gal. Total
Transmission	Mack Manual T2080 8 Spd
Axles	Tandem
Frame Type	Steel
Suspension	Walking Beam
Wheelbase	208"
Tire Size F	425/65R22.5
Tire Size R	11R22.5
Wheels	Steel
Lift Gate	No
Exterior	98"H 96"W 20'L
Air Cond	Yes * <b>See Notes</b> )
Interior Color	BLACK
Exterior Color	WHITE
Bumper	Chrome
Heated Mirrors	No
Visor	Yes

### Inspection Photos



Drive Options

Power Steering

Notes / Description









National Inspection Services  
# : 117293 on 02/14/2015  
VIN: 1M2P264C7RM015788 Unit: 233

VOCON Marcus Bowersox  
4747 NE 14th St Des Moines, IA 50313 USA  
(515) 299-6265

## 1994 MACK RD690S

Brakes	
Additional Brake Detail	
Front brakes have dust covers, unable to access rear brakes	

Tires			
Front 425/65R22.5	19 / 32 Steel	17 / 32 Steel	Rear 11R22.5
Hankook 12 / 32 Steel	11 / 32 Steel	13 / 32 Steel	14 / 32 Steel
Toyo 13 / 32 Steel	Michelin 12 / 32 Steel	14 / 32 Steel	Dunlop 15 / 32 Steel
Additional Tire Detail			

General Observations	
Oil Milky? No	Oil Leaks? No
Water Leaks? No	Oil in Coolant? No
Clutch Play? NA	Starts? No
Drives? No	
Safety / Operational Observations	
Lights Work? Yes - All	Wipers Work? Yes
Gauges Work? Yes - All	City Horn Works? Yes
Air Horn Works? See Detail	
Additional Observation Detail	
Truck will not start, no air pressure to check horn	

Wear and Tear Items		
oil filler	cap is missing	NA
breather	missing	NA
note	Employee states that Pitman Arm is bad, causing a steering problem. They have not been able to find a replacement	NA
body	10 yard mixer Housby model F3 serial number 0045115788	NA
Note	Truck has no batteries. New batteries were installed to attempt to start truck and jumpers were also attached. Engine would crank slowly but would not fire off.	NA
Water tank	Drivers side water tank strap is broken, tank held on with ratchet strap	NA
A/C	unable to check A/C operation due to vehicle not starting	NA
Note	low back driver's seat. no passenger seat	NA
Note	There is no specification tag on the body unable to get axle specs	NA
Engine	ID plate unreadable	NA
Total Estimate		NA

Condition report only. National Inspection Services does not guarantee mechanical reliability.

© 2015 National Inspection Services (NIS)  
6501 E. Commerce Ave. Suite 135 Kansas City, MO 64120  
[www.nationalinspect.com](http://www.nationalinspect.com)