



National Inspection Services

: **117387** on 02/26/2015

VIN: **1NPAX90XXVD438101**

VOCON Marcus Bowersox

4747 NE 14th St Des Moines, IA 50313 USA

(515) 299-6265

1997 PETERBILT 357

357 Specifications

Mileage	184,682
Engine Hours	8112
Engine	Cummins M11 330 HP
Fuel	Diesel 1 Alum Tanks 50 Gal. Total
Exhaust	Single
Transmission	Eaton Manual RTO-14909MLL 9 Spd
Wet Line	No
Rear	Eaton 4.88
Axles	Tri 20,000 Front / 23,000 Rear
Frame Type	Steel
Suspension	Walking Beam
Wheelbase	260"
Tire Size F	445/65R19.5
Tire Size R	11R22.5
Wheels	Steel
Interior Color	BROWN
Radio Config	AM/FM/CD * Operational
Exterior Color	WHITE
Bumper	Chrome
Heated Mirrors	No


Inspection Photos



Fairings	None
Visor	No

Drive Options
Power Steering

Notes / Description
Flat bed





National Inspection Services

: 117387 on 02/26/2015

VIN: 1NPAX90XXVD438101

VOCON Marcus Bowersox

4747 NE 14th St Des Moines, IA 50313 USA

(515) 299-6265

1997 PETERBILT 357

Brakes	
Additional Brake Detail	
dust covers	

Tires			
Front 445/65R19.5	Bridgestone 7 / 32 Steel	Bridgestone 12 / 32 Steel	Rear 11R22.5
Bridgestone 12 / 32 Steel			Michelin 10 / 32 Steel
Michelin 10 / 32 Steel	Goodyear 15 / 32 Steel	Firestone 22 / 32 Steel	General 11 / 32 Steel
Bridgestone 20 / 32 Steel	Kelly 16 / 32 Steel	Bridgestone 18 / 32 Steel	Bridgestone 18 / 32 Steel
Additional Tire Detail			
rear caps			

General Observations						
Oil Milky? No	Oil Leaks? Yes	Water Leaks? No	Oil in Coolant? No	Clutch Play? Ok	Starts? Yes	Drives? Yes
Safety / Operational Observations						
Lights Work? Yes - All	Wipers Work? Yes	Gauges Work? Yes - All	City Horn Works? Yes	Air Horn Works? Yes		

Additional Observation Detail		
oil on both sides of engine		

Wear and Tear Items		
drivers seat	torn	NA
pass seat	not installed	NA
Total Estimate		NA

Condition report only. National Inspection Services does not guarantee mechanical reliability.

© 2015 National Inspection Services (NIS)
 6501 E. Commerce Ave. Suite 135 Kansas City, MO 64120
www.nationalinspect.com