



Housby Auctions (Ashly Healey)
4747 NE 14th St, Des Moines, IA 50313 USA
(515) 299-6265

VIN: 3C7WRLBL1DG551647
Stock #: 551647

2013 RAM 4500

SPECIFICATIONS	
ENGINE	CUMMINS 6.7L I6
FUEL / TANKS	DIESEL - 1 STEEL
TRANSMISSION	AISIN AS69RC HD 6 SPD AUTO
DRIVE OPTS	POWER STEERING, OVERDRIVE, CRUISE
REAR END	SPICER 4.10
AXLE TYPE	SINGLE - F 7,000 LB / R 12,000 LB
GVWR	16,000
FRAME	STEEL
SUSPENSION	SPRING
WHEELBASE	168"
TIRE SIZE	225/70R19.5
WHEELS	F STEEL / R STEEL
AIR COND	YES
INTERIOR COLOR	BLACK
RADIO	AM/FM / BLUETOOTH
HIGH BACK SEATS	DUAL
PASSENGER SEAT	STATIONARY
EXTERIOR COLOR	WHITE
BUMPER	PAINTED



BRAKES	
LEFT FRONT	RIGHT FRONT
DISC	DISC
LEFT REAR 1	RIGHT REAR 1
DISC	DISC

TIRES & WHEELS			
LEFT FRONT		RIGHT FRONT	
8 / 32 GOODYEAR STEEL		12 / 32 GOODYEAR STEEL	
LEFT OUTER 1	LEFT INNER 1	RIGHT INNER 1	RIGHT OUTER 1
16 / 32 BF GOODRICH STEEL	15 / 32 BF GOODRICH STEEL	16 / 32 BF GOODRICH STEEL	16 / 32 BF GOODRICH STEEL
FRONT TIRES: 225/70R19.5		REAR TIRES: 225/70R19.5	

GENERAL OBSERVATIONS

OIL MILKY?	NO	LIGHTS WORK?	SEE NOTES
OIL LEAKS?	YES	WIPERS WORK?	SEE NOTES
WATER LEAKS?	NO	GAUGES WORK?	SEE NOTES
OIL IN COOLANT?	NO	AIR HORN WORKS?	NA
CLUTCH PLAY?	NA	CITY HORN WORKS?	SEE NOTES
STARTS?	SEE NOTES		
DRIVES	SEE NOTES		

ADDITIONAL OBSERVATIONS

UNIT IS NON-OPERATIONAL AND FAILED TO RESPOND TO JUMP-START ATTEMPTS HINDERING TESTING OF THE ELECTRICAL SYSTEMS. OIL LEAK AT OIL PAN GASKET AREA

WEAR & TEAR DETAIL

DRIVERS SEAT	TORN
CAB	DENTED REAR PASSENGER SIDE
PAINT	CHIPPED AT HOOD, CAB & CAB DOORS. FLAKING & SURFACE RUST AT POWERTRAIN, UNDERCARRIAGE, BUMPER & WHEELS
SEATS	UPHOLSTERY IS WORN, RIPPED & STAINED

VISOR	RIPPED ON D/S
INTERIOR	DIRTY NEEDS CLEANED
TIRES	1 MEASURE BELOW 10/32

REPORT PHOTOS





Condition report only. National Inspection Services does not guarantee mechanical reliability.

© National Inspection Services
239 W. Mill St. Liberty, MO 64068
www.nationalinspect.com