



National Inspection Services
: **130461** on 06/23/2016
VIN: **1C9AZ1472YG148851** Unit: **60281**

Housby Auctions Marcus Bowersox
4747 NE 14th St Des Moines, IA 50313 USA
(515) 299-6265


2000 COTTRELL C-7512


C-7512 Specifications	
Axles	Tandem 18,000 Front / 18,000 Rear
Spread Axle	No
Frame Type	Steel
Suspension	Air Ride
Tire Size F	285 70R 19.5
Tire Size R	285 70R 19.5
Wheels	Aluminum
Exterior	144"H 102"W 47'L
Exterior Color	BLACK

Drive Options

Notes / Description

Inspection Photos







National Inspection Services

: 130461 on 06/23/2016

VIN: 1C9AZ1472YG148851 Unit: 60281

Housby Auctions Marcus Bowersox

4747 NE 14th St Des Moines, IA 50313 USA

(515) 299-6265

2000 COTTRELL C-7512

Brakes	
Additional Brake Detail	
Drum type not visable	

Tires			
Front 285 70R 19.5	/ 32	/ 32	Rear 285 70R 19.5
7 / 32 Aluminum	9 / 32 Aluminum	6 / 32 Aluminum	8 / 32 Aluminum
9 / 32 Aluminum	9 / 32 Aluminum	6 / 32 Aluminum	6 / 32 Aluminum
Additional Tire Detail			
USED CONDITION			

General Observations	
Oil Milky?	Oil Leaks? NA Water Leaks? NA Oil in Coolant? NA Clutch Play? NA Starts? NA Drives? NA
Safety / Operational Observations	
Lights Work? NA Wipers Work? NA Gauges Work? NA City Horn Works? NA Air Horn Works? NA	
Additional Observation Detail	
unable to test Hydraulics air and electrical systems	

Wear and Tear Items		
Air tank	Loose air storage tank above axles	NA
Hydraulic Ram	laying loose on back disconnected	NA
Hydraulic System	unable to test	NA
Tires	All below terms	NA
Light	Missing marker light on right side	NA
Body	Surface rust	NA
Total Estimate		NA

Condition report only. National Inspection Services does not guarantee mechanical reliability.