



Housby Auctions (Marcus Bowersox)
4747 NE 14th St, Des Moines, IA 50313 USA
(515) 299-6265

VIN: 1D7HA18N48S563323
Stock #: 01.704896

2008 DODGE 1500

SPECIFICATIONS	
ENGINE	DODGE 4.7L V8
FUEL / TANKS	GASOLINE - 1 STEEL
TRANSMISSION	CHRYSLER 48RE 4 SPD AUTO
DRIVE OPTS	POWER STEERING, OVERDRIVE, CRUISE
REAR END	3.92
AXLE TYPE	SINGLE - F 3,700 LB / R 3,900 LB
GVWR	6,700
FRAME	STEEL
SUSPENSION	SPRING
WHEELBASE	140"
TIRE SIZE	P265/70R17
WHEELS	F ALUMINUM / R ALUMINUM
INTERIOR COLOR	GRAY
RADIO	AM/FM / CD
MIRRORS	DUAL POWER
HIGH BACK SEATS	DUAL
PASSENGER SEAT	STATIONARY
EXTERIOR COLOR	WHITE
BUMPER	PAINTED
EXTERIOR OPTS	HEATED MIRRORS



NOTES / DESCRIPTION
ENGINE DOES NOT MEET CONDITION TO START OR DRIVE. SEE COMMENTS IN CHECKLIST.

BRAKES	
LEFT REAR 1	RIGHT REAR 1
ADDITIONAL BRAKE DETAIL	
ONLY ABLE TO TAKE PICTURES.	

TIRES & WHEELS			
LEFT FRONT		RIGHT FRONT	
14 / 32 BRIDGESTONE ALUMINUM		14 / 32 BRIDGESTONE ALUMINUM	
LEFT OUTER 1	LEFT INNER 1	RIGHT INNER 1	RIGHT OUTER 1
8 / 32 GENERAL ALUMINUM	- - -	- - -	11 / 32 GENERAL ALUMINUM
FRONT TIRES: P265/70R17		REAR TIRES: P265/70R17	

GENERAL OBSERVATIONS

OIL MILKY?	NO	LIGHTS WORK?	SEE NOTES
OIL LEAKS?	YES	WIPERS WORK?	SEE NOTES
WATER LEAKS?	NO	GAUGES WORK?	SEE NOTES
OIL IN COOLANT?	NO	AIR HORN WORKS?	NA
CLUTCH PLAY?	NA	CITY HORN WORKS?	SEE NOTES
STARTS?	SEE NOTES		
DRIVES	NO		

ADDITIONAL OBSERVATIONS
OIL LEAK NOTED ON LOWER PORTION OF THE ENGINE / BOTTOM OF BLOCK AREA. TRANSMISSION PAN HAS FLUID RESIDUE NOTED.

WEAR & TEAR DETAIL	
BATTERIES	DEAD, UNABLE TO START UNIT OR TEST MOST ELECTRICAL FUNCTIONS
INTERIOR	DIRT, DUST, TRASH, ETC. EVEN MICE POOP IS PRESENT.
DRIVER SEAT	TORN
DOOR PANESL	LEFT SIDE PLASTIC COVER IS BROKEN.
BACK WINDOW	GASKET IS BROKEN, SINGS OF CAULK OR SEALER WAS USED. PROBABLY THERE IS WATER LEAKING.

PAINT (LOWER SECTIONS AND AROUND WHEELS).	ASPHALT IN PAINT
PAINT	VARIOUS CHIPS AND SCRATCHES NOTED THROUGHOUT UNIT
INTERIOR	SURFACES AND UPHOLSTERY ARE DIRTY
SEATS	COVER TORN
ENGINE BAY	MISSING MULTIPLE COMPONENTS
STEERING WHEEL	WORN
DRIVEABILITY	ENGINE CONDITIONS DO NOT PERMIT TO START IT. BROKEN MAIN BELT, RIGHT SIDE COVER IS MISSING A HOSE CONTACT STATED THAT THE ENGINE ALSO POSSIBLY NEEDS A WATER PUMP REPLACEMENT.
TIRES	1 MEASURES BELOW 10/32

REPORT PHOTOS





Condition report only. National Inspection Services does not guarantee mechanical reliability.

© National Inspection Services
 101 W. Shradar St. Liberty, MO 64068
www.nationalinspect.com