



## National Inspection Services

Report: 242379

08/08/2023

**Housby Auctions (Marcus Bowersox)**  
4747 NE 14th St, Des Moines, IA 50313 USA  
(515) 299-6265

VIN: 35398  
Stock #: FK99398

### 2011 TOYOTA 8FGU25 LP

| SPECIFICATIONS |                      |
|----------------|----------------------|
| ENGINE         | TOYOTA 4Y ECS        |
| HOURS          | 7766                 |
| FUEL / TANKS   | PROPANE              |
| TIRE SIZE      | F 7.00-12 / R 6.00-9 |



| BRAKES      |              |
|-------------|--------------|
| LEFT REAR 1 | RIGHT REAR 1 |

| TIRES & WHEELS       |              |                    |               |
|----------------------|--------------|--------------------|---------------|
| LEFT OUTER 1         | LEFT INNER 1 | RIGHT INNER 1      | RIGHT OUTER 1 |
| FRONT TIRES: 7.00-12 |              | REAR TIRES: 6.00-9 |               |

### GENERAL OBSERVATIONS

|                 |     |                  |           |
|-----------------|-----|------------------|-----------|
| OIL MILKY?      | NO  | LIGHTS WORK?     | YES - ALL |
| OIL LEAKS?      | NO  | WIPERS WORK?     | NA        |
| WATER LEAKS?    | NO  | GAUGES WORK?     | YES - ALL |
| OIL IN COOLANT? | NO  | AIR HORN WORKS?  | NA        |
| CLUTCH PLAY?    | NA  | CITY HORN WORKS? | YES       |
| STARTS?         | YES |                  |           |
| DRIVES          | YES |                  |           |

### WEAR & TEAR DETAIL

|           |                                             |
|-----------|---------------------------------------------|
| BODY      | SCRATCHES, SCRAPES, FLAKES AND SURFACE RUST |
| LOAD RACK | BENT AT TOP AND BOTTOM                      |
| TIRES     | DRIVES AND STEERS WORN SMOOTH               |

### REPORT VIDEOS



REPORT PHOTOS







Condition report only. National Inspection Services does not guarantee mechanical reliability.

© National Inspection Services  
 101 W. Shrader St. Liberty, MO 64068  
[www.nationalinspect.com](http://www.nationalinspect.com)