



National Inspection Services

Report: 339628
07/31/2026

Housby Auctions (Ashly Healey)
4747 NE 14th St, Des Moines, IA 50313 USA
(515) 299-6265

VIN: 0160058451

0000 JLG 10042B

SPECIFICATIONS

ENGINE	DEUTZ 3.6 L4
ENG SERIAL	LH015407396
FUEL / TANKS	GASOLINE
TIRE SIZE	400/7.5-28



BRAKES

LEFT FRONT	RIGHT FRONT
COVERED	COVERED
LEFT REAR 1	RIGHT REAR 1
COVERED	COVERED

TIRES & WHEELS

LEFT FRONT		RIGHT FRONT	
36 / 32 STEEL		36 / 32 STEEL	
LEFT OUTER 1	LEFT INNER 1	RIGHT INNER 1	RIGHT OUTER 1
-	36 / 32	36 / 32	-
-	-	-	-
-	STEEL	STEEL	-
FRONT TIRES: 400/7.5-28		REAR TIRES: 400/7.5-28	

GENERAL OBSERVATIONS

OIL MILKY?	NO	LIGHTS WORK?	NA
OIL LEAKS?	YES	WIPERS WORK?	NA
WATER LEAKS?	NO	GAUGES WORK?	NA
OIL IN COOLANT?	NO	AIR HORN WORKS?	NA
CLUTCH PLAY?	NA	CITY HORN WORKS?	NA
STARTS?	NA		
DRIVES	NA		


ADDITIONAL OBSERVATIONS

NEEDS PRESSURE WASHED TO DETERMINE SOURCE OF LEAK

WEAR & TEAR DETAIL

SEAT	HEAVY WEAR
DRIVE SHAFT	FRONT REMOVED
BATTERY	DEAD
DOOR	BACK DOOR BENT (RADIATOR ACCESS)
PAINT	PEELING IN VARIOUS PLACES
ENGINE	IS INOP
AIR FILTER	REMOVED

REPORT PHOTOS





Condition report only. National Inspection Services does not guarantee mechanical reliability.

© National Inspection Services
 239 W. Mill St. Liberty, MO 64068
www.nationalinspect.com